REQUEST FOR QUALIFICATIONS RFQ 17-065C

DESIGN PROFESSIONAL SERVICES

Tedder Elementary School



The School Board of Broward County, Florida

Dr. Rosalind Osgood, Chair Abby M. Freedman, Vice Chair Robin Bartleman Heather P. Brinkworth Patricia Good Donna P. Korn Laurie Rich Levinson Ann Murray Nora Rupert

Robert W. Runcie, Superintendent of Schools

Leo Bobadilla - Chief Facilities Officer Barbara J. Myrick, Interim General Counsel

Office of Facilities and Construction Procurement and Warehousing Services

NOTICES TO ALL BIDDERS Cone of Silence and Lobbyist Activities

For Cone of Silence requirements and for Lobbyist Activities restrictions, refer to Section 1, Introduction and General Information lines labeled 'Cone of Silence and Lobbyist Activities' (lines 1.10 and 1.11).

THE SCHOOL BOARD OF BROWARD COUNTY, FLORIDA Procurement and Warehousing Services Department 7720 W. Oakland Park Boulevard, Suite 323 Sunrise, Florida 33351-6704

REQUEST FOR QUALIFICATIONS (RFQ) RFQ # 17-065C DESIGN PROFESSIONAL SERVICES

RFQ Issue Date: August 19, 2016

Description of Scope:

Design Services for the following project:

Tedder Elementary School

- Fire Sprinklers
- Fire Alarm
- PE/Athletic Improvements
- HVAC Improvements
- Building Envelope Improvements

NOTICES TO ALL PROPOSERS

Cone of Silence and Lobbyist Activities

For Cone of Silence requirements and for Lobbyist Activity restrictions refer to Section 1, Introduction and General Information lines labeled Cone of Silence and Lobbyist Activities. Line numbers 1.10 and 1.11.

THE SCHOOL BOARD OF BROWARD COUNTY, FLORIDA Procurement and Warehousing Services Department 7720 W. Oakland Park Boulevard, Suite 323 Sunrise, Florida 33351-6704

RFQ - 17-065C Design Services

Version Date: 06/20/16

TABLE OF CONTENTS

<u>Section</u>			<u>Page</u>
	RFQ Cover Sheet		1
	Table of Contents and A	attachments	2
1.0	Introduction and Genera	Il Information	3
2.0	Calendar		6
3.0	RFQ Conditions		7
4.0	Required Proposal Form	nat and Response Information	11
5.0	Evaluation of Qualification	ons	15
6.0	Project Scope and Sche	dule	17
Attachment I Attachment I Attachment I Attachment I Attachment I Attachment I	— A - M/WBE Participation B – Design Professional a	Services Agreement (With attachments) Project Schedule Project Scope (See Attachment G) Electronic Media Submittal Requirements Project Consultant's Invoice Format, Reimbursable and Supple List of Project Team Members Authorization to Proceed (ATP) Form Professional Services Required – page 1 of 3 Project Schedule – page 2 of 3 Professional Fee – page 3 of 3 Document Submittal Checklist Document 00455 – Background Screening IRS Form W-9 Truth in Negotiations Certificate form Project Schedule – page 3 of 3	mental Services Format

SECTION 1.0 - INTRODUCTION AND GENERAL INFORMATION

- 1.1 The School Board of Broward County, Florida (hereinafter referred to as "SBBC") desires to receive Qualifications for Design Services as described herein.
- Questions and Interpretations: Any questions, requests for clarifications or interpretations regarding any portion of this RFQ during the Submittal preparation period (or reporting errors, inconsistencies, or ambiguities) shall be received no less than ten (10) days prior to the deadline due date for submitting the completed RFQ response, and no questions or clarifications will be considered after this date. Respondents must submit Document 00220 Bidders Request For Information Form (Attachment F) for all RFI requests and all RFI requests must be typed or printed. Questions not submitted on Document 00220 will not be considered. RFI requests must be for a single RFQ, RFI requests for multiple RFQs may not be considered. Any questions which require a response which amends the RFQ document in any manner will be answered via Addendum by the Procurement and Warehousing Services Department and provided to all Proposers. Address questions or requests for clarifications in writing to:

Vanessa S. Lauchaire
Strategic Sourcing Manager
Procurement & Warehousing Services
7720 West Oakland Park Blvd - Suite 323
Sunrise, FL 33351
754-321-0533 Fax

E-mail: <u>vanessa.lauchaire@browardschools.com</u>

- 1.3 Any verbal or written information, which is obtained other than by information in this RFQ document or by Addenda, shall not be binding on SBBC.
- 1.4 <u>Contract Term:</u> The term of this contract is anticipated to begin on the Notice to Proceed Date and end one year after final completion of the project.
- 1.5 <u>Proposal Format:</u> The RFQ's submittal shall follow the format and include the information as identified in Section 4.0 of this RFQ.
- 1.6 <u>Evaluation and Award:</u> All Proposals will be evaluated by the Selection Committee based upon the information submitted by Proposers in response to this RFQ and in accordance with the evaluation criteria established in Section 5.0. Based upon the evaluation of Proposals, the Committee will recommend a Proposer(s) to the Superintendent of Schools who may then recommend a Proposer(s) to the SBBC for award.
- 1.7 <u>Irrevocability of Proposal:</u> A Proposal may not be withdrawn before the expiration of 90 days after the date of the Proposal's opening.
- 1.8 Proposal Package Requirements:
 - --- One complete, original hard-copy Proposal (clearly labeled as "original").
 - --- One complete, original electronic version (clearly labeled as "original").
 - --- Five (5) complete, electronic version copies (clearly labeled as "copy").
 - --- Four (4) additional hard-copies (which must be identical to the original Proposal except they shall be labeled as "copy").
 - --- Proposals shall be submitted in a sealed envelope (package, box, etc.) with the RFQ number and description clearly identified by label on the Package along with the Proposers Name.

- 1.9 <u>Gratuities:</u> Proposers shall not provide any gratuities, favors, or anything of monetary value to any official, employee, or agent of SBBC; including any School Board Member, Superintendent of Schools and any Evaluation Committee Members, for any reason during this entire Procurement Process.
- 1.10 Cone of Silence: Any proposer, or lobbyist for a proposer, is prohibited from having any communications (except as provided in this rule) concerning any solicitation for a competitive procurement with any School Board member, the Superintendent, any Evaluation Committee Member, or any other School District employee after the Procurement and Warehousing Services Department releases a solicitation to the General Public. All communications regarding this solicitation shall be directed to the designated Purchasing Agent unless so notified by the Procurement and Warehousing Services Department. This "Cone of Silence" period shall go into effect and shall remain in effect from the time of release of the solicitation until the contract is awarded by the School Board. Further, any vendor, its principals, or their lobbyists shall not offer campaign contributions to School Board Members or offer contributions to School Board Members for campaigns of other candidates for political office during the period in which the vendor is attempting to sell goods or services to the School Board. This period of limitation of offering campaign contributions shall commence at the time of the "cone of silence" period for any solicitation for a competitive procurement as described by School Board Policy 3320, Part II, Section GG as well as School Board Policy 1007, Section 5.4 Campaign Contribution Fundraising. Any vendor or lobbyist who violates this provision shall cause their Proposal (or that of their principal) to be considered non-responsive and therefore be ineligible for award. This prohibition does not apply to:
 - 1. Telephone calls to the Procurement & Warehousing Services staff to request copies of this RFQ, to confirm attendance, or request directions regarding an interview notification received;
 - 2. Delivery of the Respondent's Submittal;
 - 3. Discussion at the interview;
 - 4. Delivery of written questions about the RFQ; and/or Review of background/contract documents at the staff offices.
- 1.11 <u>Lobbyist Activities:</u> In accordance with SBBC Policy 1100B, as currently enacted or as amended from time to time, persons acting as lobbyists must state, at the beginning of their presentation, letter, telephone call, e-mail or facsimile transmission to School Board Members, Superintendent or Members of Senior Management, the group, association, organization or business interest she/he is representing.
 - 1.11.1 A lobbyist is defined as a person who, for immediate or subsequent compensation (e.g., monetary profit/personal gain), represents a public or private group, association, organization or business interest and engages in efforts to influence School Board Members on matters within their official jurisdiction.
 - 1.11.2 A lobbyist is not considered to be a person representing school allied groups (e.g., PTA, DAC, Band Booster Associations, etc.) nor a public official acting in her/his official capacity.
 - 1.11.3 Lobbyists shall annually (July 1) disclose in each instance and for each client prior to any lobbying activities, their identity and activities by completing the lobbyist statement form which can be obtained from official School Board Records, School Board Member's Offices or the Superintendent's Office and will be recorded on SBBC's website, www.browardschools.com.
 - 1.11.4 The lobbyist must disclose any direct business association with any current elected or appointed official or employee of SBBC or any immediate family member of such elected or appointed official or employee of SBBC.
 - 1.11.5 Senior-level employees and/or School Board Members are prohibited from lobbying activities for two years after resignation or retirement or expiration of their term of office.
 - 1.11.6 The Office of the Superintendent shall keep a current list of persons who have submitted the lobbyist statement form.

- 1.12 <u>Preparation Cost of Proposal:</u> Proposer is solely responsible for any and all costs associated with responding to this RFQ. SBBC will not reimburse any Proposer for any costs associated with the preparation and submittal of any Proposal, or for any travel and per diem costs that are incurred by any Proposer.
- 1.13 It is the sole responsibility of the Proposer to assure it has received the entire Proposal and any and all Addendum.
- 1.14 It is the sole responsibility of the Proposer to assure that its Proposal is time stamped in the Procurement and Warehousing Services Department on or before 2:00 p.m. EST on the date due.
- 1.15 No verbal or written information which is obtained other than by information in this document or by Addenda to this RFQ shall be binding on SBBC.
- 1.16 No submissions made after the Proposal opening, amending or supplementing the Proposal, will be considered.

SECTION 2.0 CALENDAR

August 19, 2016 Issuance of RFQ #17-065C

September 7, 2016 Written questions due on or before 5:00 p.m. ET

in the Procurement and Warehousing Services Department

7720 West Oakland Park Blvd., Suite 323,

Sunrise, Florida 33351-6704.

September 22, 2016 Proposals due on or before 2:00 p.m. ET

in the Procurement and Warehousing Services Department.

7720 West Oakland Park Blvd., Suite 323,

Sunrise, Florida 33351-6704.

October 10, 2016** Selection Committee reviews Qualifications and

makes a recommendation for Selection in the Procurement and Warehousing Services Department 7720 West Oakland Park Boulevard, Suite 323 Sunrise, Florida 33351-6704 at 9:00 a.m.*

October 13, 2016 Evaluation Committees Posting of Recommendations.

December 6, 2016 Tentative School Board Award Date.

Individuals with disabilities requesting accommodations under the Americans with Disabilities Act (ADA) may call Equal Educational Opportunities (EEO) at 754-321-2150 or Teletype Machine (TTY) 754-321-2158.

^{*}These are public meetings. SBBC prohibits any policy or procedure which results in discrimination on the basis of age, color, disability, gender identity, gender expression, national origin, marital status, race, religion, sex or sexual orientation. Individuals who wish to file a discrimination and/or harassment complaint may call the Executive Director, Benefits & EEO Compliance at 754-321-2150 or Teletype Machine (TTY) 754-321-2158.

^{**}Proposers may be asked to be present at this public meeting to answer questions related to their submittal. Proposers may also be invited to make a presentation to the Selection Committee. If a presentation is requested, it must be limited to information included in their Proposal submitted to SBBC. Details related to the Selection Committee meeting will be provided to the proposers when they are given notice of the meeting.

SECTION 3.0 - RFQ CONDITIONS

- 3.1 <u>Evaluation Committees and Proposals:</u> State Statutes 119.071 and 286.0113 are adhered to by SBBC in the review and awarding of contracts.
- 3.2 <u>Public Record:</u> Proposer acknowledges that all information contained within their Proposal is part of the public domain as defined by the State of Florida Sunshine and Public Record Laws.
- 3.3 <u>Governing Law:</u> This RFQ, and any award(s) resulting from this RFQ, shall be interpreted and construed in accordance with the laws of the State of Florida. Any protests arising from this RFQ shall be subject to Section 120.57(3), Florida Statutes. Any disputes or controversies arising out of a contract awarded under this RFQ shall be submitted to the jurisdiction of the state courts of the Seventeenth Judicial Circuit in and for Broward County, Florida.
- 3.4 <u>Advertising:</u> In submitting an RFQ, Proposer agrees not to use the results therefrom as a part of any commercial advertising without prior written approval of SBBC.
- Billing Instructions and Payment: All payments made to the Design Professionals shall be made by ACH (Automated Clearing House). Monthly invoices shall be submitted to the Project Manager for review and approval. Refer to the PSA for the specifics. The ACH Payment Agreement Form is an attachment to the PSA (PSA Attachment 12). This form shall be submitted at the time of the execution of the Contract.
- 3.6 <u>Contract Value:</u> No guarantee is given or implied as to the total dollar value or work as a result of this RFQ. SBBC is not obligated to place any order for services performed as a result of this award. Order placement will be based upon the needs and in the best interest of SBBC.
- 3.7 <u>Conflict of Interest and Conflicting Employment or Contractual Relationship:</u> Section 112.313 (3) and (7), Florida Statutes, sets forth restrictions on the ability of SBBC employees acting in a private capacity to rent, lease, or sell any realty, goods, or services to SBBC. It also places restrictions on SBBC employees concerning outside employment or contractual relationships with any business entity which is doing business with SBBC. Each Proposer is to disclose any employees it has who are also SBBC employees. This Conflict of Interest Form is an attachment to the PSA (PSA attachment 9). This executed document shall be submitted at the time of Contract Execution. Any employees identified by the Proposer, should obtain legal advice as to their obligations and restrictions under Section 112.313 (3) and (7), Florida Statutes.
- 3.8 Disputes:
 - 3.8.1 In the event of a conflict between the documents, the order of priority of the documents shall be as follows:
 - 1. The Agreement resulting from the award of this RFQ (if applicable); then
 - 2. Addenda released for this RFQ, with the latest Addendum taking precedence; then
 - 3. the RFQ Documents: then
 - 4. Awardee's Proposal.
 - 3.8.2 In case of any other doubt or difference of opinion, the decision of SBBC shall be put in writing and shall be final and binding on both parties.
- 3.9 <u>Insurance:</u> Refer to PSA Agreement Part 5 Article 3 for Design Professional Insurance Requirements (RFQ Attachment C).
- 3.10 <u>Public Entity Crimes:</u> Section 287.133(2)(a), Florida Statutes, as currently enacted or as amended from time to time, states that a person or affiliate who has been placed on the convicted vendor list following a conviction for a public entity crime may not submit a Proposal on a contract to provide any goods or services to a public entity, may not submit a Proposal on a contract with a public entity for the construction or repair of a public building or public work, may not submit a Proposal on leases of real property to a public entity, may not be awarded or perform work as a contractor, supplier, subcontractor, or consultant under a contract with any public entity, and may not transact business with any public entity in excess of the threshold amount

RFQ - 17-065C Page 7 of 17
Design Services

Version Date: 06/20/16

provided in Section 287.017 for CATEGORY TWO [currently \$25,000] for a period of 36 months from the date of being placed on the convicted vendor list.

3.12 <u>M/WBE:</u>

- 3.12.1 M/WBE Goals: The Design Professional shall comply with the Owner's current M/WBE policies and procedures. The Design Professional's M/WBE goal for this Contract is 25 percent.
- 3.12.2 Information: SBBC encourages each Proposer to make every reasonable effort to include M/WBE participation on any contract award under this RFQ. An M/WBE is defined by SBBC as any legal entity, other than a joint venture, which is organized to engage in commercial transactions and which is at least 51% owned and controlled by a minority or women and has been Certified by SBBC as an approved M/WBE.
- 3.12.2.1 Any participation by firms not certified by SBBC at the time of proposal will not count in the RFQ evaluation process for the award of points in the Design Professional M/WBE Participation Category. However, firms that are certified by SBBC after the proposal's tentative award, will count towards the Design Professional's M/WBE project goal attainment. Design Professional to contact SDOP to provide the updated information.
- 3.12.2.2 For information on M/WBE Certification, or to obtain information on locating certified M/WBE's, contact SBBC's Supplier Diversity and Outreach Programs at 754-321-0550 or http://www.broward.k12.fl.us/supply/sdop/mwbe.html.
- 3.13 <u>Protesting of RFQ Conditions/Specifications:</u> Any person desiring to protest the conditions/specifications in this RFQ, or any Addenda subsequently released thereto, shall file a notice of intent to protest, in writing to the Director of Procurement and Warehousing Services Department. The formal written protest shall be filed within ten calendar days after the date the notice of protest was filed. Saturdays, Sundays, state holidays or days during which the school district administration is closed shall be excluded in the computation of the ten (10) calendar days. The formal written protest must be received on or before 5:00 p.m. EST of the 10th Calendar Day at the office of the Director of Procurement and Warehousing Services Department. Refer to Section 120.57(3)(b), Florida Statutes, as currently enacted or as amended from time to time, for the requirements for the written protest.
 - 3.13.1 Failure to file a notice of protest or to file a formal written protest within the time prescribed by Section 120.57(3), Florida Statutes, or a failure to post the bond or other security required by SBBC Policy 3320, Part VIII, within the time allowed for filing a bond, shall constitute a waiver of proceedings.
- Posting of RFQ Recommendations: RFQ Recommendations will be posted in the Procurement and Warehousing Services Department and on www.demandstar.com as noted on the Calendar (Section 2.0) or as modified by an addendum or by posting in the Procurement and Warehousing Services Department and at www.demandstar.com (under the document section for this RFQ). The Recommendations will remain posted for 72 hours. It is the responsibility of each Proposer to ascertain any revised date for the posting of RFQ Recommendations.
- 3.15 <u>Protest of Intended Decision:</u> Any person desiring to protest the Recommended Decision shall file a notice of protest, in writing, within 72 hours after the posting of the RFQ Recommendation and shall file a formal written protest within ten calendar days after the date the notice of protest was filed. The formal written protest must be received on or before 5:00 p.m. EST of the tenth (10) calendar day. Saturdays, Sundays, state holidays and days during which the school district administration is closed shall be excluded in the computation of the 72 hours.
 - 3.15.1 Failure to file a notice of protest or to file a formal written protest within the time prescribed by Section 120.57(3), Florida Statutes, or a failure to post the bond or other security required by Policy 3320, Part VIII, within the time allowed for filing a bond, shall constitute a waiver of proceedings.
 - 3.15.2 Notices of protests, formal written protests, and the bonds required by Policy 3320, shall be filed at the office of the Director of Procurement and Warehousing Services, 7720 West Oakland Park Boulevard, Suite 323, Sunrise, Florida 33351 Fax filing will not be acceptable for the filing of bonds.

- 3.16 <u>Use of Other Contracts:</u> SBBC reserves the right to utilize any other SBBC contract, any State of Florida Contract, any contract awarded by any other city or county governmental agencies, other school boards, other community college/state university system cooperative agreements, in lieu of any offer received or award made as a result of this RFQ if it is in SBBC's best interest to do so. SBBC also reserves the right to waive irregularities or technicalities in any Proposal received if such action is in the best interest of SBBC. However, such a waiver shall in no way modify the RFQ requirements or excuse the Proposer from full compliance with the RFQ specifications and other contract requirements if the Proposer is awarded a contract.
- 3.17 <u>Assignment:</u> Neither party to the Agreement shall sell, assign or sublet the same without the written consent of the other; nor shall a Design Professional assign any monies due or to become due to the Design Professional, or by reason of the Contract without the previous written consent of the Owner and as approved by the Attorney for the Owner.
- 3.18 <u>Cancellation:</u> In the event any of the provisions of this RFQ are violated by the Awardee, the Director of Procurement and Warehousing Services shall give written notice to the Awardee stating the violations and unless they are corrected within five days, a recommendation will be made to SBBC for cancellation.

3.19 SBBC Photo Identification Badge:

Background Screening: Awardee agrees to comply with all the requirements of Sections 1012.32 and 1012.465, Florida Statutes, and that Awardee and all its personnel who (1) are to be permitted access to school grounds when students are present, (2) will have direct contact with students, or (3) have access or control of school funds will successfully complete the background screening required by the referenced statutes and meet the standards established by the statutes. Personnel shall include employees, representatives, agents or sub-contractors performing duties under the contract to SBBC and who meet any or all of the three requirements identified above. Awardee will bear the cost of acquiring the background screening required under Section 1012.32, Florida Statutes, and any fee imposed by the Florida Department of Law Enforcement to maintain the fingerprints provided with respect to Awardee and its personnel. The Parties agree that the failure of Awardee to perform any of the duties described in this section shall constitute a material breach of this RFQ entitling SBBC to terminate immediately with no further responsibilities or duties to perform under this Agreement. Awardee agrees to indemnify and hold harmless SBBC, its officers and employees of any liability in the form of physical or mental injury, death or property damage resulting in Awardee's failure to comply with the requirements of this section or Sections 1012.32 and 1012.465, Florida Statutes.

- 3.19.1 SBBC issued identification badges must be worn at all times when on SBBC property and must be worn where they are visible and easily readable.
- 3.19.2 Badge Vendor Information shall be provided to the Design Professional at the time of Award.
- 3.20 <u>Withdrawal of RFQ:</u> In the best interest of SBBC, SBBC reserves the right to withdraw this RFQ at any time prior to the time and date specified for the Proposal opening.
- 3.21 <u>Severability:</u> In case of any one or more of the provisions contained in this RFQ shall be for any reason be held to be invalid, illegal, unlawful, unenforceable or void in any respect, the invalidity, illegality, unenforceability or unlawful or void nature of that provision shall not affect any other provision and this provision shall be considered as if such invalid, unlawful, unenforceable or void provision had never been included herein.
- 3.22 It is the sole responsibility of the Proposer to assure it has received the entire Proposal and any and all Addendum.
- 3.23 It is the sole responsibility of the Proposer to assure that its Proposal is time stamped in the Procurement and Warehousing Services Department on or before the due time on the date due. No submissions made after the Proposal opening, amending or supplementing the Proposal, shall be considered.
- 3.24 No verbal or written information which is obtained other than by information in this document or by Addenda to this RFQ shall be binding on SBBC.

3.25 <u>Acceptance and Rejection of Proposals:</u>

3.25.1 Acceptance: All Proposals properly completed and submitted will be evaluated in accordance with Section 5.0.

RFQ - 17-065C Page 9 of 17

Design Services Version Date: 06/20/16

- 3.25.2 Rejection: A Proposal may be rejected if it does not conform to the rules or the requirements contained in this RFQ. Examples for rejection include, but are not limited to, the following:
 - 3.25.2.1 The Proposal is time-stamped at the Procurement and Warehousing Services Department after the deadline specified in the RFQ.
 - 3.25.2.2 Proposers found legally guilty of collusion among Proposers, shall be rejected, and the participants to such shall be barred from future procurement opportunities until such time as they may be reinstated.
 - 3.25.2.3 The Proposal shows non-compliance with applicable laws; or contains any unauthorized additions or deletions; is a conditional Proposal; is an incomplete Proposal; or contains irregularities of any kind.
 - 3.26.2.4 The Proposer adds provisions reserving the right to accept or reject an award or to enter into a contract pursuant to an award or adds provisions contrary to those in the RFQ.
- 3.25.3 SBBC also reserves the right to waive irregularities or technicalities in any Proposal received if such action is in the best interest of SBBC. However, such a waiver shall in no way modify the RFQ requirements or excuse the Proposer from full compliance with the RFQ specifications and other contract requirements if the Proposer is awarded the contract.

3.26 <u>Maintenance of Records</u>:

- 3.26.1 Design Professional shall keep all records and supporting documentation which concern or reflect its Services hereunder. The records and documentation shall be retained by the Design Professional for a period of seven (7) years from the completion date of the project associated with the Authorization to Proceed; or such period of time as required by law. The Owner, or any duly authorized agents or representatives of the Owner, shall have the right to inspect and copy all such records and documentation as often as they deem necessary during the period of this Agreement and during the period noted above in which the records are to be retained. Such activity shall be conducted at the reasonable convenience of the Design Professional.
- 3.27 <u>Liability:</u> Refer to Attachment C Sample Professional Services Agreement (PSA), Part 5 Article 2 Liability Clause.
- 3.28 <u>SBBC Information Security Guidelines:</u> It is the responsibility of the Design/Builder to read and adhere to the SBBC Information Security Guidelines when using any device connected to the SBBC's network. Following the conclusion of the contract term, all of SBBC's confidential information must be removed from the Design/Builder's equipment and all access privileges must be revoked. Final payment will be withheld until the Design/Builder has confirmed, in writing, that all SBBC's confidential information has been purged from any and all electronic technology devices that were used during this contract and were connected to the SBBC's network.

SECTION 4.0 - REQUIRED QUALIFICATIONS FORMAT AND RESPONSE INFORMATION

- 4.1 The SBBC's Procurement and Warehousing Services Department shall determine whether each Proposer has Addressed and provided all RFQ submittal requirements. SBBC's Procurement and Warehousing Department shall identify the status of completion for each Proposer's proposal on a spreadsheet for the Evaluation Committee's use.
- 4.2 It is required that Proposals be organized in the manner specified below and with all the information as identified.

4.2.1 Title Page:

- Line 1 Include RFQ number and name:
- Line 2. The RFQ Due Date:
- Line 3 The name of the Proposer (company/firm name);
- Line 4 Company/firm address;
- Line 5 and telephone number.

4.2.2 <u>Section A – General</u>

NOTE: Failure to strictly comply with this section may result in a recommendation to reject the proposal.

<u>Section A1</u> <u>Table of Contents:</u> Include a clear identification of the material by scoring sections, section number and by page number.

Section A2 Letter of Responsibility: Include the names of the persons who will be authorized to make decisions for the Proposer for this proposal, and for the Design efforts that may result from this RFQ. Provide titles, work addresses, telephone numbers and e-mail addresses. Letter to be on Company Letterhead and signed by an Officer of the Company.

Section A3 – Signed Addenda: Include signed and dated copies of all addenda to verify and acknowledge receipt.

4.2.3 <u>Section B – Required Forms, Licenses, certificates, History</u>

NOTE: Failure to strictly comply with this section may result in a recommendation to reject the proposal.

Section B1 - Required Response Form

Modifications or alterations to this form shall not be accepted and will cause the Proposal to be rejected and not reviewed. The Required Response Form, shall be the only acceptable form. The Required Response Form shall be completed in ink or typewritten. The signed "original" Required Response Form shall be submitted within the Proposal Package labeled as the "original." Refer to Attachment D.

JOINT VENTURES

Required Response Form for Joint Venture Proposals shall follow the following requirements. In the event multiple Proposers submit a joint Proposal in response to the RFQ, a single Proposer shall be identified as the Prime Proposer. If offering a joint Proposal, Prime Proposer must include the name and address of all parties of the joint Proposal. Prime Proposer shall provide all bonding and insurance requirements, execute any Contract, complete the Required Response Form shown herein, and have overall and complete accountability to resolve any dispute arising within this contract. Only a single contract with one Proposer shall be acceptable. Prime Proposer responsibilities shall include, but not be limited to, performing of overall contract administration, preside over other Proposers participating or present at SBBC meetings, oversee preparation of reports and presentations, and file any notice of protest and final protest as described herein. Prime Proposer shall also prepare and present a consolidated invoice(s) for services performed. SBBC shall issue only one check for each consolidated invoice to the Prime Proposer for services performed. Prime Proposer shall remain responsible for performing services associated with response to this RFQ.

RFQ - 17-065C Page 11 of 17
Design Services

Version Date: 06/20/16

Section B2 <u>Licenses and Registrations (Florida)</u>

- 3.1 All appropriate licenses shall be provided on a list
- 3.2 Firms Architectural License/Registration if applicable
- 3.3 Architectural License/Registration for _____
- 3.4 Architectural License/Registration for_____
- 3.5 Mechanical License/Registration for_____
- 3.6 Structural License/Registration for
- 3.7 M/WBE Certificate (if applicable) for proposer firm
- 3.8 continue as appropriate

Section B3 Proposer History

Provide a listing of current and former business entities that the Proposer is operating under and has operated under in the past. Letter to be on Company Letterhead and signed by an officer of the Company.

Section B4 Litigation

Provide a statement of any litigation or regulatory action that has been filed or is pending against your firm(s) in the last three years. If an action has been filed, state and describe the litigation or regulatory action filed, and identify the court or agency before which the action was instituted, the applicable case or file number, and the status or disposition for such reported action. If no litigation or regulatory action has been filed against your firm(s), provide a statement to that effect. For joint venture or team Proposers, submit the requested information for each member of the joint venture or team.

NOTE: Sections C and D below shall be evaluated and scored by QSEC

4.2.4 <u>Section C - Experience and Qualifications</u> (55 maximum points)

Section C1 Executive Summary / Approach / Current Work Load (25 maximum points)

Executive Summary – (7 maximum points) Submit a brief abstract stating the Proposer's understanding of the nature and scope of the services to be provided and capability to comply with all terms and conditions of RFQ (3 page maximum).

Approach – (9 maximum points) Discuss your approach for delivering this project. Discuss your firm's willingness and ability to meet the project's schedule and budget. Discuss the office location from which this work will be conducted and its distance from the project site. (5 page maximum).

Current Work Load Overall – (5 maximum points) Demonstrate your ability to perform this work given your current project workload. Provide a list of current projects for all clients including SBBC, Include all projects currently under contract and all projects where your firm has been selected but is not yet under contract. Include project construction value. (2 page maximum).

Current Work Load with SBBC - (4 maximum points) Provide a list of all projects with total fees for all active contracts with SBBC. Provide a list of all projects and total fees for all projects where your firm has been selected by SBBC but is not yet under contract. (2 page maximum). (Proposer with the most total fees on current projects will be awarded zero (0) points. Other proposers will be awarded up to 3 points based on current fees, with more points being awarded to proposers with the least amount of current fees with SBBC).

Design Services
Version Date: 06/20/16

RFQ - 17-065C Page 12 of 17

Section C2 Firm Experience and Qualifications (15 maximum points)

Provide a statement of your firm's qualifications to perform the services requested under this RFQ (3 page maximum).

Section C3 Relevant Projects / References (15 maximum points)

Provide a list and description of relevant projects (maximum of 5) successfully completed by your firm in the most recent five (5) years. For each project, include:

- Name and location of project
- Scope of work that was performed by your firm
- Summary of the project scope including construction delivery method
- Name, title and contact information for client
- Initial and final construction cost (where not deemed confidential)
- Change order percentage by type, including errors and omissions
- Planned design schedule vs actual design schedule

Include 3 references with contact information, preferably from one of the projects requested above (5 pages maximum for Section C3).

4.2.5 <u>Section D – Team Composition:</u> (35 maximum points)

Section D1 Team Structure (10 maximum points)

Describe the structure of your team, including all subconsultants. Indicate which professional design services the prime firm offers with in house staff, and indicate which professional design services the firm may opt to utilize consultants. Refer to Attachment E. (3 pages maximum. Attachment E does <u>not</u> count toward page limits)

Section D2 Key Personnel (25 maximum points)

Design Professional's Staff (15 maximum points)

Provide the names of the Design Professionals staff intended for use on SBBC Projects, including applicable professional qualifications. Identify the Principal to be in charge of SBBC Projects. Identify other key personnel as appropriate, including the Senior Architect and primary production Architect. Not all staff personnel need to be listed. It is understood that staffing requirements will vary from project to project based on project scope and required design time frame. Refer to Attachment B. Resumes for key personnel should be provided.

Consultants' Staffing (10 maximum points)

For each Consultant, provide the names of the Consultants Staff intended for use on SBBC Projects, including professional qualifications. Identify the Principal to be in charge of SBBC Projects. Identify a Senior Engineer for each of the disciplines that each Consultant performs. Refer to Attachment B. Resumes for key personnel should be provided.

NOTE: Section E below shall be evaluated and scored by District Staff (not QSEC)

4.2.6 Section E - Supplier Diversity and Outreach Program (10 maximum points)

Design Services Version Date: 06/20/16

RFQ - 17-065C Page 13 of 17

Section E1 M/WBE Firms for Intended Use (10 maximum points)

Identify the M/WBE firm or firms who may be working with you on this engagement utilizing Attachment A, M/WBE Participation.

Page 14 of 17

RFQ - 17-065C Design Services

Version Date: 06/20/16

SECTION 5.0 - EVALUATION OF QUALIFICATIONS

5.1 Evaluation of Qualifications - The Evaluation Committee shall evaluate all Qualified Proposals by the following Categories.

<u>SECTION</u>		POSSIBLE POINTS
Section A – General		Pass/Fail
Section B – Required Forms		Pass/Fail
Section C - Experience and Qualifications Section C 1 - Executive Summary / Approach / Curre Section C 2 - Firm Experience and Qualifications Section C 3 - Relevant Projects / References	ent Work Load	0 to 25 0 to 15 0 to 15
Section D - Team Composition Section D 1 – Team Structure Section D 2 – Key Personnel		0 to 10 0 to 25
Section E - Supplier Diversity & Outreach Progra Section E 1 - M/WBE Participation	<u>m</u>	0 to 10
	TOTAL POSSIBLE POINTS	100

5.1.1 Scoring of M/WBE Participation – Section E1

NOTE: Section E below shall be evaluated and scored by District Staff (not QSEC)

The SBBC shall award a maximum of ten (10) points for M/WBE Participation as listed in the Evaluation Point Tables below. At the time the proposal is submitted, the proposer shall identify all M/WBE firms (if any) which will be utilized by using the M/WBE Participation Form and Statement of Intent Form. The Letter of Intent submitted with the proposal reflects the intent of the parties (prime and sub-consultant) to establish a business relationship as well as the type of work and percentage of work that the sub-consultant will perform.

5 Points For M/WBE Designer	
M/WBE Designer	5.0 Points

5 Points For M/WBE Sub-Consultant Participation		
≥ 25%	5.0 Points	
≥ 20%	4.0 Points	
≥ 15%	3.0 Points	
≥ 10%	2.0 Points	
≥ 5%	1.0 Points	

NOTE: Points for Category E shall be provided by the M/WBE Coordinator for use by QSEC members.

5.2 Qualification Selection Evaluation Committee ("QSEC") members shall rank proposers based on the total number of points received from QSEC committee member scoring, The proposer receiving the most total points received from all QSEC members

shall be considered to be the most qualified proposer ("Firm 1"). All remaining proposers shall be ranked in order based on total points received from all QSEC members (Firm 2, Firm 4, and etc.).

- 5.2.1 The first tie-breaker between identically scored proposers shall be the total number of times the applicable proposers are ranked as the most qualified (Firm 1) by individual QSEC committee members.
- 5.2.2 The second tie-breaker between identically scored proposers shall be the total number of times the applicable proposers are ranked as the second most qualified ("Firm 2") by individual QSEC committee members.
- 5.2.3 The third tie-breaker between identically scored proposers shall be the total number of times the applicable proposers are ranked as the **third most qualified** ("Firm 3") by individual QSEC committee members.
- 5.2.4 The fourth tie-breaker shall be a coin flip, to be called in the air, by the <u>tied</u> proposer who held its discussions with QSEC first.
- 5.3 Failure strictly comply with the submittal requirements of sections A and B may result in a recommendation to reject the proposal.
- After scoring has been completed, QSEC shall recommend that District staff negotiate a contract for professional design services with Firm 1 at compensation which staff determines is fair, competitive, and reasonable.
 - 5.4.1 Should staff be unable to negotiate a satisfactory contract with Firm 1, negotiations with Firm 1 shall be formally terminated.
 - 5.4.2 Staff shall then undertake negotiations with Firm 2. Should staff be unable to negotiate a satisfactory contract with Firm 2, staff shall formally terminate negotiations with Firm 2, and then undertake negotiations with Firm 3.
 - 5.4.3 This process shall continue with the remaining, most qualified firms until a satisfactory contract is negotiated. If no negotiations are successful, the procurement shall automatically terminate.
- After successful negotiations with the applicable proposer, an Agreement shall be submitted to the Board for approval and award of a Design contract.
- 5.6 <u>Award:</u> The Agreement resulting from these negotiations shall be governed by the laws of the State of Florida, and shall have venue established in the 17th Court of Broward County, Florida or the United States Court of the Southern District of Florida.

END OF EVALUATION OF QUALIFICATIONS

SECTION 6.0 - PROJECT SCOPE AND SCHEDULE

6.1 <u>Summary Project Scope</u> - The Scope of Work is summarized below.

Tedder Elementary School

- Fire Sprinklers
- Fire Alarm
- PE/Athletic Improvements
- HVAC Improvements
- Building Envelope Improvements

6.2 Project Budget - The Budget for this package is as follows.

Tedder Elementary School

Total Funds from District's approved ADEFP: \$ 3,433,000

Less:

- School Choice, Technology \$ 245,000

Total Project Budget \$ 3,188,000

Less:

- Other Owner Costs \$ 159,400

TOTAL Design, Construction and Soft Cost Funds \$ 3,028,600

6.3 <u>Project Schedule</u> - The Schedule for this project is as follows:

Authorization to Proceed January 10, 2017 Completion of Design October 6, 2017 Final Completion – Construction December 12, 2018

END OF RFQ

M/WBE PARTICIPATION

Complete the following information on the proposed M/WBE participation on this contract.

Proposer's Company Name:	
--------------------------	--

M/WBE Firm Information	Scope and/or Nature of Work to be Performed by the M/WBE	% of M/WBE Participation
Firm Name:		
Contact Person:		
Address:		
Telephone No.:		
Facsimile No.:		
M/WBE Certification No.:		
Certifying Agency Name:		
Address:		
Telephone No.:		
Firm Name:		
Contact Person:		
Address:		
Telephone No.:		
Facsimile No.:		
M/WBE Certification No.:		
Certifying Agency Name:		
Address:		
Telephone No.:		
Firm Name:		
Contact Person:		
Address:		
Telephone No.:		
Facsimile No.:		
M/WBE Certification No.:		
Certifying Agency Name:		
Address:		
Telephone No.:		

Note: percentage amount needs to be provided to receive points.

School Board of Broward County MWBE Forms Revised 12/1/15

Design and Professional Consulting Staff

Prime Firm:

Name	Title	Role	Time Commitment	Florida professional license	Email Address

Subconsultant:

Name	Title	Role	Time Commitment	Florida professional license	Email Address

Subconsultant:

Name	Title	Role	Time Commitment	Florida professional license	Email Address

Subconsultant:

Name	Title	Role	Time Commitment	Florida professional license	Email Address

ATTACHMENT C

Professional Services Agreement

PROFESSIONAL SERVICES AGREEMENT

BETWEEN

THE SCHOOL BOARD OF BROWARD COUNTY, FLORIDA

AND

PROJECT CONSULTANT

FOR

ARCHITECTURAL/ENGINEERING SERVICES

	SAGREEMENT, made this, day of in the year, by and between
THE	SCHOOL BOARD OF BROWARD COUNTY, FLORIDA, hereinafter called the "Owner", and
herea	fter called the "Project Consultant" for the following project:
	Facility:
	Site No.:
	Project Name:
	Project No:
	Fixed Limit Of Construction Cost (FLCC): \$
TT1 6	
The (wher and Project Consultant agree as follows:

TABLE OF CONTENTS

ARTICLE 1	DEFINITIONS

- ARTICLE 2 PROJECT CONSULTANT SERVICES AND RESPONSIBILITIES
- ARTICLE 3 SUB-CONSULTANTS
- ARTICLE 4 THE OWNER'S RESPONSIBILITIES
- ARTICLE 5 BASIS OF COMPENSATION
- ARTICLE 6 PAYMENTS TO THE PROJECT CONSULTANT
- ARTICLE 7 REUSE OF DRAWINGS, SPECIFICATIONS AND OTHER DOCUMENTS
- ARTICLE 8 INDEMNIFICATION
- ARTICLE 9 INSURANCE
- ARTICLE 10 GENERAL PROVISIONS
- ARTICLE 11 INCORPORATION OF DOCUMENTS INTO AGREEMENT

ATTACHMENTS:

Attachment 1: Project Schedule Attachment 2: Project Scope

Attachment 3: Electronic Media Submittal Requirements

Attachment 4: Project Consultant's Invoice Format, Reimbursable and Supplemental Services Format

Attachment 5: List of Project Team Members

Attachment 6: Authorization to Proceed (ATP) Form

Professional Services Required – page 1 of 3

Project Schedule – page 2 of 3 Professional Fee – page 3 of 3

Attachment 7: Document Submittal Checklist

Attachment 8: Document 00455 – Background Screening

Attachment 9: IRS Form W-9

Attachment 10: Truth in Negotiations Certificate

ARTICLE 1 DEFINITIONS

- The Office of Facilities & Construction ("Office" or "OFC"): The Owner's organizational entity which acts as liaison between the Consultant and Owner and provides day to day management and other professional services on the Owner's behalf. Various members of the Office of Facilities and Construction, acting as representatives of the Owner, will meet with the Project Consultant at periodic intervals throughout the preparation of the Contract Documents to assess the progress of the Work in accordance with approved schedules. Office personnel will also examine documents submitted by the Project Consultant, including invoices, and will promptly render decisions and/or recommendations pertaining thereto to avoid unreasonable delay in the progress of the Project Consultant's work. The Project Manager shall be principally responsible for direct communication to the Project Consultant and the Contractor.
- 1.2 **The Chief Facilities & Construction Officer, Office of Facilities & Construction -** An employee of The School Board of Broward County, Florida, who has the authority and responsibility for oversight and management of the specific project for the Owner. Referred to hereinafter as the Chief Facilities & Construction Officer.
- 1.3 **Authorization to Proceed:** A fully executed and approved authorization in the form of Attachment 6 to this Agreement, Authorization to Proceed ("ATP") accompanied by an executed purchase order document issued by the Owner to the Project Consultant, authorizing the performance of specific professional services, authorizing commencement of a Phase as defined in Article 2.1 through Article 2.8, and stating the time for completion and the amount of fee authorized for such services.
- 1.4 **Basic Services**: Those architectural, engineering and other professional design services defined in Article 2.1 through Article 2.8.
- 1.5 **Supplemental Services**: Those architectural, engineering and other professional design services defined in Article 2.9.
- 1.6 **Project Consultant:** The individual, partnership, corporation, association, joint venture, or any combination thereof, of professional architects, engineers or other design professionals properly registered and licensed in Florida, who has entered into a contract with the Owner to provide professional services for development of the design and contract documents for the Work of this Project and provide construction contract administration and warranty services as described in the Project Manual and under this Agreement.
- 1.7 **Project Scope**: The activities necessary to respond to the Owner's requirements for the Project, including but not limited to the full or partial range of design, bidding and construction support services required to meet

- the Owner's educational program, construction standards, project construction support requirements, Project Budget and Project Schedule.
- 1.8 **Project Budget**: The sum, established by the Owner, as available for the entire Project, including but not limited to the construction budget (Fixed Limit of Construction Cost ("FLCC")), land costs, costs of furniture, fixtures and equipment (FF&E), financing costs, compensation for all professional services, costs of Owner-furnished goods and services, contingency allowances and other similar established or estimated costs.
- 1.9 **Project Schedule**: The Owner's requirements for the progress of design and construction activities associated with the Project characterized by milestones signifying the required completion dates for design phases, construction progress, and other significant project events culminating with the completion of the project, issuance of warranties, Owner's occupancy and use of the new or improved facilities.
- 1.10 **The Contract Documents:** The Contract Documents as used herein refer to the Agreement Form, Addenda, Supplementary Conditions, General Conditions, Documents contained in the Project Manual, the Owner's Division 0 and Division 1 documents, Drawings, Specifications, Education Specifications, all modifications thereto, issued before and after execution of the Contract and all Exhibits attached thereto used by the Owner to establish a construction contract with the Contractor. These Contract Documents, and their requirements for the Project Consultant are incorporated by reference into this Agreement.
- 1.11 **Contractor:** The individual, partnership, corporation, association, joint venture, or any combination thereof, who has entered into a contract with the Owner for construction of schools, administrative and support buildings, or various other types of facilities and incidents thereto.
- 1.12 **Program Manager:** An entity hired by the School Board of Broward County to execute the delivery of the projects and act as the Owner's Representative.
- 1.13 **Project Manager**: An employee or designated representative of The School Board of Broward County, Florida, who is assigned by the Chief Facilities and Construction Officer to manage the Project as a direct representative of the Owner.
- 1.14 **The Project:** The design of new construction, remodeling and/or renovation, and all services and incidents thereto, comprising a structure, structures, facility or facilities as contemplated and budgeted by the Owner.
- 1.15 **Sub-Consultant:** A person or organization of professional architects, engineers or other design professionals, registered and licensed in Florida, who has entered into an Agreement with the Project Consultant to provide professional services for the project.
- 1.16 **Superintendent Of Schools:** The duly appointed executive officer of the Owner authorized to act by and through The School Board of Broward County, Florida. Referred to hereinafter as the Superintendent.
- 1.17 **Fixed Limit of Construction Cost:** The Fixed Limit of Construction Cost, referred to hereinafter as the FLCC, is the total dollar value of the sum of the project's anticipated base bid (the project's essential scope) including design contingency.
- 1.18 **Building Code Inspector and Plans Examiners (BCI):** Employees of The School Board of Broward County, Florida, and others designated by the Chief Building Official, who are certified by Florida Statutes 468, 633 and 553 a BCI by the Florida Department of Education to provide plan review, inspections for code compliance and report non-compliant work to the appropriate party.

- 1.19 **Value Engineering:** Value Engineering (VE) is the creative, organized process of analysis of a project as to cost and/or performance with a focus on analysis of the proposed facility (and its systems, assemblies or components) and the elimination or modification of those features which add cost without contributing to that facility's required function or design value.
- 1.20 **Constructability:** Constructability is the creative, organized process of reviewing a project's drawings, specifications and other project documentation with a goal of eliminating design, detailing, and specification problems which might render the construction contract documents unbuildable or requiring extensive Addenda or Change Orders to make them buildable.
- 1.21 **The Project Team** The Owner, Program Manager, and the Project Consultant, collectively the "Project Team", shall work jointly during the design and through the completion of the warranty phase and shall be available thereafter should additional services be required.
- 1.22 **Substantial Completion:** The term Substantial Completion as used herein, shall mean that point at which the Work, or a designated portion thereof, is at a level of completion in substantial compliance with the Contract Documents such that the Owner or its designee can enjoy use or occupancy and can use or operate it in all respects for its intended purpose. In the event the Work includes more than one Phase, the Owner, at its discretion, may set Substantial Completion dates for each Phase and may impose provisions for liquidated damages for each Phase.
- 1.23 **Chief Building Official, Inspections and Code Compliance:** ("CBO") An employee of The School Board of Broward County, Florida, who has the responsibility for oversight and management of the Building Department, and has the authority and responsibility for issuing Building Permits.
- 1.24 Code: The term Code means and refs to all applicable codes, laws and regulations of each governmental entity, as may be amended from time to time, in effect at the time of execution of this Agreement, including all codes and standards referenced therein, including, but not limited to:, the Fifth Edition of the 2014 Florida Building Code (the "FBC"), the Fifth Edition of the Florida Fire Prevention Code, Chapter 1013, Florida Statutes (2015)Florida State Board of Education Regulations ("SREF"), Chapter 6A-2.0111 (Educational Facilities), the 1999 State Requirements for Educational Facilities (2014)Florida Department of Education's State Requirements for Educational Facilities ("SREF")adopted pursuant to Rule 6A-2.0111, Florida Administrative Code, as may be amended from time to time, to the extent such requirements are not in conflict with Section 235.211, Florida Statutes 1995, Americans With Disabilities Act (ADA), in effect at the time of execution of this Agreement, and its referenced codes and standards; Crime Prevention Through Environmental Design (CPTED) (Broward Sheriff's Office), and all guidelines and regulations of the Owner (provided same are not less stringent than applicable codes) with the Owner serving as the interpreter of the intent and meaning of SREF or any other applicable code

ARTICLE 2 PROJECT CONSULTANT SERVICES AND RESPONSIBILITIES

- 2.1 Basic Services
- 2.1.1 The Project Consultant agrees to:

- .1 Provide complete professional architectural, engineering and/or other professional design services set forth in the six Phases enumerated hereinafter and all necessary personnel, equipment and materials to perform such services;
- .2 Complete those design services in accordance with the Project Schedule (Attachment 1 to this Agreement).
- .3 Collaborate in the Owner's programs of Value Engineering at the end of Phases I and II (Schematic Design and Design Development), Constructability Reviews at the end of Phase III (Construction Documents), Statement of Probable Construction Cost at end of each phase, SIT Award Application and other additional basic services as provided in Article 2.1 through Article 2.8.
- 2.1.2 Standard Of Care: The Owner's engagement of the Project Consultant is based upon the Project Consultant's representations to the Owner that:
 - .1 It is an organization of experienced design professionals, registered and licensed to do business in Florida;
 - .2 It is qualified, willing and able to perform architect and engineer of record services for the Project; and that
 - .3 It has the past experience and ability to provide design and engineering services for projects of similar size and scope which will meet the Owner's objectives and requirements.
- 2.1.3 As to all services provided pursuant to this Agreement, the Project Consultant shall furnish services by experienced personnel and under the supervision of experienced professionals licensed in Florida, and shall exercise a degree of care and diligence in the performance of these services in accordance with the customary professional standards currently practiced by firms in Florida and in compliance with any and all applicable codes, laws, ordinances, etc. The Project Consultant shall utilize the same personnel over the course of the Work and shall, if requested by the Owner, replace personnel whom the Owner has found to be incompetent or to whom the Owner otherwise reasonably objects.
- 2.1.4 As to any and all drawings, plans, specifications or other contract documents or materials provided or prepared by Project Consultant or its Sub-Consultants, the Project Consultant agrees same:
 - .1 Are sufficiently complete, accurate, and adequate for bidding, negotiating and constructing the Project and are consistent with the Owner's requirements and Owner approved Project Budget and Project Schedule;
 - .2 Meet the Owner's aesthetic, functional and operational objectives;
 - .3 Are sufficiently fit and proper for the purposes intended;
 - .4 Comply with all applicable laws, statutes, rules and regulations, building codes and Owner's guidelines or regulations, which apply to and govern the Project, and
 - .5 Will, if constructed in accordance with the Project Consultant's Design, result in a complete and properly functioning facility. Any defective drawings, specifications or other document furnished by

Project Consultant shall be promptly corrected by the Project Consultant at no cost to Owner, without limitations to other remedies or rights of Owner. Owner's approval, acceptance or use of or payment for all or any part of Project Consultant's services hereunder or of the project itself shall in no way alter the Project Consultant's obligations or Owner's rights hereunder.

- .6 Further, any approval of drawings or construction documents by Owner and/or other governmental entities having jurisdiction which do not expressly comment and/or interpret a building code requirement shall not relieve the Project Consultant from its obligations to furnish design services pursuant to the applicable building codes nor be the basis for a waiver defense should Owner accept and/or approve any drawings and/or contract documents wherein an error or omission is not discovered during the design process.
- 2.1.5 All professional design services and associated products or instruments of those services provided by the Project Consultant shall:
 - Be in accordance with all applicable codes, laws and regulations of each governmental entity, as may be amended from time to time, in effect at the time of execution of this Agreement, including all codes and standards referenced therein, including, but not limited to: the Fifth Edition of the 2014 Florida Building Code (the "FBC"), the Fifth Edition of the Florida Fire Prevention Code, Chapter 1013, Florida Statutes (2015), the State Requirements for Educational Facilities (2014) ("SREF"), Crime Prevention Through Environmental Design (CPTED) (Broward Sheriff's Office), and all guidelines and regulations of the Owner (provided same are not less stringent than applicable codes) with the Owner serving as the interpreter of the intent and meaning of SREF or any other applicable code (all of the above-referenced codes, laws, regulations and standards referenced therein are herein collectively referred to as "Code");
 - .2 Be provided for the benefit of the Owner and not for the benefit of any other party; and
 - .3 Include all of the design services normally required for a project of this type as listed in the Project Scope (Attachment 2 to this Agreement).
 - .4 Notwithstanding any other provisions of this Agreement to the contrary, any substantially affected person may appeal any building code dispute or interpretation of the Chief Building Official of the School Board of Broward County, Florida to the Florida Building Commission as set forth in section 1013.37, Florida Statutes and the FBC, as amended.
- 2.1.6 The Project Manager shall schedule and conduct a bi-weekly project review meeting with representatives of the Project Consultant throughout Phases I through IV of the Project. At each of these meetings, the Project Consultant and Owner shall review the Project's budget, schedule, and scope along with the Project Consultant's development and progress to date on the respective phases of the Project and any special problems related to the continuing progress of the project. The Project Consultant shall attend weekly meetings during Phase V (Construction) as required elsewhere in this Agreement. For each project review meeting, and as may be otherwise appropriate during any project phase, the Project Consultant shall provide progress sketches and other documents sufficient to illustrate progress and the issues at hand for the Owner's review, which will be made so as to cause no delay to the Project Schedule.
- 2.1.7 The Project Consultant's services shall conform to Owner's specifications, including but not limited to, Owner's Design and Materials Standards Manuals, Design Criteria, Educational Specifications, Document

Submittal Checklist for Plan Review and Owner's Forms for capital projects, provided, however, that in the event of conflict, the provisions of this Agreement shall govern.

- Non-Conforming Work: If the Owner (by way of BCI's or other Owner personnel or consultant) observes or otherwise becomes aware of any fault or defective Work in a project, or other non-conformance with the Contract Documents during the construction phases, the Owner or Program Manager shall give prompt notice thereof to the Project Consultant. However, whether the Owner observes a defect or not, it is the Project Consultant's duty and responsibility to determine whether said Work is defective, faulty, or not in compliance with the Contract Documents. If the Project Consultant determines that the Work is defective, faulty or not in conformance with the Contract Documents, the Project Consultant shall advise the Owner in writing and make recommendations to the Owner concerning correction of the Work. The Owner may then require the Contractor to undertake such corrections as allowed by the Contract Documents. Final determination of whether the Work is defective, faulty or in compliance with the Contract Documents is to be determined by the Owner.
- .2 **Penalty for Non-Conforming Design Documents:** Should the Project Consultant submit drawings, plans, specifications or other documents or materials for review as required herein that are deemed unacceptable as defined by the terms "Revise and Resubmit" by the plan review authority (Building Department, Design Services Department, Peer Plan Review Consultant), the costs, as solely determined by the Owner, for all subsequent reviews after the second review for that Phase shall be borne by the Project Consultant and the Owner will deduct such costs from the Project Consultant's Basic Services Fee.
- 2.1.8 The Project Consultant shall keep the Owner informed of any proposed changes in requirements or in construction materials, systems or equipment as the drawings and specifications are developed. Proposed changes must be reviewed by the Owner and approved in writing by Owner prior to incorporation into the design or construction documents.
- 2.1.9 The Project Consultant shall coordinate with Owner by participating and taking a leadership role in, reviewing and commenting on Constructability and Value Engineering studies performed by Owner, and attending meetings, where the content of design and construction contract documents will be coordinated and reconciled, scheduled during any phase of the project. In the event Owner accepts recommendations from Value Engineering and Constructability studies, the Project Consultant shall implement same, including providing revised drawings and specifications or other documents. In the event the Owner accepts such a recommendation from the Constructability and/or Value Engineering studies and requires substantial revisions by the Project Consultant, as determined at the discretion of the Owner, these revisions shall be considered Supplemental Services.
- 2.1.10 **Approval of Documents**: Owner's approval of or comments on any of the documents submitted to Owner by Project Consultant shall not be deemed the approval of or by another governmental authority having jurisdiction over the project and Project Consultant acknowledges that the aforesaid authorities may require modifications of any of the documents submitted by Project Consultant. Subject to Article 2, such modifications shall be made at no cost to Owner.

2.2 PHASE I - Schematic Design:

- 2.2.1 The Project Consultant shall confer with representatives of the Owner to verify and confirm the Program (as appropriate to the type of project), consisting of a detailed listing of all functions and spaces together with the square footage of each assignable space, gross square footage, and a description of the relationships between and among the principal programmatic elements. (If the project needs are so unique that a special analysis of the requirements is necessary to establish a more detailed program, such services may be authorized as Supplemental Services).
- 2.2.2 The Project Consultant shall, prior to commencing Phase I design activities, receive a fully approved and executed ATP and Purchase order (See 5.2.3), visit and inspect the site to verify if existing conditions conform to those portrayed on information as may have been provided by the Owner:
 - .1 Take photographs and make written documentation, sketches, notes or reports to confirm and record the general condition and age of the existing equipment and site with particular attention to the following building/site elements as appropriate to the Project:
 - .1 All above ceiling areas.
 - .2 Power supplies, switch gear, breaker panels, electrical room, electrical vault, transformers and mechanical room.
 - .3 Major components of existing HVAC systems including chillers, cooling towers, air handling units, and primary ductwork runs.
 - .4 Roofing, waterproofing and building envelope systems.
 - .5 Site drainage systems and water retention characteristics.
 - .6 Determine age and condition of fixed equipment.
 - .7 Life safety, fire alarms, public address, generators and emergency lighting.
 - .8 ADA requirements.
 - .2 Site investigations and inspections and access to concealed areas should be non-destructive except where destructive investigations, tests or means of access are authorized in advance by the Owner.
- 2.2.3 In the event that the Project Consultant believes that the project scope, schedule or budget is not achievable, the Project Consultant shall immediately notify the Owner in writing as to the reasons one or all of them are unreasonable or not achievable immediately upon discovery.
- 2.2.4 The Project Consultant shall review with Owner alternative approaches to design and construction of the project; site use and improvements; selections of materials, building systems and equipment; potential construction methods; and, if requested, shall make a recommendation among such alternatives.
- 2.2.5 The Project Consultant shall prepare, submit and present to Owner for approval by the Owner a Design Concept and Schematics Report, comprised of the SREF requirements for Schematic Design Documents and Schematic Design Studies, including an identification of any special requirement(s) affecting the Project, a Project Development Schedule, and a Statement of Probable Construction Cost, as defined below:

- .1 "Project Transmittal Form" as required by the Facilities and Construction Management Division's Design Services Department.
- .2 OEF form 208(a) "OEF Space Chart Form" formatted to follow the sequence of spaces listed in the SREF Size of Space and Occupant Design Criteria Table.
- .3 A hardcopy and electronic media copy of a site survey with the following information: the legal description of the site, acreage, points of the compass, contours, overall dimensions, vegetation, trees, hardscape elements, adjacent highways and roads, information about ownership and use of adjacent land, locations of on- and off-site utility connections, utility service point entry locations, parking areas, service areas, play areas, athletic fields, bus loop(s), parent drop off, existing buildings with height, mechanical cooling towers and chillers, floor elevations (related to base flood elevation as shown on Flood Insurance Rate Maps), and use. The site survey will be an update of informational surveys provided by the Owner but shall be prepared on electronic media and submitted in both hard and electronic media formats. (Attachment 3 to the Agreement).
- .4 **Schematic Drawings.** These documents shall be schematic drawings responding to the educational specifications and program requirements illustrating the general scope, scale, and relationship of project components. In addition to SREF requirements and information required by the Owner's document submittal checklist for phase I, the documents shall include the following:
 - .1 A site plan showing acreage, points of the compass, scale, contours and general topographical conditions, flood plain elevation and velocity zone, over-all dimensions, adjacent highways, roads, off-site improvements, emergency access, fire hydrants, power transmission lines, ownership and use of adjacent land, walks and paths, vehicle and bike parking areas, accessibility for the disabled, service areas, play areas, athletic fields, bus loop(s), parent drop off, existing buildings and use, location of proposed building(s) and future additions, portable classrooms and other relocatable or temporary structures, community use buildings, phased construction, preliminary soil borings. A statement shall be included on the site plan identifying the FEMA flood plain and velocity zone in which the project is located. The statement shall be signed and dated by the Project Consultant.
 - .2 Evidence, as jointly developed with the Owner, showing that required environmental studies have been completed and sensitive site areas have been identified as required by Florida Law or the Owner or any governmental entity having jurisdiction over the project site.
 - .3 Floor plans showing points of the compass, over-all dimensions, identity of each space, proposed door locations, accessibility for the disabled, Florida Inventory of School House (FISH) numbers, occupant load of each space, proposed passive design and low energy usage features, possible community service areas and instructional spaces that can be converted to community use areas, mechanical and electrical rooms, any existing buildings and use, future additions, and phased construction. Provide a life-safety plan delineating the necessity for and initial decisions concerning exits, accessibility for the disabled, fire walls, protected corridors, smoke partitions, fire alarm systems, fire sprinkler systems, room names and numbers, and any other life-safety features relevant to the facility.
 - .4 Provide elevations and sections of the building to fully illustrate and indicate the mass and character of the facility including fenestration, openings, walkways, preliminary material selections, and other building features and spatial relationships.

- .5 A Preliminary Project Description comprised of a narrative discussion of preliminary material selections, components, assemblies, and systems (including proposed landscape, civil, structural, mechanical, and electrical design elements, components and systems) to be used in the project. Coordinate points of service and preliminary service requirements with Florida Power and Light (FPL), BellSouth, cable TV, water, sewer, storm drainage and other utility services as required by the Project's scope and program. Format Preliminary Project Descriptions to match that specified by the latest edition of the Construction Specification's Institute's "Manual of Practice".
- Mechanical Requirements Specific to Remodeling and Addition Projects: Provide a listing of capacities for existing HVAC equipment and the available tonnage for the new connected load. Provide a survey of the condition of the existing mechanical equipment.
- .7 Electrical Requirements Specific to Remodeling and Addition Projects: Provide an electrical load analysis for the existing facility for existing and new loads. Provide a survey of the condition of the existing electrical equipment and the communication equipment room.
- A **Project Design Schedule:** The Project Consultant shall prepare a schedule of services (Project Design Schedule) in compliance with Project Schedule and for approval by the Owner. Such schedule shall show activities including but not limited to Project Consultant efforts and Owner reviews and approvals required to complete services. This schedule shall initially be submitted to Owner for approval within twenty-one (21) days of execution of this Agreement. As a condition of payment, Project Consultant will submit with each invoice a copy of the approved schedule showing progress (indicated by percentage complete) as of the invoice cutoff date and a forecast of when each phase of Project Consultant's work will be complete. No subsequent payment shall be made if Project Consultant has not obtained approval of his work schedule, the schedule is not updated, or a forecast is not submitted with each invoice (provided that Owner conducts its review promptly and does not withhold its approval unreasonably). The project development schedules shall set forth in detail the following:
 - .1 Include all activities required to complete the design phase of the project.
 - .2 Prepare in a bar chart format, or other format as required by the Owner, which may be further developed and updated for submittal during subsequent phases of the Basic Services.
 - .3 The Project Consultant shall not be permitted to deviate from the milestones indicated on the Project Schedule without specific written authorization from the Owner (Attachment 1 of this Agreement).
- .9 The Statement of Probable Construction Cost: The Consultant shall submit to Owner for review and Owner's approval a schematic design phase estimate of probable construction cost prepared by an independent cost estimator approved by Owner, itemized by major categories and projected to the expected time of bid.
- .10 Twenty-five (25) copies of a Design Concept and Schematics Report which will be utilized to communicate the schematic design and shall include: Reduced color drawings (Site and building plans, elevations, sections, sketch perspectives and miscellaneous diagramming), photographs of massing and building models, a facilities list (including the number of spaces, net/gross square footages, etc.), the Project Development Schedule, and a summary design statement indicating the general design intent, conceptual development, and preliminary material, assembly and system

selections. Provide brochure with heavy stock covers and plastic comb or metal spiral binding. Additional copies of the Schematic Design Brochure if required by the Owner will be compensated as a reimbursable service approved in advance by the Owner.

- 2.2.6 The Project Consultant shall coordinate with the assistance of the Owner to determine the municipal, county and other jurisdictional agency (such as the South Florida Water Management District, etc.) coordination required for the Project and, make applications for site plan and other review as appropriate to this phase of the project. The Project Consultant shall attend and provide representation at all review meetings, workshops, hearings and Commission/Council meetings concerning the project as conducted by any and all other agencies having jurisdiction over the project.
- 2.2.7 The Project Consultant shall submit seven (7) copies of all full size documents required under this Phase, and a completed document submittal checklist, without additional charge, for review and approval by the Owner. The Project Consultant shall not proceed with the next Phase until the completion of all required presentations and reports and receipt of a written Authorization to Proceed with the next phase.
- 2.2.8 The Project Consultant shall provide presentations of the Schematic Design to the Owner's staff, Design Review Committee and to The School Board of Broward County, Florida, as required.

2.3 Phase II - Design Development:

- 2.3.1 Only after receiving a fully approved and executed ATP and Purchase order (See 5.2.3), from Owner and based on the approved Schematic Design Documents and any adjustments authorized by Owner in the Project Scope, Project Schedule or Project Budget, the Consultant shall prepare, submit and present for review and approval by the Owner, Design Development Phase documents, comprised of the SREF requirements for Design Development documents and the following:
 - .1 "Project Transmittal Form" as required by the Facilities and Construction Management Division's Design Section.
 - .2 OEF form 208 (a) "OEF Space Chart Form" formatted to follow the sequence of spaces listed in the SREF Size of Space and Occupant Design Criteria Table.
 - .3 **Documents:** These documents shall be design development drawings corresponding to the educational specifications and program requirements illustrating the general scope, scale, and relationship of project components. In addition to Phase I requirements, SREF requirements, and information required by the Owner's document submittal checklist for phase II, the documents shall include the following:
 - .1 Architectural and Civil site plan(s) showing, in addition to Phase I site survey requirements, landscaping, drainage, water retention ponds, sewage disposal and water supply system, chilled water supply and return piping and such physical features that may adversely affect or enhance the safety, health, welfare, visual environment, or comfort of the occupants.
 - .2 A statement, signed and dated by the Project Consultant or his designated Sub-Consultant, included on the site plan identifying the number of existing trees, the number and size of required trees, and the number of new trees to be planted.

- .3 Soil testing results including a copy of the Geotechnical Engineer's report on the site. When unusual soil conditions or special foundation problems are indicated, submit the proposed method of treatment.
- .4 Plan(s) including, but not be limited to, the following:
 - .1 Floor plan drawn at an architectural scale that will allow the entire facility to be shown on one sheet, without break lines and which indicates project phasing as applicable to the Project.
 - .2 Floor plans drawn at 1/8 inch or larger scale showing typical student occupied spaces or special rooms with dimensions, sanitary facilities, stairs, elevators, and identification of accessible areas for the disabled.
 - .3 Floor plans drawn at 1/4 inch or larger scale showing typical spaces or special rooms with dimensions, equipment and furnishing layouts.
 - .4 Floor plans for additions to an existing facility: Indicate the connections and tie-ins to the existing facilities, including all existing spaces, exits, plumbing fixtures and locations, and any proposed changes thereto. Distinguish between new and existing areas for renovation, remodeling, or an addition.
 - .5 Floor plans drawn at 1/4 inch or larger scale showing typical spaces or special rooms with dimensions, indicating door and window layouts.
 - .6 Reflected ceiling plans drawn at 1/4 inch or larger scale showing typical spaces or special rooms with dimensions, lighting equipment and ceiling panel layouts.
 - .7 Roof plans drawn at 1/4 inch or larger scale showing typical spaces or special rooms with dimensions, equipment layouts.
- .5 Life-safety plans to show exit strategy, rated doors, emergency wall openings, fire walls working stage protection, range and fume hoods, eye wash, emergency showers, ramps and vertical lifts.
 - .1 By symbol, indicate fire extinguishers, fire alarm equipment, smoke vents, master valves and emergency disconnects, emergency lighting, emergency power equipment, fire sprinklers, exit signs, smoke and fire dampers, and other life-safety equipment relevant to the facility.
 - .2 By symbol, indicate connections and tie-ins to existing equipment.
 - .3 For existing facilities where remodeled or renovated spaces are required and where an ADA and code conforming ramp cannot be utilized, document proposed vertical platform lifts or inclined wheelchair lifts and provide the following documents as part of or in addition to the required life safety plans:
 - .1 Sketches of proposed vertical platform lifts, including layout drawings showing the effect of the lift on existing spaces, corridor widths and exiting from the affected facility.

- .2 Sketches of proposed inclined wheel chair lift including layout drawings showing the effect of the lift on the stairway width in the folded and unfolded position, the upper and lower platform storage locations, and the effect on exiting from the affected areas of the facility.
- .6 When planning open space schools or administrative spaces, a floor plan shall be submitted showing the methods used to permanently define the means of egress, such as surface finish or color.
- .7 Plumbing fixture locations and fixture unit calculations.
- .8 All exterior building elevations and sufficient building sections as necessary to fully illustrate and indicate the scale and massing of the facility.
- .9 Typical building sections to show dimensions, proposed construction materials, and relationship of finished floor to finished grades.
- .10 Preliminary Structural Drawings including plans and sections indicating systems, connections and foundations. These drawings may be structural roughs.
- .11 Mechanical Drawings including reflected ceiling plans and a single line diagram of the duct layout, location of grease trap(s), LP gas tank location, and natural gas pipe lay out, tie in to existing utilities. Enhance systems description to include a description of proposed HVAC system equipment including the chiller, pumps, AHU's, cooling tower, electric duct heaters, etc.
- .12 Electrical Drawings including reflected ceiling plans, lighting layouts for the outdoors and interior spaces, and a one line diagram of the electrical distribution showing electrical outlets for all systems in all spaces. Provide layout for energy management, computer networking and security systems. Location of all the main components of the electrical system such as transformers, panels, and main switch board, and emergency generator, location of the intercom console, ITV head end and tower, master clock, fire alarm panel. Also, show locations of mechanical equipment such as chillers, air handler units, etc. and their respective electrical connections.
- .13 **Equipment and Furnishing Schedules:** Indicating equipment and furnishing items that will be provided by the Contractor and those that will be provided by the Owner or others.

.14 **Outline specifications:**

- .1 Organized according to the Specification Section numbering system specified in the Construction Specifications Institute's current edition of Masterformat on the date of execution of the Contract.
- .2 Formatted to conform to the formats for outline specifications as established by the Construction Specifications Institute.
- .3 Complete for Divisions 2 through 17 giving general description of all finishes, materials, and systems including civil, structural, HVAC, electrical, plumbing, and specialty items, including fire sprinklers, alarm systems, electronic controls and computer networking components.
- .15 Office of Educational Facilities Life-Cycle Cost Analysis (LCCA). LCCA shall be submitted to the Owner for review and approval with the Phase II documents. LCCA shall be by a commercially available life-cycle cost analysis program, and as required by the Department of Education and the

Owner. Life Cycle Cost Analysis shall be compared among competing providers in accordance with Ch. 1013.451, Florida Statutes.

- .16 Florida Energy Efficiency Code for Building Construction (FEEC). FEEC forms, including calculations for mechanical systems, documenting energy efficiency ratio rating of HVAC equipment, electrical systems, insulation, and building envelope shall be submitted to the Owner for review and approval with the Phase II documents.
- .17 The Project Consultant shall advise Owner of any adjustments to the Schematic Design Phase estimate of probable construction cost and shall submit to Owner a fully detailed Design Development Phase estimate of probable construction cost, by an independent cost estimator approved by Owner, projected to the expected time of bid and containing sufficient detail to provide information necessary to evaluate compliance with the Project Budget set for this project. Format estimate and provide detail matching the organization and content of the project's Outline Specifications complete for Divisions 2 through 17 including all finishes, materials, and systems including civil, structural, HVAC, electrical, plumbing, and specialty items, including fire sprinklers, alarm systems, electronic controls and computer networking components.

Utilize the current edition of MasterFormat as published by the Construction Specifications Institute to organize the estimate.

- An updated Project Design Schedule reflecting development and anticipated schedules for all subsequent project activities.
- .19 A written response from the Project Consultant and each of the major technical disciplines and any necessary Sub-Consultants explaining how each previous review comment (as generated by the Owner and/or other reviewing agencies) concerning the project have been addressed and/or corrected.
- A simplified single line floor plan of the project; a database format schedule reflecting the room numbers; the name of the room or space; the net square footage of the space and the capacity of the space on electronic media conforming to the Owner's standards for graphics and for electronic media submittals. This drawing and database information will be for use in preparing F.I.S.H. (Florida Inventory of School Houses) information. The Project Consultant shall coordinate with and utilize the Owner's F.I.S.H requirements for room numbers, room name assignments and electronic media (format, layering, etc.) prior to developing final documents for this submittal. Hardcopy graphics shall be suitable for clearly legible half size reductions. Comply with the Owner's requirements for electronic media specified below.
- .21 A letter indicating, after coordination with the Facilities and Construction Management Division's Environmental Section, the extent of any known or suspected asbestos containing materials or other potentially hazardous materials which might require mitigation by the Owner prior to or during construction of the Project. Establish and confirm responsibility for removing the asbestos or other hazardous materials in the design development documents and coordinate with Project Development Schedule, Statement of Probable Construction Cost and other documentation.
- .22 Preliminary colorboards to review the color selections for all finish materials with the Owner.

- .23 Twenty-five (25) copies of a Design Development Brochure which will be utilized to communicate the design as developed to date and shall include updated and enhanced contents of those brochures required at the Schematic Design Phase complete as necessary to illustrate the developed design, schedules, etc. Additional copies of the Design Development Brochure if required by the Owner will be compensated as a reimbursable service approved in advance by the Owner.
- 2.3.2 Staff from each of the Project Consultant's major technical disciplines and Sub-Consultants as necessary shall attend coordination, review and presentation meetings with the Owner to explain the design concept and technical resolution of their respective building or site systems.
- 2.3.3 The Project Consultant shall submit seven (7) sets of all documents required under this Phase (except as otherwise indicated), without additional charge, for review and approval by the Owner, and the Project Consultant shall not proceed with the next Phase until the completion of all required presentations and reports and receipt of a written Authorization to Proceed with the next phase.

2.4 Phase III - Construction Documents Development:

- 2.4.1 Only after receiving a fully approved and executed ATP and Purchase order (See 5.2.3) from Owner and based on the approved Design Development Phase documents and any adjustments in the scope or quality of the project or in the Fixed Limit of Construction Cost authorized by Owner, the Project Consultant shall prepare for approval by Owner and the Florida Department of Education, and in accordance with SREF requirements and the Owner's formats, Final Construction Documents setting forth in detail the requirements for the construction of the Project. The Project Consultant is responsible for the full compliance of the design with all applicable codes.
- 2.4.2 **50% Construction Documents Submittal:** The Project Consultant shall make a 50% Construction Documents submittal, for review and approval by the Owner, which shall include seven (7) sets of the following:
 - .1 "Project Transmittal Form" as required by the Facilities and Construction Management Division's Design Section.
 - .2 An updated OEF form 208(a) "OEF Space Chart Form" formatted to follow the sequence of spaces listed in the SREF Size of Space and Occupant Design Criteria Table.
 - .3 Updated Florida Energy Efficiency Code for Building Construction (FEEC) compliance forms. Submit seven (7) copies signed and sealed by a State of Florida registered design professional with 50% Contract Documents submittal.
 - .4 **Preliminary calculations:** Provide preliminary calculations for structural, mechanical and electrical systems.
 - .5 Drawings: These documents shall be 50% construction drawings corresponding to the educational specifications and program requirements illustrating the general scope, scale, and relationship of project components. In addition to Phase II requirements, SREF requirements, and information required by the Owner's document submittal checklist for phase III 50%, the documents shall include the following:
 - .1 Site Plan(s) and detailing which, in addition to the Phase II requirements, indicate:

- .1 Spot elevations, based on the civil grading plan, for the perimeter of the new additions, sidewalk, or any other areas pertinent to the drainage of rainwater.
- .2 Location of storm water service for new additions roof drainage.
- .3 Parking lot lighting poles location and type.
- .4 Final location for manholes, handholes, pull boxes.
- .5 Layout of underground distribution systems (normal power emergency power, fire alarm, master clock, intercommunication, television, telephone, security, control and spares).
- .6 Locations of all site improvements, playground and athletic equipment, street furniture, planters and other features.
- .7 Details of all curbing, typical parking spaces (regular and handicap accessible), handicap ramps, bus loop(s), parent drop-off, directional signage, site lighting, flagpole and fence foundations, and any other site conditions pertinent to the scope of work.
- .8 Plans of new playcourts, tennis courts, tracks, event pads and other pertinent athletic, physical education or recreational areas provided with court markings and detailing for basketball goals, volleyball sleeves, tennis nets, and other playcourt equipment or accessories.
- .2 A plan to delineate staging areas, site barriers and other area designations to control and separate students, faculty, staff and the public from construction activities and traffic.
- .3 Landscape plans and detail including a plant list clearly noted and cross referenced, details for shrub and tree plantings, identification of plants and trees to remain, be removed or relocated, and other necessary documentation.
- .4 Irrigation plans and details delineating the entire area of the project, and addressing necessary connections, alteration, repair or replacement of any existing irrigation systems.

.5 Full floor plans including:

- .1 All dimensions and any cross references explaining the extent of Work, wall types, or other component, assembly or direction regarding the Construction.
- .2 Note all chases and delineate all rainwater leaders.
- .3 Show structural tie columns and coordinate with the floor plan.
- .4 Cross referenced interior elevations.
- .5 Delineate and note all built-in cabinetry or equipment.
- .6 Identify room (F.I.S.H.) and door numbers with all doors having individual numbers.

- .6 **Demolition Plans:** Indicate required demolition activities. as follows:
 - .1 Provide separate demolition plan(s) and other drawings (elevations, sections, etc.) as necessary if the scope of work includes demolition which is too excessive to indicate drawings depicting new construction.
 - .2 Indicate notes on the extent of the demolition: address dimensions at locations where partial walls are being removed or altered, existing room names and numbers, existing partitions, equipment, plumbing, HVAC or electrical elements.
 - .3 Include notes dealing with protection of existing areas as a result of demolition.
 - .4 Delineate any modifications to existing buildings involving structural elements within the structural documents rather than on the architectural.
- .7 Building elevations developed further than at Phase II and including delineation of building joints (including dimensionally located stucco control joints), material locations, elevation heights, and other building features.
- .8 Building and wall sections to establish vertical controls and construction types for the Project. Include clear graphics, and notes on construction assemblies and systems to be used, dimensions, heights. Provide associated detailing to delineate solutions for difficult connections. Specify details for any fire walls to be constructed.
- .9 Reflected ceiling plans indicating ceiling types, heights, light fixture types, mechanical diffuser locations, and sprinkler heads if area is sprinklered. Delineate and detail any dropped soffits or joint conditions between different materials. Ensure coordination with architectural, electrical, mechanical and plumbing disciplines and work of any applicable Sub-Consultants.

.10 Roof plans:

- .1 Indicating all roof penetrations, including drains, scuppers, mechanical exhaust fans, any other equipment on the roof, slopes of roof with elevations shown, type of roofing system to be used, expansion joints, typical parapet and flashing details.
- .2 Dimensions to locate the items noted previously, and cross references shown.
- .11 Large scale building details as appropriate to this level of document development and as required to establish vertical controls for the Project. Include clear graphics, and notes on construction assemblies and systems to be used, dimensions, heights. Provide associated detailing to delineate solutions for difficult connections.
- .12 Interior elevations of all classroom designs including cross references of cabinetry details, dimensions and heights, notes indicating type of equipment (and whether equipment is in or out of contract), wall materials, finishes, and classroom equipment and accessories.
- .13 Details of casework as necessary to appropriately delineate custom or pre-manufactured casework. Provide appropriate schedules referencing manufacturer's numbers or catalogs, finishes, hardware and other construction characteristics.

.14 Details of the following:

- .1 Door jamb, head and sill conditions.
- .2 Wall and partition types.
- .3 Window head, sill and jamb conditions, and anchorage methods shown, in lieu of referencing to manufacturer's standards.
- .4 Interior signage to include classroom and building identification, emergency exiting and equipment signs, and any other items pertinent to the identification of the project. Coordinate with electrical discipline.
- .5 Interior or exterior expansion control connections.
- .6 Any other specialized items necessary to clearly express the intent of the project design.
- .15 Room finish and door schedules coordinated with the floor plans, developed beyond Phase II.
- .16 Structural foundation and framing plans, with associated diagrams, schedules, notes, detailing and section drawings completed sufficiently to communicate the design intent and coordination with other disciplines.

.17 Mechanical Drawings:

- .1 Provide double line duct work layout and HVAC equipment layout drawings with related diagrams and schematic diagrams, schedules, notes, detailing and section drawings completed sufficiently to communicate the design intent and coordination with other disciplines.
- .2 Provide plumbing equipment and fixture layout drawings with related diagrams, schedules, notes, detailing and section drawings completed sufficiently to communicate the design intent and coordination with other disciplines.
- .3 Provide 1/2 inch scale plans, elevations and sections of the mechanical rooms showing service clearance, room openings, nominal equipment size, ceiling height, duct clearance between bottom of joist and top of ceiling and any ceiling mounted lighting fixtures, electrical equipment or other building assembly or component, etc.
- .18 **Electrical:** Provide drawings for the following systems:
 - .1 Lighting including circuiting and luminaire identification and switching. Also provide illuminance computer printout for all indoor typical indoor spaces and parking lots.
 - .2 Convenience outlets and circuiting, special outlets and circuiting, television outlets, and power systems and equipment. Provide riser diagrams for all electrical systems including master clock, intercom, fire alarm, ITV, computer networking/telephone. Also, provide for emergency and normal power distribution. Provide luminaire schedule.

- .3 Panel schedule may be in preliminary form but circuitry must be included.
- .4 Applicable installation details.
- .5 General legend and list of abbreviations.
- 6 Voltage drop computation for all main feeders.
- .7 Short circuit analysis
- .8 Provide 1/2" scale floor plan and wall elevations for all electrical rooms.
- .9 Indicate surge protector for main switchboard and electrical panels.

.6 **Progress specifications:**

- .1 Provide preliminary Project Manual including front end documents. Completion of fill-in items in Bidding documents and other "Division 0" documents is not required.
- .2 Provide a preliminary Division 1 based upon the standard documents provided by the Owner, and edited by the Project Consultant after consultation with the Owner to establish project specific requirements.
- .3 Include progress set of all other Sections in Divisions 2-17 with each section developed to demonstrate to the Owner an understanding of the project and an appropriate level of developmental progress comparable to that of the drawings.
- .4 Specification sections shall be organized to follow the Construction Specification Institute's (CSI) current edition of MasterFormat with each section developed to include CSI's standard 3-part section and page formats with full paragraph numbering.
- .7 An updated Project Design Schedule, reflecting continued Project development and illustrating anticipated schedules for all subsequent project activities including permitting and submittal coordination with all agencies having jurisdiction on the Project. Format updated schedule as a Bar Chart (Gantt Chart) type schedule with milestones.
- .8 Colorboards illustrating color selections, finishes, textures and aesthetic qualities for all finish materials for final review and approval by the Owner and to establish a final pallet of material selections for development of subsequent specifications, schedules and other requirements for incorporation into the Contract Documents.
- .9 A letter from the Project Consultant and each of the major technical disciplines and any necessary Sub-Consultants or explaining how each previous comment concerning the project has been addressed and/or corrected.

2.4.3 100% Construction Documents Submittal:

.1 Upon receipt of written approval of the Phase III 50 % Construction Documents and a fully approved and executed ATP and Purchase order (See 5.2.3), the Project Consultant shall proceed with the rest

of Phase III Construction Documents.

- .2 Upon 100% completion of the Construction Documents, the Project Consultant shall submit to the Owner seven (7) copies of check sets of the Drawings, Specifications, reports, programs, a final updated Project Development Schedule, a final updated Statement of Probable Construction Cost and such other documents as reasonably required by Owner. The 100% construction documents shall conform to SREF requirements, all mandatory requirements cited by the Florida Department of Education (or the designated reviewer) and those listed below.
- .3 All documents for this phase shall be provided in both hard copy and in electronic media. The Owner will review and approve Phase III documents for submission to the Department of Education (or designated reviewing agency) for review and approval. The following Phase III contract documents shall be included with the Phase III submittal:
 - .1 "Project Transmittal Form" as required by the Facilities and Construction Management Division's Design Section.
 - .2 OEF form 208 "OEF Project Transmittal Form".
 - .3 OEF form 208 (a) "OEF Space Chart Form" formatted to follow the sequence of spaces listed in the SREF Size of Space and Occupant Design Criteria Table.

.4 General Requirements.

- .1 **Record Set.** This submittal is the official record set and shall be the bid documents.
- .2 **Signed and Sealed/Statements of Compliance:** Only complete documents, properly signed and sealed by the Project Consultant and respective Sub-Consultants, will be accepted for review; in addition, these documents shall contain a statement of compliance by the architect or engineer of record that "To the best of my knowledge and belief these drawings and the project manual are complete, and comply with the State Requirements for Educational Facilities and all applicable and referenced building codes".
- .3 When requested by the Owner, engineering calculations for mechanical, electrical, and structural systems shall be submitted separately from drawings and the project manual.
- .6 **Drawings.** These documents shall be 100% construction drawings corresponding to the educational specifications and program requirements illustrating the general scope, scale, and relationship of project components. In addition to Phase III 50% requirements, SREF requirements, and information required by the Owner's document submittal checklist for phase III 100%, the documents shall include the following:
 - .1 Site plans including, but not limited to, area location map, legal description of property, demolition, excavation, utilities, finish grading, landscaping, mechanical, electrical, civil/structural, and architectural site plans.
 - .2 Plans and details including, but not limited to:

- .1 Title sheets including listing of Project Consultant, Program Manager, School Board of Broward County, a table of contents and statement of compliance by the architect or engineer of record. Each discipline shall have a list of abbreviations, schedule of material indications, and schedule of notations and symbols at the beginning of their section of the plans.
- .2 Architectural sheets including floor plans, door, window and finish schedules, roof plans, elevations, sections, and details.
- .3 Civil/Structural sheets including paving; bus loops; parent drop; service drive; parking; drainage; foundation plans; floor plans; roof plans; structural plans; sections; details; and, pipe, culvert, beam and column schedules.
- .4 Mechanical sheets including floor plans; sections; details; riser diagrams; kitchen exhaust hoods; and, equipment, fan, and fixture schedules.
- .5 Electrical sheets including floor plans; sections; details; riser diagrams; and, fixture and panel schedules.
- .6 The drawings should indicate that the approved mechanical/electrical systems, from the Phase II FEEC/LCCA analysis, have been incorporated into the documents.
- .6 **Project Manual.** The Project Consultant, in its leadership capacity, shall review and coordinate with the Owner regarding the preparation of the following:
 - .1 The necessary bidding information, the bidding forms, the conditions of the contract and Division 1 with respect to the foregoing documents and regarding any other Agreements necessary for construction of the project. However, in no case will Project Consultant amend or delete items from these documents without prior review and written approval from Owner.
 - .2 A project specific set of Division 1 specifications based upon master documents provided by the Owner, including all schedules, lists and inventories as required to complete the Owner's master documents including Contractor's Submittal schedules, warranty schedules, salvage schedules, preliminary construction schedule, etc.
 - .3 Final specification sections for Divisions 2 through 17 organized and formatted as required for the set of Phase III, 50% progress specifications.
 - .4 Approved alternate bid items, if required and authorized by the Owner, to bring the project within the Fixed Limit of Construction Cost (FLCC) which would permit Owner in its sole discretion to accept or reject portions of the construction of the project. No additional compensation shall be provided for bid alternates if they are part of the original scope of work.
- .7 A threshold building inspection plan, prepared by the Project Consultant, and the name of a certified threshold building inspector, as set forth in Section 553.79(5), Florida Statutes (2004) as amended from time to time, shall be submitted to the Owner and the Department of Education (as applicable) for review and approval with Phase III documents. Threshold building inspection plan documents shall be submitted for:

- .1 Any building greater than three (3) stories or fifty (50) feet in height, or
- .2 Any building with an assembly space that exceeds five thousand (5000) square feet in area, and an occupant load of five hundred (500) or more persons.
- .8 An Updated Statement of Probable Construction Cost as indicated by time factor, changes in requirements, or general market conditions.
- .9 A letter from the Project Consultant and each of the major technical disciplines and any necessary Sub-Consultants explaining how each previous review comment (as generated by the Owner and/or other reviewing agencies) concerning the project has been addressed and/or corrected.
- .4 If the Latest Statement of Probable Construction Cost exceeds the Fixed Limit of Construction Cost for construction, the Project Consultant shall review the materials, equipment, component systems and types of construction included in the Contract Documents with the Owner and may recommend changes in such items and/or reasonable adjustments in the scope of the Project (to be made at no additional cost to the Owner).
- .5 The Project Consultant shall make all required changes or additions and resolve all questions on the documents. The 100% complete Check Set shall be returned to the Owner. Upon final review and approval by the Owner the Project Consultant shall furnish seven (7) copies, signed and sealed of all Drawings and Specifications to the Owner without additional charge.
- .6 The Project Consultant shall, with the Owner's assistance, file the required documents for approval by governmental authorities having jurisdiction over the Project (including Broward County and municipalities and their constituent departments, the South Florida Water Management District, and other state, local or federal agency with jurisdictional authority over some aspect of the Project) and obtain certifications of "permit approval" by reviewing authorities prior to the commencement of Phase IV and early enough to ensure that the eventual contractors is not delayed by permit processing by Broward County, a municipality or other jurisdictional agency. The Project Consultant shall provide the original documents or reproducible copies as may be required for submittal to any and all governmental authorities. The Project Consultant shall attend and provide representation at all review meetings, workshops, hearings and Commission/Council meetings concerning the project as conducted by other jurisdictional agencies. Project Consultant shall assure the Owner that all mandatory requirements are complete prior to the bidding, included, but not limited to, those that may have a financial impact on the Project.
- .7 Staff from each of the Project Consultant's major technical disciplines and Sub-Consultants as necessary shall attend coordination, review and presentation meetings with the Owner to explain the development of the design concept and technical resolution of their respective building or site systems for both the Phase III, 50% and Phase III, 100% Submittals.
- .8 The Owner's review and approval of the drawings, specifications, calculations and other construction documents shall not relieve the Project Consultant of any responsibility for their accuracy, adequacy and completeness.

2.4.4 The Project Consultant shall make all changes to the documents as required by the Owner's review of the documents by issuing a written recommendation to the Owner, at no additional cost and resolve initially all questions of constructability, code compliance, coordination across disciplines, clarity of documents, compliance with Owner standards, or other issues raised by the Owner during their reviews of the documents. The Owner will retain the documents submitted at this phase.

2.5 Phase IV - Bidding and Award of Contract

- 2.5.1 **Bid Documents Approvals and Printing:** Upon obtaining a fully approved and executed ATP and Purchase order (See 5.2.3), and all necessary approvals of the Construction Documents, and review and, approval by the Owner of the latest Statement of Probable Construction Cost, the Project Consultant shall assist Owner in obtaining bids and awarding construction contracts. The Project Consultant will provide reproductions of the drawings and specifications for bidding purposes at no additional cost to the Owner.
- 2.5.2 The Owner will issue the Bid Documents to prospective bidders and keep a complete "List of Bidders."
- 2.5.3 The Project Consultant shall render initial interpretations and clarifications of the drawings and specifications in a written format, supplemented by appropriate graphics. The Owner shall make all final determinations and/or interpretations as it relates to building code issues.
- 2.5.4 The Project Consultant shall attend a pre-bid conference as requested by the Owner.
- 2.5.5 The Project Consultant shall prepare addenda, if any are required, for the Owner to issue to all prospective bidders. No addenda shall be issued without the Owner's approval and if dimensional changes or extensive graphic changes are required the drawing sheets shall be revised and issued as addendum drawings as directed by Owner.
- 2.5.6 The Project Consultant shall be present at the opening of bids with the Owner's staff.
- 2.5.7 The Project Consultant shall participate with Owner in evaluating the bids and shall provide a written recommendation for bid award.
- 2.5.8 If the lowest responsive Base Bid received exceeds the Fixed Limit of Construction Cost the Owner will either:
 - .1 Approve the increase of Project costs and award a contract or,
 - .2 Reject all bids and rebid the Project within a reasonable time with no change in the Project,
 - .3 Direct the Project Consultant to revise the Project scope or quality, or both, as approved by the Owner, and rebid the Project, or
 - .4 Suspend or abandon the Project, or
- 2.5.9 Under Article 2.5.6.2 above, the Project Consultant shall, without additional compensation, modify the Construction Documents as necessary to bring the project within the Fixed Limit of Construction Cost. The providing of such service shall be the limit of the Project Consultant's responsibility in this regard and having done so, the Project Consultant shall be compensated in accordance with this Agreement. The Owner may

recognize exceptional construction market cost fluctuations before exercising the option provided in Article 2.5.6.2 above. The Owner agrees to discuss this issue with the Project Consultant prior to exercising this option.

2.5.10 If an estimate or cost analysis is required by the Owner for this phase, the Project Consultant shall utilize the previously established independent cost estimator, or a replacement acceptable to the Owner, to analyze bids and to assist in the preparation of any modified bidding documents or re-bid documents that may be required to ensure successful bidding within the Fixed Limit of Construction Cost.

2.6 Phase V - Administration of the Construction Contract:

- 2.6.1 The Construction Administration Phase will begin with the award of the Construction Contract and will end when the Contractor's final Payment Certificate is approved by the Owner and after the one (1) year warranty period has expired. During this period, the Project Consultant shall provide Administration of the Construction Contract as set forth in the construction contract documents (hereafter referred to and defined as the "Contract Documents") between the Owner and the Contractor, as basic services.
- 2.6.2 The Project Consultant, as a representative of the Owner during the Construction Phase, shall advise and consult with the Owner within the limits established by this Agreement and the Contract Documents. The Project Consultant shall contemporaneously provide Owner with copies of all communications between Project Consultant and others concerning matters material to the cost, time, sequence, scope, performance or requirements of the project.
- 2.6.3 The Project Consultant and the Project Consultant's respective Sub-Consultants shall attend all key construction events as necessary to ascertain the progress of the Project and to determine in general if the Work is proceeding in accordance with the Contract Documents and the Project Schedule. A minimum of at least one site visit per week will be required by the Project Consultant. The Sub-Consultant will be required to visit the site at least once a week when their respective portion of the work is in progress.
 - The Project Consultant shall visit the site at least once per week to become familiar with the progress and quality of the Work and to determine if the Work is proceeding in accordance with the Contract Documents and Project Schedule. The Project Consultant shall coordinate the timing of these visits with the Owner's Representative so as to permit joint observations of the progress of the Work and discussions about project issues. On the basis of on-site observations as a Consultant, the Project Consultant shall keep Owner informed of the progress and quality of the Work. The Project Consultant shall promptly submit to Owner a detailed written report of the results of each visit to the site, and copies of all field reports and notes of meetings with contractor, subcontractors of any tier or suppliers.
 - .2 The Project Consultant shall, based upon its on-site visits, promptly report to Owner any defects and deficiencies in the Work coming to the attention of Project Consultant and shall endeavor to guard the Owner against defects and deficiencies in the Work. This obligation is not reduced or limited by the fact that others, such as the UBCI, are undertaking inspection for or on behalf of the Owner. The Project Consultant shall make on-site observations utilizing the same personnel over the course of the Work. The Project Consultant shall assist the Owner in determining the cost of additional inspections due to the Contractor's failure to perform. Any changes in personnel must be in writing and issued to the Owner.

- .3 The Project Consultant shall not have control over or charge of and shall not be responsible for construction means, methods, techniques, sequences or procedures, or for safety precautions and programs in connection with the Work.
- 2.6.4 The Project Consultant shall at all times have access to the Work where ever it is in preparation or progress. The Project Consultant and the Sub-Consultants shall review and advise the Owner as to whether the Contractor is making timely, accurate, and complete notations on the "Project Record Documents" and maintaining various other administrative records as required by the Contract Documents. In addition, the Owner may at its discretion require the Project Consultant and all Sub-Consultants to submit additional written materials or forms to the Owner relating to or regarding the Project or its progress. Complete notations to the "as built" drawings shall include, but not be limited to all changes due to RFI's, ASI's, COD's, and CO's, in addition to the changes recorded by the Contractor, as noted above.
- 2.6.5 The Project Consultant shall initially interpret matters and provide recommendations concerning performance of Owner and Contractor under the requirements of the Contract Documents upon written request of Owner. The Project Consultant's response to such requests shall be made with reasonable promptness and within any time limits agreed upon. The Project Consultant shall render written advisory decisions, only upon the Owner's request, within a reasonable time, on all claims, disputes and other matters in question between Owner and Contractor relating to the execution or progress of the Work or the interpretation of the Contract Documents.
- 2.6.6 All initial interpretations and advisory decisions of the Project Consultant shall be consistent with the intent of, and reasonably inferable from, the Contract Documents and shall be in writing or in the form of drawings. In the capacity of interpreter the Project Consultant shall endeavor to secure faithful performance by both the Owner and Contractor, and shall not show partiality to either. The Owner shall be the final interpreter of any and all matters pertaining to the performance of the Project Consultant and Contractor.
- 2.6.7 The Project Consultant shall have authority to recommend rejection of Work which does not conform to the Contract Documents. The Project Consultant shall not have authority to stop the Work without approval of the Owner. Whenever, in the Project Consultant's reasonable opinion, it is necessary or advisable for the implementation of the intent of the Contract Documents, Project Consultant may recommend special inspection or testing of the Work in accordance with the provisions of the Contract Documents, whether or not such Work is to be fabricated, installed or completed, but Project Consultant shall take such action only after consultation with Owner. The Project Consultant's monitoring of such additional special testing or inspections is a part of the Basic Services. Owner shall furnish all such tests, inspections and reports that are required by law or by the Contract Documents or that it has previously approved in writing, without waiving its right to reimbursement from Contractor. However, neither this authority of the Project Consultant nor a decision made in good faith either to exercise or not to exercise such authority shall give rise to a duty of responsibility of the Project Consultant to Contractor or other third parties performing portions of the Work.
- 2.6.8 The Project Consultant shall promptly review, and take other appropriate action upon Contractor's submittals such as shop drawings, product data and samples, but only for conformance with the design concept of the Contract Documents. Such action shall be taken within fourteen (14) days of receipt by Project Consultant unless Ownerand Project Consultant otherwise mutually agree. Project Consultant's review shall not constitute review or approval of safety precautions or of construction means, methods, techniques, sequences or procedures. Project Consultant shall maintain a log of all submittals made and shall compare the submittals with Contractor's progress schedule. The Consultant shall not approve changes to the contract or substitutions through the regular submittal process but will utilize those respective methods specified in the Contract Documents. The Project Consultant shall be compensated for reviewing re-submittals after the first

- re-submittal of a respective submittal as a reimbursable expense with the Owner reimbursed by the Contractor under provisions of the Contract Documents.
- 2.6.9 The Project Consultant shall coordinate with the Owner concerning the Owner's required review of Request for Proposals, Change Orders and Construction Change Directives. The Project Consultant shall:
 - .1 Meet with the Owner prior to the preparation and execution of Request for Proposals, Contingency Use Directives and Change Order items to ensure that proposed changes comply with the intent of the Project's scope and construction schedule and whether the Contractor is entitled to additional sums or contract time for the proposed Work.
 - .2 Reconcile the Project Consultant's analysis of Request for Proposals, Contingency Use Directives and Change Order amounts with an analysis provided by Owner's chosen independent cost estimator and provide the Owner with a recommendation concerning the respective cost studies.
 - .3 Submit written and graphic information documenting proposed changes for formal review by the Owner.
 - .4 Review and indicate concurrence through signing Request for Proposals for Owner's authorization in accordance with the Contract Documents, shall have authority to order minor changes in the Work not involving an adjustment in the contract sum or an extension of the contract time and which are not inconsistent with the intent of the Contract Documents. Such minor changes shall be implemented through an Architect's Supplemental Instructions (ASI) issued through Owner. The Basic Services shall include providing recommendations concerning Request for Proposals, Contingency Use Directives and Change Orders, and the preparation, permitting and processing of Request for Proposals, Change Orders and Construction Change Directives. This Article shall not supersede Articles 2.9.1.14 or 2.9.1.16.
 - .5 Process, prepare and issue contract modification documents, Request for Proposals, Contingency Use Directives and Change Orders, in a timely manner and not allow the period required for evaluation, preparation or to issue such documents to exceed fourteen (14) days. The Project Consultant shall provide written notification to the Owner concerning those modification documents requiring more than fourteen (14) days processing time with an attached explanation of the circumstances requiring longer processing time.
 - .6 All final decisions with respect to substitutions, Request for Proposals, Change Orders, and other contract modifications shall be at the sole determination of the Owner.
- 2.6.10 The Project Consultant shall conduct thorough site observations, make recommendations and otherwise assist Owner in determining the dates of Substantial Completion and Final Completion, shall review, approve and forward to Owner for Owner's review, written warranties and related documents required by the Contract Documents and assembled by Contractor, and shall certify a final certificate for payment. At substantial completion, the Project Consultant shall prepare a punch list of observed items requiring correction, completion or replacement by Contractor. The Project Consultant shall administer the Contractor's submittal of various closeout submittals including warranty documents, operations and maintenance materials, extra materials, and other closeout submittals as required by the Contract Documents. The Project Consultant and the Sub-Consultants shall verify and confirm the Contractor's successful demonstration of equipment and systems and the training of the Owner's personnel as required by the Contract Documents. Project Consultant shall inspect the Project upon final completion to determine compliance with the Contract Documents and,

- upon so determining, prepare and execute the required forms and other documents indicating that the Work is completed in compliance with the Contract Documents.
- 2.6.11 The Project Consultant shall within sixty (60) days of final acceptance provide the Owner with prints and electronic media copies of the original drawings, which the Project Consultant has revised to conditions based on information furnished by the Contractor as Project Record Documents. These prints and electronic media copies shall become the property of the Owner. Submittal of these documents to the Owner is a condition of final payment of construction support fees to the Project Consultant.
- 2.6.12 The Project Consultant shall assist Owner in determining amounts owing to Contractor based on observation at the site and an evaluation of Contractor's applications for payment and shall certify Certificates for Payment of such amounts as provided in the contract documents and in such forms as the Owner may request. The certification of the Certificate for Payment shall constitute the representation by Project Consultant to Owner based on Project Consultant's observation at the site and the data comprising Contractor's applications for payment, that the work has progressed to the point indicated; the quality of the work is in substantial accordance with the contract documents (subject to an evaluation of the work for substantial conformance with the contract documents upon substantial completion, to the results of any subsequent test by or performed under the contract documents, to minor deviations from the contract documents cited prior to completion, and to any specific qualification stated in the Certificate for Payment); and that the Contractor is entitled to the amount certified. However, the certification of the Certificate of Payment shall not be a representation that Project Consultant has made any examination, other than information which has come to Project Consultant's attention, to ascertain how and for what purpose Contractor has used the monies paid by the Owner.

2.7 Phase VI - Warranty Administration:

2.7.1 Upon receiving a fully approved and executed ATP and Purchase order (See 5.2.3), and for one year following substantial completion of the construction project, the Project Consultant shall assist Owner, without additional compensation, in securing correction of defects, and shall in the sixth and eleventh months make inspections of the project with the Owner and report observed discrepancies to Owner.

2.8 Other Basic Services:

2.8.1 The Project Consultant shall render to Owner without additional compensation, any proper and reasonable assistance which Owner may require as a result of any claim or any action brought relating to Project Consultant's services. Preparation of detailed analysis or documentation (if requested by Owner) shall be a supplemental service under Article 2.9.1.21 with a fully approved and executed ATP and Purchase order (See 5.2.3).

2.9 Supplemental Services

- 2.9.1 The services listed below are normally considered to be beyond the scope of Basic Services as defined in this Agreement, and if authorized in advance by having received a fully approved and executed ATP and Purchase order (See 5.2.3), will be compensated for as provided under Articles 5.7 and 6.2:
 - .1 Providing special analyses of the Owner's needs, and special detailed programming requirements for a project.
 - .2 Providing financial feasibility, or other special studies.

- .3 Providing planning surveys, site evaluations, or comparative studies of prospective sites.
- .4 Providing services relative to future facilities, systems and equipment which are not intended to be constructed as during the construction phase.
- .5 Providing services to make measured drawings of the existing site or facilities.
- .6 Providing the services of a cost estimating firm beyond the services required during Phases I-III to verify cost of the work as designed. The choice of the firm, qualifications of the firm and the terms of employment of the firm shall be approved in writing in advance by the Owner.
- .7 Providing interior design services required for or in connection with the selection of furniture or furnishings, except equipment included in the Construction Contract and identified in the educational specifications.
- .8 Providing investigations and making detailed appraisals and valuations of existing facilities, and surveys or inventories required in connection with construction performed by the Owner.
- .10 Providing the services of one or more full-time Construction Inspector during construction; including the services of a Special Threshold Inspector.
- .11 Providing extended assistance beyond that provided under Basic Services for the initial start-up, testing, adjusting and balancing of any equipment or system; extended training of Owner's personnel in operation and maintenance of equipment and systems, and consultation during such training; and preparation of operating and maintenance manuals, other than those provided by the Contractor, subcontractor, or equipment manufacturer.
- .12 Providing consultation concerning replacement of any Work damaged or built inconsistent with the Contract Drawings, providing the cause is found by the Owner to be other than by fault of the Project Consultant.
- .13 Providing consultation concerning replacement of any Work damaged by fire or other cause during construction, and furnishing services as may be required in connection with the replacement of such Work.
- .14 Preparing revisions of Schematic Design, Design Development, and Construction Document Phase Documents previously approved in writing by Owner, when so directed in writing by Owner, provided, however, that no compensation for Supplemental Services shall be paid for revisions which may be required when due to errors or omissions by the Consultant or when due to the fact that the lowest Bona Fide construction bid exceeds the "fixed limit of construction cost".
- .15 Providing services made necessary by the default of the Contractor, or any major unanticipated defects or deficiencies in the Work of the Contractor or any subcontractor not attributable in any way to an Error and/or Omission of the Project Consultant.
- .16 Preparing change orders and related documents provided the changes are significant changes (whether increases or decreases) in the scope of the project and are requested by the Owner and not for any changes due to any other reasons such as error or omission of the Project Consultant.

- .17 Providing revisions in drawings, specifications or other documents required by the enactment or revision of codes, laws or regulations subsequent to the preparation of such documents.
- .18 Preparing to serve or serving as an expert witness in connection with any public hearing, arbitration proceeding or legal proceeding.
- .19 Providing services after certification to the Owner of that Final Certificate for payment, and said payment has been made to the Contractor except those services that are a result of errors, omissions. or conflicts in documents prepared by the Project Consultant or are warranty related services.
- .21 Review of extensive claims by the Contractor or others relating to the Project. However, there shall be no additional charges to Owner from Project Consultant in the event the claims are not extensive or in the event the claims are determined by the Owner to be based upon the failure of the Project Consultant or Sub-Consultant to properly perform its services or to comply with the provisions of this Agreement.

ARTICLE 3 SUB-CONSULTANTS

3.1 Sub-Consultants' Relations

- 3.1.1 All services provided by the Sub-Consultant shall be pursuant to appropriate Agreements between the Project Consultant and the Sub-Consultants which shall contain provisions that preserve and protect the rights of the Owner and the Project Consultant under this Agreement. All such Agreements shall provide that the Project Consultant may assign or transfer to Owner any and all claims or causes of action which the Project Consultant has or may have against a Sub-Consultant as a result of or relating to any acts of omission or commission of that Sub-Consultant.
- 3.1.2 Nothing contained in this Agreement shall create any contractual relationship between the Owner and the Sub-Consultants. However the Project Consultant is at all times liable for any and all negligent acts of omission or commission of its Sub-Consultants relating to or regarding this Agreement or the Project which is the subject of this Agreement. The Owner may, at any time, require the Project Consultant to assign or transfer to the Owner any claims or causes of action which Project Consultant has or may have against one or more of its Sub-Consultants as it relates to these contract obligations regarding or relating to this Project. Upon such request, the Project Consultant shall execute a written assignment or transfer in a form to be provided by the Owner. In the event the Owner requires the Project Consultant to assign or transfer said claims or causes of action then the Owner agrees to indemnify and hold the Project Consultant harmless from any claim or cause of action brought by a Sub-Consultant against the Project Consultant directly related to the claim of cause of action brought by the Owner against a Sub-Consultant as a result of such assignment.

3.2 Proposed Sub-Consultants

- 3.2.1 The Project Consultant proposes to utilize the following Sub-Consultants: Per Attachment 5 (Project Team Members)
- 3.2.2 The Project Consultant shall not change any Sub-Consultant without written prior approval by the Owner.

3.2.3 The Project Consultant, not later than ten (10) calendar days after the date of this Agreement, shall submit a list of contact information for Sub-Consultants which includes contact names, firm addresses, phone and fax numbers and internet (or other internet e-mail service provider) e-mail addresses.

ARTICLE 4 THE OWNER'S RESPONSIBILITIES

4.1 Information, Documents, And Services

- 4.1.1 Owner shall consult with Project Consultant and provide such information regarding requirements for the project, including a Project Scope, Budget and Schedule which shall set forth Owner's contemplated design objectives, constraints and criteria, including educational specifications, facilities lists, space requirements and relationships, flexibility and expandability, special equipment and site requirements as are reasonably necessary for Project Consultant to perform its services.
- 4.1.2 The Owner shall furnish a legal description and a certified land survey of the site. When possible, the Owner shall supply the certified land survey in hardcopy and electronic media formats. The certified land survey shall provide boundary dimensions, locations of existing structures and/or trees, the grade and line of street, pavement and adjoining properties, the rights, restrictions, easements, boundaries, topographic data and information relative to sewer, water, gas and electrical services.
- 4.1.3 Owner shall furnish the services of soil engineers or other consultants if such services are necessary and requested in writing by Project Consultant. Such services may include test borings, test pits, soil bearing values, percolation tests, air and water pollution tests, ground corrosion and resistivity tests, including necessary operations for determining subsoil, air and water conditions, tests for hazardous materials, chemical, mechanical, structural or other tests with reports and appropriate professional recommendations.
- 4.1.4 Owner shall furnish a Project Schedule for the project showing all activities and critical dates necessary to complete the project within the allotted time.
- 4.1.5 Owner shall furnish a Construction Budget which is the portion of the Project Budget allocated for the construction cost of a project and will be based upon the Fixed Limit of Construction Cost with an appropriate contingency factor. This contingency factor includes but is not limited to the demolition, destructive testing and repairs, directed by the Project Consultant, to adequately investigate and document the existing conditions of the facility.
- 4.1.6 **As-Built Documentation:** When available, drawings and other available documents which were purported to represent "as-built" conditions at the time of original construction will be furnished to the Project Consultant; however, they are not warranted to represent conditions as of this date. The Project Consultant shall perform non-destructive field investigations as necessary to obtain sufficient information to perform his services and as required by field conditions, or the Owner to verify wall assemblies, construction types or other basic information as required to develop the design and documentation necessary for the project. The demolition and repairs associated with the destructive testing shall be compensated as a reimbursable expense. The Owner encourages the use of destructive testing techniques (with prior approval) to retrieve information that can be utilized by the Project Consultant to clearly indicate the disposition of the existing facility and incorporate this information into the Contract Documents.

4.1.7 District Standards and Submittal Checklist

- .1 Design And Material Standards: The Owner will furnish an electronic copy of Design and Material standards for the Project Consultant's use in developing designs and documentation for the project. These documents are technical specifications and the intent of these documents is to convey basic Owner preferences to the Project Consultant. The Project Consultant shall review the content of the Design and Material Standards provided by the Owner and may consult with the Owner concerning discrepancies, errors or suggestions for the improvement of the provided documents. The Project Consultant remains responsible for the technical content and accuracy of documents produced under the terms of this Agreement.
- .2 **Design Criteria:** The Owner will furnish an electronic copy of the Design Criteria for the Project Consultant's use in developing designs for the project. These criteria are guidelines, which address owner related issues; including but not limited to, ease of maintenance, life cycle costing, and functionality of the facility.
- .3 **Document Submittal Checklist:** The checklist is a guideline indicating minimum requirements for the submittal of contract documents for each phase of the design process. The completed checklist form will be required with each submission for all applicable disciplines.
- 4.1.8 **Standard Construction Bidding And Contract Documents:** The Owner shall furnish the Project Consultant with sample bidding and contract requirements and general requirements containing the basic provisions and requirements of Owner. These documents are comprised of the Bidding Requirements, Contracting Requirements, and Division 1 Specification Sections that will be utilized by the Project Consultant to develop the construction contract documents required under the terms of this Agreement. The Project Consultant acknowledges that these Owner Standard Documents will be made available by the Owner and shall be reviewed and analyzed by the Project Consultant and that these documents shall serve as the basis for the Project Consultant's development of bidding documents for the Owner.
- 4.1.9 Owner shall arrange and pay for the required advertisements for bid.
- 4.1.10 Owner, assisted by Project Consultant, shall issue the bid documents to bidders, maintain the planholders list, and issue addenda.
- 4.1.11 Owner shall be responsible for issuance of formal notices to proceed (if any) to the Contractor.

4.2 Owner Furnished Items

- 4.2.1 The services, information, surveys and reports specified by Article 4.1 shall be furnished at the Owner's expense, and the Project Consultant shall be entitled to rely upon the accuracy and completeness thereof. However, if the Project Consultant reviews all of the information provided by the Owner (such as surveys, soil borings and "as-built" documentation) and determines additional information and/or testing is required to properly design the project, the Project Consultant shall request same from the Owner.
- 4.2.2 When documents, services, or other materials furnished by the Owner for the Project Consultant's use are deemed by the Project Consultant as inappropriate, inaccurate, or otherwise unreasonable, the Project Consultant shall notify the Owner immediately upon discovery of same. Failure of the Project Consultant to so notify the Owner shall result in the Project Consultant's being responsible for any costs, expenses, or damages incurred by the Owner and forfeiture of claims for damages, delays or other compensation related to the use of those Owner furnished materials.

4.2.3 The Owner shall furnish the above information or authorize the Project Consultant to provide it, as a supplemental service (except where otherwise stipulated), as expeditiously as possible for the orderly progress and development of the Project.

ARTICLE 5 BASIS OF COMPENSATION

5.1 Professional Service Fees:

5.1.1 The Owner agrees to pay the Project Consultant, and the Project Consultant agrees to accept for services rendered pursuant to this Agreement a fixed fee (as computed by the Fixed Fee method below) of:

	Dollars. (\$.00)
Reuse Fee		
(Fee Written Out)	(\$)
Site Adaptation Fee		
(Fee Written Out)	(\$)
(Other – Description) Fee		
(Fee Written Out)	(\$)

5.2 Fixed Fee:

- 5.2.1 The Fixed Fee listed above is based on the scope of services for a project of this scope, size, complexity and Fixed Limit of Construction Cost (FLCC) of Construction of the project.
- 5.2.2 If the Owner authorizes a significant increase or decrease in the scope of the project, the Fixed Fee may be adjusted as mutually agreed upon. Changes in the FLCC, or, a Construction Contract awarded by the Owner in excess of the FLCC, shall not entitle the Project Consultant to additional Basic Services Fees, and, a Construction Contract awarded by the Owner that is less than the FLCC shall not entitle the Owner to a decrease in Basic Services Fees.
- 5.2.3 The Project Consultant shall not perform Professional Services, Supplemental Services, or Reimbursable Services until a written Purchase Order with the appropriate "line number" has been issued by the Supply Management and Logistics Department together with a fully executed Authorization to Proceed. <a href="MVNER SHALL HAVE NO OBLIGATION TO COMPENSATE PROJECT CONSULTANT FOR ANY WORK PERFORMED BY THE PROJECT CONSULTANT PRIOR TO RECEIPT OF A FULLY EXECUTED WRITTEN AUTHORIZATION TO PROCEED AND PURCHASE ORDER.

5.3 Not Used

5.4 Fee for Additive Alternates:

- 5.4.1 The design of alternates within the Owner's total allocated funds for construction will be a Basic Service.
- 5.4.2 The design of additive alternates, not included in the original project scope, in excess of Fixed Limit of Construction Cost of Construction must be authorized by the Chief Facilities and Construction Officer, and will be considered supplemental services, subject to negotiation.
- 5.4.3 Fees for the design of additive alternates, not included in the original project scope, will be negotiated and issued by a fully approved and executed ATP and Purchase order (See 5.2.3), . The Owner will pay one

hundred (100%) percent of the negotiated fee for alternates accepted and only pay for the design portions of the (Phases I through III) for alternates rejected.

5.5 Raw Labor Rate:

5.5.1

5.5.1 Raw Labor is defined as the raw salary rate, as determined from salaries reported to the Director of Internal Revenue, of the personnel engaged directly on a project.

5.6 Fees for Reimbursables

- 5.6.1 Reimbursables are those items pre-approved in writing by a fully approved and executed ATP and Purchase order (See 5.2.3), and authorized by the Owner in addition to the Basic and Supplemental Services and consist of actual expenditures made by the Project Consultant and the Project Consultants' employees and Sub-Consultants in the interest of the Work.
- 5.6.2 Authorized travel outside the Dade, Broward and Palm Beach County area, lodging and meals in connection with a project (subject to the limitations imposed by Chapter 112.06l, Florida Statutes); fees paid for securing approval of authorities having jurisdiction over the Work; reproductions (outside of Basic Services and with prior written Owner approval in the form of a fully approved and executed ATP and Purchase order (See 5.2.3); postage and handling of Drawings, Specifications and other documents, excluding reproductions for the office use of the Project Consultant and check sets required by the Owner; data processing and photographic production techniques when used in connection with Supplemental Services.
- 5.6.3 The Owner will reimburse the Project Consultant for authorized Reimbursables as verified by appropriate bills, invoices or statements.
- 5.6.4 Any authorized reimbursable shall not include charges for office rent or overhead expenses of any kind, including but not limited to local telephone, cell phone and utility charges, overtime or any discretionary labor benefits, office and drafting supplies, depreciation of equipment, professional dues, subscriptions, etc., reproduction of drawings and specifications, mailing, stenographic, clerical, or other employees time or travel and subsistence not directly related to a project. Authorized reproductions in excess of sets required at each phase of the work will be a Reimbursable.

5.7 Fees for Supplemental Services

5.7.1 The Consultant may be authorized by its receipt of a fully approved and executed ATP and Purchase order (See 5.2.3), to perform Supplemental Services described under Article 2.9 and negotiated in accordance with Article 2.8.2. The fee for such services will be Time Spent plus reimbursable expenses with a Guaranteed Maximum Price based on Raw Salary Rates times a fixed multiplier. The fixed multiplier shall cover mandatory personnel expenses, overhead and profit and shall be set at ______ times Raw Salary Rates and shall be included in the Guaranteed Maximum. Where a mutually agreeable Guaranteed Maximum cannot be arrived at, the Owner may secure services from an independent source or from the Owner's resources. The Consultant shall provide any information and/or copies of project documentation necessary to facilitate the provision of said supplemental services by others.

ARTICLE 6 PAYMENTS TO THE PROJECT CONSULTANT

6.1 Payment for Basic Services

- 6.1.1 Payments for Basic Services may be requested monthly in proportion to services performed during each Phase of the Work and provision of all required insurance policies is a condition precedent to becoming due any such payments to the Project Consultant. Said payments shall, in the aggregate, not exceed the percentage of the estimated total Basic Compensation, or 90% for Phases I, II, or II prior to approval of the submitted design documents, indicated below for each Phase:
 - .1 Fifteen (15%) percent of the total fee upon completion and approval of Phase I.
 - .2 Fifteen (15%) percent of the total fee upon completion and approval of Phase II.
 - .3 Twenty (20%) percent of the total fee upon submittal and approval of 50% of Phase III.
 - .4 Fifteen (15%) percent of the total fee upon completion and approval of Phase III.
 - .5 Five (5%) percent of the total fee upon 100% completion of Phase IV.
 - .6 Twenty-eight (28%) percent of the total fee upon completion of Phase V
 - .7 Two (2%) percent of the total fee upon completion of Phase VI (Warranty) and approval of all Work and audit of account, as per Article 5.
- 6.1.2 Partial payments may be made in Phase V (but not in excess of ninety (90%) percent of the aggregate of Phase V) in monthly increments which are proportioned to match the Work's percentage complete reflected by the Contractor's monthly Applications for Payment. If the Owner's required Substantial Completion date for Phase V is extended through no fault of the Project Consultant, the Project Consultant shall be reasonably compensated for any required professional services and/or expenses not otherwise compensated for in connection with such time extension(s), in accordance with Article 6.2. If the Owner's required Substantial Completion date for Phase V is extended due to an action or inaction of the Project Consultant to the detriment of the Owner, no additional payments or time shall be due to Project Consultant. The Project Consultant shall include with its billing, in either electronic or hard copy format, the following supporting information, and any additional supporting information required by the Owner: time sheets for any fees based upon Raw Salary Rates, subcontractors invoices, invoices for reimbursable expenses and time sheets, subcontractor invoices for reimbursables made necessary by the performance of Work. The invoice shall be totaled and care shall be taken to assure previously paid charges are not duplicated.
- 6.1.3 If the project reaches Final Completion (as defined by the Construction Contract Documents) prior to the expiration of the Anticipated Construction Time, then full payment shall be made at that time provided the Project Consultant has completed all obligations for submittals and other services (including Project Record Documents) as required by this Agreement.
- 6.1.4 No payments shall be due to Project Consultant unless and until all materials, forms and documents required by this Agreement have been provided by Project Consultant and its Sub-Consultant to Owner, or others whom are to receive same. The Owner retains the right to withhold payment from the Project Consultant for non-performance of the Project Consultant during any phase of the Project.
- 6.1.5 The Project Consultant shall submit invoices in the Owner's required invoice format as provided.

- 6.1.6 All Submitted invoices shall have copies of referenced ATP's attached.
- 6.1.7 During project Phases I through III, the Project Consultant shall submit an updated Project Schedule reflecting the Project Consultant's scheduled and actual progress with each submitted invoice. As an attachment to the Project Schedule, the Project Consultant shall provide a progress report giving percentage of completion of the Project development.
- 6.1.8 Project Consultant shall submit a monthly MWBE Sub-Consultant Utilization Report with the monthly request for payment, on forms provided by the Owner.
- 6.1.9 Payments are due and payable thirty (30) days from receipt of the Project Consultant's invoice provided it is in accord with the requirements of this Agreement.

6.2 Payment for Supplemental Services / Reimbursables

- 6.2.1 Payment for Supplemental Services and/or Reimbursables may be requested monthly (on the Owner's standard invoice format) in proportion to the services performed. When such services are authorized, the Project Consultant shall submit for approval by the Chief Facilities and Construction Officer, a duly certified invoice, attaching to the invoice all supporting data for payments made to Sub-Consultants engaged on the project or task.
- 6.2.2 Payments are due and payable thirty (30) days from receipt of the Project Consultant's invoice.

6.3 Project Suspension

- 6.3.1 If the project is suspended for the convenience of the Owner for more than three months or terminated in whole or in part, during any Phase, the Project Consultant shall be paid for services authorized by an Authorization To Proceed which were performed prior to such suspension or termination, together with the cost of Reimbursable Services and expenses then due.
- 6.3.2 If the Project is resumed after having been suspended for more than three months, the Project Consultant's further compensation shall be adjusted by the addition of Project Resumption Expenses. Project Resumption Expenses are in addition to compensation for Basic and Supplemental Services, and are full compensation for all damages and expenses which are directly or indirectly attributable to resumption of the Project Consultant's services after a Project Suspension. Project Resumption Expenses are applicable only to a Project Suspension by the Owner and shall be computed as a percentage of the total compensation for Basic Services and Supplemental Services earned to the time of termination, as follows:
 - .1 Two (2%) percent of the total compensation for Basic and Supplemental Services earned to the date of Project Suspension for the respective schematic or design development Phase only, if Project Suspension occurs before or during the design development design phase; or
 - .2 Five (5%) percent of the total compensation for Basic and Supplemental Services earned to the date of Project Suspension for the construction documents phase only, if Project Suspension occurs during the construction documents phase development phase; or
 - .3 Five (5%) percent of the total compensation for Basic and Supplemental Services scheduled for the construction contract administration phase only, if Project Suspension occurs during the construction support phase.

ARTICLE 7 REUSE OF DRAWINGS, SPECIFICATIONS AND OTHER DOCUMENTS

7.1 Scope of Services

- 7.1.1 It is understood that all Professional Service Agreements for design and other services include the provision for the Owner's optional re-use of drawings, specifications and other documents (including Phase V of Basic Services described in Article 2); and that the Project Consultant agrees to such re-use in accordance with this provision.
- 7.1.2 If the Owner elects to re-use the drawings, specifications and other documents, in whole or in part, prepared for the project for other projects on other sites, the Project Consultant will be paid a re-use fee, for Basic Services described in Article 2 for Phases I through VI, in the amounts of:
 - .1 Twenty (20%) percent of the original fee for Basic Services for Phases I through III.
 - .2 Thirty-eight (38%) percent of the original fee for Basic Services for Phases IV, V and VI.

Alternatively, the Owner agrees to pay the Project Consultant, and the Project Consultant agrees to accept, a flat reuse fee of:

This flat reuse fee will only apply if an actual dollar amount is listed above.

- 7.1.3 For each re-use the Project Consultant shall review the final as-built design of any prior reuse or reuses and shall include all Basic Services rendered under the reuse(s) and incorporate all modifications to the drawings, specifications and other documents resulting from Change-Orders, Errors and Omissions, Code revisions and Code corrections made during the prior reuse(s), and, modifications normally required to suit the new site. (This does not include preparation of reverse plans, changes to the program, subsequent code revisions or exceptional site conditions). The stipulations and conditions of this Agreement shall remain in force for each re-use project, unless otherwise agreed. Reuse fees do not include preparation of documents for offsite improvements.
- 7.1.4 If a reuse project commences in excess of three years from the acceptance of the design development documents by the Owner then Owner shall negotiate the fees to be paid to Project Consultant.

ARTICLE 8 INDEMNIFICATION

8.1 Indemnification

8.1.1 To the fullest extent permitted by law, the Project Consultant shall indemnify, defend and hold harmless the Owner, its members, officers, employees and agents (hereinafter collectively "Related Parties") from and against any and all liability, claims, causes of action (by whomever brought or alleged and regardless of the legal theories upon which the liability, claims or causes of action are based), losses, damage, costs, expenses and fees (including but not limited to reasonable fees of attorneys, expert witnesses and other consultants), which are or may be imposed upon, incurred by or asserted against Owner and/or the Related Parties to the extent said liability, claims, causes of action, losses, damages, costs, expenses and/or fees are caused by any errors, omissions or negligent acts of the Project Consultant, any sub-consultant or sub-sub-consultant, any

- supplier and any individual or entity directly or indirectly employed by any of them.
- 8.1.2 In any and all claims against the Owner by any employee of the Project Consultant, or anyone for whose acts the Project Consultant may be liable, the obligations for Project Consultant to indemnify Owner under this contract shall not be limited in any way by any limitation on the amount or type of damages, compensation, or benefits payable by or for the Project Consultant under workman's compensation acts, disability acts, or other employee benefit acts.
- 8.1.3 In the event that any claims are brought or actions filed against the Owner with respect to the indemnity contained herein, the Project Consultant agrees to defend against any such claims or actions regardless of whether such claims or actions are rightfully or wrongfully brought or filed. The Project Consultant agrees that the Owner may select the attorneys to appear and defend such claims or actions on behalf of the Owner. The Project Consultant further agrees to pay, at the sole expense of the Project Consultant, the attorney's fees and cost incurred by those attorneys selected by the Owner to appear and defend such claims or actions on behalf of the Owner. However, if the claims or actions are covered by insurance and such coverage is acknowledged by the insurance company in writing to the Owner, then, in that case, the insurance company shall choose counsel, direct the defense and be the judge of the acceptability of any compromise or settlement of any such claims or actions against the Owner which are within the insurance policy limits and are paid by the insurance company solely. Otherwise, if the claims or actions are not covered by insurance, then, at its sole option the Owner shall have the sole authority for the direction of the defense, and shall be the sole judge of the acceptability of any compromise or settlement of any claims or actions asserted against the Owner.
- 8.1.4 The Project Consultant recognizes the nature of the indemnification obligations imposed under this contract and voluntarily makes these covenants. The obligation imposed upon the Project Consultant under this Indemnification Agreement shall survive termination of this contract.

ARTICLE 9 INSURANCE

9.1 General Insurance Requirements

- 9.1.1 The Project Consultant shall not start work under this Agreement until the Project Consultant has obtained all insurance required hereunder and such insurance has been approved by the Owner.
- 9.1.2 All insurance policies shall be issued by companies authorized to do business under the laws of the State of Florida. All insurance companies providing policies required under this Agreement shall have at least an "A-" rating and a financial rating of no less than VI in the current A. M. Best Manual or hold a Moody's Investors Service Financial Strength of "Aa3" or better.
- 9.1.3 Insurance policies required under this Agreement shall be endorsed to be primary of all other valid and collectible coverages maintained by The School Board of Broward County, Florida.
- 9.1.4 The Project Consultant shall furnish certificates of insurance to the Owner for review and approval at the time of execution of this Contract and shall maintain same at all times during the term of this Agreement.
- 9.1.5 All Certificates of Insurance shall be in the form as approved by Insurance Standards Office (ISO), unless approved by Owner and shall clearly indicate that the Project Consultant has obtained insurance of the type, amount and classification required by these provisions, in excess of any pending claims at the time of contract award to the Project Consultant. No material change or cancellation of the insurance shall be effective

without a thirty (30) day prior written notice to and approval by the Owner. All Certificates shall list the Owner's project number and full project title (including applicable facility name).

9.1.6 Certificates of Insurance must clearly list any and all deductibles by coverages.

9.2 Insurance Required:

- 9.2.1 Automobile Liability Insurance: The Project Consultant shall maintain Automobile Liability Insurance covering all owned, non-owned and hired vehicles used in connection with this Agreement in amounts not less than One Million (\$1,000,000) Dollars per occurrence for bodily injury and property damage combined single limit and shall not be less than the standard ISO Business Auto Policy CA 00 01.
- 9.2.2 Professional Liability (Errors and Omissions): The Project Consultant shall procure Professional Liability Insurance in the manner described herein. The deductible shall not be more than Fifty Thousand (\$50,000) Dollars for each policy and must be indicated on the certificate of insurance. The insurance policy shall be non-cancelable and the limits of the Professional Liability Insurance Policy shall be as follows:
- 9.2.2.1 Not used.
- 9.2.2.2. Projects require a practice policy with a per claim/annual aggregate in accordance with the specifications delineated below relative to the cumulative construction value of all projects:
 - .1 One Million (\$1,000,000) Dollars on a per claim/One Million (\$1,000,000) Dollars annual aggregate basis for Project Consultants whose cumulative construction value for all Board contracts is less than Five Million (\$5,000,000) Dollars.
 - .2 One Million (\$1,000,000) Dollars on a per claim/Three Million (\$3,000,000) Dollars annual aggregate basis for Project Consultants whose cumulative construction value for all Board contracts is between Five Million One (\$5,000,001) Dollars to Ten Million (\$10,000,000) Dollars.
 - .3 One Million (\$1,000,000) Dollars on a per claim/Five Million (\$5,000,000) Dollars annual aggregate basis for Project Consultants whose cumulative construction value for all Board contracts is greater than Ten Million One (\$10,000,001) Dollars.

The Project Consultant shall be required to maintain the practice policy in accordance with the above specifications for a period commencing with execution of this contract and terminating three years after final completion of said projects. Should additional projects or change orders be added that increase the cumulative construction value to another tier shown above, the Project Consultant will be required to show proof of coverage at the higher limit / aggregate. In addition, the project consultant shall provide information regarding the total claims against said practice policy on an annual basis for the term of the contract upon and terminating three years after final completion of the project (Claims/Loss history should be forwarded to the Risk Management Department), as The School Board of Broward County, Florida, deems appropriate.

The Professional Liability insurance must provide for all sums which the Project Consultant shall be legally obligated to pay as damages for claims arising out of or relating to the negligent services performed by the Project Consultant or any person employed or acting on the Project Consultant's

behalf (including, but not limited to, Sub-Consultants) in connection with this Agreement. If the Owner, at its sole discretion, agrees that such coverage is not commercially reasonably available, the Owner may, at its discretion, authorize the Project Consultant to alter the coverage by substituting a lower aggregate or changing any other terms and conditions of the coverage (including but not limited to deductible amounts) based upon the scope of the project.

- 9.2.3 Workers' Compensation Insurance: The Project Consultant shall maintain Workers' Compensation Insurance in compliance with Florida Statutes, Chapter 440 and Employer's Liability Limit of not less than Five Hundred Thousand (\$500,000) Dollars per Occurrence.
- 9.2.4 General Liability Insurance: The Project Consultant shall maintain General Liability Insurance, including Contractual Liability to cover the "Hold Harmless Agreement" set forth herein, with bodily injury limits of not less than One Million (\$1,000,000) Dollars per occurrence combined single limit for bodily injury and property damage and not less than the Two Million (\$2,000,000) General Aggregate such coverage shall apply separately to each project. The School Board of Broward County, Florida, its members, officers, employees, and agents shall be named as an additional insured under the General Liability policy.

ARTICLE 10 GENERAL PROVISIONS

10.1 Performance

- 10.1.1 **Performance and Delegation:** The services to be performed hereunder shall be performed by the Project Consultant's and Sub-Consultant's own staff, unless otherwise approved by the Owner in writing. Said approval shall not be construed as constituting an Agreement between the Owner and said other person or firm.
- 10.1.2 **Term of Agreement:** The term of this Agreement shall start upon execution by the parties hereto and extend until the completion of Phase VI (Warranty) activities as set forth above except as may be otherwise agreed to in writing by the parties hereto, or as provided further herein under Article 10 and Article 7.
- 10.1.3 **Time for Performance:** The Project Consultant agrees to start all work hereunder upon receipt of an Authorization to Proceed issued by the Chief Facilities and Construction Officer or his designee and to complete each Phase within the time stipulated in the Authorization To Proceed (Attachment 6 to this Agreement ("ATP")) and as required by the Project Schedule (Attachment 1 to this Agreement). The Project Consultant acknowledges that failure to perform timely may cause the Owner to sustain loss and damages and will be responsible for same. The Consultant agrees that Owner is entitled to recover no less than One Hundred Dollars (\$100) per consecutive calendar day of unexcused delay caused by the Consultant's failure to comply with the times set forth in the fully executed ATP. Owner shall have the right to deduct such amounts from payments due and owing to the Consultant.
- 10.1.4 **Time Extensions**: A reasonable extension of time for completion of various Phases may be granted by the Owner should there be a delay on the part of the Owner in fulfilling its obligations pursuant to this Agreement. Such extension shall not be the basis or cause for any claims or causes of action by the Project Consultant for additional or extra compensation. Under no circumstances shall the Project Consultant be entitled to additional compensation or payment as a result of or relating to delays on the Project.
- 10.1.5 Time is of the essence with regard to the performance of this Contract.

10.1.6 **Excess Funds:** Any party receiving funds paid by the School Board of Broward County, Florida under this Agreement agrees to promptly notify the School Board of Broward County, Florida of any funds erroneously received from the School Board of Broward County, Florida of upon the discovery of such erroneous payment or overpayment. Interest shall be calculated using the interest rate for judgments under Section 55.03, Florida Statutes, as amended, applicable at the time the erroneous payment or overpayment was made by the School Board of Broward County, Florida. The erroneous payment and/or overpayment will be promptly transmitted and returned to the School Board of Broward County, Florida with applicable interest as set forth herein.

10.2 Termination Of Agreement

- 10.2.1 **Right to Terminate:** The Owner has the right to terminate this Agreement for its own convenience on seven days written notice. Upon termination of this Agreement, the Project Consultant shall be paid in accordance with Article 10.2.5. To receive payment, all charts, sketches, studies, drawings, and other documents or other materials related to work authorized under this Agreement, whether finished or not, must be turned over to the Owner.
- 10.2.2 The Consultant may terminate this Agreement only for a material breach of the Agreement and provided the Project Consultant has given the Owner written notice of the material breach and ten (10) days to cure that breach. In the event of any dispute regarding or relating to performance pursuant to this Agreement, or payment hereunder, then in that event, the Project Consultant is obligated to continue performance in accordance with the terms of this Agreement unless instructed by the Owner to suspend or delay performance.
- 10.2.3 Owner may terminate this Agreement for cause, which may include, but not be limited to any of the following; failure of Project Consultant to comply with any of its material obligations under this Agreement; a decrease in the projected, available Capital Outlay funds which renders continuation of the design or construction of the Project impossible or impractical; or conditions which arise that constitute Force Majeure under Article 10.2.8 of this Agreement. In such event Project Consultant shall not be entitled to any additional payments and may be liable to Owner for any damages or losses incurred or suffered as a result of Project Consultant's failure to properly perform pursuant to the terms of this Agreement. In the event it is later determined that the Owner was not justified in terminating the Agreement for cause, then it shall be deemed to be a termination for convenience pursuant to Article 10.2.1 above, and the Project Consultant's sole compensation shall be compensation in accordance with that paragraph.
- 10.2.4 Whether or not this Agreement is so terminated, Project Consultant shall be liable to Owner for any damage or loss resulting from such failure or violation by Project Consultant, including, but not limited to, costs in addition to those agreed to herein for prosecuting professional services to completion and delay damages paid or incurred by Owner. The rights and remedies of Owner provided by this paragraph are cumulative with and in addition to any other rights and remedies provided by law or this Agreement.
- 10.2.5 **Termination Expenses:** Termination Expenses are in addition to compensation for Basic and Supplemental Services, and are full compensation for all damages and expenses which are directly or indirectly attributable to termination. Termination Expenses are applicable only to a termination for convenience by Owner and shall be computed as a percentage of the total compensation for Basic Services and Supplemental Services earned to the time of termination, as follows:
 - .1 Twenty (20%) percent of the total compensation for Basic and Supplemental Services earned to the date of termination, if termination occurs before or during the schematic design phase; or

- .2 Ten (10%) percent of the total compensation for Basic and Supplemental Services earned to the date of termination, if termination occurs during the design development phase; or
- .3 Five (5%) percent of the total compensation for Basic and Supplemental Services earned to the date of termination, if termination occurs during any subsequent phase.
- 10.2.6 **Annulment:** The Project Consultant warrants that no one has been employed or retained other than an employee working solely for the Project Consultant, to solicit or secure this Agreement; and that the Project Consultant has not paid, nor agreed to pay, any company or other person any fee, commission, gift or other consideration contingent upon the making of this Agreement. For breach or violation of this warranty, the Owner has the right to annul this Agreement without liability.
- 10.2.7 **Fixed Fees Exceeding \$50,000:** For all Fixed Fees or other "lump-sum" fees for professional service Agreements over Fifty Thousand (\$50,000) Dollars the Project Consultant shall execute a truth-innegotiations certificate as in accordance with 287.05 and all required language set forth therein. Requirements of Florida Statute 287.055 (2004), as amended, are incorporated herein by reference.
- 10.2.8 **Force Majeure:** The Owner's or Consultant's failure to perform any term or condition of this Agreement as a result of conditions beyond its control such as, but not limited to, war, strikes, fires, floods, acts of God, governmental restrictions, power failures, or damage or destruction of any network facilities or servers, shall not be deemed a breach of this Agreement.

10.3 Project Consultant's Accounting Records and Right to Audit Provisions

- 10.3.1 Project Consultant's records which shall include any and all records reasonably requested by Owner that relate to performance of services by Project Consultant or Sub-Consultants. Records include but are not limited to information, materials and data of every kind and character (hard copy, as well as computer readable data if it exists), books, papers, documents subscriptions, recordings, estimates, price quotations, agreements purchase orders, leases, contracts, commitments, arrangements, notes, daily diaries, superintendent reports, drawings, receipts, vouchers, monthly, quarterly, yearly or other financial statements, accounting records, payroll time sheets, job cost reports, job cost history, margin analysis, written policies and procedures, all Sub-Consultant files (including proposals of successful and unsuccessful Sub-Consultants, contracts, correspondence), original estimates, estimating worksheets, computer records, disks and software, videos, photography, correspondence, change order files (including documentation covering negotiated settlements), constructability or peer reviews, coordination documents, logs and supporting documentation, general ledger entries, insurance information, and any other supporting evidence necessary to substantiate charges related to this contract (all the foregoing hereinafter referred to as "records") shall be open to inspection and subject to audit and/or reproduction, during normal working hours, by Owner's agent or its authorized representative to the extent necessary to adequately permit evaluation and verification of any invoices, payments or claims submitted by the contractor or any of his payees pursuant to the execution of the contract. Such records subject to examination shall also include, but not be limited to, those records necessary to evaluate and verify direct and indirect costs (including overhead allocations), fees, reimbursable services, etc. as they may apply to costs, matters or items associated with this contract.
- 10.3.2 For the purpose of such audits, inspections, examinations and evaluations, the Owner's agent or authorized representative shall have access to said records from the effective date of this contract, for the duration of the work, and until five (5) years after the date of final payment by Owner to Project Consultant pursuant to this contract. All costs which the Consultant is unable to provide support or documentation to substantiate that it was incurred as represented by the original estimated breakdown of cost or found not to be in compliance

- with provisions of this contract, shall be reimbursed to the Owner.
- 10.3.3 Owner's agent or its authorized representative shall have access to the Project Consultant's facilities, shall have access to all necessary records, and shall be provided adequate and appropriate work space, in order to conduct audits in compliance with this article. Owner's agent or its authorized representative shall give auditees reasonable advance notice of intended audits.
- 10.3.4 Project Consultant shall require all Sub-Consultants and insurance agents, to comply with the provisions of this article by insertion of the requirements hereof in any written contract Agreement. Failure to obtain such written contracts which include such provisions shall be reason to exclude some or all of the related costs from amounts payable to the Project Consultant pursuant to this contract.
- 10.3.5 If an audit inspection or examination in accordance with this article, discloses overcharges (of any nature) by the Project Consultant to the Owner in excess of \$25,000 the actual cost of the Owner's audit shall be paid by the Project Consultant.

10.4 Ownership of Documents

- 10.4.1 The Schematic Design and Design Development documents developed under this Contract shall become and be the sole property of the Owner whether the Project for which they were developed is executed or not. The Project Consultant may maintain copies thereof for its records and for its future professional endeavors although the Owner shall bear no liability or any responsibility whatsoever for such use of said documents by the Project Consultant. All or part of the Schematic Design and Design Development documents prepared by the Project Consultant for this project may be used as a prototype for other facilities by the Owner. Any reuse of Schematic Design or Design Development documents developed under this Contract by the Owner or others as permitted by the Owner shall be at the sole discretion of the Owner and at the Owner's sole risk.
- 10.4.2 Provided the Project Consultant has complied with the terms of this Agreement, construction working drawings, specifications and other documents or materials developed after the completion of the design development phase are and shall remain the property of the Project Consultant whether the Project for which they are made is executed or not.
- 10.4.3 The Owner shall be permitted to retain copies, including reproducible and electronic media copies, of drawings, specifications and other documents or materials developed after the Design Development Phase for various informational and reference purposes related to management, maintenance and operation of facilities, establishing construction standards, and various other archival functions without limitation and without subsequent notice to the Project Consultant.
- 10.4.4 The drawings and specifications may be used by the Owner on other projects, or for any other purpose included, but not limited to, for completion of the Project's construction in the event the Project Consultant's services are terminated as per other provisions of this Contract.
- 10.4.5 Submission or distribution to meet official regulatory requirements or for other purposes in connection with the Project is not to be construed as publication in derogation of the Project Consultant's rights.
- 10.4.6 In the event of the Project Consultant's termination under other provisions of this Agreement, the Owner shall receive all original documents prepared to the date of termination and shall have the right to use those documents and any reproductions in any way necessary to complete the Project, or for any other purpose.

- 10.4.7 In the event Owner requests any such documents or materials referred to in this Article and Project Consultant fails to provide same as requested by Owner, then Project Consultant acknowledges that Owner will be irreparably harmed and subject to an injunction to provide same.
- 10.4.8 The Owner will not modify or distribute the documents, including electronic media versions, to third parties except for those purposes listed above without the expressed permission and consent of the Project Consultant. The Owner will delete any title blocks or other marks identifying the originating Project Consultant from any materials so distributed. The Owner will indemnify the Project Consultant against any claims that result from the modification of data and disks by the Owner.

10.5 Electronic Media

10.5.1 Where this Agreement or referenced provisions in the Contract Documents require the Project Consultant to provide information or documents in either electronic or magnetic media, the preparation and format of that media shall conform to the Owner's Electronic Media Submittal Requirements (Attachment 3 to this Agreement).

10.6 Attachments and References

10.6.1 The following named attachments are made an integral part of this Agreement:

.1 Attachment 1: Project Schedule.2 Attachment 2: Project Scope

.3 Attachment 3: Electronic Media Submittal Requirements

.4 Attachment 4: Project Consultant's Invoice Format, Reimbursable and Supplemental

Services Format

.5 Attachment 5: List of Project Team Members

.6 Attachment 6: Authorization to Proceed (ATP) Form

Professional Services Required – page 1 of 3

Project Schedule – page 2 of 3 Professional Fee – page 3 of 3

.7 Attachment 7: Document Submittal Checklist

.8 Attachment 8: Document 00455 – Background Screening

.9 Attachment 9: IRS Form W-9

.10 Attachment 10: Truth in Negotiations Certificate

10.6.2 Online Documents: The following documents shall be downloaded by the Project Consultant and are considered as Attachments to this Contract:

Design Standards

http://www.broward.k12.fl.us/facilities_construction/DSS/DS_Docs/DesignStandards.htm

- Design Criteria
- Design and Material Standards Division 1 thru Division 17
- Document Submittal Checklist for Plan Review

http://www.broward.k12.fl.us/constructioncontracts/D0docs.html

• Specifications – Division 0

State Requirements for Educational Facilities (SREF) latest edition

http://www.fldoe.org/edfacil/sref.asp

• F.I.S.H. layering system for AutoCAD: Note: the laying system is not posted on line. It will need to be requested thru:

Facility Planning and Real Estate 600 SE 3rd Avenue Fort Lauderdale, FL 33312 754-321-1932

10.7 Extent of Agreement:

- 10.7.1 This Agreement represents the entire and integrated Agreement between the Owner and the Project Consultant and supersedes all prior negotiations, representations or agreements, written or oral.
- 10.7.2 This Agreement may not be amended, changed, modified, or otherwise altered in any particular, at any time after the execution hereof, except by resolution of The School Board of Broward County, Florida.
- 10.7.3 This Agreement is for the benefit of the parties to the Agreement and is not for the benefit of any other parties nor shall it create a contractual relationship with any other party.
- 10.7.4 This Agreement shall be governed by the laws of the State of Florida Venue of any action arising out of this Agreement shall be in Broward County, Florida. The parties are encouraged to participate in mediation of any dispute before engaging in litigation.

10.8 Strict Performance:

10.8.1 The failure of either party to insist upon or enforce strict performance by the other party of any of the provisions of this Agreement or to exercise any rights under this Agreement shall not be construed as a waiver or relinquishment to any extent of its rights to assert or rely upon any such provisions or rights in that or any other instance.

10.9 Prompt and Satisfactory Correction:

10.9.1 The Owner, at its sole discretion, may direct the Project Consultant, at no additional cost to the Owner, to promptly and satisfactorily correct any services found to be defective or not in compliance with the requirements of this Agreement or the requirements of any governmental authority, law, regulations or ordinances.

10.10 Successors and Assigns:

- 10.10.1 The performance of this Agreement shall not be delegated or assigned by the Project Consultant without the written consent of the Owner.
- 10.10.2 The Project Consultant and the Owner each binds one another, their partners, successors, legal representatives and assigns to the other party of this Agreement and to the partners, successors, legal representatives and assigns of such party in respect to all covenants of this Agreement.

10.11 Certification Regarding Debarment, Suspension, Ineligibility or Voluntary Exclusion:

10.11.1 Lower Tier Covered Transactions: Executive Order 12549 provides that, to the extent permitted by law, Executive departments and agencies shall participate in a government-wide system for non-procurement debarment and suspension. A person who is debarred or suspended shall be excluded from Federal financial and non-financial assistance and benefits under Federal programs and activities. Except as provided in ß 85.200, Debarment or Suspension, ß 85.201, Treatment of Title IV HEA participation, and ß85.215, Exception provision, debarment or suspension of a participant in a program by one agency shall have government-wide effect. A lower tier covered transaction is, in part, any transaction between a participant [SBBC] and a person other than a procurement contract for goods or services, regardless of type, under a primary covered transaction; and any procurement contract for goods or services between a participant and a person, regardless of type, expected to equal or exceed the Federal procurement small purchase threshold fixed at 10 U.S.C. 2304(g) and 41 U.S.C. 253(g) (currently \$100,000) under a primary covered transaction. A participant may rely upon the certification of a prospective participant in a lower tier covered transaction that it and its principals are not debarred, suspended, proposed for debarment under 48 CFR part 9, subpart 9.4, ineligible, or voluntarily excluded from the covered transaction, unless it knows that the certification is erroneous. Each participant shall require participants in lower tier covered transactions to include the following certification for it and its principals in any proposal submitted in connection with such lower tier covered transactions.

10.11.2 Certification and Disclosure

- .1 The lower tier participant (Project Consultant) certifies, by entering this Agreement, that neither it nor its principals is presently debarred, suspended, proposed for debarment, declared ineligible, or voluntarily excluded from participation in this transaction by any Federal department or agency.
- .2 Where the lower tier participant (Project Consultant) is unable to certify to any of the statements in this certification, such participant shall provide an explanation to the Owner.
- .3 The Consultant warrants that he or she has not employed or retained any company or person, other than a bona fide employee working solely for the Consultant to solicit or secure this Agreement and that he or she has not paid or agreed to pay any person, company, corporation, individual, or firm, other than a bona fide employee working solely for the Consultant any fee, commission, percentage, gift, or other consideration contingent upon or resulting from the award or making of this agreement. For the breach or violation of this provision, the Owner shall have the right to terminate the Agreement without liability and, at its discretion, to deduct from the fees due and owing to the Consultant, or otherwise recover, the full amount of such fee, commission, percentage, gift, or consideration. (Ch. 287.055, F.S.)

10.12 Non-Discrimination, EEO, and ADAAA

- 10.12.1 **Non-Discrimination -** The School Board of Broward County, Florida prohibits any policy or procedure which results in discrimination on the basis of age, color, disability, gender, national origin, marital status, race, religion or sexual orientation.
- 10.12.2 Equal Employment Opportunity (EEO) The School Board of Broward County, Florida, prohibits any

policy or procedure which results in discrimination on the basis of age, color, disability, gender identity, gender expression, national origin, marital status, race, religion, sex or sexual orientation. Individuals who wish to file a discrimination and/or harassment complaint may call the Executive Director, Benefits & EEO Compliance at 754-321-2150 or Teletype Machine (TTY) 754-321-2158.

10.12.3 Americans with Disabilities Act Amendments Act of 2008 - Individuals with disabilities requesting accommodations under the Americans with Disabilities Act Amendments Act of 2008, (ADAAA) may call Equal Educational Opportunities (EEO) at 754-321-2150 or Teletype Machine (TTY) 754-321-2158.

10.13 Captions

10.13.1 Captions – The captions, section numbers, article numbers, title and headings appearing in this Agreement are inserted only as a matter of convenience and in no way define, limit, construe or describe the scope or intent of such articles or sections of this Agreement, nor in any way effect this Agreement and shall not be construed to create a conflict with the provisions of this Agreement.

10.14 Authority

10.14.1 **Authority Provision:** Each person signing this agreement on behalf of either party individually warrants that he or she has full legal power to execute this Agreement on behalf of the party for whom he or she is signing, and to bind and obligate such party with respect to all provisions contained in this Agreement.

10.15 Notice

Notice Provision: When any of the parties desire to give notice to the other, such notice must be in writing, sent by US Mail, postage prepaid, addressed to the party for whom it is intended at the place last specified; the place for giving notice shall remain such until it is changed by written notice in compliance with the provisions of the paragraph. For the present, the parties designate the following as the respective places for giving notice.

To SBBC: Superintendent of Schools

The School Board of Broward County, Florida

600 Southeast Third Avenue Fort Lauderdale, Florida 33301

With a Copy to: Office of the Chief Facilities Officer

600 SE 3 Avenue

Fort Lauderdale, FL 33312 **Attn: Leo Bobadilla** Chief Facilities Officer

With a Copy to: Office of Facilities and Construction

3775 SW 16th St

Fort Lauderdale, FL 33312 **Attn: Shelley N. Meloni**

Director, Pre-Construction Office of Facilities and Construction

And

Heery International, Owners Representative

811 Ponce de Leon Boulevard Coral Gables, FL 33134

Attn: Robert Corbin

Program Director/Vice President

To Design Professional: Insert Name and Address Provided by Other Party

With a Copy to: Insert Name and Address Provided by Other Party

10.16 Excess Funds

10.16.1 Any party receiving funds paid by The School Board of Broward County, Florida (SBBC) under this Agreement agrees to promptly notify SBBC of any funds erroneously received from SBBC upon the discovery of such erroneous payment or overpayment. Any such excess funds shall be refunded to SBBC with interest calculated from the date of the erroneous payment or overpayment. Interest shall be calculated using the interest rate for judgments under Section 55.03, Florida Statutes, applicable at the time the erroneous payment or overpayment was made by SBBC.

10.17 Background Screening

10.17.1 **Background Screening**. Project Consultant agrees to comply with all requirements of Sections 1012.32 and 1012.465, Florida Statutes, and that Project Consultant, its agents, subconsultants and all of its personnel who (1) are to be permitted access to school grounds when students are present, (2) will have direct contact with students, or (3) have access or control of school funds will successfully complete the background screening required by the referenced statutes and meet the standards established by the statutes. This background screening will be conducted by SBBC in advance of Project Consultant or its personnel providing any services under the conditions described in the previous sentence. Project Consultant will bear the cost of acquiring the background screening required by Section 1012.32, Florida Statutes, and any fee imposed by the Florida Department of Law Enforcement to maintain the fingerprints provided with respect to Project Consultant and its personnel. The Parties agree that the failure of Project Consultant to perform any of the duties described in this section shall constitute a material breach of this Agreement entitling SBBC to terminate immediately with no further responsibilities or duties to perform under this Agreement.

Project Consultant agrees to indemnify and hold harmless SBBC, its officers and employees from any liability in the form of physical or mental injury, death or property damage resulting from Project Consultant's failure to comply with the requirement of this Section or Section 1012.32 and Section 1012.465, Florida Statutes in addition to any other indemnification obligations that may be imposed upon Project Consultant pursuant to Article 8 of this Agreement and the laws of Florida.

10.18 Errors and Omissions

10.18.1 The Project Consultant shall be responsible for any errors, inconsistencies or omissions in the drawings, specifications, and other documents. The Project Consultant will correct the drawings and specifications at no additional design cost to the Owner for any and all errors and omissions in the drawings, specifications prepared by the Project Consultant. The Project Consultant further agrees, at no additional cost, to render assistance to the Owner in resolving problems relating to the design or specified materials.

10.18.2 Deductions may be made from the Project Consultant's Basic Services Compensation on account of errors and omissions in the drawings, specifications and other documents prepared by the Project Consultant or in the Project Consultant's performance of its obligations under this Agreement.

ARTICLE 11 INCORPORATION OF RFQ INTO AGREEMENT

11.1 In addition to those Attachments and References identified and made part of this Agreement in Article 10.6.1, the provisions of RFQ No. XXX ("TYPE OF SERVICE") (the "RFQ") are hereby incorporated into this Agreement. In the event of conflict between the provisions contained in this Agreement and the RFQ, the more stringent provision shall prevail. If this Agreement is silent on an issue that is contained with the RFQ, the provisions of the RFQ shall be followed.

IN WITNESS WHEREOF, The School Board of Broward County, Florida, has caused this Agreement to be executed by the undersigned and the seal of the School Board to be set hereto; and the said Project Consultant has caused this Agreement to be executed by the undersigned and the seal of the Project Consultant set hereto on this day and year first above written.

THE SCHOOL BOARD OF BROWARD COUNTY, FLORIDA

(SEAL)		
ATTEST THE SCHOOL BOARD OF BROWARD COUNTY, FLORIDA		
Robert W. Runcie, Superintendent of Schools	Dr. Rosalind Osgood, Chair	
Approved as to Form and Legal Content:		
Office of the General Counsel		
DELETE THE SIGNATURE SECTIONS NOT USED		
WHEN THE PROJECT CONSULTANT IS A CORPORATION OR PROFESSIONAL ASSOCIATION		
(Corporate Seal)		
(ATTEST)	(Type Name of Firm Here) Legal Name of Corporation	

Secretary, (Type Name Here)
(Type Registration Number Here)
Project Consultant's
Registration Number

WHEN THE PROJECT CONSULTANT IS AN INDIVIDUAL OR PARTNERSHIP

(ATTEST)	
Witness (Type Name Here)	Legal Name of Individual or Partnership
Witness (Type Name Here)	By: Signature (Type Name Here)
	Project Consultant's Registration Number
WHEN THE PROJEC	T CONSULTANT IS A JOINT VENTURE
(Corporate Seal)	(Corporate Seal)
Firm's Legal Name	Firm's Legal Name
By:	By:Signature (Type Name Here)

	Project Consultant's Registration Number
(ATTEST)	
Witness (Type Name Here)	Witness (Type Name Here)
Witness (Type Name Here)	Witness (Type Name Here)

ACKNOWLEDGEMENT

STATE OF FLORIDA COUNTY OF BROWARD

BEFORE ME this	day of	,	, appeared	, and,
		_ personally known t	o me to be the persons des	cribed in and who executed
the foregoing contract an	nd acknowledge	that he executed the	same as his free act and de	eed for the purposes therein
expressed.				
WITNESS my hand a	and official seal	l in the County ar	nd State last official thi	isday of
	, 201			
Notary Public State of F	lorida			
My Commission Expires	s:			

				Owner's Initial Schooling	
Activity ID	Activity Name	Remaining	Start	Finish	oute 2014 2015 2016
		Duration			A S O N D J F M A M J Jul A S O N D J F M A M
SCHEDULE	<u> </u>	324	08-Jul-14	02-Jun-15	Q2-Jun-15, SCHEDULE
DESIGN		26	08-Jul-14	13-Oct-14	13-Oct-14, DESIGN
A1000	Pre-Design	7	08-Jul-14	14-Jul-14	Pre-Design
A1010	Authorization to Proceed (ATP)	0	15-Jul-14		Authorization to Proceed (ATP)
A1020	Schematic Design (30%)	21	15-Jul-14	04-Aug-14	Schematic Design (30%)
A1030	Plan Review - Schematic Design	2	05-Aug-14	09-Aug-14	Plan Review - Schematic Design
A1040	Design Development (60%)	28	10-Aug-14	07-Sep-14	Design Development (60%)
A1050	Plan Review - Design Development	2	08-Sep-14	12-Sep-14	Plan Review - Design Development
A1060	90% Constuction Documents	41	13-Sep-14	26-Sep-14	90% Constuction Documents
A1070	Plan Review - 90% Construction Documents	2	27-Sep-14	01-Oct-14	Plan: Review - 90% Construction Documents
A1080	100% Construction Documents	7	02-Oct-14	08-Oct-14	100% Construction Documents
A1090	Plan Review - 100% Construction Documents	2	09-Oct-14	13-Oct-14	Plan Review - 100% Construction Documents
A1100	Submittal of 100% CDs to Building Dept.	0		13-Oct-14	Submittal of 100% CDs to Building Dept.
PERMITTING	ING	26	14-Oct-14	08-Nov-14	V8-Nov-14, PERMITTING
A1110	Building Deparment Initial Plan Review	41	14-Oct-14	27-0ot-14	Building Department Initial Plan Review
A1120	Plan Revisions by Design Professional	7	28-Oct-14	03-Nov-14	Plan Revisions by Design Professional
A1130	Resubmittal of revised Plans to Building Dept.	0	04-Nov-14		Resubmittal of revised Plans to Building Dept.
A1140	Building Department 2nd Plan Review	5	04-Nov-14	08-Nov-14	Building Department 2nd Plan Review
A1150	Permit Approval	0		08-Nov-14	Permit Approval
PROCUREMENT	EMENT	21	09-Nov-14	01-Dec-14	OI-DEC-14, PROCUREMENT.
A1160	Procurement	21	09-Nov-14	01-Dec-14	Procurement
CONSTRUCTION	UCTION	180	02-Dec-14	02-Jun-15	▼ C2-Jun-15, CONSTRUCTION
A1170	Construction & Closeout	180	02-Dec-14	02-Jun-15	Gonstruction & Closeout

Electronic Media Requirements

All Work product for all projects, requires hard copies, electronic copies (PDF) and electronic original copies. The electronic media requirements are as listed below.

ELECTRONIC MEDIA

1.0 General Information

1.1 The School Board of Broward County, Florida contracts with one or more Internet bid advertising and distribution services. The Design Professional shall post the complete bid package to these services upon written notification by the Owner. The posted documents shall be read only documents and the file format shall be PDF.

2.0 Software Requirements

- 2.1 Word Processing
 - 2.1.1 Provide word processing files in Microsoft Word for Windows compatible file formats including all information necessary for remote printing.
- 2.2 Spreadsheets
 - 2.2.1 Provide spreadsheet files in Microsoft Excel for windows compatible file formats including all information necessary for remote printing.
- 2.3 Computer aided Design and Drafting
 - 2.3.1 Provide all CADD files as AutoCAD 2010 files, Window's version.

3.0 CAD Standards

- 3.1 Standard plotted drawing size: 24 inch x 36 inch or 30 inch x 42 inch sheets.
 - 3.1.1 All sheets within a set shall be the same size unless pre-approved otherwise. (for example survey sheets)
- 3.2 Design Professional shall provide to the Owner the standard file naming Protocol they will be utilizing.
- 3.3 CAD File Layering
 - 3.3.1 Conform to the most up to date guidelines defined by the American Institute of Architects (AIA) standard document, "CAD Layer Guidelines."
 - 3.3.2 Provide the required Layering for the Florida Inventory of Schoolhouses (F.I.S.H.) documents
 - 3.3.1.1 The F.I.S.H. layering scheme is not available on-line. It can be requested through:

- 3.3.3 Provide a separate list of all layers which do not conform to the standard AIA CAD Layer Guidelines or the FISH layering scheme.
- 3.4 No custom hatch patterns shall be utilized.
- 3.5 All symbols and blocks to have descriptive names
- 4.0 Electronic Media Delivery Requirements
 - 4.1 Transmittals shall include the following
 - 4.1.1 The Project Number, Project Title and date
 - 4.1.2 The Facility Name
 - 4.1.3 The submittal type
 - 4.1.4 The format and version of the software.
 - 4.1.5 An attached Listing of file names with the latest document publish dates
 - 4.2 All electronic media shall contain an attached label which shall identify 4.1.1, 4.1.2, and 4.1.3.
 - 4.3 Document clean-up
 - 4.3.1 Before a CADD file is placed on the delivery electronic digital media, the following procedures shall be performed:
 - 4.3.1.1 Purge all files and remove all extraneous graphics outside the border area.
 - 4.3.1.2 Make sure all reference files are attached without device path
 - 4.3.1.3 All required project files both graphic and nongraphic, shall include color tables, pen tables, font libraries, block libraries, user command files, plot files, etc. All project related blocks must be provided to the Owner as a part of the electronic digital deliverables.
 - 4.3.1.4 Make sure that all support files such as those listed above are in the same directory and that references to those files do not include device Path.
 - 4.4 The following Plot File Development and Project Documentation Information shall be submitted as an enclosure or attachment to the transmittal letter provided with each electronic digital media submittal.
 - 4.4.1 Documentation of the plot files for each drawing which will be needed to be able to allow identical plotting by the Owner at a later date. This documentation shall include the plotter configuration (e.g., name and model of plotter), pen settings, drawing orientation, drawing

size, and any other special instructions.

- 4.4.2 Instructions concerning how to generate plotted, drawings from the provided plot files.
- 4.5 Provide all symbols and blocks used in the project in a separate files.
- 4.6 List of all database/spreadsheet files associated with each drawing, as well as a description and documentation of the database format.
- 5.0 Ownership: Refer to Agreement for specific Owner and Design Professional's rights.
- 6.0 Documents for the Construction Contractor:
 - 6.1 The Owner and the Design Professional shall make various electronic information available to the Contractor during the Construction phase of the Project.
- 7.0 Where electronic media submittals of final site surveys are required: Provide electronic copies of any existing site survey data already on electronic media.
- 8.0 At the Contractors option, the Design Professional will provide the Contractor one set of AutoCAD (.dwg) electronic file format contract drawings, to be used for as built drawings at the Contractor's option. Note that the Architect's name and information to be removed.

Design Professionals Invoice Format

The School Board of Broward County, Florida requires submittal of the Design Professional's invoice on the District's standard invoice forms attached to a transmittal form or letter on the Design Professional's company letterhead. Include the information and attachments described below:

- 1. Letterhead Containing Firm Information
 - A. Firm Name
 - B. Address
 - C. Telephone and FAX Numbers
 - D. Consultant's Invoice Reference Number
- 2. Address Transmittal/Letter to:

Office of Facilities and Construction The School Board of Broward County, Florida 3775 SW 16th Street Fort Lauderdale, FL 33312 Attention: Name of Project Manager

- 3. Ensure that Transmittal/Letter references the following information:
 - A. Date of submittal.
 - B. The Invoice Number for ATP Number (example: Invoice No. 01 for ATP No. 01).
 - C. The School Board of Broward County's Purchase Order No.: (Which will be provided by the Facilities Project Manager at the beginning of the project.)
 - D. Name of Facility (and Facility Number).
 - E. Name of Project
 - F. School Board Project Number
- 4. Ensure attachment of the following documents to the Transmittal/Letter:
 - A. Design Professional's Invoice Form
 - B. Design Professional's Reimbursable Invoice Form
 - C. Copy of signature page (page 3 of 3) of the Design Professional's Authorization to Proceed.



The School Board of Broward County, Florida Florida Facilities and Construction Management Department 3775 SW 16th Street Fort Lauderdale, FL 33312 (754) 321-1500

Design Professional	Date:
Design Professional	Date.

(Name)

Project No: Facility Name: Invoice No: Project Title: SBBC PO No. Design Professional's ATP No. Remit to address: Invoice From:

Project Manager

Original Basic Fee	\$
Current basic fee	\$

INVOICE TOTALS:

Summary	Current Fee	Previously Billed	This Invoice	Balance
Basic Services	\$	\$	\$	\$
Reimbursable	\$	\$	\$	\$
Total:	\$	\$	\$	\$

BASIC FEE TOTALS:

Period	Fee	Previously Bille	ed .		This	Invoice	Balance	
From to dates	\$	\$	%	\$		%	\$	%
	\$	\$	%	\$		%	\$	%
	\$	\$	%	\$		%	\$	%
	\$	\$	%	\$		%	\$	%
	\$	\$	%	\$		%	\$	%
Other Services	\$	\$	%	\$		%	\$	%
Total Previously	Billed:	\$						 _
Total Amount T	his Invoice:			\$				
Total Balance:				•				\$

Submitted By: Name:	Certified By: Name: Title:	Recommended By:	Approved By:
Title: Date: (Signature)	Project Manager Date:	Name: Title: Date:	Name: Title: Date:
	(Signature)	(Signature)	(Signature)



The School Board of Broward County, Florida Florida Facilities and Construction Management Department 3775 SW 16th Street Fort Lauderdale, FL 33312 (754) 321-1500

Design Professional's Reimbursable Invoice
--

Project No:	Facility Name: Invoice No:	
Project Title:	SBBC PO No.	
Design Professional's:	ATP No.	
Remit to address:	Invoice From:	
	Project Manager:	

Item No.	Date	Reimbursable Item	Amount
		Invoice Total	\$

Receipts for each Item must be attached.

Current Contract Amount:

Total This Invoice:

Total Previously Billed:

Total Balance:

Submitted By: Name:	Certified By: Name: Title:	Recommended By:	Approved By: Name: Title:
Title: Date:	Project Manager Date:	Name: Title: Date:	Date:
(Signature)	(Signature)	(Signature)	(Signature)

PSA Attachment 6



The School Board of Broward County, Florida **Office of Facilities & Construction** 3775 S.W. 16th Street

Fort Lauderdale, Florida 33312

(754) 321-1500

Consultant's Authorization To Proceed						
Project No.:		Date:				
Location No.:		SDDC D C. N.				
Project Title:		SBBC P.O. No.:				
		Line No.:				
Facility Name:		Project Manager:				
Project Consultant:		Dir. Capital Planni	ng & Programming			
Under the mor	visions of vov	a contract for professional convices	you are housey outhonized to mucoood with the			
		ject referenced above.	you are hereby authorized to proceed with the			
following service	ees for the pro	jeet referenced above.				
Schematic Design	Design	n Development	Construction Documents			
Bidding		ruction Contract Administration	Warranty			
Other Services:	Attached	:				
_	-					
This Authorizat	tion to Proceed	l is subject to the following attachmen	ts:			
Augustus Deutschen Deutschen Bereitung						
Attachments: Professional Services Required Project Schedule						
	Project Schedule Professional Fees					
	Previous	ATP's				
			onal Services Required with a Fixed Limit of			
Construction Co	ost (FLCC) to	r this project as indicated below:				
Original FLCO	C	Current Cost Estimate	Revised FLCC by ATP			
31-6-1111						
			•			
		ervices will be provided by the Project	Consultant as a normal part of its Basic Services			
for the Project 1	isted above:					
Item	Discipline	Description				
пеш	Discipline	Description				

PSA Attachment 6



The School Board of Broward County, Florida Office of Facilities & Construction 3775 S.W. 16th Street Fort Lauderdale, Florida 33312

(754) 321-1500

Consultant's Authorization To Proceed (Term Contracts) Cont.

	Project Schedule		
Project No. & Location No.:	Project Title:		
Facility Name: Project Consultant:			
The required project schedule milestones for th	is project are presented below. (N	Iandatory)	
ACTIVITY Schematic Design		Date Required Or Estin Start	nated Time Period Finish
Design Development			
Construction Documents Development			
50% Construction Documents			
100% Construction Documents			
Bidding and Award of Contract			
Time for Permitting of Submittals, Prior to the Issuance of the Construction NTP (Part of Contract Administration)		
Construction			
Warranty			

PSA Attachment 6



The School Board of Broward County, Florida **Office of Facilities & Construction** 3775 S.W. 16th Street

Fort Lauderdale, Florida 33312

(754) 321-1500

	Consultant's Authorization To Proceed (Term Contracts)				
		Profession	nal Fees		
Project No. & Location No.:		Project Tit	le:		
Facility Name: Project Consultant:					
Phase	Original Basic Fee	Fee Authorized by ATP	Fee Previously Paid	Fee Balance	
I (SD) (5%)		%	%	%	
II (DD) (10%)		%	%	%	
III (CD) (35%/60%)		%	%	%	
IV (BID) (65%)		%	%	%	
V (CA) (98%)		%	%	%	
VI (Warr) (100%)		%	%	%	
Other Service		%	%	%	
Item No. 1					
Other Service		%	%	%	
(Item No. 2)					
Other Service		%	%	%	
(Item No. 3)					
Other Service		%	%	%	
(Item No. 4)					
Total:					
Payment for	these services shall	be made In accordance with	h the provisions of the Prot	fessional Services Agreement.	

Approved By Consultant			Recommended By SBBC			
Name:		Name: Shelley N. Meloni				
Title:		Title: Director, Pre-Construction				
Signature:		Date:		Signature:		Date
Certified By SBBC		Approval by SBBC				
Name:		Name: Leo Bobadilla				
Title:		Title: Chief Facilities Officer				
Signature:		Date:		Signature:		Date

This document is part of the Professional Services Agreement between The School Board of Broward County, Florida (Owner) and the Design Professional and is incorporated by reference into the terms and conditions of that agreement.

Form W-9 (Flow, August 2013) Department of the Treasury

Request for Taxpayer Identification Number and Certification

Give Form to the requester. Do not send to the IRS.

internal	Rayenua Sarvice		
	Name (as shown o	on your income tax return)	,
ci e	Business name/dis	sregarded entity name, if different from above	
e bad uo si	Check appropriate	Examptions (see Instructions):	
Print or type See Specific Instructions on	Limited liabili	Examption from FATCA reporting code (if any)	
돌트	Other (see in	ostructions) >	A ***
affic.			ame and address (optional)
See Spe	City, state, and Zit	P code	
"	List account numb	ber(s) here (optional)	
Par	Tayna	aver Identification Number (TIN)	
			al security number
to avo	id backup withho nt alien, sole proj	olding. For Individuals, this is your social security number (SSN). However, for a prietor, or disregarded entity, see the Part I Instructions on page 3. For other over identification number (EIN). If you do not have a number, see How to get a	□-□-□
Note.		In more than one name, see the chart on page 4 for guidelines on whose	oyer identification number
Part	Certifi	ication	
Under	penalties of perju	ury, I certify that:	
1. The	e number shown	on this form is my correct taxpayer identification number (or I am waiting for a number to b	de issued to me), and
Ser	rvice (IRS) that I a	backup withholding because: (a) I am exempt from backup withholding, or (b) I have not be am subject to backup withholding as a result of a failure to report all interest or dividends, o backup withholding, and	
3. I an	n a U.S. citizen o	or other U.S. person (defined below), and	
4. The	FATCA code(s) e	entered on this form (if any) indicating that I am exempt from FATCA reporting is correct.	
Interes genera Instruc	se you have falle st paid, acquisitio ally, payments ot ctions on page 3.	ons. You must cross out Item 2 above if you have been notified by the IRS that you are our of to report all interest and dividends on your tax return. For real estate transactions, Item 2 on or abandonment of secured property, cancellation of debt, contributions to an individual ther than interest and dividends, you are not required to sign the certification, but you must	does not apply. For mortgage I retirement arrangement (IRA), and
Sign Here			
		A DECEMBER OF THE PROPERTY OF	

General Instructions

Section references are to the Internal Revenue Code unless otherwise noted.

Future developments. The IRS has created a page on IRS.gov for information about Form W-9, at www.hs.gov/w9. Information about any future developments affecting Form W-9 (such as legislation enacted after we release it) will be posted on that page.

Purpose of Form

A person who is required to flie an information return with the IRS must obtain your correct taxpayer identification number (TIN) to report, for example, income paid to you, payments made to you in settlement of payment card and third party network transactions, real estate transactions, mortgage interest you paid, acquisition or abandonment of secured property, cancellation of debt, or contributions you made to an IRA.

Use Form W-9 only if you are a U.S. person (including a resident aller), to provide your correct TIN to the person requesting It (the requester) and, when applicable, to:

- Cortify that the TIN you are giving is correct (or you are waiting for a number to be issued),
- 2. Certify that you are not subject to backup withholding, or
- Claim exemption from backup withholding if you are a U.S. exempt payee. If applicable, you are also certifying that as a U.S. person, your allocable share of any partnership income from a U.S. trade or business is not subject to the

withholding tax on foreign partners' share of effectively connected income, and 4. Certify that FATCA code(s) entered on this form (if any) indicating that you are exempt from the FATCA reporting, is correct.

Note. If you are a U.S. person and a requester gives you a form other than Form W-9 to request your TIN, you must use the requester's form if it is substantially similar to this Form W-9.

Definition of a U.S. person. For federal tax purposes, you are considered a U.S. person if you are:

- . An individual who is a U.S. citizan or U.S. resident allen,
- A partnership, corporation, company, or association created or organized in the United States or under the laws of the United States,
- . An estate (other than a foreign estate), or
- A domestic trust (as defined in Regulations section 301.7701-7).

Special rules for partnerships. Partnerships that conduct a trade or business in the United States are generally required to pay a withholding tax under section 1446 on any foreign partners' share of offschiely connected taxable income from such business. Further, in certain cases where a Form W-9 has not been received, the rules under section 1446 require a partnership to presume that a partner is a foreign person, and pay the section 1446 withholding tax. Therefore, if you are a U.S. person that is a partner in a partnership conducting a trade or business in the United States, provide Form W-9 to the partnership to establish your U.S. status and avoid section 1446 withholding on your share of partnership income.

Cat. No. 10231X Form W-9 (Flov. 8-2013)

Page 2 Form W-9 (Rev. 8-2013)

In the cases below, the following person must give Form W-9 to the partnership for purposes of establishing its U.S. status and avoiding withholding on its allocable share of not income from the partnership conducting a trade or business in the United States:

- In the case of a disregarded entity with a U.S. owner, the U.S. owner of the disregarded entity and not the entity,
- In the case of a grantor trust with a U.S. grantor or other U.S. owner, generally, the U.S. grantor or other U.S. owner of the grantor trust and not the trust, and
- In the case of a U.S. trust (other than a granter trust), the U.S. trust (other than a granter trust) and not the beneficiaries of the trust.

Foreign person, if you are a foreign person or the U.S. branch of a foreign bank that has elected to be treated as a U.S. person, do not use Form W.9. Instead, u the appropriate Form W-8 or Form 8233 (see Publication 515, Withholding of Tax on Normaldent Allens and Foreign Entities).

Nonresident alien who becomes a resident alien. Generally, only a nonresident alien individual may use the terms of a tax treatly to reduce or eliminate U.S. tax or certain types of income. However, most tax treatles contain a provision known as a "serving clause." Exceptions specified in the saving clause may permit an examption from tax to continue for certain types of income even after the payee has otherwise become a U.S. resident alien for tax purposes.

If you are a U.S. resident allen who is relying or an exception contained in the saving clause of a tax treaty to claim an exemption from U.S. tax on certain types of income, you must attach a statement to Form W-9 that specifies the following flee tarms:

- The treaty country. Generally, this must be the same treaty under which you claimed exemption from tax as a nonresident alien.
- 2. The treaty article addressing the income.
- 3. The article number (or location) in the tax treaty that contains the saving clause and its exceptions.
- 4. The type and amount of income that qualifies for the exemption from tax.
- 5. Sufficient facts to justify the examption from tax under the terms of the treaty

Example. Article 20 of the U.S.-China income tax treaty allows an exemption from tax for scholarship income received by a Chinese student temporarity present in the United States. Under U.S. taw, this student will become a resident allen for tax purposes if his or her stay in the United States exceeds 5 calander years. However, paragraph 2 of the first Protocol to the U.S.-China treaty (dated April 30, However, paragraph 2 of the inter Protocol to the U.S.-China treaty (cased April 30, 1984) allows the provisions of Article 20 to continue to apply even after the Chinese student becomes a resistent alien of the United States. A Chinese student who qualifies for this exception (under paragraph 2 of the first protocol) and is relying on this exception to claim an exemption from tax on his or her scholarship or fallowship income would attach to Form W-9 a statement that includes the information described above to support that exemption.

If you are a norresident alien or a foreign entity, give the requester the ppropriate completed Form W-8 or Form 8233.

appropriate completed Form W-8 or Form 8233.

What is backup withholding? Persons making certain payments to you must under certain conditions withhold and pay to the IRS a percentage of such payments. This is called "backup withholding." Payments that may be subject to backup withholding include interest, tax-exemple interest, dividends, broker and barter exchange transactions, rants, royalties, nonemployee pay, payments made in softlement of payments and third party network transactions, and certain payments from fishing boat operators. Real estate transactions are not subject to backup withholding.

You will not be subject to backup withholding on payments you receive if you give the requester your correct TIN, make the proper certifications, and report all your taxable interest and dividends on your tax return.

Payments you receive will be subject to backup withholding if:

- 1. You do not furnish your TIN to the requester,
- 2. You do not certify your TIN when required (see the Part II instructions on page
- 3. The IRS tells the requester that you furnished an incorrect TIN,
- The IRS tells you that you are subject to backup withholding because you did not report all your interest and dividends on your tax return (for reportable interest and dividends only), or
- You do not cartify to the requester that you are not subject to backup withholding under 4 above (for reportable interest and dividend accounts opened after 1983 only).

Certain payoes and payments are exempt from backup withholding. See Exempt payoe code on page 3 and the separate instructions for the Requester of Form W-9 for more information.

Also see Special rules for partnerships on page 1.

What is FATCA reporting? The Foreign Account Tax Compilance Act (FATCA) requires a participating foreign financial institution to report all United States account holders that are specified United States persons. Certain payees are exempt from FATCA reporting. See Exemption from FATCA reporting code on page 3 and the Instructions for the Requester of Form W-9 for more information.

Updating Your Information

You must provide updated information to any person to whom you claimed to be an axempt payee if you are no longer an exempt payee and anticipate receiving reportable payments in the future from this person. For example, you may need to provide updated information if you are a C corporation that elects to be an S corporation, or if you no longer are tax exempt. In addition, you must furnish a new Form W-9 if the name or TIN changes for the account, for example, if the grantor of a strately that they of a grantor trust dies.

Failure to furnish TIN. If you fail to furnish your correct TIN to a requester, you are subject to a penalty of \$50 for each such failure unless your failure is due to reasonable cause and not to willful neglect.

Civil penalty for false information with respect to withholding. If you make a false statement with no reasonable basis that results in no backup withholding, you are subject to a \$500 penalty.

Criminal penalty for faisitying information. Willfully faisitying certifications or affirmations may subject you to criminal penalties including fines and/or imprisonment.

suse of TINs, if the requester discloses or uses TINs in violation of federal law, requester may be subject to civil and criminal penalties.

Specific Instructions

if you are an individual, you must generally enter the name shown on your income tax return. However, if you have changed your last name, for instance, due to marriage without informing the Social Security Administration of the name change, enter your first name, the last name shown on your social security card, and your now last name.

If the account is in joint names, list first, and then circle, the name of the person or entity whose number you entered in Part I of the form.

Sole proprietor. Enter your individual name as shown on your income tax return on the "Name" line. You may enter your business, trade, or "doing business as (DBA)" name on the "Business name/disregarded entity name" line.

Partnership, C Corporation, or S Corporation. Enter the entity's name on the "Name" line and any business, trade, or "doing business as (DBA) name" on the "Business name/disregarded entity name" line.

Disregarded entity. For U.S. toderal tax purposes, an entity that is disregarded as an entity separate from its owner is treated as a "disregarded entity." See Regulation section 301.7701-2(c)(2)(ii). Enter the owner's name on the "Name" line. The name of the entity entered on the "Name" line should never be a disregarded entity. The name on the "Name" line must be the name shown on the disregarded ontity. The name on the "Name" line must be the name shown on the income tax return on which the income should be reported. For example, if a foreign LLC that is treated as a disregarded entity for U.S. federal tax purposes has a single owner that is a U.S. person, the U.S. owner's name is required to be provided on the "Name" line. If the direct owner of the entity is also a disregarded entity, enter the first owner that is not disregarded for federal tax purposes. Enforthed disregarded entity's name on the "Business name/disregarded entity name" line. If the owner of the disregarded entity is a foreign person, the owner must complete an appropriate Form W.-8 instead of a Form W.-9. This is the case even if the foreign person person have a U.S. Till. the foreign person has a U.S. TIN.

Note. Chack the appropriate box for the U.S. federal tax classification of the person whose name is entered on the "Name" line (Individual/sole proprietor, Partnership, C Corporation, S Corporation, Trust/estate).

Partnership, C Corporation, S Corporation, Trust/estate).

Limited Liability Company (LLC). If the person identified on the "Name" line is an LLC, check the "Limited liability company" box only and enter the appropriate code for the U.S. federal tax classification in the space provided, if you are an LLC that is treated as a partnership for U.S. federal tax purposes, enter "P" for partnership. If you are an LLC that has filed a Form 8832 or a Form 2553 to be taxed as a corporation, enter "C" for C corporation or "S" for S corporation, as appropriate. If you are an LLC that is disregarded as an entity separate from its owner under Regulation section 301.7701-3 (except for employment and excise tax), do not check the LLC box unless the owner of the LLC (regulared to be identified on the "Name" line) is another LLC that is not disregarded for U.S. footral fax purposes. If the LLC is disregarded as an entity separate from its owner, enter the appropriate tax classification of the owner identified on the "Name" line) in the lack of the owner identified on the "Name" line). "Name" line.

Other entitles. Enter your business name as shown on required U.S. federal tax documents on the "Name" line. This name should match the name shown on the charter or other legal document creating the entity. You may enter any business, trade, or DBA name on the "Business name/disregarded entity name" line.

Exemptions

If you are exempt from backup withholding and/or FATCA reporting, enter in the Exemptions box, any code(s) that may apply to you. See Exempt payee code and Exemption from FATCA reporting code on page 3.

Form W-0 (Rev. 8-2013) Page 3

Exempt payee code. Generally, individuals (including sole proprietors) are not exampt from backup withholding. Corporations are exempt from backup withholding for contain paymonts, such as interest and dividends. Corporations are not exampt from backup withholding for payments made in settlement of payment card or third party network transactions.

Note. If you are exampt from backup withholding, you should still complete this form to avoid possible erroneous backup withholding.

The following codes identify payees that are exempt from backup withholding:

- 1—An organization exempt from tax under section 501(a), any IRA, or a custodial account under section 403(b)(7) if the account satisfies the requirements of section 401(f)(2)
- 2-The United States or any of its agencies or instrumentalities
- 3—A state, the District of Columbia, a possession of the United States, or any of their political subdivisions or instrumentalities
- 4—A foreign government or any of its political subdivisions, agencies, or instrumentalities
- 5-A corporation
- 6—A dealer in securities or commodities required to register in the United States, the District of Columbia, or a possession of the United States
- 7—A futures commission merchant registered with the Commodity Futures Trading Commission
- 8-A real estate investment trust
- $9-\text{An ontity registered at all times during the tax year under the investment Company Act of 1940$
 - 10-A common trust fund operated by a bank under section 584(a)
 - 11-A financial institution
- 12—A middleman known in the investment community as a nominee or custodian
- 13-A trust exampt from tax under section 664 or described in section 4947

The following chart shows types of payments that may be exempt from backup withholding. The chart applies to the exempt payees listed above, 1 through 13.

IF the payment is for	THEN the payment is exempt for
Interest and dividend payments	All exempt payees except for 7
Broker transactions	Exempt payees 1 through 4 and 6 through 11 and all C corporations. S corporations must not enter an exempt payee code because they are exempt only for sales of noncovered securities acquired prior to 2012.
Barter exchange transactions and patronage dividends	Exempt payous 1 through 4
Payments over \$600 required to be reported and direct sales over \$5,000 f	Generally, exempt payees 1 through 5 ²
Payments made in settlement of payment card or third party network transactions	Exempt payees 1 through 4

See Form 1009-MISC, Miscellaneous Income, and its instructions.

Examption from FATCA reporting code. The following codes identify payees that are exempt from reporting under FATCA. These codes apply to persons submitting this form for accounts maintained outside of the United States by certain foreign financial institutions. Therefore, if you are only submitting this form for an account you hold in the United States, you may leave this field blank. Consult with the person requesting this form if you are uncertain if the financial institution is subject to these requirements.

- A-An organization exampt from tax under section 501(a) or any individual retirement plan as defined in section 7701(a)(37)
 - B-The United States or any of its agencies or instrumentalities
- C—A state, the District of Columbia, a possession of the United States, or any of their political subdivisions or instrumentalities
- D.—A corporation the stock of which is regularly traded on one or more established securities markets, as described in Reg. section 1.1472-1 (c)(1)(i)
- E—A corporation that is a member of the same expanded affiliated group as a corporation described in Reg. section 1.1472-1(c)(1)(1)
- F—A dealer in securities, commodities, or derivative financial instruments (including notional principal contracts, futures, forwards, and options) that is registered as such under the laws of the United States or any state

- G-A real estate investment trust
- H—A regulated investment company as defined in section 861 or an entity registered at all times during the tax year under the investment Company Act of 1640
- I-A common trust fund as defined in section 584(a)
- J-A bank as defined in section 581
- K-A broker
- L-A trust exempt from tax under section 664 or described in section 4947(a)(1)
- M-A tax exempt trust under a section 403(b) plan or section 457(g) plan

Part I. Taxpaver Identification Number (TIN)

Enter your TIN in the appropriate box. If you are a resident alian and you do not have and are not eligible to get an SSN, your TIN is your IRS individual taxpayer identification number of TIN). Enter it in the social security number box. If you do not have an ITIN, see How to get a TIN below.

If you are a sole proprietor and you have an EIN, you may enter either your SSN or EIN. However, the IRS prefers that you use your SSN.

If you are a single-member LLC that is disregarded as an entity separate from its owner (see Limited Liability Company (LLC) on page 2), enter the owner's SSN for EIN, if the owner has one). Do not enter the disregarded entity's EIN. If the LLC is classified as a corporation or partnership, enter the entity's EIN.

Note. See the chart on page 4 for further clarification of name and TIN combinations.

How to get a TIN. If you do not have a TIN, apply for one immediately. To apply for an SSN, get Form SS-5, Application for a Social Security Card, from your local Social Security Administration office or get this form online at www.ssa.gov. You may also get this form by calling 1-800-772-1213. Use Form W-7, Application for IRS individual Taxpayer Identification Number, to apply for an ITIN, or Form SS-4, Application for Employer Identification Number, to apply for an ITIN, or Form SS-4, for an ITIN online by accessing the IRS wobsite at www.ins.gov/businesses and clicking on Employer Identification Number (EIN) under Starting a Business. You can get Form W-7 and SS-4 from the IRS by visiting IRS.gov or by calling 1-800-TAX-FORM (1-800-829-3676).

If you are asked to complete Form W-9 but do not have a TIN, apply for a TIN and write "Applied For" in the space for the TIN, sign and date the form, and give it to the requestor. For interest and dividend payments, and cortain payments made with respect to readily tradable instruments, generally you will have 60 days to get a TIN and give it to the requisator before you are subject to backup withholding on payments. The 60-day rule does not apply to other types of payments. You will be subject to backup withholding on all such payments until you provide your TIN to the requisition.

Note. Entering "Applied For" means that you have already applied for a TIN or that you intend to apply for one soon.

Caution: A disregarded U.S. entity that has a foreign owner must use the appropriate Form W-8.

Part II. Certification

To establish to the withholding agent that you are a U.S. person, or resident allen, sign Form W-2, You may be requested to sign by the withholding agent even if items 1, 4, or 5 below indicate otherwise.

For a joint account, only the person whose TIN is shown in Part I should sign (when required), in the case of a disregarded entity, the person identified on the "Name" line must sign. Exempt payees, see Exempt payee code earlier.

Signature requirements. Complete the certification as indicated in items 1 through 5 below.

- Interest, dividend, and barter exchange accounts opened before 1984 and broker accounts considered active during 1983. You must give your correct TIN, but you do not have to sign the certification.
- 2. Interest, dividend, broker, and barter exchange accounts opened after 1983 and broker accounts considered inactive during 1983. You must sign the certification or backup withholding will apply. If you are subject to backup withholding and you are marely providing your correct TIN to the requester, you must cross out item 2 in the certification before signing the form.
- Real estate transactions. You must sign the certification. You may cross out item 2 of the certification.
- 4. Other payments. You must give your correct TIN, but you do not have to sign the certification unless you have been notified that you have previously given an incorrect TIN. "Other payments" include payments made in the course of the requester's trade or business for rents, reyalties, goods (other than bills for merchandise), medical and health care services (including payments to corporations), payments to a nonemployee for services, payments made in settlement of payment card and third party network transactions, payments to certain fishing boat crew members and fishermen, and gross proceeds paid to attorneys (including payments to corporations).
- Mortgage interest paid by you, acquisition or abandonment of secured property, cancellation of debt, qualified tuition program payments (under section 529), IRA, Coverdell ESA, Archer MSA or HSA contributions or distributions, and pension distributions. You must give your correct TIN, but you do not have to sign the certification.

² However, the following payments made to a corporation and reportable on Form 1009-MISC are not exempt from backup withholding: medical and health care payments, attorneys' feet, gross proceeds paid to an attorney, and payments for services paid by a tederal executive agency.

Form W-9 (Flav. 8-2013) Page 4

What Name and Number To Give the Requester

For this type of account:	Give name and SSN of:
1. Individual	The Individual
 Two or more individuals (joint account) 	The actual owner of the account or, if combined funds, the first
	Individual on the account '
Custodian account of a minor (Uniform Gift to Minors Act)	The minor "
 a. The usual revocable savings trust (grantor is also trustee) 	The grantor-trustee '
 So-called trust account that is not a legal or valid trust under state law 	The actual owner *
 Sole proprietorship or disregarded entity owned by an individual 	The owner*
 Grantor trust filing under Optional Form 1000 Filing Method 1 (see Regulation section 1.671-4(b)(2)()(A)) 	The grantor*
For this type of account:	Give name and EIN of:
 Disregarded entity not owned by an individual 	The owner
8. A valid trust, estate, or pension trust	Logal entity *
 Corporation or LLC electing corporate status on Form 8832 or Form 2553 	The corporation
 Association, club, religious, charitable, educational, or other tax-exempt organization 	The organization
11. Partnership or multi-member LLC	The partnership
12. A broker or registered nominee	The broker or nominee
 Account with the Department of Agriculture in the name of a public entity (such as a state or local government, school district, or prison) that receives agricultural program payments 	The public entity
 Granfor trust filing under the Form 1041 Filing Method or the Optional Form 1099 Filing Method 2 (see Regulation section 1.671–4(b)(2)(f(8)) 	The trust

¹ List first and circle the name of the person whose number you furnish. If only one person on a joint account has an SSN, that person's number must be furnished.

Note. If no name is circled when more than one name is listed, the number will be considered to be that of the first name listed.

Secure Your Tax Records from Identity Theft

Identify theft occurs when someone uses your personal information such as your name, social security number (SSN), or other identifying information, without your permission, to commit fraud or other crimes. An identify their may use your SSN to get a job or may file a tax return using your SSN to receive a retund.

To reduce your risk:

- · Protect your SSN,
- . Ensure your employer is protecting your SSN, and
- . Be careful when choosing a tax preparer.

If your tax records are affected by identity theft and you receive a notice from the IRS, respond right away to the name and phone number printed on the IRS notice or letter.

If your tax records are not currently affected by identity theft but you think you are at risk due to a lost or stoken purse or wallet, questionable credit card activity or credit report, centact the IRS identity Theft Hottine at 1-800-908-4490 or submit Form 14039.

For more information, see Publication 4535, Identity Theft Prevention and Victim Assistance.

Victims of identity theft who are experiencing economic harm or a system problem, or are seeking help in resolving tax problems that have not been resolved through normal channels, may be eligible for Taxpayer Advocate Service (TAS) assistance. You can reach TAS by calling the TAS toll-free case Intake line at 1-877-777-4778 or TTY/TDO 1-800-829-4059.

Protect yourself from suspicious emails or phishing schemes. Phishing is the creation and use of small and websites designed to mimic legitimate business emails and websites. The most common act is sending an email to a user falsely claiming to be an established legitimate enterprise in an attempt to scarm the user into surrendering private information that will be used for identify theft.

The IRS does not initiate contacts with texpayers via smalls. Also, the IRS does not request personal detailed information through small or ask texpayers for the PIN numbers, passwords, or similar secret access information for their credit card, bank, or other financial accounts.

If you receive an unsolicited email claiming to be from the IRS, forward this message to phishing@irs.gov. You may also report insuse of the IRS name, logo, or other IRS property to the Treasury inspector General for Tax Administration at 1-800-306-4484. You can forward suspicious emails to the Federal Trade Commission at spam@iuce.gov or contact them at www.flc.gov/kdtheft or 1-877-IDTHEFT (1-877-438-4338).

Visit IRS.gov to learn more about identity theft and how to reduce your risk.

Privacy Act Notice

Section 6109 of the Internal Revenue Code requires you to provide your correct TIN to persons (including federal agencies) who are required to file information returns with the IRS to report interest, dividends, or certain other income paid to your mortgage interest you paid; the acquisition or abandomment of secured property; the cancellation of debt; or contributions you made to an IRA, Archer MSA, or HSA. The person collecting this form uses the information on the form to file information in shurns with the IRS, reporting the above information. Pourtine uses of this information information in shurns with the IRS, or Columbia, and U.S. commonwealths and possessions for use in administering their laws. The information also may be disclosed to other countries under a treaty, to federal and state agencies to enforce civil and criminal laws, or to federal law enforcement and intelligence agencies to combat terrorism. You must provide your TIN whether or not you are required to file a tax return. Under section 3406, payers must generally withhold a percentage of taxable interest, dividend, and certain other payments to a payee who does not give a TIN to the payer. Certain penalties may also apply for providing take or fraudulent information.

² Circle the minor's name and furnish the minor's SSN.

⁵ You must show your individual name and you may also enter your business or "DBA" name on the "Business name/deragarded entity" name line. You may use either your SSN or EIN (if you have one), but the IRS encourages you to use your SSN.
⁶ List first and circle the name of the trust, estatio, or pension brust. (Do not furnish the TIN of the

List first and dicta the name of the trust, estate, or pension trust. (Do not furnish the TIN of the personal representative or trustee unless the logal entity itself is not designated in the account title.) Also see Special rules for partnerships on page 1.

[&]quot;Note. Crantor also must provide a Form W-e to trustee of trust

REQUIRED RESPONSE FORM - Proposer Information

RFQ Issued Date:	Title of Request or Solicita	ution:		
	Note: For Joint Venture Proposals, see instructions at the bottom of this page. PROPOSER INFORMATION			
PROPOSER'S (COMPANY) NA	ME:			
STREET ADDRESS:				
PROPOSER TELEPHONE:	PROPOSE	ER FAX:		
CONTACT PERSON:				
		T FAX:		
E-MAIL ADDRESS TO SEND P	URCHASE ORDERS TO:			
INTERNET E-MAIL ADDRESS:	INTE	RNET URL:		
	TIFICATION NUMBER:			
I hereby certify that:	Proposal Cert	ification		
 Proposer has not discussed, of the Proposer is attempting to qualify of silence" period for any solicita School Board Policy School Board Policy Proposer acknowledges that Records Laws. All responses, data and inform Proposer agrees to acceptant all issued Addenda. Proposer agrees to be boundattachments. 	eir lobbyists has not provided any campaign of the provide Design Services to the School Botton for a competitive procurement as described and a 3320, Part II, Section HH and 1007, Section 5.4 Campaign Contribution Fur all information contained herein is part of the mation contained in this Proposal are true and a ce of the contents of all pages in this Request and to all terms, conditions and requirement	contributions to School Board Members during the period in which the coard. This period of limitation shall commence at the time of the "cone ed by: Indicate the coard of the coard of the "cone ed by: Indicate the coard of the coard o		
Signature of Proposer's Office	er (blue ink preferred on original)	Date		
Name of Proposer's Officer		Title of Proposer's Officer.		

<u>JOINT VENTURES:</u> In the event multiple Proposers submit a joint Proposal in response to the RFQ, a single Proposer shall be identified as the Prime Proposer. If offering a joint Proposal, Prime Proposer must include the name and address of all parties of the joint Proposal. Prime Proposer shall provide all bonding and insurance requirements, execute any Contract, complete the <u>REQUIRED RESPONSE FORM</u> shown herein, have overall and complete accountability to resolve any dispute arising within this contract. Only a single contract with one Proposer shall be acceptable. Prime Proposer responsibilities shall include, but not be limited to, performing of overall contract administration, preside over other Proposers participating or present at SBBC meetings, oversee preparation of reports and presentations, and file any notice of protest and final protest as described herein. Prime Proposer shall also prepare and present a consolidated invoice(s) for services performed. SBBC shall issue only one check for each consolidated invoice to the Prime Proposer for services performed. Prime Proposer shall remain responsible for performing services associated with response to this RFQ.

RFQ #:			
Scope of Available Se	ervices Form		
	(B	oth of these col	umns can be yes)
Scope of Services	In House Services		Consultant
Architecture			
Civil Engineering			
Electrical Engineering			
Land Surveying			
Mechanical Engineering			
Structural Engineering			
Landscape Design			
Site Analysis and Planning			
Plumbing Design			
Other			

Firm:



The School Board of Broward County, Florida Procurement and Warehousing Department 7720 W. Oakland Park Blvd., Suite 323 Sunrise, Florida 33351

(754) 321-0505

Document 00220a: Proposer's Request for Information			
To:	Purchasing Agent Procurement and War 7720 W. Oakland Park Sunrise, Florida 3335	k Blvd., Suite 323	Date:
	Sumise, Florida 5000	•	(For Owner's Use Only) Bidder's RFI No.:
Proje	ect:	Project Nur Location Nu	
Facil	ity Name:	Project Con	sultant:
	Category: Information not shown or Interpretation of RFQ Doc Conflict in RFQ Requirem Coordination	cuments	
Desc	cription:		
Atta	chments:		
Bid	ler: npany Name & Address:	Ву:	Signature
	Phone:		Title

Attachment G - Project Scope of Work

Tedder Elementary School 4157 NE 1st Terrace Deerfield Beach FL 33064

Project Number: P-0016xx (TBD)

Project Description: Design & Renovation

RFQ Number: 17-065C

Prepared for: The School Board of Broward County

600 SE 3rd Ave Ft Lauderdale, FL 33301

Prepared by: **HEERY**

A group of professional service practices 999 Peachtree St, NE Atlanta, Georgia 30309

Contents

Attachment G - Project Scope of Work	1
1.0.0 Executive Summary	
2.0.0 Tedder Elementary School	
2.1.0 Project Scope of Work	4
2.2.0 Site Summary	5
2.3.0 FISH Documents	€
2.3.1 FISH Summary Report	6
2.3.2 FISH Inventory	9
2.3.3 FISH Site Plan	52
2.3.4 FISH Building Plan	53
2.4.0 Facility Assessments and Budgetary Documentation	54
2.4.1 Adopted District Educational Facilities Plan (DEFP)	55
2.4.2 SMART Campus Summary	56
2.4.3 MAPPS Deficiency Listing	58
2.4.4 MAPPS Deficiency Data	75
2.4.5 MADDS Deficiency Detail	79

1.0.0 Executive Summary

On November 4, 2014, Broward County voters approved a General Obligation Bond (Bond) referendum that provides critically needed funding for Broward's students. Broward County Public Schools has committed to investing the funding to enhance students' learning environments by focusing on improvements in Safety, Music, Art, Athletics, Renovations and Technology (SMART).

To ensure equity among schools regarding Broward County Public Schools SMART initiative, a comprehensive Facility Needs Assessment was conducted Districtwide. The Needs Assessment provided an objective, data-driven overview of the District as a whole, as well as a strategic planning tool for prioritizing the most critical needs facing our schools for safety and security; repairs and renovations; and technology and technology infrastructure.

Based on the Facility Needs Assessment, Tedder Elementary School was found to require renovations to multiple facility components. The key objectives are 1) to thoroughly plan the work to allow normal school activities to continue without interruption with a focus on safety and completing work as soon as possible, and 2) to capitalize on 2017 Summer break to complete portions of scope when students are not on campus.

Included in this project scope of work is:

Tedder Elementary School

- Fire Sprinklers
- Fire Alarm
- PE/Athletic Improvements
- HVAC Improvements
- Building Envelope Improvements

2.0.0 Tedder Elementary School

2.1.0 Project Scope of Work

The scope of work is broken down in accordance with the Approved District Educational Facility Plan SMART Program. The scope is presented as overall site deficiencies with specific trades called out when possible. Additionally, the scope of services specific to each campus building is itemized in section 2.4.0 facility assessment reports with specific trades called out when possible for reference purposes only. The Design Team is responsible for confirming all areas within the scope of work and necessary quantities and component sizes relevant to the campus renovations. The scope of work is limited to that which is being funded by the General Obligation Bond or agreed upon alternatives with the designated representatives of the school district.

The Design Team shall be responsible for the full design of a complete replacement Fire Alarm System for the entire campus, and Fire Sprinkler System in multiple campus buildings, which shall meet all applicable codes and SREF design requirements. The specific Life Safety systems are viewed as a mission critical concern of the highest priority level.

The Design Team shall work with the designated representatives of the school district to coordinate the demolition, removal, and replacement of various playground equipment. The design shall meet all applicable codes and SREF design requirements, along with district Educational Specifications and guidelines.


The facility assessment determined various HVAC mechanical building systems to require replacement. The Design Team shall be responsible for the design and engineering of building systems to correct deficiencies listed in section 2.4.0 in accordance with applicable codes and standards recognized by the jurisdiction. These deficiencies include, but are not limited to, the replacement of roof top air handling units, exhaust hoods and ventilation fans, kitchen exhaust system in Building 19, roof top air handling units, test and balancing of HVAC systems and pneumatic controls with DDC controls for multiple campus buildings. The design shall comply with applicable codes, standards, SREF design requirements and owner's design guidelines.

The envelope scope includes, but is not limited to the replacement of exterior doors, aluminum and steel windows, exterior painting at multiple buildings throughout the campus and the reroofing of multiple campus buildings. The Design Team shall provide a full design of complete replacement of the existing roofing system with new decking requirements per County standards. Moreover, some existing roof areas will need to be raised to provide positive drainage and new minimum roof R-Values and may necessitate the need to raise existing equipment, utilities and other construction to accommodate new flashing heights.

In addition to the identified deficiencies found in section 2.4.0, the Design Team is responsible for working with the designated representatives of the school district to identify additional deficiencies related to the envelope, indoor air quality, lighting, and HVAC systems. The facility assessment reports stand as initial budgeted concerns, but does not serve as the limits of scope of work for the project renovation.

2.2.0 Site Summary

Tedder Elementary School is an existing school originally built in 1964 with expansions and renovations having taken place in 1969, 1990, 2003, and 2004. The campus currently encompasses fourteen (14) buildings with an approximate square footage of 119,000 SF.



2.3.0 FISH Documents

2.3.1 FISH Summary Report



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FLORIDA DEPARTMENT OF EDUCATION EDUCATIONAL FACILITIES AGENCY NSF/STUDENT STATIONS SUMMARY REPORT

ORGANIZATION: 6-BROWARD COUNTY SCHOOL DISTRICT

FACILITY: TEDDER ELEMENTARY

FACILITY USE: All
STRUCTURE TYPE: All
CONDITION: All
GROUP BY: DISTRICT

District: 6 - BROWARD COUNTY SCHOOL DISTRICT

DESIGN CODE	ROOM DESIGN CODE	TOTAL ROOMS	NET SQ FT	STUDENT STATIONS
00001	PRIMARY CLASSROOM (K-3)	34	30,167	612
00002	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	26	23,487	572
00010	PRIMARY SKILLS LAB (K-3)	2	1,924	0
00030	PRIMARY OPEN PLAN (K-3)	1	2,030	36
00040	RESOURCE ROOM	3	1,470	0
00050	ART -ELEMENTARY	1	1,295	0
00055	MUSIC - ELEMENTARY	1	1,560	0
00062	E S E FULL-TIME	2	1,560	20
00065	E S E RESOURCE	1	510	0
00300	PRINCIPAL/DIRECTOR OFFICE	1	221	0
00301	ASSISTANT PRINCIPAL/OTHER OFFICE	4	1,057	0
00303	SECRETARIAL SPACE	1	808	0
00304	RECEPTION AREA	1	275	0
00305	PRODUCTION WORKROOM	1	307	0
00306	CONFERENCE ROOM	2	536	0
00307	CLINIC	1	159	0
00308	GENERAL SCHOOL STORAGE	3	952	0
00309	VAULT/STUDENT RECORDS	1	77	0
00312	COMPUTER AREA	1	160	0
00314	ITINER ANT OFFICE	2	320	0
00315	TEACHER PLANNING OFFICE	7	2,890	0
00316	TEACHER LOUNGE/DINING	4	1,034	0
00330	CUSTODIAL RECEIMING	2	677	0
00331	CUSTODIAL SERVICE CLOSET	11	781	0

PAGE:1 of 3 Report Date: 4/30/2010 8:57:44 AM



FLORIDA DEPARTMENT OF EDUCATION EDUCATIONAL FACILITIES AGENCY NSF/STUDENT STATIONS SUMMARY REPORT

District: 6 - BROWARD COUNTY SCHOOL DISTRICT

DESIGN CODE	ROOM DESIGN CODE	TOTAL ROOMS	NET SQ FT	STUDENT STATIONS
00332	CUSTODIAL WORK AREA	1	135	0
00333	FLAMMABLE STORAGE	1	150	0
00334	CUSTODIAL EQUIPMENT STORAGE	1	425	0
00340	DINING AREA	1	4,000	0
00341	KITCHEN & SERVING AREA	1	1,569	0
00342	KITCHEN DRY STORAGE	1	200	0
00343	KITCHEN OFFICE	1	170	0
00344	KITCHEN GARBAGE WASH	3	247	0
00345	KITCHEN NONFOOD STORAGE	1	128	0
00349	KITCHEN CHAIR STORAGE	1	120	0
00350	OTHER FOOD SERVICE	4	305	0
00361	MULTIPURPOSE ROOM (DINING)	1	2,336	0
00362	MULTIPURPOSE ROOM CHAIR STORAGE	2	279	0
00363	STAGE	1	1,052	0
00364	STAGE STORAGE	3	263	0
00365	STAGE DRESSING ROOM (MALE)	1	178	0
00366	STAGE DRESSING ROOM (FEMALE)	1	178	C
00368	TEXTBOOK STORAGE	1	86	C
00380	LIBRARY (READING ROOM/STACKS)	1	2,281	C
00381	MEDIA TE CHNICAL PROCESSING	1	899	0
00383	AUDIO VISUAL STORAGE	1	532	0
00385	CLOSED CIRCUIT TV LAB	1	460	0
00386	CLOSED CIRCUIT STORAGE	1	188	0
00390	MEDIA GROUP PROJECTS/INSTRUCTION	1	325	0
00700	INSIDE CIRCULATION	26	9,864	0
00701	COVERED WALKWAY	32	22,975	0
00702	MECHANICAL ROOM	28	3,257	0
00703	ELECTRICAL ROOM	51	2,551	0
00707	TELEPHONE EQUIPMENT/COMMUNICATION CLOSET	3	366	C
00805	KILN	1	60	C
00806	REFERENCE	1	153	0

PAGE:2 of 3 Report Date: 4/30/2010 8:57:44 AM



FLORIDA DEPARTMENT OF EDUCATION EDUCATIONAL FACILITIES AGENCY NSF/STUDENT STATIONS SUMMARY REPORT

District: 6 - BROWARD COUNTY SCHOOL DISTRICT

DESIGN CODE	ROOM DESIGN CODE	TOTAL ROOMS	NET SQ FT	STUDENT STATIONS
00808	MATERIAL STORAGE	52	1,968	0
00810	MATERIAL STORAGE (LARGE)	1	315	0
00811	OUTSIDE STORAGE	1	46	0
00814	STUDENT RESTROOM (BOTH SEXES)	59	2,224	0
00815	STUDENT RESTROOM (MALE)	3	465	0
00816	STUDENT RESTROOM (FEMALE)	3	584	0
00819	STAFF RESTROOM (MALE)	4	200	0
00820	STAFF RESTROOM (FEMALE)	5	288	0
00821	STAFF RESTROOM (BOTH SEXES)	2	114	0
00827	ELEVATOR (PASSENGER/HANDICAPPED)	1	40	0
00831	MUSIC PRACTICE ROOM	1	75	0
	TOTALS:	419	136,308	1,240

TOTALS FOR SELECTED DISTRICTS:	419	136,308	1,240

PAGE:3 of 3 Report Date: 4/30/2010 8:57:44 AM

2.3.2 FISH Inventory

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

6-BROWARD COUNTY SCHOOL DISTRICT ORGANIZATION:

TEDDER ELEMENTARY FACILITY:

₹ FACILITY USE: DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 46-A TEDDER ELEMENTARY

DOE Validation Date: Grades Housed: PK - 05 Primary Use: ELEMENTARY MASTER SCHOOL ID

Capital Outlay Classification: SCHOOL RECOMMENDED FOR CONTINUED USE

MSID	Мате	Status
571	TEDDER ELEMENTARY SCHOOL	Default

CAPITAL OUTLAY FTE

real. 2000 / 2003					
PK: 48.87	01: 126.50	03: 113.50	05: 77.50	00: 0:00	03: 0.0
KG: 109.00	02: 88.50	04: 109.00	00: 0:00	08: 0.00	10: 0.0

PK-12: 672.87

11: 0.00 12: 0.00

8 8

Total: 672.87 Adult: 0.00

SCHOOL CAPACITY

SCHOOL CAPACITY	YEAR ROUND CAPACITY	UTILIZATION FACTOR	PRIMARY USE
1,240	1,488	100	ELEMENTARY

Report Date: 4/19/2010 10:31:31 AM

Report Date: 4/19/2010 10:31:31 AM

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

6-BROWARD COUNTY SCHOOL DISTRICT ORGANIZATION:

TEDDER ELEMENTARY FACILITY

FACILITY USE:

DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 46-A TEDDER ELEMENTARY

DOE Validation Date: Grades Housed: PK - 05 Primary Use: ELEMENTARY

Capital Outlay Classification: SCHOOL RECOMMENDED FOR CONTINUED USE

MASTER SCHOOL ID

Status Default TEDDER ELEMENTARY SCHOOL Name MSID

CAPITAL OUTLAY FTE

00:0:60 10: 0.00 00'0 '20 08: 0.00 05: 77:50 06: 0.00 03: 113.50 04: 109.00 01: 126.50 02: 88.50 fear: 2008 / 2009 KG: 109.00 PK: 48.87

PK-12: 672.87

11: 0.00 12: 0.00

Total: 672.87 Adult: 0.00

SCHOOL CAPACITY

PRIMARY USE	ELEMENTARY
UTILIZATION FACTOR	100
YEAR ROUND CAPACITY	1,488
SCHOOL CAPACITY	1,240

Page 1 of 41

FACILITY INVENTORY REPORT

PARCEL: 47

4157 NE 1ST TERRACE

POMP AND BEACH, FL 33064

Parking: P.ARTI ALLY DEVELOPED	Owner. SCHOOL BOARD	Fire 8
Athletiα INCLUDED WITH SITE	Water: P UBLIC	Police: COUNTY
Sewage: P UBLIC	Plan: CAMPUS	Drainage: INADEQUATE
Landscape: PARTIALLY DEVELOPED	Playground: INCLUDED WITH SITE	Acreage: 12.00
Date Acquired: 1/1/1957		Lease Expiration Date:

DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 46-A TEDDER ELEMENTARY

BUILDING: 1 - Building Number 00001

Owner, SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
USS: ELEMENTARY	Mech Vent: NONE	Heat Source: ELECTRIC
Year Constructed: 1969	Artificial Lighting: SHELDED FLORE SCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational TV: FIXED SERVICE TRANSMITTER, RECEIVER	Heat Capacity. ADEQUATE
Average Age NSF: 1969	Intercom: TWO WAY COMPLETE	Walls STUCCO
Relocatable Units: 0	Telephone: NONE	Struct Comp. COMBINATION OF 1-3
Stories: 1		Corridor: SINGLE OUTSIDE

ROOM	NET SQ FT	ROOM NET SQ DESIGN FT CODE	DESCRIPTION	STU	FLR LOC	FLOOR COVER	YEAR	СОИВІДОИ	BLDG PAR		FAC
100 1168	1168	704	COVERED WALKWAY		Б	CONCRETE	1969	SATISFACTORY	-	47	46
100A 736	736	701	COVERED WALKWAY		Б	CONCRETE	1969	SATISFACTORY	-	47	46
101	096	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	Б	COMPOSITION TILE	1969	SATISFACTORY	-	47	46

Page 2 of 41

FACILITY INVENTORY REPORT

TO THE STATE OF TH

PARCEL: 47

4157 NE 1ST TERRACE

POMPANO BEACH, FL 33064

Fire 8	Police: COUNTY	Drainage: INADEQUATE	Acreage: 12.00	Lease Expiration Date:
Owner: SCHOOL BOARD	Water: P UBLIC	Plan: CAMPUS	Playground: INCLUDED WITH SITE	
Parking: PARTIALLY DEVELOPED	Athletiα INCLUDED WITH SITE	Sewage: PUBLIC	Landscape: PARTIALLY DEVELOPED	Date Acquired: 1M 957

DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 46-A TEDDER ELEMENTARY

BUILDING: 1 - Building Number 0000'

Owner. SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
USS: ELEMENTARY	Mech Vent: NONE	Heat Source: ELECTRIC
Year Constructed: 1969	Artificial Lighting: SHELDED FLORE SCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational TV: FIXED SERVICE TRANSMITTER/RECEIVER	Heat Capacity. ADEQUATE
Average Age NSF: 1969	Intercom: TW/O W/A Y COMPLETE	Walls: STUCCO
Relocatable Units: 0	Telephone: NONE	Struct Comp. COMBINATION OF 1-3
Stories: 1		Corridor: SINGLE OUTSIDE

ROOM	NET SQ FT	ROOM NET SQ DESIGN FT CODE	DESCRIPTION	STU STA	H 201	FLOOR COVER	YEAR CONST	СОИВІЛОИ	BLDG PAR	PAR	FAC
100 1168	l	701	COVERED WALKWAY		Б	CONCRETE	1969	SATISFACTORY	-	47	46
100A 736		701	COVERED WALKWAY		Б	CONCRETE	1969	SATISFACTORY	-	47	46
101	096	2	INTERMEDIATE MIDDLE CLASSROOM (4-8)	22	Ю	COMPOSITION TILE	1969	SATISFACTORY	-	47	46

Page 2 of 41

FACILITY INVENTORY REPORT

101A 1	168 315	<u> </u>	TEACHER PLANNING OFFICE	FICE	<u>.</u>	Б	COMPOSITION TILE	1969	SATISFACTORY	'ORY	-	47	46
102	960 2	롣	INTERMEDIATEMIDDLE	DDLE CLASSROOM (4-8)	22	Б	COMPOSITION TILE	1969	SATISFACTORY	ORY	-	47	46
102A 1	168 315	쁘	TEACHER PLANNING OFFICE	FICE	0	Б	COMPOSITION TILE	1969	SATISFACTORY	ORY	-	47	46
103	960 2	≧	INTERMEDIATEMIDDLE	DDLE CLASSROOM (4-8)	22	Б	COMPOSITION TILE	1969	SATISFACTORY	ORY	-	47	46
104	960 2	Z	INTERMEDIATEAMIDDLE	DDLE CLASSROOM (4-8)	22	Б	COMPOSITION TILE	1969	SATISFACTORY	'ORY	-	47	46
				34.54									
		Sags	Saustactory	Unsatisfactory	actony		ralled standards	indards		scheduled For Keplacement	ог кері	acement	
	Square Feet	Feet	Student Stations	Square Feet	Student Stations	ations	Square Feet	Student Stations	tations	Square Feet	8	Student Stations	8
Permanent		080'9	88	0		0							
TOTAL		080'9	88	0		0	0		0)	0		0

GREAT SE

Page 3 of 41

Report Date: 4/19/2010 10:31:31 AM

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

ICT	
DISTR	
HOOL	
TY SC	
COUN	
WARD	
6 BRO	
SICT: (
DIST	

FACILITY: 46-A TEDDER ELEMENTARY BUILDING: 2 - Building Number 00002

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: ELEMENTARY	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1964	Artificial Lighting: SHIELDED FLORE SCENT	Heat Distribution: CENTR.AL HOT AIR
Year Modified:	Educational TV: FIXED SERVICE TRANSMITTER/RECEIVER	Heat Capacity, ADEQUATE
Average Age NSF: 1964	Intercom: TWO WAY COMPLETE	Wall≈ STUCCO
Relocatable Units: 0	Telephone: NONE	Struct Comp. COMBINATION OF 1-3
Stories: 1		Comidor: SINGLE OUTSIDE

										•	1
ROOM	NET SQ FT	DESIGN	DESCRIPTION	STU	F.R. 201	FLOOR COVER	YEAR CONST	СОИВІЛОИ	BLDG	PAR	FAC
200	3568	701	COVERED WALKWAY	·	Б	CONCRETE	1964	SATISFACTORY	2	47	46
200A	306	701	COVERED WALKWAY	·	Б	CONCRETE	1964	SATISFACTORY	2	47	46
200B	210	701	COVERED WALKWAY		Б	CONCRETE	1964	SATISFACTORY	2	47	46
200C	210	701	COVERED WALKWAY		Б	CONCRETE	1964	SATISFACTORY	2	47	46
201	874	2	INTERMEDIATE MIDDLE CLASSROOM (4-8)	22	Б	COMPOSITION TILE	1964	SATISFACTORY	2	47	46
201A	32	702	MECHANICAL ROOM	0	10	COMPOSITION TILE	1964	SATISFACTORY	2	47	46
202	885	2	INTERMEDIATE MIDDLE CLASSROOM (4-8)	22	Б	COMPOSITION TILE	1964	SATISFACTORY	2	47	46
202A	35	702	MECHANICAL ROOM		Б	COMPOSITION TILE	1964	SATISFACTORY	2	47	46
203	858	2	INTERMEDIATE MIDDLE CLASSROOM (4-8)	22	Б	COMPOSITION TILE	1964	SATISFACTORY	2	47	46
203A	29	702	MECHANICAL ROOM		Б	COMPOSITION TILE	1964	SATISFACTORY	2	47	46
204	885	2	INTERMEDIATE MIDDLE CLASSROOM (4-8)	22	10	COMPOSITION TILE	1964	SATISFACTORY	2	47	46
204.4	35	702	MECHANICAL ROOM	0	10	COMPOSITION TILE	1964	SATISFACTORY	2	47	46

Page 4 of 41



FACILITY INVENTORY REPORT

0	101	CONCRETE	1964	1964 SATISFACTORY	JRY SA	2	47	46
-			-					
Unsatisfactory		Failed Standards	ndards		Scheduled For Replacement	or Repl	acement	
Square Feet Stud	ent Stations	Square Feet	Student Stat	ions	Square Feet	ਲ	udent Stati	SIIO
0	0							
0	0	0		0		0		0
	00	Student Stations 0 0 0	Student Stations 0 0 0	Student Stations Square Feet 0 0 0 0	Student Stations 0 0 0	Student Stations Square Feet Student Stations 0 0 0 0 0 0	Student Stations Square Feet Student Stations Square Feet 0 <	Student Stations Square Feet Student Stations 0 0 0 0 0 0



Ř

Page 5 of 41

Report Date: 4/19/2010 10:31:31 AM

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

STRICT
<u> </u>
<u>00</u>
SG
₹
ē
RDC
ΜÃ
BRO
9:
SICT
IST
_

FACILITY: 46-A TEDDER ELEMENTARY

BUILDING: 3 - Building Number 00003

Owner: SCHOOL BO ARD	Light: ADEQUATE	Cooling: CENTRAL
Use: ELEMENTARY	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1964	Artificial Lighting: SHELDED FLORE SCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational TV: FIXED SERVICE TRANSMITTER/RECEIVER Heat Capacity. ADEQUATE	Heat Capacity: ADEQUATE
Average Age NSF: 1964	Intercom: TWO WAY COMPLETE	Walls STUCCO
Relocatable Units: 0	Telephone: NONE	Struct Comp. COMBINATION OF 1-3
Stories: 1		Corridor: SINGLE OUTSIDE

ROOM NET SQ DESCRIPTION STA FLD FLOOR COVER VEAR 300 288 701 COVERED WALKWAY 0 01 CONCRETE 1964 SA 3004 288 701 COVERED WALKWAY 0 01 CONCRETE 1964 SA 3014 288 1 PRIMARY CLASSROOM (K-3) 18 0 COMPOSITION TILE 1964 SA 3016 28 700 INSIDE CIRCULATION 0 0 0 COMPOSITION TILE 1964 SA 3017 35 702 MECHANICAL ROOM (K-3) 18 0 CONCRETE 1964 SA 302A 30 11 PRIMARY CLASSROOM (K-3) 18 0 CONCRETE 1964 SA 302B 28 700 BIA STUDENT RESTROOM (BOTH SEXES) 0 0 COMPOSITION TILE 1964 SA 302B 28 700 MECHANICAL ROOM 0 0 COMPOSITION TILE <												
298 701 COVERED WALKWAY 0 01 CONCRETE 1964 298 701 COVERED WALKWAY 0 01 CONCRETE 1964 883 1 PRIMARY CLASSROOM (K-3) 18 01 COMPOSITION TILE 1964 20 814 STUDENT RESTROOM (BOTH SEXES) 0 01 CERAMIC TILE 1964 35 702 MECHANICAL ROOM 0 01 COMPOSITION TILE 1964 902 1 PRIMARY CLASSROOM (K-3) 18 01 COMPOSITION TILE 1964 20 814 STUDENT RESTROOM (BOTH SEXES) 0 01 CORPOSITION TILE 1964 21 702 MECHANICAL ROOM 0 0 CONCRETE 1964 22 700 INSIDE CIRCULATION 0 0 COMPOSITION TILE 1964 23 702 MECHANICAL ROOM 0 0 CONCRETE 1964 24 702 MECHANICAL ROOM 0 0 CONCRETE	ROOM	NET SQ FT	DESIGN		STU	FIR	FLOOR COVER	YEAR	СОИВІПОИ	BLDG	PAR	FAC
298 701 COVERED WALKNAY 0 01 CONCRETE 1964 883 1 PRIMARY CLASSROOM (K-3) 18 01 COMPOSITION TILE 1964 20 814 STUDENT RESTROOM (BOTH SEXES) 0 01 CERAMIC TILE 1964 35 702 INSIDE CIRCULATION 0 01 COMPOSITION TILE 1964 902 1 PRIMARY CLASSROOM (K-3) 18 01 COMPOSITION TILE 1964 20 814 STUDENT RESTROOM (BOTH SEXES) 0 01 COMPOSITION TILE 1964 28 700 INSIDE CIRCULATION 0 01 COMPOSITION TILE 1964 21 702 MECHANICAL ROOM 0 0 CONCRETE 1964 883 1 PRIMARY CLASSROOM (K-3) 18 0 COMPOSITION TILE 1964 20 814 STUDENT RESTROOM (BOTH SEXES) 0 0 COMPOSITION TILE 1964 20 814 STUDENT RESTROOM (BOTH SEXES) 0 <td>300</td> <td></td> <td>701</td> <td>COVERED WALKWAY</td> <td></td> <td>Б</td> <td>CONCRETE</td> <td>1964</td> <td>SATISFACTORY</td> <td>6</td> <td>47</td> <td>46</td>	300		701	COVERED WALKWAY		Б	CONCRETE	1964	SATISFACTORY	6	47	46
883 1 PRIMARY CLASSROOM (K-3) 18 01 COMPOSITION TILE 1964 20 814 STUDENT RESTROOM (BOTH SEXES) 0 01 CERAMIC TILE 1964 28 700 INSIDE CIRCULATION 0 01 COMPOSITION TILE 1964 902 1 PRIMARY CLASSROOM (K-3) 18 01 COMPOSITION TILE 1964 20 814 STUDENT RESTROOM (BOTH SEXES) 0 01 CERAMIC TILE 1964 28 700 INSIDE CIRCULATION 0 01 COMPOSITION TILE 1964 21 702 MECHANICAL ROOM 0 0 CONCRETE 1964 883 1 PRIMARY CLASSROOM (K-3) 18 01 COMPOSITION TILE 1964 20 814 STUDENT RESTROOM (BOTH SEXES) 0 01 CERAMIC TILE 1964 20 814 STUDENT RESTROOM (BOTH SEXES) 0 01 CERAMIC TILE 1964	300A		701	COVERED WALKWAY		Б	CONCRETE	1964	SATISFACTORY	6	47	46
20 814 STUDENT RESTROOM (BOTH SEXES) 0 01 CERAMIC TILE 1964 28 700 INSIDE CIRCULATION 0 01 COMPOSITION TILE 1964 35 702 MECHANICAL ROOM 18 01 CONCRETE 1964 20 814 PRIMARY CLASSROOM (K-3) 0 01 CERAMIC TILE 1964 28 700 INSIDE CIRCULATION 0 01 COMPOSITION TILE 1964 21 702 MECHANICAL ROOM 0 01 CONCRETE 1964 883 1 PRIMARY CLASSROOM (K-3) 18 01 COMPOSITION TILE 1964 20 814 STUDENT RESTROOM (BOTH SEXES) 0 01 COMPOSITION TILE 1964		883	-	PRIMARY CLASSROOM (K-3)		Б		1964	SATISFACTORY	е	47	46
28 700 INSIDE CIRCULATION 0 01 COMPOSITION TILE 1964 35 702 MECHANICAL ROOM 0 01 CONCRETE 1964 902 1 PRIMARY CLASSROOM (K-3) 18 01 COMPOSITION TILE 1964 20 814 STUDENT RESTROOM (BOTH SEXES) 0 01 CERAMIC TILE 1964 21 702 MECHANICAL ROOM 0 01 CONCRETE 1964 883 1 PRIMARY CLASSROOM (K-3) 18 01 COMPOSITION TILE 1964 20 814 STUDENT RESTROOM (BOTH SEXES) 0 01 COMPOSITION TILE 1964	301A		814	STUDENT RESTROOM (BOTH SEXES)		Б	CERAMICTILE	1964	SATISFACTORY	е	47	46
35 702 MECHANICAL ROOM 0 01 CONCRETE 1964 902 1 PRIMARY CLASSROOM (K-3) 18 01 COMPOSITION TILE 1964 20 814 STUDENT RESTROOM (BOTH SEXES) 0 01 CERAMIC TILE 1964 28 700 INSIDE CIRCULATION 0 01 COMPOSITION TILE 1964 883 1 PRIMARY CLASSROOM (K-3) 18 01 COMPOSITION TILE 1964 20 814 STUDENT RESTROOM (BOTH SEXES) 0 01 CERAMIC TILE 1964	301B		200	INSIDE CIRCULATION		Б		1964	SATISFACTORY	е	47	46
902 1 PRIMARY CLASSROOM (K-3) 18 01 COMPOSITION TILE 1964 20 814 STUDENT RESTROOM (BOTH SEXES) 0 01 CERAMIC TILE 1964 28 700 INSIDE CIRCULATION 0 01 COMPOSITION TILE 1964 21 702 MECHANICAL ROOM 0 01 CONCRETE 1964 883 1 PRIMARY CLASSROOM (K-3) 18 01 COMPOSITION TILE 1964 20 814 STUDENT RESTROOM (BOTH SEXES) 0 01 CERAMIC TILE 1964	301C		702	MECHANICAL ROOM		Б	CONCRETE	1964	SATISFACTORY	е	47	46
20 814 STUDENT RESTROOM (BOTH SEXES) 0 01 CERAMIC TILE 1964 28 700 INSIDE CIRCULATION 0 01 COMPOSITION TILE 1964 21 702 MECHANICAL ROOM 0 01 CONCRETE 1964 883 1 PRIMARY CLASSROOM (K-3) 18 01 COMPOSITION TILE 1964 20 814 STUDENT RESTROOM (BOTH SEXES) 0 01 CERAMIC TILE 1964		902	-	PRIMARY CLASSROOM (K-3)		Б		1964	SATISFACTORY	e	47	46
28 700 INSIDE CIRCULATION 0 01 COMPOSITION TILE 1964 21 702 MECHANICAL ROOM 0 01 CONCRETE 1964 883 1 PRIMARY CLASSROOM (K-3) 18 01 COMPOSITION TILE 1964 20 814 STUDENT RESTROOM (BOTH SEXES) 0 01 CERAMIC TILE 1964	302A		814	STUDENT RESTROOM (BOTH SEXES)		Б		1964	SATISFACTORY	е	47	46
21 702 MECHANICAL ROOM 0 01 CONCRETE 1964 883 1 PRIMARY CLASSROOM (K-3) 18 01 COMPOSITION TILE 1964 20 814 STUDENT RESTROOM (BOTH SEXES) 0 01 CERAMICTILE 1964	302B		200	INSIDE CIRCULATION		Б		1964	SATISFACTORY	e	47	46
883 1 PRIMARY CLASSROOM (K-3) 18 01 COMPOSITION TILE 1964 20 814 STUDENT RESTROOM (BOTH SEXES) 0 01 CERAMIC TILE 1964			702	MECHANICAL ROOM		Б	CONCRETE	1964	SATISFACTORY	e	47	46
20 814 STUDENT RESTROOM (BOTH SEXES) 0 01 CERAMIC TILE 1964		883	←	PRIMARY CLASSROOM (K-3)		Б		1964	SATISFACTORY	е	47	46
	303A		814	STUDENT RESTROOM (BOTH SEXES)		0		1964	SATISFACTORY	е	47	46

FACILITY INVENTORY REPORT

303B	21	200	INSIDE CIRCULATION	0	М	COMPOSITION TILE	1964	SATISFACTORY	т	47	46
3030	35	702	MECHANICAL ROOM	0	Б	CONCRETE	1964	SATISFACTORY	m	47	46
3030	18	203	ELECTRICAL ROOM	0	Б	CONCRETE	1964	SATISFACTORY	e	47	46
	880	-	PRIMARY CLASSROOM (K-3)	18	Б	COMPOSITION TILE	1964	SATISFACTORY	n	47	46
304A	20	814	STUDENT RESTROOM (BOTH SEXES)		Б	CERAMICTILE	1964	SATISFACTORY	m	47	46
304B	24	200	INSIDE CIRCULATION		Б	COMPOSITION TILE	1964	SATISFACTORY	m	47	46
304C	29	702	MECHANICAL ROOM	0	Б	CONCRETE	1964	SATISFACTORY	m	47	46
305	45	331	CUSTODIAL SERVICE CLOSET		Б	CONCRETE	1964	SATISFACTORY	ю	47	46

	Satie	Satisfactory	Unsati	Unsatisfactory	Failed Standards	andards	Scheduled For Replacement	Replacement
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	4,505	72	0	0				
TOTAL	4,505	72	0	0	0	0	0	0





Report Date: 4/19/2010 10:31:31 AM

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

UNTY SCHOOL DISTRICT
DISTRICT: 6 BROWARD CO

FACILITY: 46-A TEDDER ELEMENTARY BUILDING: 4 - Building Number 00004

Owner. SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: ELEMENTARY	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1964	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational TV: FIXED SERVICE TRANSMITTER/RECEIVER	Heat Capacity. ADEQUATE
Average Age NSF: 1964	Intercom: TWO WAY COMPLETE	Walls STUCCO
Relocatable Units: 0	Telephone: NONE	Struct Comp. COMBINATION OF 1-3
Stories: 1		Corridor: SINGLE OUTSIDE

ROOM	ROOM NET SQ FT	DESIGN	DESCRIPTION	STU	E COC	FLOOR COVER	YEAR CONST	соирішом	BLDG	PAR	FAC
400	346	701	COVERED WALKWAY	0	ы	CONCRETE	1964	SATISFACTORY	4	47	46
400A	346	701	COVERED WALKWAY	0	Б	CONCRETE	1964	SATISFACTORY	4	47	46
401	998	-	PRIMARY CLASSROOM (K-3)	92	Б	CARPET	1964	SATISFACTORY	4	47	46
401A	15	814	STUDENT RESTROOM (BOTH SEXES)		Б	CERAMICTILE	1964	SATISFACTORY	4	47	46
401B	17	200	INSIDE CIRCULATION	0	Б	COMPOSITION TILE	1964	SATISFACTORY	4	47	46
401C	35	702	MECHANICAL ROOM		Б	CONCRETE	1964	SATISFACTORY	4	47	46
402	855	10	PRIMARY SKILLS LAB (K-3)	0	Б	CARPET	1964	SATISFACTORY	4	47	46
402A	15	814	STUDENT RESTROOM (BOTH SEXES)	0	Б	CERAMICTILE	1964	SATISFACTORY	4	47	46
402B	17	200	INSIDE CIRCULATION	0	Б	COMPOSITION TILE	1964	SATISFACTORY	4	47	46
402C	29	702	MECHANICAL ROOM	0	Б	CONCRETE	1964	SATISFACTORY	4	47	46
403	998	-	PRIMARY CLASSROOM (K-3)	18	ы	CARPET	1964	SATISFACTORY	4	47	46
403A	15	814	STUDENT RESTROOM (BOTH SEXES)	0	О	CERAMICTILE	1964	SATISFACTORY	4	47	46



FACILITY INVENTORY REPORT

4	4	4	4	4	4	4
47	47	47	47	47	47	47
4	4	4	4	4	4	4
1964 SATISFACTORY	SATISFACTORY	SATISFACTORY	SATISFACTORY	SATISFACTORY	SATISFACTORY	SATISFACTORY
1964	1964	1964	1964	1964	1964	1964
COMPOSITION TILE	CONCRETE	CONCRETE	CARPET	CERAMICTILE	COMPOSITION TILE	CONCRETE
75	5	5	5	5	5	Б
INSIDE CIRCULATION 0	MECHANICAL ROOM 0	ELECTRICAL ROOM 0	PRIMARY CLASSROOM (K-3)	STUDENT RESTROOM (BOTH SEXES) 0	INSIDE CIRCULATION 0	MECHANICAL ROOM
200	702	203	-	814	200	702
17	29	18	840	15	17	35
403B	403C	403D	404	404A	404B	404C

8 8 8 8 9 9

Student Stations

Square Feet

Scheduled For Replacement

	ndards	Failed Standards		ctory	Unsatisfactory	Satisfactory	Sati		
SATISFACI	1964	CONCRETE	Б	0		MECHANICAL ROOM	702	35	404C
SATISFACT	1964	COMPOSITION TILE	Б			INSIDE CIRCULATION	200	17	404B
SATISFACT	1964	CERAMICTILE	Б		(BOTH SEXES)	STUDENT RESTROOM (BOTH SEXES)	814	15	404A
SATISFACT	1964	CARPET	Б	6	1 (K-3)	PRIMARY CLASSROOM (K-3)	-	840	404
SATISFACT	1964	CONCRETE	Б	0		ELECTRICAL ROOM	703	92	403D
SATISFACT	1964	CONCRETE	Б			MECHANICAL ROOM	702	29	403C
SATISFACT	1964	COMPOSITION TILE	Б	0		INSIDE CIRCULATION	1 002	17	403B



Page 9 of 41

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

STRICT
百
00
SCH
≱
Ş
ပ
WARD
ゑ
6 BR
ä
2
SH
=

FACILITY: 46-A TEDDER ELEMENTARY BUILDING: 5 - Building Number 00005

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: ELEMENTARY	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1969	Artificial Lighting: SHELDED FLORE SCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational TV: FIXED SERVICE TRANSMITTER/RECEIVER	Heat Capacity, ADEQUATE
Average Age NSF: 1969	Intercom: TW/O W/A Y COMPLETE	Wall≤ STUCCO
Relocatable Units: 0	Telephone: NONE	Struct Comp. COMBINATION OF 1-3
Stories: 1		Corridor: DOUBLE INSIDE

ROOM											
	ROOM NET SQ FT	DESIGN	DESCRIPTION	STU	FIR	FLOOR COVER	YEAR	СОМВІШОМ	BLDG	PAR	FAC
900	384	200	INSIDE CIRCULATION	0	ы	CARPET	1969	SATISFACTORY	5	47	46
200	429	701	COVERED WALKWAY	0	ы	CONCRETE	1969	SATISFACTORY	5	47	46
500A	. 225	701	COVERED WALKWAY	0	ы	CONCRETE	1969	SATISFACTORY	5	47	46
9009	. 223	701	COVERED WALKWAY	0	10	CONCRETE	1969	SATISFACTORY	5	47	46
501	924	1	PRIMARY CLASSROOM (K-3)	18	10	CARPET	1969	SATISFACTORY	5	47	46
501A	168	315	TEACHER PLANNING OFFICE	0	10	CARPET	1969	SATISFACTORY	5	47	46
501B	88	814	STUDENT RESTROOM (BOTH SEXES)	0	10	CERAMICTILE	1969	SATISFACTORY	5	47	46
502	924	-	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1969	SATISFACTORY	5	47	46
502A	168	315	TEACHER PLANNING OFFICE	0	01	CARPET	1969	SATISFACTORY	5	47	46
502B	98	814	STUDENT RESTROOM (BOTH SEXES)	0	10	CERAMICTILE	1969	SATISFACTORY	5	47	46
503	924	-	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1969	SATISFACTORY	5	47	46
503A	36	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMICTILE	1969	SATISFACTORY	S	47	46



											İ		
504 924	24 1	<u></u>	PRIMARY CLASSROOM (K-3)	(K-3)	6	5	CARPET	1969	SATISFACTORY	TORY .	S.	47	49
504A 36	814		STUDENT RESTROOM (BOTH SEXES)	BOTH SEXES)	0	Б	CERAMICTILE	1969	1989 SATISFACTORY	TORY	5	47	46
		Sati	Satisfactory	Unsatie	Unsatisfactory		Failed Standards	ndards		Scheduled For Replacement	For Rep	lacement	
	Squa	neFeet	Square Feet Student Stations	Square Feet	Student Stations	ations	Square Feet	Student Stations	ations	Square Feet		Student Stations	ions
Permanent		6,119	72	0		0							
TOTAL		6,119	72	0		0	0		0		0		0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 46-A TEDDER ELEMENTARY

BUILDING: 6 - Building Number 00006

Owner. SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
USE: ELEMENTARY	Mech Vert: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1964	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTR.AL HOT AIR
Year Modified:	Educational TV: FIXED SERVICE TRANSMITTER/RECEIVER	Heat Capacity, ADEQUATE
Average Age NSF: 1964	Intercom: TWO WAY COMPLETE	Wall≲ STUCCO
Relocatable Units: 0	Telephone: NONE	Struct Comp. COMBINATION OF 1-3
Stories 1		Corridor: SINGLE OUTSIDE

ROOM	ROOM NET SQ FT	DESIGN CODE	DESCRIPTION	STU	FIR COC	FLOOR COVER	YEAR CONST	СОИВІДОИ	BLDG	PAR	FAC
009	1682	701	COVERED WALKWAY		Б	CONCRETE	1964	SATISFACTORY	9	47	46
600A	326	701	COVERED WALKWAY		Б	CONCRETE	1964	SATISFACTORY	9	47	46
8009	308	701	COVERED WALKWAY		Б	CONCRETE	1964	SATISFACTORY	9	47	46
2009	250	701	COVERED WALKWAY		Б	CONCRETE	1964	SATISFACTORY	9	47	46
601	998	+	PRIMARY CLASSROOM (K-3)	18	Б	CARPET	1964	SATISFACTORY	9	47	46
601A	17	814	STUDENT RESTROOM (BOTH SEXES)		М	CERAMICTILE	1964	SATISFACTORY	9	47	46
6018	17	200	INSIDE CIRCULATION		Б	COMPOSITION TILE	1964	SATISFACTORY	9	47	46
901C	35	702	MECHANICAL ROOM		Ю	CONCRETE	1964	SATISFACTORY	9	47	46
601D	9	203	ELECTRICAL ROOM		Б	CONCRETE	1964	SATISFACTORY	9	47	46
602	840	+	PRIMARY CLASSROOM (K-3)	18	Б	WOOD	1964	SATISFACTORY	9	47	46
602A	17	814	STUDENT RESTROOM (BOTH SEXES)		О	CERAMICTILE	1964	SATISFACTORY	9	47	46
602B	17	200	INSIDE CIRCULATION	0	01	COMPOSITION TILE	1964	SATISFACTORY	9	47	46



FACILITY INVENTORY REPORT

602C	29	702	MECHANICAL ROOM	0	01	CONCRETE	1964	SATISFACTORY	9	47	46
603	998	-	PRIMARY CLASSROOM (K-3)	18	Б	CARPET	1964	SATISFACTORY	9	47	46
603A	17	814	STUDENT RESTROOM (BOTH SEXES)	0	Б	CERAMICTILE	1964	SATISFACTORY	Θ	47	46
803B	17	200	INSIDE CIRCULATION	0	Б	COMPOSITION TILE	1964	SATISFACTORY	9	47	46
903C	35	702	MECHANICAL ROOM	0	Б	CONCRETE	1964	SATISFACTORY	9	47	46
604	855	-	PRIMARY CLASSROOM (K-3)	18	Б	CARPET	1964	SATISFACTORY	9	47	46
604A	17	814	STUDENT RESTROOM (BOTH SEXES)	0	Б	CERAMICTILE	1964	SATISFACTORY	9	47	46
604B	17	200	INSIDE CIRCULATION	0	Б	COMPOSITION TILE	1964	SATISFACTORY	9	47	46
604C	32	702	MECHANICAL ROOM	0	Б	CONCRETE	1964	SATISFACTORY	9	47	46

Scheduled For Replacement	Student Stations		0
ScheduledFo	Square Feet		0
Failed Standards	Student Stations		0
Failed St	Square Feet		0
Unsatisfactory	Square Feet Student Stations	0	0
Unsatie	Square Feet	0	0
Satisfactory	Student Stations	72	72
Satist	Square Feet	6,278	6,278
		Permanent	TOTAL



Prepared by: **HEERY**

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 46-A TEDDER ELEMENTARY

BUILDING: 7 - Building Number 00007

Owner. SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: ELEMENTARY	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1964	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational TV: FIXED SERVICE TRANSMITTER/RECEIVER	Heat Capacity. ADEQUATE
Average Age NSF: 1964	Intercom: TWO WAY COMPLETE	Wall≲ STUCCO
Relocatable Units: 0	Telephone: P.ARTIAL SYSTEM	Struct Comp. COMBINATION OF 1-3
Stories: 1		Corridor: SINGLE OUTSIDE

ROOM	ROOM NET SQ FT	DESIGN	DESCRIPTION	STU	F 20	FLOOR COVER	YEAR	СОИВІЛІОМ	BLDG	PAR	FAC
200	410	701	COVERED WALKWAY		Б	CONCRETE	1964	SATISFACTORY	2	47	46
700A	338	701	COVERED WALKWAY		5	CONCRETE	1964	SATISFACTORY	2	47	46
701	1295	50	ART - ELEMENTARY		5	COMPOSITION TILE	1964	SATISFACTORY	2	47	46
701.8	315	810	MATERIAL STORAGE (LARGE)		Б	COMPOSITION TILE	1964	SATISFACTORY	2	47	46
701B	8	805	KILN		δ	COMPOSITION TILE	1964	SATISFACTORY	2	47	46
702	110	702	MECHANICAL ROOM		δ	CONCRETE	1964	SATISFACTORY	2	47	46
703	176	816	STUDENT RESTROOM (FEMALE)		5	CERAMICTILE	1964	SATISFACTORY	2	47	46
704	142	815	STUDENT RESTROOM (MALE)		Б	CERAMICTILE	1964	SATISFACTORY	2	47	46
202	288	301	ASSISTANT PRINCIP AL/OTHER OFFICE		Б	CARPET	1964	SATISFACTORY	2	47	46
705A	55	808	MATERIAL STORAGE	0	М	COMPOSITION TILE	1964	SATISFACTORY	2	47	46



46			92		0
47		acement	Student Stations		
2		r Repla	₽g.		
TORY		Scheduled For Replacement	Square Feet		0
SATISFAC			tions		0
1964 SATISFACTORY	•	ndards	Student Stations		
CONCRETE		Failed Standards	Square Feet		0
101			tations	0	0
0		actory	Student Stations		
LOSET		Unsatisfactory	Square Feet	0	0
CUSTODIAL SERVICE CLOSET		Satisfactory	Student Stations	0	0
334 CI		Satist	Square Feet	3,514	3,514
25				ant	
902				Permanent	TOTAL





FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 46-A TEDDER ELEMENTARY BUILDING: 8 - Building Number 00008

Cooling: CENTRAL	Heat Source: ELECTRIC	Heat Distribution: CENTRAL HOT AIR	Heat Capacity. ADEQUATE	Wall≲ STUCCO	Struct Comp. COMBINATION OF 1-3	Corridor: SINGLE OUTSIDE
Light: ADEQUATE	Mech Vent: ADEQUATE	Artificial Lighting: SHIELDED FLORESCENT	Educational TV: FIXED SERVICE TRANSMITTERRECEIVER	Intercom: TWO WAY COMPLETE	Telephone: COMPLETE TO ALL ROOMS	
Owner. SCHOOL BOARD	Use: ELEMENTARY	Year Constructed: 1964	Year Modified:	Average Age NSF: 1964	Relocatable Units: 0	Stories: 1

ROOM NET SQ FT											Ì
	NET SQ FT	DESIGN	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR	СОИВІПОИ	вгре	PAR	FAC
8	20	200	INSIDE CIRCULATION	0	М	CARPET	1964	SATISFACTORY	00	47	46
800	1077	701	COVERED WALKWAY	0	М	CONCRETE	1964	SATISFACTORY	00	47	46
800A	395	701	COVERED WALKWAY	0	М	CONCRETE	1964	SATISFACTORY	00	47	46
800B	623	701	COVERED WALKWAY	0	М	CONCRETE	1964	SATISFACTORY	00	47	46
801	275	304	RECEPTION AREA	0	М	CARPET	1964	SATISFACTORY	ω	47	46
802 (808	303	SECRETARIAL SPACE	0	М	CARPET	1964	SATISFACTORY	ω	47	46
803	221	300	PRINCIPAL/DIRECTOR OFFICE	0	М	CARPET	1964	SATISFACTORY	00	47	46
804	144	301	ASSISTANT PRINCIP AL/OTHER OFFICE	0	М	COMPOSITION TILE	1964	SATISFACTORY	00	47	46
, 508	159	307	CLINIC	0	М	COMPOSITION TILE	1964	SATISFACTORY	00	47	46
805A	72	814	STUDENT RESTROOM (BOTH SEXES)	0	М	COMPOSITION TILE	1964	SATISFACTORY	00	47	46
908	88	820	STAFF RESTROOM (FEMALE)	0	М	COMPOSITION TILE	1964	SATISFACTORY	ω	47	46
208	50	819	STAFF RESTROOM (MALE)	0	01	COMPOSITION TILE	1964	SATISFACTORY	00	47	46

Page 16 of 41



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

	8 47 46	8 47 46	Scheduled For Replacement	Square Feet Student Stations		0
5	SATISFACTORY	SATISFACTORY	s			0
1964	1964	1964	andards	Student Stations		
CANFEL	CONCRETE	CONCRETE	Failed Standards	Square Feet		0
<u>8</u>	Б	Б		Stations	0	0
<u>-</u>	0	0	Unsatisfactory	Student Stations		
MOC	RDS		Superior	Square Feet	0	0
PRODUCTION WORKROOM	VAULT/STUDENT RECORDS	COMPUTER AREA	Satisfactory	Student Stations	0	0
305 PF	308	312	Satis	Square Feet	4,456	4,456
307	22	160		47	int	
808	608	810			Permanent	TOTAL



FACILITY INVENTORY REPORT

DISTRICT	
TY SCHOOL	
RD COUN	
: 6 BROWA	
DISTRICT	

FACILITY: 46-A TEDDER ELEMENTARY

BUILDING: 9 - Building Number 00009

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: ELEMENTARY	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 2003	Artificial Lighting: SHELDED FLORE SCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational TV: FIXED SERVICE RECEIVER	Heat Capacity, ADEQUATE
Average Age NSF: 2003	Intercom: TWO WAY COMPLETE	Walls STUCCO
Relocatable Units: 0	Telephone P.ARTIAL SYSTEM	Struct Comp. COMBINATION OF 1-3
Stories: 1		Corridor: SINGLE OUTSIDE

ROOM NET SQ FT DESIGN CODE DESIGN INSIDE CIRCULATION 091 113 700 INSIDE CIRCULATION 092 110 700 INSIDE CIRCULATION 092B 38 700 INSIDE CIRCULATION 093B 46 700 INSIDE CIRCULATION 094 42 700 INSIDE CIRCULATION 095 50 INSIDE CIRCULATION 095 50 INSIDE CIRCULATION 096 700 INSIDE CIRCULATION 097 700 INSIDE CIRCULATION 098 50 700 INSIDE CIRCULATION 099 1591 701 COVERED WALKWAY	CRIPTION	STU	1		1		2010	:	500
199 700 113 700 110 700 38 700 46 700 64 700 50 700 1591 701		STA	1 1 1 1	FLOOR COVER	CONST	Nollida	BLUG	YA.	į
113 700 110 700 38 700 46 700 64 700 50 700 1591 701			Б	COMPOSITION TILE	2003	SATISFACTORY	6	47	46
110 700 38 700 46 700 64 700 42 700 50 700 1591 701	N	0	Б	COMPOSITION TILE	2003	SATISFACTORY	6	47	46
38 700 46 700 64 700 42 700 50 700 1591 701		0	Б	COMPOSITION TILE	2003	SATISFACTORY	6	47	46
46 700 64 700 42 700 50 700 1591 701		0	Б	COMPOSITION TILE	2003	SATISFACTORY	o	47	46
64 700 42 700 50 700 1591 701		0	Б	COMPOSITION TILE	2003	SATISFACTORY	6	47	46
42 700 50 700 1591 701		0	Б	COMPOSITION TILE	2003	SATISFACTORY	6	47	46
50 700		0	Б	COMPOSITION TILE	2003	SATISFACTORY	6	47	46
1591 701			۵	COMPOSITION TILE	2003	SATISFACTORY	6	47	46
		0	Б	CONCRETE	2003	SATISFACTORY	6	47	46
900A 668 701 COVERED WALKWAY		0	Б	CONCRETE	2003	SATISFACTORY	o	47	46
900B 254 701 COVERED WALKWAY		0	Б	CONCRETE	2003	SATISFACTORY	6	47	46
900C 254 701 COVERED WALKWAY		0	01	CONCRETE	2003	SATISFACTORY	6	47	46

Page 18 of 41



FACILITY INVENTORY REPORT

Г	5	1	2000 C 1000 C 10		2	CONCETE	0000	>00000000000000000000000000000000000000	ŀ	ţ	٦
ZSU (701 COVERED WALKW	COVERED WA	COVERED WALKW	۵۲	<u> </u>	5	CONCRETE	2003	SALISFACIORY	n	4	₹
2336 361 MULTIPURPOSE ROOM (DINING)		MULTIPURPOSE R	OOM (DINING)		Б	COMPOSITION TILE	2003	SATISFACTORY	6	47	4
102 362 MULTIPURPOSE R		MULTIPURPOSE R	MULTIPURPOSE ROOM CHAIR STORAGE		Б	COMPOSITION TILE	2003	SATISFACTORY	o	47	4
102 364 STAGE STORAGE		STAGE STORAGE			Б	COMPOSITION TILE	2003	SATISFACTORY	6	47	4
33 707 TELEPHONE EQUIF		TELEPHONE EQUIF	TELEPHONE EQUIPMENT/COMMUNICATION CLOSET	0	20	COMPOSITION TILE	2003	SATISFACTORY	o	47	₹
177 362 MULTIPURPOSE R		MULTIPURPOSE R	MULTIPURPOSE ROOM CHAIR STORAGE	0	Б	COMPOSITION TILE	2003	SATISFACTORY	6	47	4
1052 363 STAGE		STAGE			Б	COMPOSITION TILE	2003	SATISFACTORY	6	47	4
35 364 STAGE STORAGE		STAGE STORAGE			Б	COMPOSITION TILE	2003	SATISFACTORY	6	47	4
126 364 STAGE STORAGE		STAGE STORAGE			Б	COMPOSITION TILE	2003	SATISFACTORY	6	47	4
178 365 STAGE DRESSING ROOM (MALE)		STAGE DRESSING F	(OOM (MALE)		Б	COMPOSITION TILE	2003	SATISFACTORY	6	47	4
178 366 STAGE DRESSING ROOM (FEMALE)		STAGE DRESSING R	OOM (FEMALE)		Б	COMPOSITION TILE	2003	SATISFACTORY	6	47	4
289 816 STUDENT RESTROC	STUDENT REST	ı ⊢	ROOM (FEMALE)	0	Б	CERAMICTILE	2003	SATISFACTORY	o	47	4
226 815 STUDENT RESTROC	STUDENT REST		ROOM (MALE)	0	Б	CERAMICTILE	2003	SATISFACTORY	o	47	4
38 331 CUSTODIAL SERVICE CLOSET		CUSTODIAL SERVIC	E CLOSET	0	Б	CONCRETE	2003	SATISFACTORY	o	47	4
331 702 MECHANICAL ROOM		MECHANICAL ROOF	5	0	Б	CONCRETE	2003	SATISFACTORY	6	47	4
4000 340 DINING AREA		DINING AREA		0	Б	COMPOSITION TILE	2003	SATISFACTORY	6	47	4
120 349 KITCHEN CHAIR S	KITCHEN CHAI		R STORAGE	0	Б	COMPOSITION TILE	2003	SATISFACTORY	6	47	4
120 344 KITCHEN GARBAGE WASH		KITCHEN GARBAC	SE WASH	0	10	QUARRYTILE	2003	SATISFACTORY	6	47	4
76 350 OTHER FOOD SERVICE		OTHER FOOD SEF	RMCE	0	Б	COMPOSITION TILE	2003	SATISFACTORY	6	47	4
1589 341 KITCHEN & SERVING AREA		KITCHEN & SERV	ING AREA	0	10	QUARRYTILE	2003	SATISFACTORY	6	47	4
200 342 MITCHEN DRY STORAGE		KITCHEN DRY ST	ORAGE	0	10	COMPOSITION TILE	2003	SATISFACTORY	6	47	4
170 343 KITCHEN OFFICE	KITCHEN OFFI	KITCHEN OFFICE		0	10	COMPOSITION TILE	2003	SATISFACTORY	6	47	4
128 345 KITCHEN NONFOOD STORAGE		KITCHEN NONFOO	DD STORAGE	0	10	COMPOSITION TILE	2003	SATISFACTORY	9	47	46



9100	40	350	OTHER FOOD SERVICE	0	Б	COMPOSITION TILE	2003	SATISFACTORY	σ	47	46
910E	99	344	KITCHEN GARBAGE WASH	0	Б	QUARRYTILE	2003	SATISFACTORY	o	47	46
910F	88	350	OTHER FOOD SERVICE	0	Б	CONCRETE	2003	SATISFACTORY	o	47	46
9100	103	350	OTHER FOOD SERVICE	0	Б	CONCRETE	2003	SATISFACTORY	o	47	46
910H	æ	820	STAFF RESTROOM (FEMALE)	0	Б	CERAMICTILE	2003	SATISFACTORY	o	47	46
910.1	154	316	TEACHER LOUNGE/DINING	0	Б	COMPOSITION TILE	2003	SATISFACTORY	б	47	46
911	48	819	STAFF RESTROOM (MALE)	0	Б	CERAMICTILE	2003	SATISFACTORY	6	47	46
912	62	820	STAFF RESTROOM (FEMALE)	0	Б	CERAMICTILE	2003	SATISFACTORY	6	47	46
913	422	316	TEACHER LOUNGE/DINING	0	Б	COMPOSITION TILE	2003	SATISFACTORY	o	47	46
914	224	702	MECHANICAL ROOM	0	Б	CONCRETE	2003	SATISFACTORY	o	47	46
915	8	331	CUSTODIAL SERMCE CLOSET	0	Б	CONCRETE	2003	SATISFACTORY	o	47	46
916	150	333	FLAMMABLE STORAGE	0	Б	CONCRETE	2003	SATISFACTORY	o	47	46
917	425	334	CUSTODIAL EQUIPMENT STORAGE	0	Б	CONCRETE	2003	SATISFACTORY	o	47	46
918	187	703	ELECTRICAL ROOM	0	Б	CONCRETE	2003	SATISFACTORY	o	47	46
919	247	702	MECHANICAL ROOM	0	Б	CONCRETE	2003	SATISFACTORY	o	47	46
920	794	702	MECHANICAL ROOM	0	Б	CONCRETE	2003	SATISFACTORY	o	47	46
920A	157	203	ELECTRICAL ROOM	0	Ю	CONCRETE	2003	SATISFACTORY	o	47	46
922	280	330	CUSTODIAL RECEIVING	0	Б	CONCRETE	2003	SATISFACTORY	o	47	46
922A	135	332	CUSTODIAL WORK AREA	0	Б	COMPOSITION TILE	2003	SATISFACTORY	o	47	46
922B	41	819	STAFF RESTROOM (MALE)	0	Ю	CERAMICTILE	2003	SATISFACTORY	б	47	46
923	211	203	ELECTRICAL ROOM	0	Ю	COMPOSITION TILE	2003	SATISFACTORY	б	47	46
924	88	203	ELECTRICAL ROOM	0	Б	COMPOSITION TILE	2003	SATISFACTORY	б	47	46
925	47	331	CUSTODIAL SERMCE CLOSET	0	Б	CONCRETE	2003	SATISFACTORY	6	47	46



FACILITY INVENTORY REPORT

925A 71	344 þ	KITCHEN GARBAGE WASH	SH	0	01	CONCRETE	2003	2003 SATISFACTORY	TORY	6	47	46
	Sati	Satisfactory	Unsatisfactory	actory		Failed Standards	andards		Scheduled For Replacement	or Replac	ement	
Sq	Square Feet	Student Stations	Square Feet	Student Stations	ations	Square Feet	Student Stations	ations	Square Feet	Strud	Student Stations	ø
Permanent	19,656	0	0		0							
TOTAL	19,656	0	0		0	0		0		0		0



Page 21 of 41

FACILITY INVENTORY REPORT

DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILIY: 46-A TEDDER ELEMENTARY

BUILDING: 13 - Building Number 00013

Owner. SCHOOL BO ARD	Light: ADEQUATE	Cooling: CENTRAL
Use: ELEMENTARY	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1990	Artificial Lighting: SHIELDED FLORE SCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational TV: FIXED SERVICE TRANSMITTER/RECEIVER	Heat Capacity. ADEQUATE
Average Age NSF: 1990	Intercom: TWO WAY COMPLETE	Walls: STUCCO
Relocatable Units: 0	Telephone: P.ARTIAL SYSTEM	Struct Comp. COMBINATION OF 1-3
Stories: 1		Corridor: SINGLE OUTSIDE

]
							•			•	•	•
ROOM	ROOM NET SQ FT	DESIGN	DESCRIPTION		STU	F.R. 201	FLOOR COVER	YEAR CONST	соивілои	BLDG	PAR	FAC
134	1560	55	MUSIC - ELEMENTARY	0		Б	CARPET	1990	SATISFACTORY	13	47	46
131A	22	831	MUSIC PRACTICE ROOM	0		Б	CARPET	1990	SATISFACTORY	13	47	46
131B	153	808	MATERIAL STORAGE	0		б	COMPOSITION TILE	1990	SATISFACTORY	13	47	46
131C	153	908	REFERENCE	0		М	CARPET	1990	SATISFACTORY	13	47	46
131D	113	315	TEACHER PLANNING OFFICE	0		О	COMPOSITION TILE	1990	SATISFACTORY	13	47	46
132	208	702	MECHANICAL ROOM	0		д	CONCRETE	1990	SATISFACTORY	13	47	46
133	290	316	TEACHER LOUNGE/DINING	0		д	CARPET	1990	SATISFACTORY	13	47	46
133A	168	316	TEACHER LOUNGE/DINING	0		01	CARPET	1990	SATISFACTORY	13	47	46
134	1335	315	TEACHER PLANNING OFFICE	0		01	CARPET	1990	SATISFACTORY	13	47	46
134A	61	820	STAFF RESTROOM (FEMALE)	0		01	CERAMICTILE	1990	SATISFACTORY	13	47	46



FACILITY INVENTORY REPORT

134B 61		819	STAFF RESTROOM (MALE)	LE)	0	П	CERAMICTILE	1990	SATISFACTORY	TORY	13	47	46
		Sat	Satisfactory	Unsatisfactory	actory		Failed Standards	indards		Scheduled For Replacement	or Rep	acement	
	Š	quare Feet	Square Feet Student Stations	Square Feet	Student Stations	Suo	Square Feet	Student Stations	itions	Square Feet	\$	Student Stations	SUO
Permanent	+	4,177	0	0		0							
TOTAL		4,177	0	0		0	0		0		0		0



Page 23 of 41

Prepared by: **HEERY**

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT	
SCHOOL	
COUNTY	
BROWARD	
DISTRICT: 6	
_	

FACILITY: 46-A TEDDER ELEMENTARY BUILDING: 14 - Building Number 00014

Cooling: CENTRAL	Heat Source: ELECTRIC	IT Heat Distribution: CENTRAL HOT AIR	MITTER/RECEIVER Heat Capacity, ADEQUATE	Walls STUCCO	Struct Comp. COMBINATION OF 1-3	POLITRIDE
Light: ADEQUATE	Mech Vent: ADEQUATE	Artificial Lighting: SHIELDED FLORESCENT	Educational TV: FIXED SERVICE TRANSMITTER/RECEIVER	Intercom: TWO WAY COMPLETE	Telephone P ARTIAL SYSTEM	
Owner: SCHOOL BO ARD	USE: ELEMENTARY	Year Constructed: 1990	Year Modified:	Average Age NSF: 1990	Relocatable Units: 0	Otherine 1

ROOM	ROOM NET SQ FT	DESIGN	DESCRIPTION	STU	FLR	FLOOR COVER	YEAR CONST	соирішом	BLDG	PAR	FAC
014	418	700	INSIDE CIRCULATION		Б	COMPOSITION TILE	1990	SATISFACTORY	14	47	46
141	780	1	PRIMARY CLASSROOM (K-3)	18	10	COMPOSITION TILE	1990	SATISFACTORY	14	47	46
141.8	88	814	STUDENT RESTROOM (BOTH SEXES)	0	ы	CERAMICTILE	1990	SATISFACTORY	14	47	46
1418	100	808	MATERIAL STORAGE	0	ы	COMPOSITION TILE	1990	SATISFACTORY	14	47	46
141C	8	808	MATERIAL STORAGE	0	ы	CARPET	1990	SATISFACTORY	14	47	46
142	780	62	ESEFULL-TIME	10	Б	CARPET	1990	SATISFACTORY	14	47	46
142A	8	814	STUDENT RESTROOM (BOTH SEXES)	0	Б	CERAMICTILE	1990	SATISFACTORY	14	47	46
142B	100	808	MATERIAL STORAGE		Б	COMPOSITION TILE	1990	SATISFACTORY	14	47	46
142C	3	808	MATERIAL STORAGE	0	Б	CARPET	1990	SATISFACTORY	14	47	46
143	510	40	RESOURCE ROOM	0	Б	CARPET	1990	SATISFACTORY	4	47	46
143A	8	814	STUDENT RESTROOM (BOTH SEXES)	0	ы	CERAMICTILE	1990	SATISFACTORY	4	47	46
143B	86	808	MATERIAL STORAGE	0	ы	COMPOSITION TILE	1990	SATISFACTORY	4	47	46



									İ	ŀ	
144	510	92	E S E RESOURCE	0	Б	CARPET	1990	SATISFACTORY	4	47	46
144A	8	814	STUDENT RESTROOM (BOTH SEXES)	0	Б	CERAMIC TILE	1990	SATISFACTORY	4	47	46
144B	8	808	MATERIAL STORAGE		Б	COMPOSITION TILE	1990	SATISFACTORY	4	47	46
145	8	808	MATERIAL STORAGE		Б	CONCRETE	1990	SATISFACTORY	4	47	46
146	117	702	MECHANICAL ROOM	0	Б	CONCRETE	1990	SATISFACTORY	4	47	46
148	780	62	ESEFULL-TIME	10	Б	COMPOSITION TILE	1990	SATISFACTORY	4	47	46
148A	8	814	STUDENT RESTROOM (BOTH SEXES)		Б	CERAMICTILE	1990	SATISFACTORY	4	47	46
148B	6	808	MATERIAL STORAGE		Б	COMPOSITION TILE	1990	SATISFACTORY	4	47	46
148C	ਲ	808	MATERIAL STORAGE		Б	CARPET	1990	SATISFACTORY	4	47	46
149	1069	10	PRIMARY SKILLS LAB (K-3)		Б	COMPOSITION TILE	1990	SATISFACTORY	4	47	46
150	510	40	RESOURCE ROOM		Б	COMPOSITION TILE	1990	SATISFACTORY	4	47	46
150A	8	814	STUDENT RESTROOM (BOTH SEXES)		Б	CER,AMIC TILE	1990	SATISFACTORY	4	47	46
150B	8	808	MATERIAL STORAGE	0	Б	COMPOSITION TILE	1990	SATISFACTORY	4	47	46
151	160	314	ITINERANT OFFICE	0	Б	CARPET	1990	SATISFACTORY	4	47	46
151A	9	808	MATERIAL STORAGE		Б	COMPOSITION TILE	1990	SATISFACTORY	4	47	46
152	160	314	ITINERANT OFFICE		Б	CARPET	1990	SATISFACTORY	4	47	46
152A	9	808	MATERIAL STORAGE		Б	COMPOSITION TILE	1990	SATISFACTORY	4	47	46
153	46	811	OUTSIDE STORAGE		Б	CONCRETE	1990	SATISFACTORY	4	47	46
154	117	702	MECHANICAL ROOM		Б	CONCRETE	1990	SATISFACTORY	4	47	46
155	28	331	CUSTODIAL SERVICE CLOSET		Б	CONCRETE	1990	SATISFACTORY	4	47	46

	Sati	Satisfactory	Unsati	Unsatisfactory	Failed Standards	andards	Scheduled For Replacement	Replacement
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	7,146	38	0	0				
TOTAL	7,146	38	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT FACILITY: 46-A TEDDER ELEMENTARY

BUILDING: 15 - Building Number 00015

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
USS: ELEMENTARY	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1990	Artificial Lighting: SHELDED FLORE SCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational TV: FIXED SERVICE TRANSMITTER, RECEIVER	Heat Capacity, ADEQUATE
Average Age NSF: 1990	Intercom: TWO WAY COMPLETE	Walls STUCCO
Relocatable Units: 0	Telephone P.ARTIAL SYSTEM	Struct Comp: COMBINATION OF 1-3
Stories: 1		Corridor: SINGLE OUTSIDE

ROOM	ROOM NET SQ FT	DESIGN	DESCRIPTION	STU	F.R.	FLOOR COVER	YEAR	сомрідом	BLDG	PAR	FAC
161	2281	380	LIBRARY (READING ROOM/STACKS)	0	М	CARPET	1990	SATISFACTORY	15	47	46
161A	26	815	STUDENT RESTROOM (MALE)	0	Б	CERAMICTILE	1990	SATISFACTORY	15	47	46
161B	119	816	STUDENT RESTROOM (FEMALE)	0	Ю	CERAMICTILE	1990	SATISFACTORY	15	47	46
161C	460	385	CLOSED CIRCUIT TV LAB	0	Ю	COMPOSITION TILE	1990	SATISFACTORY	15	47	46
161D	532	383	AUDIO VISUAL STORAGE	0	Б	CARPET	1990	SATISFACTORY	15	47	46
161E	325	390	MEDIA GROUP PROJECTSANSTRUCTION	0	Ю	CARPET	1990	SATISFACTORY	15	47	46
161F	888	381	MEDIA TECHNICAL PROCESSING	0	Ю	CARPET	1990	SATISFACTORY	15	47	46
1616	149	301	ASSISTANT PRINCIP AL/OTHER OFFICE	0	Ю	CARPET	1990	SATISFACTORY	15	47	46
161H	176	306	CONFERENCE ROOM	0	Ю	CARPET	1990	SATISFACTORY	15	47	46
161	188	386	CLOSED CIRCUIT STORAGE	0	Ю	CARPET	1990	SATISFACTORY	15	47	46
162	144	702	MECHANICAL ROOM	0	Б	CONCRETE	1990	SATISFACTORY	15	47	46
163	98	331	CUSTODIAL SERMCE CLOSET	0	01	CONCRETE	1990	SATISFACTORY	15	47	46

Page 26 of 41



FACILITY INVENTORY REPORT

164	88	. 898	TEXTBOOK STORAGE		0	Б	CONCRETE	1990	1990 SATISFACTORY	TORY	15	47	46
		Sat	Satisfactory	Unsatisfactory	actory		Failed Standards	andards		Scheduled For Replacement	For Rep	acement	
	Ñ	Square Feet	Student Stations	Square Feet	Student Stations	ations	Square Feet	Student Stations	ations	Square Feet		Student Stations	8
Permanent	ŧ	5,542	0 :	0		0							
TOTAL		5,542	0 :	0		0	0		0		0		0



164

Page 27 of 41

FACILITY INVENTORY REPORT

ICT
ST
8
SG
ĭ
S
ဗ
8
Š
BRO
9:
C
Ĕ
OIS

FACILITY: 46-A TEDDER ELEMENTARY

BUILDING: 16 - Building Number 00016

Owner. SCHOOL BOARD	Light: ADEQUATE	Cooling: INDIMDUAL UNITS
USS: ELEMENTARY	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 2004	Artificial Lighting: SHELDED FLORE SCENT	Heat Distribution: INDIMDUAL UNIT REVERSE CYCLE
Year Modified:	Educational TV: FIXED SERVICE RECEIVER	Heat Capacity, ADEQUATE
Average Age NSF: 2004	Intercom: TWO WAY COMPLETE	Walls: CONCRETE
Relocatable Units: 0	Telephone: P ARTIAL SYSTEM	Struct Comp: CONCRETE
Stories: 2		Corridor: DOUBLE INSIDE

											1
ROOM	ROOM NET SQ FT	DESIGN	DESCRIPTION	STU	H 201	FLOOR COVER	YEAR CONST	соивілои	BLDG	PAR	FAC
910	4044	200	INSIDE CIRCULATION		Б	COMPOSITION TILE	2004	SATISFACTORY	16	47	46
016A	40	827	ELEVATOR (PASSENGER/HANDICAPPED)		Б	COMPOSITION TILE	2004	SATISFACTORY	16	47	46
1600	270	701	COVERED WALKWAY		Б	CONCRETE	2004	SATISFACTORY	16	47	46
1600A	247	701	COVERED WALKWAY		Б	CONCRETE	2004	SATISFACTORY	16	47	46
1600B	261	701	COVERED WALKWAY		Б	CONCRETE	2004	SATISFACTORY	16	47	46
1600C	4465	701	COVERED WALKWAY		Б	CONCRETE	2004	SATISFACTORY	16	47	46
1600D	261	701	COVERED WALKWAY		Б	CONCRETE	2004	SATISFACTORY	16	47	46
1601	868	-	PRIMARY CLASSROOM (K-3)	18	Б	COMPOSITION TILE	2004	SATISFACTORY	16	47	46
1601A	45	814	STUDENT RESTROOM (BOTH SEXES)		Б	CERAMICTILE	2004	SATISFACTORY	16	47	46
1601B	20	808	MATERIAL STORAGE		Б	COMPOSITION TILE	2004	SATISFACTORY	16	47	46
1601C	35	703	ELECTRICAL ROOM		Б	CONCRETE	2004	SATISFACTORY	16	47	46
1602	888	-	PRIMARY CLASSROOM (K-3)	18	Б	COMPOSITION TILE	2004	SATISFACTORY	16	47	46

Page 28 of 41



Report Date: 4/19/2010 10:31:31 AM

46 \$ 46 46 46 46 46 46 # 46 46 46 46 46 46 # 46 46 46 46 46

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

47 16 16 16 16 16 16 16 16 16 16 9 16 16 16 16 16 16 9 16 16 16 16 16 16 SATISFACTORY 2004 TI_E 븰 COMPOSITION TILE 빌 1 COMPOSITION TILE COMPOSITION COMPOSITION COMPOSITION COMPOSITION COMPOSITION COMPOSITION COMPOSITION CERAMIC TILE COMPOSITION CERAMIC TILE CERAMIC TILE COMPOSITION CERAMIC TILE CERAMIC TILE COMPOSITION CERAMIC TILE CONCRETE CONCRETE CONCRETE CONCRETE CONCRETE CONCRETE 8 8 8 8 2 5 5 5 5 2 2 2 5 8 5 5 8 2 2 8 5 9 9 9 9 9 9 0 STUDENT RESTROOM (BOTH SEXES) (BOTH SEXES) STUDENT RESTROOM (BOTH SEXES) STUDENT RESTROOM (BOTH SEXES) (BOTH SEXES) STUDENT RESTROOM (BOTH SEXES) PRIMARY CLASSROOM (K-3) STUDENT RESTROOM STUDENT RESTROOM MATERIAL STORAGE MATERIAL STORAGE MATERIAL STORAGE MATERIAL STORAGE MATERIAL STORAGE MATERIAL STORAGE ELECTRICAL ROOM ELECTRICAL ROOM ELECTRICAL ROOM ELECTRICAL ROOM ELECTRICAL ROOM ELECTRICAL ROOM 814 914 23 914 8 24 8 <u>84</u> 8 8 8 8 8 <u>8</u> 8 8 8 233 88 88 88 88 88 88 \$ \$ \$ g \$ \$ \$ 8 g 8 Ж 8 8 g 8 Ж 8 Ж 1602A 1604B 602B 802C 603A 803 803 1604A 1604C 1605A B05B 1606A B009 1607A B07B 883 1605C 9090 1607C 603 88 8 8 8 607



46 \$ 46 46 46 46 46 46 # 46 46 46 46 46 46 # 46 46 46 46

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

47 16 16 16 16 16 16 16 16 16 16 16 16 16 16 16 16 16 9 16 16 16 16 16 16 SATISFACTORY 2004 11 빌 COMPOSITION TILE 빌 COMPOSITION TILE COMPOSITION TILE COMPOSITION COMPOSITION COMPOSITION COMPOSITION COMPOSITION COMPOSITION CERAMIC TILE CERAMIC TILE COMPOSITION CERAMIC TILE CERAMIC TILE COMPOSITION CERAMIC TILE CERAMIC TILE CERAMIC TILE CONCRETE CONCRETE CONCRETE CONCRETE CONCRETE CONCRETE 8 8 8 8 2 5 5 5 5 2 2 2 5 8 5 5 8 2 2 8 5 9 9 9 9 STUDENT RESTROOM (BOTH SEXES) STUDENT RESTROOM (BOTH SEXES) STUDENT RESTROOM (BOTH SEXES) STUDENT RESTROOM (BOTH SEXES) STUDENT RESTROOM (BOTH SEXES) STAFF RESTROOM (BOTH SEXES) CUSTODIAL SERVICE CLOSET GENERAL SCHOOL STORAGE GENERAL SCHOOL STORAGE PRIMARY CLASSROOM (K-3) PRIMARY CLASSROOM (K-3) PRIMARY CLASSROOM (K-3) PRIMARY CLASSROOM (K-3) MATERIAL STORAGE MATERIAL STORAGE MATERIAL STORAGE MATERIAL STORAGE MATERIAL STORAGE ELECTRICAL ROOM ELECTRICAL ROOM ELECTRICAL ROOM ELECTRICAL ROOM ELECTRICAL ROOM ELECTRICAL ROOM 914 203 308 8 <u>8</u> 808 23 <u>84</u> 88 233 8 914 88 8 8 8 8 ਲ 8 420 88 112 88 8 8 88 \$ \$ \$ 8 \$ 8 g 8 Ж 23 8 8 8 8 \$ 8 1617A 1615A 1617B 1608A 808 609A 80g 1615B 16150 1616A 1616B 1616C 16170 8080 9090 1615 1612 1814 919 609 9 8 9 617



\$ 46 \$ 46 46 46 46 46 46 # 46 46 46 46 46 46 # 46 46 46 46 46

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

47 16 16 16 16 9 16 16 16 16 16 9 16 16 16 16 16 16 9 16 16 16 16 16 16 SATISFACTORY 2004 1 1 빌 빌 빌 빌 TI_E COMPOSITION TILE COMPOSITION COMPOSITION COMPOSITION COMPOSITION COMPOSITION COMPOSITION COMPOSITION CERAMIC TILE COMPOSITION CERAMIC TILE CERAMIC TILE COMPOSITION COMPOSITION CERAMIC TILE CERAMIC TILE COMPOSITION CERAMIC TILE CONCRETE CONCRETE CONCRETE CONCRETE CONCRETE CONCRETE 8 8 2 5 5 5 5 5 2 8 8 2 2 5 8 5 5 8 2 2 8 5 9 9 9 9 9 9 STUDENT RESTROOM (BOTH SEXES) (BOTH SEXES) STUDENT RESTROOM (BOTH SEXES) STUDENT RESTROOM (BOTH SEXES) STUDENT RESTROOM (BOTH SEXES) STUDENT RESTROOM (BOTH SEXES) PRIMARY CLASSROOM (K-3) STUDENT RESTROOM MATERIAL STORAGE MATERIAL STORAGE MATERIAL STORAGE MATERIAL STORAGE MATERIAL STORAGE MATERIAL STORAGE ELECTRICAL ROOM ELECTRICAL ROOM ELECTRICAL ROOM ELECTRICAL ROOM ELECTRICAL ROOM ELECTRICAL ROOM 8 8 233 814 8 <u>8</u> 23 <u>84</u> 88 233 8 <u>8</u> 8 808 914 88 <u>8</u> 8 8 88 8 88 8 88 \$ \$ \$ g \$ \$ 8 g 8 Ж 8 8 8 8 8 \$ 8 1618A 1620A 621A 1621C 1623A 618B 16180 1619A 1619B 1620B 950C 1621B 622A 622B 622C 1623B 1623C 16190 918 93 620 622 623 8



\$ 46 \$ 46 46 46 46 46 46 # 46 46 46 46 46 46 # 46 46 46 46 46

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

47 16 16 16 16 16 16 16 16 16 16 9 16 16 16 16 16 16 9 16 16 16 16 16 16 SATISFACTORY 2004 1 1 COMPOSITION TILE 1 빌 빌 빌 TI_E COMPOSITION COMPOSITION COMPOSITION COMPOSITION COMPOSITION CERAMIC TILE COMPOSITION CERAMIC TILE COMPOSITION CERAMIC TILE COMPOSITION CERAMIC TILE COMPOSITION COMPOSITION CERAMIC TILE CONCRETE CONCRETE CONCRETE CONCRETE CONCRETE CONCRETE CONCRETE CONCRETE 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 18 02 5 8 22 22 22 8 22 0 0 INTERMEDIATE/MIDDLE CLASSROOM (4-8) INTERMEDIATE MIDDLE CLASSROOM (4-8) INTERMEDIATE MIDDLE CLASSROOM (4-8) INTERMEDIATE/MIDDLE CLASSROOM (4-8) INTERMEDIATE MIDDLE CLASSROOM (4-8) STUDENT RESTROOM (BOTH SEXES) (BOTH SEXES) STUDENT RESTROOM (BOTH SEXES) STUDENT RESTROOM (BOTH SEXES) STUDENT RESTROOM (BOTH SEXES) STUDENT RESTROOM INSIDE CIRCULATION MATERIAL STORAGE MATERIAL STORAGE MATERIAL STORAGE MATERIAL STORAGE MATERIAL STORAGE MECHANICAL ROOM ELECTRICAL ROOM 8 703 808 8 <u>8</u> 203 88 203 702 <u>8</u> 24 <u>8</u> 914 88 8 8 8 8 8 N 4044 98 9 88 88 8 88 8 9 \$ \$ g \$ 8 \$ 8 Ж 8 8 8 Ж \$ 8 1633A 631A 631B 1631C 1632A 1632B 1632C 1633B 1634A 634B 6340 1635A 1635B 16350 1633C 9168 624 832 83 834 83 82 979 8



	_		_		_	_	_	_	_		_		_	_	_	_	_	_	_			_
47	47	47	47	47	47	47	47	47	47	47	47	47	47	47	47	47	47	47	47	47	47	47
16	91	16	16	16	16	16	16	16	16	16	16	16	16	16	91	16	16	16	16	16	16	16
SATISFACTORY	SATISFACTORY	SATISFACTORY	SATISFACTORY	SATISFACTORY	SATISFACTORY	SATISFACTORY	SATISFACTORY	SATISFACTORY	SATISFACTORY	SATISFACTORY	SATISFACTORY	SATISFACTORY	SATISFACTORY	SATISFACTORY	SATISFACTORY	SATISFACTORY	SATISFACTORY	SATISFACTORY	SATISFACTORY	SATISFACTORY	SATISFACTORY	SATISFACTORY
2004	2004	2004	2004	2004	2004	2004	2004	2004	2004	2004	2004	2004	2004	2004	2004	2004	2004	2004	2004	2004	2004	2004
COMPOSITION TILE	CERAMICTILE	COMPOSITION TILE	CONCRETE	COMPOSITION TILE	CERAMICTILE	COMPOSITION TILE	CONCRETE	COMPOSITION TILE	CERAMICTILE	COMPOSITION TILE	CONCRETE	COMPOSITION TILE	CERAMICTILE	COMPOSITION TILE	CONCRETE	CERAMICTILE	CERAMICTILE	CONCRETE	COMPOSITION TILE	CONCRETE	COMPOSITION TILE	CERAMICTILE
02	02	02	02	02	02	02	02	02	02	02	02	02	02	02	02	02	02	02	02	02	02	02
22				22				22				22									22	
INTERMEDIATE MIDDLE CLASSROOM (4-8)	STUDENT RESTROOM (BOTH SEXES) 0	MATERIAL STORAGE 0	ELECTRICAL ROOM 0	INTERMEDIATE MIDDLE CLASSROOM (4-8)	STUDENT RESTROOM (BOTH SEXES) 0	MATERIAL STORAGE 0	ELECTRICAL ROOM 0	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	STUDENT RESTROOM (BOTH SEXES) 0	MATERIAL STORAGE 0	ELECTRICAL ROOM 0	INTERMEDIATE MIDDLE CLASSROOM (4-8)	STUDENT RESTROOM (BOTH SEXES) 0	MATERIAL STORAGE 0	ELECTRICAL ROOM 0	CUSTODIAL SERVICE CLOSET 0	STAFF RESTROOM (BOTH SEXES) 0	ELECTRICAL ROOM 0	GENERAL SCHOOL STORAGE 0	TELEPHONE EQUIPMENT/COMMUNICATION 0	INTERMEDIATE MIDDLE CLASSROOM (4-8)	STUDENT RESTROOM (BOTH SEXES) 0
2	814	808	203	2	814	808	703	2	814	808	703	2	814	808	703	331	821	203	308	202	2	814
968	45	20	35	968	45	20	35	888	45	20	35	888	45	20	35	200	25	82	420	112	868	45
1636	1636A	1636B	1636C	1637	1637A	1637B	1637C	1638	1638A	1638B	1638C	1639	1639A	1639B	1639C	1640	1641	1642	1643	1644	1645	1645A



46 \$ 46 46 46 46 46 46 # 46 46 46 46 46 46 # 46 46 46 46 46

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

47 16 16 16 16 16 16 16 16 16 16 16 9 16 16 16 16 16 9 16 16 16 16 16 16 SATISFACTORY 2004 TILE 11 1 COMPOSITION TILE COMPOSITION TILE COMPOSITION COMPOSITION COMPOSITION COMPOSITION COMPOSITION COMPOSITION COMPOSITION CERAMIC TILE COMPOSITION CERAMIC TILE CERAMIC TILE CERAMIC TILE COMPOSITION CERAMIC TILE CERAMIC TILE COMPOSITION CONCRETE CONCRETE CONCRETE CONCRETE CONCRETE CONCRETE 8 18 8 8 22 22 22 22 8 22 0 0 0 INTERMEDIATE/MIDDLE CLASSROOM (4-8) INTERMEDIATE MIDDLE CLASSROOM (4-8) STUDENT RESTROOM (BOTH SEXES) (BOTH SEXES) (BOTH SEXES) STUDENT RESTROOM (BOTH SEXES) STUDENT RESTROOM (BOTH SEXES) (BOTH SEXES) STUDENT RESTROOM STUDENT RESTROOM STUDENT RESTROOM MATERIAL STORAGE MATERIAL STORAGE MATERIAL STORAGE MATERIAL STORAGE MATERIAL STORAGE MATERIAL STORAGE ELECTRICAL ROOM ELECTRICAL ROOM ELECTRICAL ROOM ELECTRICAL ROOM ELECTRICAL ROOM ELECTRICAL ROOM 233 8 8 814 8 233 8 914 203 88 914 8 <u>8</u> 24 88 <u>8</u> 8 8 88 88 8 88 8 88 g \$ g \$ \$ \$ \$ \$ 8 8 8 g 8 8 8 g 8 g 1651A 1645B 1645C 646A 646B 1647A 1647B 1647C 1648A 648B 1648C 1649A 649B 6490 650A 650B 1650C 646C 848 98 646 649 647 8



Page 34 of 41

FACILITY INVENTORY REPORT

1651B	20	808	MATERIAL STORAGE	0	05	COMPOSITION TILE	2004	SATISFACTORY	16	47	46
1651C	88	203	ELECTRICAL ROOM		62	CONCRETE	2004	SATISFACTORY	16	47	46
1652	888	2	INTERMEDIATEMIDDLE CLASSROOM (4-8)	77	62	COMPOSITION TILE	2004	SATISFACTORY	16	47	46
1652A	45	814	STUDENT RESTROOM (BOTH SEXES)	0	62	CERAMICTILE	2004	SATISFACTORY	16	47	46
1652B	8	808	MATERIAL STORAGE		62	COMPOSITION TILE	2004	SATISFACTORY	16	47	46
1652C	85	203	ELECTRICAL ROOM		62	CONCRETE	2004	SATISFACTORY	16	47	46
1653	868	2	INTERMEDIATEMIDDLE CLASSROOM (4-8)	22	05	COMPOSITION TILE	2004	SATISFACTORY	16	47	46
1653A	45	814	STUDENT RESTROOM (BOTH SEXES)		05	CERAMICTILE	2004	SATISFACTORY	16	47	46
1653B	8	808	MATERIAL STORAGE		62	CERAMICTILE	2004	SATISFACTORY	16	47	46
1653C	98	703	ELECTRICAL ROOM		62	CONCRETE	2004	SATISFACTORY	16	47	46
1654	221	202	TELEPHONE EQUIPMENT/COMMUNICATION CLOSET	0	00	CONCRETE	2004	SATISFACTORY	16	47	46
1655	68	702	MECHANICAL ROOM	0	02	CONCRETE	2004	SATISFACTORY	16	47	46

	Satie	Satisfactory	Unsati	Unsatisfactory	Failed St	Failed Standards	Scheduled For Replacement	r Replacement
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	21,897	720	0	0				
TOTAL	28'15	720	0	0	0	0	0	



Page 35 of 41

FACILITY INVENTORY REPORT

A

FACILITY: 46-A TEDDER ELEMENTARY

DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

BUILDING: 19 - Building Number 00019

OL BO ARD TARY ted: 1964	C00 Hea	Cooling: CENTRAL
964	Hea	
		Heat Source: ELECTRIC
		Heat Distribution: CENTRAL HOT AIR
Year Modified: Educational TV: FIXED SERVICE RECEIVER		Heat Capacity, ADEQUATE
Average Age NSF: 1964 Intercom: TWO WAY COMPLETE		Wall≲ STUCCO
Relocatable Units: 0 Telephone P ARTIAL SYSTEM		Struct Comp. COMBINATION OF 1-3
Stories: 1	Com	Corridor: NONE

ROOM	NET SQ FT	DESIGN	DESCRIPTION	STU STA	E 20	FLOOR COVER	YEAR	СОИВІДОИ	BLDG	PAR	FAC
600	28	200	INSIDE CIRCULATION	0	Б	COMPOSITION TILE	1964	SATISFACTORY	19	47	46
1901	2030	8	PRIMARY OPEN PLAN (K-3)	38	Б	COMPOSITION TILE	1964	SATISFACTORY	19	47	46
1901A	450	40	RESOURCE ROOM	0	Б	COMPOSITION TILE	1964	SATISFACTORY	19	47	46
1902	022	315	TEACHER PLANNING OFFICE	0	Б	COMPOSITION TILE	1964	SATISFACTORY	19	47	46
1902A	176	301	ASSISTANT PRINCIP AL/OTHER OFFICE	0	Б	COMPOSITION TILE	1964	SATISFACTORY	19	47	46
1902B	380	306	CONFERENCE ROOM	0	Б	COMPOSITION TILE	1964	SATISFACTORY	19	47	46
1902C	32	808	MATERIAL STORAGE	0	Б	COMPOSITION TILE	1964	SATISFACTORY	19	47	46
1902D	25	808	MATERIAL STORAGE	0	Б	COMPOSITION TILE	1964	SATISFACTORY	19	47	46
1902E	99	331	CUSTODIAL SERVICE CLOSET	0	Б	CONCRETE	1964	SATISFACTORY	19	47	46
1902F	49	703	ELECTRICAL ROOM	0	Б	CONCRETE	1964	SATISFACTORY	19	47	46
19026	72	820	STAFF RESTROOM (FEMALE)	0	Б	CERAMICTILE	1964	SATISFACTORY	19	47	46
1903	24	703	ELECTRICAL ROOM	0	04	CONCRETE	1964	SATISFACTORY	19	47	46

1904 510	<u>ال</u> ا	707	MECHANICAL ROOM		<u>></u>	5_	CONCRETE	1964	VALISTACIONY	- E	2	74	0
1904A 60	8	703	ELECTRICAL ROOM		0	Б	CONCRETE	1964	SATISFACTORY	ORY	19	47	46
1904B	117	330	CUSTODIAL RECEIMING		0	Б	CONCRETE	1964	SATISFACTORY	ORY	19	47	46
1904C 25	55	334	CUSTODIAL SERVICE CLOSET	LOSET	0	Б	CONCRETE	1964	SATISFACTORY	ORY	19	47	46
		Sat	Satisfactory	Unsatie	Unsatisfactory		Failed Standards	indards		Scheduled For Replacement	For Rep	acement	
	S.	Square Feet	Student Stations	Square Feet	Student Stations	ations	Square Feet	Student Stations	tations	Square Feet		Student Stations	ons
Permanent	Įį.	4,599	98	0		0							
TOTAL		4,599	8	0		0	0		0		0		0



ODE LOR.	
STUDENT STRITONS DI DE SION CODE LOR	ACILITY: TEDDER ELEMENTARY
SHOULD	TEDDER E
31005	FACILITY

		_		_	_	_		_	_	_	_	_	_	_	_	_	_		_	_	_	_	_	_	_
Repl Rooms	Relo	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Fail Std Rooms	Relo	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Repl Stu Sta	Relo	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Fail Std Stu Sta	Relo	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
SEO	Relo	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Unsatis Rooms	Mod	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
sin .	Реш	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2	Relo	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Satis Rooms	Mod	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Sat	Pem	34	28	2	-	е	-	-	2	-	-	4	-	-	-	2	-	е	-	-	2	2	4	2	Ξ
Unsat	Tot_	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
tg S	Tot	812	572	0	98	0	0	0	28	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Sta	Relo	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Unsat Stu Sta	Mod	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Uns	Perm	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
ta ta	Relo	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Satis Stu Sta	Mod	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Sati	Perm	612	572	0	Ж	0	0	0	8	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
	Design Code Description	PRIMARY CLASSROOM (K-3)	INTERMEDIATE MIDDLE CLASSROOM (4-8)	00010 PRIMARY SKILLS LAB (K-3)	PRIMARY OPEN PLAN (K-3)	00040 RESOURCE ROOM	00050 ART-ELEMENTARY	MUSIC - ELEMENTARY	ESEFULL-TIME	E S E RESOURCE	00300 PRINCIPAL/DIRECTOR OFFICE	ASSISTANT PRINCIP AL/OTHER OFFICE	SECRETARIAL SPACE	00:304 RECEPTION AREA	00305 PRODUCTION WORKROOM	CONFERENCE ROOM	CLINIC	00308 GENERAL SCHOOL STORAGE	00:309 VAULT/STUDENT RECORDS	00312 COMPUTER AREA	00314 ITINERANT OFFICE	TEACHER PLANNING OFFICE	00316 TEACHER LOUNGE/DINING	00330 CUSTODIAL RECEIVING	CUSTODIAL SERVICE CLOSET
	Design Code	10000	00002	000010	08000	00040	09000	9000	00062	9000	00300	10000	00303	00304	00305	90800	20000	90308	90309	00312	00314	00315	0031E	00330	90331



FACILITY INVENTORY REPORT

용 Fail Std Rooms Relo Repl Stu Sta Relo Fail Std Stu Sta Relo Unsatis Rooms Mod Ь Pem Relo Satis Rooms ₩ Реш N m ğ ğ lο Ю Re ee Unsat Stu Sta Mod Perm Relo Satis Stu Sta Mod MULTIPURPOSE ROOM CHAIR STORAGE MEDIA GROUP PROJECTS/INSTRUCTION Design Code Description LIBRARY (READING ROOM/STACKS) CUSTODIAL EQUIPMENT STORAGE STAGE DRESSING ROOM (FEMALE) MEDIA TECHNICAL PROCESSING STAGE DRESSING ROOM (MALE) MULTIPURPOSE ROOM (DINING) KITCHEN NONFOOD STORAGE CLOSED CIRCUIT STORAGE KITCHEN & SERVING AREA KITCHEN GARBAGE WASH KITCHEN CHAIR STORAGE AUDIO MSUAL STORAGE CLOSED CIRCUIT TV LAB CUSTODIAL WORK AREA KITCHEN DRY STORAGE FLAMMABLE STORAGE OTHER FOOD SERVICE TEXTBOOK STORAGE INSIDE CIRCULATION COVERED WALKWAY STAGE STORAGE KITCHEN OFFICE DINING AREA STAGE esign Code 掖



Page 39 of 41

Prepared by: **HEERY**

FACILITY INVENTORY REPORT

Design Code Design Code Design Code Perm Mod Relo Ferm Mod Relo Total Code MECHANICAL ROOM 0 <td< th=""><th></th><th>E</th><th></th><th></th><th></th><th></th><th></th><th></th><th></th><th></th><th></th><th></th><th></th><th>otu ota</th><th>Stu Sta</th><th>Rooms</th><th>Rooms</th></td<>		E												otu ota	Stu Sta	Rooms	Rooms
MECHANICAL ROOM 0	CCOMMINICATION			_	E			Tot Tot	Pem	Mod Relo	о Реш	Mod	Relo	Relo	Relo	Relo	Relo
ELECTRICAL ROOM 0	FICOMMINICATION	0	0	-	0	-		0	28	0	0	0	0	0	0	0	0
TELEPHONE EQUIPMENTACOMMUNICATION 0	DCOMMINICATION	0	0	-	0	-		0	51	0	0	0	0	0	0	0	0
KILN 0		0	0	0	0	0		0	е	0 0	0	0	0	0	0	0	0
REFERENCE 0		0	0	0	0	0		0	-	0 0	0	0	0	0	0	0	0
MATERIAL STORAGE MATERIAL STORAGE (LARGE) 0 <td></td> <td>-</td> <td>0</td> <td>-</td> <td>0</td> <td>-</td> <td></td> <td>0</td> <td>-</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td>		-	0	-	0	-		0	-	0	0	0	0	0	0	0	0
MATERIAL STORAGE (LARGE) 0 </td <td></td> <td>0</td> <td>0</td> <td>-</td> <td>0</td> <td>-</td> <td></td> <td>0</td> <td>25</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td>		0	0	-	0	-		0	25	0	0	0	0	0	0	0	0
OUTSIDE STORAGE 0	RGE)	0	0	0	0	0		0	-	0 0	0	0	0	0	0	0	0
STUDENT RESTROOM (MALE) 0		0	0	0	0	0		0	-	0 0	0	0	0	0	0	0	0
STUDENT RESTROOM (MALE) 0	OTH SEXES)	0	0	0	0	0		0	89	0	0	0	0	0	0	0	0
STUDENT RESTROOM (FEMALE) 0 <td>(ALE)</td> <td>-</td> <td>-</td> <td>-</td> <td>0</td> <td>0</td> <td></td> <td>0</td> <td>m</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td>	(ALE)	-	-	-	0	0		0	m	0	0	0	0	0	0	0	0
STAFF RESTROOM (MALE) 0	EMALE)	0	0	0	0	0		0	e	0 0	0	0	0	0	0	0	0
STAFF RESTROOM (FEMALE) 0 <td>E)</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td></td> <td>0</td> <td>4</td> <td>0 0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td>	E)	0	0	0	0	0		0	4	0 0	0	0	0	0	0	0	0
STAFF RESTROOM (BOTH SEXES) 0<	ALE)	0	0	0	0	0		0	2	0 0	0	0	0	0	0	0	0
ELEVATOR (PASSENGERMANDICAPPED) 0 0 0 0 0 0	H SEXES)	-	0	-	0	-		0	2	0	0	0	0	0	0	0	0
	(MANDICAPPED)	0	0	-	0	-			_	0	0	0	0	0	0	0	0
00831 MUSIC PRACTICE ROOM 0 0 0 0 0 0 0		0	0	0	0	0		0	-	0 0	0	0	0	0	0	0	0
Totals: 1240 0 0 0 0 1240	,	1240	0	0	0	0		0	419	0 0	0	0	0	0	0	0	0




Prepared by: **HEERY**


FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)



2.3.3 FISH Site Plan



2.3.4 FISH Building Plan



2.4.0 Facility Assessments and Budgetary Documentation

This section includes facility condition assessments and budgetary documentation that has been completed over recent years regarding the General Obligation Bond funding and approved budgetary construction scope of work.

2.3.1 Adopted District Educational Facilities Plan

The ADEFP is the most recent approved budget for each campus of Broward County Schools. Construction scope is itemized including changes to the initial deficiency listings for each campus. It is the responsibility of the Design/Build Contractor to reconcile any differences between the ADEFP and additional budgetary or facility condition assessments.

2.3.2 SMART Campus Summary

The SMART Campus Summary is the most recent facility condition assessment completed for each campus. The summary provides existing building applicable dates and square footage, in addition to deficiency listings broken down into Safety & Security, Music & Arts, Athletics, Renovations, and Technology (SMART) categories to organize the approved funding in terms of programs that are affected.

The Campus Summary does not represent the final approved funding, and is for information purposes only.

2.3.3 MAPPS Deficiency Listing

The MAPPS Deficiency Listing is a detailed facility condition assessment conducted by Jacobs over recent years. The deficiency listing is presented as an itemized list of deficiencies on a site and building specific level organized by discipline. Note that all deficiency items are not in the scope of work. Items initialed "GOB" are included in the initial General Obligation Bond, prior to final approval of ADEFP.

The MAPPS Deficiency Listing does not represent the final approved funding, and is for information purposes only.

2.3.4 MAPPS Detailed List

The MAPPS Detailed List is raw database information in tabular format. The purpose of the Detailed List is to provide additional notes and quantity to cost estimate information. It is important to note that the Detailed List does not include all items from the approved budget. Additional items may occur and should be confirmed with the ADEFP.

2.3.5 MAPPS Deficiency Detail

The MAPPS Deficiency Detail report is raw database information with a breakdown of the cost estimate including construction adjustments and soft cost adjustments. As is with the Detail List, budget confirmation with the ADEFP is required.



RFQ Number: 17-065C

P-0016xx

2.4.1 Adopted District Educational Facilities Plan (DEFP)

Tedder Elementary School

	Carryover	Year 1	Year 2	Year 3	Year 4		
Project	(2014-15)	(2015-16)	(2016-17)	(2017-18)	(2018-19)	Total	Scope

			SMART	Program			
Project	Carryover (2014-15)	Year 1 (2015-16)	Year 2 (2016-17)	Year 3 (2017-18)	Year 4 (2018-19)	Total	Scope
Safety & Security		215,000				215,000	Fire Sprinklers
Safety & Security		294,000				294,000	Fire Alarm
Athletics		14,000				14,000	PE/Athletic Improvements
Renovation			50,000			50,000	Wireless Network Upgrade
Renovation		100,000				100,000	School Choice Enhancement
Renovation		994,000				994,000	HVAC Improvements
Renovation			5,000			5,000	CAT 6 Data port Upgrade
Renovation		1,671,000				1,671,000	Building Envelope Improvements (Roof, Window, Ext Wall, etc.)
Technology			90,000			90,000	Additional computers to close computer gap
SMART Sub-Total	0	3,288,000	145,000	0	0	3,433,000	
	Carryover (2014-15)	Year 1 (2015-16)	Year 2 (2016-17)	Year 3 (2017-18)	Year 4 (2018-19)	Total	
School Total	0	3,288,000	145,000	0	0	3,433,000	

P-0016xx RFQ Number: 17-065C

2.4.2 SMART Campus Summary



0571 Tedder Elementary School

4157 NE 1st Terrace Deerfield Beach FL 33064

Tedder Elementary School PE/Athletic Improvements

Year Open 1964 1969, 1990, 2003, 2004 Other Years 119,000 Perm. Bldgs/SF 14 Port. Bldgs/SF 0 0

Current FCI Need 6,841,312 Replacement Value 20,155,030

Facility Condition Index 33.9 %

2014 Facility Condition Assessment Campus Summary



Facility Condition Index

Athletics

\$6,841,312 Current Need		\$2	0,155,030 Replac	cement Value
GOB Bond / Construction Projects	33.9 % FCI			
Safety & Security		Budget	Fund Yr.	Status

Budget

\$14,000

Fund Yr.

2016

Status

2014 GOB

Tedder ES Single Point of Entry*	\$208,000	2016	2014 GOB
Tedder Elementary School Fire Alarm	\$294,000	2016	2014 GOB
Tedder Elementary School Fire Sprinklers	\$323,000	2016	2014 GOB
	\$825,000		

Music & Arts	Budget	Fund Yr.	Status
None Identified			

	\$14,000		
Renovations	Budget	Fund Yr.	Status
Tedder Elementary School Envelope	\$148,000	2016	2014 GOB
Tedder Elementary School Roofing	\$1,085,000	2016	2014 GOB
Tedder Elementary School HVAC	\$716,000	2016	2014 GOB
Tedder ES School Choice Enhancement	\$100,000	2016	2014 GOB
Tedder Elementary School Other Envelope Improvements	\$1,028,000	2016	2014 GOB
Tedder Elementary School Other HVAC Improvements	\$891,000	2016	2014 GOB

	\$3,968,000		
Technology	Budget	Fund Yr.	Status
Tedder ES Computer Gap	\$90,000	2017	2014 GOB
Tedder ES CAT 6 Dataport	\$10,000	2017	2014 GOB
Tedder ES Wireless Network	\$50,000	2017	2014 GOB

\$150,000

Total In-Progress and Planned \$4,957,000 Total Unplanned Need \$2,212,436

*Budgets for Single Point of Entry projects are currently under review and will be updated upon completion of review.



Rev 1 Sept 2014



2014 Facility Condition Assessment Campus Summary

Unplanned Need

Safety & Security	Budget
None Identified	
	\$0
Music & Arts	Budget
Tedder Elementary School Music / Art Renovations	\$68,244
	\$68,244
Athletics	Budget
None Identified	
	\$0
Renovations	Budget
Media Center Expansion	\$34,099
Other Electrical improvements at Tedder Elementary School	\$100,536
Various maintenance projects throughout campus	
Tedder Elementary School STEM Lab Renovations	\$12,756
Misc Maintenance Improvements at Tedder ES	\$455,907
Misc Site Improvements at Tedder ES	\$208,954
Misc Interior Improvements at Tedder ES	\$728,206
Misc Plumbing Improvements at Tedder ES	\$231,340
Misc Specialties Improvements at Tedder ES	\$273,398
	\$2,045,195
Technology	Budget
Fiber Optic Network (10GB) Upgrade at Tedder ES	\$98,997
	\$98,997

Total Unplanned Need \$2,212,436



0571

2.4.3 MAPPS Deficiency Listing

Broward County Public Schools

Tedder Elementary School

School Deficiency Listing

9/2/2014 8:01 AM

Site						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
Fencing Requires Replacement (Chain Link Fence)	Capital Renewal	10 LF	3	\$438	312647	
Playground Requires Impact Resistant Material	Educational Adequacy	1 Ea.	3	\$5,722	226612	
CPlay Area Requires Replacement	Capital Renewal	3 Ea.	4	\$128,051	312649	
Playground Equipment Requires Replacement	Capital Renewal	8 Ea.	4	\$13,697	312650	GO
School lacks marquee or marquee in poor condition.	Educational Adequacy	1 Ea.	4	\$26,600	303554	
Site Marquee Is Damaged And Requires Replacement	Deferred Maintenance	1 Ea.	4	\$8,535	312645	
Site Signage Requires Replacement	Deferred Maintenance	1 Ea.	4	\$287	312646	
Paving Requires Restriping	Deferred Maintenance	104 CAR	5	\$1,651	312648	
Play Field Requires Regrading	Deferred Maintenance	30,000 SF	5	\$37,670	312651	
	Sub Total for System	9 items		\$222,650		
Roofing						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
Numinum Covered Walkways Require Replacement	Capital Renewal	2,000 SF	3	\$12,970	207485	
Aluminum Covered Walkways Require Replacement	Capital Renewal	2,600 SF	3	\$16,861	207647	
Aluminum Covered Walkways Require Replacement	Capital Renewal	2,600 SF	3	\$16,861	207649	
	Sub Total for System	3 items		\$46,693		
Exterior						
	Cotogon	Qty UoM	Priority	Repair Cost	ID	
Deficiency Single Point of Entry Needs to be Installed	Category Capital Renewal	1 LS	2	\$207,999		GO
origie Portit of Entry Needs to be installed	Sub Total for System	1 items	2	\$207,999	213173	60
Fire and Security	Sub Total for System	i itellis		\$201,999		
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
Entire Fire Alarm System Needs to be Replaced	Capital Renewal	1 LS	1	\$293,695	220887	GO
Location: Main/Portable	Capital Relieval	1 20	'	Ψ293,093	220007	00
	Sub Total for System	1 items		\$293,695		
Technology				,,		
• • • • • • • • • • • • • • • • • • • •						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
CAT-6 wiring to WAP needs to be provided	Functional Deficiency	36 Ea.	3	\$28,395	225012	GO
School requires computers to close accessibility gap	Functional Deficiency	1 LS	3	\$89,600		GO
School requires Wireless Access Point hardware	Functional Deficiency	1 LS	3	\$21,744	313553	GO
Oth a r	Sub Total for System	3 items		\$139,739		
Other						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
School Selected Educational Adequacy Enhancement	Educational Adequacy	1 LS	2	\$100,000	314205	GOI
School requires additional media center space	New Construction	136 SF	5	\$34,099	314720	
	Sub Total for System	2 items		\$134,099		
	Sub Total for School and Site Level	19 items		\$1,044,875		
Building: 01 - Building 1						
	Category	Qty UoM				
Deficiency			Priority	Repair Cost	ID	

 Deficiency
 Category
 Qty UoM
 Priority
 Repair Cost
 ID

 The Exterior Security Camera Is Damaged And Should Be Replaced
 Capital Renewal
 14 Ea.
 2
 \$56,309
 207395

 Sub Total for System
 0 items
 \$56,309
 \$56,309
 \$56,309

Rev 1 Sept 2014 Tedder Elementary School

M•A•P•P•S ©, Jacobs 2014 Page 1 of 17

0571

9/2/2014 8:01 AM

Broward County Public Schools

School Deficiency Listing

0571	Tedder Elementary School					9/2/2012	1 8:U1 AM
Building: 0	1 - Building 1						
Roofing							
Deficiency		Category	Qty UoM	Priority	Repair Cost	ID	
Reroofing with new Dec	king Required (Broward CPS)	Capital Renewal	6,290 SF	1	\$79,762	208109	GOB
		Sub Total for System	1 items		\$79,762		
Structural							
Deficiency		Category	Qty UoM	Priority	Repair Cost	ID	
The Stucco Exterior Red	quires Repair	Deferred	3,780 SF Wa	II 3	\$26,095	207470	GOB
		Maintenance			***		
		Sub Total for System	1 items		\$26,095		
Exterior							
Deficiency		Category	Qty UoM	Priority	Repair Cost	ID	
Exterior Door Hardware	Requires Replacement	Deferred Maintenance	4 Ea.	3	\$11,530	207473	GOB
The Exterior Requires P	eainting	Capital Renewal	3,780 SF Wa	II 3	\$12,904	207468	GOB
	aged In The Exterior Window:	Deferred	4 SF	3	\$319	207474	GOB
The Edward School	Na anima	Maintenance	2 700 05:::		A7 0 · -	207127	
The Exterior Requires C	Cleaning	Deferred Maintenance	3,780 SF Wa	II 5	\$7,645	207467	
		Sub Total for System	4 items		\$32,398		
Interior							
Deficiency		Category	Qty UoM	Priority	Repair Cost	ID	
The Wood Exterior Doo	r Is Damaged And Requires Replacement	Capital Renewal	4 Door	2	\$16,861	207472	GOB
Classroom doors lack a	ppropriate signs.	Educational Adequacy	6 Ea.	3	\$1,026	Rollup	
Interior Doors Require F	Replacement	Capital Renewal	4 Door	3	\$9,802	207478	
Room has insufficient w	riting area.	Educational Adequacy	4 Ea.	3	\$4,154	Rollup	
The Vinyl Composition 1	File Requires Replacement	Capital Renewal	4,860 SF	3	\$43,596	207477	
Room lacks appropriate	amount of teacher storage.	Educational Adequacy	20 Ea.	4	\$12,096	Rollup	
The Interior Door Hardw	vare Requires Replacement	Capital Renewal	4 Door	4	\$8,928	207479	
Interior Gypboard Walls	Require Repainting	Deferred Maintenance	4,860 SF Wa	II 5	\$16,382	207476	
The Plaster Ceilings Are	e Damaged And Requires Repainting	Deferred Maintenance	4,385 SF	5	\$9,428	207475	
		Sub Total for System	9 items		\$122,273		
Mechanical							
Deficiency		Category	Qty UoM	Priority	Repair Cost	ID	
The Exterior Condenser	Requires Replacement	Capital Renewal	1 Ea.	1	\$8,623	207676	GOB
Controls Are Inadequate	e And Should Be Replaced With DDC Controls	Capital Renewal	4,385 SF	3	\$18,699	207670	GOB
Duct Heater Requires R	eplacement	Capital Renewal	1 Ea.	3	\$5,223	207674	GOB
Ductwork Requires Rep	lacement	Capital Renewal	364 LF	3	\$3,637	207669	GOB
Exhaust Fan Ventilation	Requires Replacement	Capital Renewal	1 Ea.	3	\$2,108	207663	GOB
Make-Up Air Should Be	Increased	Functional Deficiency	4,385 SF	3	\$7,357	207672	GOB
Package Roof Top Unit	Requires Replacement	Capital Renewal	1 Ea.	3	\$18,026	207656	GOB
Roof Top Unit Condens	ate Drain Is Missing And Needed	Functional Deficiency	1 Ea.	3	\$478	207659	
Test And Balancing Red	quired	Deferred Maintenance	4,385 SF	3	\$6,150	207671	GOB
The Package Unit HVA	C Component Requires Replacement	Capital Renewal	1 TonAC	3	\$2,401	207666	GOB
Duct Grill is Damaged R	requires Replacement	Deferred Maintenance	4 Ea.	5	\$418	207667	
Duct Register Requires	Replacement	Deferred Maintenance	16 Ea.	5	\$4,804	207668	
		Sub Total for System	12 items		\$77,923		

Rev 1 Sept 2014 M•A•P•P•S ©, Jacobs 2014 Tedder Elementary School

0571

Page 2 of 17



School Deficiency Listing

0571 Tedder Elementary School						
Building: 01 - Building 1						
Electrical						
	0-1	Ohn Haka	Dui a vita	Dan sia Cast	ID	
Deficiency Room lacks controls to partially dim lights.	Category Educational	Qty UoM 4 Ea.	Priority 5	Repair Cost \$3,117	ID Rollup	
Room lacks controls to partially unit lights.	Adequacy	4 Ea.	5	φ5,117	Rollup	
	Sub Total for System	1 items		\$3,117		
Fire and Security						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
nstall Fire Sprinklers	Code Compliance	4,385 SF	1	\$38,246	207664	GOE
Security Alarm is Missing or Inadequate	Functional Deficiency	4,385 SF	2	\$12,474	207397	
	Sub Total for System	2 items		\$50,720		
Technology						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
Public Address Is Inadequate And Should Be Replaced	Capital Renewal	4,385 SF	2	\$5,551	207398	
Room lacks Interactive White Board	Educational	4 Ea.	2	\$10,887	Rollup	
	Adequacy	, Lu.	-	ψ10,007	толир	
	Sub Total for System	2 items		\$16,437		
Specialties						
- Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
Blinds are missing or in poor condition.	Educational	336 SF Surf	4	\$9,490	Rollup	
	Adequacy					
he Base Storage Cabinets Require Replacement	Capital Renewal	88 LF	4	\$21,584	207480	
	Sub Total for System	2 items		\$31,075		
Building: 02 - Classroom	otal for Building 01 - Building 1	34 items		\$496,109		
Building: 02 - Classroom Roofing	otal for Building 01 - Building 1 Category	34 Items Qty UoM	Priority	\$496,109 Repair Cost	ID	
Building: 02 - Classroom Roofing Deficiency	Category Capital Renewal		Priority 1	Repair Cost \$103,031	ID 208110	GOE
Building: 02 - Classroom Roofing Deficiency Reroofing with new Decking Required (Broward CPS)	Category	Qty UoM		Repair Cost		GOB
Building: 02 - Classroom Roofing Deficiency Reroofing with new Decking Required (Broward CPS)	Category Capital Renewal	Qty UoM 8,125 SF		Repair Cost \$103,031		GOB
Building: 02 - Classroom Roofing Deficiency Reroofing with new Decking Required (Broward CPS) Exterior	Category Capital Renewal	Qty UoM 8,125 SF		Repair Cost \$103,031		GOE
Building: 02 - Classroom Roofing Deficiency Reroofing with new Decking Required (Broward CPS) Exterior Deficiency	Category Capital Renewal Sub Total for System	Qty UoM 8,125 SF 1 items	1 Priority	Repair Cost \$103,031 \$103,031	208110	
Building: 02 - Classroom Roofing Deficiency Reroofing with new Decking Required (Broward CPS) Exterior Deficiency The Exterior Requires Painting	Category Capital Renewal Sub Total for System Category Capital Renewal Deferred	Qty UoM 8,125 SF 1 items Qty UoM	1 Priority 3	Repair Cost \$103,031 \$103,031 Repair Cost \$11,948	208110 ID	
Building: 02 - Classroom Roofing Deficiency Reroofing with new Decking Required (Broward CPS) Exterior Deficiency The Exterior Requires Painting	Category Capital Renewal Sub Total for System Category Capital Renewal Deferred Maintenance	Qty UoM 8,125 SF 1 items Qty UoM 3,500 SF Wall	1 Priority 3	Repair Cost \$103,031 \$103,031 Repair Cost \$11,948 \$7,078	208110 ID 207491	
Building: 02 - Classroom Roofing Deficiency Reroofing with new Decking Required (Broward CPS) Exterior Deficiency The Exterior Requires Painting The Exterior Requires Cleaning	Category Capital Renewal Sub Total for System Category Capital Renewal Deferred	Qty UoM 8,125 SF 1 items Qty UoM 3,500 SF Wall 3,500 SF Wall	1 Priority 3	Repair Cost \$103,031 \$103,031 Repair Cost \$11,948	208110 ID 207491	
Building: 02 - Classroom Roofing Deficiency Reroofing with new Decking Required (Broward CPS) Exterior Deficiency The Exterior Requires Painting The Exterior Requires Cleaning	Category Capital Renewal Sub Total for System Category Capital Renewal Deferred Maintenance Sub Total for System	Qty UoM 8,125 SF 1 items Qty UoM 3,500 SF Wall 3,500 SF Wall 2 items	1 Priority 3 5	Repair Cost \$103,031 \$103,031 Repair Cost \$11,948 \$7,078 \$19,027	ID 207491 207489	
Building: 02 - Classroom Roofing Deficiency Reroofing with new Decking Required (Broward CPS) Exterior Deficiency The Exterior Requires Painting The Exterior Requires Cleaning Interior Deficiency Deficiency	Category Capital Renewal Sub Total for System Category Capital Renewal Deferred Maintenance Sub Total for System Category	Qty UoM 8,125 SF 1 items Qty UoM 3,500 SF Wall 3,500 SF Wall 2 items	Priority 3 5	Repair Cost \$103,031 \$103,031 Repair Cost \$11,948 \$7,078 \$19,027 Repair Cost	208110 ID 207491 207489	
Building: 02 - Classroom Roofing Deficiency Reroofing with new Decking Required (Broward CPS) Exterior Deficiency The Exterior Requires Painting The Exterior Requires Cleaning Interior Deficiency Deficiency	Category Capital Renewal Sub Total for System Category Capital Renewal Deferred Maintenance Sub Total for System	Qty UoM 8,125 SF 1 items Qty UoM 3,500 SF Wall 3,500 SF Wall 2 items	1 Priority 3 5	Repair Cost \$103,031 \$103,031 Repair Cost \$11,948 \$7,078 \$19,027	ID 207491 207489	
Building: 02 - Classroom Roofing Deficiency Reroofing with new Decking Required (Broward CPS) Exterior Deficiency The Exterior Requires Painting The Exterior Requires Cleaning Interior Deficiency Classroom doors lack appropriate signs.	Category Capital Renewal Sub Total for System Category Capital Renewal Deferred Maintenance Sub Total for System Category Educational Adequacy Educational	Qty UoM 8,125 SF 1 items Qty UoM 3,500 SF Wall 3,500 SF Wall 2 items	Priority 3 5	Repair Cost \$103,031 \$103,031 Repair Cost \$11,948 \$7,078 \$19,027 Repair Cost	208110 ID 207491 207489	
Building: 02 - Classroom Roofing Deficiency Reroofing with new Decking Required (Broward CPS) Exterior Deficiency The Exterior Requires Painting The Exterior Requires Cleaning Interior Deficiency Classroom doors lack appropriate signs. Room has insufficient writing area.	Category Capital Renewal Sub Total for System Category Capital Renewal Deferred Maintenance Sub Total for System Category Educational Adequacy Educational Adequacy	Qty UoM 8,125 SF 1 items Qty UoM 3,500 SF Wall 3,500 SF Wall 2 items Qty UoM 4 Ea. 4 Ea.	Priority 3 5 Priority 3 3 3	Repair Cost \$103,031 \$103,031 Repair Cost \$11,948 \$7,078 \$19,027 Repair Cost \$684 \$4,154	208110 ID 207491 207489 ID Rollup	
Building: 02 - Classroom Roofing Deficiency Reroofing with new Decking Required (Broward CPS) Exterior Deficiency The Exterior Requires Painting The Exterior Requires Cleaning Interior Deficiency Classroom doors lack appropriate signs.	Category Capital Renewal Sub Total for System Category Capital Renewal Deferred Maintenance Sub Total for System Category Educational Adequacy Educational	Qty UoM 8,125 SF 1 items Qty UoM 3,500 SF Wall 3,500 SF Wall 2 items Qty UoM 4 Ea.	Priority 3 5 Priority 3	Repair Cost \$103,031 \$103,031 Repair Cost \$11,948 \$7,078 \$19,027 Repair Cost \$684	208110 ID 207491 207489 ID Rollup	
Building: 02 - Classroom Roofing Deficiency Reroofing with new Decking Required (Broward CPS) Exterior Deficiency The Exterior Requires Painting The Exterior Requires Cleaning Interior Deficiency Classroom doors lack appropriate signs. Room has insufficient writing area.	Category Capital Renewal Sub Total for System Category Capital Renewal Deferred Maintenance Sub Total for System Category Educational Adequacy Educational Adequacy Educational	Qty UoM 8,125 SF 1 items Qty UoM 3,500 SF Wall 3,500 SF Wall 2 items Qty UoM 4 Ea. 4 Ea.	Priority 3 5 Priority 3 3 3	Repair Cost \$103,031 \$103,031 Repair Cost \$11,948 \$7,078 \$19,027 Repair Cost \$684 \$4,154	208110 ID 207491 207489 ID Rollup	
Building: 02 - Classroom Roofing Deficiency Reroofing with new Decking Required (Broward CPS) Exterior Deficiency The Exterior Requires Painting The Exterior Requires Cleaning Interior Deficiency Classroom doors lack appropriate signs. Room has insufficient writing area. Room lacks appropriate amount of teacher storage.	Category Capital Renewal Sub Total for System Category Capital Renewal Deferred Maintenance Sub Total for System Category Educational Adequacy Educational Adequacy Educational Adequacy Educational Adequacy	Qty UoM 8,125 SF 1 items Qty UoM 3,500 SF Wall 3,500 SF Wall 2 items Qty UoM 4 Ea. 4 Ea. 20 Ea.	Priority 3 5 Priority 3 3 3	Repair Cost \$103,031 \$103,031 Repair Cost \$11,948 \$7,078 \$19,027 Repair Cost \$684 \$4,154 \$12,096	208110 ID 207491 207489 ID Rollup	GOB
Building: 02 - Classroom Roofing Deficiency Reroofing with new Decking Required (Broward CPS) Exterior Deficiency The Exterior Requires Painting The Exterior Requires Cleaning Interior Deficiency Classroom doors lack appropriate signs. Room has insufficient writing area. Room lacks appropriate amount of teacher storage.	Category Capital Renewal Sub Total for System Category Capital Renewal Deferred Maintenance Sub Total for System Category Educational Adequacy Educational Adequacy Educational Adequacy Educational Adequacy	Qty UoM 8,125 SF 1 items Qty UoM 3,500 SF Wall 3,500 SF Wall 2 items Qty UoM 4 Ea. 4 Ea. 20 Ea.	Priority 3 5 Priority 3 3 3	Repair Cost \$103,031 \$103,031 Repair Cost \$11,948 \$7,078 \$19,027 Repair Cost \$684 \$4,154 \$12,096	208110 ID 207491 207489 ID Rollup	
Building: 02 - Classroom Roofing Deficiency Reroofing with new Decking Required (Broward CPS) Exterior Deficiency The Exterior Requires Painting The Exterior Requires Cleaning Interior Deficiency Classroom doors lack appropriate signs. Room has insufficient writing area. Room lacks appropriate amount of teacher storage. Wechanical Deficiency	Category Capital Renewal Sub Total for System Category Capital Renewal Deferred Maintenance Sub Total for System Category Educational Adequacy Educational Adequacy Educational Adequacy Sub Total for System	Qty UoM 8,125 SF 1 items Qty UoM 3,500 SF Wall 3,500 SF Wall 2 items Qty UoM 4 Ea. 4 Ea. 20 Ea. 3 items	Priority 3 5 Priority 3 4	Repair Cost \$103,031 \$103,031 Repair Cost \$11,948 \$7,078 \$19,027 Repair Cost \$684 \$4,154 \$12,096 \$16,935	ID 207489 ID Rollup Rollup Rollup	GOB
Building: 02 - Classroom Roofing Deficiency Reroofing with new Decking Required (Broward CPS) Exterior Deficiency The Exterior Requires Painting The Exterior Requires Cleaning Interior Deficiency Classroom doors lack appropriate signs. Room has insufficient writing area. Room lacks appropriate amount of teacher storage. Mechanical Deficiency The Exterior Air Handler Is Damaged And Requires Replacement	Category Capital Renewal Sub Total for System Category Capital Renewal Deferred Maintenance Sub Total for System Category Educational Adequacy Educational Adequacy Educational Adequacy Sub Total for System	Qty UoM 8,125 SF 1 items Qty UoM 3,500 SF Wall 3,500 SF Wall 2 items Qty UoM 4 Ea. 4 Ea. 20 Ea. 3 items	Priority 3 5 Priority 3 4	Repair Cost \$103,031 \$103,031 Repair Cost \$11,948 \$7,078 \$19,027 Repair Cost \$684 \$4,154 \$12,096 \$16,935 Repair Cost	ID 207489 ID Rollup Rollup Rollup ID 207680	GOB
Building: 02 - Classroom Roofing Deficiency Reroofing with new Decking Required (Broward CPS) Exterior Deficiency The Exterior Requires Painting The Exterior Requires Cleaning Interior Deficiency Deficiency Classroom doors lack appropriate signs. Room has insufficient writing area. Room lacks appropriate amount of teacher storage. Mechanical Deficiency The Exterior Air Handler Is Damaged And Requires Replacement Controls Are Inadequate And Should Be Replaced With DDC Controls	Category Capital Renewal Sub Total for System Category Capital Renewal Deferred Maintenance Sub Total for System Category Educational Adequacy Educational Adequacy Educational Adequacy Sub Total for System	Qty UoM 8,125 SF 1 items Qty UoM 3,500 SF Wall 3,500 SF Wall 2 items Qty UoM 4 Ea. 4 Ea. 20 Ea. 3 items Qty UoM 1 Ea.	Priority 3 3 4 Priority 2	Repair Cost \$103,031 \$103,031 Repair Cost \$11,948 \$7,078 \$19,027 Repair Cost \$684 \$4,154 \$12,096 \$16,935 Repair Cost	ID 207489 ID Rollup Rollup Rollup ID 207680 207686	GOB
Building: 02 - Classroom Roofing Deficiency Reroofing with new Decking Required (Broward CPS) Exterior Deficiency The Exterior Requires Painting The Exterior Requires Cleaning Interior Deficiency Classroom doors lack appropriate signs. Room has insufficient writing area. Room lacks appropriate amount of teacher storage. Mechanical Deficiency The Exterior Air Handler Is Damaged And Requires Replacement Controls Are Inadequate And Should Be Replaced With DDC Controls Duct Heater Requires Replacement	Category Capital Renewal Sub Total for System Category Capital Renewal Deferred Maintenance Sub Total for System Category Educational Adequacy Educational Adequacy Sub Total for System Category Capital Renewal Category Capital Renewal Capital Renewal	Qty UoM 8,125 SF 1 items Qty UoM 3,500 SF Wall 3,500 SF Wall 2 items Qty UoM 4 Ea. 4 Ea. 20 Ea. 3 items Qty UoM 1 Ea. 3,835 SF	Priority 3 3 4 Priority 2 3	Repair Cost \$103,031 \$103,031 Repair Cost \$11,948 \$7,078 \$19,027 Repair Cost \$684 \$4,154 \$12,096 \$16,935 Repair Cost \$132,614 \$16,354	ID 207489 ID Rollup Rollup Rollup D 207680 207686 207690	GOE
Building: 02 - Classroom Roofing Deficiency Reroofing with new Decking Required (Broward CPS) Exterior Deficiency The Exterior Requires Painting The Exterior Requires Cleaning Interior Deficiency Classroom doors lack appropriate signs. Room has insufficient writing area. Room lacks appropriate amount of teacher storage. Mechanical Deficiency The Exterior Air Handler Is Damaged And Requires Replacement Controls Are Inadequate And Should Be Replaced With DDC Controls Duct Heater Requires Replacement Exhaust Fan Ventilation Requires Replacement	Category Capital Renewal Sub Total for System Category Capital Renewal Deferred Maintenance Sub Total for System Category Educational Adequacy Educational Adequacy Sub Total for System Category Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal	Qty UoM 8,125 SF 1 items Qty UoM 3,500 SF Wall 3,500 SF Wall 2 items Qty UoM 4 Ea. 4 Ea. 20 Ea. 3 items Qty UoM 1 Ea. 3,835 SF 4 Ea.	Priority 3 4 Priority 2 3 3	Repair Cost \$103,031 \$103,031 Repair Cost \$11,948 \$7,078 \$19,027 Repair Cost \$684 \$4,154 \$12,096 \$16,935 Repair Cost \$132,614 \$16,354 \$20,891	ID 207489 ID Rollup Rollup Rollup D 207680 207686 207690	GOB
Building: 02 - Classroom Roofing Deficiency Reroofing with new Decking Required (Broward CPS) Exterior Deficiency The Exterior Requires Painting The Exterior Requires Cleaning Interior Deficiency Classroom doors lack appropriate signs. Room has insufficient writing area. Room lacks appropriate amount of teacher storage. Mechanical Deficiency The Exterior Air Handler Is Damaged And Requires Replacement Controls Are Inadequate And Should Be Replaced With DDC Controls Duct Heater Requires Replacement Exhaust Fan Ventilation Requires Replacement Exhaust Fan Ventilation Requires Replacement Fest And Balancing Required	Category Capital Renewal Sub Total for System Category Capital Renewal Deferred Maintenance Sub Total for System Category Educational Adequacy Educational Adequacy Sub Total for System Category Capital Renewal	Qty UoM 8,125 SF 1 items Qty UoM 3,500 SF Wall 3,500 SF Wall 2 items Qty UoM 4 Ea. 4 Ea. 20 Ea. 3 items Qty UoM 1 Ea. 3,835 SF 4 Ea. 1 Ea. 3,835 SF	Priority 3 5 Priority 3 4 Priority 2 3 3 3 3 3 3	Repair Cost \$103,031 \$103,031 \$103,031 Repair Cost \$11,948 \$7,078 \$19,027 Repair Cost \$684 \$4,154 \$12,096 \$16,935 Repair Cost \$132,614 \$16,354 \$20,891 \$2,108 \$5,378	ID 207489 ID Rollup Rollup Rollup 207680 207680 207682 207685	GOB GOB GOB GOB GOB GOB
Building: 02 - Classroom Roofing Deficiency Reroofing with new Decking Required (Broward CPS) Exterior Deficiency The Exterior Requires Painting The Exterior Requires Cleaning Interior Deficiency Classroom doors lack appropriate signs. Room has insufficient writing area. Room lacks appropriate amount of teacher storage. Mechanical Deficiency The Exterior Air Handler Is Damaged And Requires Replacement Controls Are Inadequate And Should Be Replaced With DDC Controls Duct Heater Requires Replacement Exhaust Fan Ventilation Requires Replacement	Category Capital Renewal Sub Total for System Category Capital Renewal Deferred Maintenance Sub Total for System Category Educational Adequacy Educational Adequacy Sub Total for System Category Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal	Qty UoM 8,125 SF 1 items Qty UoM 3,500 SF Wall 3,500 SF Wall 2 items Qty UoM 4 Ea. 4 Ea. 20 Ea. 3 items Qty UoM 1 Ea. 3,835 SF 4 Ea. 1 Ea.	Priority 3 5 Priority 3 4 Priority 2 3 3 3 3	Repair Cost \$103,031 \$103,031 \$103,031 Repair Cost \$11,948 \$7,078 \$19,027 Repair Cost \$684 \$4,154 \$12,096 \$16,935 Repair Cost \$132,614 \$16,354 \$20,891 \$2,108 \$5,378	ID 207489 ID Rollup Rollup Rollup 207680 207682	

Rev 1 Sept 2014

Tedder Elementary School

0571

M-A-P-P-S ©, Jacobs 2014

Page 3 of 17

School Deficiency Listing

0571 Tedder Elementary School			\neg		9/2/2014	1 8:01 A
,						
Building: 02 - Classroom						
Electrical						
eficiency	Category	Qty UoM	Priority	Repair Cost	ID	
ne Panelboard Requires Replacement	Capital Renewal	1 Ea.	2	\$8,070	207402	
he Incandescent Lighting Is Damaged And Should Be Replaced	Capital Renewal	4 Ea.	3	\$1,585	207404	
toom lacks controls to partially dim lights.	Educational Adequacy	4 Ea.	5	\$3,117	Rollup	
	Sub Total for System	3 items		\$12,772		
Plumbing						
eficiency	Category	Qty UoM	Priority	Repair Cost	ID	
he Class Room Lavatories Plumbing Fixtures Require Replacement	Capital Renewal	4 Ea.	2	\$8,432	207691	
he Plumbing / Domestic Water Piping System Is Beyond Its Useful Life	Capital Renewal	3,835 SF	2	\$23,196	207692	
	Sub Total for System	2 items		\$31,628		
Fire and Security						
eficiency	Category	Qty UoM	Priority	Repair Cost	ID	
ecurity Alarm is Missing or Inadequate	Functional Deficiency	3,835 SF	2	\$10,909	207406	
	Sub Total for System	1 items		\$10,909		
Гесhnology						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
ublic Address Is Inadequate And Should Be Replaced	Capital Renewal	3,835 SF	2	\$4,854	207405	
Room lacks Interactive White Board	Educational Adequacy	4 Ea.	2	\$10,887	Rollup	
	Sub Total for System	2 items		\$15,741		
Specialties						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
linds are missing or in poor condition.	Educational Adequacy	336 SF Surf	4	\$9,490	Rollup	
	Sub Total for System	1 items		\$9,490		
Subl	Total for Building 02 - Classroom	21 items		\$404,883		
Building: 03 - Classroom						
Roofing						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
Reroofing with new Decking Required (Broward CPS)	Capital Renewal	4.700 SF	1	\$59,599	208111	GOE
reforming with hew beening required (bloward of 6)	Sub Total for System	1 items	,	\$59,599	200111	001
nterior	our rounts system			400,000		
	Catagoni	Otu HoM	Priority	Papair Cost	ID	
eficiency Classroom doors lack appropriate signs.	Category Educational	Qty UoM 4 Ea.	3	Repair Cost \$684	ID Rollup	
nassi com doors rack appropriate signs.	Adequacy	4 La.		φοστ	Kollup	
toom has insufficient writing area.	Educational Adequacy	4 Ea.	3	\$4,154	Rollup	
toom lacks appropriate amount of teacher storage.	Educational Adequacy	4 Ea.	4	\$2,419	Rollup	
	Sub Total for System	3 items		\$7,258		
Vlechanical Programme Transfer of the Control of th						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
ontrols Are Inadequate And Should Be Replaced With DDC Controls	Capital Renewal	4,104 SF	3	\$17,501	207716	GO
uct Heater Requires Replacement	Capital Renewal	4 Ea.	3	\$20,891	207725	GO
ouctwork Requires Replacement	Capital Renewal	361 LF	3	\$3,607	207718	GO
xhaust Fan Ventilation Requires Replacement	Capital Renewal	1 Ea.	3		207712	GO
ackage Roof Top Unit Requires Replacement	Capital Renewal	1 Ea.	3	\$18,026		GO
oof Top Unit Condensate Drain Is Missing And Needed	Functional Deficiency	1 Ea.	3		207710	
est And Balancing Required	Deferred	4,104 SF	3		207715	GO

 Rev 1 Sept 2014
 Tedder Elementary School
 0571

 M•A•P•P•S ©, Jacobs 2014
 Page 4 of 17

School Deficiency Listing

0571 Tedder Elementary School					9/2/2012	4 8:01 A
Building: 03 - Classroom						
-						
Mechanical						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
The Air Handler HVAC Component Requires Replacement	Capital Renewal	1 Ea.	3	\$56,145	207720	GOE
	Sub Total for System	8 items		\$124,511		
Electrical						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
The Panelboard Requires Replacement	Capital Renewal	1 Ea.	2	\$8,070	207407	
Room lacks controls to partially dim lights.	Educational Adequacy	4 Ea.	5	\$3,117	Rollup	
	Sub Total for System	2 items		\$11,187		
Plumbing				,,		
_	Cetegory	Otu Hahi	Delovitu	Donois Cost	ID	
Deficiency The Class Room Lavatories Plumbing Fixtures Require Replacement	Category Capital Renewal	Qty UoM 4 Ea.	Priority 2	Repair Cost	207721	
The Class Room Lavalones Plumbing Fixtures Require Replacement The Toilets Plumbing Fixtures Require Replacement	Capital Renewal	4 Ea.	2		207723	
The Rest Room Lavatories Plumbing Fixtures Require Replacement	Capital Renewal	4 Ea.	3	\$9,960		
	Sub Total for System	3 items	~	\$27,512	201122	
Fire and Security				,-· -		
-	Cotogon	Oto Haki	Drioritu	Panais Cart	ID	
Deficiency Install Fire Sprinklers	Category Code Compliance	Qty UoM 4,104 SF	Priority 1	Repair Cost \$35,795	ID 207724	GOB
Security Alarm is Missing or Inadequate	Functional Deficiency	4,104 SF	2	\$11,675		GOL
Security Alaim is Missing or madequate	Sub Total for System	2 items	2	\$47,470	207410	
Tochnology				*,		
Technology	0.1					
Deficiency Public Address Is Inadequate And Should Be Replaced	Category Capital Renewal	Qty UoM 4,104 SF	Priority 2	Repair Cost \$5,195	ID 207409	
Room lacks Fixed Projector	Educational	4,104 Si 4 Ea.	2	\$14,737	Rollup	
recommendation in recommendation	Adequacy	4 Lu.	2	ψ14,757	Rollap	
Room lacks Interactive White Board	Educational Adequacy	4 Ea.	2	\$10,887	Rollup	
The Computer Closet Requires Fiber Optic Access to CER	Functional Deficiency	400 LF	2	\$9,000	Rollup	
	Sub Total for System	4 items		\$39,818		
Specialties						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
Blinds are missing or in poor condition.	Educational	336 SF Surf		\$9,490	Rollup	
	Adequacy					
Room does not have sufficient cubbies.	Educational Adequacy	104 Ea.	5	\$4,334	Rollup	
Room has an insufficient number of coat hooks.	Educational	96 Ea.	5	\$1,113	Rollup	
	Adequacy Sub Total for System	3 items		\$14,937		
	Sub Total for Building 03 - Classroom	26 items		\$332,293		
Building 04 Classroom	Cap Fotal for Ballaning 60 - Glassiconii	20 101113		¥002,230		
Building: 04 - Classroom						
Roofing						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
Reroofing with new Decking Required (Broward CPS)	Capital Renewal	4,578 SF	1	\$58,052	208112	GOB
	Sub Total for System	1 items		\$58,052		
Interior						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
Classroom doors lack appropriate signs.	Educational Adequacy	4 Ea.	3	\$684	Rollup	
Room has insufficient writing area.	Educational	6 Ea.	3	\$6,231	Rollup	
Toom has albamorate witting area.	Adequacy	5 La.	9	Ψ0,231	Konup	

Rev 1 Sept 2014 M•A•P•P•S ©, Jacobs 2014 Tedder Elementary School

0571

Page 5 of 17



School Deficiency Listing

0571 Tedder Elementary Sc	chool				9/2/201	4 8:01 AM
Building: 04 - Classroom						
_						
Interior Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
Room lacks appropriate amount of teacher storage.	Educational	3 Ea.	4	\$1,814		
	Adequacy Sub Total for System	3 items		\$8,730		
Electrical	oub rotal for dystolii	o items		40,100		
Deficiency	Category	Qtv UoM	Priority	Repair Cost	ID	
Room has insufficient electrical outlets.	Educational	70 Ea.	3	\$25,605	Rollup	
Room lacks controls to partially dim lights.	Adequacy Educational	4 Ea.	5	\$3,117	Rollup	
recommends controls to partially aim rights.	Adequacy	4 Lu.	J	ΨΟ,ΤΤΥ	Rollup	
	Sub Total for System	2 items		\$28,722		
Technology						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID.	005
Room has insufficient dataports.	Educational Adequacy	28 Ea.	2	\$4,844	Rollup	GOB
Room lacks Fixed Projector	Educational Adequacy	4 Ea.	2	\$14,737	Rollup	
Room lacks Interactive White Board	Educational Adequacy	4 Ea.	2	\$10,887	Rollup	
The Computer Closet Requires Fiber Optic Access to CER	Functional Deficiency	400 LF	2	\$9,000	Rollup	
	Sub Total for System	4 items		\$39,467		
Specialties						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
Blinds are missing or in poor condition.	Educational Adequacy	336 SF Surf	4	\$9,490	Rollup	
Room does not have sufficient cubbies.	Educational Adequacy	78 Ea.	5	\$3,250	Rollup	
Room has an insufficient number of coat hooks.	Educational Adequacy	72 Ea.	5	\$835	Rollup	
	Sub Total for System	3 items		\$13,576		
Other						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
STEM lab requires renovation based on condition of room(s)	Capital Renewal	1 LS	2	\$12,756	316984	
	Sub Total for System	1 items		\$12,756		
	Sub Total for Building 04 - Classroom	14 items		\$161,304		
Building: 05 - Building 5						
Roofing						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
Reroofing with new Decking Required (Broward CPS)	Capital Renewal	6,347 SF	1	\$80,485	208113	GOB
	Sub Total for System	1 items		\$80,485		
Interior						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
Classroom doors lack appropriate signs.	Educational Adequacy	6 Ea.	3	\$1,026	Rollup	
Room has insufficient writing area.	Educational Adequacy	4 Ea.	3	\$4,154	Rollup	
Room lacks appropriate amount of teacher storage.	Educational Adequacy	4 Ea.	4	\$2,419	Rollup	
	Sub Total for System	3 items		\$7,600		

Rev 1 Sept 2014 M•A•P•P•S ©, Jacobs 2014 Tedder Elementary School

0571

Page 6 of 17

School Deficiency Listing

0571 Tedder Elementary School			7		9/2/2014	1 8:01 A
Building: 05 - Building 5						
Electrical						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
Room lacks controls to partially dim lights.	Educational Adequacy	4 Ea.	5	\$3,117	Rollup	
	Sub Total for System	1 items		\$3,117		
Гесhnology						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
toom lacks Fixed Projector	Educational	4 Ea.	2	\$14,737	Rollup	
Room lacks Interactive White Board	Adequacy Educational	4 Ea.	2	\$10,887	Rollup	
Contracks litteractive write board	Adequacy	4 La.	2	φ10,007	Rollup	
he Computer Closet Requires Fiber Optic Access to CER	Functional Deficiency	400 LF	2	\$9,000	Rollup	
	Sub Total for System	3 items		\$34,623		
Specialties						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
Blinds are missing or in poor condition.	Educational Adequacy	336 SF Surf	4	\$9,490	Rollup	
Room does not have sufficient cubbies.	Educational	104 Ea.	5	\$4,334	Rollup	
Described and investment of each banks	Adequacy	00 5-	-	\$4.440	Dalling	
Room has an insufficient number of coat hooks.	Educational Adequacy	96 Ea.	5	\$1,113	Kollup	
	Sub Total for System	3 items		\$14,937		
Su	b Total for Building 05 - Building 5	11 items		\$140,763		
Building: 06 - Classroom						
Roofing						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
Reroofing with new Decking Required (Broward CPS)	Capital Renewal	6,464 SF	1	\$81,968	208114	GOE
	Sub Total for System	1 items		\$81,968		
nterior						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
Classroom doors lack appropriate signs.	Educational	4 Ea.	3	\$684	Rollup	
Ocean has insufficient witing area	Adequacy	4 Ea.	3	Φ4.4E4	Dallus	
Room has insufficient writing area.	Educational Adequacy	4 Ea.	3	\$4,154	Rollup	
Room lacks appropriate amount of teacher storage.	Educational	4 Ea.	4	\$2,419	Rollup	
	Adequacy Sub Total for System	3 items		\$7,258		
Viechanical	our rotal for dystem	0 1101110		ψ, ,200		
Deficiency	Category	Qtv UoM	Priority	Repair Cost	ID	
he Exterior Air Handler Is Damaged And Requires Replacement	Capital Renewal	1 Ea.	2	\$132,614	207738	GOE
Controls Are Inadequate And Should Be Replaced With DDC Controls	Capital Renewal	3,898 SF	3	\$16,623	207743	GOE
ouct Heater Requires Replacement	Capital Renewal	4 Ea.	3	\$20,891		GOE
		0.000 05	3	\$5,467	207742	GOE
est And Balancing Required	Deferred	3,898 SF				
	Maintenance		2	PEC 11E	207757	001
	Maintenance Capital Renewal	1 Ea.	3	\$56,145 \$231,739	207757	GOE
he Air Handler HVAC Component Requires Replacement	Maintenance		3	\$56,145 \$231,739	207757	GOE
he Air Handler HVAC Component Requires Replacement	Maintenance Capital Renewal Sub Total for System	1 Ea. 5 items		\$231,739		GOE
he Air Handler HVAC Component Requires Replacement Electrical eficiency	Maintenance Capital Renewal Sub Total for System Category	1 Ea. 5 items Qty UoM	Priority	\$231,739 Repair Cost	ID	GOE
rest And Balancing Required The Air Handler HVAC Component Requires Replacement Electrical Deficiency Room lacks controls to partially dim lights.	Maintenance Capital Renewal Sub Total for System	1 Ea. 5 items Qty UoM 4 Ea.		\$231,739		GOE
The Air Handler HVAC Component Requires Replacement Electrical Deficiency Room lacks controls to partially dim lights.	Maintenance Capital Renewal Sub Total for System Category Educational	1 Ea. 5 items Qty UoM	Priority	\$231,739 Repair Cost	ID	GOE
The Air Handler HVAC Component Requires Replacement Electrical Deficiency Toom lacks controls to partially dim lights.	Maintenance Capital Renewal Sub Total for System Category Educational Adequacy	1 Ea. 5 items Qty UoM 4 Ea.	Priority	\$231,739 Repair Cost \$3,117	ID	GOI
the Air Handler HVAC Component Requires Replacement Electrical Deficiency From lacks controls to partially dim lights.	Maintenance Capital Renewal Sub Total for System Category Educational Adequacy	1 Ea. 5 items Qty UoM 4 Ea.	Priority	\$231,739 Repair Cost \$3,117	ID	GOE
Electrical Deficiency Room lacks controls to partially dim lights. Plumbing Deficiency The Class Room Lavatories Plumbing Fixtures Require Replacement	Maintenance Capital Renewal Sub Total for System Category Educational Adequacy Sub Total for System Category Category Category Capital Renewal	1 Ea. 5 items Qty UoM 4 Ea. 1 items Qty UoM 4 Ea.	Priority 5 Priority 2	\$231,739 Repair Cost \$3,117 \$3,117 Repair Cost \$8,432	ID Rollup ID 207759	GOE
The Air Handler HVAC Component Requires Replacement Electrical Deficiency Toom lacks controls to partially dim lights. Plumbing Deficiency	Maintenance Capital Renewal Sub Total for System Category Educational Adequacy Sub Total for System Category	1 Ea. 5 items Qty UoM 4 Ea. 1 items	Priority 5 Priority	\$231,739 Repair Cost \$3,117 \$3,117 Repair Cost \$8,432	ID Rollup ID	GOE
the Air Handler HVAC Component Requires Replacement Electrical reficiency room lacks controls to partially dim lights. Plumbing reficiency the Class Room Lavatories Plumbing Fixtures Require Replacement	Maintenance Capital Renewal Sub Total for System Category Educational Adequacy Sub Total for System Category Category Category Capital Renewal	1 Ea. 5 items Gty UoM 4 Ea. 1 items Qty UoM 4 Ea. 4 Ea. 4 Ea.	Priority 5 Priority 2 2	\$231,739 Repair Cost \$3,117 \$3,117 Repair Cost \$8,432	ID Rollup ID 207759 207763	GOI

School Deficiency Listing

				9/2/2014	
0-1	0111.11	D. C. C.	D1- O1	10	
			· ·		
Maintenance		'		201100	
Sub Total for System	4 Items		\$29,216		
Category		Priority			
Code Compliance Sub Total for System	3,898 SF 1 items	1	\$33,998 \$33,998	207766	GOB
•			. ,		
Catogoni	Otu HoM	Drioritu	Popair Cost	ID	
Adequacy		-	¥11,101	TOTAL	
Functional Deficiency	400 LF	2	\$9,000	Rollup	
Sub Total for System	2 items		\$23,737		
Category	Qty UoM	Priority	Repair Cost	ID	
Educational Adequacy	336 SF Surf	4	\$9,490	Rollup	
Educational Adequacy	104 Ea.	5	\$4,334	Rollup	
Educational Adequacy	96 Ea.	5	\$1,113	Rollup	
Sub Total for System	3 items		\$14,937		
otal for Building 06 - Classroom	20 items		\$425,971		
Category	Qty UoM	Priority	Repair Cost	ID	
Capital Renewal	3,652 SF	1	\$46,310	208115	GOB
Sub Total for System	1 items		\$46,310		
Category	Qty UoM	Priority	Repair Cost	ID	
Educational	1 Ea.	3	\$171	Rollup	
Educational	1 Ea.	3	\$1,039	Rollup	
Educational	9 Ea.	4	\$5,443	Rollup	
Adequacy					
Sub Total for System	3 itame		\$6.653		
Sub Total for System	3 items		\$6,653		
·					
Category	Qty UoM	Priority	Repair Cost	ID	
Category Educational Adequacy	Qty UoM 1 Ea.	Priority 5	Repair Cost \$779	ID Rollup	
Category Educational	Qty UoM		Repair Cost		
Category Educational Adequacy	Qty UoM 1 Ea.		Repair Cost \$779		
Category Educational Adequacy Sub Total for System Category	Qty UoM 1 Ea. 1 items Qty UoM	5 Priority	Repair Cost \$779 \$779 Repair Cost	Rollup ID	
Category Educational Adequacy Sub Total for System Category Educational	Qty UoM 1 Ea. 1 items	5	Repair Cost \$779 \$779	Rollup ID	
Category Educational Adequacy Sub Total for System Category	Qty UoM 1 Ea. 1 items Qty UoM	5 Priority	Repair Cost \$779 \$779 Repair Cost	Rollup ID	
Category Educational Adequacy Sub Total for System Category Educational Adequacy	Qty UoM 1 Ea. 1 items Qty UoM 1 Ea.	5 Priority	Repair Cost \$779 \$779 Repair Cost \$4,450	Rollup ID	
Category Educational Adequacy Sub Total for System Category Educational Adequacy Sub Total for System	Qty UoM 1 Ea. 1 items Qty UoM 1 Ea.	5 Priority	Repair Cost \$779 \$779 Repair Cost \$4,450	Rollup ID	
Category Educational Adequacy Sub Total for System Category Educational Adequacy	Qty UoM 1 Ea. 1 items Qty UoM 1 Ea. 1 items	5 Priority 3	Repair Cost \$779 \$779 Repair Cost \$4,450	Rollup ID Rollup ID	
Category Educational Adequacy Sub Total for System Category Educational Adequacy Sub Total for System Category	Qty UoM 1 Ea. 1 items Qty UoM 1 Ea. 1 items	5 Priority 3	Repair Cost \$779 \$779 Repair Cost \$4,450 Repair Cost	Rollup ID Rollup	
Category Educational Adequacy Sub Total for System Category Educational Adequacy Sub Total for System Category Functional Deficiency	Qty UoM 1 Ea. 1 items Qty UoM 1 Ea. 1 items Qty UoM 2,904 SF 1 items	Priority 3 Priority 2	Repair Cost \$779 \$779 Repair Cost \$4,450 Repair Cost \$8,261	ID Rollup ID 207423	057
	Category Code Compliance Sub Total for System Category Educational Adequacy Functional Deficiency Sub Total for System Category Educational Adequacy Educational Adequacy Educational Adequacy Sub Total for System category Category Category Sub Total for System category Sub Total for System category Category Category Category Category Category Category Category Category Category Educational Adequacy Educational Adequacy Educational Adequacy Educational Adequacy Educational Adequacy	Capital Renewal 4 Ea. Deferred 1 Ea. Deferred 3 Ea. Deferred 4 Items Category City UoM Code Compliance 3,898 SF Sub Total for System 1 Items Category City UoM Educational 4 Ea. Adequacy Functional Deficiency 400 LF Sub Total for System 2 Items Category City UoM Educational 336 SF Surf Adequacy Educational Adequacy Educational Adequacy Educational Adequacy Sub Total for System 3 Items Defended Category City UoM Capital Renewal 3,652 SF Sub Total for System 1 Items Category City UoM Capital Renewal 3,652 SF Sub Total for System 1 Items Category City UoM Capital Renewal 3,652 SF Sub Total for System 1 Items Category City UoM Capital Renewal 3,652 SF Sub Total for System 1 Items Category City UoM Capital Renewal 3,652 SF Sub Total for System 1 Items Category City UoM Capital Renewal 3,652 SF Sub Total for System 1 Items Category City UoM Capital Renewal 3,652 SF Sub Total for System 1 Items Category City UoM Capital Renewal 3,652 SF Sub Total for System 1 Items Category City UoM Capital Renewal 3,652 SF Sub Total for System 1 Items Category City UoM Capital Renewal 3,652 SF Sub Total for System 1 Items Category City UoM Capital Renewal 3,652 SF Sub Total for System 1 Items Category City UoM Capital Renewal 3,652 SF Category City UoM Capital Renewal 3,652 SF Category City UoM Capital Renewal 3,652 SF Category City UoM Category City Capital Renewal 4 Ea. 3 Deferred Maintenance Sub Total for System 4 Items	Capital Renewal 4 Ea. 3 \$9,960	Category	

Page 8 of 17

M-A-P-P-S ©, Jacobs 2014

School Deficiency Listing

0571 Tedder Elementary School	 ol		\neg		9/2/2014	4 8:01 AN
<u> </u>	'					
Building: 07 - Building 7						
Technology	Category	Obs. IIaha	Dairait	Repair Cost	ID.	
Deficiency Public Address Is Inadequate And Should Be Replaced		Qty UoM 2,904 SF	Priority 2	•	ID 207422	
	Capital Renewal Educational	2,904 SF 1 Ea.	2	\$3,676 \$3,684	Rollup	
Room lacks Fixed Projector	Adequacy	1 Ca.	2	ФЭ,004	Rollup	
Room lacks Interactive White Board	Educational Adequacy	1 Ea.	2	\$2,722	Rollup	
The Computer Closet Requires Fiber Optic Access to CER	Functional Deficiency	400 LF	2	\$9,000	Rollup	
	Sub Total for System	4 items		\$19,082		
Specialties						
Peficiency	Category	Qty UoM	Priority	Repair Cost	ID	
coom lacks the required demonstration table.	Educational	1 Ea.	3	\$7,463	Rollup	
ME de la companya de la companya de la companya de la companya de la companya de la companya de la companya de	Adequacy	04.05.0	4	#0.070	Daller	
Blinds are missing or in poor condition.	Educational Adequacy	84 SF Surf	4	\$2,373	Rollup	
	Sub Total for System	2 items		\$9,836		
Other						
eficiency	Category	Qty UoM	Priority	Repair Cost	ID	
enovate / Remodel Music and Art Rooms	Deferred Maintenance	1 LS	2	\$68,244	316812	
	Sub Total for System	1 items		\$68,244		
	Sub Total for Building 07 - Building 7	14 items		\$163,615		
eficiency eroofing with new Decking Required (Broward CPS)	Category Capital Renewal	Qty UoM 4,574 SF	Priority 1	Repair Cost \$58,002	ID 208116	GOB
crooming with new Decrining required (Drowland Cr. Cy	Sub Total for System	1 items		\$58,002	200110	000
Exterior						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
he Steel Window is Damaged And Requires Replacement	Capital Renewal	2 SF	2	\$350	207523	GOB
he Exterior Requires Painting	Capital Renewal	2,940 SF Wall	3	\$10,036	207501	GOB
he Exterior Requires Cleaning	Deferred	2,940 SF Wall	5	\$5,946	207500	
	Maintenance			*** ***		
manui au	Sub Total for System	3 Items		\$16,332		
nterior	Catanan	Obs. Hald	Deineth	Deneis Cost	5	
Periciency	Category	Qty UoM 900 SF	Priority	Repair Cost	1D	
he Carpet Flooring Requires Replacement he Suspended Ceiling Grid and Tiles Require Replacement	Capital Renewal Capital Renewal	900 SF 850 SF	3	\$9,480	207504 207502	
ne Suspended Ceiling Grid and Tiles. Require Replacement he Vinyl Composition Tile Requires Replacement	Capital Renewal	1,352 SF	3	\$7,682 \$12,128	207502	
ne vinyi Composition Tile Requires Replacement Iterior Gypboard Walls Require Repainting	Capital Renewal Deferred	6,480 SF Wall		\$12,128 \$21,842		
The state of the s	Maintenance		,			
Machanian	Sub Total for System	4 items		\$51,132		
Mechanical	a :					
reficiency	Category	Qty UoM	Priority	Repair Cost	ID	0.00
controls Are Inadequate And Should Be Replaced With DDC Controls	Capital Renewal	2,479 SF	3	\$10,571		GOB
uct Heater Requires Replacement	Capital Renewal	1 Ea.	3		207799	GOB
luctwork Requires Replacement	Capital Renewal	220 LF	3		207789	GOB
xhaust Fan Ventilation Requires Replacement	Capital Renewal	4 Ea.	3	\$8,431	207785	GOB
act And Ralancing Required	Deferred	2.470 CE	2	62 477	207797	COP
Fest And Balancing Required	Deferred Maintenance	2,479 SF	3	\$3,477	207787	GOB

Rev 1 Sept 2014 M•A•P•P•S ©, Jacobs 2014 Tedder Elementary School

0571

Page 9 of 17



School Deficiency Listing

0571 Tedder Elementary Scho	ool					
Building: 08 - Administration			•			
Plumbing						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
The Toilets Plumbing Fixtures Require Replacement	Capital Renewal	3 Ea.	2	\$6,840	207792	
The Rest Room Lavatories Plumbing Fixtures Require Replacement	Capital Renewal	4 Ea.	3	\$9,960	207791	
The Custodial Mop Or Service Sink Requires Replacement	Deferred Maintenance	1 Ea.	4		207790	
	Sub Total for System	3 items		\$18,504		
Fire and Security						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
Install Fire Sprinklers	Code Compliance	2,479 SF	1	\$21,622	207793	GOE
	Sub Total for System	1 items		\$21,622		
Technology						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
The Computer Closet Requires Fiber Optic Access to CER	Functional Deficiency	400 LF	2	\$9,000	Rollup	
	Sub Total for System	1 items		\$9,000		
Specialties	-					
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
The Base Storage Cabinets Require Replacement	Capital Renewal	16 LF	4	\$3,924	207506	
	Sub Total for System	1 items		\$3,924		
Roofing	Sub Total for Building 08 - Administration	19 items	Dianto	\$208,414	ID.	
Roofing Deficiency	Category	Qty UoM	Prionty 1	Repair Cost	ID 208117	GOE
Roofing Deficiency	-		Prionty 1		ID 208117	GOE
Building: 09 - Building 9 Roofing Deliciency Reroofing with new Decking Required (Broward CPS)	Category Capital Renewal	Qty UoM 20,488 SF		Repair Cost \$249,285		GOE
Roofing Deficiency Reroofing with new Decking Required (Broward CPS)	Category Capital Renewal	Qty UoM 20,488 SF		Repair Cost \$249,285		GOE
Roofing Deficiency Reroofing with new Decking Required (Broward CPS)	Category Capital Renewal Sub Total for System Category Educational	Qty UoM 20,488 SF 1 items	1	Repair Cost \$249,285 \$249,285	208117	GOE
Roofing Deficiency Reroofing with new Decking Required (Broward CPS) Interior Deficiency Classroom Door Requires Vision Panel	Category Capital Renewal Sub Total for System Category	Qty UoM 20,488 SF 1 items	1 Priority	Repair Cost \$249,285 \$249,285 Repair Cost	208117 ID	GOE
Roofing Deliciency Rerooling with new Decking Required (Broward CPS) Interior Deliciency Classroom Door Requires Vision Panel Classroom doors lack appropriate signs	Category Capital Renewal Sub Total for System Category Educational Adequacy Educational Adequacy	Oty UoM 20,488 SF 1 Items Oty UoM 1 Ea 4 Ea	Priority 3	Repair Cost \$249,285 \$249,285 Repair Cost \$373 \$684	ID Rollup Rollup	GOE
Roofing Deficiency Reroofing with new Decking Required (Broward CPS) Interior Deficiency Classroom Door Requires Vision Panel Classroom doors lack appropriate signs	Category Capital Renewal Sub Total for System Category Educational Adequacy Educational	Oty UoM 20,488 SF 1 Items Oty UoM 1 Ea	1 Priority 3	Repair Cost \$249,285 \$249,285 Repair Cost \$373	208117 ID Rollup	GOE
Roofing Deliciency Rerooling with new Decking Required (Broward CPS) Interior Deliciency Classroom Door Requires Vision Panel Classroom doors lack appropriate signs Room has insufficient tackboard area.	Category Capital Renewal Sub Total for System Category Educational Adequacy Educational Adequacy Educational	Oty UoM 20,488 SF 1 Items Oty UoM 1 Ea 4 Ea	Priority 3	Repair Cost \$249,285 \$249,285 Repair Cost \$373 \$684	ID Rollup Rollup	GOE
Roofing Deliciency Rerooling with new Decking Required (Broward CPS) Interior Deliciency Classroom Door Requires Vision Panel Classroom doors lack appropriate signs Room has insufficient tackboard area.	Category Capital Renewal Sub Total for System Category Educational Adequacy Educational Adequacy Educational Adequacy Educational Adequacy Educational	Oty UoM 20,488 SF 1 Items Oty UoM 1 Ea 4 Ea 2 Ea.	Priority 3 3 4	Repair Cost \$249,285 \$249,285 Repair Cost \$373 \$684 \$771	ID Rollup Rollup Rollup	GOE
Roofing Deficiency Reroofing with new Decking Required (Broward CPS) Interior Deficiency	Category Capital Renewal Sub Total for System Category Educational Adequacy Educational Adequacy Educational Adequacy Educational Adequacy Educational Adequacy Educational	Qty UoM 20.488 SF 1 Items Qty UoM 1 Ea. 4 Ea. 2 Ea. 1,517 SF	Priority 3 3 4	Repair Cost \$249,285 \$249,285 Repair Cost \$373 \$684 \$771	ID Rollup Rollup Rollup	GOB
Roofing Deliciency Rerooling with new Decking Required (Broward CPS) Interior Deliciency Classroom Door Requires Vision Panel Classroom doors lack appropriate signs Room has insufficient tackboard area. Room lacks appropriate sound controt.	Category Capital Renewal Sub Total for System Category Educational Adequacy Educational Adequacy Educational Adequacy Educational Adequacy Educational Adequacy Educational	Qty UoM 20.488 SF 1 Items Qty UoM 1 Ea. 4 Ea. 2 Ea. 1,517 SF	Priority 3 3 4	Repair Cost \$249,285 \$249,285 Repair Cost \$373 \$684 \$771	ID Rollup Rollup Rollup	GOE
Roofing Deficiency Reroofing with new Decking Required (Broward CPS) Interior Deficiency Classroom Door Requires Vision Panel Classroom doors lack appropriate signs Room has insufficient tackboard area. Room lacks appropriate sound control. Electrical Deficiency	Category Capital Renewal Sub Total for System Category Educational Adequacy Educational Adequacy Educational Adequacy Educational Adequacy Educational Adequacy Sub Total for System	Oty UoM 20,488 SF 1 Items Oty UoM 1 Ea. 4 Ea. 2 Ea. 1,517 SF 4 items	Priority 3 4 4 Priority 3	Repair Cost \$249,285 \$249,285 Repair Cost \$373 \$684 \$771 \$47,580 \$49,409	ID Rollup Rollup Rollup Rollup	GOE
Roofing Deliciency Rerooling with new Decking Required (Broward CPS) Interior Deliciency Classroom Door Requires Vision Panel Classroom doors lack appropriate signs Room has insufficient tackboard area. Room lacks appropriate sound control. Electrical Deliciency Room has insufficient electrical outlets.	Category Capital Renewal Sub Total for System Category Educational Adequacy Sub Total for System Category Educational	Oty UoM 20,488 SF 1 Items Oty UoM 1 Ea. 4 Ea. 2 Ea. 1,517 SF 4 items	Priority 3 3 4 4	Repair Cost \$249,285 \$249,285 Repair Cost \$373 \$684 \$771 \$47,580 \$49,409	ID Rollup Rollup Rollup Rollup	GOB
Roofing Deficiency Reroofing with new Decking Required (Broward CPS) Interior Deficiency Classroom Door Requires Vision Panel Classroom doors lack appropriate signs Room has insufficient tackboard area. Room lacks appropriate sound controt. Electrical Deficiency Room has insufficient electrical outlets. Room does not have tamper-proof light switching.	Category Capital Renewal Sub Total for System Category Educational Adequacy Educational Adequacy Educational Adequacy Educational Adequacy Sub Total for System Category Educational Adequacy Sub Total for System	Oty UoM 20,488 SF 1 Items Oty UoM 1 Ea 4 Ea 2 Ea 1,517 SF 4 Items Oty UoM 16 Ea	Priority 3 4 4 Priority 3	Repair Cost \$249,285 \$249,285 Repair Cost \$373 \$684 \$771 \$47,580 \$49,409 Repair Cost \$5,853	ID Rollup Rollup Rollup Rollup Rollup Rollup Rollup Rollup	GOE
Roofing Deliciency Rerooling with new Decking Required (Broward CPS) Interior Deliciency Classroom Door Requires Vision Panel Classroom doors lack appropriate signs. Room has insufficient tackboard area. Room lacks appropriate sound control. Electrical Deliciency Room has insufficient electrical outlets. Room does not have tamper-proof light switching.	Category Capital Renewal Sub Total for System Category Educational Adequacy Educational Adequacy Educational Adequacy Educational Adequacy Educational Adequacy Educational Adequacy Sub Total for System Category Educational Adequacy Educational Adequacy Educational Adequacy Educational Educational Educational Educational Educational Educational Educational	Qty UoM 20.488 SF 1 Items Qty UoM 1 Ea. 4 Ea. 2 Ea. 1.517 SF 4 Items Qty UoM 16 Ea. 1 Ea.	Priority 3 4 4 Priority 3 5	Repair Cost \$249,285 \$249,285 Repair Cost \$373 \$684 \$771 \$47,580 \$49,409 Repair Cost \$5,853 \$486	ID Rollup Rollup Rollup Rollup Rollup Rollup	GOE
Roofing Deliciency Rerooling with new Decking Required (Broward CPS) Interior Deliciency Classroom Door Requires Vision Panel Classroom doors lack appropriate signs. Room has insufficient tackboard area. Room lacks appropriate sound control. Electrical Deliciency Room has insufficient electrical outlets. Room does not have tamper-proof light switching.	Category Capital Renewal Sub Total for System Category Educational Adequacy Educational Adequacy Educational Adequacy Educational Adequacy Educational Adequacy Sub Total for System Category Educational Adequacy Educational Adequacy Educational Adequacy Educational Adequacy Educational Adequacy Educational Adequacy	Oty UoM 20,488 SF 1 Items Oty UoM 1 Ea 4 Ea 2 Ea. 1,517 SF 4 Items Oty UoM 16 Ea. 1 Ea. 1 Ea.	Priority 3 4 4 Priority 3 5	Repair Cost \$249,285 \$249,285 Repair Cost \$373 \$684 \$771 \$47,580 \$49,409 Repair Cost \$5,853 \$486 \$779	ID Rollup Rollup Rollup Rollup Rollup Rollup Rollup Rollup Rollup	GOE
Roofing Deliciency Reroofing with new Decking Required (Broward CPS) Interior Deliciency Classroom Door Requires Vision Panel Classroom doors lack appropriate signs Room has insufficient tackboard area. Room lacks appropriate sound control. Electrical Deliciency Room has insufficient electrical outlets. Room does not have tamper-proof light switching. Room lacks controls to partially dim lights. Plumbing Deliciency	Category Capital Renewal Sub Total for System Category Educational Adequacy Educational Adequacy Educational Adequacy Educational Adequacy Educational Adequacy Sub Total for System Category Educational Adequacy Sub Total for System	Oty UoM 20,488 SF 1 Items Oty UoM 1 Ea. 4 Ea. 2 Ea. 1,517 SF 4 Items Oty UoM 16 Ea. 1 Ea. 1 Ea. 3 Items	Priority 3 4 4 Priority 3 5 Figure 1	Repair Cost \$249,285 \$249,285 \$249,285 Repair Cost \$373 \$684 \$771 \$47,580 \$49,409 Repair Cost \$5,853 \$486 \$779 \$7,118 Repair Cost	ID Rollup Rollup Rollup ID Rollup Rollup Rollup Rollup Rollup Rollup Rollup Rollup Rollup Rollup Rollup	GOB
Roofing Deliciency Reroofing with new Decking Required (Broward CPS) Interior Deficiency Classroom Door Requires Vision Panel Classroom doors lack appropriate signs Room has insufficient tackboard area. Room lacks appropriate sound control.	Category Capital Renewal Sub Total for System Category Educational Adequacy Educational Adequacy Educational Adequacy Educational Adequacy Educational Adequacy Sub Total for System Category Educational Adequacy Sub Total for System	Oty UoM 20,488 SF 1 Items Oty UoM 1 Ea 4 Ea 2 Ee. 1,517 SF 4 Items Oty UoM 16 Ea. 1 Ea. 1 Ea. 3 Items	Priority 3 4 4 Priority 3 5 5	Repair Cost \$249,285 \$249,285 \$249,285 Repair Cost \$373 \$684 \$771 \$47,580 \$49,409 Repair Cost \$5,853 \$486 \$779 \$7,118	ID Rollup Rollup Rollup Rollup Rollup Rollup Rollup Rollup Rollup	GOB

Rev 1 Sept 2014 M•A•P•P•S ©, Jacobs 2014 Tedder Elementary School

0571

Page 10 of 17



School Deficiency Listing

0571 Tedder Elementary Schoo	ol .				9/2/2014	+ 0.017
Building: 09 - Building 9						
•						
Technology						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
The Computer Closet Requires Fiber Optic Access to CER	Functional Deficiency	400 LF	2	\$9,000	Rollup	
	Sub Total for System	1 items		\$9,000		
	Sub Total for Building 09 - Building 9	10 items		\$315,770		
Building: 13 - Music						
Roofing						
-	Cotomo	Ob. HeM	Deineller	Danair Coat	ID	
Deficiency Reroofing with new Decking Required (Broward CPS)	Category	Qty UoM 4,177 SF	Priority 1	Repair Cost \$51,943	ID 208118	GOE
Relocing with new Decking Required (Broward CPS)	Capital Renewal Sub Total for System	4,177 SF	1	\$51,943	200110	GUE
Post and an	Sub Total for System	i items		\$01,943		
Exterior						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
The Exterior Requires Painting	Capital Renewal	2,500 SF Wal	1 3	\$8,369	207542	GOE
The Glass Pane Is Damaged In The Exterior Window:	Deferred Maintenance	2 SF	3	\$157	207543	GOE
The Exterior Requires Cleaning	Deferred	2,500 SF Wal	1 5	\$4.058	207541	
The Exterior Regards Crearing	Maintenance	2,000 01 110		44,550	207041	
	Sub Total for System	3 items		\$13,484		
Interior						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
Classroom doors lack appropriate signs.	Educational	4 Ea.	3	\$684	Rollup	
sadd of the sadd appropriate eight.	Adequacy	. 23.	·	4001	r to map	
The Vinyl Composition Tile Requires Replacement	Capital Renewal	1,500 SF	3	\$13,195	207545	
Room has insufficient tackboard area.	Educational	4 Ea.	4	\$1,541	Rollup	
Secretaria de la constata del constata de la constata del constata de la constata del constata de la constata de la constata de la constata del constata de la constata del constata de la constata de la constata de la constata del constata de la constata de la constata de la constata del constata del constata del constata de la constata de la constat	Adequacy	٥.5-		25.440	D. H.	
Room lacks appropriate amount of teacher storage.	Educational Adequacy	9 Ea.	4	\$5,443	Rollup	
Room lacks appropriate sound control.	Educational	947 SF	4	\$29,702	Rollup	
	Adequacy					
nterior Gypboard Walls Require Repainting	Deferred Maintenance	2,500 SF Wal	1 5	\$8,264	207544	
	Sub Total for System	6 items		\$58,830		
Mechanical				,,,,,,,,,		
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
Wall Pack Lighting Is Damaged And Should Be Replaced	Capital Renewal	6 Ea.	2	\$5,253		
Controls Are Inadequate And Should Be Replaced With DDC Controls	Capital Renewal	4,386 SF	3	\$18,342	207947	GOE
		3 Ea.	3	\$15,365	207950	GOE
	Capital Renewal					
Ductwork Requires Replacement	Capital Renewal	440 LF	3	\$4,311		
Ductwork Requires Replacement			3		207948 207946	GOE
Ductwork Requires Replacement Test And Balancing Required	Capital Renewal Deferred	440 LF			207946	GOE
Ductwork Requires Replacement Test And Balancing Required	Capital Renewal Deferred Maintenance	440 LF 4,386 SF	3	\$6,032	207946	
Ductwork Requires Replacement Test And Balancing Required The Air Handler HVAC Component Requires Replacement	Capital Renewal Deferred Maintenance Capital Renewal	440 LF 4,386 SF 3 Ea.	3	\$6,032 \$165,179	207946	GOE
Ductwork Requires Replacement Fest And Balancing Required The Air Handler HVAC Component Requires Replacement Electrical	Capital Renewal Deferred Maintenance Capital Renewal Sub Total for System	440 LF 4,386 SF 3 Ea. 6 items	3	\$6,032 \$165,179 \$214,482	207946 207949	GOE
Ductwork Requires Replacement Fest And Balancing Required Fine Air Handler HVAC Component Requires Replacement Electrical Deficiency	Capital Renewal Deferred Maintenance Capital Renewal Sub Total for System Category	440 LF 4,386 SF 3 Ea. 6 items	3 3 Prionty	\$6,032 \$165,179 \$214,482 Repair Cost	207946 207949 ID	GOE
Ductwork Requires Replacement Fest And Balancing Required The Air Handler HVAC Component Requires Replacement Electrical Deficiency	Capital Renewal Deferred Maintenance Capital Renewal Sub Total for System	440 LF 4,386 SF 3 Ea. 6 items	3	\$6,032 \$165,179 \$214,482	207946 207949 ID	GOE
Ductwork Requires Replacement Test And Balancing Required The Air Handler HVAC Component Requires Replacement Electrical Deficiency	Capital Renewal Deferred Maintenance Capital Renewal Sub Total for System Category Deferred	440 LF 4,386 SF 3 Ea. 6 items	3 3 Prionty	\$6,032 \$165,179 \$214,482 Repair Cost	207946 207949 ID	GOE
Duct Heater Requires Replacement Ductwork Requires Replacement Test And Balancing Required The Air Handler HVAC Component Requires Replacement Electrical Deticiency Emergency Exit Signage Requires Replacement	Capital Renewal Deferred Maintenance Capital Renewal Sub Total for System Category Deferred Maintenance	440 LF 4,386 SF 3 Ea. 6 items Gty UoM 6 Ea	3 3 Prionty	\$6,032 \$165,179 \$214,482 Repair Cost \$4,315	207946 207949 ID	GOE
Ductwork Requires Replacement Fest And Balancing Required Fine Air Handler HVAC Component Requires Replacement Electrical Deticiency Emergency Exit Signage Requires Replacement	Capital Renewal Deferred Maintenance Capital Renewal Sub Total for System Category Deferred Maintenance Sub Total for System	440 LF 4,386 SF 3 Ea. 6 items Qty UoM 6 Ea. 1 items	3 3 Prionty 2	\$6,032 \$165,179 \$214,482 Repair Cost \$4,315	207946 207949 ID 207425	GOE
Ductwork Requires Replacement Fest And Balancing Required Fine Air Handler HVAC Component Requires Replacement Electrical Deticiency Emergency Exit Signage Requires Replacement Plumbing Deficiency	Capital Renewal Deferred Maintenance Capital Renewal Sub Total for System Category Deferred Maintenance Sub Total for System Category	440 LF 4,386 SF 3 Ea. 6 items Qty UoM 6 Ea. 1 items	3 3 Prionty 2 Priority	\$6,032 \$165,179 \$214,482 Repair Cost \$4,315 \$4,315	207946 207949 ID 207425	GOE
Ductwork Requires Replacement Test And Balancing Required The Air Handler HVAC Component Requires Replacement Electrical Deficiency Emergency Exit Signage Requires Replacement Plumbing Deficiency The Rest Room Lavatories Plumbing Fixtures Require Replacement	Capital Renewal Deferred Maintenance Capital Renewal Sub Total for System Category Deferred Maintenance Sub Total for System Category Capital Renewal	440 LF 4,386 SF 3 Ea. 6 items Qty UoM 6 Ea. 1 items Qty UoM 2 Ea.	3 3 Priority 2 Priority 3	\$6,032 \$165,179 \$214,482 Repair Cost \$4,315 Repair Cost \$4,884	207946 207949 ID 207425 ID 207952	GOE
Ductwork Requires Replacement Test And Balancing Required The Air Handler HVAC Component Requires Replacement Electrical Deficiency	Capital Renewal Deferred Maintenance Capital Renewal Sub Total for System Category Deferred Maintenance Sub Total for System Category	440 LF 4,386 SF 3 Ea. 6 items Qty UoM 6 Ea. 1 items	3 3 Prionty 2 Priority	\$6,032 \$165,179 \$214,482 Repair Cost \$4,315 Repair Cost \$4,884	207946 207949 ID 207425	GOE

 Rev 1 Sept 2014
 Tedder Elementary School
 0571

 M•A•P•P•S ©, Jacobs 2014
 Page 11 of 17

School Deficiency Listing

0571 Tedder Elementary School			٦		9/2/2014	\$:01 AN
Building: 13 - Music						
Fire and Security						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
install Fire Sprinklers	Code Compliance	4,386 SF	1	\$37,515	207953	GOB
istali i ilo Opininoi s	Sub Total for System	1 items		\$37,515	207333	000
Technology				,,		
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
Room lacks Fixed Projector	Educational	1 Ea.	2	\$3,684	Rollup	
Total Control (1990)	Adequacy	. 20.	-	40,001		
The Computer Closet Requires Fiber Optic Access to CER	Functional Deficiency	400 LF	2	\$9,000	Rollup	
	Sub Total for System	2 items		\$12,684		
	Sub Total for Building 13 - Music	22 items		\$399,808		
Building: 14 - Building 14						
Roofing						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
Reroofing with new Decking Required (Broward CPS)	Capital Renewal	7,146 SF	1	\$88,865	208119	GOB
	Sub Total for System	1 items		\$88,865		
Exterior						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
The Aluminum Window is Damaged And Requires Replacement	Capital Renewal	17 SF	2	\$2,516	207572	GOB
The Exterior Requires Painting	Capital Renewal	6,300 SF Wall	3	\$21,091	207564	GOB
The Exterior Soffit Requires Repainting	Deferred Maintenance	2,700 SF	3	\$7,641	207567	GOB
The Exterior Requires Cleaning	Deferred Maintenance	6,300 SF Wall	5	\$12,495	207563	
	Sub Total for System	4 items		\$43,743		
Interior						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
Classroom doors lack appropriate signs.	Educational Adequacy	6 Ea.	3	\$1,026	Rollup	
Room has insufficient writing area.	Educational Adequacy	2 Ea.	3	\$2,077	Rollup	
The Suspended Ceiling Grid and Tiles Require Replacement	Capital Renewal	3,100 SF	3	\$27,473	207573	
Room lacks appropriate amount of teacher storage.	Educational Adequacy	3 Ea.	4	\$1,814	Rollup	
Room lacks appropriate sound control.	Educational Adequacy	1,340 SF	4	\$42,030	Rollup	
nterior Gypboard Walls Require Repainting	Deferred Maintenance	10,800 SF Wall	5	\$35,700	207574	
Room lacks a changing table.	Educational Adequacy	2 Ea.	5	\$4,977	Rollup	
	Sub Total for System	7 items		\$115,098		
Mechanical						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
The Exterior Air Handler Is Damaged And Requires Replacement	Capital Renewal	2 Ea.	2	\$260,101	207954	GOB
Controls Are Inadequate And Should Be Replaced With DDC Controls	Capital Renewal	7,503 SF	3	\$31,377	207957	GOB
Duct Heater Requires Replacement	Capital Renewal	2 Ea.	3	\$10,243		GOB
Test And Balancing Required	Deferred Maintenance	7,503 SF	3	\$10,319	207956	GOB
The Air Handler HVAC Component Requires Replacement	Capital Renewal	2 Ea.	3	\$110,119	207958	GOB
	Sub Total for System	5 items		\$422,160		
Electrical						
Liecu icai						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	

Rev 1 Sept 2014 M•A•P•P•S ©, Jacobs 2014 Tedder Elementary School

0571

Page 12 of 17



School Deficiency Listing

0571 Tedder Elementary School			\neg		9/2/2014	8:01
Building: 14 - Building 14						
Electrical						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
Room does not have tamper-proof light switching.	Educational Adequacy	3 Ea.	5	\$1,457	Rollup	
	Sub Total for System	2 items		\$30,720		
Plumbing						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
Backflow Preventer Requires Replacement	Capital Renewal	1 Ea.	2	\$2,399	207965	
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Inst	alled Educational Adequacy	1 Ea.	2	\$1,357	Rollup	
The Class Room Lavatories Plumbing Fixtures Require Replacement	Capital Renewal	11 Ea.	2	\$22,740	207960	
The Toilets Plumbing Fixtures Require Replacement	Capital Renewal	6 Ea.	2	\$13,416	207963	
The Rest Room Lavatories Plumbing Fixtures Require Replacement	Capital Renewal	6 Ea.	3	\$14,651	207962	
Room lacks a private shower area.	Educational Adequacy	2 Ea.	4	\$18,266	Rollup	
The Custodial Mop Or Service Sink Requires Replacement	Deferred Maintenance	1 Ea.	4	\$1,671	207961	
	Sub Total for System	7 items		\$74,498		
Fire and Security						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
Install Fire Sprinklers	Code Compliance	7,503 SF	1	\$64,176	207964	GC
	Sub Total for System	1 items		\$64,176		
Technology						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
Room has insufficient dataports.	Educational	28 Ea.	2	\$4,844	Rollup	GC
Room lacks Fixed Projector	Adequacy Educational Adequacy	1 Ea.	2	\$3,684	Rollup	
The Computer Closet Requires Fiber Optic Access to CER	Functional Deficiency	400 LF	2	\$9,000	Rollup	
	Sub Total for System	3 items		\$17,528		
Specialties						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
Room lacks an appropriate refrigerator.	Educational	2 Ea.	3	\$10,507	Rollup	
and the state of t	Adequacy		-			
Room lacks an appropriate stove.	Educational Adequacy	2 Ea.	3	\$14,343	Rollup	
Room does not have sufficient cubbies	Educational Adequacy	62 Ea.	5	\$2,582	Rollup	
Room has an insufficient number of coat hooks.	Educational Adequacy	48 Ea.	5	\$558	Rollup	
	Sub Total for System	4 items		\$27,989		
Sub	otal for Building 14 - Building 14	34 items		\$884,776		
Building: 15 - Media Center						
Roofing						
	Category	Ohr Hald	Drington	Danais Oct	ID.	
Deficiency Reroofing with new Decking Required (Broward CPS)	Category Capital Renewal	Qty UoM 5,542 SF	Priority 1	Repair Cost \$68,918	ID 208120	GC
renound with new Decknith redning (blowsing ct.2)	Sub Total for System	1 Items	'	\$68,918 \$68,918	200120	90
Exterior	Sub Islanion System	, iteliis		200 ,210		
	Others	Ab	B4: **	B		
Deficiency The Education Review Reliation	Category	Qty UoM	Priority	Repair Cost	ID	0.0
The Exterior Requires Painting	Capital Renewal	3,360 SF Wall	3	\$11,248	207593	GO
The Glass Pane is Damaged in The Exterior Window:	Deferred	64 SF	3	\$5,008	207594	GO

Rev 1 Sept 2014 M•A•P•P•S ©, Jacobs 2014 Tedder Elementary School

0571

Page 13 of 17



9/2/2014 8:01 AM

Broward County Public Schools

School Deficiency Listing

Decision Part	0571 Tedder Elementary School					9/2/2014	10.01
Calcaps	Building: 15 - Media Center			_			
Deterror Sub Total for System S 16ms S 2009 S 2019	Exterior						
Matriceannes Sub-Total for System 3 Items 122,000					•		
Deficiency Category Caty Units	The Exterior Requires Cleaning		3,360 SF Wal	5	\$6,664	207592	
Marcianney Catagory Catagor		Sub Total for System	3 items		\$22,920		
The Carpat Fiborring Regulacement	nterior						
The Supprended Ceiling Grief and Tiles Require Registerement Capital Renowal 10 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
Remarks	he Carpet Flooring Requires Replacement	Capital Renewal	5,300 SF	3	\$54,748	207596	
Adequate Adequate	he Suspended Ceiling Grid and Tiles Require Replacement	Capital Renewal	800 SF	3	\$7,090	207595	
Recursion Recu	Room lacks appropriate amount of teacher storage.		18 Ea.	4	\$10,887	Rollup	
Name	Room lacks appropriate sound control.	Educational	1,146 SF	4	\$35,944	Rollup	
Cotogony		Sub Total for System	4 items		\$108,669		
The Exterior Air Handler is Damaged And Requires Replacement Capital Renewal 5,819 SF 3 \$24,355 207888 60 Controls Are Inadequate And Should Be Replaced With DDC Controls Capital Renewal 1 Ea 3 \$42,355 207888 67 3 \$24,355 207888 67 3 \$24,355 207888 67 3 \$24,355 207888 67 3 \$24,355 207888 67 3 \$24,355 207888 67 3 \$24,355 207888 67 3 \$24,355 207888 67 3 \$24,355 207888 67 3 \$24,355 207888 67 3 \$24,355 20788 67 3	Vlechanical						
Controls Are Inadequate And Should Be Replaced With DDC Controls Capital Renewal 5,819 SF 3 \$24,335 207808 04 Dut Hinder Requires Replacement Capital Renewal 1 Ea 3 \$5,122 207871 04 Dut Hinder HVAC Component Requires Replacement Capital Renewal 1 Ea 3 \$5,122 207871 04 Dut Hinder HVAC Component Requires Replacement Capital Renewal 1 Ea 3 \$5,128 207870 04 Dut Hinder HVAC Component Requires Replacement Capital Renewal 1 Ea 3 \$5,080 207870 05 Dut Hinder HVAC Component Requires Replacement Capital Renewal 1 Ea 3 \$5,080 207870 05 Dut Hinder HVAC Component Requires Replacement Capital Renewal 1 Ea 5 \$488 Rollup Renewal Capital Rene)eficiency	Category	Qty UoM	Priority	Repair Cost	ID	
Capital Renewal 1 Ea. 3	he Exterior Air Handler Is Damaged And Requires Replacement	Capital Renewal	1 Ea.	2	\$130,050	207864	Gr
The Air Handler HVAC Component Requires Replacement Sub Total for System 4 terms \$214,667	Controls Are Inadequate And Should Be Replaced With DDC Controls	Capital Renewal	5,819 SF	3			G
Sub Total for System							
Part Part	he Air Handler HVAC Component Requires Replacement			3		207870	G
Politic Poli		Sub Total for System	4 items		\$214,567		
toom has insufficient electrical outlets. Adequacy south flags and specified in the second does not have tamper-proof light switching. Educational Adequacy south Total for System 2 items \$7,069 Plumbing Plumbing Plumbing Poeficiency Category Qity UoM Priority Repair Cost ID The Totalets Plumbing Fixtures Require Replacement Capital Renewal 4 Ea. 2 \$8,944 207874 to United Plumbing Fixtures Require Replacement Capital Renewal 4 Ea. 2 \$8,944 207874 to United Plumbing Fixtures Require Replacement Capital Renewal 4 Ea. 3 \$9,76 207872 to 207875 to Rest Room Levistories Plumbing Fixtures Require Replacement Capital Renewal 4 Ea. 3 \$9,76 207872 to 207875 to Rest Room Levistories Plumbing Fixtures Require Replacement Capital Renewal 4 Ea. 3 \$9,76 207872 to 207875 to Rest Room Levistories Plumbing Fixtures Require Replacement Capital Renewal 4 Ea. 3 \$9,76 207872 to 207875 to Rest Room Levistories Plumbing Fixtures Require Replacement Capital Renewal 5 Ea. 3 \$9,76 207872 to Rest Room Levistories Plumbing Fixtures Require Replacement Capital Renewal 4 Ea. 3 \$9,76 207872 to Rest Rest Room Levistories Plumbing Fixtures Require Replacement Capital Renewal 4 Ea. 3 \$9,76 207872 to Rest Rest Room Levistories Plumbing Fixtures Require Replacement Capital Renewal 4 Ea. 3 \$9,76 207872 to Rest Rest Room Levistories Plumbing Fixtures Require Replacement Capital Renewal 4 Ea. 3 \$9,70 207872 to Rest Rest Rest Rest Rest Rest Rest Rest		0.4					
Adequacy Sub Total for System 1 Eu. 5 \$488 Rollup 1 Eu. 5 \$489 Rollu							
Sub Total for System 2 items \$7,069		Adequacy					
Plumbing Deficiency Category Qty UoM Priority Repair Cost ID The Tollets Plumbing Fixtures Require Replacement Capital Renewal 4 Ea. 2 \$8,944 207874 The Unional Plumbing Fixtures Require Replacement Capital Renewal 1 Ea. 2 \$1,792 207875 The Rest Room Lavatories Plumbing Fixtures Require Replacement Capital Renewal 4 Ea. 3 \$9,767 207875 The Rest Room Lavatories Plumbing Fixtures Require Replacement Rubbing R	toon ages not have tamper-proofing a systeming.		. 20.		4+00	rromap	
Deficiency Category Oty UoM Priority Repair Cost ID Priority Priority Repair Cost ID Priority Plumbing Fixtures Require Replacement Capital Renewal 1 Ea. 2 \$1,902 207874 The Urinal Plumbing Fixtures Require Replacement Capital Renewal 1 Ea. 2 \$1,702 207875 The Rest Room Lavatories Plumbing Fixtures Require Replacement Capital Renewal 4 Ea. 3 \$9,767 207872 The Rest Room Lavatories Plumbing Fixtures Require Replacement Capital Renewal 4 Ea. 3 \$9,767 207872 The Rest Room Lavatories Plumbing Fixtures Require Replacement Capital Renewal 4 Ea. 3 \$9,767 207872 The Rest Room Lavatories Plumbing Fixtures Require Replacement Capital Renewal 4 Ea. 3 \$9,767 207872 The Rest Room Lavatories Plumbing Fixtures Require Replacement Capital Renewal 4 Ea. 3 \$9,767 207872 The Rest Room Lavatories Plumbing Fixtures Require Replacement Capital Renewal 4 Ea. 3 \$9,767 207872 The Rest Room Lavatories Plumbing Fixtures Require Replacement Capital Renewal 4 Ea. 3 \$9,760 207872 The Capital Renewal 4 Ea. 3 \$9,767 207872 The Rest Room Lavatories Plumbing Fixtures Require Replacement Capital Renewal 4 Ea. 3 \$9,767 207872 The Capital Fixed Projector Sub Total For System 1 Items \$49,772 207676 Complete Closet Requires Fiber Optic Access to CER Functional Deficiency 400 LF 2 \$9,000 Rollup Recom lacks access to video distribution. Educational 1 Ea. 5 \$865 Rollup Recom lacks access to video distribution. Sub Total for System 3 Items \$13,349 Sub Total for Building 16 - Media Center 21 Items \$505,768 Building: 16 - Building 16 - Building 16 - Media Center 21 Items \$505,768 The Exterior Security Camera is Damaged And Should Be Repaired Deferred 2 Ea. 2 \$907 207430 The Exterior Security Camera is Damaged And Should Be Repaired Deferred Maintenance 2 Ea. 2 \$907 207430 The Exterior Security Camera is Damaged And Should Be Repaired Deferred Maintenance 2 Ea. 2 \$907 207430 The Exterior Security Camera is Damaged And Should Be Repaired Deferred Maintenance 2 Ea. 2 \$900 207430 The Exterior Security Camera is Damaged And S		Sub Total for System	2 items		\$7,069		
The Toilets Plumbing Fixtures Require Replacement The Urinal Plumbing Fixtures Require Replacement The Urinal Plumbing Fixtures Require Replacement The Rest Room Lavatories Plumbing Fixtures Require Replacement The Interest Require Replacement The Rest Room Lavatories Plumbing Fixtures Require Replacement The Interest Require Replacement The Interest Require Replacement The Interest Require Replacement The Interest Require Replacement The Interest Require Replacement The Interest Require Plumbing Fixtures Require Replacement The Interest Require Plumbing Fixtures Require Replacement The Interest Require Plumbing Fixtures Require Replacement The Interest Require Plumbing Fixtures Require Replacement The Interest Rest Require Plumbing Fixtures Require Plumbing Fixtures Require Replacement The Interest Require Plumbing Fixtures Require Plum	Plumbing						
The Urinal Plumbing Fixtures Require Replacement Capital Renewal 1 Ea. 2 \$1,792 207875 The Rest Room Lavatories Plumbing Fixtures Require Replacement Capital Renewal 4 Ea. 3 \$9,767 207872 The Rest Room Lavatories Plumbing Fixtures Require Replacement Sub Total for System 3 items \$20,503	Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
The Rest Room Lavatories Plumbing Fixtures Require Replacement Capital Renewal 4 Ea. 3 \$9,767 207872 Sub Total for System 3 items \$20,503 Fire and Security Deficiency Category Qty UoM Priority Repair Cost ID Install Fire Sprinklers Code Compliance 5,819 SF 1 \$49,772 207876 Compliance 5,819 SF 1 \$49,772	he Toilets Plumbing Fixtures Require Replacement	Capital Renewal	4 Ea.	2	\$8,944	207874	
Fire and Security Peticiency Category Oty UoM Priority Repair Cost ID Install Fire Sprinklers Code Compliance 5,819 SF 1 \$49,772 207676 CODE Compliance 5,819 SF 1 \$49,772 207676 CODE COMPLIANCE SUBTRIANCE STREET STREET SPRINKLERS STREET STREET SPRINKLERS STREET STREET SPRINKLERS STREET STREET SPRINKLERS STREET STREET SPRINKLERS STREET	The Urinal Plumbing Fixtures Require Replacement	Capital Renewal	1 Ea.	2	\$1,792	207875	
Fire and Security Deficiency Category Oty UoM Priority Repair Cost Deficiency Sub Total for System Category Oty UoM Priority Repair Cost Deficiency Code Compliance Sub Total for System Technology Complex Complex Cost Category Oty UoM Priority Repair Cost Deficiency Complex Complex Cost Category Oty UoM Priority Repair Cost Deficiency Complex Complex Cost Category Complex Cost Complex Cost Complex Cost Category Complex Cost Complex Cost Category Complex Cost Complex Cost Complex Cost Category Complex Cost Category Category Coty UoM Complex Cost Category Category Catego	he Rest Room Lavatories Plumbing Fixtures Require Replacement	Capital Renewal	4 Ea.	3	\$9,767	207872	
Category Oty UoM Priority Repair Cost ID Sub Total For System 1 items \$49,772 207876 COST Sub Total for System 1 items \$49,772 207876 COST Sub Total for System 1 items \$49,772 207876 COST Sub Total for System 1 items \$49,772 207876 COST Sub Total for System 1 items \$49,772 207876 COST Sub Total for System 1 items \$49,772 207876 COST Sub Total for System 1 items \$49,772 207876 COST Sub Total for System 1 items \$49,772 207876 COST Sub Total for System 2 items 2 \$3,684 Rollup Sub Total for System 3 items \$13,349 2014 Sub Total for System 2 items \$505,788 Sub Total for Building 15 - Media Center 21 items \$505,788 Sub Total for Building 15 - Media Center 2 items \$505,788 Sub Total for System 2 items 2 items \$505,788 Sub Total for System 2 items 2 it		Sub Total for System	3 items		\$20,503		
Technology Deficiency Category	Fire and Security						
Sub Total for System 1 items \$49,772 Technology Deficiency Category Qty UoM Priority Repair Cost ID Room lacks Fixed Projector Educational Adequacy The Computer Closet Requires Fiber Optic Access to CER Functional Deficiency 400 LF 2 \$9,000 Rollup Room lacks access to video distribution. Educational Adequacy Sub Total for System 3 items \$13,349 Sub Total for Building 15 - Media Center 21 items \$505,768 Building: 16 - Building 16 Category Qty UoM Priority Repair Cost ID Peficiency Category Qty UoM Priority Repair Cost ID Category Qty UoM Priority Repair Cost ID Peficiency Category Qty UoM Priority Repair Cost ID Category Qty UoM Priority Repair Cost ID Category Qty UoM Priority Repair Cost ID Category Qty UoM Priority Repair Cost ID Category Qty UoM Priority Repair Cost ID Category Qty UoM Priority Repair Cost ID Category Qty UoM Priority Repair Cost ID Category Qty UoM Priority Repair Cost ID Category Qty UoM Priority Repair Cost ID Category Qty UoM Priority Repair Cost ID Category Qty UoM Priority Repair Cost ID Category Qty UoM Priority Repair Cost ID Category Qty UoM Priority Repair Cost ID Category Qty UoM Priority Repair Cost ID Category Qty UoM Priority Repair Cost ID	Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
Technology Deficiency Category Qty UoM Priority Repair Cost ID Room lacks Fixed Projector Educational Adequacy The Computer Closet Requires Fiber Optic Access to CER Functional Deficiency 400 LF 2 \$9,000 Rollup Room lacks access to video distribution. Educational Adequacy Sub Total for System 3 items \$13,349 Sub Total for Building 15 - Media Center 21 items \$505,768 Building: 16 - Building 16 Category Qty UoM Priority Repair Cost ID The Exterior Security Camera is Damaged And Should Be Repaired Deferred Maintenance 2 Ea 2 \$907 207430	nstall Fire Sprinklers	Code Compliance	5,819 SF	1	\$49,772	207876	C
Deficiency Category Oty UoM Priority Repair Cost ID Report Repair Cost Educational Adequacy The Computer Closet Requires Fiber Optic Access to CER Functional Deficiency Educational Adequacy Functional Deficiency Func		Sub Total for System	1 items		\$49,772		
Room lacks Fixed Projector Educational Adequacy 1 Ea 2 \$3,684 Rollup	Technology						
Adequacy The Computer Closet Requires Fiber Optic Access to CER Functional Deficiency Educational 1 Ea. 5 \$885 Rollup Adequacy Sub Total for System 3 items Sub Total for Building 15 - Media Center 21 items Sub Total for Building 16 - Building 16 Category Cuty UoM Priority Repair Cost ID The Exterior Security Camera is Damaged And Should Be Repaired Adequacy Functional Deficiency Adequacy Auto LF 2 \$9,000 Rollup Adequacy Functional 1 Ea. 5 \$885 Rollup Adequacy Functional 1 Ea. 5 \$885 Rollup Adequacy Sub Total for System 3 items \$13,349 Sub Total for Building 15 - Media Center 21 items Sob5,768 Category City UoM Priority Repair Cost ID The Exterior Security Camera is Damaged And Should Be Repaired Adintenance							
The Computer Closet Requires Fiber Optic Access to CER Functional Deficiency Educational Adequacy Sub Total for System Sub Total for Building 15 - Media Center Building: 16 - Building 16 Category Cat	Room lacks Fixed Projector		1 Ea.	2	\$3,684	Rollup	
Room lacks access to video distribution. Educational Adequacy Sub Total for System 3 items \$13,349 Sub Total for Building 15 - Media Center 21 items \$505,768 Building: 16 - Building 16 Category Oty UoM Priority Repair Cost ID The Exterior Security Camera is Damaged And Should Be Repaired Maintenance	The Computer Closet Requires Fiber Optic Access to CER		400 LF	2	\$9,000	Rollup	
Adequacy Sub Total for System 3 items \$13,349 Sub Total for Building 15 - Media Center 21 items \$505,768 Building: 16 - Building 16 Category Qty UoM Priority Repair Cost ID The Exterior Security Camera is Damaged And Should Be Repaired Maintenance 2 Ea 2 \$907 207430		•					
Sub Total for Building 15 - Media Center 21 items \$505,768 Building: 16 - Building 16 Category Oty UoM Priority Repair Cost ID The Exterior Security Camera Is Damaged And Should Be Repaired Maintenance 2 Ea. 2 \$907 207430					,		
Building: 16 - Building 16 Category Oty UoM Priority Repair Cost ID The Exterior Security Camera Is Damaged And Should Be Repaired Deferred Maintenance 2 Ea 2 \$907 207430		Sub Total for System	3 items		\$13,349		
The Exterior Security Camera Is Damaged And Should Be Repaired Deferred 2 Ea 2 \$907 20743 Maintenance	Room lacks access to video distribution.	Educational Adequacy Sub Total for System	3 items	5	\$665 \$13,349		
The Exterior Security Camera Is Damaged And Should Be Repaired Deferred 2 Ea 2 \$907 207430 Maintenance	Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
		Deferred					
		Maintanana					
			0 items		\$907		

Page 14 of 17

M•A•P•P•S ©, Jacobs 2014

School Deficiency Listing

D. 0 11 a. a. a. a. a. a. a. a. a. a. a. a. a.	anty i ablic ochools		· ·		Denoie	_	\$ 8:01 AM
0571	Tedder Elementary School					0/2/2014	70.017411
Building: 1	6 - Building 16			_			
Exterior							
Deficiency		Category	Qty UoM	Priority	Repair Cost	ID	
The Concrete / CMU E	xterior Requires Repair	Deferred Maintenance	1,000 SF Wall	3	\$897,867	207612	GOB
The Exterior Requires (Cleaning	Deferred Maintenance	23,520 SF Wall	5	\$45,636	207610	
		Sub Total for System	2 items		\$943,503		
Interior							
Deficiency		Category	Qty UoM	Priority	Repair Cost	ID	
Classroom doors lack a	appropriate signs.	Educational Adequacy	1 Ea.	3	\$171	Rollup	
Room has insufficient v	writing area.	Educational Adequacy	1 Ea.	3	\$1,039	Rollup	
Room has insufficient to	ackboard area.	Educational Adequacy	21 Ea.	4	\$8,093	Rollup	
	e amount of teacher storage.	Educational Adequacy	77 Ea.	4	\$46,571	Rollup	
Interior Gypboard Walls	s Require Repainting	Deferred Maintenance	30,400 SF Wall	5	\$98,308	207613	
		Sub Total for System	5 items		\$154,181		
Plumbing							
Deficiency		Category	Qty UoM	Priority	Repair Cost	ID.	
The Class Room Lavat	ories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	1 Ea.	2	\$1,357	Rollup	
Room lacks a drinking t	fountain.	Educational Adequacy	1 Ea.	5	\$959	Rollup	
		Sub Total for System	2 items		\$2,316		
Technology							
Deficiency		Category	Qty UoM	Priority	Repair Cost	ID	
Room lacks Fixed Proje	ector	Educational Adequacy	1 Ea.	2	\$3,684	Rollup	
Room lacks Interactive	White Board	Educational Adequacy	1 Ea.	2	\$2,722	Rollup	
The Computer Closet F	Requires Fiber Optic Access to CER	Functional Deficiency	400 LF	2	\$9,000	Rollup	
		Sub Total for System	3 items		\$15,406		
Conveyances	5						
Deficiency		Category	Qty UoM	Priority	Repair Cost	ID	
Elevator Sump Require	s Draining And Cleaning	Deferred Maintenance	1 Ea.	2	\$865	207839	
		Sub Total for System	1 items		\$865		
Specialties							
Deficiency		Category	Qty UoM	Priority	Repair Cost	ID	
Room does not have su	ufficient cubbies.	Educational Adequacy	468 Ea.	5	\$19,503	Rollup	
Room has an insufficier	nt number of coat hooks.	Educational Adequacy	432 Ea.	5	\$5,008	Rollup	
		Sub Total for System	2 items		\$24,511		
		Building 16 - Building 16	15 items		\$1,141,688		
Building: 1	9 - Classroom						
Roofing							
Deficiency		Category	Qty UoM	Priority	Repair Cost	ID	
	cking Required (Broward CPS)	Capital Renewal	4,599 SF	1	\$58,319		GOB
		Sub Total for System	1 items		\$58,319		

Rev 1 Sept 2014 M•A•P•P•S ©, Jacobs 2014 Tedder Elementary School

0571

Page 15 of 17



9/2/2014 8:01 AM

Broward County Public Schools

School Deficiency Listing

Michanish Michanish Cataglary Cata	0571 Tedder Elementary School			7		9/2/2014	+ Q.UT /W
Category	Building: 19 - Classroom			•			
Page Page	Structural	Catagoni	Oty HoM	Briantu	Ropair Cost	10	
Sub Total for System 1							COR
Calegory Calegory Calegory Calegory Calegory Promity Repair Cost Discrimination Discrimina	ne stacco Exterior is Damaged And Requires Replacement	·		2		210003	GOB
Processing 19 19 19 19 19 19 19 1	Exterior						
Designation Designation	Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
Maintenance Maintenance	he Aluminum Window Is Damaged And Requires Replacement	Capital Renewal	18 SF	2	\$2,717	207637	GOB
### Autonomous Page P	he Exterior Soffit Requires Repainting		1,200 SF	3	\$3,463	207632	GOB
Meterion	he Exterior Requires Cleaning		3,840 SF Wall	5	\$7,766	207631	
Category		Sub Total for System	3 items		\$13,946		
New Wood Estention Door is Damaged And Requires Replacement Capital Renewal 12 Door 2 \$50,583 207835 GoB	nterior						
Eacational Adoqueby 1 Ea 3 \$37 Rolup Adoqueby 1 Ea 3 \$37 Rolup Adoqueby 1 Eacational Adoqueby 1 Eacational 2 Ea 3 \$34 Rolup Adoqueby 1 Eacational 2 Ea 3 \$3.258 207644 1 Eacational 2 Ea 3 \$3.258 207644 1 Eacational 2 Ea 3 \$3.258 207644 1 Eacational 3 Ea 3 \$3.258 207644 1 Eacational 3 Ea 3 \$3.258 207644 1 Eacational 3 Ea 3 \$3.258 207644 1 Eacational 3 Ea 3 \$3.258 207644 1 Eacational 4 Ea 3 \$3.258 207644 1 Eacational 4 Ea 3 \$3.258 207644 1 Eacational 4 Ea 3 \$3.258 207644 1 Eacational 4 Ea 4 \$3.05 207645 1 Eacational 4 Ea 4 \$3.05 207645 1 Eacational 4 Ea 4 \$3.05 207639 1 Eacational 4 Ea 4 \$3.05 207643 1 Ea 4 \$3.05 207643 1 Eacational 4 Ea 4 \$3.05 207643 1 Ea 4 \$3.05 207643 1 Eacational 4 Ea 4 \$3.05 207643 1 Eacational 4 Ea 4 \$3.05 207643 1 Ea 4 \$3.05 207643 1 Eacational 4 Ea 4 \$3.05 207643 1 Eacational 4 Ea 4 \$3.05 207643 1 Eacational 4 Ea 4 \$3.05 207643 1 Ea 4 \$3.05 207643 1 Ea 4 \$3.05 207643 1 Ea 4 \$3.05 207643 1 Ea 4 \$3.05 207643 1 Ea 4 \$3.05 207643 1 Ea 4 \$3.05 207643 1 Ea 4 \$3.05 207643 1 Ea 4 \$3.05 207643 1 Ea 4 \$3.05 207643 1 Ea 4 \$3.05 207643 1 Ea 4 \$3.05 207643 1 Ea 4 \$3.05 207643 1 Ea 4 \$3.05 20764	reficiency	Category	Qty UoM	Priority	Repair Cost		
Adequacy Repair Adequacy Repair	he Wood Exterior Door Is Damaged And Requires Replacement						GOB
Educational 2 Ea. 3 \$3.42 Rolup Adequacy Adequacy Eternor Doors Requires Re-Keying Cupital Renewal 8 Ea. 3 \$3.258 20784 February 2007642 Eternor Doors Requires Requires Re-Keying Cupital Renewal 8 Ea. 3 \$3.258 20784 February 2007642 Eternor Doors Requires Replacement Cupital Renewal 1 Ea. 3 \$1.009 207642 Eternor Doors Requires Replacement Educational 1.500 SF 3 \$5.647 20764 February February Flooring is Damaged And Requires Replacement Capital Renewal 4.50 SF 3 \$3.66,477 20764 February Flooring Requires Replacement Capital Renewal 4.50 SF 3 \$3.66,477 20764 February February Flooring Requires Replacement Capital Renewal 4.50 SF 3 \$3.66,477 20764 February February Flooring Requires Replacement Educational 3 Ea. 4 \$3.55 Rolup Adequacy February Flooring Requires Replacement Capital Renewal 8 Door 4 \$3.75 80.000 February February Flooring Requires Replacement Capital Renewal 8 Door 4 \$1.7569 207642 February Flooring Requires Replacement Capital Renewal 8 Door 4 \$1.7569 207642 February Flooring Requires Replacement Capital Renewal 8 Door 4 \$1.7569 207642 February Flooring Requires Replacement Capital Renewal 1 Remember February Flooring Requires Replacement Capital Renewal 1 Ea. 2 \$5.1,751 Collisional Requires Replacement Capital Renewal 4,029 SF 3 \$2.000 207642 Collisional Requires Replacement Capital Renewal 1 Ea. 3 \$2.000 207642 Collisional Requires Replacement Capital Renewal 1 Ea. 3 \$2.000 207642 Collisional Renewal 1 Ea. 3 \$2.000 207642 Collisional Renewal 1 Ea. 3 \$2.000 207642 Collisional Reguires Replacement Capital Renewal 1 Ea. 3 \$2.000 207642 Collisional Reguires Replacement Capital Renewal 1 Ea. 3 \$2.000 207642 Collisional Reguires Replacement Capital Renewal 1 Ea. 3 \$2.000 207642 Collisional Reguires Replacement Capital R	lassroom Door Requires Vision Panel		1 Ea.	3	\$373	Rollup	
Elemon Door Hardware Requires Re-Keying Capital Renewal 8 Ea. 3 \$3.258 207644 Interior Doors Require Replacement Capital Renewal 8 Door 3 \$19.055 207642 Interior Doors Require Replacement Educational 1 Ea. 3 \$1.039 \$10.050 Interior Doors Requires Replacement Educational 1 Ea. 3 \$1.039 \$1.039 \$1.030 \$1	lassroom doors lack appropriate signs.	Educational	2 Ea.	3	\$342	Rollup	
Educational 1 Ea. 3 \$1,039 Rollup Adequates 1 Ea. 3 \$1,039 Rollup Adequates 1 Ea. 3 \$1,039 Rollup Restance Adequates 1,500 SF 3 \$56,477 207641 1	iterior Door Hardware Requires Re-Keying		8 Ea.	3	\$3,258	207644	
Adequacy Adequacy	nterior Doors Require Replacement	Capital Renewal	8 Door	3	\$19,605	207642	
Capital Renewal 4.50 SF 3 \$9.863 207639 Capital Renewal 4.50 SF 3 \$9.863 207639 Capital Renewal 1 Ea 4 \$3.85 Rollup Capital Renewal 1 Ea 4 \$3.85 Rollup Capital Renewal 1 Ea 4 \$3.85 Rollup Capital Renewal 3 Ea 4 \$1.814 Rollup Capital Renewal 8 Door 4 \$17.856 207643 Renewal Renewal Renewal 8 Door 4 \$17.856 207643 Renewal R	oom has insufficient writing area.		1 Ea.	3	\$1,039	Rollup	
Educational Adequacy	he Stone/Quarry Flooring Is Damaged And Requires Replacement		1,500 SF	3	\$56,477	207641	
Educational Adequacy		Capital Renewal	450 SF	3	\$9,363	207639	
Educational 3 Ea. 4 \$1,814 Rollup Adequacy Adeq		Educational	1 Ea.	4			
Part Part	oom lacks appropriate amount of teacher storage.	Educational	3 Ea.	4	\$1,814	Rollup	
Deferred Deferred Maintenance Sub Total for System 12 Items S 170,534 S 17	The Interior Countillantures Countins Countins		0.0	4	\$47.0E0	207042	
Maintenance Sub Total for System 12 Items \$170,534							
Maintenanical Maintenanica	terior Oypodard Wars Regarding Repairting		2,000 01 11011	Ü	40,400	207000	
Deficiency Category Oty UoM Priority Repair Cost ID		Sub Total for System	12 items		\$170,534		
Each Functional Deficiency 1 Each Ea	Mechanical						
Controls Are Inadequate And Should Be Replaced With DDC Controls Capital Renewal 4,829 SF 3 \$20,593 207914 GOB Ductwork Requires Replacement Capital Renewal 600 LF 3 \$5,995 207915 GOB Ductwork Requires Replacement Capital Renewal 1 Ca 3 \$2,000 207942 GOD Education Requires Replacement Capital Renewal 1 Ea 3 \$2,000 207942 GOD Education Requires Replacement Capital Renewal 1 Ea 3 \$2,000 207909 GOB Education Requires Replacement Capital Renewal 1 Ea 3 \$8,102 207911 GOB Education Requires Replacement Capital Renewal 1 Ea 3 \$8,102 207911 GOB Education Requires Replacement Capital Renewal 1 Ea 3 \$8,102 207912 GOB Education Requires Replacement Capital Renewal 1 Ea 3 \$8,102 207913 GOB Education Requires Replacement Capital Renewal 1 TonAC 3 \$2,000 207913 GOB Maintenance Capital Renewal 1 TonAC 3 \$2,000 207913 GOB Capital Renewal 1 TonAC 3 \$2,000 207913 Capital Renewal 1 TonAC 3 \$2,000 207913 Capital Renewal 2 Ea 5 \$3,600 207914 Capital Renewal 2 Ea 5 \$3,600 207916 Capital Renewal 2 Ea 2 2 2 2 2 2 2 2 2	y						
Buckwork Requires Replacement Capital Renewal 600 LF 3 \$5,995 207915 GOB Bedric Unit Heater Requires Replacement Capital Renewal 1 Ea 3 \$2,060 207942 GOD Idea of Lectric Unit Heater Requires Replacement Capital Renewal 1 Ea 3 \$2,108 207909 GOB Idea of Lectric Unit Heater Requires Replacement Capital Renewal 1 Ea 3 \$2,108 207909 GOB Idea of Top Unit Requires Replacement Capital Renewal 1 Ea 3 \$8,102 207911 GOB Idea of Top Unit Condensate Drain Requires Replacement Deferred Maintenance 1 Ea 3 \$6,772 207913 GOB Idea of Top Unit Condensate Drain Requires Replacement Deferred Maintenance 4,829 SF 3 \$6,772 207913 GOB Idea of Top Unit Condensate Drain Requires Replacement Capital Renewal 1 TonAC 3 \$2,401 207919 GOB Idea of Top Unit Condensate Drain Requires Requires Replacement </td <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>							
Schaust Fan Ventilation Requires Replacement Capital Renewal 1 Ea 3 \$2,108 207909 GOB		•					
Section Functional Deficiency 4,829 SF 3 \$8,102 207911 GOB							
Capital Renewal 1 Ea. 3 \$18.026 207908 GOB							
Deferred Maintenance 1 Ea. 3 \$302 207931		·					
Deferred Maintenance Mai		Deferred					000
Package Unit HVAC Component Requires Replacement Capital Renewal 1 TonAC 3 \$2,401 207919 GOB	est And Balancing Required	Deferred	4,829 SF	3	\$6,772	207913	GOB
Deferred Maintenance 2 Ea 5 \$ \$209 207917	he Package Unit HVAC Component Requires Replacement		1 TonAC	3	\$2,401	207919	GOB
Deferred Maintenance Sub Total for System 12 Ea 5 \$3,603 207916			2 Ea.	5			
Sub Total for System 12 items \$121,930 Electrical Category Qty UoM Priority Repair Cost ID Imergency Exit Signage Requires Replacement Deferred Maintenance 4 Ea. 2 \$2,933 207444	ouct Register Requires Replacement		12 Ea.	5	\$3,603	207916	
Electrical Category Qty UoM Priority Repair Cost ID mergency Exit Signage Requires Replacement Deferred 4 Ea. 2 \$2,933 207444 Maintenance			12 items		\$121,930		
mergency Exit Signage Requires Replacement Deferred 4 Ea. 2 \$2,933 207444 Maintenance	Electrical				,		
mergency Exit Signage Requires Replacement Deferred 4 Ea. 2 \$2,933 207444 Maintenance	reficiency	Category	Qty UoM	Priority	Repair Cost	ID	
he Panelboard Requires Replacement Capital Renewal 1 Ea. 2 \$2,961 207457	mergency Exit Signage Requires Replacement	Deferred			\$2,933	207444	
	he Panelboard Requires Replacement	Capital Renewal	1 Ea.	2	\$2,961	207457	
	Rev 1 Sept 2014		led	uer Eleme	entary School		057

Page 16 of 17

M•A•P•P•S ©, Jacobs 2014

School Deficiency Listing

0574	Todder Flowenten, School	<u> </u>				9/2/2014	₽8:01 A
0571	Tedder Elementary School	DI					
Building: 1	19 - Classroom						
Electrical							
Deficiency		Category	Qty UoM	Priority	Repair Cost	ID	
Room has insufficient	electrical outlets.	Educational Adequacy	16 Ea.	3	\$5,853	Rollup	
The 1 X 4 Interior Fluo	rescent Light Fixture Requires Replacement	Capital Renewal	60 Ea.	3	\$21,645	218648	
The 2 X 4 Interior Fluo	rescent Lighting Requires Replacement	Capital Renewal	11 Ea.	3	\$6,313	207458	
Room lacks controls to	partially dim lights.	Educational Adequacy	1 Ea.	5	\$779	Rollup	
		Sub Total for System	6 items	3	\$40,485		
Plumbing							
Deficiency		Category	Qty UoM	Priority	Repair Cost	ID	
The Toilets Plumbing F	Fixtures Require Replacement	Capital Renewal	1 Ea.	2	\$2,280	207926	
The Rest Room Lavato	ories Plumbing Fixtures Require Replacement	Capital Renewal	4 Ea.	3	\$9,960	207924	
The Custodial Mop Or	Service Sink Requires Replacement	Deferred Maintenance	1 Ea.	4	\$1,704	207922	
		Sub Total for System	3 items	5	\$13,943		
Fire and Sec	urity						
Deficiency	•	Category	Qty UoM	Priority	Repair Cost	ID	
Install Fire Sprinklers		Code Compliance	4,829 SF	1	\$42,119	207927	GOB
		Sub Total for System	1 item:	3	\$42,119		
Technology							
Deficiency		Category	Qty UoM	Priority	Repair Cost	ID	
Room lacks Interactive	White Board	Educational Adequacy	2 Ea.	2	\$5,443	Rollup	
		Sub Total for System	1 item:	3	\$5,443		
		Sub Total for Building 19 - Classroom	40 item:	6	\$541,717		
		Total for Permanent Buildings	320 items	5	\$7,167,755		
		Total for Portable Buildings			\$0		
		Total for Campus			\$7,167,755		

Rev 1 Sept 2014 M•A•P•P•S ©, Jacobs 2014 Tedder Elementary School

0571

Page 17 of 17

2.4.4 MAPPS Deficiency Data

9		6 9	10	13	14	20	21	22	23	27 28	
	Building Name	Deficiency Description	Def Note	Sycem ID Sys	system Name	Uniformat Description	Category Pi Description	Priority Priority Description		Quantity Unit	TTL Cost GOB
1	Administration	The Exterior Requires Painting		4 Ext	tentor	Exterior Wall Veneer	Capital Renewal	3 Short Term Conditions (2-3 Years)	onditions (2-3	2940 SF Wall	\$10,036
1	Administration	The Steel Window Is Damaged And Requires Replacement	3(L) × 6*(W)	4 Ext	Exterior	Exterior Fixed Windows	Capital Renewal	2 Indirect Impact Year)	ndirect impact to Mission (1 rear)	-S	809 998 \$
1		The Extendr Requires Painting		4 Ext	Exterior	Exterior Wall Veneer	Capital Renewal	3 Short Term Co Years)	short Term Conditions (2-3 rears)	2500 SF Wall	88,369 GOB
l	Music	The Glass Pane is Damaged in The Exterior Window:	8(L)×16(W)	4 Ext	Exterior	Exterior Fixed Windows	Deferred Maintenance	3 Short Term Co Years)	Short Term Conditions (2-3 Years)	15 15 15 15 15 15 15 15 15 15 15 15 15 1	\$157 608
l	Building 14	The Extendr Requires Painting		4 Ext	Exterior	Exterior Wall Veneer	Capital Renewal	3 Short Term Co Years)	Short Term Conditions (2-3 rears)	6300 SF Wall	\$21,091 GOB
		The Exterior Soffit Requires Repainting		4 Ext	Exterior	Exterior Wall Veneer	Deferred Maintenance	3 Short Term Conditions (2-3 Years)	onditions (2-3	2700 SF	\$7,641
		The Aluminum Window Is Damaged And Requires Replacement	6(L) X 3°(W)	4	Exterior	Exterior Fixed Windows	Capital Renewal	2 Indirect Impact Year)	ndirect Impact to Mission (1 (ear)	17 SF	\$2,516 GOB
		The Exterior Requires Painting		4 Ext	Extenor	Exterior Wall Veneer	Captal Renewal	3 Short Term Conditions (2-3 Years)	onditions (2:3	3360 SF Wall	\$11,248
	je je	The Glass Pane is Damaged in The Exterior Window:		4 Ext	Exterior	Exterior Fixed Windows	Deferred Maintenance	3 Short Term Co Years)	Short Term Conditions (2-3 Years)	64 SF	36,008
		The Concrete / CMU Exterior Requires Repair		4 Ext	Extenior	Exterior Wall Veneer	Deferred Maintenance	3 Short Term Conditions (2-3 Years)	onditions (2-3	1000 SF Wall	\$897,867
	Classroom	The Exterior Soffit Requires Repainting		4 Ext	Exterior	Exterior Wall Veneer	Deferred Maintenance	3 Short Term Co Years)	Short Term Conditions (2:3 rears)	1200 SF	805)
		The Wood Exterior Door Is Damaged And Requires Replacement		4 Ext	Exterior	Interior Sliding Doors	Capital Renewal	2 Indirect Impact Year)	rindirect Impact to Mission (1 Year)	12 Door	805
	Classroom	The Aluminum Window Is Damaged And Requires Replacement	28@ 6*(L.) × 3*(M)	4 Bit	Extendor	Exterior Fixed Windows	Capital Renewal	2 Indirect Impact to Mission (Year)	ttoMission (1	18 SF	\$2,717 G08
	Administration	Exhaust Fan Ventilation Regulres Replacement	300CFM	9 WB	Aechanical	Decentralized Coding	Capital Renewal	3 Short Term Co Years)	Short Term Conditions (2:3 Years)	4 Ea.	\$8,431 G08
		Test And Balanding Required		9 We	Wechanical	Decentralized Coding	Deferred Maintenance	3 Short Term Conditions (2-3 Years)	onditions (2-3	3479 SF	53,477 GOB
		Controls Are Inadequate And Should Be Replaced With DDC Controls		9 We	Aechanical	Decentralized	Captal Renewal	3 Short Term Conditions (2-3 Years)	onditions (2-3	2479 SF	\$10,571 GOB
		Ductwork Requires Replacement		9 Me	Mechanical	Decentralized Cooling	Capital Renewal	3 Short Term Conditions (2-3 Years)	onditions (2-3	220 LF	
		Install Fire Sprinklers		9 Fire	ire and Security	Water-Based Fire- Suppression	Code Compilance	1 Mission Ortical Concerns	al Concerns	2479 SF	\$21,622 GOB
		Duct Heater Requires Replacement		9 WB	Mechanical	Decentralized Heating Equipment	Capital Renewal	3 Short Term Conditions (2-3 Years)	onditions (2-3	1 Ea.	\$6,223 GOB
		The Exterior Air Handler is Damaged And Requires Replacement	7,500CFM	9 9	Aechanical	Decentralized	Capital Renewal	2 Indirect Impact Year)	ndirect impact to Mission (1 rear)	1 Ea.	\$130,050 GOB
	Media Center	Controls Are Inadequate And Should Be Replaced With DDC controls		9 We	Mechanical	Decentralized	Captal Renewal	3 Short Term Conditions (2-3 Years)	onditions (2:3	5819 SF	\$24,336
		The Air Handler HVAC Component Requires Replacement	7,500CFM	6 Me	Mechanical	Decentralized	Capital Renewal	3 Short Term Co Years)	Short Term Conditions (2-3 rears)	1 Ea.	926,060 GDB
	Media Center	Duct Heater Requires Replacement		9 We	Kechanical	Decentralized Heating Equipment	Capital Renewal	3 Short Term Conditions (2-3 Years)	onditions (2:3	1 E3.	\$6,122 G0B
	Media Center	Install Fire Spriniders	install	9 Fire	ire and Security	Water-Based Fire- Suppression	Code Compliance	1 Mission Ordical Concerns	al Concerns	5819 SF	
	Classroom	Package Roof Top Unit Requires Replacement	10TonAC	9 Me	Aechanical	Decentralized	Capital Renewal	3 Short Term Conditions (2-3 Years)	onditions (2-3	1 Ea.	\$18,026 GOB
	Classroom	Exhaust Fan Ventilation Requires Replacement	500CFM	9 Wei	/echanical		Capital Renewal	3 Short Term Conditions (2-3 Years)	onditions (2-3	1 Ea.	\$2,108 GDB
		Make-Up Air Should Be Increased		9 Me	Mechanical	Decentralized Coding	Functional Deficiency	3 Short Term Conditions (2-3 Years)	Short Term Conditions (2-3 Years)	4829 SF	\$8,102 GOB
	Classroom	Kitchen Air Exhaust is		2 140	Machaninal	l	Conchinent				

1 of 3

l-		_			608	809	608	608	GOB		809	608	809	608	808	608	60B	GOB	809	608	608	GOB	809	809	809	800
29	TTL Cost	\$6,772	\$20,583	98°98	\$2,401	\$42,119	\$2,068	\$6,032	\$18,342	£,31	\$165,179	\$15,365	\$37,518	\$260,101	\$10,319	531,377	\$110,119	\$10,243	\$64,176	\$68,002	\$249,285	\$51,943	\$88,88\$	\$68,918	\$68,319	\$74,999
27 28	Quantity Unit	4829 SF	4829 SF	600 LF	1 TanAC	4829 SF	1 Ea.	4386 SF	4386 SF	440 LF	3 Ea.	3 Ea.	4386 SF	2 Ea.	7503 SF	7503 SF	2 E3.	2 Ea.	7503 SF	4574 SF	20488 SF	4177 SF	7146 SF	5542 SF	4599 SF	3840 SF Wall
23		Short Term Conditions (2-3	Short Tern Conditions (2-3 Years)	Short Term Canditions (2-3 Years)	9 Short Term Canditions (2-3 Years)	Mission Critical Concerns	Short Term Conditions (2-3 Years)	Short Term Conditions (2-3 Years)	Years)	Short Term Conditions (2-3 Years)	3 Short Term Conditions (2-3 Years)	Short Term Conditions (2-3 Years)	Mission Critical Concerns	2 Indirect Impact to Mission (1 Year)	Snort Term Conditions (2-3 Years)	Years)	9 Short Term Canditions (2-3 Years)	Snort Term Conditions (2-3 Years)	Mission Critical Concerns	Mission Critical Concerns	Mission Critical Concerns	Mission Critical Concerns	Mission Critical Concerns	Mission Critical Concerns	Mission Critical Concerns	2 Indirect Impact to Mission (1 Year)
21 22	Category Priority Description	Deferred	Capital Renewal	Capital Renewal	Capital Renewal	Code Compliance	Sapital Renewal	Deferred Maintenance	Sapital Renewal	Capital Renewal	Capital Renewal	Sapital Renewal	Sode Compliance	Capital Renewal	Deferred	Capital Renewal	Capital Renewal	Sapital Renewal	Sode Compliance	Capital Renewal	Capital Renewal	Capital Renewal				
20		R	lized	Decentralized Cooling	Decentralized	Water-Based Fire-	_	Decembalized Cooling				Decentralized Heating Equipment	Water-Based Fire-	Decentralized Coding		Decentralized Cooling		Decentralized Heating Equipment	_		Law-Slape Roofing	Law-Slape Roafing C	_	Low-Slope Roofing C	Law-Slape Roafing C	Perimeter Insulation (
14	SyxemName	Mechanical	Mechanical	Mechanical	Mechanical	ire and Security	Mechanical	Mechanical	Mechanical			Mechanical	ire and Security	Mechanical	Mechanical	Mechanical	Mechanical	Mechanical	ire and Security	Roofing	Roding	Roding	Roding	Roding	Roding	Exterior
13	Sytem ID	9	9	9	4	9	9	9	<u>u</u>	9	N 9	9	o a	49	9	<u>4</u> 9	9	N 9	9	28	2	C4	24	C4	(c)	4
	Def Note				10TonAC	Install								10,000CFM			10,000CFM									
	Deficiency Description 1	Test And Balanding	Controls Are Inadequate And Should Be Replaced With DDC Controls	Ductwork Requires Replacement	The Package Unit HVAC Component Requires Replacement	Install Fire Sprinkers	Electric Unit Heater Requires Replacement	Test And Balanding Required	Controls Are Inadequate And Should Be Replaced With DDC controls	Ductwark Requires Replacement	The Air Handler HVAC Component Requires Replacement	Dudt Heater Requires Replacement	Install Fire Sprinklers	The Extenor Air Handler is Damaged And Requires Replacement	Test And Balanding Required	Controls Are inadequate And Should Be Replaced With DDC controls	The Air Handler HVAC Component Requires Repiscement	Duct Heater Requires Replacement	Install Fire Sprinklers	Reroding with new Decking Required (Broward CPS)	Reroding with new Decking Required (Broward CPS)	Reroding with new Decking Required (Broward CPS)	Renading with new Decking Required (Broward CPS)	Reroating with new Decking Required (Broward CPS)	Reroding with new Dedving Required (Broward CPS)	The Stucco Exterior Is Damaged And Requires
	Building Name	Classroom	Classroom				Clas sroom		Music			Music	Music			Building 14	Building 14		Building 14	Administration	Building 9	Music		Media Center	Classroom	Classroom
3	Building	19	19	19	19	19	19	13	13	13	13	13	13	14	14	14	14	14	14	88	88	13	21	15	61	19
en	Site Name	edder Elementary	207914 Tedder Elementary School	Tedder Elementary School	Tedder Elementary School	Tedder Elementary School	Tedder Elementary School	Tedder Elementary School	Tedder Elementary School	Tedder Elementary School	Tedder Elementary School	Tedder Elementary School	Tedder Elementary School	Tedder Elementary School	Tedder Elementary School	207957 Tedder Elementary School	Tedder Elementary School	Teddar Elementary School	edder Elementary chodi	School School	Tedder Elementary School	Tedder Elementary School	Tedder Elementary School	Tedder Elementary School	Tedder Elementary School	Tedder Elementary School
-	Def Assess Si	207913 Te	207914 Ti	207915 Te		207927 Te		207946 Te	207947 Te	207948 Te	207949 Te	207950 Te	207963 Te	207954 Te	207956 Te	207967 T.	207958 Te	207959 Te	207964 Te	208116 Te	208117 Te	208118 Te	208119 Te	208120 Te	208121 Te	218663 Te

2 of 3

۸	r	L	
•		۰	
٠,			

on.	GOB	608	608
22	TTL Cost	\$250,695	\$13,697
28		S	Ea.
27	Quantity	-	8
23	Priority Description Quantity Unit	Mission Critical Concerns	Long Term Requirements (3- 5 years)
22	Priority	1	4
21	Category Description	Capital Renewal	Capital Renewal
20	Uniformat Description	Fire Detection and Alarm	Fences and Gates
14	SystemName	Fire and Security	Site
13	Sytem ID	on .	-
10	Def Note	Model: 190004	
6	Deficiency Description	Entire Fire Alam System Model 19000A Needs to be Replaced	Playground Equipment Requires Replacement
9	Building Name		
3	Building Number		
ers.	Site Name	20887 Tedder Elementary School	12650 Tedder Elementary School
1	f Assess	220887	312650

2.4.5 MAPPS Deficiency Detail

Broward County Public Schools

Deficiency Detail

2/4/2016 1:41 PM

Tedder ES->Admin Location:

Deficiency:

290

207501 Surveyor/Update Sherry Sims Assess ID

Defeciency Code ID A26-01

Estimated FCI Status Yes

Life Cycle

Deficiency The Exterior Requires Painting

Tedder Elementary School

Category Capital Renewal System Exterior

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Paint Building Exterior Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty	UoM	Price	Extension
U	099123528400	Paints & coatings, miscellaneous interior, cornice, ornate design, paint 1 coat, oil base, brushwork	434	SF	1.57	\$681
U	099113601800	Paints & coatings, siding, exterior, Texture 1-111 or clapboard, oil base, primer coat, brushwork	2,940	SF	0.93	\$2,734
U	099103300080	Surface preparation, exterior, doors, per side, wire brush, metal, flush, excl. frames or trim	2,940	SF	0.79	\$2,323
			s	ub Total		\$5,738
		Con	struction Ac	ljustment	35%	1,980
			Constructi	ion Cost		\$7,718
			Adjustme	nt Factor	0%	0
		S	Soft Cost Ac	ljustment	48%	3,739
		Total	Estimated	Amount		\$11,457

Tedder Elementary School

290



Deficiency Detail

2/4/2016 1:41 PM

290 **Tedder Elementary School** Tedder ES->Admin

Location: Deficiency:

Status

Deficiency

Assess ID 207523 Surveyor/Update

Sherry Sims

A41-03 Defeciency Code ID

Estimated

Yes

Life Cycle 40296

The Steel Window Is Damaged And Requires Replacement

Capital Renewal Category

System

FCI

Exterior

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy

Non Related

Correction Replace Steel Frame Window Quantity / UoM

Project(s) Note

3"(L) X 6"(W)

Estimate:

	u.c.				
Туре	Number	Description	Qty UoM	Price	Extension
U	062213506000	Moldings, window & door, window trim sets, 2-1/2" wide, maximum	0 OPNG	169.00	\$28
U	080505205040	Window demolition, window, remove and reset, average	0 Ea.	151.00	\$25
U	085123202000	Windows, steel, custom units, double hung, intermediate projected, 2'-9" x 4'-1" opening, incl. frame, trim and insulated glass	0 Ea.	880.00	\$147
			Sub Total		\$200
			Construction Adjustment	35%	69
			Construction Cost		\$269
			Adjustment Factor	0%	0
			Soft Cost Adjustment	48%	130
		1	otal Estimated Amount		\$399

Prepared by: **HEERY**

Deficiency Detail

2/4/2016 1:41 PM

290 Tedder Elementary School
Location: Tedder ES->Music

Location: **Deficiency:**

Assess ID 207542 Surveyor/Update Sherry Sims

Defeciency Code ID A26-01

Status Estimated FCI Yes

Life Cycle

Deficiency The Exterior Requires Painting

Category Capital Renewal System Exterior

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Paint Building Exterior Quantity / UoM

Project(s) Note

Туре	Number	Description	Qty	UoM	Price	Extension
U	099123528400	Paints & coatings, miscellaneous interior, cornice, ornate design, paint 1 coat, oil base, brushwork	369	SF	1.57	\$579
U	099113601800	Paints & coatings, siding, exterior, Texture 1-111 or clapboard, oil base, primer coat, brushwork	2,500	SF	0.93	\$2,325
U	099103300080	Surface preparation, exterior, doors, per side, wire brush, metal, flush, excl. frames or trim	2,500	SF	0.79	\$1,975
			s	ub Total		\$4,879
		Cons	truction Ac	ljustment	35%	1,683
			Constructi	on Cost		\$6,563
			Adjustme	nt Factor	0%	0
		So	oft Cost Ac	ljustment	46%	2,991
		Total I	Estimated	Amount		\$9,554



Deficiency Detail

2/4/2016 1:41 PM

290 **Tedder Elementary School** Location: Tedder ES->Music

Deficiency:

Status

Assess ID 207543 Surveyor/Update

Sherry Sims

Defeciency Code ID A42-03

FCI Yes

Life Cycle 40412

Estimated

The Glass Pane Is Damaged In The Exterior Window: Deficiency

Deferred Maintenance Category System Exterior

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Reglaze Exterior Window Quantity / UoM

Project(s) Note 8"(L) X 16"(W)

Туре	Number	Description	Qty UoM	Price	Extension
U	080505202000	Window demolition, wood, to 12 S.F., includes trim	2 Ea.	22.00	\$44
U	062213503270	Moldings, window & door, glass beads, stock pine, 3/8" x 7/8"	8 LF	2.78	\$22
U	088155100700	Window glass, tempered, 3/16" thick	2 SF	12.50	\$25
			Sub Total		\$91
			Construction Adjustment	35%	31
			Construction Cost		\$123
			Adjustment Factor	0%	0
			Soft Cost Adjustment	46%	56
		т	otal Estimated Amount		\$179



Deficiency Detail

2/4/2016 1:41 PM

Tedder Elementary School Location: Tedder ES->Bldg 14

Deficiency:

290

Assess ID 207564 Surveyor/Update Sherry Sims

Defeciency Code ID A26-01

Estimated FCI Status Yes

Life Cycle

Deficiency The Exterior Requires Painting

Capital Renewal Category System Exterior

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Paint Building Exterior Quantity / UoM

Project(s) Note

Туре	Number	Description	Qty	UoM	Price	Extension
U	099123528400	Paints & coatings, miscellaneous interior, cornice, ornate design, paint 1 coat, oil base, brushwork	930	SF	1.57	\$1,460
U	099113601800	Paints & coatings, siding, exterior, Texture 1-111 or clapboard, oil base, primer coat, brushwork	6,300	SF	0.93	\$5,859
U	099103300080	Surface preparation, exterior, doors, per side, wire brush, metal, flush, excl. frames or trim	6,300	SF	0.79	\$4,977
			s	ub Total		\$12,296
		Cons	truction Ac	ljustment	35%	4,242
			Constructi	on Cost		\$16,538
			Adjustme	nt Factor	0%	0
		So	oft Cost Ac	ljustment	46%	7,538
		Total I	Estimated	Amount		\$24,076



Deficiency Detail

2/4/2016 1:41 PM

Location: Tedder ES->Bldg 14

Deficiency:

290

Assess ID 207567 Surveyor/Update

Sherry Sims

Defeciency Code ID A27-04

Status Life Cycle **Estimated**

Tedder Elementary School

FCI

Yes

The Exterior Soffit Requires Repainting Deficiency

Deferred Maintenance Category

System

Exterior

Priority

3-Short Term Conditions (2-3 Years)

Functional Adequacy

Non Related

Correction

Repaint Exterior Soffit

Quantity / UoM

Project(s) Note

Type	Number	Description	Qty UoM	Price	Extension
U	099113602400	Paints & coatings, siding, exterior, Texture 1-111 or clapboard, oil base, paint 2 coats, brushwork	2,700 SF	1.65	\$4,455
			Sub Total		\$4,455
		Const	ruction Adjustment	35%	1,537
		C	onstruction Cost		\$5,992
			Adjustment Factor	0%	0
		So	ft Cost Adjustment	46%	2,731
		Total E	stimated Amount		\$8,723



Deficiency Detail

2/4/2016 1:41 PM

290 **Tedder Elementary School** Location: Tedder ES->Bldg 14

Deficiency:

Assess ID 207572 Surveyor/Update Sherry Sims

A40-03 Defeciency Code ID

FCI Status **Estimated** Yes

Life Cycle

The Aluminum Window Is Damaged And Requires Replacement Deficiency

Capital Renewal Category System Exterior

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Non Related

Correction Replace Aluminum Frame Window Quantity / UoM

Project(s) Note 6"(L) X 3"(W)

Туре	Number	Description	Qty UoM	Price	Extension
U	062213506000	Moldings, window & door, window trim sets, 2-1/2" wide, maximum	1 OPNG	169.00	\$239
U	085113203920	Windows, aluminum, commercial grade, stock units, awning type, insulating glass, 3'-0" x 4'-0" opening, incl. frame and glazing	1 Ea.	770.00	\$1,091
U	080505200280	Window demolition, aluminum, to 50 S.F.	1 Ea.	96.50	\$137
			Sub Total		\$1,467
		Consti	ruction Adjustment	35%	506
		C	onstruction Cost		\$1,973
			Adjustment Factor	0%	0
		So	ft Cost Adjustment	46%	899
		Total E	stimated Amount		\$2,872



Deficiency Detail

2/4/2016 1:41 PM

290 **Tedder Elementary School** Tedder ES->Media Ctr

Location: Deficiency:

Assess ID 207593 Surveyor/Update Sherry Sims

Defeciency Code ID A26-01

Estimated FCI Status Yes

Life Cycle

Deficiency The Exterior Requires Painting

Capital Renewal Category System Exterior

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Paint Building Exterior Quantity / UoM

Project(s) Note

Type	Number	Description	Qty	UoM	Price	Extension
U	099123528400	Paints & coatings, miscellaneous interior, cornice, ornate design, paint 1 coat, oil base, brushwork	496	SF	1.57	\$779
U	099113601800	Paints & coatings, siding, exterior, Texture 1-111 or clapboard, oil base, primer coat, brushwork	3,360	SF	0.93	\$3,125
U	099103300080	Surface preparation, exterior, doors, per side, wire brush, metal, flush, excl. frames or trim	3,360	SF	0.79	\$2,654
			s	ub Total		\$6,558
		Con	struction Ac	ljustment	35%	2,262
			Constructi	on Cost		\$8,820
			Adjustme	nt Factor	0%	0
		5	Soft Cost Ac	ljustment	46%	4,020
		Total	Estimated	Amount	_	\$12,841



Deficiency Detail

2/4/2016 1:41 PM

290 **Tedder Elementary School** Tedder ES->Media Ctr

Location: Deficiency:

Assess ID 207594 Surveyor/Update Sherry Sims

Defeciency Code ID A42-03

Status **Estimated** FCI Yes

Life Cycle 40528

The Glass Pane Is Damaged In The Exterior Window: Deficiency

Deferred Maintenance Category System Exterior

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Reglaze Exterior Window Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty	UoM	Price	Extension
U	080505202000	Window demolition, wood, to 12 S.F., includes trim	64	Ea.	22.00	\$1,408
U	062213503270	Moldings, window & door, glass beads, stock pine, 3/8" x 7/8"	256	LF	2.78	\$712
U	088155100700	Window glass, tempered, 3/16" thick	64	SF	12.50	\$800
			s	ub Total		\$2,920
		C	Construction Ad	ljustment	35%	1,007
			Construction Cost			\$3,927
			Adjustme	nt Factor	0%	0
			Soft Cost Ad	ljustment	46%	1,790
		To	tal Estimated	Amount	_	\$5,717

Prepared by: **HEERY**

Deficiency Detail

2/4/2016 1:41 PM

290 **Tedder Elementary School** Tedder ES->Bldg 16

Location: Deficiency:

Assess ID 207612 Surveyor/Update Sherry Sims

Defeciency Code ID A31-02

Estimated FCI Status Yes

Life Cycle

The Concrete / CMU Exterior Requires Repair Deficiency

Deferred Maintenance Category System Exterior

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Repair Concrete/Cmu Units Quantity / UoM

Project(s) Note

Туре	Number	Description	Qty UoM	Price	Extension
U	042710309000	Brick walls, minimum labor/equipment charge	1,000 Job	535.00	\$535,000
			Sub Total		\$535,000
			Construction Adjustment	35%	184,575
			Construction Cost		\$719,575
			Adjustment Factor	0%	0
			Soft Cost Adjustment	42%	305,388
			Total Estimated Amount	_	\$1,024,963



Deficiency Detail

2/4/2016 1:41 PM

290 **Tedder Elementary School** Location: Tedder ES->CR

Deficiency:

Assess ID 207632 Surveyor/Update Sherry Sims

Defeciency Code ID A27-04

Estimated FCI Status Yes

Life Cycle

The Exterior Soffit Requires Repainting Deficiency

Deferred Maintenance Category System Exterior

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction **Repaint Exterior Soffit** Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
U	099113602400	Paints & coatings, siding, exterior, Texture 1-111 or clapboard, o base, paint 2 coats, brushwork	l 1,200 SF	1.65	\$1,980
			Sub Total		\$1,980
		Col	nstruction Adjustment	35%	683
			Construction Cost		\$2,663
			Adjustment Factor	0%	0
			Soft Cost Adjustment	48%	1,290
		Tota	I Estimated Amount		\$3,953

M-A-P-P-S ©, Jacobs 2016



290

Deficiency Detail

2/4/2016 1:41 PM

290 **Tedder Elementary School** Location: Tedder ES->CR

Deficiency:

Status

Assess ID 207635 Surveyor/Update

Sherry Sims

Defeciency Code ID A35-03

FCI Yes

Life Cycle 40613

Estimated

The Wood Exterior Door Is Damaged And Requires Replacement Deficiency

Category Capital Renewal System Exterior

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Non Related

Correction Replace Wood Exterior Door Quantity / UoM

Project(s) Note

Туре	Number	Description	Qty UoM	Price	Extension
U	081313131360	Doors, commercial, steel, flush, half glass, hollow core, hollow metal, 18 ga., 3'-0" x 7'-0" x 1-3/4" thick	12 Ea.	780.00	\$9,360
U	087120152250	Door hardware, school, single, exterior, incl. lever, panic device	12 Door	1,600.00	\$19,200
U	080505100200	Door demolition, exterior door, single, 3' x 7' high, 1-3/4" thick, remove	12 Ea.	30.00	\$360
			Sub Total		\$28,920
		Cor	struction Adjustment	35%	9,977
			Construction Cost		\$38,897
			Adjustment Factor	0%	0
			Soft Cost Adjustment	48%	18,846
		Tota	l Estimated Amount		\$57,743



Deficiency Detail

2/4/2016 1:41 PM

290 **Tedder Elementary School** Location: Tedder ES->CR

Deficiency:

Assess ID 207637 Surveyor/Update Sherry Sims

A40-03 Defeciency Code ID

FCI Status **Estimated** Yes

Life Cycle 40612

The Aluminum Window Is Damaged And Requires Replacement Deficiency

Capital Renewal Category System Exterior

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Non Related

Correction Replace Aluminum Frame Window Quantity / UoM

Project(s) Note 28@ 6"(L) X 3"(W)

Туре	Number	Description	Qty UoM	Price	Extension
U	062213506000	Moldings, window & door, window trim sets, 2-1/2" wide, maximum	2 OPNG	169.00	\$254
U	085113203920	Windows, aluminum, commercial grade, stock units, awning type, insulating glass, 3'-0" x 4'-0" opening, incl. frame and glazing	2 Ea.	770.00	\$1,155
U	080505200280	Window demolition, aluminum, to 50 S.F.	2 Ea.	96.50	\$145
			Sub Total		\$1,553
		Constr	uction Adjustment	35%	536
		С	onstruction Cost		\$2,089
		,	Adjustment Factor	0%	0
		Sot	t Cost Adjustment	48%	1,012
		Total E	stimated Amount		\$3,101



Deficiency Detail

2/4/2016 1:41 PM

290 **Tedder Elementary School**

Tedder ES->Admin Location: Deficiency:

Assess ID 207785

Surveyor/Update

FCI

Sherry Sims

Yes

Defeciency Code ID M60-03

Estimated

Status Life Cycle

Exhaust Fan Ventilation Requires Replacement Deficiency

Capital Renewal Category System Mechanical

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Replace Exhaust Fan Quantity / UoM

Project(s) Note 300CFM

Туре	Number	Description	Qty UoM	Price	Extension
U	230505102120	Fans, up thru 1 H.P. or 2000 CFM, selective demolition	4 Ea.	155.00	\$620
U	233423106180	Fans, propeller exhaust, wall shutter, direct drive, 1/4" S.P., two speed, 3275 CFM, 1/2 H.P.	4 Ea.	1,050.00	\$4,200
			Sub Total		\$4,820
		Cons	truction Adjustment	35%	1,663
			Construction Cost		\$6,483
			Adjustment Factor	0%	0
		S	oft Cost Adjustment	48%	3,141
		Total	Estimated Amount		\$9,624



Broward County Public Schools 290 **Tedder Elementary School**

Deficiency Detail

2/4/2016 1:41 PM

Tedder ES->Admin Location:

Deficiency:

Assess ID 207787 Surveyor/Update

FCI

Sherry Sims

Yes

Defeciency Code ID M52-01

Estimated

Status Life Cycle

Deficiency **Test And Balancing Required**

Deferred Maintenance Category

System

Mechanical

Priority

3-Short Term Conditions (2-3 Years)

Functional Adequacy

Non Related

Correction

Fix HVAC Test/Adjust/Balance

Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty	UoM	Price	Extension
U	230593101400	Balancing, air, heating and ventilating equipment, roof exhaust fan, (Subcontractor's quote including material & labor)	1	Ea.	267.00	\$265
U	230593103600	Balancing, air conditioning equipment, supply, return, exhaust, registers and diffusers, laboratory fume hood, (Subcontractor's quote including material & labor)		Ea.	400.00	\$397
U	230593104500	Balancing, taps into ceiling plenums, (Subcontractor's quote including material & labor)	5	Ea.	100.00	\$496
U	230593102400	Balancing, air conditioning equipment, central station, built-up variable volume, (Subcontractor's quote including material & labor)	0	Ea.	1,750.00	\$434
U	230593104600	Balancing, air conditioning equipment, supply, return, exhaust, registers and diffusers, variable volume boxes, (Subcontractor quote including material & labor)		Ea.	80.00	\$397
			S	ub Total		\$1,988
			Construction Ac	djustment	35%	686
			Construct	ion Cost		\$2,673
			Adjustme	nt Factor	0%	0
			Soft Cost Ad	djustment	48%	1,295
		т	otal Estimated	Amount		\$3,969

Tedder Elementary School

290

Page 56 of 620

M-A-P-P-S ©, Jacobs 2016

Deficiency Detail

Sherry Sims

2/4/2016 1:41 PM

290 **Tedder Elementary School** Tedder ES->Admin

Location: Deficiency:

Assess ID 207788

Defeciency Code ID M54-03

Status **Estimated** FCI Yes

Life Cycle 40841

Controls Are Inadequate And Should Be Replaced With DDC Controls Deficiency

Category Capital Renewal Mechanical System

Surveyor/Update

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Replace DDC HVAC Controls Quantity / UoM

Project(s) Note



Deficiency Detail

2/4/2016 1:41 PM

290 **Tedder Elementary School** Tedder ES->Admin

Location: Deficiency:

Assess ID 207789 Surveyor/Update Sherry Sims

Defeciency Code ID M59-03

Estimated FCI Status Yes

Life Cycle 40844

Ductwork Requires Replacement Deficiency

Capital Renewal Mechanical Category System

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Replace HVAC Ductwork Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
U	090505101540	Ceiling demolition, ceiling tile, wood fiber, stapled, 12" x 12", remove	220 SF	0.64	\$141
U	095123101130	Suspended acoustic ceiling tiles, mineral fiber tile, lay-in, rough texture, 2' x 2' or 2' x 4', 3/4" thick	220 SF	2.82	\$620
U	230505101590	Ductwork, spiral wound, prefabricated, selective demolition	23 LF	3.11	\$72
U	233113130570	Metal ductwork, fabricated rectangular, galvanized steel, 2000 to 5000 lb., includes fittings, joints, supports and allow for a flexible connections field sketches, excludes as-built drawings and insulation	55 Lb	7.70	\$424
			Sub Total		\$1,257
		Cons	truction Adjustment	35%	434
			Construction Cost		\$1,690
			Adjustment Factor	0%	0
		Se	oft Cost Adjustment	48%	819
		Total I	Estimated Amount		\$2,509

Tedder Elementary School



Deficiency Detail

2/4/2016 1:41 PM

290 **Tedder Elementary School** Tedder ES->Admin

Location: Deficiency:

Assess ID 207793 Surveyor/Update Sherry Sims

Defeciency Code ID BP20-01

Estimated FCI Status Yes

Life Cycle 40846

Deficiency Install Fire Sprinklers

Code Compliance Fire and Security Category System

Priority 1-Mission Critical Concerns Functional Adequacy Non Related

Correction Install Fire Sprinkler System Quantity / UoM

Project(s) Note

Туре	Number	Description	Qty UoM	Price	Extension
U	095123100400	Suspended acoustic ceiling tiles, fiberglass boards, film faced, 2' x 2' or 2' x 4' x 3/4" thick	689 SF	2.84	\$1,956
U	090505101200	Ceiling demolition, suspended ceiling, mineral fiber, 2 x 2 or 2 x 4, remove	689 SF	0.64	\$441
Α	D40104101100	Wet pipe sprinkler systems, steel, ordinary hazard, 1 floor, 50,000 SF	2,479 SF	4.02	\$9,966
			Sub Total		\$12,362
		Constr	uction Adjustment	35%	4,265
		c	onstruction Cost		\$16,627
			Adjustment Factor	0%	0
		So	ft Cost Adjustment	48%	8,056
		Total E	stimated Amount		\$24,683



Deficiency Detail

2/4/2016 1:41 PM

290 Tedder Elementary School
Location: Tedder ES->Admin

Deficiency:

Assess ID 207799 Surveyor/Update Sherry Sims

Defeciency Code ID M57-21c

Status Estimated FCI Yes

Life Cycle 40826

Deficiency Duct Heater Requires Replacement

Category Capital Renewal System Mechanical

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Learning Environment

Correction Replace Duct Heater Quantity / UoM

Project(s) Note

	ucc.				
Туре	Number	Description	Qty UoM	Price	Extension
U	238216200360	Duct heater, electric, finned tubular insert, 480 V, 3Ph., 500Deg.F, 26.7 kW, 12" wide x 24" high	1 Ea.	2,825.00	\$2,825
U	230505101850	Air conditioner, duct heater, electric strip, selective demolition, minimum labor/equipment charge	1 Job	161.00	\$161
			Sub Total		\$2,986
		Constru	uction Adjustment	35%	1,030
		Co	onstruction Cost		\$4,016
		A	Adjustment Factor	0%	0
		Sof	Cost Adjustment	48%	1,946
		Total Es	stimated Amount		\$5,962



Deficiency Detail

2/4/2016 1:41 PM

290 **Tedder Elementary School** Tedder ES->Media Ctr

Location: Deficiency:

Assess ID 207864 Surveyor/Update

M04-03 Defeciency Code ID

FCI Status **Estimated** Yes

Life Cycle 40968

The Exterior Air Handler Is Damaged And Requires Replacement Deficiency

Capital Renewal Category System Mechanical

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Non Related

Replace 10,000 CFM Exterior Air Handler Correction Quantity / UoM

Project(s) Note 7,500CFM

Estimate:

Туре	Number	Description	Qty	UoM	Price	Extension
U 230	505100400	Central station air handler, up thru 15 ton, selective demolition	1	Ea.	820.00	\$820
U 237	413103250	Air handling unit, packaged weatherproof, with cooling/heating coil section, filters, mixing box, variable air volume, single zone, 10,000 CFM, cooling coils may be chilled water or DX, heating coils may be hot water, steam or electric	1	Ea.	75,000.00	\$75,000

Sub Total		\$75,820
Construction Adjustment	35%	26,158
Construction Cost		\$101,978
Adjustment Factor	0%	0
Soft Cost Adjustment	46%	46,482
Total Estimated Amount		\$148,459

Sherry Sims



Deficiency Detail

2/4/2016 1:41 PM

Broward County Public Schools 290 **Tedder Elementary School**

Tedder ES->Media Ctr Location:

Deficiency:

Assess ID 207868 Surveyor/Update Sherry Sims

M54-03 Defeciency Code ID

FCI Status **Estimated** Yes

Life Cycle 40965

Deficiency Controls Are Inadequate And Should Be Replaced With DDC Controls

Category Capital Renewal System Mechanical

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Replace DDC HVAC Controls Quantity / UoM

Project(s) Note



Deficiency Detail

2/4/2016 1:41 PM

290 **Tedder Elementary School** Tedder ES->Media Ctr

Location: Deficiency:

Assess ID 207870 Surveyor/Update Sherry Sims

M57-02C Defeciency Code ID

FCI Status **Estimated** Yes

Life Cycle

The Air Handler HVAC Component Requires Replacement Deficiency

Category Capital Renewal System Mechanical

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Replace 5000 CFM Air Handler Correction Quantity / UoM

Project(s) Note 7,500CFM

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
U	237313202340	Central station air handling unit, packaged indoor, variable air volume, 5000 CFM, cooling colls may be chilled water or DX, heating colls may be hot water, steam or electric	1 Ea.	26,000.00	\$26,000
U	230505100400	Central station air handler, up thru 15 ton, selective demolition	1 Ea.	820.00	\$820
U	015419500100	Crane crew, daily use for small jobs, 12-ton truck-mounted hydraulic crane, portal to portal	1 Day	1,600.00	\$1,600
U	233113131030	Metal ductwork, fabricated rectangular, 500 to 1000 lb., stainless steel, type 304, includes fittings, joints, supports and allow for a flexible connections field sketches, excludes as-built drawings and insulation	250 Lb	13.40	\$3,350
U	260580101590	Motor connections, flexible conduit and fittings, 3 phase, 460 volt, 100 HP motor	1 Ea.	330.00	\$330
			Sub Total		\$32,100
		Constr	uction Adjustment	35%	11,074
		c	onstruction Cost		\$43,174
		,	Adjustment Factor	0%	0
		Sof	t Cost Adjustment	46%	19,679
		Total E	stimated Amount		\$62,853

Tedder Elementary School



Deficiency Detail

2/4/2016 1:41 PM

290 Tedder Elementary School
Location: Tedder ES->Media Ctr

Location: **Deficiency:**

Assess ID 207871 Surveyor/Update Sherry Sims

Defeciency Code ID M57-21c

Status Estimated FCI Yes

Life Cycle 40976

Deficiency Duct Heater Requires Replacement

Category Capital Renewal System Mechanical

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Learning Environment

Correction Replace Duct Heater Quantity / UoM

Project(s) Note

Number	Description	Qty UoM	Price	Extension
238216200360	Duct heater, electric, finned tubular insert, 480 V, 3Ph., 500Deg.F, 26.7 kW, 12" wide x 24" high	1 Ea.	2,825.00	\$2,825
230505101850	Air conditioner, duct heater, electric strip, selective demolition, minimum labor/equipment charge	1 Job	161.00	\$161
		Sub Total		\$2,986
	Constru	uction Adjustment	35%	1,030
	Co	nstruction Cost		\$4,016
	A	djustment Factor	0%	0
	Soft	Cost Adjustment	46%	1,831
	Total Es	timated Amount		\$5,847
	238216200360	238216200360 Duct heater, electric, finned tubular insert, 480 V, 3Ph., 500Deg.F, 26.7 kW, 12" wide x 24" high 230505101850 Air conditioner, duct heater, electric strip, selective demolition, minimum labor/equipment charge Constru	238216200360 Duct heater, electric, finned tubular insert, 480 V, 3Ph., 500Deg.F, 26.7 kW, 12" wide x 24" high 230505101850 Air conditioner, duct heater, electric strip, selective demolition, 1 Job minimum labor/equipment charge	238216200360 Duct heater, electric, finned tubular insert, 480 V, 3Ph., 500Deg.F, 26.7 kW, 12" wide x 24" high 230505101850 Air conditioner, duct heater, electric strip, selective demolition, 1 Job 161.00 minimum labor/equipment charge Sub Total Construction Adjustment 35% Construction Cost Adjustment Factor 0% Soft Cost Adjustment 46%



Deficiency Detail

2/4/2016 1:41 PM

290 **Tedder Elementary School** Tedder ES->Media Ctr Location:

Deficiency:

Assess ID 207876 Surveyor/Update Sherry Sims

Defeciency Code ID BP20-01

Estimated FCI Status Yes

Life Cycle

Deficiency Install Fire Sprinklers

Fire and Security Category **Code Compliance** System

Priority 1-Mission Critical Concerns Functional Adequacy Non Related

Correction Install Fire Sprinkler System Quantity / UoM

Project(s) Note Install

Туре	Number	Description	Qty	UoM	Price	Extension
U	095123100400	Suspended acoustic ceiling tiles, fiberglass boards, film faced, 2' x 2' or 2' x 4' x 3/4" thick	1,616	SF	2.84	\$4,591
U	090505101200	Ceiling demolition, suspended ceiling, mineral fiber, 2 x 2 or 2 x 4, remove	1,616	SF	0.64	\$1,034
Α	D40104101100	Wet pipe sprinkler systems, steel, ordinary hazard, 1 floor, $50,000$ SF	5,819	SF	4.02	\$23,392
			Sı	ub Total		\$29,017
		Const	truction Adj	justment	35%	10,011
			Constructi	on Cost		\$39,028
			Adjustmer	nt Factor	0%	0
		Sc	oft Cost Adj	justment	46%	17,789
		Total E	Estimated	Amount		\$56,818



Deficiency Detail

2/4/2016 1:41 PM

290 Tedder Elementary School
Location: Tedder ES->CR

Deficiency:

Assess ID 207908 Surveyor/Update Sherry Sims

Defeciency Code ID M29-03

Status Estimated FCI Yes

Life Cycle

Deficiency Package Roof Top Unit Requires Replacement

Category Capital Renewal System Mechanical

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Replace 5 Ton Packaged RTU Quantity / UoM

Project(s) Note 10TonAC

Estimate:

Estim	ate:				
Туре	Number	Description	Qty UoM	Price	Extension
U	230505105100	Rooftop air conditioner, up thru 10 ton, selective demolition	1 Ea.	940.00	\$940
U	260580101500	Motor connections, flexible conduit and fittings, 3 phase, 460 volt, 5 HP motor	1 Ea.	91.00	\$91
U	015436502200	Mobilization or demobilization, crane, crawler-mounted, up to 75 ton	1 Ea.	1,125.00	\$1,125
U	237433101140	Rooftop air conditioner, single zone, electric cool, gas heat, 5 ton cooling, 112 MBH heating, includes, standard controls, curb and economizer	1 Ea.	8,150.00	\$8,150
			Sub Tota		\$10,306
		Constr	uction Adjustmen	t 35%	3,556
		c	onstruction Cost	t	\$13,862
		,	Adjustment Factor	0%	0
		So	ft Cost Adjustmen	t 48%	6,716

Total Estimated Amount

\$20,578



Deficiency Detail

2/4/2016 1:41 PM

Location: Tedder ES->CR

Deficiency:

290

Assess ID 207909 Surveyor/Update Sherry Sims

M60-03 Defeciency Code ID

FCI Status **Estimated** Yes

Life Cycle 40995

Exhaust Fan Ventilation Requires Replacement Deficiency

Tedder Elementary School

Capital Renewal Category System Mechanical

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Replace Exhaust Fan Quantity / UoM

Project(s) Note 500CFM

Qty UoM	Price	Extension
1 Ea.	155.00	\$155
two 1 Ea.	1,050.00	\$1,050
Sub Total		\$1,205
Construction Adjustment	35%	416
Construction Cost		\$1,621
Adjustment Factor	0%	0
Soft Cost Adjustment	48%	785
Total Estimated Amount		\$2,406
	Sub Total Construction Adjustment Construction Cost Adjustment Factor	1 Ea. 155.00 two 1 Ea. 1,050.00 Sub Total Construction Adjustment 35% Construction Cost Adjustment Factor 0% Soft Cost Adjustment 48%



Broward County Public Schools 290 **Tedder Elementary School**

Deficiency Detail

2/4/2016 1:41 PM

Location: Tedder ES->CR

Deficiency:

Assess ID 207911 Surveyor/Update

FCI

Sherry Sims

M53-01 Defeciency Code ID

Yes

Status Life Cycle

Deficiency Make-Up Air Should Be Increased

Estimated

Functional Deficiency Category System Mechanical

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Increase Make-Up Air Capacity Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
М	260533050700	Aluminum conduit, 1" diameter, to 15' H, incl 2 terminations, 2 elbows & 11 beam clamps per 100 LF	78 LF	9.71	\$760
U	260580102025	Motor connections, flexible conduit and fittings, 3 phase, sealtite, 460 volt, 40 HP motor	1 Ea.	180.00	\$188
U	050505100270	Selective metals demolition, structural framing members, 10 - 15 tons, remove whole or cut up into smaller pieces, incl loading, excl shoring, bracing, cutting, hauling, dumping	1 Ea.	370.00	\$193
U	233113130570	Metal ductwork, fabricated rectangular, galvanized steel, 2000 to 5000 lb., includes fittings, joints, supports and allow for a flexible connections field sketches, excludes as-built drawings and insulation	48 Lb	7.70	\$372
U	237339100100	Make-up air unit, indoor suspension, natural/LP gas, direct fired, MBH is input, 70Deg.F temperature rise, 75 MBH, includes standard controls	1 Ea.	5,975.00	\$3,119
			Sub Total		\$4,632
		Cons	truction Adjustment	35%	1,598
			Construction Cost		\$6,231
			Adjustment Factor	0%	0
		s	oft Cost Adjustment	48%	3,019
		Total	Estimated Amount	_	\$9,249

Tedder Elementary School



Deficiency Detail

2/4/2016 1:41 PM

Location: Tedder ES->CR

Deficiency:

290

Assess ID 207912 Surveyor/Update Sherry Sims

M58-01 Defeciency Code ID

FCI Status **Estimated** Yes

Life Cycle

Deficiency Kitchen Air/Exhaust is missing and is needed

Tedder Elementary School

Functional Deficiency Category System Mechanical

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Non Related

Install Kitchen Air/Exhaust Hood Correction Quantity / UoM

Project(s) Note

Estimate:

LStilli	ate.					
Type	Number	Description	Qty	UoM	Price	Extension
М	015433602400	Rent crane truck mounted, hydraulic, 12 ton capacity	1	Day	595.62	\$298
U	260580102045	Motor connections, flexible conduit and fittings, 3 phase, sealtite, 460 volt, 100 HP motor	2	Ea.	370.00	\$740
U	237423161060	Make-up air unit, indirect-fired, rooftop unit, natural gas, gravity vent, stainless steel exchanger, MBH is output, 70Deg.F temperature rise, 550 MBH, includes standard controls	1	Ea.	20,000.00	\$20,000
U	233813102980	Exhaust hood, commercial kitchen equipment, stainless steel, gutter on all sides, 4' x 4' x 7'	1	Ea.	8,550.00	\$8,550
			S	ub Total		\$29,588
		Cor	struction Ac	ljustment	35%	10,208
			Construct	ion Cost		\$39,796
			Adjustme	nt Factor	0%	0
			Soft Cost Ad	ljustment	48%	19,281
		Tota	l Estimated	Amount		\$59,077

Tedder Elementary School



Broward County Public Schools 290 Tedder Elementary School

Deficiency Detail

Sherry Sims

2/4/2016 1:41 PM

Location: Tedder ES->CR

Deficiency:

Assess ID 207913 Surveyor/Update

Defeciency Code ID M52-01

Status Estimated FCI Yes

Life Cycle

Deficiency Test And Balancing Required

Category Deferred Maintenance System Mechanical

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Fix HVAC Test/Adjust/Balance Quantity / UoM

Project(s) Note

Estimate:

U 230593101400 Balancing, air, heating and ventilating equipment, roof exhaust fan, (Subcontractor's quote including material & labor) U 230593103600 Balancing, air conditioning equipment, supply, return, exhaust, registers and diffusers, laboratory fume hood, (Subcontractor's quote including material & labor) U 230593104500 Balancing, taps into ceiling plenums, (Subcontractor's quote including material & labor) U 230593102400 Balancing, air conditioning equipment, central station, built-up variable volume, (Subcontractor's quote including material & labor) U 230593104600 Balancing, air conditioning equipment, supply, return, exhaust, registers and diffusers, variable volume boxes, (Subcontractor's quote including material & labor) Sub Total Construction Adjustment 35%	LStill	iate.				
fan, (Subcontractor's quote including material & labor) U 230593103600 Balancing, air conditioning equipment, supply, return, exhaust, registers and diffusers, laboratory fume hood, (Subcontractor's quote including material & labor) U 230593104500 Balancing, taps into ceiling plenums, (Subcontractor's quote including material & labor) U 230593102400 Balancing, air conditioning equipment, central station, built-up variable volume, (Subcontractor's quote including material & labor) U 230593104600 Balancing, air conditioning equipment, supply, return, exhaust, registers and diffusers, variable volume boxes, (Subcontractor's quote including material & labor) Sub Total Construction Adjustment 35%	Туре	Number	Description	Qty UoM	Price	Extension
registers and diffusers, laboratory fume hood, (Subcontractor's quote including material & labor) U 230593104500 Balancing, taps into ceiling plenums, (Subcontractor's quote including material & labor) U 230593102400 Balancing, air conditioning equipment, central station, built-up variable volume, (Subcontractor's quote including material & labor) U 230593104600 Balancing, air conditioning equipment, supply, return, exhaust, registers and diffusers, variable volume boxes, (Subcontractor's quote including material & labor) Sub Total Construction Adjustment 35%	U	230593101400		2 Ea.	267.00	\$516
including material & labor) U 230593102400 Balancing, air conditioning equipment, central station, built-up variable volume, (Subcontractor's quote including material & labor) U 230593104600 Balancing, air conditioning equipment, supply, return, exhaust, registers and diffusers, variable volume boxes, (Subcontractor's quote including material & labor) Sub Total Construction Adjustment 35%	U	230593103600	registers and diffusers, laboratory fume hood, (Subcontractor's	2 Ea.	400.00	\$773
variable volume, (Subcontractor's quote including material & labor) U 230593104600 Balancing, air conditioning equipment, supply, return, exhaust, registers and diffusers, variable volume boxes, (Subcontractor's quote including material & labor) Sub Total Construction Adjustment 35% Construction Cost	U	230593104500		10 Ea.	100.00	\$966
registers and diffusers, variable volume boxes, (Subcontractor's quote including material & labor) Sub Total Construction Adjustment 35% Construction Cost	U	230593102400	variable volume, (Subcontractor's quote including material &	0 Ea.	1,750.00	\$845
Construction Adjustment 35% Construction Cost	U	230593104600	registers and diffusers, variable volume boxes, (Subcontractor's	10 Ea.	80.00	\$773
Construction Cost S				Sub Total		\$3,872
			Co	nstruction Adjustment	35%	1,336
Adjustment Factor 0%				Construction Cost		\$5,208
				Adjustment Factor	0%	0
Soft Cost Adjustment 48%				Soft Cost Adjustment	48%	2,523
Total Estimated Amount			Tota	al Estimated Amount		\$7,731

Tedder Elementary School

290

Page 59 of 620

M-A-P-P-S ©, Jacobs 2016

Deficiency Detail

2/4/2016 1:41 PM

290 **Tedder Elementary School**

Location: Tedder ES->CR

Deficiency:

Assess ID 207914 Surveyor/Update Sherry Sims

M54-03 Defeciency Code ID

FCI Status **Estimated** Yes

Life Cycle 41003

Controls Are Inadequate And Should Be Replaced With DDC Controls Deficiency

Category Capital Renewal System Mechanical

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Replace DDC HVAC Controls Quantity / UoM

Project(s) Note



Deficiency Detail

2/4/2016 1:41 PM

Location: Tedder ES->CR

Deficiency:

290

Assess ID 207915 Surveyor/Update

Sherry Sims

M59-03 Defeciency Code ID

Estimated

Life Cycle

41004

FCI

Yes

Deficiency

Status

Ductwork Requires Replacement

Category

Capital Renewal

Tedder Elementary School

System

Mechanical

Priority

3-Short Term Conditions (2-3 Years)

Functional Adequacy

Non Related

Correction

Replace HVAC Ductwork

Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
U	090505101540	Ceiling demolition, ceiling tile, wood fiber, stapled, 12" x 12", remove	600 SF	0.64	\$384
U	095123101130	Suspended acoustic ceiling tiles, mineral fiber tile, lay-in, rough texture, 2' x 2' or 2' x 4', 3/4" thick	600 SF	2.82	\$1,692
U	230505101590	Ductwork, spiral wound, prefabricated, selective demolition	63 LF	3.11	\$196
U	233113130570	Metal ductwork, fabricated rectangular, galvanized steel, 2000 to 5000 lb., includes fittings, joints, supports and allow for a flexible connections field sketches, excludes as-built drawings and insulation	150 Lb	7.70	\$1,155
			Sub Total		\$3,427
		Con	struction Adjustment	35%	1,182
			Construction Cost		\$4,610
			Adjustment Factor	0%	0
		8	Soft Cost Adjustment	48%	2,233
		Total	Estimated Amount		\$6,843

Tedder Elementary School

290

Page 520 of 620

Prepared by: **HEERY**

Deficiency Detail

2/4/2016 1:41 PM

290 **Tedder Elementary School** Location: Tedder ES->CR

Deficiency:

Assess ID 207919 Surveyor/Update Sherry Sims

Defeciency Code ID M57-01C

FCI Status **Estimated** Yes

Life Cycle 40997

Deficiency The Package Unit HVAC Component Requires Replacement

Capital Renewal Category System Mechanical

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Replace packaged HVAC Unit Quantity / UoM

Project(s) Note 10TonAC

Estimato:

Туре	Number	Description	Qty UoM	Price	Extension
М	015433602500	Rent crane truck mounted, hydraulic, 25 ton capacity	0 Day	615.31	\$18
М	D30502011010	A/C packaged, DX, air cooled, electric heat, constant volume, 5 ton	0 Ea.	9,822.62	\$982
U	233723104250	Ventilator, stationary mushroom, aluminum, 42" orifice diameter, includes base	0 Ea.	2,950.00	\$295
U	230505109000	HVAC, selective demolition, minimum labor/equipment charge	0 Job	680.00	\$78
			Sub Total		\$1,373
		Constr	uction Adjustment	35%	474
		C	onstruction Cost		\$1,846
		,	Adjustment Factor	0%	0
		Sof	t Cost Adjustment	48%	894
		Total E	stimated Amount		\$2,741



Deficiency Detail

2/4/2016 1:41 PM

290 Tedder Elementary School
Location: Tedder ES->CR

Deficiency:

Assess ID 207927 Surveyor/Update Sherry Sims

Defeciency Code ID BP20-01

Status Estimated FCI Yes

Life Cycle 41005

Deficiency Install Fire Sprinklers

Category Code Compliance System Fire and Security

Priority 1-Mission Critical Concerns Functional Adequacy Non Related

Correction Install Fire Sprinkler System Quantity / UoM

Project(s) Note Install

Туре	Number	Description	Qty UoM	Price	Extension
U	095123100400	Suspended acoustic ceiling tiles, fiberglass boards, film faced, 2' x 2' or 2' x 4' x 3/4" thick	1,341 SF	2.84	\$3,810
U	090505101200	Ceiling demolition, suspended ceiling, mineral fiber, 2 x 2 or 2 x 4, remove	1,341 SF	0.64	\$858
Α	D40104101100	Wet pipe sprinkler systems, steel, ordinary hazard, 1 floor, 50,000 SF	4,829 SF	4.02	\$19,413
			Sub Total		\$24,081
		Constr	uction Adjustment	35%	8,308
		c	onstruction Cost		\$32,388
			Adjustment Factor	0%	0
		Sof	t Cost Adjustment	48%	15,692
		Total E	stimated Amount		\$48,081



Tedder ES->CR

Deficiency Detail

2/4/2016 1:41 PM

290 **Tedder Elementary School**

Location: Deficiency:

Assess ID 207942 Surveyor/Update

Sherry Sims

Defeciency Code ID M100-03E Status

Estimated

Yes

Life Cycle

Category

40994

Electric Unit Heater Requires Replacement Deficiency

Capital Renewal

System

FCI

Mechanical

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy

Non Related

Correction

Replace 10 KW Electric Unit Heater

Quantity / UoM

Project(s) Note

Type	Number	Description	Qty UoM	Price	Extension
U	238333106080	Electric heating, unit heater, heavy duty, 480 volt, 10 kW, includes fan & mounting bracket	1 Ea.	1,100.00	\$1,100
U	230505102750	Heater, electric, unit, cabinet, fan or convector, selective demolition	1 Ea.	82.50	\$83
			Sub Total		\$1,183
		Constru	uction Adjustment	35%	408
		Co	onstruction Cost		\$1,590
		A	Adjustment Factor	0%	0
		Soft	t Cost Adjustment	48%	771
		Total Es	stimated Amount		\$2,361



Broward County Public Schools 290 **Tedder Elementary School**

Deficiency Detail

Sherry Sims

Yes

2/4/2016 1:41 PM

Location: Tedder ES->Music

Deficiency:

Assess ID 207946

Defeciency Code ID M52-01

Status **Estimated**

Life Cycle

Deficiency **Test And Balancing Required**

Deferred Maintenance Category System Mechanical

Surveyor/Update

FCI

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Fix HVAC Test/Adjust/Balance Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty	UoM	Price	Extension
U	230593101400	Balancing, air, heating and ventilating equipment, roof exhaust fan, (Subcontractor's quote including material & labor)	2	Ea.	267.00	\$468
U	230593103600	Balancing, air conditioning equipment, supply, return, exhaust, registers and diffusers, laboratory fume hood, (Subcontractor's quote including material & labor)		Ea.	400.00	\$702
U	230593104500	Balancing, taps into ceiling plenums, (Subcontractor's quote including material & labor)	9	Ea.	100.00	\$877
U	230593102400	Balancing, air conditioning equipment, central station, built-up variable volume, (Subcontractor's quote including material & labor)	0	Ea.	1,750.00	\$768
U	230593104600	Balancing, air conditioning equipment, supply, return, exhaust, registers and diffusers, variable volume boxes, (Subcontractor quote including material & labor)		Ea.	80.00	\$702
			s	ub Total		\$3,517
		C	Construction Ad	ljustment	35%	1,213
			Constructi	on Cost		\$4,730
			Adjustme	nt Factor	0%	0
			Soft Cost Ad	justment	46%	2,156
		То	otal Estimated	Amount	:	\$6,886

Tedder Elementary School



Deficiency Detail

2/4/2016 1:41 PM

290 **Tedder Elementary School**

Location: Tedder ES->Music

Deficiency:

Assess ID 207947 Surveyor/Update Sherry Sims

Defeciency Code ID M54-03

Status **Estimated** FCI Yes

Life Cycle 41025

Controls Are Inadequate And Should Be Replaced With DDC Controls Deficiency

Category Capital Renewal Mechanical System

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Replace DDC HVAC Controls Quantity / UoM

Project(s) Note



Deficiency Detail

2/4/2016 1:41 PM

Location: Tedder ES->Music

Deficiency:

290

Assess ID 207948 Surveyor/Update

Sherry Sims

Defeciency Code ID M59-03

Estimated FCI Status Yes

Life Cycle 41027

Ductwork Requires Replacement Deficiency

Tedder Elementary School

Capital Renewal Mechanical Category System

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Replace HVAC Ductwork Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty UoM	Price	Extension
U	090505101540	Ceiling demolition, ceiling tile, wood fiber, stapled, 12" x 12", remove	440 SF	0.64	\$282
U	095123101130	Suspended acoustic ceiling tiles, mineral fiber tile, lay-in, rough texture, 2' x 2' or 2' x 4', 3/4" thick	440 SF	2.82	\$1,241
U	230505101590	Ductwork, spiral wound, prefabricated, selective demolition	46 LF	3.11	\$144
U	233113130570	Metal ductwork, fabricated rectangular, galvanized steel, 2000 to 5000 lb., includes fittings, joints, supports and allow for a flexible connections field sketches, excludes as-built drawings and insulation	110 Lb	7.70	\$847
			Sub Total		\$2,513
		Const	ruction Adjustment	35%	867
		C	Construction Cost		\$3,381
			Adjustment Factor	0%	0
		Sc	oft Cost Adjustment	46%	1,541
		Total E	stimated Amount		\$4,921

Tedder Elementary School

290

Page 521 of 620



Deficiency Detail

2/4/2016 1:41 PM

290 **Tedder Elementary School** Location: Tedder ES->Music

Deficiency:

Assess ID 207949 Surveyor/Update Sherry Sims

Defeciency Code ID M57-02C

FCI Status **Estimated** Yes

Life Cycle 41017

Deficiency The Air Handler HVAC Component Requires Replacement

Capital Renewal Category System Mechanical

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Replace 5000 CFM Air Handler Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
U	237313202340	Central station air handling unit, packaged indoor, variable air volume, 5000 CFM, cooling coils may be chilled water or DX, heating coils may be hot water, steam or electric	3 Ea.	26,000.00	\$78,000
U	230505100400	Central station air handler, up thru 15 ton, selective demolition	3 Ea.	820.00	\$2,460
U	015419500100	Crane crew, daily use for small jobs, 12-ton truck-mounted hydraulic crane, portal to portal	3 Day	1,600.00	\$4,800
U	233113131030	Metal ductwork, fabricated rectangular, 500 to 1000 lb., stainless steel, type 304, includes fittings, joints, supports and allow for a flexible connections field sketches, excludes as-built drawings and insulation	750 Lb	13.40	\$10,050
U	260580101590	Motor connections, flexible conduit and fittings, 3 phase, 460 volt, 100 HP motor	3 Ea.	330.00	\$990
			Sub Total		\$96,300
		Constr	uction Adjustment	35%	33,223
		c	onstruction Cost		\$129,523
		,	Adjustment Factor	0%	0
		Sot	ft Cost Adjustment	46%	59,037
		Total E	stimated Amount		\$188,560

Tedder Elementary School



Deficiency Detail

2/4/2016 1:41 PM

290 **Tedder Elementary School** Tedder ES->Music

Location: Deficiency:

Assess ID 207950

Defeciency Code ID M57-21c

Surveyor/Update

Sherry Sims

Status **Estimated** FCI Yes

Life Cycle

41016

Duct Heater Requires Replacement Deficiency

Capital Renewal Category System Mechanical

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Learning Environment

Correction Replace Duct Heater Quantity / UoM

Project(s) Note

	ucc.				
Туре	Number	Description	Qty UoM	Price	Extension
U	238216200360	Duct heater, electric, finned tubular insert, 480 V, 3Ph., 500Deg.F, 26.7 kW, 12" wide x 24" high	3 Ea.	2,825.00	\$8,475
U	230505101850	Air conditioner, duct heater, electric strip, selective demolition, minimum labor/equipment charge	3 Job	161.00	\$483
			Sub Total		\$8,958
		Constru	uction Adjustment	35%	3,091
		Co	onstruction Cost		\$12,049
		A	Adjustment Factor	0%	0
		Soft	Cost Adjustment	46%	5,492
		Total Es	stimated Amount		\$17,540



Deficiency Detail

Sherry Sims

2/4/2016 1:41 PM

Tedder Elementary School Location: Tedder ES->Music

Deficiency:

290

Assess ID 207953 Surveyor/Update

Defeciency Code ID BP20-01

Estimated FCI Status Yes

Life Cycle 41028

Deficiency Install Fire Sprinklers

Code Compliance Fire and Security Category System

Priority 1-Mission Critical Concerns Functional Adequacy Non Related

Correction Install Fire Sprinkler System Quantity / UoM

Project(s) Note

Estimate:

⊏Sum	ate:				
Type	Number	Description	Qty UoM	Price	Extension
U	095123100400	Suspended acoustic ceiling tiles, fiberglass boards, film faced, 2' x 2' or 2' x 4' x 3/4" thick	1,218 SF	2.84	\$3,460
U	090505101200	Ceiling demolition, suspended ceiling, mineral fiber, 2 x 2 or 2 x 4, remove	1,218 SF	0.64	\$780
Α	D40104101100	Wet pipe sprinkler systems, steel, ordinary hazard, 1 floor, 50,000 SF	4,386 SF	4.02	\$17,632
			Sub Total		\$21,872
		Consti	ruction Adjustment	35%	7,546
		c	onstruction Cost		\$29,417
			Adjustment Factor	0%	0
		So	ft Cost Adjustment	46%	13,408
		Total E	stimated Amount		\$42,826

Tedder Elementary School



Tedder Elementary School

Deficiency Detail

2/4/2016 1:41 PM

Location: Tedder ES->Bldg 14

Deficiency:

290

Assess ID 207954 Surveyor/Update Sherry Sims

Defeciency Code ID M04-03

Status Estimated FCI Yes

Life Cycle

Deficiency The Exterior Air Handler Is Damaged And Requires Replacement

Category Capital Renewal System Mechanical

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Non Related

Correction Replace 10,000 CFM Exterior Air Handler Quantity / UoM

Project(s) Note 10,000CFM

Туре	Number	Description	Qty UoM	Price	Extension
U	230505100400	Central station air handler, up thru 15 ton, selective demolition	2 Ea.	820.00	\$1,640
U	237413103250	Air handling unit, packaged weatherproof, with cooling/heating coil section, filters, mixing box, variable air volume, single zone, 10,000 CFM, cooling coils may be chilled water or DX, heating coils may be hot water, steam or electric	2 Ea.	75,000.00	\$150,000
			Sub Tota	l	\$151,640

Sub Total		\$151,640
Construction Adjustment	35%	52,316
Construction Cost		\$203,956
Adjustment Factor	0%	0
Soft Cost Adjustment	46%	92,963
Total Estimated Amount	_	\$296,919



Deficiency Detail

2/4/2016 1:41 PM

Location: Tedder ES->Bldg 14

Deficiency:

290

Assess ID 207956

Tedder Elementary School

Surveyor/Update Sherry Sims

M52-01 Defeciency Code ID

FCI Status **Estimated** Yes

Life Cycle

Deficiency **Test And Balancing Required**

Deferred Maintenance Category System Mechanical

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Fix HVAC Test/Adjust/Balance Quantity / UoM

Project(s) Note

Estimate:

LStilli	aie.				
Type	Number	Description	Qty UoM	Price	Extension
U	230593101400	Balancing, air, heating and ventilating equipment, roof exhaust fan, (Subcontractor's quote including material & labor)	3 Ea.	267.00	\$801
U	230593103600	Balancing, air conditioning equipment, supply, return, exhaust, registers and diffusers, laboratory fume hood, (Subcontractor's quote including material & labor)		400.00	\$1,200
U	230593104500	Balancing, taps into ceiling plenums, (Subcontractor's quote including material & labor)	15 Ea.	100.00	\$1,501
U	230593102400	Balancing, air conditioning equipment, central station, built-up variable volume, (Subcontractor's quote including material & labor)	1 Ea.	1,750.00	\$1,313
U	230593104600	Balancing, air conditioning equipment, supply, return, exhaust, registers and diffusers, variable volume boxes, (Subcontractor's quote including material & labor)	15 Ea.	80.00	\$1,200
			Sub Total		\$6,016
		Co	nstruction Adjustment	35%	2,075
			Construction Cost		\$8,091
			Adjustment Factor	0%	0
			Soft Cost Adjustment	46%	3,688
		Tota	al Estimated Amount		\$11,779

Tedder Elementary School



Deficiency Detail

2/4/2016 1:41 PM

290 **Tedder Elementary School** Tedder ES->Bldg 14

Location: Deficiency:

Assess ID 207957 Surveyor/Update Sherry Sims

Defeciency Code ID M54-03

Status **Estimated** FCI Yes

Life Cycle 41011

Controls Are Inadequate And Should Be Replaced With DDC Controls Deficiency

Category Capital Renewal Mechanical System

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Replace DDC HVAC Controls Quantity / UoM

Project(s) Note



Tedder Elementary School

Deficiency Detail

2/4/2016 1:41 PM

Location: Tedder ES->Bldg 14

Deficiency:

290

Assess ID 207958 Surveyor/Update Sherry Sims

M57-02C Defeciency Code ID

FCI Status **Estimated** Yes

Life Cycle 41013

The Air Handler HVAC Component Requires Replacement Deficiency

Capital Renewal Category System Mechanical

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Replace 5000 CFM Air Handler Quantity / UoM

Project(s) Note 10,000CFM

Estimate:

LStilli	ate.				
Type	Number	Description	Qty UoM	Price	Extension
U	237313202340	Central station air handling unit, packaged indoor, variable air volume, 5000 CFM, cooling coils may be chilled water or DX, heating coils may be hot water, steam or electric	2 Ea.	26,000.00	\$52,000
U	230505100400	Central station air handler, up thru 15 ton, selective demolition	2 Ea.	820.00	\$1,640
U	015419500100	Crane crew, daily use for small jobs, 12-ton truck-mounted hydraulic crane, portal to portal	2 Day	1,600.00	\$3,200
U	233113131030	Metal ductwork, fabricated rectangular, 500 to 1000 lb., stainless steel, type 304, includes fittings, joints, supports and allow for a flexible connections field sketches, excludes as-built drawings and insulation	500 Lb	13.40	\$6,700
U	260580101590	Motor connections, flexible conduit and fittings, 3 phase, 460 volt, 100 HP motor	2 Ea.	330.00	\$660
			Sub Total		\$64,200
		Const	ruction Adjustment	35%	22,149
		C	Construction Cost		\$86,349
			Adjustment Factor	0%	0
		Sc	oft Cost Adjustment	46%	39,358
		Total E	stimated Amount		\$125,707

Tedder Elementary School



Deficiency Detail

Sherry Sims

2/4/2016 1:41 PM

Location: Tedder ES->Bldg 14

Deficiency:

290

Assess ID 207959 Surveyor/Update

Defeciency Code ID M57-21c

Status Estimated FCI Yes

Life Cycle 41014

Deficiency Duct Heater Requires Replacement

Tedder Elementary School

Category Capital Renewal System Mechanical

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Learning Environment

Correction Replace Duct Heater Quantity / UoM

Project(s) Note

Number	Description	Qty UoM	Price	Extension
238216200360	Duct heater, electric, finned tubular insert, 480 V, 3Ph., 500Deg.F, 26.7 kW, 12" wide x 24" high	2 Ea.	2,825.00	\$5,650
230505101850	Air conditioner, duct heater, electric strip, selective demolition, minimum labor/equipment charge	2 Job	161.00	\$322
		Sub Total		\$5,972
Construction Adjustment		35%	2,060	
	Construction Cost			\$8,032
Adjustment Factor Soft Cost Adjustment Total Estimated Amount		0%	0	
		46%	3,661	
		imated Amount		\$11,693
	238216200360	238216200360 Duct heater, electric, finned tubular insert, 480 V, 3Ph., 500Deg.F, 26.7 kW, 12" wide x 24" high 230505101850 Air conditioner, duct heater, electric strip, selective demolition, minimum labor/equipment charge Constru	238216200360 Duct heater, electric, finned tubular insert, 480 V, 3Ph., 500Deg.F, 2 Ea. 26.7 kW, 12" wide x 24" high 230505101850 Air conditioner, duct heater, electric strip, selective demolition, 2 Job minimum labor/equipment charge Sub Total Construction Adjustment Construction Cost Adjustment Factor Soft Cost Adjustment	238216200360 Duct heater, electric, finned tubular insert, 480 V, 3Ph., 500Deg.F, 2 Ea. 2,825.00 26.7 kW, 12" wide x 24" high 230505101850 Air conditioner, duct heater, electric strip, selective demolition, 2 Job 161.00 minimum labor/equipment charge Sub Total Construction Adjustment 35% Construction Cost Adjustment Factor 0% Soft Cost Adjustment 46%



Tedder Elementary School

Deficiency Detail

2/4/2016 1:41 PM

Location: Tedder ES->Bldg 14

Deficiency:

290

Assess ID 207964 Surveyor/Update Sherry Sims

BP20-01 Defeciency Code ID

Estimated FCI Status Yes

Life Cycle

Deficiency Install Fire Sprinklers

Code Compliance Fire and Security Category System

Priority 1-Mission Critical Concerns Functional Adequacy Non Related

Correction Install Fire Sprinkler System Quantity / UoM

Project(s) Note

Type	Number	Description	Qty	UoM	Price	Extension
U	095123100400	Suspended acoustic ceiling tiles, fiberglass boards, film faced, 2' x 2' or 2' x 4' x 3/4" thick	2,084	SF	2.84	\$5,919
U	090505101200	Ceiling demolition, suspended ceiling, mineral fiber, 2 x 2 or 2 x 4, remove	2,084	SF	0.64	\$1,334
Α	D40104101100	Wet pipe sprinkler systems, steel, ordinary hazard, 1 floor, 50,000 SF	7,503	SF	4.02	\$30,162
			Sı	ub Total		\$37,415
		Consti	ruction Adj	ustment	35%	12,908
		Construction Cost			\$50,323	
	Adjustment Factor		0%	0		
		So	ft Cost Adj	ustment	46%	22,937
		Total E	stimated	Amount		\$73,260



Deficiency Detail

2/4/2016 1:41 PM

290 **Tedder Elementary School** Tedder ES->Admin

Location: Deficiency:

Assess ID 208116

Surveyor/Update

Eric Sheppard

Defeciency Code ID BCRoof-02

Status

Estimated

FCI Yes

Life Cycle

Deficiency

Reroofing with new Decking Required (Broward CPS)

Category

Capital Renewal

System

Roofing

Priority

1-Mission Critical Concerns Reroof and Replace Decking Functional Adequacy

Quantity / UoM

Non Related

Correction

Project(s) Note

Est	imate:
_	

Type	Number	Description	Qty UoM	Price	Extension
М		Estimate based of BCPS experience	4,574 SF	7.25	\$33,162
			Sub Total		\$33,162
			Construction Adjustment	35%	11,441
			Construction Cost		\$44,602
			Adjustment Factor	0%	0
			Soft Cost Adjustment	48%	21,610
			Total Estimated Amount	_	\$66,212

Prepared by: **HEERY**

Deficiency Detail

2/4/2016 1:41 PM

290 **Tedder Elementary School** Location: Tedder ES->Bldg 9

Deficiency:

Assess ID 208117 Surveyor/Update

BCRoof-02 Defeciency Code ID

Estimated FCI Status Yes

Life Cycle

Reroofing with new Decking Required (Broward CPS) Deficiency

Capital Renewal Roofing Category System

1-Mission Critical Concerns Priority Functional Adequacy Non Related

Correction Reroof and Replace Decking Quantity / UoM

Project(s) Note

Туре	Number	Description	Qty UoM	Price	Extension
М		Estimate based of BCPS experience	20,488 SF	7.25	\$148,538
			Sub Total		\$148,538
			Construction Adjustment	35%	51,246
			Construction Cost		\$199,784
			Adjustment Factor	0%	0
			Soft Cost Adjustment	42%	84,788
			Total Estimated Amount		\$284,572



Deficiency Detail

2/4/2016 1:41 PM

290 **Tedder Elementary School** Tedder ES->Music

Location: Deficiency:

Assess ID 208118

Defeciency Code ID BCRoof-02

Estimated FCI Status Yes

Life Cycle

Reroofing with new Decking Required (Broward CPS) Deficiency

Capital Renewal Roofing Category System

1-Mission Critical Concerns Priority Functional Adequacy Non Related

Correction Reroof and Replace Decking Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
M		Estimate based of BCPS experience	4,177 SF	7.25	\$30,283
			Sub Total		\$30,283
			Construction Adjustment	35%	10,448
			Construction Cost		\$40,731
			Adjustment Factor	0%	0
			Soft Cost Adjustment	46%	18,565
			Total Estimated Amount		\$59,296

Surveyor/Update

Prepared by: **HEERY**

Deficiency Detail

2/4/2016 1:41 PM

290 **Tedder Elementary School** Tedder ES->Bldg 14

Location: Deficiency:

Assess ID 208119 Surveyor/Update

BCRoof-02 Defeciency Code ID

Estimated FCI Status Yes

Life Cycle

Reroofing with new Decking Required (Broward CPS) Deficiency

Capital Renewal Category System Roofing

1-Mission Critical Concerns Priority Functional Adequacy Non Related

Correction Reroof and Replace Decking Quantity / UoM

Project(s) Note

Туре	Number	Description	Qty UoM	Price	Extension
М		Estimate based of BCPS experience	7,146 SF	7.25	\$51,809
			Sub Total		\$51,809
			Construction Adjustment	35%	17,874
			Construction Cost		\$69,682
			Adjustment Factor	0%	0
			Soft Cost Adjustment	46%	31,761
			Total Estimated Amount		\$101,444



Deficiency Detail

2/4/2016 1:41 PM

290 **Tedder Elementary School** Tedder ES->Media Ctr

Location: Deficiency:

Assess ID 208120 Surveyor/Update

Defeciency Code ID BCRoof-02

Estimated FCI Status Yes

Life Cycle

Reroofing with new Decking Required (Broward CPS) Deficiency

Capital Renewal Category System Roofing

1-Mission Critical Concerns Priority Functional Adequacy Non Related

Correction Reroof and Replace Decking Quantity / UoM

Project(s) Note

Туре	Number	Description	Qty UoM	Price	Extension
м		Estimate based of BCPS experience	5,542 SF	7.25	\$40,180
			Sub Total		\$40,180
			Construction Adjustment	35%	13,862
			Construction Cost		\$54,041
			Adjustment Factor	0%	0
			Soft Cost Adjustment	46%	24,632
			Total Estimated Amount		\$78,674



Deficiency Detail

2/4/2016 1:41 PM

290 **Tedder Elementary School** Location: Tedder ES->CR

Deficiency:

Assess ID 208121 Surveyor/Update

Defeciency Code ID BCRoof-02

Estimated FCI Status Yes

Life Cycle

Reroofing with new Decking Required (Broward CPS) Deficiency

Capital Renewal Category System Roofing

1-Mission Critical Concerns Priority Functional Adequacy Non Related

Correction Reroof and Replace Decking Quantity / UoM

Project(s) Note

Туре	Number	Description	Qty UoM	Price	Extension
м		Estimate based of BCPS experience	4,599 SF	7.25	\$33,343
			Sub Total		\$33,343
			Construction Adjustment	35%	11,503
			Construction Cost		\$44,846
			Adjustment Factor	0%	0
			Soft Cost Adjustment	48%	21,728
			Total Estimated Amount		\$66,574



Deficiency Detail

2/4/2016 1:41 PM

290 **Tedder Elementary School** Location: Tedder ES->CR

Deficiency:

Assess ID 218663 Surveyor/Update Sherry Sims

Defeciency Code ID A30-03

FCI Status **Estimated** Yes

Life Cycle 65883

The Stucco Exterior Is Damaged And Requires Replacement Deficiency

Capital Renewal Category System Exterior

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Non Related

Correction Replace Stucco Quantity / UoM

Project(s) Note

Туре	Number	Description	Qty	UoM	Price	Extension
U	090505300300	Walls and partitions demolition, exterior stucco over netting, 1" thick	3,840	SF	0.84	\$3,226
U	092423401000	Stucco, exterior, with bonding agent, 3 coats, on walls, excl. mesh	1,800	SY	17.60	\$31,680
U	092236232800	Metal lath, stucco mesh, painted, 3.6 lb	1,800	SY	4.43	\$7,974
			s	ub Total		\$42,880
		Cons	truction Ac	ljustment	35%	14,793
			Constructi	ion Cost		\$57,673
			Adjustme	nt Factor	0%	0
		Sc	oft Cost Ac	ljustment	48%	27,943
		Total E	Estimated	Amount		\$85,616



Deficiency Detail

2/4/2016 1:41 PM

Tedder Elementary School Location: Tedder ES

Deficiency:

290

Assess ID 220887 Surveyor/Update

Defeciency Code ID FireAlarm-01

Estimated FCI Status Yes

Life Cycle

Deficiency Entire Fire Alarm System Needs to be Replaced

Capital Renewal Fire and Security Category System

Priority 1-Mission Critical Concerns Functional Adequacy Non Related

Correction Replace Entire Fire Alarm System Quantity / UoM

Project(s) Note Model: 19000A

Type	Number	Description	Qty UoM	Price	Extension
М		Allowance for Fire Alarm Replacement	1 LS	175,000.0 0	\$175,000
			Sub Total		\$175,000
			Construction Adjustment	35%	60,375
			Construction Cost		\$235,375
			Adjustment Factor	0%	0
			Soft Cost Adjustment	42%	99,893
			Total Estimated Amount		\$335,268



Deficiency Detail

Sherry Sims

2/4/2016 1:41 PM

Location: **Tedder ES**

Deficiency:

290

Assess ID 312650 Surveyor/Update

Defeciency Code ID A08-03

Estimated FCI Status Yes

Life Cycle

Playground Equipment Requires Replacement Deficiency

Tedder Elementary School

Capital Renewal Category System Site

Priority 4-Long Term Requirements (3-5 years) Functional Adequacy Support for Programs

Correction Replace Playground Equipment Quantity / UoM

Project(s) Note

	ucc.				
Type	Number	Description	Qty UoM	Price	Extension
U	024113951400	Selective demolition, athletic/playground equipment, slides, long	12' 8 Ea.	245.00	\$1,960
U	116813100590	Playground equipment, parallel bars, 10' long	8 Ea.	720.00	\$5,760
			Sub Total		\$7,720
			Construction Adjustment	35%	2,663
			Construction Cost		\$10,383
			Adjustment Factor	0%	0
			Soft Cost Adjustment	55%	5,673
			Total Estimated Amount		\$16,057



Attachment H



The School Board of Broward County, Florida Office of Facilities & Construction 3775 S.W. 16th Street Fort Lauderdale, Florida 33312

(754) 321-1500

	Consul	tant's Authorizati	on To Proceed
Project No.:		Date:	
Location No.:		CDDCD O M	
Project Title:		SBBC P.O. No).:
		Line No.:	
Facility Name:		Project Manager	:
Project Consultant:		Dir. Capital Plar	nning & Programming
			s, you are hereby authorized to proceed with the
following services	for the project refer	enced above.	
Schematic Design	Design Devel	onment	Construction Documents
Bidding	= ~	Contract Administration	
= ~	Construction \ Attached:	Contract Administration	onwarranty
Other services.	Attached.		
This Authorization	to Proceed is subje-	ct to the following attachm	ents:
Attachments:	Professional Servi	ices Required	
	Project Schedule		
L	Professional Fees Previous ATP's		
L	rievious Air s		
The scope of the	required services	is specified on the Profe	ssional Services Required with a Fixed Limit of
		ject as indicated below:	•
Original FLCC	C	Surrent Cost Estimate	Revised FLCC by ATP
TT1 C 11 ' ('''' '' '' '' '' '' '' '' '' '' '' '' '	
for the Project liste		iii be provided by the Proje	ect Consultant as a normal part of its Basic Services
for the Froject liste	u above.		
Item I	Discipline	Description	

Attachment H



The School Board of Broward County, Florida Office of Facilities & Construction 3775 S.W. 16th Street Fort Lauderdale, Florida 33312

(754) 321-1500

Consultant's Author	rization To Proceed (Term Contracts) C	ont.
	Project Schedule	
Project No. & Location No.:	Project Title:	
Facility Name: Project Consultant:		
The required project schedule milestones for this	project are presented below. (Mandatory)	
	Date Required Or Estin	nated Time Period
ACTIVITY	Start	Finish
Schematic Design		
Design Development		
Construction Documents Development		
50% Construction Documents		
100% Construction Documents		
Bidding and Award of Contract		
Time for Permitting of Submittals, Prior to the Issuance of the Construction NTP (Pa	art of Contract Administration)	
Construction		
Warranty		

Attachment H



The School Board of Broward County, Florida Office of Facilities & Construction 3775 S.W. 16th Street Fort Lauderdale, Florida 33312

(754) 321-1500

	Consultant's	s Authorization To	Proceed (Term Co	ontracts)
		Professiona	al Fees	
Project No. &		Project Title	: :	
Location No.:				
Facility Name:				
Project Consultant:				
Phase	Original Basic	Fee Authorized by ATP	Fee Previously Paid	
	Fee			Fee Balance
I (SD) (5%)		%	%	%
II (DD) (10%)		%	%	%
III (CD) (35%/60%)		%	%	%
IV (BID) (65%)		%	%	%
V (CA) (98%)		%	%	%
VI (Warr) (100%)		%	%	%
Other Service		%	%	%
Item No. 1				
Other Service		%	%	%
(Item No. 2)				
Other Service		%	%	%
(Item No. 3)				
Other Service		%	%	%
(Item No. 4)				
Total:				
	these services shall	he made In accordance with	the provisions of the Profe	essional Services Agreement

Payment for these services shall be made in accordance with the provisions of the Professional Services Agreement.

Approved By Con	sultant			Recommen	ded By SBBC		
Name:			Name: Shelley N. Meloni				
Title:			Title: Director, Pre-Construction				
Signature:		Date:		Signature:		Date	
Certified By SBB0	C			Approval b	y SBBC		
Name:	<u> </u>			Approval b Name: Leo	•		
<u> </u>	<u> </u>			Name: Leo	•		

This document is part of the Professional Services Agreement between The School Board of Broward County, Florida (Owner) and the Design Professional and is incorporated by reference into the terms and conditions of that agreement.