

REQUEST FOR QUALIFICATIONS
RFQ 17-066C

DESIGN PROFESSIONAL SERVICES

Parkway Middle School



The School Board of Broward County, Florida

Dr. Rosalind Osgood, Chair
Abby M. Freedman, Vice Chair
Robin Bartleman
Heather P. Brinkworth
Patricia Good
Donna P. Korn
Laurie Rich Levinson
Ann Murray
Nora Rupert

Robert W. Runcie, Superintendent of Schools

Leo Bobadilla - Chief Facilities Officer
Barbara J. Myrick, Interim General Counsel

Office of Facilities and Construction
Procurement and Warehousing Services

NOTICES TO ALL BIDDERS

Cone of Silence and Lobbyist Activities

For Cone of Silence requirements and for Lobbyist Activities restrictions, refer to Section 1, Introduction and General Information lines labeled 'Cone of Silence and Lobbyist Activities' (lines 1.10 and 1.11).

THE SCHOOL BOARD OF BROWARD COUNTY, FLORIDA
Procurement and Warehousing Services Department
7720 W. Oakland Park Boulevard, Suite 323
Sunrise, Florida 33351-6704



THE SCHOOL BOARD OF BROWARD COUNTY, FLORIDA
7720 WEST OAKLAND PARK BOULEVARD, SUITE 323 • SUNRISE, FLORIDA 33351-6704 • TEL 754-321-0501

REQUEST FOR QUALIFICATIONS (RFQ)

RFQ # 17-066C

DESIGN PROFESSIONAL SERVICES

RFQ Issue Date: August 19, 2016

Description of Scope:

Design Services for the following project:

Parkway Middle School

- Fire Sprinklers
- Media Center Improvements
- HVAC Improvements
- Building Envelope Improvements

NOTICES TO ALL PROPOSERS

Cone of Silence and Lobbyist Activities

For Cone of Silence requirements and for Lobbyist Activity restrictions refer to Section 1, Introduction and General Information lines labeled Cone of Silence and Lobbyist Activities. Line numbers 1.10 and 1.11.

THE SCHOOL BOARD OF BROWARD COUNTY, FLORIDA
Procurement and Warehousing Services Department
7720 W. Oakland Park Boulevard, Suite 323
Sunrise, Florida 33351-6704

TABLE OF CONTENTS

<u>Section</u>	<u>Page</u>
---	RFQ Cover Sheet.....1
---	Table of Contents and Attachments..... 2
1.0	Introduction and General Information3
2.0	Calendar6
3.0	RFQ Conditions7
4.0	Required Proposal Format and Response Information..... 11
5.0	Evaluation of Qualifications 15
6.0	Project Scope and Schedule 17

Attachments

Attachment A - M/WBE Participation

Attachment B – Design Professional and Consultants Staffing

Attachment C – Sample Professional Services Agreement (With attachments)

Attachment 1: Project Schedule

Attachment 2: Project Scope (See Attachment G)

Attachment 3: Electronic Media Submittal Requirements

Attachment 4: Project Consultant’s Invoice Format, Reimbursable and Supplemental Services Format

Attachment 5: List of Project Team Members

Attachment 6: Authorization to Proceed (ATP) Form

Professional Services Required – page 1 of 3

Project Schedule – page 2 of 3

Professional Fee – page 3 of 3

Attachment 7: Document Submittal Checklist

Attachment 8: Document 00455 – Background Screening

Attachment 9: IRS Form W-9

Attachment 10: Truth in Negotiations Certificate

Attachment D - Required Response Form

Attachment E - Scope of Available Services

Attachment F – Proposers Request for Information Form

Attachment G – Project Scope of Work

SECTION 1.0 - INTRODUCTION AND GENERAL INFORMATION

1.1 The School Board of Broward County, Florida (hereinafter referred to as "SBBC") desires to receive Qualifications for Design Services as described herein.

1.2 **Questions and Interpretations:** Any questions, requests for clarifications or interpretations regarding any portion of this RFQ during the Submittal preparation period (or reporting errors, inconsistencies, or ambiguities) shall be received no less than ten (10) days prior to the deadline due date for submitting the completed RFQ response, and no questions or clarifications will be considered after this date. Respondents must submit Document 00220 – Bidders Request For Information Form (Attachment F) for all RFI requests and all RFI requests must be typed or printed. Questions not submitted on Document 00220 will not be considered. RFI requests must be for a single RFQ, RFI requests for multiple RFQs may not be considered. Any questions which require a response which amends the RFQ document in any manner will be answered via Addendum by the Procurement and Warehousing Services Department and provided to all Proposers. Address questions or requests for clarifications in writing to:

Vanessa S. Lauchaire
Strategic Sourcing Manager
Procurement & Warehousing Services
7720 West Oakland Park Blvd - Suite 323
Sunrise, FL 33351
754-321-0533 Fax

E-mail: vanessa.lauchaire@browardschools.com

1.3 Any verbal or written information, which is obtained other than by information in this RFQ document or by Addenda, shall not be binding on SBBC.

1.4 **Contract Term:** The term of this contract is anticipated to begin on the Notice to Proceed Date and end one year after final completion of the project.

1.5 **Proposal Format:** The RFQ's submittal shall follow the format and include the information as identified in Section 4.0 of this RFQ.

1.6 **Evaluation and Award:** All Proposals will be evaluated by the Selection Committee based upon the information submitted by Proposers in response to this RFQ and in accordance with the evaluation criteria established in Section 5.0. Based upon the evaluation of Proposals, the Committee will recommend a Proposer(s) to the Superintendent of Schools who may then recommend a Proposer(s) to the SBBC for award.

1.7 **Irrevocability of Proposal:** A Proposal may not be withdrawn before the expiration of 90 days after the date of the Proposal's opening.

1.8 **Proposal Package Requirements:**

--- One complete, original hard-copy Proposal (clearly labeled as "original").

--- One complete, original electronic version (clearly labeled as "original").

--- Five (5) complete, electronic version copies (clearly labeled as "copy").

--- Four (4) additional hard-copies (which must be identical to the original Proposal except they shall be labeled as "copy").

--- Proposals shall be submitted in a sealed envelope (package, box, etc.) with the RFQ number and description clearly identified by label on the Package along with the Proposers Name.

- 1.9 **Gratuities:** Proposers shall not provide any gratuities, favors, or anything of monetary value to any official, employee, or agent of SBBC; including any School Board Member, Superintendent of Schools and any Evaluation Committee Members, for any reason during this entire Procurement Process.
- 1.10 **Cone of Silence:** Any proposer, or lobbyist for a proposer, is prohibited from having any communications (except as provided in this rule) concerning any solicitation for a competitive procurement with any School Board member, the Superintendent, any Evaluation Committee Member, or any other School District employee after the Procurement and Warehousing Services Department releases a solicitation to the General Public. All communications regarding this solicitation shall be directed to the designated Purchasing Agent unless so notified by the Procurement and Warehousing Services Department. This “Cone of Silence” period shall go into effect and shall remain in effect from the time of release of the solicitation until the contract is awarded by the School Board. Further, any vendor, its principals, or their lobbyists shall not offer campaign contributions to School Board Members or offer contributions to School Board Members for campaigns of other candidates for political office during the period in which the vendor is attempting to sell goods or services to the School Board. This period of limitation of offering campaign contributions shall commence at the time of the “cone of silence” period for any solicitation for a competitive procurement as described by School Board Policy 3320, Part II, Section GG as well as School Board Policy 1007, Section 5.4 – Campaign Contribution Fundraising. Any vendor or lobbyist who violates this provision shall cause their Proposal (or that of their principal) to be considered non-responsive and therefore be ineligible for award. This prohibition does not apply to:
1. Telephone calls to the Procurement & Warehousing Services staff to request copies of this RFQ, to confirm attendance, or request directions regarding an interview notification received;
 2. Delivery of the Respondent’s Submittal;
 3. Discussion at the interview;
 4. Delivery of written questions about the RFQ; and/or Review of background/contract documents at the staff offices.
- 1.11 **Lobbyist Activities:** In accordance with SBBC Policy 1100B, as currently enacted or as amended from time to time, persons acting as lobbyists must state, at the beginning of their presentation, letter, telephone call, e-mail or facsimile transmission to School Board Members, Superintendent or Members of Senior Management, the group, association, organization or business interest she/he is representing.
- 1.11.1 A lobbyist is defined as a person who, for immediate or subsequent compensation (e.g., monetary profit/personal gain), represents a public or private group, association, organization or business interest and engages in efforts to influence School Board Members on matters within their official jurisdiction.
- 1.11.2 A lobbyist is not considered to be a person representing school allied groups (e.g., PTA, DAC, Band Booster Associations, etc.) nor a public official acting in her/his official capacity.
- 1.11.3 Lobbyists shall annually (July 1) disclose in each instance and for each client prior to any lobbying activities, their identity and activities by completing the lobbyist statement form which can be obtained from official School Board Records, School Board Member's Offices or the Superintendent's Office and will be recorded on SBBC's website, www.browardschools.com.
- 1.11.4 The lobbyist must disclose any direct business association with any current elected or appointed official or employee of SBBC or any immediate family member of such elected or appointed official or employee of SBBC.
- 1.11.5 Senior-level employees and/or School Board Members are prohibited from lobbying activities for two years after resignation or retirement or expiration of their term of office.
- 1.11.6 The Office of the Superintendent shall keep a current list of persons who have submitted the lobbyist statement form.
- 1.12 **Preparation Cost of Proposal:** Proposer is solely responsible for any and all costs associated with responding to this RFQ. SBBC will not reimburse any Proposer for any costs associated with the preparation and submittal of any Proposal, or for any travel and per diem costs that are incurred by any Proposer.

- 1.13 It is the sole responsibility of the Proposer to assure it has received the entire Proposal and any and all Addendum.
- 1.14 It is the sole responsibility of the Proposer to assure that its Proposal is time stamped in the Procurement and Warehousing Services Department on or before 2:00 p.m. EST on the date due.
- 1.15 No verbal or written information which is obtained other than by information in this document or by Addenda to this RFQ shall be binding on SBBC.
- 1.16 No submissions made after the Proposal opening, amending or supplementing the Proposal, will be considered.

SECTION 2.0 CALENDAR

August 19, 2016	Issuance of RFQ #17-066C
September 7, 2016	Written questions due on or before 5:00 p.m. ET in the Procurement and Warehousing Services Department 7720 West Oakland Park Blvd., Suite 323, Sunrise, Florida 33351-6704.
September 22, 2016	Proposals due on or before 2:00 p.m. ET in the Procurement and Warehousing Services Department. 7720 West Oakland Park Blvd., Suite 323, Sunrise, Florida 33351-6704.
October 11, 2016**	Selection Committee reviews Qualifications and makes a recommendation for Selection in the Procurement and Warehousing Services Department 7720 West Oakland Park Boulevard, Suite 323 Sunrise, Florida 33351-6704 at 9:00 a.m.*
October 14, 2016	Evaluation Committees Posting of Recommendations.
December 6, 2016	Tentative School Board Award Date.

*These are public meetings. SBBC prohibits any policy or procedure which results in discrimination on the basis of age, color, disability, gender identity, gender expression, national origin, marital status, race, religion, sex or sexual orientation. Individuals who wish to file a discrimination and/or harassment complaint may call the Executive Director, Benefits & EEO Compliance at 754-321-2150 or Teletype Machine (TTY) 754-321-2158.

Individuals with disabilities requesting accommodations under the Americans with Disabilities Act (ADA) may call Equal Educational Opportunities (EEO) at 754-321-2150 or Teletype Machine (TTY) 754-321-2158.

**Proposers may be asked to be present at this public meeting to answer questions related to their submittal. Proposers may also be invited to make a presentation to the Selection Committee. If a presentation is requested, it must be limited to information included in their Proposal submitted to SBBC. Details related to the Selection Committee meeting will be provided to the proposers when they are given notice of the meeting.

SECTION 3.0 - RFQ CONDITIONS

- 3.1 **Evaluation Committees and Proposals:** State Statutes 119.071 and 286.0113 are adhered to by SBBC in the review and awarding of contracts.
- 3.2 **Public Record:** Proposer acknowledges that all information contained within their Proposal is part of the public domain as defined by the State of Florida Sunshine and Public Record Laws.
- 3.3 **Governing Law:** This RFQ, and any award(s) resulting from this RFQ, shall be interpreted and construed in accordance with the laws of the State of Florida. Any protests arising from this RFQ shall be subject to Section 120.57(3), Florida Statutes. Any disputes or controversies arising out of a contract awarded under this RFQ shall be submitted to the jurisdiction of the state courts of the Seventeenth Judicial Circuit in and for Broward County, Florida.
- 3.4 **Advertising:** In submitting an RFQ, Proposer agrees not to use the results therefrom as a part of any commercial advertising without prior written approval of SBBC.
- 3.5 **Billing Instructions and Payment:** All payments made to the Design Professionals shall be made by ACH (Automated Clearing House). Monthly invoices shall be submitted to the Project Manager for review and approval. Refer to the PSA for the specifics. The ACH Payment Agreement Form is an attachment to the PSA (PSA Attachment 12). This form shall be submitted at the time of the execution of the Contract.
- 3.6 **Contract Value:** No guarantee is given or implied as to the total dollar value or work as a result of this RFQ. SBBC is not obligated to place any order for services performed as a result of this award. Order placement will be based upon the needs and in the best interest of SBBC.
- 3.7 **Conflict of Interest and Conflicting Employment or Contractual Relationship:** Section 112.313 (3) and (7), Florida Statutes, sets forth restrictions on the ability of SBBC employees acting in a private capacity to rent, lease, or sell any realty, goods, or services to SBBC. It also places restrictions on SBBC employees concerning outside employment or contractual relationships with any business entity which is doing business with SBBC. Each Proposer is to disclose any employees it has who are also SBBC employees. This Conflict of Interest Form is an attachment to the PSA (PSA attachment 9). This executed document shall be submitted at the time of Contract Execution. Any employees identified by the Proposer, should obtain legal advice as to their obligations and restrictions under Section 112.313 (3) and (7), Florida Statutes.
- 3.8 **Disputes:**
- 3.8.1 In the event of a conflict between the documents, the order of priority of the documents shall be as follows:
1. The Agreement resulting from the award of this RFQ (if applicable) ; then
 2. Addenda released for this RFQ, with the latest Addendum taking precedence; then
 3. the RFQ Documents; then
 4. Awardee's Proposal.
- 3.8.2 In case of any other doubt or difference of opinion, the decision of SBBC shall be put in writing and shall be final and binding on both parties.
- 3.9 **Insurance:** Refer to PSA Agreement – Part 5 – Article 3 for Design Professional Insurance Requirements (RFQ Attachment C).
- 3.10 **Public Entity Crimes:** Section 287.133(2)(a), Florida Statutes, as currently enacted or as amended from time to time, states that a person or affiliate who has been placed on the convicted vendor list following a conviction for a public entity crime may not submit a Proposal on a contract to provide any goods or services to a public entity, may not submit a Proposal on a contract with a public entity for the construction or repair of a public building or public work, may not submit a Proposal on leases of real property to a public entity, may not be awarded or perform work as a contractor, supplier, subcontractor, or consultant under a contract with any public entity, and may not transact business with any public entity in excess of the threshold amount

provided in Section 287.017 for CATEGORY TWO [currently \$25,000] for a period of 36 months from the date of being placed on the convicted vendor list.

3.12 **M/WBE:**

3.12.1 M/WBE Goals: The Design Professional shall comply with the Owner's current M/WBE policies and procedures. The Design Professional's M/WBE goal for this Contract is 25 percent.

3.12.2 Information: SBBC encourages each Proposer to make every reasonable effort to include M/WBE participation on any contract award under this RFQ. An M/WBE is defined by SBBC as any legal entity, other than a joint venture, which is organized to engage in commercial transactions and which is at least 51% owned and controlled by a minority or women and has been Certified by SBBC as an approved M/WBE.

3.12.2.1 Any participation by firms not certified by SBBC at the time of proposal will not count in the RFQ evaluation process for the award of points in the Design Professional M/WBE Participation Category. However, firms that are certified by SBBC after the proposal's tentative award, will count towards the Design Professional's M/WBE project goal attainment. Design Professional to contact SDOP to provide the updated information.

3.12.2.2 For information on M/WBE Certification, or to obtain information on locating certified M/WBE's, contact SBBC's Supplier Diversity and Outreach Programs at 754-321-0550 or <http://www.broward.k12.fl.us/supply/sdop/mwbe.html>.

3.13 **Protesting of RFQ Conditions/Specifications:** Any person desiring to protest the conditions/specifications in this RFQ, or any Addenda subsequently released thereto, shall file a notice of intent to protest, in writing to the Director of Procurement and Warehousing Services Department. The formal written protest shall be filed within ten calendar days after the date the notice of protest was filed. Saturdays, Sundays, state holidays or days during which the school district administration is closed shall be excluded in the computation of the ten (10) calendar days. The formal written protest must be received on or before 5:00 p.m. EST of the 10th Calendar Day at the office of the Director of Procurement and Warehousing Services Department. Refer to Section 120.57(3)(b), Florida Statutes, as currently enacted or as amended from time to time, for the requirements for the written protest.

3.13.1 Failure to file a notice of protest or to file a formal written protest within the time prescribed by Section 120.57(3), Florida Statutes, or a failure to post the bond or other security required by SBBC Policy 3320, Part VIII, within the time allowed for filing a bond, shall constitute a waiver of proceedings.

3.14 **Posting of RFQ Recommendations:** RFQ Recommendations will be posted in the Procurement and Warehousing Services Department and on www.demandstar.com as noted on the Calendar (Section 2.0) or as modified by an addendum or by posting in the Procurement and Warehousing Services Department and at www.demandstar.com (under the document section for this RFQ). The Recommendations will remain posted for 72 hours. It is the responsibility of each Proposer to ascertain any revised date for the posting of RFQ Recommendations.

3.15 **Protest of Intended Decision:** Any person desiring to protest the Recommended Decision shall file a notice of protest, in writing, within 72 hours after the posting of the RFQ Recommendation and shall file a formal written protest within ten calendar days after the date the notice of protest was filed. The formal written protest must be received on or before 5:00 p.m. EST of the tenth (10) calendar day. Saturdays, Sundays, state holidays and days during which the school district administration is closed shall be excluded in the computation of the 72 hours.

3.15.1 Failure to file a notice of protest or to file a formal written protest within the time prescribed by Section 120.57(3), Florida Statutes, or a failure to post the bond or other security required by Policy 3320, Part VIII, within the time allowed for filing a bond, shall constitute a waiver of proceedings.

3.15.2 Notices of protests, formal written protests, and the bonds required by Policy 3320, shall be filed at the office of the Director of Procurement and Warehousing Services, 7720 West Oakland Park Boulevard, Suite 323, Sunrise, Florida 33351 Fax filing will not be acceptable for the filing of bonds.

- 3.16 **Use of Other Contracts:** SBBC reserves the right to utilize any other SBBC contract, any State of Florida Contract, any contract awarded by any other city or county governmental agencies, other school boards, other community college/state university system cooperative agreements, in lieu of any offer received or award made as a result of this RFQ if it is in SBBC's best interest to do so. SBBC also reserves the right to waive irregularities or technicalities in any Proposal received if such action is in the best interest of SBBC. However, such a waiver shall in no way modify the RFQ requirements or excuse the Proposer from full compliance with the RFQ specifications and other contract requirements if the Proposer is awarded a contract.
- 3.17 **Assignment:** Neither party to the Agreement shall sell, assign or sublet the same without the written consent of the other; nor shall a Design Professional assign any monies due or to become due to the Design Professional, or by reason of the Contract without the previous written consent of the Owner and as approved by the Attorney for the Owner.
- 3.18 **Cancellation:** In the event any of the provisions of this RFQ are violated by the Awardee, the Director of Procurement and Warehousing Services shall give written notice to the Awardee stating the violations and unless they are corrected within five days, a recommendation will be made to SBBC for cancellation.
- 3.19 **SBBC Photo Identification Badge:**
Background Screening: Awardee agrees to comply with all the requirements of Sections 1012.32 and 1012.465, Florida Statutes, and that Awardee and all its personnel who (1) are to be permitted access to school grounds when students are present, (2) will have direct contact with students, or (3) have access or control of school funds will successfully complete the background screening required by the referenced statutes and meet the standards established by the statutes. Personnel shall include employees, representatives, agents or sub-contractors performing duties under the contract to SBBC and who meet any or all of the three requirements identified above. Awardee will bear the cost of acquiring the background screening required under Section 1012.32, Florida Statutes, and any fee imposed by the Florida Department of Law Enforcement to maintain the fingerprints provided with respect to Awardee and its personnel. The Parties agree that the failure of Awardee to perform any of the duties described in this section shall constitute a material breach of this RFQ entitling SBBC to terminate immediately with no further responsibilities or duties to perform under this Agreement. Awardee agrees to indemnify and hold harmless SBBC, its officers and employees of any liability in the form of physical or mental injury, death or property damage resulting in Awardee's failure to comply with the requirements of this section or Sections 1012.32 and 1012.465, Florida Statutes.
- 3.19.1 SBBC issued identification badges must be worn at all times when on SBBC property and must be worn where they are visible and easily readable.
- 3.19.2 Badge Vendor Information shall be provided to the Design Professional at the time of Award.
- 3.20 **Withdrawal of RFQ:** In the best interest of SBBC, SBBC reserves the right to withdraw this RFQ at any time prior to the time and date specified for the Proposal opening.
- 3.21 **Severability:** In case of any one or more of the provisions contained in this RFQ shall be for any reason be held to be invalid, illegal, unlawful, unenforceable or void in any respect, the invalidity, illegality, unenforceability or unlawful or void nature of that provision shall not affect any other provision and this provision shall be considered as if such invalid, unlawful, unenforceable or void provision had never been included herein.
- 3.22 It is the sole responsibility of the Proposer to assure it has received the entire Proposal and any and all Addendum.
- 3.23 It is the sole responsibility of the Proposer to assure that its Proposal is time stamped in the Procurement and Warehousing Services Department on or before the due time on the date due. No submissions made after the Proposal opening, amending or supplementing the Proposal, shall be considered.
- 3.24 No verbal or written information which is obtained other than by information in this document or by Addenda to this RFQ shall be binding on SBBC.
- 3.25 **Acceptance and Rejection of Proposals:**
- 3.25.1 **Acceptance:** All Proposals properly completed and submitted will be evaluated in accordance with Section 5.0.

3.25.2 **Rejection:** A Proposal may be rejected if it does not conform to the rules or the requirements contained in this RFQ. Examples for rejection include, but are not limited to, the following:

3.25.2.1 The Proposal is time-stamped at the Procurement and Warehousing Services Department after the deadline specified in the RFQ.

3.25.2.2 Proposers found legally guilty of collusion among Proposers, shall be rejected, and the participants to such shall be barred from future procurement opportunities until such time as they may be reinstated.

3.25.2.3 The Proposal shows non-compliance with applicable laws; or contains any unauthorized additions or deletions; is a conditional Proposal; is an incomplete Proposal; or contains irregularities of any kind.

3.26.2.4 The Proposer adds provisions reserving the right to accept or reject an award or to enter into a contract pursuant to an award or adds provisions contrary to those in the RFQ.

3.25.3 SBBC also reserves the right to waive irregularities or technicalities in any Proposal received if such action is in the best interest of SBBC. However, such a waiver shall in no way modify the RFQ requirements or excuse the Proposer from full compliance with the RFQ specifications and other contract requirements if the Proposer is awarded the contract.

3.26 **Maintenance of Records:**

3.26.1 Design Professional shall keep all records and supporting documentation which concern or reflect its Services hereunder. The records and documentation shall be retained by the Design Professional for a period of seven (7) years from the completion date of the project associated with the Authorization to Proceed; or such period of time as required by law. The Owner, or any duly authorized agents or representatives of the Owner, shall have the right to inspect and copy all such records and documentation as often as they deem necessary during the period of this Agreement and during the period noted above in which the records are to be retained. Such activity shall be conducted at the reasonable convenience of the Design Professional.

3.27 **Liability:** Refer to Attachment C - Sample Professional Services Agreement (PSA), Part 5 Article 2 - Liability Clause.

3.28 **SBBC Information Security Guidelines:** It is the responsibility of the Design/Builder to read and adhere to the SBBC Information Security Guidelines when using any device connected to the SBBC's network. Following the conclusion of the contract term, all of SBBC's confidential information must be removed from the Design/Builder's equipment and all access privileges must be revoked. Final payment will be withheld until the Design/Builder has confirmed, in writing, that all SBBC's confidential information has been purged from any and all electronic technology devices that were used during this contract and were connected to the SBBC's network.

SECTION 4.0 - REQUIRED QUALIFICATIONS FORMAT AND RESPONSE INFORMATION

4.1 The SBBC's Procurement and Warehousing Services Department shall determine whether each Proposer has Addressed and provided all RFQ submittal requirements. SBBC's Procurement and Warehousing Department shall identify the status of completion for each Proposer's proposal on a spreadsheet for the Evaluation Committee's use.

4.2 It is required that Proposals be organized in the manner specified below and with all the information as identified.

4.2.1 Title Page:

- Line 1 Include RFQ number and name;
- Line 2. The RFQ Due Date;
- Line 3 The name of the Proposer (company/firm name);
- Line 4 Company/firm address;
- Line 5 and telephone number.

4.2.2 Section A – General

NOTE: Failure to strictly comply with this section may result in a recommendation to reject the proposal.

Section A1 Table of Contents: Include a clear identification of the material by scoring sections, section number and by page number.

Section A2 Letter of Responsibility: Include the names of the persons who will be authorized to make decisions for the Proposer for this proposal, and for the Design efforts that may result from this RFQ. Provide titles, work addresses, telephone numbers and e-mail addresses. Letter to be on Company Letterhead and signed by an Officer of the Company.

Section A3 – Signed Addenda: Include signed and dated copies of all addenda to verify and acknowledge receipt.

4.2.3 Section B – Required Forms, Licenses, certificates, History

NOTE: Failure to strictly comply with this section may result in a recommendation to reject the proposal.

Section B1 - Required Response Form

Modifications or alterations to this form shall not be accepted and will cause the Proposal to be rejected and not reviewed. The Required Response Form, shall be the only acceptable form. The Required Response Form shall be completed in ink or typewritten. The signed "original" Required Response Form shall be submitted within the Proposal Package labeled as the "original." Refer to Attachment D.

JOINT VENTURES

Required Response Form for Joint Venture Proposals shall follow the following requirements. In the event multiple Proposers submit a joint Proposal in response to the RFQ, a single Proposer shall be identified as the Prime Proposer. If offering a joint Proposal, Prime Proposer must include the name and address of all parties of the joint Proposal. Prime Proposer shall provide all bonding and insurance requirements, execute any Contract, complete the Required Response Form shown herein, and have overall and complete accountability to resolve any dispute arising within this contract. Only a single contract with one Proposer shall be acceptable. Prime Proposer responsibilities shall include, but not be limited to, performing of overall contract administration, preside over other Proposers participating or present at SBBC meetings, oversee preparation of reports and presentations, and file any notice of protest and final protest as described herein. Prime Proposer shall also prepare and present a consolidated invoice(s) for services performed. SBBC shall issue only one check for each consolidated invoice to the Prime Proposer for services performed. Prime Proposer shall remain responsible for performing services associated with response to this RFQ.

Section B2 Licenses and Registrations (Florida)

- 3.1 All appropriate licenses shall be provided on a list
- 3.2 Firms Architectural License/Registration if applicable
- 3.3 Architectural License/Registration – for _____
- 3.4 Architectural License/Registration – for _____
- 3.5 Mechanical License/Registration – for _____
- 3.6 Structural License/Registration – for _____
- 3.7 M/WBE Certificate (if applicable) – for proposer firm
- 3.8 continue as appropriate

Section B3 Proposer History

Provide a listing of current and former business entities that the Proposer is operating under and has operated under in the past. Letter to be on Company Letterhead and signed by an officer of the Company.

Section B4 Litigation

Provide a statement of any litigation or regulatory action that has been filed or is pending against your firm(s) in the last three years. If an action has been filed, state and describe the litigation or regulatory action filed, and identify the court or agency before which the action was instituted, the applicable case or file number, and the status or disposition for such reported action. If no litigation or regulatory action has been filed against your firm(s), provide a statement to that effect. For joint venture or team Proposers, submit the requested information for each member of the joint venture or team.

NOTE: Sections C and D below shall be evaluated and scored by QSEC

4.2.4 Section C - Experience and Qualifications (55 maximum points)

Section C1 Executive Summary / Approach / Current Work Load (25 maximum points)

Executive Summary – (7 maximum points) Submit a brief abstract stating the Proposer's understanding of the nature and scope of the services to be provided and capability to comply with all terms and conditions of RFQ (3 page maximum).

Approach – (9 maximum points) Discuss your approach for delivering this project. Discuss your firm's willingness and ability to meet the project's schedule and budget. Discuss the office location from which this work will be conducted and its distance from the project site. (5 page maximum).

Current Work Load Overall – (5 maximum points) Demonstrate your ability to perform this work given your current project workload. Provide a list of current projects for all clients including SBBC, Include all projects currently under contract and all projects where your firm has been selected but is not yet under contract. Include project construction value. (2 page maximum).

Current Work Load with SBBC - (4 maximum points) Provide a list of all projects with total fees for all active contracts with SBBC. Provide a list of all projects and total fees for all projects where your firm has been selected by SBBC but is not yet under contract. (2 page maximum). (Proposer with the most total fees on current projects will be awarded zero (0) points. Other proposers will be awarded up to 3 points based on current fees, with more points being awarded to proposers with the least amount of current fees with SBBC).

Section C2 Firm Experience and Qualifications (15 maximum points)

Provide a statement of your firm's qualifications to perform the services requested under this RFQ (3 page maximum).

Section C3 Relevant Projects / References (15 maximum points)

Provide a list and description of relevant projects (maximum of 5) successfully completed by your firm in the most recent five (5) years. For each project, include:

- Name and location of project
- Scope of work that was performed by your firm
- Summary of the project scope including construction delivery method
- Name, title and contact information for client
- Initial and final construction cost (where not deemed confidential)
- Change order percentage by type, including errors and omissions
- Planned design schedule vs actual design schedule

Include 3 references with contact information, preferably from one of the projects requested above (5 pages maximum for Section C3).

4.2.5 **Section D – Team Composition:** (35 maximum points)

Section D1 Team Structure (10 maximum points)

Describe the structure of your team, including all subconsultants. Indicate which professional design services the prime firm offers with in house staff, and indicate which professional design services the firm may opt to utilize consultants. Refer to Attachment E. (3 pages maximum. Attachment E does not count toward page limits)

Section D2 Key Personnel (25 maximum points)

Design Professional's Staff (15 maximum points)

Provide the names of the Design Professionals staff intended for use on SBBC Projects, including applicable professional qualifications. Identify the Principal to be in charge of SBBC Projects. Identify other key personnel as appropriate, including the Senior Architect and primary production Architect. Not all staff personnel need to be listed. It is understood that staffing requirements will vary from project to project based on project scope and required design time frame. Refer to Attachment B. Resumes for key personnel should be provided.

Consultants' Staffing (10 maximum points)

For each Consultant, provide the names of the Consultants Staff intended for use on SBBC Projects, including professional qualifications. Identify the Principal to be in charge of SBBC Projects. Identify a Senior Engineer for each of the disciplines that each Consultant performs. Refer to Attachment B. Resumes for key personnel should be provided.

NOTE: Section E below shall be evaluated and scored by District Staff (not QSEC)

4.2.6 **Section E - Supplier Diversity and Outreach Program** (10 maximum points)

Section E1 M/WBE Firms for Intended Use (10 maximum points)

Identify the M/WBE firm or firms who may be working with you on this engagement utilizing Attachment A, M/WBE Participation.

SECTION 5.0 - EVALUATION OF QUALIFICATIONS

5.1 Evaluation of Qualifications - The Evaluation Committee shall evaluate all Qualified Proposals by the following Categories.

<u>SECTION</u>	<u>POSSIBLE POINTS</u>
Section A – General	Pass/Fail
Section B – Required Forms	Pass/Fail
<u>Section C - Experience and Qualifications</u>	
Section C 1 - Executive Summary / Approach / Current Work Load	0 to 25
Section C 2 – Firm Experience and Qualifications	0 to 15
Section C 3 - Relevant Projects / References	0 to 15
<u>Section D - Team Composition</u>	
Section D 1 – Team Structure	0 to 10
Section D 2 – Key Personnel	0 to 25
<u>Section E - Supplier Diversity & Outreach Program</u>	
Section E 1 - M/WBE Participation	0 to 10
TOTAL POSSIBLE POINTS	100

5.1.1 Scoring of M/WBE Participation – Section E1

NOTE: Section E below shall be evaluated and scored by District Staff (not QSEC)

The SBBC shall award a maximum of ten (10) points for M/WBE Participation as listed in the Evaluation Point Tables below. At the time the proposal is submitted, the proposer shall identify all M/WBE firms (if any) which will be utilized by using the M/WBE Participation Form and Statement of Intent Form. The Letter of Intent submitted with the proposal reflects the intent of the parties (prime and sub-consultant) to establish a business relationship as well as the type of work and percentage of work that the sub-consultant will perform.

5 Points For M/WBE Designer	
M/WBE Designer	5.0 Points

5 Points For M/WBE Sub-Consultant Participation	
≥ 25%	5.0 Points
≥ 20%	4.0 Points
≥ 15%	3.0 Points
≥ 10%	2.0 Points
≥ 5%	1.0 Points

NOTE: Points for Category E shall be provided by the M/WBE Coordinator for use by QSEC members.

5.2 Qualification Selection Evaluation Committee (“QSEC”) members shall rank proposers based on the total number of points received from QSEC committee member scoring, The proposer receiving the most total points received from all QSEC members

shall be considered to be the most qualified proposer ("Firm 1"). All remaining proposers shall be ranked in order based on total points received from all QSEC members (Firm 2, Firm 3, Firm 4, and etc.).

- 5.2.1 The first tie-breaker between identically scored proposers shall be the total number of times the applicable proposers are ranked as the most qualified (Firm 1) by individual QSEC committee members.
- 5.2.2 The second tie-breaker between identically scored proposers shall be the total number of times the applicable proposers are ranked as the second most qualified ("Firm 2") by individual QSEC committee members.
- 5.2.3 The third tie-breaker between identically scored proposers shall be the total number of times the applicable proposers are ranked as the third most qualified ("Firm 3") by individual QSEC committee members.
- 5.2.4 The fourth tie-breaker shall be a coin flip, to be called in the air, by the tied proposer who held its discussions with QSEC first.
- 5.3 Failure strictly comply with the submittal requirements of sections A and B may result in a recommendation to reject the proposal.
- 5.4 After scoring has been completed, QSEC shall recommend that District staff negotiate a contract for professional design services with Firm 1 at compensation which staff determines is fair, competitive, and reasonable.
 - 5.4.1 Should staff be unable to negotiate a satisfactory contract with Firm 1, negotiations with Firm 1 shall be formally terminated.
 - 5.4.2 Staff shall then undertake negotiations with Firm 2. Should staff be unable to negotiate a satisfactory contract with Firm 2, staff shall formally terminate negotiations with Firm 2, and then undertake negotiations with Firm 3.
 - 5.4.3 This process shall continue with the remaining, most qualified firms until a satisfactory contract is negotiated. If no negotiations are successful, the procurement shall automatically terminate.
- 5.5 After successful negotiations with the applicable proposer, an Agreement shall be submitted to the Board for approval and award of a Design contract.
- 5.6 **Award:** The Agreement resulting from these negotiations shall be governed by the laws of the State of Florida, and shall have venue established in the 17th Court of Broward County, Florida or the United States Court of the Southern District of Florida.

END OF EVALUATION OF QUALIFICATIONS

SECTION 6.0 – PROJECT SCOPE AND SCHEDULE

6.1 Summary Project Scope - The Scope of Work is summarized below.

Parkway Middle School

- Fire Sprinklers
- Media Center Improvements
- HVAC Improvements
- Building Envelope Improvements

6.2 Project Budget - The Budget for this package is as follows.

Parkway Middle School

Total Funds from District's approved ADEFP:	\$ 4,209,000
Less:	
- Roofing of Bldg. 22 & 24	\$ 754,360
- School Choice and Technology	<u>\$ 288,000</u>
Total Project Budget	\$ 3,166,640
Less:	
- Other Owner Costs	<u>\$ 158,332</u>

TOTAL Design, Construction and Soft Cost Funds \$ 3,008,308

6.3 Project Schedule - The Schedule for this project is as follows:

Authorization to Proceed	January 10, 2017
Completion of Design	September 22, 2017
Final Completion – Construction	November 19, 2018

END OF RFQ

M/WBE PARTICIPATION

Complete the following information on the proposed M/WBE participation on this contract.

Proposer's Company Name: _____

M/WBE Firm Information	Scope and/or Nature of Work to be Performed by the M/WBE	% of M/WBE Participation	
Firm Name: _____ Contact Person: _____ Address: _____ _____ Telephone No.: _____ Facsimile No.: _____ M/WBE Certification No.: _____ Certifying Agency Name: _____ Address: _____ _____ Telephone No.: _____			
Firm Name: _____ Contact Person: _____ Address: _____ _____ Telephone No.: _____ Facsimile No.: _____ M/WBE Certification No.: _____ Certifying Agency Name: _____ Address: _____ _____ Telephone No.: _____			
Firm Name: _____ Contact Person: _____ Address: _____ _____ Telephone No.: _____ Facsimile No.: _____ M/WBE Certification No.: _____ Certifying Agency Name: _____ Address: _____ _____ Telephone No.: _____			

Note: percentage amount needs to be provided to receive points.

Design and Professional Consulting Staff

Prime Firm:

Name	Title	Role	Time Commitment	Florida professional license	Email Address

Subconsultant:

Name	Title	Role	Time Commitment	Florida professional license	Email Address

Subconsultant:

Name	Title	Role	Time Commitment	Florida professional license	Email Address

Subconsultant:

Name	Title	Role	Time Commitment	Florida professional license	Email Address

ATTACHMENT C

Professional Services Agreement

PROFESSIONAL SERVICES AGREEMENT

BETWEEN

THE SCHOOL BOARD OF BROWARD COUNTY, FLORIDA

AND

PROJECT CONSULTANT

FOR

ARCHITECTURAL/ENGINEERING SERVICES

THIS AGREEMENT, made this, ____ day of _____ in the year _____, by and between **THE SCHOOL BOARD OF BROWARD COUNTY, FLORIDA**, hereinafter called the "Owner", and:

hereafter called the "Project Consultant" for the following project:

Facility:

Site No.:

Project Name:

Project No.:

Fixed Limit Of Construction Cost (FLCC): \$ _____

The Owner and Project Consultant agree as follows:

TABLE OF CONTENTS

ARTICLE 1	DEFINITIONS
ARTICLE 2	PROJECT CONSULTANT SERVICES AND RESPONSIBILITIES
ARTICLE 3	SUB-CONSULTANTS
ARTICLE 4	THE OWNER'S RESPONSIBILITIES
ARTICLE 5	BASIS OF COMPENSATION
ARTICLE 6	PAYMENTS TO THE PROJECT CONSULTANT
ARTICLE 7	REUSE OF DRAWINGS, SPECIFICATIONS AND OTHER DOCUMENTS
ARTICLE 8	INDEMNIFICATION
ARTICLE 9	INSURANCE
ARTICLE 10	GENERAL PROVISIONS
ARTICLE 11	INCORPORATION OF DOCUMENTS INTO AGREEMENT

ATTACHMENTS:

Attachment 1: Project Schedule

Attachment 2: Project Scope

Attachment 3: Electronic Media Submittal Requirements

- Attachment 4: Project Consultant’s Invoice Format, Reimbursable and Supplemental Services Format
- Attachment 5: List of Project Team Members
- Attachment 6: Authorization to Proceed (ATP) Form
 - Professional Services Required – page 1 of 3
 - Project Schedule – page 2 of 3
 - Professional Fee – page 3 of 3
- Attachment 7: Document Submittal Checklist
- Attachment 8: Document 00455 – Background Screening
- Attachment 9: IRS Form W-9
- Attachment 10: Truth in Negotiations Certificate

ARTICLE 1 DEFINITIONS

- 1.1 **The Office of Facilities & Construction (“Office” or “OFC”):** The Owner’s organizational entity which acts as liaison between the Consultant and Owner and provides day to day management and other professional services on the Owner’s behalf. Various members of the Office of Facilities and Construction, acting as representatives of the Owner, will meet with the Project Consultant at periodic intervals throughout the preparation of the Contract Documents to assess the progress of the Work in accordance with approved schedules. Office personnel will also examine documents submitted by the Project Consultant, including invoices, and will promptly render decisions and/or recommendations pertaining thereto to avoid unreasonable delay in the progress of the Project Consultant's work. The Project Manager shall be principally responsible for direct communication to the Project Consultant and the Contractor.

- 1.2 **The Chief Facilities & Construction Officer, Office of Facilities & Construction -** An employee of The School Board of Broward County, Florida, who has the authority and responsibility for oversight and management of the specific project for the Owner. Referred to hereinafter as the Chief Facilities & Construction Officer.

- 1.3 **Authorization to Proceed:** A fully executed and approved authorization in the form of Attachment 6 to this Agreement, Authorization to Proceed (“ATP”) accompanied by an executed purchase order document issued by the Owner to the Project Consultant, authorizing the performance of specific professional services, authorizing commencement of a Phase as defined in Article 2.1 through Article 2.8, and stating the time for completion and the amount of fee authorized for such services.

- 1.4 **Basic Services:** Those architectural, engineering and other professional design services defined in Article 2.1 through Article 2.8.

- 1.5 **Supplemental Services:** Those architectural, engineering and other professional design services defined in Article 2.9.

- 1.6 **Project Consultant:** The individual, partnership, corporation, association, joint venture, or any combination thereof, of professional architects, engineers or other design professionals properly registered and licensed in Florida, who has entered into a contract with the Owner to provide professional services for development of the design and contract documents for the Work of this Project and provide construction contract administration and warranty services as described in the Project Manual and under this Agreement.

- 1.7 **Project Scope:** The activities necessary to respond to the Owner's requirements for the Project, including but not limited to the full or partial range of design, bidding and construction support services required to meet

the Owner's educational program, construction standards, project construction support requirements, Project Budget and Project Schedule.

- 1.8 **Project Budget:** The sum, established by the Owner, as available for the entire Project, including but not limited to the construction budget (Fixed Limit of Construction Cost (“FLCC”)), land costs, costs of furniture, fixtures and equipment (FF&E), financing costs, compensation for all professional services, costs of Owner-furnished goods and services, contingency allowances and other similar established or estimated costs.
- 1.9 **Project Schedule:** The Owner's requirements for the progress of design and construction activities associated with the Project characterized by milestones signifying the required completion dates for design phases, construction progress, and other significant project events culminating with the completion of the project, issuance of warranties, Owner's occupancy and use of the new or improved facilities.
- 1.10 **The Contract Documents:** The Contract Documents as used herein refer to the Agreement Form, Addenda, Supplementary Conditions, General Conditions, Documents contained in the Project Manual, the Owner's Division 0 and Division 1 documents, Drawings, Specifications, Education Specifications, all modifications thereto, issued before and after execution of the Contract and all Exhibits attached thereto used by the Owner to establish a construction contract with the Contractor. These Contract Documents, and their requirements for the Project Consultant are incorporated by reference into this Agreement.
- 1.11 **Contractor:** The individual, partnership, corporation, association, joint venture, or any combination thereof, who has entered into a contract with the Owner for construction of schools, administrative and support buildings, or various other types of facilities and incidents thereto.
- 1.12 **Program Manager:** An entity hired by the School Board of Broward County to execute the delivery of the projects and act as the Owner's Representative.
- 1.13 **Project Manager:** An employee or designated representative of The School Board of Broward County, Florida, who is assigned by the Chief Facilities and Construction Officer to manage the Project as a direct representative of the Owner.
- 1.14 **The Project:** The design of new construction, remodeling and/or renovation, and all services and incidents thereto, comprising a structure, structures, facility or facilities as contemplated and budgeted by the Owner.
- 1.15 **Sub-Consultant:** A person or organization of professional architects, engineers or other design professionals, registered and licensed in Florida, who has entered into an Agreement with the Project Consultant to provide professional services for the project.
- 1.16 **Superintendent Of Schools:** The duly appointed executive officer of the Owner authorized to act by and through The School Board of Broward County, Florida. Referred to hereinafter as the Superintendent.
- 1.17 **Fixed Limit of Construction Cost:** The Fixed Limit of Construction Cost, referred to hereinafter as the FLCC, is the total dollar value of the sum of the project's anticipated base bid (the project's essential scope) including design contingency.
- 1.18 **Building Code Inspector and Plans Examiners (BCI):** Employees of The School Board of Broward County, Florida, and others designated by the Chief Building Official, who are certified by Florida Statutes 468, 633 and 553 a BCI by the Florida Department of Education to provide plan review, inspections for code compliance and report non-compliant work to the appropriate party.

- 1.19 **Value Engineering:** Value Engineering (VE) is the creative, organized process of analysis of a project as to cost and/or performance with a focus on analysis of the proposed facility (and its systems, assemblies or components) and the elimination or modification of those features which add cost without contributing to that facility's required function or design value.
- 1.20 **Constructability:** Constructability is the creative, organized process of reviewing a project's drawings, specifications and other project documentation with a goal of eliminating design, detailing, and specification problems which might render the construction contract documents unbuildable or requiring extensive Addenda or Change Orders to make them buildable.
- 1.21 **The Project Team-** The Owner, Program Manager, and the Project Consultant, collectively the “Project Team”, shall work jointly during the design and through the completion of the warranty phase and shall be available thereafter should additional services be required.
- 1.22 **Substantial Completion:** The term Substantial Completion as used herein, shall mean that point at which the Work, or a designated portion thereof, is at a level of completion in substantial compliance with the Contract Documents such that the Owner or its designee can enjoy use or occupancy and can use or operate it in all respects for its intended purpose. In the event the Work includes more than one Phase, the Owner, at its discretion, may set Substantial Completion dates for each Phase and may impose provisions for liquidated damages for each Phase.
- 1.23 **Chief Building Official, Inspections and Code Compliance:** ("CBO") An employee of The School Board of Broward County, Florida, who has the responsibility for oversight and management of the Building Department, and has the authority and responsibility for issuing Building Permits.
- 1.24 **Code:** The term Code means and refs to all applicable codes, laws and regulations of each governmental entity, as may be amended from time to time, in effect at the time of execution of this Agreement, including all codes and standards referenced therein, including, but not limited to:, the Fifth Edition of the 2014 Florida Building Code (the “FBC”), the Fifth Edition of the Florida Fire Prevention Code, Chapter 1013, Florida Statutes (2015)Florida State Board of Education Regulations (“SREF”), Chapter 6A-2.0111 (Educational Facilities), the 1999 State Requirements for Educational Facilities (2014)Florida Department of Education's State Requirements for Educational Facilities (“SREF”)adopted pursuant to Rule 6A-2.0111, Florida Administrative Code, as may be amended from time to time, to the extent such requirements are not in conflict with Section 235.211, Florida Statutes 1995, Americans With Disabilities Act (ADA), in effect at the time of execution of this Agreement, and its referenced codes and standards; Crime Prevention Through Environmental Design (CPTED) (Broward Sheriff’s Office), and all guidelines and regulations of the Owner (provided same are not less stringent than applicable codes) with the Owner serving as the interpreter of the intent and meaning of SREF or any other applicable code

ARTICLE 2 PROJECT CONSULTANT SERVICES AND RESPONSIBILITIES

2.1 Basic Services

- 2.1.1 The Project Consultant agrees to:

- .1 Provide complete professional architectural, engineering and/or other professional design services set forth in the six Phases enumerated hereinafter and all necessary personnel, equipment and materials to perform such services;
 - .2 Complete those design services in accordance with the Project Schedule (Attachment 1 to this Agreement).
 - .3 Collaborate in the Owner's programs of Value Engineering at the end of Phases I and II (Schematic Design and Design Development), Constructability Reviews at the end of Phase III (Construction Documents), Statement of Probable Construction Cost at end of each phase, SIT Award Application and other additional basic services as provided in Article 2.1 through Article 2.8.
- 2.1.2 Standard Of Care: The Owner's engagement of the Project Consultant is based upon the Project Consultant's representations to the Owner that:
- .1 It is an organization of experienced design professionals, registered and licensed to do business in Florida;
 - .2 It is qualified, willing and able to perform architect and engineer of record services for the Project; and that
 - .3 It has the past experience and ability to provide design and engineering services for projects of similar size and scope which will meet the Owner's objectives and requirements.
- 2.1.3 As to all services provided pursuant to this Agreement, the Project Consultant shall furnish services by experienced personnel and under the supervision of experienced professionals licensed in Florida, and shall exercise a degree of care and diligence in the performance of these services in accordance with the customary professional standards currently practiced by firms in Florida and in compliance with any and all applicable codes, laws, ordinances, etc. The Project Consultant shall utilize the same personnel over the course of the Work and shall, if requested by the Owner, replace personnel whom the Owner has found to be incompetent or to whom the Owner otherwise reasonably objects.
- 2.1.4 As to any and all drawings, plans, specifications or other contract documents or materials provided or prepared by Project Consultant or its Sub-Consultants, the Project Consultant agrees same:
- .1 Are sufficiently complete, accurate, and adequate for bidding, negotiating and constructing the Project and are consistent with the Owner's requirements and Owner approved Project Budget and Project Schedule;
 - .2 Meet the Owner's aesthetic, functional and operational objectives;
 - .3 Are sufficiently fit and proper for the purposes intended;
 - .4 Comply with all applicable laws, statutes, rules and regulations, building codes and Owner's guidelines or regulations, which apply to and govern the Project, and
 - .5 Will, if constructed in accordance with the Project Consultant's Design, result in a complete and properly functioning facility. Any defective drawings, specifications or other document furnished by

Project Consultant shall be promptly corrected by the Project Consultant at no cost to Owner, without limitations to other remedies or rights of Owner. Owner's approval, acceptance or use of or payment for all or any part of Project Consultant's services hereunder or of the project itself shall in no way alter the Project Consultant's obligations or Owner's rights hereunder.

- .6 Further, any approval of drawings or construction documents by Owner and/or other governmental entities having jurisdiction which do not expressly comment and/or interpret a building code requirement shall not relieve the Project Consultant from its obligations to furnish design services pursuant to the applicable building codes nor be the basis for a waiver defense should Owner accept and/or approve any drawings and/or contract documents wherein an error or omission is not discovered during the design process.

2.1.5 All professional design services and associated products or instruments of those services provided by the Project Consultant shall:

- .1 Be in accordance with all applicable codes, laws and regulations of each governmental entity, as may be amended from time to time, in effect at the time of execution of this Agreement, including all codes and standards referenced therein, including, but not limited to: the Fifth Edition of the 2014 Florida Building Code (the "FBC"), the Fifth Edition of the Florida Fire Prevention Code, Chapter 1013, Florida Statutes (2015), the State Requirements for Educational Facilities (2014) ("SREF"), Crime Prevention Through Environmental Design (CPTED) (Broward Sheriff's Office), and all guidelines and regulations of the Owner (provided same are not less stringent than applicable codes) with the Owner serving as the interpreter of the intent and meaning of SREF or any other applicable code (all of the above-referenced codes, laws, regulations and standards referenced therein are herein collectively referred to as "**Code**");
- .2 Be provided for the benefit of the Owner and not for the benefit of any other party; and
- .3 Include all of the design services normally required for a project of this type as listed in the Project Scope (Attachment 2 to this Agreement).
- .4 Notwithstanding any other provisions of this Agreement to the contrary, any substantially affected person may appeal any building code dispute or interpretation of the Chief Building Official of the School Board of Broward County, Florida to the Florida Building Commission as set forth in section 1013.37, Florida Statutes and the FBC, as amended.

2.1.6 The Project Manager shall schedule and conduct a bi-weekly project review meeting with representatives of the Project Consultant throughout Phases I through IV of the Project. At each of these meetings, the Project Consultant and Owner shall review the Project's budget, schedule, and scope along with the Project Consultant's development and progress to date on the respective phases of the Project and any special problems related to the continuing progress of the project. The Project Consultant shall attend weekly meetings during Phase V (Construction) as required elsewhere in this Agreement. For each project review meeting, and as may be otherwise appropriate during any project phase, the Project Consultant shall provide progress sketches and other documents sufficient to illustrate progress and the issues at hand for the Owner's review, which will be made so as to cause no delay to the Project Schedule.

2.1.7 The Project Consultant's services shall conform to Owner's specifications, including but not limited to, Owner's Design and Materials Standards Manuals, Design Criteria, Educational Specifications, Document

Submittal Checklist for Plan Review and Owner's Forms for capital projects, provided, however, that in the event of conflict, the provisions of this Agreement shall govern.

- .1 **Non-Conforming Work:** If the Owner (by way of BCI's or other Owner personnel or consultant) observes or otherwise becomes aware of any fault or defective Work in a project, or other non-conformance with the Contract Documents during the construction phases, the Owner or Program Manager shall give prompt notice thereof to the Project Consultant. However, whether the Owner observes a defect or not, it is the Project Consultant's duty and responsibility to determine whether said Work is defective, faulty, or not in compliance with the Contract Documents. If the Project Consultant determines that the Work is defective, faulty or not in conformance with the Contract Documents, the Project Consultant shall advise the Owner in writing and make recommendations to the Owner concerning correction of the Work. The Owner may then require the Contractor to undertake such corrections as allowed by the Contract Documents. Final determination of whether the Work is defective, faulty or in compliance with the Contract Documents is to be determined by the Owner.
 - .2 **Penalty for Non-Conforming Design Documents:** Should the Project Consultant submit drawings, plans, specifications or other documents or materials for review as required herein that are deemed unacceptable as defined by the terms "Revise and Resubmit" by the plan review authority (Building Department, Design Services Department, Peer Plan Review Consultant), the costs, as solely determined by the Owner, for all subsequent reviews after the second review for that Phase shall be borne by the Project Consultant and the Owner will deduct such costs from the Project Consultant's Basic Services Fee.
- 2.1.8 The Project Consultant shall keep the Owner informed of any proposed changes in requirements or in construction materials, systems or equipment as the drawings and specifications are developed. Proposed changes must be reviewed by the Owner and approved in writing by Owner prior to incorporation into the design or construction documents.
 - 2.1.9 The Project Consultant shall coordinate with Owner by participating and taking a leadership role in, reviewing and commenting on Constructability and Value Engineering studies performed by Owner, and attending meetings, where the content of design and construction contract documents will be coordinated and reconciled, scheduled during any phase of the project. In the event Owner accepts recommendations from Value Engineering and Constructability studies, the Project Consultant shall implement same, including providing revised drawings and specifications or other documents. In the event the Owner accepts such a recommendation from the Constructability and/or Value Engineering studies and requires substantial revisions by the Project Consultant, as determined at the discretion of the Owner, these revisions shall be considered Supplemental Services.
 - 2.1.10 **Approval of Documents:** Owner's approval of or comments on any of the documents submitted to Owner by Project Consultant shall not be deemed the approval of or by another governmental authority having jurisdiction over the project and Project Consultant acknowledges that the aforesaid authorities may require modifications of any of the documents submitted by Project Consultant. Subject to Article 2, such modifications shall be made at no cost to Owner.

2.2 PHASE I - Schematic Design:

- 2.2.1 The Project Consultant shall confer with representatives of the Owner to verify and confirm the Program (as appropriate to the type of project), consisting of a detailed listing of all functions and spaces together with the square footage of each assignable space, gross square footage, and a description of the relationships between and among the principal programmatic elements. (If the project needs are so unique that a special analysis of the requirements is necessary to establish a more detailed program, such services may be authorized as Supplemental Services).
- 2.2.2 The Project Consultant shall, prior to commencing Phase I design activities, receive a fully approved and executed ATP and Purchase order (See 5.2.3), visit and inspect the site to verify if existing conditions conform to those portrayed on information as may have been provided by the Owner:
- .1 Take photographs and make written documentation, sketches, notes or reports to confirm and record the general condition and age of the existing equipment and site with particular attention to the following building/site elements as appropriate to the Project:
 - .1 All above ceiling areas.
 - .2 Power supplies, switch gear, breaker panels, electrical room, electrical vault, transformers and mechanical room.
 - .3 Major components of existing HVAC systems including chillers, cooling towers, air handling units, and primary ductwork runs.
 - .4 Roofing, waterproofing and building envelope systems.
 - .5 Site drainage systems and water retention characteristics.
 - .6 Determine age and condition of fixed equipment.
 - .7 Life safety, fire alarms, public address, generators and emergency lighting.
 - .8 ADA requirements.
 - .2 Site investigations and inspections and access to concealed areas should be non-destructive except where destructive investigations, tests or means of access are authorized in advance by the Owner.
- 2.2.3 In the event that the Project Consultant believes that the project scope, schedule or budget is not achievable, the Project Consultant shall immediately notify the Owner in writing as to the reasons one or all of them are unreasonable or not achievable immediately upon discovery.
- 2.2.4 The Project Consultant shall review with Owner alternative approaches to design and construction of the project; site use and improvements; selections of materials, building systems and equipment; potential construction methods; and, if requested, shall make a recommendation among such alternatives.
- 2.2.5 The Project Consultant shall prepare, submit and present to Owner for approval by the Owner a Design Concept and Schematics Report, comprised of the SREF requirements for Schematic Design Documents and Schematic Design Studies, including an identification of any special requirement(s) affecting the Project, a Project Development Schedule, and a Statement of Probable Construction Cost, as defined below:

- .1 "Project Transmittal Form" as required by the Facilities and Construction Management Division's Design Services Department.
- .2 OEF form 208(a) "OEF Space Chart Form" formatted to follow the sequence of spaces listed in the SREF Size of Space and Occupant Design Criteria Table.
- .3 A hardcopy and electronic media copy of a site survey with the following information: the legal description of the site, acreage, points of the compass, contours, overall dimensions, vegetation, trees, hardscape elements, adjacent highways and roads, information about ownership and use of adjacent land, locations of on- and off-site utility connections, utility service point entry locations, parking areas, service areas, play areas, athletic fields, bus loop(s), parent drop off, existing buildings with height, mechanical cooling towers and chillers, floor elevations (related to base flood elevation as shown on Flood Insurance Rate Maps), and use. The site survey will be an update of informational surveys provided by the Owner but shall be prepared on electronic media and submitted in both hard and electronic media formats. (Attachment 3 to the Agreement).
- .4 **Schematic Drawings.** These documents shall be schematic drawings responding to the educational specifications and program requirements illustrating the general scope, scale, and relationship of project components. In addition to SREF requirements and information required by the Owner's document submittal checklist for phase I, the documents shall include the following:
 - .1 A site plan showing acreage, points of the compass, scale, contours and general topographical conditions, flood plain elevation and velocity zone, over-all dimensions, adjacent highways, roads, off-site improvements, emergency access, fire hydrants, power transmission lines, ownership and use of adjacent land, walks and paths, vehicle and bike parking areas, accessibility for the disabled, service areas, play areas, athletic fields, bus loop(s), parent drop off, existing buildings and use, location of proposed building(s) and future additions, portable classrooms and other relocatable or temporary structures, community use buildings, phased construction, preliminary soil borings. A statement shall be included on the site plan identifying the FEMA flood plain and velocity zone in which the project is located. The statement shall be signed and dated by the Project Consultant.
 - .2 Evidence, as jointly developed with the Owner, showing that required environmental studies have been completed and sensitive site areas have been identified as required by Florida Law or the Owner or any governmental entity having jurisdiction over the project site.
 - .3 Floor plans showing points of the compass, over-all dimensions, identity of each space, proposed door locations, accessibility for the disabled, Florida Inventory of School House (FISH) numbers, occupant load of each space, proposed passive design and low energy usage features, possible community service areas and instructional spaces that can be converted to community use areas, mechanical and electrical rooms, any existing buildings and use, future additions, and phased construction. Provide a life-safety plan delineating the necessity for and initial decisions concerning exits, accessibility for the disabled, fire walls, protected corridors, smoke partitions, fire alarm systems, fire sprinkler systems, room names and numbers, and any other life-safety features relevant to the facility.
 - .4 Provide elevations and sections of the building to fully illustrate and indicate the mass and character of the facility including fenestration, openings, walkways, preliminary material selections, and other building features and spatial relationships.

- .5 A Preliminary Project Description comprised of a narrative discussion of preliminary material selections, components, assemblies, and systems (including proposed landscape, civil, structural, mechanical, and electrical design elements, components and systems) to be used in the project. Coordinate points of service and preliminary service requirements with Florida Power and Light (FPL), BellSouth, cable TV, water, sewer, storm drainage and other utility services as required by the Project's scope and program. Format Preliminary Project Descriptions to match that specified by the latest edition of the Construction Specification's Institute's "Manual of Practice".
- .6 Mechanical Requirements Specific to Remodeling and Addition Projects: Provide a listing of capacities for existing HVAC equipment and the available tonnage for the new connected load. Provide a survey of the condition of the existing mechanical equipment.
- .7 Electrical Requirements Specific to Remodeling and Addition Projects: Provide an electrical load analysis for the existing facility for existing and new loads. Provide a survey of the condition of the existing electrical equipment and the communication equipment room.
- .8 **A Project Design Schedule:** The Project Consultant shall prepare a schedule of services (Project Design Schedule) in compliance with Project Schedule and for approval by the Owner. Such schedule shall show activities including but not limited to Project Consultant efforts and Owner reviews and approvals required to complete services. This schedule shall initially be submitted to Owner for approval within twenty-one (21) days of execution of this Agreement. As a condition of payment, Project Consultant will submit with each invoice a copy of the approved schedule showing progress (indicated by percentage complete) as of the invoice cutoff date and a forecast of when each phase of Project Consultant's work will be complete. No subsequent payment shall be made if Project Consultant has not obtained approval of his work schedule, the schedule is not updated, or a forecast is not submitted with each invoice (provided that Owner conducts its review promptly and does not withhold its approval unreasonably). The project development schedules shall set forth in detail the following:
 - .1 Include all activities required to complete the design phase of the project.
 - .2 Prepare in a bar chart format, or other format as required by the Owner, which may be further developed and updated for submittal during subsequent phases of the Basic Services.
 - .3 The Project Consultant shall not be permitted to deviate from the milestones indicated on the Project Schedule without specific written authorization from the Owner (Attachment 1 of this Agreement).
- .9 The Statement of Probable Construction Cost: The Consultant shall submit to Owner for review and Owner's approval a schematic design phase estimate of probable construction cost prepared by an independent cost estimator approved by Owner, itemized by major categories and projected to the expected time of bid.
- .10 Twenty-five (25) copies of a Design Concept and Schematics Report which will be utilized to communicate the schematic design and shall include: Reduced color drawings (Site and building plans, elevations, sections, sketch perspectives and miscellaneous diagramming), photographs of massing and building models, a facilities list (including the number of spaces, net/gross square footages, etc.), the Project Development Schedule, and a summary design statement indicating the general design intent, conceptual development, and preliminary material, assembly and system

selections. Provide brochure with heavy stock covers and plastic comb or metal spiral binding. Additional copies of the Schematic Design Brochure if required by the Owner will be compensated as a reimbursable service approved in advance by the Owner.

- 2.2.6 The Project Consultant shall coordinate with the assistance of the Owner to determine the municipal, county and other jurisdictional agency (such as the South Florida Water Management District, etc.) coordination required for the Project and, make applications for site plan and other review as appropriate to this phase of the project. The Project Consultant shall attend and provide representation at all review meetings, workshops, hearings and Commission/Council meetings concerning the project as conducted by any and all other agencies having jurisdiction over the project.
- 2.2.7 The Project Consultant shall submit seven (7) copies of all full size documents required under this Phase, and a completed document submittal checklist, without additional charge, for review and approval by the Owner. The Project Consultant shall not proceed with the next Phase until the completion of all required presentations and reports and receipt of a written Authorization to Proceed with the next phase.
- 2.2.8 The Project Consultant shall provide presentations of the Schematic Design to the Owner's staff, Design Review Committee and to The School Board of Broward County, Florida, as required.

2.3 Phase II - Design Development:

- 2.3.1 Only after receiving a fully approved and executed ATP and Purchase order (See 5.2.3), from Owner and based on the approved Schematic Design Documents and any adjustments authorized by Owner in the Project Scope, Project Schedule or Project Budget, the Consultant shall prepare, submit and present for review and approval by the Owner, Design Development Phase documents, comprised of the SREF requirements for Design Development documents and the following:
 - .1 "Project Transmittal Form" as required by the Facilities and Construction Management Division's Design Section.
 - .2 OEF form 208 (a) "OEF Space Chart Form" formatted to follow the sequence of spaces listed in the SREF Size of Space and Occupant Design Criteria Table.
 - .3 **Documents:** These documents shall be design development drawings corresponding to the educational specifications and program requirements illustrating the general scope, scale, and relationship of project components. In addition to Phase I requirements, SREF requirements, and information required by the Owner's document submittal checklist for phase II, the documents shall include the following:
 - .1 Architectural and Civil site plan(s) showing, in addition to Phase I site survey requirements, landscaping, drainage, water retention ponds, sewage disposal and water supply system, chilled water supply and return piping and such physical features that may adversely affect or enhance the safety, health, welfare, visual environment, or comfort of the occupants.
 - .2 A statement, signed and dated by the Project Consultant or his designated Sub-Consultant, included on the site plan identifying the number of existing trees, the number and size of required trees, and the number of new trees to be planted.

- .3 Soil testing results including a copy of the Geotechnical Engineer's report on the site. When unusual soil conditions or special foundation problems are indicated, submit the proposed method of treatment.
- .4 Plan(s) including, but not be limited to, the following:
 - .1 Floor plan drawn at an architectural scale that will allow the entire facility to be shown on one sheet, without break lines and which indicates project phasing as applicable to the Project.
 - .2 Floor plans drawn at 1/8 inch or larger scale showing typical student occupied spaces or special rooms with dimensions, sanitary facilities, stairs, elevators, and identification of accessible areas for the disabled.
 - .3 Floor plans drawn at 1/4 inch or larger scale showing typical spaces or special rooms with dimensions, equipment and furnishing layouts.
 - .4 Floor plans for additions to an existing facility: Indicate the connections and tie-ins to the existing facilities, including all existing spaces, exits, plumbing fixtures and locations, and any proposed changes thereto. Distinguish between new and existing areas for renovation, remodeling, or an addition.
 - .5 Floor plans drawn at 1/4 inch or larger scale showing typical spaces or special rooms with dimensions, indicating door and window layouts.
 - .6 Reflected ceiling plans drawn at 1/4 inch or larger scale showing typical spaces or special rooms with dimensions, lighting equipment and ceiling panel layouts.
 - .7 Roof plans drawn at 1/4 inch or larger scale showing typical spaces or special rooms with dimensions, equipment layouts.
- .5 Life-safety plans to show exit strategy, rated doors, emergency wall openings, fire walls working stage protection, range and fume hoods, eye wash, emergency showers, ramps and vertical lifts.
 - .1 By symbol, indicate fire extinguishers, fire alarm equipment, smoke vents, master valves and emergency disconnects, emergency lighting, emergency power equipment, fire sprinklers, exit signs, smoke and fire dampers, and other life-safety equipment relevant to the facility.
 - .2 By symbol, indicate connections and tie-ins to existing equipment.
 - .3 For existing facilities where remodeled or renovated spaces are required and where an ADA and code conforming ramp cannot be utilized, document proposed vertical platform lifts or inclined wheelchair lifts and provide the following documents as part of or in addition to the required life safety plans:
 - .1 Sketches of proposed vertical platform lifts, including layout drawings showing the effect of the lift on existing spaces, corridor widths and exiting from the affected facility.

- .2 Sketches of proposed inclined wheel chair lift including layout drawings showing the effect of the lift on the stairway width in the folded and unfolded position, the upper and lower platform storage locations, and the effect on exiting from the affected areas of the facility.
- .6 When planning open space schools or administrative spaces, a floor plan shall be submitted showing the methods used to permanently define the means of egress, such as surface finish or color.
- .7 Plumbing fixture locations and fixture unit calculations.
- .8 All exterior building elevations and sufficient building sections as necessary to fully illustrate and indicate the scale and massing of the facility.
- .9 Typical building sections to show dimensions, proposed construction materials, and relationship of finished floor to finished grades.
- .10 Preliminary Structural Drawings including plans and sections indicating systems, connections and foundations. These drawings may be structural roughs.
- .11 Mechanical Drawings including reflected ceiling plans and a single line diagram of the duct layout, location of grease trap(s), LP gas tank location, and natural gas pipe lay out, tie in to existing utilities. Enhance systems description to include a description of proposed HVAC system equipment including the chiller, pumps, AHU's, cooling tower, electric duct heaters, etc.
- .12 Electrical Drawings including reflected ceiling plans, lighting layouts for the outdoors and interior spaces, and a one line diagram of the electrical distribution showing electrical outlets for all systems in all spaces. Provide layout for energy management, computer networking and security systems. Location of all the main components of the electrical system such as transformers, panels, and main switch board, and emergency generator, location of the intercom console, ITV head end and tower, master clock, fire alarm panel. Also, show locations of mechanical equipment such as chillers, air handler units, etc. and their respective electrical connections.
- .13 **Equipment and Furnishing Schedules:** Indicating equipment and furnishing items that will be provided by the Contractor and those that will be provided by the Owner or others.
- .14 **Outline specifications:**
 - .1 Organized according to the Specification Section numbering system specified in the Construction Specifications Institute's current edition of Masterformat on the date of execution of the Contract.
 - .2 Formatted to conform to the formats for outline specifications as established by the Construction Specifications Institute.
 - .3 Complete for Divisions 2 through 17 giving general description of all finishes, materials, and systems including civil, structural, HVAC, electrical, plumbing, and specialty items, including fire sprinklers, alarm systems, electronic controls and computer networking components.
- .15 Office of Educational Facilities Life-Cycle Cost Analysis (LCCA). LCCA shall be submitted to the Owner for review and approval with the Phase II documents. LCCA shall be by a commercially available life-cycle cost analysis program, and as required by the Department of Education and the

Owner. Life Cycle Cost Analysis shall be compared among competing providers in accordance with Ch. 1013.451, Florida Statutes.

- .16 Florida Energy Efficiency Code for Building Construction (FEEC). FEEC forms, including calculations for mechanical systems, documenting energy efficiency ratio rating of HVAC equipment, electrical systems, insulation, and building envelope shall be submitted to the Owner for review and approval with the Phase II documents.
- .17 The Project Consultant shall advise Owner of any adjustments to the Schematic Design Phase estimate of probable construction cost and shall submit to Owner a fully detailed Design Development Phase estimate of probable construction cost, by an independent cost estimator approved by Owner, projected to the expected time of bid and containing sufficient detail to provide information necessary to evaluate compliance with the Project Budget set for this project. Format estimate and provide detail matching the organization and content of the project's Outline Specifications complete for Divisions 2 through 17 including all finishes, materials, and systems including civil, structural, HVAC, electrical, plumbing, and specialty items, including fire sprinklers, alarm systems, electronic controls and computer networking components.

Utilize the current edition of MasterFormat as published by the Construction Specifications Institute to organize the estimate.
- .18 An updated Project Design Schedule reflecting development and anticipated schedules for all subsequent project activities.
- .19 A written response from the Project Consultant and each of the major technical disciplines and any necessary Sub-Consultants explaining how each previous review comment (as generated by the Owner and/or other reviewing agencies) concerning the project have been addressed and/or corrected.
- .20 A simplified single line floor plan of the project; a database format schedule reflecting the room numbers; the name of the room or space; the net square footage of the space and the capacity of the space on electronic media conforming to the Owner's standards for graphics and for electronic media submittals. This drawing and database information will be for use in preparing F.I.S.H. (Florida Inventory of School Houses) information. The Project Consultant shall coordinate with and utilize the Owner's F.I.S.H requirements for room numbers, room name assignments and electronic media (format, layering, etc.) prior to developing final documents for this submittal. Hardcopy graphics shall be suitable for clearly legible half size reductions. Comply with the Owner's requirements for electronic media specified below.
- .21 A letter indicating, after coordination with the Facilities and Construction Management Division's Environmental Section, the extent of any known or suspected asbestos containing materials or other potentially hazardous materials which might require mitigation by the Owner prior to or during construction of the Project. Establish and confirm responsibility for removing the asbestos or other hazardous materials in the design development documents and coordinate with Project Development Schedule, Statement of Probable Construction Cost and other documentation.
- .22 Preliminary colorboards to review the color selections for all finish materials with the Owner.

.23 Twenty-five (25) copies of a Design Development Brochure which will be utilized to communicate the design as developed to date and shall include updated and enhanced contents of those brochures required at the Schematic Design Phase complete as necessary to illustrate the developed design, schedules, etc. Additional copies of the Design Development Brochure if required by the Owner will be compensated as a reimbursable service approved in advance by the Owner.

2.3.2 Staff from each of the Project Consultant's major technical disciplines and Sub-Consultants as necessary shall attend coordination, review and presentation meetings with the Owner to explain the design concept and technical resolution of their respective building or site systems.

2.3.3 The Project Consultant shall submit seven (7) sets of all documents required under this Phase (except as otherwise indicated), without additional charge, for review and approval by the Owner, and the Project Consultant shall not proceed with the next Phase until the completion of all required presentations and reports and receipt of a written Authorization to Proceed with the next phase.

2.4 Phase III - Construction Documents Development:

2.4.1 Only after receiving a fully approved and executed ATP and Purchase order (See 5.2.3) from Owner and based on the approved Design Development Phase documents and any adjustments in the scope or quality of the project or in the Fixed Limit of Construction Cost authorized by Owner, the Project Consultant shall prepare for approval by Owner and the Florida Department of Education, and in accordance with SREF requirements and the Owner's formats, Final Construction Documents setting forth in detail the requirements for the construction of the Project. The Project Consultant is responsible for the full compliance of the design with all applicable codes.

2.4.2 **50% Construction Documents Submittal:** The Project Consultant shall make a 50% Construction Documents submittal, for review and approval by the Owner, which shall include seven (7) sets of the following:

.1 "Project Transmittal Form" as required by the Facilities and Construction Management Division's Design Section.

.2 An updated OEF form 208(a) "OEF Space Chart Form" formatted to follow the sequence of spaces listed in the SREF Size of Space and Occupant Design Criteria Table.

.3 Updated Florida Energy Efficiency Code for Building Construction (FEEC) compliance forms. Submit seven (7) copies signed and sealed by a State of Florida registered design professional with 50% Contract Documents submittal.

.4 **Preliminary calculations:** Provide preliminary calculations for structural, mechanical and electrical systems.

.5 **Drawings:** These documents shall be 50% construction drawings corresponding to the educational specifications and program requirements illustrating the general scope, scale, and relationship of project components. In addition to Phase II requirements, SREF requirements, and information required by the Owner's document submittal checklist for phase III 50%, the documents shall include the following:

.1 Site Plan(s) and detailing which, in addition to the Phase II requirements, indicate:

- .1 Spot elevations, based on the civil grading plan, for the perimeter of the new additions, sidewalk, or any other areas pertinent to the drainage of rainwater.
 - .2 Location of storm water service for new additions roof drainage.
 - .3 Parking lot lighting poles location and type.
 - .4 Final location for manholes, handholes, pull boxes.
 - .5 Layout of underground distribution systems (normal power emergency power, fire alarm, master clock, intercommunication, television, telephone, security, control and spares).
 - .6 Locations of all site improvements, playground and athletic equipment, street furniture, planters and other features.
 - .7 Details of all curbing, typical parking spaces (regular and handicap accessible), handicap ramps, bus loop(s), parent drop-off, directional signage, site lighting, flagpole and fence foundations, and any other site conditions pertinent to the scope of work.
 - .8 Plans of new playcourts, tennis courts, tracks, event pads and other pertinent athletic, physical education or recreational areas provided with court markings and detailing for basketball goals, volleyball sleeves, tennis nets, and other playcourt equipment or accessories.
- .2 A plan to delineate staging areas, site barriers and other area designations to control and separate students, faculty, staff and the public from construction activities and traffic.
 - .3 Landscape plans and detail including a plant list clearly noted and cross referenced, details for shrub and tree plantings, identification of plants and trees to remain, be removed or relocated, and other necessary documentation.
 - .4 Irrigation plans and details delineating the entire area of the project, and addressing necessary connections, alteration, repair or replacement of any existing irrigation systems.
 - .5 **Full floor plans including:**
 - .1 All dimensions and any cross references explaining the extent of Work, wall types, or other component, assembly or direction regarding the Construction.
 - .2 Note all chases and delineate all rainwater leaders.
 - .3 Show structural tie columns and coordinate with the floor plan.
 - .4 Cross referenced interior elevations.
 - .5 Delineate and note all built-in cabinetry or equipment.
 - .6 Identify room (F.I.S.H.) and door numbers with all doors having individual numbers.

- .6 **Demolition Plans:** Indicate required demolition activities. as follows:
- .1 Provide separate demolition plan(s) and other drawings (elevations, sections, etc.) as necessary if the scope of work includes demolition which is too excessive to indicate drawings depicting new construction.
 - .2 Indicate notes on the extent of the demolition: address dimensions at locations where partial walls are being removed or altered, existing room names and numbers, existing partitions, equipment, plumbing, HVAC or electrical elements.
 - .3 Include notes dealing with protection of existing areas as a result of demolition.
 - .4 Delineate any modifications to existing buildings involving structural elements within the structural documents rather than on the architectural.
- .7 Building elevations developed further than at Phase II and including delineation of building joints (including dimensionally located stucco control joints), material locations, elevation heights, and other building features.
- .8 Building and wall sections to establish vertical controls and construction types for the Project. Include clear graphics, and notes on construction assemblies and systems to be used, dimensions, heights. Provide associated detailing to delineate solutions for difficult connections. Specify details for any fire walls to be constructed.
- .9 Reflected ceiling plans indicating ceiling types, heights, light fixture types, mechanical diffuser locations, and sprinkler heads if area is sprinklered. Delineate and detail any dropped soffits or joint conditions between different materials. Ensure coordination with architectural, electrical, mechanical and plumbing disciplines and work of any applicable Sub-Consultants.
- .10 **Roof plans:**
- .1 Indicating all roof penetrations, including drains, scuppers, mechanical exhaust fans, any other equipment on the roof, slopes of roof with elevations shown, type of roofing system to be used, expansion joints, typical parapet and flashing details.
 - .2 Dimensions to locate the items noted previously, and cross references shown.
- .11 Large scale building details as appropriate to this level of document development and as required to establish vertical controls for the Project. Include clear graphics, and notes on construction assemblies and systems to be used, dimensions, heights. Provide associated detailing to delineate solutions for difficult connections.
- .12 Interior elevations of all classroom designs including cross references of cabinetry details, dimensions and heights, notes indicating type of equipment (and whether equipment is in or out of contract), wall materials, finishes, and classroom equipment and accessories.
- .13 Details of casework as necessary to appropriately delineate custom or pre-manufactured casework. Provide appropriate schedules referencing manufacturer's numbers or catalogs, finishes, hardware and other construction characteristics.

.14 Details of the following:

- .1 Door jamb, head and sill conditions.
- .2 Wall and partition types.
- .3 Window head, sill and jamb conditions, and anchorage methods shown, in lieu of referencing to manufacturer's standards.
- .4 Interior signage to include classroom and building identification, emergency exiting and equipment signs, and any other items pertinent to the identification of the project. Coordinate with electrical discipline.
- .5 Interior or exterior expansion control connections.
- .6 Any other specialized items necessary to clearly express the intent of the project design.

.15 Room finish and door schedules coordinated with the floor plans, developed beyond Phase II.

.16 Structural foundation and framing plans, with associated diagrams, schedules, notes, detailing and section drawings completed sufficiently to communicate the design intent and coordination with other disciplines.

.17 Mechanical Drawings:

- .1 Provide double line duct work layout and HVAC equipment layout drawings with related diagrams and schematic diagrams, schedules, notes, detailing and section drawings completed sufficiently to communicate the design intent and coordination with other disciplines.
- .2 Provide plumbing equipment and fixture layout drawings with related diagrams, schedules, notes, detailing and section drawings completed sufficiently to communicate the design intent and coordination with other disciplines.
- .3 Provide 1/2 inch scale plans, elevations and sections of the mechanical rooms showing service clearance, room openings, nominal equipment size, ceiling height, duct clearance between bottom of joist and top of ceiling and any ceiling mounted lighting fixtures, electrical equipment or other building assembly or component, etc.

.18 Electrical: Provide drawings for the following systems:

- .1 Lighting including circuiting and luminaire identification and switching. Also provide illuminance computer printout for all indoor typical indoor spaces and parking lots.
- .2 Convenience outlets and circuiting, special outlets and circuiting, television outlets, and power systems and equipment. Provide riser diagrams for all electrical systems including master clock, intercom, fire alarm, ITV, computer networking/telephone. Also, provide for emergency and normal power distribution. Provide luminaire schedule.

- .3 Panel schedule may be in preliminary form but circuitry must be included.
 - .4 Applicable installation details.
 - .5 General legend and list of abbreviations.
 - .6 Voltage drop computation for all main feeders.
 - .7 Short circuit analysis
 - .8 Provide 1/2" scale floor plan and wall elevations for all electrical rooms.
 - .9 Indicate surge protector for main switchboard and electrical panels.
- .6 **Progress specifications:**
- .1 Provide preliminary Project Manual including front end documents. Completion of fill-in items in Bidding documents and other "Division 0" documents is not required.
 - .2 Provide a preliminary Division 1 based upon the standard documents provided by the Owner, and edited by the Project Consultant after consultation with the Owner to establish project specific requirements.
 - .3 Include progress set of all other Sections in Divisions 2-17 with each section developed to demonstrate to the Owner an understanding of the project and an appropriate level of developmental progress comparable to that of the drawings.
 - .4 Specification sections shall be organized to follow the Construction Specification Institute's (CSI) current edition of MasterFormat with each section developed to include CSI's standard 3-part section and page formats with full paragraph numbering.
 - .7 An updated Project Design Schedule, reflecting continued Project development and illustrating anticipated schedules for all subsequent project activities including permitting and submittal coordination with all agencies having jurisdiction on the Project. Format updated schedule as a Bar Chart (Gantt Chart) type schedule with milestones.
 - .8 Colorboards illustrating color selections, finishes, textures and aesthetic qualities for all finish materials for final review and approval by the Owner and to establish a final pallet of material selections for development of subsequent specifications, schedules and other requirements for incorporation into the Contract Documents.
 - .9 A letter from the Project Consultant and each of the major technical disciplines and any necessary Sub-Consultants or explaining how each previous comment concerning the project has been addressed and/or corrected.

2.4.3 100% Construction Documents Submittal:

- .1 Upon receipt of written approval of the Phase III 50 % Construction Documents and a fully approved and executed ATP and Purchase order (See 5.2.3), the Project Consultant shall proceed with the rest

of Phase III Construction Documents.

- .2 Upon 100% completion of the Construction Documents, the Project Consultant shall submit to the Owner seven (7) copies of check sets of the Drawings, Specifications, reports, programs, a final up-dated Project Development Schedule, a final up-dated Statement of Probable Construction Cost and such other documents as reasonably required by Owner. The 100% construction documents shall conform to SREF requirements, all mandatory requirements cited by the Florida Department of Education (or the designated reviewer) and those listed below.
- .3 All documents for this phase shall be provided in both hard copy and in electronic media. The Owner will review and approve Phase III documents for submission to the Department of Education (or designated reviewing agency) for review and approval. The following Phase III contract documents shall be included with the Phase III submittal:
 - .1 "Project Transmittal Form" as required by the Facilities and Construction Management Division's Design Section.
 - .2 OEF form 208 "OEF Project Transmittal Form".
 - .3 OEF form 208 (a) "OEF Space Chart Form" formatted to follow the sequence of spaces listed in the SREF Size of Space and Occupant Design Criteria Table.

4 **General Requirements.**

- .1 **Record Set.** This submittal is the official record set and shall be the bid documents.
- .2 **Signed and Sealed/Statements of Compliance:** Only complete documents, properly signed and sealed by the Project Consultant and respective Sub-Consultants, will be accepted for review; in addition, these documents shall contain a statement of compliance by the architect or engineer of record that "To the best of my knowledge and belief these drawings and the project manual are complete, and comply with the State Requirements for Educational Facilities and all applicable and referenced building codes".
- .3 When requested by the Owner, engineering calculations for mechanical, electrical, and structural systems shall be submitted separately from drawings and the project manual.
- .6 **Drawings.** These documents shall be 100% construction drawings corresponding to the educational specifications and program requirements illustrating the general scope, scale, and relationship of project components. In addition to Phase III 50% requirements, SREF requirements, and information required by the Owner's document submittal checklist for phase III 100%, the documents shall include the following:
 - .1 Site plans including, but not limited to, area location map, legal description of property, demolition, excavation, utilities, finish grading, landscaping, mechanical, electrical, civil/structural, and architectural site plans.
 - .2 Plans and details including, but not limited to:

- .1 Title sheets including listing of Project Consultant, Program Manager, School Board of Broward County, a table of contents and statement of compliance by the architect or engineer of record. Each discipline shall have a list of abbreviations, schedule of material indications, and schedule of notations and symbols at the beginning of their section of the plans.
 - .2 Architectural sheets including floor plans, door, window and finish schedules, roof plans, elevations, sections, and details.
 - .3 Civil/Structural sheets including paving; bus loops; parent drop; service drive; parking; drainage; foundation plans; floor plans; roof plans; structural plans; sections; details; and, pipe, culvert, beam and column schedules.
 - .4 Mechanical sheets including floor plans; sections; details; riser diagrams; kitchen exhaust hoods; and, equipment, fan, and fixture schedules.
 - .5 Electrical sheets including floor plans; sections; details; riser diagrams; and, fixture and panel schedules.
 - .6 The drawings should indicate that the approved mechanical/electrical systems, from the Phase II FEEC/LCCA analysis, have been incorporated into the documents.
- .6 **Project Manual.** The Project Consultant, in its leadership capacity, shall review and coordinate with the Owner regarding the preparation of the following:
- .1 The necessary bidding information, the bidding forms, the conditions of the contract and Division 1 with respect to the foregoing documents and regarding any other Agreements necessary for construction of the project. However, in no case will Project Consultant amend or delete items from these documents without prior review and written approval from Owner.
 - .2 A project specific set of Division 1 specifications based upon master documents provided by the Owner, including all schedules, lists and inventories as required to complete the Owner's master documents including Contractor's Submittal schedules, warranty schedules, salvage schedules, preliminary construction schedule, etc.
 - .3 Final specification sections for Divisions 2 through 17 organized and formatted as required for the set of Phase III, 50% progress specifications.
 - .4 Approved alternate bid items, if required and authorized by the Owner, to bring the project within the Fixed Limit of Construction Cost (FLCC) which would permit Owner in its sole discretion to accept or reject portions of the construction of the project. No additional compensation shall be provided for bid alternates if they are part of the original scope of work.
- .7 A threshold building inspection plan, prepared by the Project Consultant, and the name of a certified threshold building inspector, as set forth in Section 553.79(5), Florida Statutes (2004) as amended from time to time, shall be submitted to the Owner and the Department of Education (as applicable) for review and approval with Phase III documents. Threshold building inspection plan documents shall be submitted for:

- .1 Any building greater than three (3) stories or fifty (50) feet in height, or
- .2 Any building with an assembly space that exceeds five thousand (5000) square feet in area, and an occupant load of five hundred (500) or more persons.
- .8 An Updated Statement of Probable Construction Cost as indicated by time factor, changes in requirements, or general market conditions.
- .9 A letter from the Project Consultant and each of the major technical disciplines and any necessary Sub-Consultants explaining how each previous review comment (as generated by the Owner and/or other reviewing agencies) concerning the project has been addressed and/or corrected.
- .4 If the Latest Statement of Probable Construction Cost exceeds the Fixed Limit of Construction Cost for construction, the Project Consultant shall review the materials, equipment, component systems and types of construction included in the Contract Documents with the Owner and may recommend changes in such items and/or reasonable adjustments in the scope of the Project (to be made at no additional cost to the Owner).
- .5 The Project Consultant shall make all required changes or additions and resolve all questions on the documents. The 100% complete Check Set shall be returned to the Owner. Upon final review and approval by the Owner the Project Consultant shall furnish seven (7) copies, signed and sealed of all Drawings and Specifications to the Owner without additional charge.
- .6 The Project Consultant shall, with the Owner's assistance, file the required documents for approval by governmental authorities having jurisdiction over the Project (including Broward County and municipalities and their constituent departments, the South Florida Water Management District, and other state, local or federal agency with jurisdictional authority over some aspect of the Project) and obtain certifications of "permit approval" by reviewing authorities prior to the commencement of Phase IV and early enough to ensure that the eventual contractors is not delayed by permit processing by Broward County, a municipality or other jurisdictional agency. The Project Consultant shall provide the original documents or reproducible copies as may be required for submittal to any and all governmental authorities. The Project Consultant shall attend and provide representation at all review meetings, workshops, hearings and Commission/Council meetings concerning the project as conducted by other jurisdictional agencies. Project Consultant shall assure the Owner that all mandatory requirements are complete prior to the bidding, included, but not limited to, those that may have a financial impact on the Project.
- .7 Staff from each of the Project Consultant's major technical disciplines and Sub-Consultants as necessary shall attend coordination, review and presentation meetings with the Owner to explain the development of the design concept and technical resolution of their respective building or site systems for both the Phase III, 50% and Phase III, 100% Submittals.
- .8 The Owner's review and approval of the drawings, specifications, calculations and other construction documents shall not relieve the Project Consultant of any responsibility for their accuracy, adequacy and completeness.

2.4.4 The Project Consultant shall make all changes to the documents as required by the Owner's review of the documents by issuing a written recommendation to the Owner, at no additional cost and resolve initially all questions of constructability, code compliance, coordination across disciplines, clarity of documents, compliance with Owner standards, or other issues raised by the Owner during their reviews of the documents. The Owner will retain the documents submitted at this phase.

2.5 Phase IV - Bidding and Award of Contract

2.5.1 **Bid Documents Approvals and Printing:** Upon obtaining a fully approved and executed ATP and Purchase order (See 5.2.3), and all necessary approvals of the Construction Documents, and review and, approval by the Owner of the latest Statement of Probable Construction Cost, the Project Consultant shall assist Owner in obtaining bids and awarding construction contracts. The Project Consultant will provide reproductions of the drawings and specifications for bidding purposes at no additional cost to the Owner.

2.5.2 The Owner will issue the Bid Documents to prospective bidders and keep a complete "List of Bidders."

2.5.3 The Project Consultant shall render initial interpretations and clarifications of the drawings and specifications in a written format, supplemented by appropriate graphics. The Owner shall make all final determinations and/or interpretations as it relates to building code issues.

2.5.4 The Project Consultant shall attend a pre-bid conference as requested by the Owner.

2.5.5 The Project Consultant shall prepare addenda, if any are required, for the Owner to issue to all prospective bidders. No addenda shall be issued without the Owner's approval and if dimensional changes or extensive graphic changes are required the drawing sheets shall be revised and issued as addendum drawings as directed by Owner.

2.5.6 The Project Consultant shall be present at the opening of bids with the Owner's staff.

2.5.7 The Project Consultant shall participate with Owner in evaluating the bids and shall provide a written recommendation for bid award.

2.5.8 If the lowest responsive Base Bid received exceeds the Fixed Limit of Construction Cost the Owner will either:

- .1 Approve the increase of Project costs and award a contract or,
- .2 Reject all bids and rebid the Project within a reasonable time with no change in the Project,
- .3 Direct the Project Consultant to revise the Project scope or quality, or both, as approved by the Owner, and rebid the Project, or
- .4 Suspend or abandon the Project, or

2.5.9 Under Article 2.5.6.2 above, the Project Consultant shall, without additional compensation, modify the Construction Documents as necessary to bring the project within the Fixed Limit of Construction Cost. The providing of such service shall be the limit of the Project Consultant's responsibility in this regard and having done so, the Project Consultant shall be compensated in accordance with this Agreement. The Owner may

recognize exceptional construction market cost fluctuations before exercising the option provided in Article 2.5.6.2 above. The Owner agrees to discuss this issue with the Project Consultant prior to exercising this option.

- 2.5.10 If an estimate or cost analysis is required by the Owner for this phase, the Project Consultant shall utilize the previously established independent cost estimator, or a replacement acceptable to the Owner, to analyze bids and to assist in the preparation of any modified bidding documents or re-bid documents that may be required to ensure successful bidding within the Fixed Limit of Construction Cost.

2.6 Phase V - Administration of the Construction Contract:

- 2.6.1 The Construction Administration Phase will begin with the award of the Construction Contract and will end when the Contractor's final Payment Certificate is approved by the Owner and after the one (1) year warranty period has expired. During this period, the Project Consultant shall provide Administration of the Construction Contract as set forth in the construction contract documents (hereafter referred to and defined as the "Contract Documents") between the Owner and the Contractor, as basic services.

- 2.6.2 The Project Consultant, as a representative of the Owner during the Construction Phase, shall advise and consult with the Owner within the limits established by this Agreement and the Contract Documents. The Project Consultant shall contemporaneously provide Owner with copies of all communications between Project Consultant and others concerning matters material to the cost, time, sequence, scope, performance or requirements of the project.

- 2.6.3 The Project Consultant and the Project Consultant's respective Sub-Consultants shall attend all key construction events as necessary to ascertain the progress of the Project and to determine in general if the Work is proceeding in accordance with the Contract Documents and the Project Schedule. A minimum of at least one site visit per week will be required by the Project Consultant. The Sub-Consultant will be required to visit the site at least once a week when their respective portion of the work is in progress.

- .1 The Project Consultant shall visit the site at least once per week to become familiar with the progress and quality of the Work and to determine if the Work is proceeding in accordance with the Contract Documents and Project Schedule. The Project Consultant shall coordinate the timing of these visits with the Owner's Representative so as to permit joint observations of the progress of the Work and discussions about project issues. On the basis of on-site observations as a Consultant, the Project Consultant shall keep Owner informed of the progress and quality of the Work. The Project Consultant shall promptly submit to Owner a detailed written report of the results of each visit to the site, and copies of all field reports and notes of meetings with contractor, subcontractors of any tier or suppliers.

- .2 The Project Consultant shall, based upon its on-site visits, promptly report to Owner any defects and deficiencies in the Work coming to the attention of Project Consultant and shall endeavor to guard the Owner against defects and deficiencies in the Work. This obligation is not reduced or limited by the fact that others, such as the UBCI, are undertaking inspection for or on behalf of the Owner. The Project Consultant shall make on-site observations utilizing the same personnel over the course of the Work. The Project Consultant shall assist the Owner in determining the cost of additional inspections due to the Contractor's failure to perform. Any changes in personnel must be in writing and issued to the Owner.

- .3 The Project Consultant shall not have control over or charge of and shall not be responsible for construction means, methods, techniques, sequences or procedures, or for safety precautions and programs in connection with the Work.
- 2.6.4 The Project Consultant shall at all times have access to the Work where ever it is in preparation or progress. The Project Consultant and the Sub-Consultants shall review and advise the Owner as to whether the Contractor is making timely, accurate, and complete notations on the "Project Record Documents" and maintaining various other administrative records as required by the Contract Documents. In addition, the Owner may at its discretion require the Project Consultant and all Sub-Consultants to submit additional written materials or forms to the Owner relating to or regarding the Project or its progress. Complete notations to the "as built" drawings shall include, but not be limited to all changes due to RFI's, ASI's, COD's, and CO's, in addition to the changes recorded by the Contractor, as noted above.
- 2.6.5 The Project Consultant shall initially interpret matters and provide recommendations concerning performance of Owner and Contractor under the requirements of the Contract Documents upon written request of Owner. The Project Consultant's response to such requests shall be made with reasonable promptness and within any time limits agreed upon. The Project Consultant shall render written advisory decisions, only upon the Owner's request, within a reasonable time, on all claims, disputes and other matters in question between Owner and Contractor relating to the execution or progress of the Work or the interpretation of the Contract Documents.
- 2.6.6 All initial interpretations and advisory decisions of the Project Consultant shall be consistent with the intent of, and reasonably inferable from, the Contract Documents and shall be in writing or in the form of drawings. In the capacity of interpreter the Project Consultant shall endeavor to secure faithful performance by both the Owner and Contractor, and shall not show partiality to either. The Owner shall be the final interpreter of any and all matters pertaining to the performance of the Project Consultant and Contractor.
- 2.6.7 The Project Consultant shall have authority to recommend rejection of Work which does not conform to the Contract Documents. The Project Consultant shall not have authority to stop the Work without approval of the Owner. Whenever, in the Project Consultant's reasonable opinion, it is necessary or advisable for the implementation of the intent of the Contract Documents, Project Consultant may recommend special inspection or testing of the Work in accordance with the provisions of the Contract Documents, whether or not such Work is to be fabricated, installed or completed, but Project Consultant shall take such action only after consultation with Owner. The Project Consultant's monitoring of such additional special testing or inspections is a part of the Basic Services. Owner shall furnish all such tests, inspections and reports that are required by law or by the Contract Documents or that it has previously approved in writing, without waiving its right to reimbursement from Contractor. However, neither this authority of the Project Consultant nor a decision made in good faith either to exercise or not to exercise such authority shall give rise to a duty of responsibility of the Project Consultant to Contractor or other third parties performing portions of the Work.
- 2.6.8 The Project Consultant shall promptly review, and take other appropriate action upon Contractor's submittals such as shop drawings, product data and samples, but only for conformance with the design concept of the Contract Documents. Such action shall be taken within fourteen (14) days of receipt by Project Consultant unless Owner and Project Consultant otherwise mutually agree. Project Consultant's review shall not constitute review or approval of safety precautions or of construction means, methods, techniques, sequences or procedures. Project Consultant shall maintain a log of all submittals made and shall compare the submittals with Contractor's progress schedule. The Consultant shall not approve changes to the contract or substitutions through the regular submittal process but will utilize those respective methods specified in the Contract Documents. The Project Consultant shall be compensated for reviewing re-submittals after the first

re-submittal of a respective submittal as a reimbursable expense with the Owner reimbursed by the Contractor under provisions of the Contract Documents.

2.6.9 The Project Consultant shall coordinate with the Owner concerning the Owner's required review of Request for Proposals, Change Orders and Construction Change Directives. The Project Consultant shall:

- .1 Meet with the Owner prior to the preparation and execution of Request for Proposals, Contingency Use Directives and Change Order items to ensure that proposed changes comply with the intent of the Project's scope and construction schedule and whether the Contractor is entitled to additional sums or contract time for the proposed Work.
- .2 Reconcile the Project Consultant's analysis of Request for Proposals, Contingency Use Directives and Change Order amounts with an analysis provided by Owner's chosen independent cost estimator and provide the Owner with a recommendation concerning the respective cost studies.
- .3 Submit written and graphic information documenting proposed changes for formal review by the Owner.
- .4 Review and indicate concurrence through signing Request for Proposals for Owner's authorization in accordance with the Contract Documents, shall have authority to order minor changes in the Work not involving an adjustment in the contract sum or an extension of the contract time and which are not inconsistent with the intent of the Contract Documents. Such minor changes shall be implemented through an Architect's Supplemental Instructions (ASI) issued through Owner. The Basic Services shall include providing recommendations concerning Request for Proposals, Contingency Use Directives and Change Orders, and the preparation, permitting and processing of Request for Proposals, Change Orders and Construction Change Directives. This Article shall not supersede Articles 2.9.1.14 or 2.9.1.16.
- .5 Process, prepare and issue contract modification documents, Request for Proposals, Contingency Use Directives and Change Orders, in a timely manner and not allow the period required for evaluation, preparation or to issue such documents to exceed fourteen (14) days. The Project Consultant shall provide written notification to the Owner concerning those modification documents requiring more than fourteen (14) days processing time with an attached explanation of the circumstances requiring longer processing time.
- .6 All final decisions with respect to substitutions, Request for Proposals, Change Orders, and other contract modifications shall be at the sole determination of the Owner.

2.6.10 The Project Consultant shall conduct thorough site observations, make recommendations and otherwise assist Owner in determining the dates of Substantial Completion and Final Completion, shall review, approve and forward to Owner for Owner's review, written warranties and related documents required by the Contract Documents and assembled by Contractor, and shall certify a final certificate for payment. At substantial completion, the Project Consultant shall prepare a punch list of observed items requiring correction, completion or replacement by Contractor. The Project Consultant shall administer the Contractor's submittal of various closeout submittals including warranty documents, operations and maintenance materials, extra materials, and other closeout submittals as required by the Contract Documents. The Project Consultant and the Sub-Consultants shall verify and confirm the Contractor's successful demonstration of equipment and systems and the training of the Owner's personnel as required by the Contract Documents. Project Consultant shall inspect the Project upon final completion to determine compliance with the Contract Documents and,

upon so determining, prepare and execute the required forms and other documents indicating that the Work is completed in compliance with the Contract Documents.

- 2.6.11 The Project Consultant shall within sixty (60) days of final acceptance provide the Owner with prints and electronic media copies of the original drawings, which the Project Consultant has revised to conditions based on information furnished by the Contractor as Project Record Documents. These prints and electronic media copies shall become the property of the Owner. Submittal of these documents to the Owner is a condition of final payment of construction support fees to the Project Consultant.
- 2.6.12 The Project Consultant shall assist Owner in determining amounts owing to Contractor based on observation at the site and an evaluation of Contractor's applications for payment and shall certify Certificates for Payment of such amounts as provided in the contract documents and in such forms as the Owner may request. The certification of the Certificate for Payment shall constitute the representation by Project Consultant to Owner based on Project Consultant's observation at the site and the data comprising Contractor's applications for payment, that the work has progressed to the point indicated; the quality of the work is in substantial accordance with the contract documents (subject to an evaluation of the work for substantial conformance with the contract documents upon substantial completion, to the results of any subsequent test by or performed under the contract documents, to minor deviations from the contract documents cited prior to completion, and to any specific qualification stated in the Certificate for Payment); and that the Contractor is entitled to the amount certified. However, the certification of the Certificate of Payment shall not be a representation that Project Consultant has made any examination, other than information which has come to Project Consultant's attention, to ascertain how and for what purpose Contractor has used the monies paid by the Owner.

2.7 Phase VI - Warranty Administration:

- 2.7.1 Upon receiving a fully approved and executed ATP and Purchase order (See 5.2.3), and for one year following substantial completion of the construction project, the Project Consultant shall assist Owner, without additional compensation, in securing correction of defects, and shall in the sixth and eleventh months make inspections of the project with the Owner and report observed discrepancies to Owner.

2.8 Other Basic Services:

- 2.8.1 The Project Consultant shall render to Owner without additional compensation, any proper and reasonable assistance which Owner may require as a result of any claim or any action brought relating to Project Consultant's services. Preparation of detailed analysis or documentation (if requested by Owner) shall be a supplemental service under Article 2.9.1.21 with a fully approved and executed ATP and Purchase order (See 5.2.3).

2.9 Supplemental Services

- 2.9.1 The services listed below are normally considered to be beyond the scope of Basic Services as defined in this Agreement, and if authorized in advance by having received a fully approved and executed ATP and Purchase order (See 5.2.3), will be compensated for as provided under Articles 5.7 and 6.2:
- .1 Providing special analyses of the Owner's needs, and special detailed programming requirements for a project.
 - .2 Providing financial feasibility, or other special studies.

- .3 Providing planning surveys, site evaluations, or comparative studies of prospective sites.
- .4 Providing services relative to future facilities, systems and equipment which are not intended to be constructed as during the construction phase.
- .5 Providing services to make measured drawings of the existing site or facilities.
- .6 Providing the services of a cost estimating firm beyond the services required during Phases I-III to verify cost of the work as designed. The choice of the firm, qualifications of the firm and the terms of employment of the firm shall be approved in writing in advance by the Owner.
- .7 Providing interior design services required for or in connection with the selection of furniture or furnishings, except equipment included in the Construction Contract and identified in the educational specifications.
- .8 Providing investigations and making detailed appraisals and valuations of existing facilities, and surveys or inventories required in connection with construction performed by the Owner.
- .10 Providing the services of one or more full-time Construction Inspector during construction; including the services of a Special Threshold Inspector.
- .11 Providing extended assistance beyond that provided under Basic Services for the initial start-up, testing, adjusting and balancing of any equipment or system; extended training of Owner's personnel in operation and maintenance of equipment and systems, and consultation during such training; and preparation of operating and maintenance manuals, other than those provided by the Contractor, subcontractor, or equipment manufacturer.
- .12 Providing consultation concerning replacement of any Work damaged or built inconsistent with the Contract Drawings, providing the cause is found by the Owner to be other than by fault of the Project Consultant.
- .13 Providing consultation concerning replacement of any Work damaged by fire or other cause during construction, and furnishing services as may be required in connection with the replacement of such Work.
- .14 Preparing revisions of Schematic Design, Design Development, and Construction Document Phase Documents previously approved in writing by Owner, when so directed in writing by Owner, provided, however, that no compensation for Supplemental Services shall be paid for revisions which may be required when due to errors or omissions by the Consultant or when due to the fact that the lowest Bona Fide construction bid exceeds the "fixed limit of construction cost".
- .15 Providing services made necessary by the default of the Contractor, or any major unanticipated defects or deficiencies in the Work of the Contractor or any subcontractor not attributable in any way to an Error and/or Omission of the Project Consultant.
- .16 Preparing change orders and related documents provided the changes are significant changes (whether increases or decreases) in the scope of the project and are requested by the Owner and not for any changes due to any other reasons such as error or omission of the Project Consultant.

- .17 Providing revisions in drawings, specifications or other documents required by the enactment or revision of codes, laws or regulations subsequent to the preparation of such documents.
- .18 Preparing to serve or serving as an expert witness in connection with any public hearing, arbitration proceeding or legal proceeding.
- .19 Providing services after certification to the Owner of that Final Certificate for payment, and said payment has been made to the Contractor except those services that are a result of errors, omissions, or conflicts in documents prepared by the Project Consultant or are warranty related services.
- .21 Review of extensive claims by the Contractor or others relating to the Project. However, there shall be no additional charges to Owner from Project Consultant in the event the claims are not extensive or in the event the claims are determined by the Owner to be based upon the failure of the Project Consultant or Sub-Consultant to properly perform its services or to comply with the provisions of this Agreement.

ARTICLE 3 SUB-CONSULTANTS

3.1 Sub-Consultants' Relations

- 3.1.1 All services provided by the Sub-Consultant shall be pursuant to appropriate Agreements between the Project Consultant and the Sub-Consultants which shall contain provisions that preserve and protect the rights of the Owner and the Project Consultant under this Agreement. All such Agreements shall provide that the Project Consultant may assign or transfer to Owner any and all claims or causes of action which the Project Consultant has or may have against a Sub-Consultant as a result of or relating to any acts of omission or commission of that Sub-Consultant.
- 3.1.2 Nothing contained in this Agreement shall create any contractual relationship between the Owner and the Sub-Consultants. However the Project Consultant is at all times liable for any and all negligent acts of omission or commission of its Sub-Consultants relating to or regarding this Agreement or the Project which is the subject of this Agreement. The Owner may, at any time, require the Project Consultant to assign or transfer to the Owner any claims or causes of action which Project Consultant has or may have against one or more of its Sub-Consultants as it relates to these contract obligations regarding or relating to this Project. Upon such request, the Project Consultant shall execute a written assignment or transfer in a form to be provided by the Owner. In the event the Owner requires the Project Consultant to assign or transfer said claims or causes of action then the Owner agrees to indemnify and hold the Project Consultant harmless from any claim or cause of action brought by a Sub-Consultant against the Project Consultant directly related to the claim of cause of action brought by the Owner against a Sub-Consultant as a result of such assignment.

3.2 Proposed Sub-Consultants

- 3.2.1 The Project Consultant proposes to utilize the following Sub-Consultants:
Per Attachment 5 (Project Team Members)
- 3.2.2 The Project Consultant shall not change any Sub-Consultant without written prior approval by the Owner.

- 3.2.3 The Project Consultant, not later than ten (10) calendar days after the date of this Agreement, shall submit a list of contact information for Sub-Consultants which includes contact names, firm addresses, phone and fax numbers and internet (or other internet e-mail service provider) e-mail addresses.

ARTICLE 4 THE OWNER'S RESPONSIBILITIES

4.1 Information, Documents, And Services

- 4.1.1 Owner shall consult with Project Consultant and provide such information regarding requirements for the project, including a Project Scope, Budget and Schedule which shall set forth Owner's contemplated design objectives, constraints and criteria, including educational specifications, facilities lists, space requirements and relationships, flexibility and expandability, special equipment and site requirements as are reasonably necessary for Project Consultant to perform its services.
- 4.1.2 The Owner shall furnish a legal description and a certified land survey of the site. When possible, the Owner shall supply the certified land survey in hardcopy and electronic media formats. The certified land survey shall provide boundary dimensions, locations of existing structures and/or trees, the grade and line of street, pavement and adjoining properties, the rights, restrictions, easements, boundaries, topographic data and information relative to sewer, water, gas and electrical services.
- 4.1.3 Owner shall furnish the services of soil engineers or other consultants if such services are necessary and requested in writing by Project Consultant. Such services may include test borings, test pits, soil bearing values, percolation tests, air and water pollution tests, ground corrosion and resistivity tests, including necessary operations for determining subsoil, air and water conditions, tests for hazardous materials, chemical, mechanical, structural or other tests with reports and appropriate professional recommendations.
- 4.1.4 Owner shall furnish a Project Schedule for the project showing all activities and critical dates necessary to complete the project within the allotted time.
- 4.1.5 Owner shall furnish a Construction Budget which is the portion of the Project Budget allocated for the construction cost of a project and will be based upon the Fixed Limit of Construction Cost with an appropriate contingency factor. This contingency factor includes but is not limited to the demolition, destructive testing and repairs, directed by the Project Consultant, to adequately investigate and document the existing conditions of the facility.
- 4.1.6 **As-Built Documentation:** When available, drawings and other available documents which were purported to represent "as-built" conditions at the time of original construction will be furnished to the Project Consultant; however, they are not warranted to represent conditions as of this date. The Project Consultant shall perform non-destructive field investigations as necessary to obtain sufficient information to perform his services and as required by field conditions, or the Owner to verify wall assemblies, construction types or other basic information as required to develop the design and documentation necessary for the project. The demolition and repairs associated with the destructive testing shall be compensated as a reimbursable expense. The Owner encourages the use of destructive testing techniques (with prior approval) to retrieve information that can be utilized by the Project Consultant to clearly indicate the disposition of the existing facility and incorporate this information into the Contract Documents.
- 4.1.7 **District Standards and Submittal Checklist**

- .1 **Design And Material Standards:** The Owner will furnish an electronic copy of Design and Material standards for the Project Consultant's use in developing designs and documentation for the project. These documents are technical specifications and the intent of these documents is to convey basic Owner preferences to the Project Consultant. The Project Consultant shall review the content of the Design and Material Standards provided by the Owner and may consult with the Owner concerning discrepancies, errors or suggestions for the improvement of the provided documents. The Project Consultant remains responsible for the technical content and accuracy of documents produced under the terms of this Agreement.
- .2 **Design Criteria:** The Owner will furnish an electronic copy of the Design Criteria for the Project Consultant's use in developing designs for the project. These criteria are guidelines, which address owner related issues; including but not limited to, ease of maintenance, life cycle costing, and functionality of the facility.
- .3 **Document Submittal Checklist:** The checklist is a guideline indicating minimum requirements for the submittal of contract documents for each phase of the design process. The completed checklist form will be required with each submission for all applicable disciplines.

4.1.8 **Standard Construction Bidding And Contract Documents:** The Owner shall furnish the Project Consultant with sample bidding and contract requirements and general requirements containing the basic provisions and requirements of Owner. These documents are comprised of the Bidding Requirements, Contracting Requirements, and Division 1 Specification Sections that will be utilized by the Project Consultant to develop the construction contract documents required under the terms of this Agreement. The Project Consultant acknowledges that these Owner Standard Documents will be made available by the Owner and shall be reviewed and analyzed by the Project Consultant and that these documents shall serve as the basis for the Project Consultant's development of bidding documents for the Owner.

4.1.9 Owner shall arrange and pay for the required advertisements for bid.

4.1.10 Owner, assisted by Project Consultant, shall issue the bid documents to bidders, maintain the planholders list, and issue addenda.

4.1.11 Owner shall be responsible for issuance of formal notices to proceed (if any) to the Contractor.

4.2 Owner Furnished Items

4.2.1 The services, information, surveys and reports specified by Article 4.1 shall be furnished at the Owner's expense, and the Project Consultant shall be entitled to rely upon the accuracy and completeness thereof. However, if the Project Consultant reviews all of the information provided by the Owner (such as surveys, soil borings and "as-built" documentation) and determines additional information and/or testing is required to properly design the project, the Project Consultant shall request same from the Owner.

4.2.2 When documents, services, or other materials furnished by the Owner for the Project Consultant's use are deemed by the Project Consultant as inappropriate, inaccurate, or otherwise unreasonable, the Project Consultant shall notify the Owner immediately upon discovery of same. Failure of the Project Consultant to so notify the Owner shall result in the Project Consultant's being responsible for any costs, expenses, or damages incurred by the Owner and forfeiture of claims for damages, delays or other compensation related to the use of those Owner furnished materials.

4.2.3 The Owner shall furnish the above information or authorize the Project Consultant to provide it, as a supplemental service (except where otherwise stipulated), as expeditiously as possible for the orderly progress and development of the Project.

ARTICLE 5 BASIS OF COMPENSATION

5.1 Professional Service Fees:

5.1.1 The Owner agrees to pay the Project Consultant, and the Project Consultant agrees to accept for services rendered pursuant to this Agreement a fixed fee (as computed by the Fixed Fee method below) of: _____ Dollars. (\$ _____ .00)

<i>Reuse Fee</i>	
<i>(Fee Written Out)</i>	(\$ _____)
<i>Site Adaptation Fee</i>	
<i>(Fee Written Out)</i>	(\$ _____)
<i>(Other – Description) Fee</i>	
<i>(Fee Written Out)</i>	(\$ _____)

5.2 Fixed Fee:

5.2.1 The Fixed Fee listed above is based on the scope of services for a project of this scope, size, complexity and Fixed Limit of Construction Cost (FLCC) of Construction of the project.

5.2.2 If the Owner authorizes a significant increase or decrease in the scope of the project, the Fixed Fee may be adjusted as mutually agreed upon. Changes in the FLCC, or, a Construction Contract awarded by the Owner in excess of the FLCC, shall not entitle the Project Consultant to additional Basic Services Fees, and, a Construction Contract awarded by the Owner that is less than the FLCC shall not entitle the Owner to a decrease in Basic Services Fees.

5.2.3 The Project Consultant shall not perform Professional Services, Supplemental Services, or Reimbursable Services until a written Purchase Order with the appropriate "line number" has been issued by the Supply Management and Logistics Department together with a fully executed Authorization to Proceed. **OWNER SHALL HAVE NO OBLIGATION TO COMPENSATE PROJECT CONSULTANT FOR ANY WORK PERFORMED BY THE PROJECT CONSULTANT PRIOR TO RECEIPT OF A FULLY EXECUTED WRITTEN AUTHORIZATION TO PROCEED AND PURCHASE ORDER.**

5.3 Not Used

5.4 Fee for Additive Alternates:

5.4.1 The design of alternates within the Owner's total allocated funds for construction will be a Basic Service.

5.4.2 The design of additive alternates, not included in the original project scope, in excess of Fixed Limit of Construction Cost of Construction must be authorized by the Chief Facilities and Construction Officer, and will be considered supplemental services, subject to negotiation.

5.4.3 Fees for the design of additive alternates, not included in the original project scope, will be negotiated and issued by a fully approved and executed ATP and Purchase order (See 5.2.3), . The Owner will pay one

hundred (100%) percent of the negotiated fee for alternates accepted and only pay for the design portions of the (Phases I through III) for alternates rejected.

5.5 Raw Labor Rate:

5.5.1

5.5.1 Raw Labor is defined as the raw salary rate, as determined from salaries reported to the Director of Internal Revenue, of the personnel engaged directly on a project.

5.6 Fees for Reimbursables

5.6.1 Reimbursables are those items pre-approved in writing by a fully approved and executed ATP and Purchase order (See 5.2.3), and authorized by the Owner in addition to the Basic and Supplemental Services and consist of actual expenditures made by the Project Consultant and the Project Consultants' employees and Sub-Consultants in the interest of the Work.

5.6.2 Authorized travel outside the Dade, Broward and Palm Beach County area, lodging and meals in connection with a project (subject to the limitations imposed by Chapter 112.061, Florida Statutes); fees paid for securing approval of authorities having jurisdiction over the Work; reproductions (outside of Basic Services and with prior written Owner approval in the form of a fully approved and executed ATP and Purchase order (See 5.2.3); postage and handling of Drawings, Specifications and other documents, excluding reproductions for the office use of the Project Consultant and check sets required by the Owner; data processing and photographic production techniques when used in connection with Supplemental Services.

5.6.3 The Owner will reimburse the Project Consultant for authorized Reimbursables as verified by appropriate bills, invoices or statements.

5.6.4 Any authorized reimbursable shall not include charges for office rent or overhead expenses of any kind, including but not limited to local telephone, cell phone and utility charges, overtime or any discretionary labor benefits, office and drafting supplies, depreciation of equipment, professional dues, subscriptions, etc., reproduction of drawings and specifications, mailing, stenographic, clerical, or other employees time or travel and subsistence not directly related to a project. Authorized reproductions in excess of sets required at each phase of the work will be a Reimbursable.

5.7 Fees for Supplemental Services

5.7.1 The Consultant may be authorized by its receipt of a fully approved and executed ATP and Purchase order (See 5.2.3), to perform Supplemental Services described under Article 2.9 and negotiated in accordance with Article 2.8.2. The fee for such services will be Time Spent plus reimbursable expenses with a Guaranteed Maximum Price based on Raw Salary Rates times a fixed multiplier. The fixed multiplier shall cover mandatory personnel expenses, overhead and profit and shall be set at _____ times Raw Salary Rates and shall be included in the Guaranteed Maximum. Where a mutually agreeable Guaranteed Maximum cannot be arrived at, the Owner may secure services from an independent source or from the Owner's resources. The Consultant shall provide any information and/or copies of project documentation necessary to facilitate the provision of said supplemental services by others.

ARTICLE 6 PAYMENTS TO THE PROJECT CONSULTANT

6.1 Payment for Basic Services

- 6.1.1 Payments for Basic Services may be requested monthly in proportion to services performed during each Phase of the Work and provision of all required insurance policies is a condition precedent to becoming due any such payments to the Project Consultant. Said payments shall, in the aggregate, not exceed the percentage of the estimated total Basic Compensation, or 90% for Phases I, II, or III prior to approval of the submitted design documents, indicated below for each Phase:
- .1 Fifteen (15%) percent of the total fee upon completion and approval of Phase I.
 - .2 Fifteen (15%) percent of the total fee upon completion and approval of Phase II.
 - .3 Twenty (20%) percent of the total fee upon submittal and approval of 50% of Phase III.
 - .4 Fifteen (15%) percent of the total fee upon completion and approval of Phase III.
 - .5 Five (5%) percent of the total fee upon 100% completion of Phase IV.
 - .6 Twenty-eight (28%) percent of the total fee upon completion of Phase V
 - .7 Two (2%) percent of the total fee upon completion of Phase VI (Warranty) and approval of all Work and audit of account, as per Article 5.
- 6.1.2 Partial payments may be made in Phase V (but not in excess of ninety (90%) percent of the aggregate of Phase V) in monthly increments which are proportioned to match the Work's percentage complete reflected by the Contractor's monthly Applications for Payment. If the Owner's required Substantial Completion date for Phase V is extended through no fault of the Project Consultant, the Project Consultant shall be reasonably compensated for any required professional services and/or expenses not otherwise compensated for in connection with such time extension(s), in accordance with Article 6.2. If the Owner's required Substantial Completion date for Phase V is extended due to an action or inaction of the Project Consultant to the detriment of the Owner, no additional payments or time shall be due to Project Consultant. The Project Consultant shall include with its billing, in either electronic or hard copy format, the following supporting information, and any additional supporting information required by the Owner: time sheets for any fees based upon Raw Salary Rates, subcontractors invoices, invoices for reimbursable expenses and time sheets, subcontractor invoices for reimbursables made necessary by the performance of Work. The invoice shall be totaled and care shall be taken to assure previously paid charges are not duplicated.
- 6.1.3 If the project reaches Final Completion (as defined by the Construction Contract Documents) prior to the expiration of the Anticipated Construction Time, then full payment shall be made at that time provided the Project Consultant has completed all obligations for submittals and other services (including Project Record Documents) as required by this Agreement.
- 6.1.4 No payments shall be due to Project Consultant unless and until all materials, forms and documents required by this Agreement have been provided by Project Consultant and its Sub-Consultant to Owner, or others whom are to receive same. The Owner retains the right to withhold payment from the Project Consultant for non-performance of the Project Consultant during any phase of the Project.
- 6.1.5 The Project Consultant shall submit invoices in the Owner's required invoice format as provided.

- 6.1.6 All Submitted invoices shall have copies of referenced ATP's attached.
- 6.1.7 During project Phases I through III, the Project Consultant shall submit an updated Project Schedule reflecting the Project Consultant's scheduled and actual progress with each submitted invoice. As an attachment to the Project Schedule, the Project Consultant shall provide a progress report giving percentage of completion of the Project development.
- 6.1.8 Project Consultant shall submit a monthly MWBE Sub-Consultant Utilization Report with the monthly request for payment, on forms provided by the Owner.
- 6.1.9 Payments are due and payable thirty (30) days from receipt of the Project Consultant's invoice provided it is in accord with the requirements of this Agreement.

6.2 Payment for Supplemental Services / Reimbursables

- 6.2.1 Payment for Supplemental Services and/or Reimbursables may be requested monthly (on the Owner's standard invoice format) in proportion to the services performed. When such services are authorized, the Project Consultant shall submit for approval by the Chief Facilities and Construction Officer, a duly certified invoice, attaching to the invoice all supporting data for payments made to Sub-Consultants engaged on the project or task.
- 6.2.2 Payments are due and payable thirty (30) days from receipt of the Project Consultant's invoice.

6.3 Project Suspension

- 6.3.1 If the project is suspended for the convenience of the Owner for more than three months or terminated in whole or in part, during any Phase, the Project Consultant shall be paid for services authorized by an Authorization To Proceed which were performed prior to such suspension or termination, together with the cost of Reimbursable Services and expenses then due.
- 6.3.2 If the Project is resumed after having been suspended for more than three months, the Project Consultant's further compensation shall be adjusted by the addition of Project Resumption Expenses. Project Resumption Expenses are in addition to compensation for Basic and Supplemental Services, and are full compensation for all damages and expenses which are directly or indirectly attributable to resumption of the Project Consultant's services after a Project Suspension. Project Resumption Expenses are applicable only to a Project Suspension by the Owner and shall be computed as a percentage of the total compensation for Basic Services and Supplemental Services earned to the time of termination, as follows:
 - .1 Two (2%) percent of the total compensation for Basic and Supplemental Services earned to the date of Project Suspension for the respective schematic or design development Phase only, if Project Suspension occurs before or during the design development design phase; or
 - .2 Five (5%) percent of the total compensation for Basic and Supplemental Services earned to the date of Project Suspension for the construction documents phase only, if Project Suspension occurs during the construction documents phase development phase; or
 - .3 Five (5%) percent of the total compensation for Basic and Supplemental Services scheduled for the construction contract administration phase only, if Project Suspension occurs during the construction support phase.

ARTICLE 7 REUSE OF DRAWINGS, SPECIFICATIONS AND OTHER DOCUMENTS

7.1 Scope of Services

7.1.1 It is understood that all Professional Service Agreements for design and other services include the provision for the Owner's optional re-use of drawings, specifications and other documents (including Phase V of Basic Services described in Article 2); and that the Project Consultant agrees to such re-use in accordance with this provision.

7.1.2 If the Owner elects to re-use the drawings, specifications and other documents, in whole or in part, prepared for the project for other projects on other sites, the Project Consultant will be paid a re-use fee, for Basic Services described in Article 2 for Phases I through VI, in the amounts of:

- .1 Twenty (20%) percent of the original fee for Basic Services for Phases I through III.
- .2 Thirty-eight (38%) percent of the original fee for Basic Services for Phases IV, V and VI.

Alternatively, the Owner agrees to pay the Project Consultant, and the Project Consultant agrees to accept, a flat reuse fee of:

(Fee Written Out) \$XX,XXX for the reuse of <project> <Project number> <facility>:

This flat reuse fee will only apply if an actual dollar amount is listed above.

7.1.3 For each re-use the Project Consultant shall review the final as-built design of any prior reuse or reuses and shall include all Basic Services rendered under the reuse(s) and incorporate all modifications to the drawings, specifications and other documents resulting from Change-Orders, Errors and Omissions, Code revisions and Code corrections made during the prior reuse(s), and, modifications normally required to suit the new site. (This does not include preparation of reverse plans, changes to the program, subsequent code revisions or exceptional site conditions). The stipulations and conditions of this Agreement shall remain in force for each re-use project, unless otherwise agreed. Reuse fees do not include preparation of documents for offsite improvements.

7.1.4 If a reuse project commences in excess of three years from the acceptance of the design development documents by the Owner then Owner shall negotiate the fees to be paid to Project Consultant.

ARTICLE 8 INDEMNIFICATION

8.1 Indemnification

8.1.1 To the fullest extent permitted by law, the Project Consultant shall indemnify, defend and hold harmless the Owner, its members, officers, employees and agents (hereinafter collectively "Related Parties") from and against any and all liability, claims, causes of action (by whomever brought or alleged and regardless of the legal theories upon which the liability, claims or causes of action are based), losses, damage, costs, expenses and fees (including but not limited to reasonable fees of attorneys, expert witnesses and other consultants), which are or may be imposed upon, incurred by or asserted against Owner and/or the Related Parties to the extent said liability, claims, causes of action, losses, damages, costs, expenses and/or fees are caused by any errors, omissions or negligent acts of the Project Consultant, any sub-consultant or sub-sub-consultant, any

supplier and any individual or entity directly or indirectly employed by any of them.

- 8.1.2 In any and all claims against the Owner by any employee of the Project Consultant, or anyone for whose acts the Project Consultant may be liable, the obligations for Project Consultant to indemnify Owner under this contract shall not be limited in any way by any limitation on the amount or type of damages, compensation, or benefits payable by or for the Project Consultant under workman's compensation acts, disability acts, or other employee benefit acts.
- 8.1.3 In the event that any claims are brought or actions filed against the Owner with respect to the indemnity contained herein, the Project Consultant agrees to defend against any such claims or actions regardless of whether such claims or actions are rightfully or wrongfully brought or filed. The Project Consultant agrees that the Owner may select the attorneys to appear and defend such claims or actions on behalf of the Owner. The Project Consultant further agrees to pay, at the sole expense of the Project Consultant, the attorney's fees and cost incurred by those attorneys selected by the Owner to appear and defend such claims or actions on behalf of the Owner. However, if the claims or actions are covered by insurance and such coverage is acknowledged by the insurance company in writing to the Owner, then, in that case, the insurance company shall choose counsel, direct the defense and be the judge of the acceptability of any compromise or settlement of any such claims or actions against the Owner which are within the insurance policy limits and are paid by the insurance company solely. Otherwise, if the claims or actions are not covered by insurance, then, at its sole option the Owner shall have the sole authority for the direction of the defense, and shall be the sole judge of the acceptability of any compromise or settlement of any claims or actions asserted against the Owner.
- 8.1.4 The Project Consultant recognizes the nature of the indemnification obligations imposed under this contract and voluntarily makes these covenants. The obligation imposed upon the Project Consultant under this Indemnification Agreement shall survive termination of this contract.

ARTICLE 9 INSURANCE

9.1 General Insurance Requirements

- 9.1.1 The Project Consultant shall not start work under this Agreement until the Project Consultant has obtained all insurance required hereunder and such insurance has been approved by the Owner.
- 9.1.2 All insurance policies shall be issued by companies authorized to do business under the laws of the State of Florida. All insurance companies providing policies required under this Agreement shall have at least an "A-" rating and a financial rating of no less than VI in the current A. M. Best Manual or hold a Moody's Investors Service Financial Strength of "Aa3" or better.
- 9.1.3 Insurance policies required under this Agreement shall be endorsed to be primary of all other valid and collectible coverages maintained by The School Board of Broward County, Florida.
- 9.1.4 The Project Consultant shall furnish certificates of insurance to the Owner for review and approval at the time of execution of this Contract and shall maintain same at all times during the term of this Agreement.
- 9.1.5 All Certificates of Insurance shall be in the form as approved by Insurance Standards Office (ISO), unless approved by Owner and shall clearly indicate that the Project Consultant has obtained insurance of the type, amount and classification required by these provisions, in excess of any pending claims at the time of contract award to the Project Consultant. No material change or cancellation of the insurance shall be effective

without a thirty (30) day prior written notice to and approval by the Owner. All Certificates shall list the Owner's project number and full project title (including applicable facility name).

9.1.6 Certificates of Insurance must clearly list any and all deductibles by coverages.

9.2 Insurance Required:

9.2.1 Automobile Liability Insurance: The Project Consultant shall maintain Automobile Liability Insurance covering all owned, non-owned and hired vehicles used in connection with this Agreement in amounts not less than One Million (\$1,000,000) Dollars per occurrence for bodily injury and property damage combined single limit and shall not be less than the standard ISO Business Auto Policy CA 00 01.

9.2.2 Professional Liability (Errors and Omissions): The Project Consultant shall procure Professional Liability Insurance in the manner described herein. The deductible shall not be more than Fifty Thousand (\$50,000) Dollars for each policy and must be indicated on the certificate of insurance. The insurance policy shall be non-cancelable and the limits of the Professional Liability Insurance Policy shall be as follows:

9.2.2.1 Not used.

9.2.2.2. Projects require a practice policy with a per claim/annual aggregate in accordance with the specifications delineated below relative to the cumulative construction value of all projects:

- .1 One Million (\$1,000,000) Dollars on a per claim/One Million (\$1,000,000) Dollars annual aggregate basis for Project Consultants whose cumulative construction value for all Board contracts is less than Five Million (\$5,000,000) Dollars.
- .2 One Million (\$1,000,000) Dollars on a per claim/Three Million (\$3,000,000) Dollars annual aggregate basis for Project Consultants whose cumulative construction value for all Board contracts is between Five Million One (\$5,000,001) Dollars to Ten Million (\$10,000,000) Dollars.
- .3 One Million (\$1,000,000) Dollars on a per claim/Five Million (\$5,000,000) Dollars annual aggregate basis for Project Consultants whose cumulative construction value for all Board contracts is greater than Ten Million One (\$10,000,001) Dollars.

The Project Consultant shall be required to maintain the practice policy in accordance with the above specifications for a period commencing with execution of this contract and terminating three years after final completion of said projects. Should additional projects or change orders be added that increase the cumulative construction value to another tier shown above, the Project Consultant will be required to show proof of coverage at the higher limit / aggregate. In addition, the project consultant shall provide information regarding the total claims against said practice policy on an annual basis for the term of the contract upon and terminating three years after final completion of the project (Claims/Loss history should be forwarded to the Risk Management Department), as The School Board of Broward County, Florida, deems appropriate.

The Professional Liability insurance must provide for all sums which the Project Consultant shall be legally obligated to pay as damages for claims arising out of or relating to the negligent services performed by the Project Consultant or any person employed or acting on the Project Consultant's

behalf (including, but not limited to, Sub-Consultants) in connection with this Agreement. If the Owner, at its sole discretion, agrees that such coverage is not commercially reasonably available, the Owner may, at its discretion, authorize the Project Consultant to alter the coverage by substituting a lower aggregate or changing any other terms and conditions of the coverage (including but not limited to deductible amounts) based upon the scope of the project.

9.2.3 **Workers' Compensation Insurance:** The Project Consultant shall maintain Workers' Compensation Insurance in compliance with Florida Statutes, Chapter 440 and Employer's Liability Limit of not less than Five Hundred Thousand (\$500,000) Dollars per Occurrence.

9.2.4 **General Liability Insurance:** The Project Consultant shall maintain General Liability Insurance, including Contractual Liability to cover the "Hold Harmless Agreement" set forth herein, with bodily injury limits of not less than One Million (\$1,000,000) Dollars per occurrence combined single limit for bodily injury and property damage and not less than the Two Million (\$2,000,000) General Aggregate such coverage shall apply separately to each project. The School Board of Broward County, Florida, its members, officers, employees, and agents shall be named as an additional insured under the General Liability policy.

ARTICLE 10 GENERAL PROVISIONS

10.1 Performance

10.1.1 **Performance and Delegation:** The services to be performed hereunder shall be performed by the Project Consultant's and Sub-Consultant's own staff, unless otherwise approved by the Owner in writing. Said approval shall not be construed as constituting an Agreement between the Owner and said other person or firm.

10.1.2 **Term of Agreement:** The term of this Agreement shall start upon execution by the parties hereto and extend until the completion of Phase VI (Warranty) activities as set forth above except as may be otherwise agreed to in writing by the parties hereto, or as provided further herein under Article 10 and Article 7.

10.1.3 **Time for Performance:** The Project Consultant agrees to start all work hereunder upon receipt of an Authorization to Proceed issued by the Chief Facilities and Construction Officer or his designee and to complete each Phase within the time stipulated in the Authorization To Proceed (Attachment 6 to this Agreement ("ATP")) and as required by the Project Schedule (Attachment 1 to this Agreement). The Project Consultant acknowledges that failure to perform timely may cause the Owner to sustain loss and damages and will be responsible for same. The Consultant agrees that Owner is entitled to recover no less than One Hundred Dollars (\$100) per consecutive calendar day of unexcused delay caused by the Consultant's failure to comply with the times set forth in the fully executed ATP. Owner shall have the right to deduct such amounts from payments due and owing to the Consultant.

10.1.4 **Time Extensions:** A reasonable extension of time for completion of various Phases may be granted by the Owner should there be a delay on the part of the Owner in fulfilling its obligations pursuant to this Agreement. Such extension shall not be the basis or cause for any claims or causes of action by the Project Consultant for additional or extra compensation. Under no circumstances shall the Project Consultant be entitled to additional compensation or payment as a result of or relating to delays on the Project.

10.1.5 Time is of the essence with regard to the performance of this Contract.

10.1.6 **Excess Funds:** Any party receiving funds paid by the School Board of Broward County, Florida under this Agreement agrees to promptly notify the School Board of Broward County, Florida of any funds erroneously received from the School Board of Broward County, Florida of upon the discovery of such erroneous payment or overpayment. Interest shall be calculated using the interest rate for judgments under Section 55.03, Florida Statutes, as amended, applicable at the time the erroneous payment or overpayment was made by the School Board of Broward County, Florida. The erroneous payment and/or overpayment will be promptly transmitted and returned to the School Board of Broward County, Florida with applicable interest as set forth herein.

10.2 Termination Of Agreement

10.2.1 **Right to Terminate:** The Owner has the right to terminate this Agreement for its own convenience on seven days written notice. Upon termination of this Agreement, the Project Consultant shall be paid in accordance with Article 10.2.5. To receive payment, all charts, sketches, studies, drawings, and other documents or other materials related to work authorized under this Agreement, whether finished or not, must be turned over to the Owner.

10.2.2 The Consultant may terminate this Agreement only for a material breach of the Agreement and provided the Project Consultant has given the Owner written notice of the material breach and ten (10) days to cure that breach. In the event of any dispute regarding or relating to performance pursuant to this Agreement, or payment hereunder, then in that event, the Project Consultant is obligated to continue performance in accordance with the terms of this Agreement unless instructed by the Owner to suspend or delay performance.

10.2.3 Owner may terminate this Agreement for cause, which may include, but not be limited to any of the following; failure of Project Consultant to comply with any of its material obligations under this Agreement; a decrease in the projected, available Capital Outlay funds which renders continuation of the design or construction of the Project impossible or impractical; or conditions which arise that constitute Force Majeure under Article 10.2.8 of this Agreement. In such event Project Consultant shall not be entitled to any additional payments and may be liable to Owner for any damages or losses incurred or suffered as a result of Project Consultant's failure to properly perform pursuant to the terms of this Agreement. In the event it is later determined that the Owner was not justified in terminating the Agreement for cause, then it shall be deemed to be a termination for convenience pursuant to Article 10.2.1 above, and the Project Consultant's sole compensation shall be compensation in accordance with that paragraph.

10.2.4 Whether or not this Agreement is so terminated, Project Consultant shall be liable to Owner for any damage or loss resulting from such failure or violation by Project Consultant, including, but not limited to, costs in addition to those agreed to herein for prosecuting professional services to completion and delay damages paid or incurred by Owner. The rights and remedies of Owner provided by this paragraph are cumulative with and in addition to any other rights and remedies provided by law or this Agreement.

10.2.5 **Termination Expenses:** Termination Expenses are in addition to compensation for Basic and Supplemental Services, and are full compensation for all damages and expenses which are directly or indirectly attributable to termination. Termination Expenses are applicable only to a termination for convenience by Owner and shall be computed as a percentage of the total compensation for Basic Services and Supplemental Services earned to the time of termination, as follows:

- .1 Twenty (20%) percent of the total compensation for Basic and Supplemental Services earned to the date of termination, if termination occurs before or during the schematic design phase; or

- .2 Ten (10%) percent of the total compensation for Basic and Supplemental Services earned to the date of termination, if termination occurs during the design development phase; or
- .3 Five (5%) percent of the total compensation for Basic and Supplemental Services earned to the date of termination, if termination occurs during any subsequent phase.

10.2.6 **Annulment:** The Project Consultant warrants that no one has been employed or retained other than an employee working solely for the Project Consultant, to solicit or secure this Agreement; and that the Project Consultant has not paid, nor agreed to pay, any company or other person any fee, commission, gift or other consideration contingent upon the making of this Agreement. For breach or violation of this warranty, the Owner has the right to annul this Agreement without liability.

10.2.7 **Fixed Fees Exceeding \$50,000:** For all Fixed Fees or other "lump-sum" fees for professional service Agreements over Fifty Thousand (\$50,000) Dollars the Project Consultant shall execute a truth-in-negotiations certificate as in accordance with 287.05 and all required language set forth therein. Requirements of Florida Statute 287.055 (2004), as amended, are incorporated herein by reference.

10.2.8 **Force Majeure:** The Owner's or Consultant's failure to perform any term or condition of this Agreement as a result of conditions beyond its control such as, but not limited to, war, strikes, fires, floods, acts of God, governmental restrictions, power failures, or damage or destruction of any network facilities or servers, shall not be deemed a breach of this Agreement.

10.3 Project Consultant's Accounting Records and Right to Audit Provisions

10.3.1 Project Consultant's records which shall include any and all records reasonably requested by Owner that relate to performance of services by Project Consultant or Sub-Consultants. Records include but are not limited to information, materials and data of every kind and character (hard copy, as well as computer readable data if it exists), books, papers, documents subscriptions, recordings, estimates, price quotations, agreements purchase orders, leases, contracts, commitments, arrangements, notes, daily diaries, superintendent reports, drawings, receipts, vouchers, monthly, quarterly, yearly or other financial statements, accounting records, payroll time sheets, job cost reports, job cost history, margin analysis, written policies and procedures, all Sub-Consultant files (including proposals of successful and unsuccessful Sub-Consultants, contracts, correspondence), original estimates, estimating worksheets, computer records, disks and software, videos, photography, correspondence, change order files (including documentation covering negotiated settlements), constructability or peer reviews, coordination documents, logs and supporting documentation, general ledger entries, insurance information, and any other supporting evidence necessary to substantiate charges related to this contract (all the foregoing hereinafter referred to as "records") shall be open to inspection and subject to audit and/or reproduction, during normal working hours, by Owner's agent or its authorized representative to the extent necessary to adequately permit evaluation and verification of any invoices, payments or claims submitted by the contractor or any of his payees pursuant to the execution of the contract. Such records subject to examination shall also include, but not be limited to, those records necessary to evaluate and verify direct and indirect costs (including overhead allocations), fees, reimbursable services, etc. as they may apply to costs, matters or items associated with this contract.

10.3.2 For the purpose of such audits, inspections, examinations and evaluations, the Owner's agent or authorized representative shall have access to said records from the effective date of this contract, for the duration of the work, and until five (5) years after the date of final payment by Owner to Project Consultant pursuant to this contract. All costs which the Consultant is unable to provide support or documentation to substantiate that it was incurred as represented by the original estimated breakdown of cost or found not to be in compliance

with provisions of this contract, shall be reimbursed to the Owner.

- 10.3.3 Owner's agent or its authorized representative shall have access to the Project Consultant's facilities, shall have access to all necessary records, and shall be provided adequate and appropriate work space, in order to conduct audits in compliance with this article. Owner's agent or its authorized representative shall give auditees reasonable advance notice of intended audits.
- 10.3.4 Project Consultant shall require all Sub-Consultants and insurance agents, to comply with the provisions of this article by insertion of the requirements hereof in any written contract Agreement. Failure to obtain such written contracts which include such provisions shall be reason to exclude some or all of the related costs from amounts payable to the Project Consultant pursuant to this contract.
- 10.3.5 If an audit inspection or examination in accordance with this article, discloses overcharges (of any nature) by the Project Consultant to the Owner in excess of \$25,000 the actual cost of the Owner's audit shall be paid by the Project Consultant.

10.4 Ownership of Documents

- 10.4.1 The Schematic Design and Design Development documents developed under this Contract shall become and be the sole property of the Owner whether the Project for which they were developed is executed or not. The Project Consultant may maintain copies thereof for its records and for its future professional endeavors although the Owner shall bear no liability or any responsibility whatsoever for such use of said documents by the Project Consultant. All or part of the Schematic Design and Design Development documents prepared by the Project Consultant for this project may be used as a prototype for other facilities by the Owner. Any reuse of Schematic Design or Design Development documents developed under this Contract by the Owner or others as permitted by the Owner shall be at the sole discretion of the Owner and at the Owner's sole risk.
- 10.4.2 Provided the Project Consultant has complied with the terms of this Agreement, construction working drawings, specifications and other documents or materials developed after the completion of the design development phase are and shall remain the property of the Project Consultant whether the Project for which they are made is executed or not.
- 10.4.3 The Owner shall be permitted to retain copies, including reproducible and electronic media copies, of drawings, specifications and other documents or materials developed after the Design Development Phase for various informational and reference purposes related to management, maintenance and operation of facilities, establishing construction standards, and various other archival functions without limitation and without subsequent notice to the Project Consultant.
- 10.4.4 The drawings and specifications may be used by the Owner on other projects, or for any other purpose included, but not limited to, for completion of the Project's construction in the event the Project Consultant's services are terminated as per other provisions of this Contract.
- 10.4.5 Submission or distribution to meet official regulatory requirements or for other purposes in connection with the Project is not to be construed as publication in derogation of the Project Consultant's rights.
- 10.4.6 In the event of the Project Consultant's termination under other provisions of this Agreement, the Owner shall receive all original documents prepared to the date of termination and shall have the right to use those documents and any reproductions in any way necessary to complete the Project, or for any other purpose.

10.4.7 In the event Owner requests any such documents or materials referred to in this Article and Project Consultant fails to provide same as requested by Owner, then Project Consultant acknowledges that Owner will be irreparably harmed and subject to an injunction to provide same.

10.4.8 The Owner will not modify or distribute the documents, including electronic media versions, to third parties except for those purposes listed above without the expressed permission and consent of the Project Consultant. The Owner will delete any title blocks or other marks identifying the originating Project Consultant from any materials so distributed. The Owner will indemnify the Project Consultant against any claims that result from the modification of data and disks by the Owner.

10.5 Electronic Media

10.5.1 Where this Agreement or referenced provisions in the Contract Documents require the Project Consultant to provide information or documents in either electronic or magnetic media, the preparation and format of that media shall conform to the Owner's Electronic Media Submittal Requirements (Attachment 3 to this Agreement).

10.6 Attachments and References

10.6.1 The following named attachments are made an integral part of this Agreement:

- .1 Attachment 1: Project Schedule
- .2 Attachment 2: Project Scope
- .3 Attachment 3: Electronic Media Submittal Requirements
- .4 Attachment 4: Project Consultant's Invoice Format, Reimbursable and Supplemental Services Format
- .5 Attachment 5: List of Project Team Members
- .6 Attachment 6: Authorization to Proceed (ATP) Form
Professional Services Required – page 1 of 3
Project Schedule – page 2 of 3
Professional Fee – page 3 of 3
- .7 Attachment 7: Document Submittal Checklist
- .8 Attachment 8: Document 00455 – Background Screening
- .9 Attachment 9: IRS Form W-9
- .10 Attachment 10: Truth in Negotiations Certificate

10.6.2 Online Documents: The following documents shall be downloaded by the Project Consultant and are considered as Attachments to this Contract:

Design Standards

http://www.broward.k12.fl.us/facilities_construction/DSS/DS_Docs/DesignStandards.htm

- Design Criteria
- Design and Material Standards - Division 1 thru Division 17
- Document Submittal Checklist for Plan Review

<http://www.broward.k12.fl.us/constructioncontracts/D0docs.html>

- Specifications – Division 0

State Requirements for Educational Facilities (SREF) latest edition

<http://www.fldoe.org/edfacil/sref.asp>

- F.I.S.H. layering system for AutoCAD: Note: the layering system is not posted on line. It will need to be requested thru:

Facility Planning and Real Estate
600 SE 3rd Avenue
Fort Lauderdale, FL 33312
754-321-1932

10.7 Extent of Agreement:

- 10.7.1 This Agreement represents the entire and integrated Agreement between the Owner and the Project Consultant and supersedes all prior negotiations, representations or agreements, written or oral.
- 10.7.2 This Agreement may not be amended, changed, modified, or otherwise altered in any particular, at any time after the execution hereof, except by resolution of The School Board of Broward County, Florida.
- 10.7.3 This Agreement is for the benefit of the parties to the Agreement and is not for the benefit of any other parties nor shall it create a contractual relationship with any other party.
- 10.7.4 This Agreement shall be governed by the laws of the State of Florida Venue of any action arising out of this Agreement shall be in Broward County, Florida. The parties are encouraged to participate in mediation of any dispute before engaging in litigation.

10.8 Strict Performance:

- 10.8.1 The failure of either party to insist upon or enforce strict performance by the other party of any of the provisions of this Agreement or to exercise any rights under this Agreement shall not be construed as a waiver or relinquishment to any extent of its rights to assert or rely upon any such provisions or rights in that or any other instance.

10.9 Prompt and Satisfactory Correction:

- 10.9.1 The Owner, at its sole discretion, may direct the Project Consultant, at no additional cost to the Owner, to promptly and satisfactorily correct any services found to be defective or not in compliance with the requirements of this Agreement or the requirements of any governmental authority, law, regulations or ordinances.

10.10 Successors and Assigns:

- 10.10.1 The performance of this Agreement shall not be delegated or assigned by the Project Consultant without the written consent of the Owner.
- 10.10.2 The Project Consultant and the Owner each binds one another, their partners, successors, legal representatives and assigns to the other party of this Agreement and to the partners, successors, legal representatives and assigns of such party in respect to all covenants of this Agreement.

10.11 Certification Regarding Debarment, Suspension, Ineligibility or Voluntary Exclusion:

10.11.1 **Lower Tier Covered Transactions:** Executive Order 12549 provides that, to the extent permitted by law, Executive departments and agencies shall participate in a government-wide system for non-procurement debarment and suspension. A person who is debarred or suspended shall be excluded from Federal financial and non-financial assistance and benefits under Federal programs and activities. Except as provided in § 85.200, Debarment or Suspension, § 85.201, Treatment of Title IV HEA participation, and §85.215, Exception provision, debarment or suspension of a participant in a program by one agency shall have government-wide effect. A lower tier covered transaction is, in part, any transaction between a participant [SBBC] and a person other than a procurement contract for goods or services, regardless of type, under a primary covered transaction; and any procurement contract for goods or services between a participant and a person, regardless of type, expected to equal or exceed the Federal procurement small purchase threshold fixed at 10 U.S.C. 2304(g) and 41 U.S.C. 253(g) (currently \$100,000) under a primary covered transaction. A participant may rely upon the certification of a prospective participant in a lower tier covered transaction that it and its principals are not debarred, suspended, proposed for debarment under 48 CFR part 9, subpart 9.4, ineligible, or voluntarily excluded from the covered transaction, unless it knows that the certification is erroneous. Each participant shall require participants in lower tier covered transactions to include the following certification for it and its principals in any proposal submitted in connection with such lower tier covered transactions.

10.11.2 Certification and Disclosure

- .1 The lower tier participant (Project Consultant) certifies, by entering this Agreement, that neither it nor its principals is presently debarred, suspended, proposed for debarment, declared ineligible, or voluntarily excluded from participation in this transaction by any Federal department or agency.
- .2 Where the lower tier participant (Project Consultant) is unable to certify to any of the statements in this certification, such participant shall provide an explanation to the Owner.
- .3 The Consultant warrants that he or she has not employed or retained any company or person, other than a bona fide employee working solely for the Consultant to solicit or secure this Agreement and that he or she has not paid or agreed to pay any person, company, corporation, individual, or firm, other than a bona fide employee working solely for the Consultant any fee, commission, percentage, gift, or other consideration contingent upon or resulting from the award or making of this agreement. For the breach or violation of this provision, the Owner shall have the right to terminate the Agreement without liability and, at its discretion, to deduct from the fees due and owing to the Consultant, or otherwise recover, the full amount of such fee, commission, percentage, gift, or consideration. (Ch. 287.055, F.S.)

10.12 Non-Discrimination, EEO, and ADA

10.12.1 **Non-Discrimination** - The School Board of Broward County, Florida prohibits any policy or procedure which results in discrimination on the basis of age, color, disability, gender, national origin, marital status, race, religion or sexual orientation.

10.12.2 **Equal Employment Opportunity (EEO)** - The School Board of Broward County, Florida, prohibits any

policy or procedure which results in discrimination on the basis of age, color, disability, gender identity, gender expression, national origin, marital status, race, religion, sex or sexual orientation. Individuals who wish to file a discrimination and/or harassment complaint may call the Executive Director, Benefits & EEO Compliance at 754-321-2150 or Teletype Machine (TTY) 754-321-2158.

10.12.3 Americans with Disabilities Act Amendments Act of 2008 - Individuals with disabilities requesting accommodations under the Americans with Disabilities Act Amendments Act of 2008, (ADAAA) may call Equal Educational Opportunities (EEO) at 754-321-2150 or Teletype Machine (TTY) 754-321-2158.

10.13 Captions

10.13.1 Captions – The captions, section numbers, article numbers, title and headings appearing in this Agreement are inserted only as a matter of convenience and in no way define, limit, construe or describe the scope or intent of such articles or sections of this Agreement, nor in any way effect this Agreement and shall not be construed to create a conflict with the provisions of this Agreement.

10.14 Authority

10.14.1 Authority Provision: Each person signing this agreement on behalf of either party individually warrants that he or she has full legal power to execute this Agreement on behalf of the party for whom he or she is signing, and to bind and obligate such party with respect to all provisions contained in this Agreement.

10.15 Notice

10.15.1 Notice Provision: When any of the parties desire to give notice to the other, such notice must be in writing, sent by US Mail, postage prepaid, addressed to the party for whom it is intended at the place last specified; the place for giving notice shall remain such until it is changed by written notice in compliance with the provisions of the paragraph. For the present, the parties designate the following as the respective places for giving notice.

To SBBC: Superintendent of Schools
The School Board of Broward County, Florida
600 Southeast Third Avenue
Fort Lauderdale, Florida 33301

With a Copy to: Office of the Chief Facilities Officer
600 SE 3 Avenue
Fort Lauderdale, FL 33312
Attn: Leo Bobadilla
Chief Facilities Officer

With a Copy to: Office of Facilities and Construction
3775 SW 16th St
Fort Lauderdale, FL 33312
Attn: Shelley N. Meloni
Director, Pre-Construction Office of Facilities and Construction

And

Heery International, Owners Representative
811 Ponce de Leon Boulevard Coral Gables, FL 33134
Attn: Robert Corbin
Program Director/Vice President

To Design Professional: Insert Name and Address Provided by Other Party

With a Copy to: Insert Name and Address Provided by Other Party

10.16 Excess Funds

10.16.1 Any party receiving funds paid by The School Board of Broward County, Florida (SBBC) under this Agreement agrees to promptly notify SBBC of any funds erroneously received from SBBC upon the discovery of such erroneous payment or overpayment. Any such excess funds shall be refunded to SBBC with interest calculated from the date of the erroneous payment or overpayment. Interest shall be calculated using the interest rate for judgments under Section 55.03, Florida Statutes, applicable at the time the erroneous payment or overpayment was made by SBBC.

10.17 Background Screening

10.17.1 **Background Screening.** Project Consultant agrees to comply with all requirements of Sections 1012.32 and 1012.465, Florida Statutes, and that Project Consultant, its agents, subconsultants and all of its personnel who (1) are to be permitted access to school grounds when students are present, (2) will have direct contact with students, or (3) have access or control of school funds will successfully complete the background screening required by the referenced statutes and meet the standards established by the statutes. This background screening will be conducted by SBBC in advance of Project Consultant or its personnel providing any services under the conditions described in the previous sentence. Project Consultant will bear the cost of acquiring the background screening required by Section 1012.32, Florida Statutes, and any fee imposed by the Florida Department of Law Enforcement to maintain the fingerprints provided with respect to Project Consultant and its personnel. The Parties agree that the failure of Project Consultant to perform any of the duties described in this section shall constitute a material breach of this Agreement entitling SBBC to terminate immediately with no further responsibilities or duties to perform under this Agreement.

Project Consultant agrees to indemnify and hold harmless SBBC, its officers and employees from any liability in the form of physical or mental injury, death or property damage resulting from Project Consultant's failure to comply with the requirement of this Section or Section 1012.32 and Section 1012.465, Florida Statutes in addition to any other indemnification obligations that may be imposed upon Project Consultant pursuant to Article 8 of this Agreement and the laws of Florida.

10.18 Errors and Omissions

10.18.1 The Project Consultant shall be responsible for any errors, inconsistencies or omissions in the drawings, specifications, and other documents. The Project Consultant will correct the drawings and specifications at no additional design cost to the Owner for any and all errors and omissions in the drawings, specifications prepared by the Project Consultant. The Project Consultant further agrees, at no additional cost, to render assistance to the Owner in resolving problems relating to the design or specified materials.

10.18.2 Deductions may be made from the Project Consultant's Basic Services Compensation on account of errors and omissions in the drawings, specifications and other documents prepared by the Project Consultant or in the Project Consultant's performance of its obligations under this Agreement.

ARTICLE 11 INCORPORATION OF RFQ INTO AGREEMENT

11.1 In addition to those Attachments and References identified and made part of this Agreement in Article 10.6.1, the provisions of RFQ No. **XXX (“TYPE OF SERVICE”)** (the “RFQ”) are hereby incorporated into this Agreement. In the event of conflict between the provisions contained in this Agreement and the RFQ, the more stringent provision shall prevail. If this Agreement is silent on an issue that is contained with the RFQ, the provisions of the RFQ shall be followed.

IN WITNESS WHEREOF, The School Board of Broward County, Florida, has caused this Agreement to be executed by the undersigned and the seal of the School Board to be set hereto; and the said Project Consultant has caused this Agreement to be executed by the undersigned and the seal of the Project Consultant set hereto on this day and year first above written.

THE SCHOOL BOARD OF BROWARD COUNTY, FLORIDA

(SEAL)

**ATTEST THE SCHOOL BOARD OF
BROWARD COUNTY, FLORIDA**

Robert W. Runcie, Superintendent of Schools

Dr. Rosalind Osgood, Chair

Approved as to Form and Legal Content:

Office of the General Counsel

DELETE THE SIGNATURE SECTIONS NOT USED

WHEN THE PROJECT CONSULTANT IS A CORPORATION OR PROFESSIONAL ASSOCIATION

(Corporate Seal)

(ATTEST)

(Type Name of Firm Here)
Legal Name of Corporation

President, (Type Name Here)

Secretary, (Type Name Here)
(Type Registration Number Here)
Project Consultant's
Registration Number

WHEN THE PROJECT CONSULTANT IS AN INDIVIDUAL OR PARTNERSHIP

(ATTEST)

Witness (Type Name Here)

Legal Name of Individual or Partnership

Witness (Type Name Here)

By: _____
Signature (Type Name Here)

Project Consultant's
Registration Number

WHEN THE PROJECT CONSULTANT IS A JOINT VENTURE

(Corporate Seal)

(Corporate Seal)

Firm's Legal Name

Firm's Legal Name

By: _____
Signature (Type Name Here)

By: _____
Signature (Type Name Here)

Project Consultant's
Registration Number

(ATTEST)

Witness (Type Name Here)

Witness (Type Name Here)

Witness (Type Name Here)

Witness (Type Name Here)

ACKNOWLEDGEMENT

**STATE OF FLORIDA
COUNTY OF BROWARD**

BEFORE ME this _____ day of _____, _____, appeared _____, and, _____

_____ personally known to me to be the persons described in and who executed the foregoing contract and acknowledge that he executed the same as his free act and deed for the purposes therein expressed.

WITNESS my hand and official seal in the County and State last official this _____ day of _____, 201_.

Notary Public State of Florida

My Commission Expires:

Attachment 1

Owner's Initial Schedule



Electronic Media Requirements

All Work product for all projects, requires hard copies, electronic copies (PDF) and electronic original copies. The electronic media requirements are as listed below.

ELECTRONIC MEDIA

1.0 General Information

- 1.1 The School Board of Broward County, Florida contracts with one or more Internet bid advertising and distribution services. The Design Professional shall post the complete bid package to these services upon written notification by the Owner. The posted documents shall be read only documents and the file format shall be PDF.

2.0 Software Requirements

2.1 Word Processing

- 2.1.1 Provide word processing files in Microsoft Word for Windows compatible file formats including all information necessary for remote printing.

2.2 Spreadsheets

- 2.2.1 Provide spreadsheet files in Microsoft Excel for windows compatible file formats including all information necessary for remote printing.

2.3 Computer aided Design and Drafting

- 2.3.1 Provide all CADD files as AutoCAD 2010 files, Window's version.

3.0 CAD Standards

3.1 Standard plotted drawing size: 24 inch x 36 inch or 30 inch x 42 inch sheets.

- 3.1.1 All sheets within a set shall be the same size unless pre-approved otherwise. (for example survey sheets)

3.2 Design Professional shall provide to the Owner the standard file naming Protocol they will be utilizing.

3.3 CAD File Layering

- 3.3.1 Conform to the most up to date guidelines defined by the American Institute of Architects (AIA) standard document, "CAD Layer Guidelines."

- 3.3.2 Provide the required Layering for the Florida Inventory of Schoolhouses (F.I.S.H.) documents

- 3.3.1.1 The F.I.S.H. layering scheme is not available on-line. It can be requested through:

Facility Planning and Real Estate
600 SE 3rd Avenue, Fort Lauderdale, FL 33312 754-321-1932

- 3.3.3 Provide a separate list of all layers which do not conform to the standard AIA CAD Layer Guidelines or the FISH layering scheme.
- 3.4 No custom hatch patterns shall be utilized.
- 3.5 All symbols and blocks to have descriptive names
- 4.0 Electronic Media Delivery Requirements
 - 4.1 Transmittals shall include the following
 - 4.1.1 The Project Number, Project Title and date
 - 4.1.2 The Facility Name
 - 4.1.3 The submittal type
 - 4.1.4 The format and version of the software.
 - 4.1.5 An attached Listing of file names with the latest document publish dates
 - 4.2 All electronic media shall contain an attached label which shall identify 4.1.1, 4.1.2, and 4.1.3.
 - 4.3 Document clean-up
 - 4.3.1 Before a CADD file is placed on the delivery electronic digital media, the following procedures shall be performed:
 - 4.3.1.1 Purge all files and remove all extraneous graphics outside the border area.
 - 4.3.1.2 Make sure all reference files are attached without device path
 - 4.3.1.3 All required project files both graphic and nongraphic, shall include color tables, pen tables, font libraries, block libraries, user command files, plot files, etc. All project related blocks must be provided to the Owner as a part of the electronic digital deliverables.
 - 4.3.1.4 Make sure that all support files such as those listed above are in the same directory and that references to those files do not include device Path.
 - 4.4 The following Plot File Development and Project Documentation Information shall be submitted as an enclosure or attachment to the transmittal letter provided with each electronic digital media submittal.
 - 4.4.1 Documentation of the plot files for each drawing which will be needed to be able to allow identical plotting by the Owner at a later date. This documentation shall include the plotter configuration (e.g., name and model of plotter), pen settings, drawing orientation, drawing

size, and any other special instructions.

4.4.2 Instructions concerning how to generate plotted, drawings from the provided plot files.

4.5 Provide all symbols and blocks used in the project in a separate files.

4.6 List of all database/spreadsheet files associated with each drawing, as well as a description and documentation of the database format.

5.0 Ownership: Refer to Agreement for specific Owner and Design Professional's rights.

6.0 Documents for the Construction Contractor:

6.1 The Owner and the Design Professional shall make various electronic information available to the Contractor during the Construction phase of the Project.

7.0 Where electronic media submittals of final site surveys are required: Provide electronic copies of any existing site survey data already on electronic media.

8.0 At the Contractors option, the Design Professional will provide the Contractor one set of AutoCAD (.dwg) electronic file format contract drawings, to be used for as built drawings at the Contractor's option. Note that the Architect's name and information to be removed.

Design Professionals Invoice Format

The School Board of Broward County, Florida requires submittal of the Design Professional's invoice on the District's standard invoice forms attached to a transmittal form or letter on the Design Professional's company letterhead. Include the information and attachments described below:

1. Letterhead Containing Firm Information

- A. Firm Name
- B. Address
- C. Telephone and FAX Numbers
- D. Consultant's Invoice Reference Number

2. Address Transmittal/Letter to:

Office of Facilities and Construction
The School Board of Broward County, Florida
3775 SW 16th Street
Fort Lauderdale, FL 33312
Attention: Name of Project Manager

3. Ensure that Transmittal/Letter references the following information:

- A. Date of submittal.
- B. The Invoice Number for ATP Number (example: Invoice No. 01 for ATP No. 01).
- C. The School Board of Broward County's Purchase Order No.: (Which will be provided by the Facilities Project Manager at the beginning of the project.)
- D. Name of Facility (and Facility Number).
- E. Name of Project
- F. School Board Project Number

4. Ensure attachment of the following documents to the Transmittal/Letter:

- A. Design Professional's Invoice Form
- B. Design Professional's Reimbursable Invoice Form
- C. Copy of signature page (page 3 of 3) of the Design Professional's Authorization to Proceed.



The School Board of Broward County, Florida
 Florida Facilities and Construction Management Department
 3775 SW 16th Street Fort Lauderdale, FL 33312 (754) 321-1500

Design Professional (Name) _____ Date: _____
 Project No: _____ Facility Name: _____ Invoice No: _____
 Project Title: _____ SBBC PO No. _____
 Design Professional's _____ ATP No. _____
 Remit to address: _____ Invoice From: _____
 Project Manager

Original Basic Fee	\$
Current basic fee	\$

INVOICE TOTALS:

Summary	Current Fee	Previously Billed	This Invoice	Balance
Basic Services	\$	\$	\$	\$
Reimbursable	\$	\$	\$	\$
Total:	\$	\$	\$	\$

BASIC FEE TOTALS:

Period	Fee	Previously Billed	This Invoice	Balance
From to dates	\$	\$ % \$	% \$	%
	\$	\$ % \$	% \$	%
	\$	\$ % \$	% \$	%
	\$	\$ % \$	% \$	%
	\$	\$ % \$	% \$	%
Other Services	\$	\$ % \$	% \$	%
Total Previously Billed:		\$		
Total Amount This Invoice:			\$	
Total Balance:				\$

Submitted By: Name: Title: Date: (Signature)	Certified By: Name: Title: Project Manager Date: (Signature)	Recommended By: Name: Title: Date: (Signature)	Approved By: Name: Title: Date: (Signature)
---	--	--	---



The School Board of Broward County, Florida
 Florida Facilities and Construction Management Department
 3775 SW 16th Street Fort Lauderdale, FL 33312 (754) 321-1500

Design Professional's Reimbursable Invoice

Project No:	Facility Name: Invoice No:
Project Title:	SBBC PO No.
Design Professional's:	ATP No.
Remit to address:	Invoice From:
Project Manager:	

Item No.	Date	Reimbursable Item	Amount
Invoice Total			\$

Receipts for each Item must be attached.

Current Contract Amount:	\$		
Total This Invoice:		\$	
Total Previously Billed:			\$
Total Balance:			\$

Submitted By: Name: Title: Date:	Certified By: Name: Title: Project Manager Date:	Recommended By: Name: Title: Date:	Approved By: Name: Title: Date:
(Signature)	(Signature)	(Signature)	(Signature)



The School Board of Broward County, Florida
Office of Facilities & Construction
3775 S.W. 16th Street
Fort Lauderdale, Florida 33312

(754) 321-1500

Consultant's Authorization To Proceed

Form with fields for Project No., Location No., Project Title, Facility Name, Project Consultant, Date, SBBC P.O. No., Line No., Project Manager, and Dir. Capital Planning & Programming.

Under the provisions of your contract for professional services, you are hereby authorized to proceed with the following services for the project referenced above.

- Checkboxes for Schematic Design, Design Development, Construction Documents, Bidding, Construction Contract Administration, Warranty, and Other Services: Attached.

This Authorization to Proceed is subject to the following attachments:

- Attachments: Professional Services Required, Project Schedule, Professional Fees, Previous ATP's

The scope of the required services is specified on the Professional Services Required with a Fixed Limit of Construction Cost (FLCC) for this project as indicated below:

Table with 3 columns: Original FLCC, Current Cost Estimate, Revised FLCC by ATP

The following professional services will be provided by the Project Consultant as a normal part of its Basic Services for the Project listed above:

Item Discipline Description



The School Board of Broward County, Florida
Office of Facilities & Construction
3775 S.W. 16th Street
Fort Lauderdale, Florida 33312

(754) 321-1500

Consultant's Authorization To Proceed (Term Contracts) Cont.

Project Schedule

Project No. & Location No.: _____ Project Title: _____

Facility Name: _____
Project Consultant: _____

The required project schedule milestones for this project are presented below. (Mandatory)

ACTIVITY	Date Required Or Estimated Time Period	
	Start	Finish
Schematic Design		
Design Development		
Construction Documents Development		
50% Construction Documents		
100% Construction Documents		
Bidding and Award of Contract		
Time for Permitting of Submittals, Prior to the Issuance of the Construction NTP (Part of Contract Administration)		
Construction		
Warranty		



The School Board of Broward County, Florida
Office of Facilities & Construction
3775 S.W. 16th Street
Fort Lauderdale, Florida 33312

(754) 321-1500

Consultant's Authorization To Proceed (Term Contracts)

Professional Fees

Project No. & Location No.: _____ Project Title: _____

Facility Name: _____
 Project Consultant: _____

Phase	Original Basic Fee	Fee Authorized by ATP	Fee Previously Paid	Fee Balance
I (SD) (5%)		%	%	%
II (DD) (10%)		%	%	%
III (CD) (35%/60%)		%	%	%
IV (BID) (65%)		%	%	%
V (CA) (98%)		%	%	%
VI (Warr) (100%)		%	%	%
Other Service Item No. 1		%	%	%
Other Service (Item No. 2)		%	%	%
Other Service (Item No. 3)		%	%	%
Other Service (Item No. 4)		%	%	%
Total:				

Payment for these services shall be made In accordance with the provisions of the Professional Services Agreement.

Approved By Consultant				Recommended By SBBC			
Name:				Name: Shelley N. Meloni			
Title:				Title: Director, Pre-Construction			
Signature:	_____	Date:	_____	Signature:	_____	Date:	_____
Certified By SBBC				Approval by SBBC			
Name:				Name: Leo Bobadilla			
Title:				Title: Chief Facilities Officer			
Signature:	_____	Date:	_____	Signature:	_____	Date:	_____

This document is part of the Professional Services Agreement between The School Board of Broward County, Florida (Owner) and the Design Professional and is incorporated by reference into the terms and conditions of that agreement.

Form W-9 (Rev. August 2013) Department of the Treasury Internal Revenue Service	<h2 style="margin:0;">Request for Taxpayer Identification Number and Certification</h2>	Give Form to the requester. Do not send to the IRS.
---	---	---

Print or type See Specific Instructions on page 2.	Name (as shown on your income tax return)	
	Business name/disregarded entity name, if different from above	
	Check appropriate box for federal tax classification: <input type="checkbox"/> Individual/sole proprietor <input type="checkbox"/> C Corporation <input type="checkbox"/> S Corporation <input type="checkbox"/> Partnership <input type="checkbox"/> Trust/estate <input type="checkbox"/> Limited liability company. Enter the tax classification (C=C corporation, S=S corporation, P=partnership) ▶ _____ <input type="checkbox"/> Other (see instructions) ▶ _____	
	Exemptions (see instructions): Exempt payee code (if any) _____ Exemption from FATCA reporting code (if any) _____	
	Address (number, street, and apt. or suite no.)	Requester's name and address (optional)
City, state, and ZIP code		
List account number(s) here (optional)		

Part I Taxpayer Identification Number (TIN)																						
Enter your TIN in the appropriate box. The TIN provided must match the name given on the "Name" line to avoid backup withholding. For individuals, this is your social security number (SSN). However, for a resident alien, sole proprietor, or disregarded entity, see the Part I Instructions on page 3. For other entities, it is your employer identification number (EIN). If you do not have a number, see <i>How to get a TIN</i> on page 3.																						
	<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th colspan="10" style="text-align: left; padding: 2px;">Social security number</th> </tr> <tr> <td style="width:30px; height: 25px;"></td> <td style="width:30px;"></td> <td style="width:30px;"></td> <td style="width:30px;"></td> <td style="width:30px;"></td> <td style="width:30px;"></td> <td style="width:30px;"></td> <td style="width:30px;"></td> <td style="width:30px;"></td> <td style="width:30px;"></td> <td style="width:30px;"></td> </tr> </table>	Social security number																				
Social security number																						
Note. If the account is in more than one name, see the chart on page 4 for guidelines on whose number to enter.																						
	<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th colspan="10" style="text-align: left; padding: 2px;">Employer identification number</th> </tr> <tr> <td style="width:30px; height: 25px;"></td> <td style="width:30px;"></td> <td style="width:30px;"></td> <td style="width:30px;"></td> <td style="width:30px;"></td> <td style="width:30px;"></td> <td style="width:30px;"></td> <td style="width:30px;"></td> <td style="width:30px;"></td> <td style="width:30px;"></td> <td style="width:30px;"></td> </tr> </table>	Employer identification number																				
Employer identification number																						

Part II Certification	
Under penalties of perjury, I certify that:	
1. The number shown on this form is my correct taxpayer identification number (or I am waiting for a number to be issued to me), and 2. I am not subject to backup withholding because: (a) I am exempt from backup withholding, or (b) I have not been notified by the Internal Revenue Service (IRS) that I am subject to backup withholding as a result of a failure to report all interest or dividends, or (c) the IRS has notified me that I am no longer subject to backup withholding, and 3. I am a U.S. citizen or other U.S. person (defined below), and 4. The FATCA code(s) entered on this form (if any) indicating that I am exempt from FATCA reporting is correct.	
Certification instructions. You must cross out item 2 above if you have been notified by the IRS that you are currently subject to backup withholding because you have failed to report all interest and dividends on your tax return. For real estate transactions, item 2 does not apply. For mortgage interest paid, acquisition or abandonment of secured property, cancellation of debt, contributions to an individual retirement arrangement (IRA), and generally, payments other than interest and dividends, you are not required to sign the certification, but you must provide your correct TIN. See the instructions on page 3.	
Sign Here	Signature of U.S. person ▶ _____ Date ▶ _____

General Instructions

Section references are to the Internal Revenue Code unless otherwise noted.

Future developments. The IRS has created a page on www.irs.gov/w9 for information about Form W-9, at www.irs.gov/w9. Information about any future developments affecting Form W-9 (such as legislation enacted after we release it) will be posted on that page.

Purpose of Form

A person who is required to file an information return with the IRS must obtain your correct taxpayer identification number (TIN) to report, for example, income paid to you, payments made to you in settlement of payment card and third party network transactions, real estate transactions, mortgage interest you paid, acquisition or abandonment of secured property, cancellation of debt, or contributions you made to an IRA.

Use Form W-9 only if you are a U.S. person (including a resident alien), to provide your correct TIN to the person requesting it (the requester) and, when applicable, to:

1. Certify that the TIN you are giving is correct (or you are waiting for a number to be issued).
2. Certify that you are not subject to backup withholding, or
3. Claim exemption from backup withholding if you are a U.S. exempt payee. If applicable, you are also certifying that as a U.S. person, your allocable share of any partnership income from a U.S. trade or business is not subject to the withholding tax on foreign partners' share of effectively connected income, and

4. Certify that FATCA code(s) entered on this form (if any) indicating that you are exempt from the FATCA reporting, is correct.

Note. If you are a U.S. person and a requester gives you a form other than Form W-9 to request your TIN, you must use the requester's form if it is substantially similar to this Form W-9.

Definition of a U.S. person. For federal tax purposes, you are considered a U.S. person if you are:

- An individual who is a U.S. citizen or U.S. resident alien,
- A partnership, corporation, company, or association created or organized in the United States or under the laws of the United States,
- An estate (other than a foreign estate), or
- A domestic trust (as defined in Regulations section 301.7701-7).

Special rules for partnerships. Partnerships that conduct a trade or business in the United States are generally required to pay a withholding tax under section 1446 on any foreign partners' share of effectively connected taxable income from such business. Further, in certain cases where a Form W-9 has not been received, the rules under section 1446 require a partnership to presume that a partner is a foreign person, and pay the section 1446 withholding tax. Therefore, if you are a U.S. person that is a partner in a partnership conducting a trade or business in the United States, provide Form W-9 to the partnership to establish your U.S. status and avoid section 1446 withholding on your share of partnership income.

In the cases below, the following person must give Form W-9 to the partnership for purposes of establishing its U.S. status and avoiding withholding on its allocable share of net income from the partnership conducting a trade or business in the United States:

- In the case of a disregarded entity with a U.S. owner, the U.S. owner of the disregarded entity and not the entity.
- In the case of a grantor trust with a U.S. grantor or other U.S. owner, generally, the U.S. grantor or other U.S. owner of the grantor trust and not the trust, and
- In the case of a U.S. trust (other than a grantor trust), the U.S. trust (other than a grantor trust) and not the beneficiaries of the trust.

Foreign person. If you are a foreign person or the U.S. branch of a foreign bank that has elected to be treated as a U.S. person, do not use Form W-9. Instead, use the appropriate Form W-8 or Form 8233 (see Publication 515, Withholding of Tax on Nonresident Aliens and Foreign Entities).

Nonresident alien who becomes a resident alien. Generally, only a nonresident alien individual may use the terms of a tax treaty to reduce or eliminate U.S. tax on certain types of income. However, most tax treaties contain a provision known as a "saving clause." Exceptions specified in the saving clause may permit an exemption from tax to continue for certain types of income even after the payee has otherwise become a U.S. resident alien for tax purposes.

If you are a U.S. resident alien who is relying on an exception contained in the saving clause of a tax treaty to claim an exemption from U.S. tax on certain types of income, you must attach a statement to Form W-9 that specifies the following five items:

1. The treaty country. Generally, this must be the same treaty under which you claimed exemption from tax as a nonresident alien.
2. The treaty article addressing the income.
3. The article number (or location) in the tax treaty that contains the saving clause and its exceptions.
4. The type and amount of income that qualifies for the exemption from tax.
5. Sufficient facts to justify the exemption from tax under the terms of the treaty article.

Example. Article 20 of the U.S.-China income tax treaty allows an exemption from tax for scholarship income received by a Chinese student temporarily present in the United States. Under U.S. law, this student will become a resident alien for tax purposes if his or her stay in the United States exceeds 5 calendar years. However, paragraph 2 of the first Protocol to the U.S.-China treaty (dated April 30, 1984) allows the provisions of Article 20 to continue to apply even after the Chinese student becomes a resident alien of the United States. A Chinese student who qualifies for this exception (under paragraph 2 of the first protocol) and is relying on this exception to claim an exemption from tax on his or her scholarship or fellowship income would attach to Form W-9 a statement that includes the information described above to support that exemption.

If you are a nonresident alien or a foreign entity, give the requester the appropriate completed Form W-8 or Form 8233.

What is backup withholding? Persons making certain payments to you must under certain conditions withhold and pay to the IRS a percentage of such payments. This is called "backup withholding." Payments that may be subject to backup withholding include interest, tax-exempt interest, dividends, broker and barter exchange transactions, rents, royalties, nonemployee pay, payments made in settlement of payment card and third party network transactions, and certain payments from fishing boat operators. Real estate transactions are not subject to backup withholding.

You will not be subject to backup withholding on payments you receive if you give the requester your correct TIN, make the proper certifications, and report all your taxable interest and dividends on your tax return.

Payments you receive will be subject to backup withholding if:

1. You do not furnish your TIN to the requester.
2. You do not certify your TIN when required (see the Part II instructions on page 3 for details).
3. The IRS tells the requester that you furnished an incorrect TIN.
4. The IRS tells you that you are subject to backup withholding because you did not report all your interest and dividends on your tax return (for reportable interest and dividends only), or
5. You do not certify to the requester that you are not subject to backup withholding under 4 above (for reportable interest and dividend accounts opened after 1983 only).

Certain payees and payments are exempt from backup withholding. See *Exempt payee code* on page 3 and the separate instructions for the Requester of Form W-9 for more information.

Also see *Special rules for partnerships* on page 1.

What is FATCA reporting? The Foreign Account Tax Compliance Act (FATCA) requires a participating foreign financial institution to report all United States account holders that are specified United States persons. Certain payees are exempt from FATCA reporting. See *Exemption from FATCA reporting code* on page 3 and the instructions for the Requester of Form W-9 for more information.

Updating Your Information

You must provide updated information to any person to whom you claimed to be an exempt payee if you are no longer an exempt payee and anticipate receiving reportable payments in the future from this person. For example, you may need to provide updated information if you are a C corporation that elects to be an S corporation, or if you no longer are tax exempt. In addition, you must furnish a new Form W-9 if the name or TIN changes for the account, for example, if the grantor of a grantor trust dies.

Penalties

Failure to furnish TIN. If you fail to furnish your correct TIN to a requester, you are subject to a penalty of \$50 for each such failure unless your failure is due to reasonable cause and not to willful neglect.

Civil penalty for false information with respect to withholding. If you make a false statement with no reasonable basis that results in no backup withholding, you are subject to a \$500 penalty.

Criminal penalty for falsifying information. Willfully falsifying certifications or affirmations may subject you to criminal penalties including fines and/or imprisonment.

Misuse of TINs. If the requester discloses or uses TINs in violation of federal law, the requester may be subject to civil and criminal penalties.

Specific Instructions

Name

If you are an individual, you must generally enter the name shown on your income tax return. However, if you have changed your last name, for instance, due to marriage without informing the Social Security Administration of the name change, enter your first name, the last name shown on your social security card, and your new last name.

If the account is in joint names, list first, and then circle, the name of the person or entity whose number you entered in Part I of the form.

Sole proprietor. Enter your individual name as shown on your income tax return on the "Name" line. You may enter your business, trade, or "doing business as (DBA)" name on the "Business name/disregarded entity name" line.

Partnership, C Corporation, or S Corporation. Enter the entity's name on the "Name" line and any business, trade, or "doing business as (DBA)" name on the "Business name/disregarded entity name" line.

Disregarded entity. For U.S. federal tax purposes, an entity that is disregarded as an entity separate from its owner is treated as a "disregarded entity." See Regulation section 301.7701-2(c)(2)(ii). Enter the owner's name on the "Name" line. The name of the entity entered on the "Name" line should never be a disregarded entity. The name on the "Name" line must be the name shown on the income tax return on which the income should be reported. For example, if a foreign LLC that is treated as a disregarded entity for U.S. federal tax purposes has a single owner that is a U.S. person, the U.S. owner's name is required to be provided on the "Name" line. If the direct owner of the entity is also a disregarded entity, enter the first owner that is not disregarded for federal tax purposes. Enter the disregarded entity's name on the "Business name/disregarded entity name" line. If the owner of the disregarded entity is a foreign person, the owner must complete an appropriate Form W-8 instead of a Form W-9. This is the case even if the foreign person has a U.S. TIN.

Note. Check the appropriate box for the U.S. federal tax classification of the person whose name is entered on the "Name" line (Individual/sole proprietor, Partnership, C Corporation, S Corporation, Trust/estate).

Limited Liability Company (LLC). If the person identified on the "Name" line is an LLC, check the "limited liability company" box only and enter the appropriate code for the U.S. federal tax classification in the space provided. If you are an LLC that is treated as a partnership for U.S. federal tax purposes, enter "P" for partnership. If you are an LLC that has filed a Form 8832 or a Form 2553 to be taxed as a corporation, enter "C" for C corporation or "S" for S corporation, as appropriate. If you are an LLC that is disregarded as an entity separate from its owner under Regulation section 301.7701-3 (except for employment and excise tax), do not check the LLC box unless the owner of the LLC (required to be identified on the "Name" line) is another LLC that is not disregarded for U.S. federal tax purposes. If the LLC is disregarded as an entity separate from its owner, enter the appropriate tax classification of the owner identified on the "Name" line.

Other entities. Enter your business name as shown on required U.S. federal tax documents on the "Name" line. This name should match the name shown on the charter or other legal document creating the entity. You may enter any business, trade, or DBA name on the "Business name/disregarded entity name" line.

Exemptions

If you are exempt from backup withholding and/or FATCA reporting, enter in the Exemptions box, any code(s) that may apply to you. See *Exempt payee code and Exemption from FATCA reporting code* on page 3.

Exempt payee code. Generally, individuals (including sole proprietors) are not exempt from backup withholding. Corporations are exempt from backup withholding for certain payments, such as interest and dividends. Corporations are not exempt from backup withholding for payments made in settlement of payment card or third party network transactions.

Note. If you are exempt from backup withholding, you should still complete this form to avoid possible erroneous backup withholding.

The following codes identify payees that are exempt from backup withholding:

- 1—An organization exempt from tax under section 501(c)(3), any IRA, or a custodial account under section 403(b)(7) if the account satisfies the requirements of section 401(f)(2)
- 2—The United States or any of its agencies or instrumentalities
- 3—A state, the District of Columbia, a possession of the United States, or any of their political subdivisions or instrumentalities
- 4—A foreign government or any of its political subdivisions, agencies, or instrumentalities
- 5—A corporation
- 6—A dealer in securities or commodities required to register in the United States, the District of Columbia, or a possession of the United States
- 7—A futures commission merchant registered with the Commodity Futures Trading Commission
- 8—A real estate investment trust
- 9—An entity registered at all times during the tax year under the Investment Company Act of 1940
- 10—A common trust fund operated by a bank under section 584(a)
- 11—A financial institution
- 12—A middleman known in the investment community as a nominee or custodian
- 13—A trust exempt from tax under section 664 or described in section 4947

The following chart shows types of payments that may be exempt from backup withholding. The chart applies to the exempt payees listed above, 1 through 13.

IF the payment is for . . .	THEN the payment is exempt for . . .
Interest and dividend payments	All exempt payees except for 7
Broker transactions	Exempt payees 1 through 4 and 6 through 11 and all C corporations. S corporations must not enter an exempt payee code because they are exempt only for sales of noncovered securities acquired prior to 2012.
Barter exchange transactions and patronage dividends	Exempt payees 1 through 4
Payments over \$600 required to be reported and direct sales over \$5,000 ¹	Generally, exempt payees 1 through 5 ²
Payments made in settlement of payment card or third party network transactions	Exempt payees 1 through 4

¹ See Form 1099-MISC, Miscellaneous Income, and its instructions.
² However, the following payments made to a corporation and reportable on Form 1099-MISC are not exempt from backup withholding: medical and health care payments, attorneys' fees, gross proceeds paid to an attorney, and payments for services paid by a federal executive agency.

Exemption from FATCA reporting code. The following codes identify payees that are exempt from reporting under FATCA. These codes apply to persons submitting this form for accounts maintained outside of the United States by certain foreign financial institutions. Therefore, if you are only submitting this form for an account you hold in the United States, you may leave this field blank. Consult with the person requesting this form if you are uncertain if the financial institution is subject to these requirements.

- A—An organization exempt from tax under section 501(c)(3) or any individual retirement plan as defined in section 7701(a)(37)
- B—The United States or any of its agencies or instrumentalities
- C—A state, the District of Columbia, a possession of the United States, or any of their political subdivisions or instrumentalities
- D—A corporation the stock of which is regularly traded on one or more established securities markets, as described in Reg. section 1.1472-1(c)(1)(i)
- E—A corporation that is a member of the same expanded affiliated group as a corporation described in Reg. section 1.1472-1(c)(1)(i)
- F—A dealer in securities, commodities, or derivative financial instruments (including notional principal contracts, futures, forwards, and options) that is registered as such under the laws of the United States or any state

- G—A real estate investment trust
- H—A regulated investment company as defined in section 851 or an entity registered at all times during the tax year under the Investment Company Act of 1940
- I—A common trust fund as defined in section 584(a)
- J—A bank as defined in section 581
- K—A broker
- L—A trust exempt from tax under section 664 or described in section 4947(a)(1)
- M—A tax exempt trust under a section 403(b) plan or section 457(g) plan

Part I. Taxpayer Identification Number (TIN)

Enter your TIN in the appropriate box. If you are a resident alien and you do not have and are not eligible to get an SSN, your TIN is your IRS individual taxpayer identification number (ITIN). Enter it in the social security number box. If you do not have an ITIN, see *How to get a TIN* below.

If you are a sole proprietor and you have an EIN, you may enter either your SSN or EIN. However, the IRS prefers that you use your SSN.

If you are a single-member LLC that is disregarded as an entity separate from its owner (see *Limited Liability Company (LLC)* on page 2), enter the owner's SSN (or EIN, if the owner has one). Do not enter the disregarded entity's EIN. If the LLC is classified as a corporation or partnership, enter the entity's EIN.

Note. See the chart on page 4 for further clarification of name and TIN combinations.

How to get a TIN. If you do not have a TIN, apply for one immediately. To apply for an SSN, get Form SS-5, Application for a Social Security Card, from your local Social Security Administration office or get this form online at www.ssa.gov. You may also get this form by calling 1-800-772-1213. Use Form W-7, Application for IRS Individual Taxpayer Identification Number, to apply for an ITIN, or Form SS-4, Application for Employer Identification Number, to apply for an EIN. You can apply for an EIN online by accessing the IRS website at www.irs.gov/businesses and clicking on Employer Identification Number (EIN) under Starting a Business. You can get Forms W-7 and SS-4 from the IRS by visiting IRS.gov or by calling 1-800-TAX-FORM (1-800-829-3676).

If you are asked to complete Form W-9 but do not have a TIN, apply for a TIN and write "Applied For" in the space for the TIN, sign and date the form, and give it to the requester. For interest and dividend payments, and certain payments made with respect to readily tradable instruments, generally you will have 60 days to get a TIN and give it to the requester before you are subject to backup withholding on payments. The 60-day rule does not apply to other types of payments. You will be subject to backup withholding on all such payments until you provide your TIN to the requester.

Note. Entering "Applied For" means that you have already applied for a TIN or that you intend to apply for one soon.

Caution: A disregarded U.S. entity that has a foreign owner must use the appropriate Form W-8.

Part II. Certification

To establish to the withholding agent that you are a U.S. person, or resident alien, sign Form W-9. You may be requested to sign by the withholding agent even if items 1, 4, or 5 below indicate otherwise.

For a joint account, only the person whose TIN is shown in Part I should sign (when required). In the case of a disregarded entity, the person identified on the "Name" line must sign. Exempt payees, see *Exempt payee code* earlier.

Signature requirements. Complete the certification as indicated in items 1 through 5 below.

1. **Interest, dividend, and barter exchange accounts opened before 1964 and broker accounts considered active during 1963.** You must give your correct TIN, but you do not have to sign the certification.
2. **Interest, dividend, broker, and barter exchange accounts opened after 1963 and broker accounts considered inactive during 1963.** You must sign the certification or backup withholding will apply. If you are subject to backup withholding and you are merely providing your correct TIN to the requester, you must cross out item 2 in the certification before signing the form.
3. **Real estate transactions.** You must sign the certification. You may cross out item 2 of the certification.
4. **Other payments.** You must give your correct TIN, but you do not have to sign the certification unless you have been notified that you have previously given an incorrect TIN. "Other payments" include payments made in the course of the requester's trade or business for rents, royalties, goods (other than bills for merchandise), medical and health care services (including payments to corporations), payments to a nonemployee for services, payments made in settlement of payment card and third party network transactions, payments to certain fishing boat crew members and fishermen, and gross proceeds paid to attorneys (including payments to corporations).
5. **Mortgage interest paid by you, acquisition or abandonment of secured property, cancellation of debt, qualified tuition program payments (under section 529), IRA, Coverdell ESA, Archer MSA or HSA contributions or distributions, and pension distributions.** You must give your correct TIN, but you do not have to sign the certification.

What Name and Number To Give the Requester

For this type of account:	Give name and SSN of:
1. Individual	The individual
2. Two or more individuals (joint account)	The actual owner of the account or, if combined funds, the first individual on the account ¹
3. Custodian account of a minor (Uniform Gift to Minors Act)	The minor ²
4. a. The usual revocable savings trust (grantor is also trustee) b. So-called trust account that is not a legal or valid trust under state law	The grantor-trustee ³
5. Sole proprietorship or disregarded entity owned by an individual	The actual owner ⁴
6. Grantor trust filing under Optional Form 1099 Filing Method 1 (see Regulation section 1.671-4(b)(2)(A))	The owner ⁴
7. Disregarded entity not owned by an individual	The grantor ⁴
8. A valid trust, estate, or pension trust	The owner
9. Corporation or LLC electing corporate status on Form 8832 or Form 2553	Legal entity ⁴
10. Association, club, religious, charitable, educational, or other tax-exempt organization	The corporation
11. Partnership or multi-member LLC	The organization
12. A broker or registered nominee	The partnership
13. Account with the Department of Agriculture in the name of a public entity (such as a state or local government, school district, or prison) that receives agricultural program payments	The broker or nominee
14. Grantor trust filing under the Form 1041 Filing Method or the Optional Form 1099 Filing Method 2 (see Regulation section 1.671-4(b)(2)(B))	The public entity
	The trust

¹ List first and circle the name of the person whose number you furnish. If only one person on a joint account has an SSN, that person's number must be furnished.

² Circle the minor's name and furnish the minor's SSN.

³ You must show your individual name and you may also enter your business or "DBA" name on the "Business name/disregarded entity" name line. You may use either your SSN or EIN (if you have one), but the IRS encourages you to use your SSN.

⁴ List first and circle the name of the trust, estate, or pension trust. (Do not furnish the TIN of the personal representative or trustee unless the legal entity itself is not designated in the account title.) Also see Special rules for partnerships on page 1.

*Note. Grantor also must provide a Form W-9 to trustee of trust.

Note. If no name is circled when more than one name is listed, the number will be considered to be that of the first name listed.

Secure Your Tax Records from Identity Theft

Identity theft occurs when someone uses your personal information such as your name, social security number (SSN), or other identifying information, without your permission, to commit fraud or other crimes. An identity thief may use your SSN to get a job or may file a tax return using your SSN to receive a refund.

To reduce your risk:

- Protect your SSN,
- Ensure your employer is protecting your SSN, and
- Be careful when choosing a tax preparer.

If your tax records are affected by identity theft and you receive a notice from the IRS, respond right away to the name and phone number printed on the IRS notice or letter.

If your tax records are not currently affected by identity theft but you think you are at risk due to a lost or stolen purse or wallet, questionable credit card activity or credit report, contact the IRS Identity Theft Hotline at 1-800-908-4490 or submit Form 14039.

For more information, see Publication 4535, Identity Theft Prevention and Victim Assistance.

Victims of identity theft who are experiencing economic harm or a system problem, or are seeking help in resolving tax problems that have not been resolved through normal channels, may be eligible for Taxpayer Advocate Service (TAS) assistance. You can reach TAS by calling the TAS toll-free case intake line at 1-877-777-4778 or TTY/TDD 1-800-829-4059.

Protect yourself from suspicious emails or phishing schemes. Phishing is the creation and use of email and websites designed to mimic legitimate business emails and websites. The most common act is sending an email to a user falsely claiming to be an established legitimate enterprise in an attempt to scam the user into surrendering private information that will be used for identity theft.

The IRS does not initiate contacts with taxpayers via emails. Also, the IRS does not request personal detailed information through email or ask taxpayers for the PIN numbers, passwords, or similar secret access information for their credit card, bank, or other financial accounts.

If you receive an unsolicited email claiming to be from the IRS, forward this message to phishing@irs.gov. You may also report misuse of the IRS name, logo, or other IRS property to the Treasury Inspector General for Tax Administration at 1-800-368-4484. You can forward suspicious emails to the Federal Trade Commission at: spam@ftc.gov or contact them at www.ftc.gov/idtheft or 1-877-IDTHEFT (1-877-438-4338).

Visit IRS.gov to learn more about identity theft and how to reduce your risk.

Privacy Act Notice

Section 6109 of the Internal Revenue Code requires you to provide your correct TIN to persons (including federal agencies) who are required to file information returns with the IRS to report interest, dividends, or certain other income paid to you; mortgage interest you paid; the acquisition or abandonment of secured property; the cancellation of debt; or contributions you made to an IRA, Archer MSA, or HSA. The person collecting this form uses the information on the form to file information returns with the IRS, reporting the above information. Routine uses of this information include giving it to the Department of Justice for civil and criminal litigation and to cities, states, the District of Columbia, and U.S. commonwealths and possessions for use in administering their laws. The information also may be disclosed to other countries under a treaty, to federal and state agencies to enforce civil and criminal laws, or to federal law enforcement and intelligence agencies to combat terrorism. You must provide your TIN whether or not you are required to file a tax return. Under section 3406, payors must generally withhold a percentage of taxable interest, dividend, and certain other payments to a payee who does not give a TIN to the payor. Certain penalties may also apply for providing false or fraudulent information.

REQUIRED RESPONSE FORM - Proposer Information

RFQ Issued Date: _____ Title of Request or Solicitation: _____

Note: For Joint Venture Proposals, see instructions at the bottom of this page.

PROPOSER INFORMATION

PROPOSER'S (COMPANY) NAME: _____

STREET ADDRESS: _____

CITY, STATE AND ZIP CODE: _____

PROPOSER TELEPHONE: _____ PROPOSER FAX: _____

CONTACT PERSON: _____

CONTACT TELEPHONE: _____ CONTACT FAX: _____

E-MAIL ADDRESS TO SEND PURCHASE ORDERS TO: _____

INTERNET E-MAIL ADDRESS: _____ INTERNET URL: _____

PROPOSER FIRM - TAX IDENTIFICATION NUMBER: _____

Proposal Certification

I hereby certify that:

1. I am submitting the following information as my Firm's Qualifications and I am an Officer of the Firm.
2. Proposer has not discussed, or compared the Qualifications with other Proposers and has not colluded with any other Proposer.
3. Proposer, its principals, or their lobbyists has not provided any campaign contributions to School Board Members during the period in which the Proposer is attempting to qualify, to provide Design Services to the School Board. This period of limitation shall commence at the time of the "cone of silence" period for any solicitation for a competitive procurement as described by:
 - School Board Policy 3320, Part II, Section HH
 - School Board Policy 1007, Section 5.4 Campaign Contribution Fundraising
4. Proposer acknowledges that all information contained herein is part of the public record as defined by the State of Florida Sunshine and Public Records Laws.
- 5 All responses, data and information contained in this Proposal are true and accurate
6. Proposer agrees to acceptance of the contents of all pages in this Request for Qualifications (RFQ) including all attachments and the contents of all issued Addenda.
7. Proposer agrees to be bound to all terms, conditions and requirements identified in the Request for Qualifications, its Addenda and its Attachments.
8. The Proposer understands that everything contained herein are requirements of this RFQ and failure to comply will result in disqualification of the Qualifications submitted.

Signature of Proposer's Officer (blue ink preferred on original)

Date

Name of Proposer's Officer

Title of Proposer's Officer.

JOINT VENTURES: In the event multiple Proposers submit a joint Proposal in response to the RFQ, a single Proposer shall be identified as the Prime Proposer. If offering a joint Proposal, Prime Proposer must include the name and address of all parties of the joint Proposal. Prime Proposer shall provide all bonding and insurance requirements, execute any Contract, complete the **REQUIRED RESPONSE FORM** shown herein, have overall and complete accountability to resolve any dispute arising within this contract. Only a single contract with one Proposer shall be acceptable. Prime Proposer responsibilities shall include, but not be limited to, performing of overall contract administration, preside over other Proposers participating or present at SBBC meetings, oversee preparation of reports and presentations, and file any notice of protest and final protest as described herein. Prime Proposer shall also prepare and present a consolidated invoice(s) for services performed. SBBC shall issue only one check for each consolidated invoice to the Prime Proposer for services performed. Prime Proposer shall remain responsible for performing services associated with response to this RFQ.

Firm: _____

RFQ #: _____

Scope of Available Services Form

(Both of these columns can be yes)

Scope of Services	In House Services (yes or no)	Consultant
Architecture		
Civil Engineering		
Electrical Engineering		
Land Surveying		
Mechanical Engineering		
Structural Engineering		
Landscape Design		
Site Analysis and Planning		
Plumbing Design		
Other		



The School Board of Broward County, Florida
Procurement and Warehousing Department
7720 W. Oakland Park Blvd., Suite 323
Sunrise, Florida 33351

(754) 321-0505

Document 00220a: Proposer's Request for Information

To: **Purchasing Agent**
Procurement and Warehousing Department
7720 W. Oakland Park Blvd., Suite 323
Sunrise, Florida 33351

Date: _____

(For Owner's Use Only)
Bidder's
RFI No.:

Project: _____ Project Number &
Location Number: _____
Facility Name: _____ Project Consultant: _____

Category:

- Information not shown on RFQ Documents
- Interpretation of RFQ Documents
- Conflict in RFQ Requirements
- Coordination

Subject: _____

Description:

Attachments:

Bidder:

Company Name
& Address:

Phone:

By:

Signature

Title

Attachment G - Project Scope of Work

Parkway Middle School
3600 NW 5th Court
Lauderhill FL 33311

Project Number: P-0016xx (TBD)
Project Description: Design & Renovation
RFQ Number: 17-066C

Prepared for: The School Board of Broward County

600 SE 3rd Ave
Ft Lauderdale, FL 33301

Prepared by: **HEERY**

A group of professional service practices
999 Peachtree St, NE
Atlanta, Georgia 30309

Contents

Attachment G - Project Scope of Work.....	1
1.0.0 Executive Summary.....	3
2.0.0 Parkway Middle School.....	4
2.1.0 Project Scope of Work	4
2.2.0 Site Summary	6
2.3.0 FISH Documents	7
2.3.1 FISH Summary Report.....	7
2.3.2 FISH Inventory	11
2.3.3 FISH Site Plan	70
2.3.4 FISH Building Plan	71
2.4.0 Facility Assessments and Budgetary Documentation.....	74
2.4.1 Adopted District Educational Facilities Plan (DEFP).....	75
2.4.2 SMART Campus Summary	76
2.4.3 MAPPS Deficiency Listing.....	78
2.4.4 MAPPS Deficiency Data	104
2.4.5 MAPPS Deficiency Detail	110

1.0.0 Executive Summary

On November 4, 2014, Broward County voters approved a General Obligation Bond (Bond) referendum that provides critically needed funding for Broward's students. Broward County Public Schools has committed to investing the funding to enhance students' learning environments by focusing on improvements in Safety, Music, Art, Athletics, Renovations and Technology (SMART).

To ensure equity among schools regarding Broward County Public Schools SMART initiative, a comprehensive Facility Needs Assessment was conducted Districtwide. The Needs Assessment provided an objective, data-driven overview of the District as a whole, as well as a strategic planning tool for prioritizing the most critical needs facing our schools for safety and security; repairs and renovations; and technology and technology infrastructure.

Based on the Facility Needs Assessment, Parkway Middle School was found to require renovations to multiple facility components. The key objectives are 1) to thoroughly plan the work to allow normal school activities to continue without interruption with a focus on safety and completing work as soon as possible, and 2) to capitalize on 2017 Summer break to complete portions of scope when students are not on campus.

Included in this project scope of work is:

Parkway Middle School

- Fire Sprinklers
- Media Center Improvements
- HVAC Improvements
- Building Envelope Improvements

2.0.0 Parkway Middle School

2.1.0 Project Scope of Work

The scope of work is broken down in accordance with the Approved District Educational Facility Plan SMART Program. The scope is presented as overall site deficiencies with specific trades called out when possible. Additionally, the scope of services specific to each campus building is itemized in section 2.4.0 facility assessment reports with specific trades called out when possible for reference purposes only.

The Design Team is responsible for confirming all areas within the scope of work and necessary quantities and component sizes relevant to the campus renovations. The scope of work is limited to that which is being funded by the General Obligation Bond or agreed upon alternatives with the designated representatives of the school district.

The Design Team shall be responsible for the full design of a replacement of Fire Sprinklers in various campus buildings, which shall meet all applicable codes and SREF design requirements. The fire Sprinkler System is viewed as a mission critical concern of the highest priority level. Refer to Section 2.4.0 and subsequent sections for itemized deficiency scopes.

The Design Team shall be responsible for the full design of the Media Center improvements. The Designer shall work with the designated representatives of the school district to identify and perform remodeling of these spaces. These renovations may include but are not limited to typical design disciplines and may require specialty trades. Refer to Section 2.4.1 ADEFP for budgeted SMART program allocation. The Designer shall coordinate the overall ADEFP budget with individual Media Center and associated restroom scope budgets. See Section 2.3.3 and 2.3.4 for room designations, and 2.3.2 FISH Inventory for relevant Design Code for room coordination. All renovations shall comply with applicable codes, standards, SREF design requirements, and owner's design guidelines.

The facility assessment determined various HVAC mechanical building systems to require replacement. The Design Team shall be responsible for the design and engineering of building systems to correct deficiencies listed in section 2.4.0 in accordance with applicable codes and standards recognized by the jurisdiction. These deficiencies include, but are not limited to, the replacement of fan coil units, exhaust hoods and ventilation fans, HVAC piping in Building 19, roof top air handling units, and a complete replacement of the Kitchen HVAC system in Building 2 which is currently non-conditioned. The design shall comply with applicable codes, standards, SREF design requirements and owner's design guidelines.


The envelope scope includes, but is not limited to the replacement of exterior doors, aluminum and steel windows, exterior painting at multiple buildings throughout the campus and the reroofing of multiple campus buildings. The Design Team shall provide a full design of complete replacement of the existing roofing system with new decking requirements per County standards. Moreover, some existing roof areas will need to be raised to provide positive drainage and new minimum roof R-Values and may necessitate the need to raise existing equipment, utilities and other construction to accommodate new flashing heights.

In addition to the identified deficiencies found in section 2.4.0, the Design Team is responsible for working with the designated representatives of the school district to identify additional deficiencies related to the envelope, indoor air quality, lighting, and HVAC systems. The facility assessment reports

stand as initial budgeted concerns, but does not serve as the limits of scope of work for the project renovation.

2.2.0 Site Summary

Parkway Middle School is an existing school originally built in 1958 with expansions and renovations having taken place in 1971, 1975, 1990, 1991, 1997, 2009, and 2010. The campus currently encompasses twenty-eight (28) buildings with an approximate square footage of 223,546 SF.



Buildings not shown: Bldg 18, Bldg 27, Bldg 28, Bld 29

2.3.0 FISH Documents

2.3.1 FISH Summary Report



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

**FLORIDA DEPARTMENT OF EDUCATION
EDUCATIONAL FACILITIES
AGENCY NSF/STUDENT STATIONS SUMMARY REPORT**

ORGANIZATION: 6-BROWARD COUNTY SCHOOL DISTRICT
FACILITY: PARKWAY MIDDLE
FACILITY USE: All
STRUCTURE TYPE: All
CONDITION: 1-SATISFACTORY
GROUP BY: DISTRICT

District : 6 - BROWARD COUNTY SCHOOL DISTRICT

DESIGN CODE	ROOM DESIGN CODE	TOTAL ROOMS	NET SQ FT	STUDENT STATIONS
00002	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	65	50,496	1,430
00011	INTERMEDIATE/MIDDLE SKILLS LAB (4-8)	4	4,362	88
00020	INTERMEDIATE/MIDDLE SCIENCE DEMO (4-8)	12	14,119	264
00040	RESOURCE ROOM	7	2,869	0
00051	ART - MIDDLE	4	4,968	118
00061	E S E PART-TIME	5	4,046	75
00062	E S E FULL-TIME	5	3,833	50
00065	E S E RESOURCE	4	1,767	0
00075	VOCAL MUSIC CLASS (MIDDLE-SR HIGH)	2	1,784	31
00076	BAND CLASS (MIDDLE-SR HIGH)	1	1,540	50
00077	ORCHESTRA CLASS (MIDDLE-SR HIGH)	1	1,400	25
00078	GENERAL MUSIC CLASS (MIDDLE-SR HIGH)	2	3,232	60
00083	MUSIC RELATED SPACE	8	3,216	0
00090	P E DRESSING ROOM (MALE)	2	2,112	0
00091	P E DRESSING ROOM (FEMALE)	2	2,070	0
00094	P E SHOWER (MALE)	2	861	0
00095	P E SHOWER (FEMALE)	2	837	0
00098	P E STORAGE (MIDDLE-SR HIGH)	3	1,258	0
00099	P E TEACHERS SHOWER (MALE)	1	60	0
00100	P E TEACHERS SHOWER (FEMALE)	1	60	0
00110	P E MULTIPURPOSE ROOM (MIDDLE-SR HIGH)	1	1,914	0
00111	JR HIGH GYMNASIUM	1	10,463	160
00114	P E LAUNDRY	1	200	0
00115	P E FIRST AID	1	265	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FLORIDA DEPARTMENT OF EDUCATION EDUCATIONAL FACILITIES AGENCY NSF/STUDENT STATIONS SUMMARY REPORT

District : 6 - BROWARD COUNTY SCHOOL DISTRICT

DESIGN CODE	ROOM DESIGN CODE	TOTAL ROOMS	NET SQ FT	STUDENT STATIONS
00119	P E GYMNASICS & DANCE	3	2,873	0
00210	BUSINESS E XPLORATION LAB	2	1,660	30
00230	HOME E CONOMICS EXPLORATION LAB	2	2,324	33
00240	TECHNOLOGY/INDUSTRY EXPLORATION LAB	1	2,142	22
00272	VOCATIONAL LAB SUPPORT SPACE	3	791	0
00300	PRINCIPAL/DIRECTOR OFFICE	1	287	0
00301	ASSISTANT PRINCIPAL/OTHER OFFICE	16	2,352	0
00302	BOOKKEEPING OFFICE	1	140	0
00303	SECRETARIAL SPACE	1	399	0
00304	RECEPTION AREA	5	1,980	0
00305	PRODUCTION WORKROOM	1	496	0
00306	CONFERENCE ROOM	5	1,494	0
00307	CLINIC	2	363	0
00308	GENERAL SCHOOL STORAGE	3	476	0
00309	VAULT/STUDENT RECORDS	3	432	0
00312	COMPUTER AREA	1	125	0
00313	CAREERS ROOM	2	761	0
00314	ITINERANT OFFICE	3	369	0
00315	TEACHER PLANNING OFFICE	17	4,756	0
00316	TEACHER LOUNGE /DINING	2	302	0
00330	CUSTODIAL RECEIVING	1	391	0
00331	CUSTODIAL SERVICE CLOSET	24	822	0
00332	CUSTODIAL WORK AREA	2	200	0
00333	FLAMMABLE STORAGE	2	164	0
00334	CUSTODIAL EQUIPMENT STORAGE	3	622	0
00340	DINING AREA	1	4,658	0
00342	KITCHEN DRY STORAGE	1	270	0
00343	KITCHEN OFFICE	1	121	0
00344	KITCHEN GARBAGE WASH	1	130	0
00346	KITCHEN FOOD PREPARATION	1	1,209	0
00347	KITCHEN DISH WASHING	1	387	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FLORIDA DEPARTMENT OF EDUCATION EDUCATIONAL FACILITIES AGENCY NSF/STUDENT STATIONS SUMMARY REPORT

District : 6 - BROWARD COUNTY SCHOOL DISTRICT

DESIGN CODE	ROOM DESIGN CODE	TOTAL ROOMS	NET SQ FT	STUDENT STATIONS
00350	OTHER FOOD SERVICE	1	90	0
00360	AUDITORIUM	1	5,321	0
00363	STAGE	2	2,747	0
00364	STAGE STORAGE	5	1,985	0
00365	STAGE DRESSING ROOM (MALE)	3	309	0
00366	STAGE DRESSING ROOM (FEMALE)	3	312	0
00367	CONTROL BOOTH/PROJECTION ROOM	2	527	0
00368	TEXTBOOK STORAGE	3	558	0
00370	LOBBY	3	1,977	0
00371	CONCESSIONS	3	464	0
00372	TICKET BOOTH	2	119	0
00380	LIBRARY (READING ROOM/STACKS)	1	3,649	0
00387	MEDIA PRODUCTION LAB	1	1,087	0
00700	INSIDE CIRCULATION	50	19,960	0
00701	COVERED WALKWAY	42	71,291	0
00702	MECHANICAL ROOM	28	7,907	0
00703	ELECTRICAL ROOM	18	3,595	0
00707	TELEPHONE EQUIPMENT/COMMUNICATION CLOSET	7	556	0
00803	INSTRUCTIONAL DARKROOM	2	152	0
00805	KILN	2	172	0
00806	REFERENCE	1	136	0
00808	MATERIAL STORAGE	43	3,744	0
00810	MATERIAL STORAGE (LARGE)	7	2,351	0
00811	OUTSIDE STORAGE	1	768	0
00812	PROJECT STORAGE	2	240	0
00814	STUDENT RESTROOM (BOTH SEXES)	4	148	0
00815	STUDENT RESTROOM (MALE)	15	3,049	0
00816	STUDENT RESTROOM (FEMALE)	15	3,154	0
00817	STUDENT RESTROOM & BATH	1	70	0
00819	STAFF RESTROOM (MALE)	10	483	0
00820	STAFF RESTROOM (FEMALE)	11	496	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FLORIDA DEPARTMENT OF EDUCATION EDUCATIONAL FACILITIES AGENCY NSF/STUDENT STATIONS SUMMARY REPORT

District : 6 - BROWARD COUNTY SCHOOL DISTRICT

DESIGN CODE	ROOM DESIGN CODE	TOTAL ROOMS	NET SQ FT	STUDENT STATIONS
00821	STAFF RESTROOM (BOTH SEXES)	1	21	0
00822	PUBLIC USE RESTROOM (MALE)	1	200	0
00823	PUBLIC USE RESTROOM (FEMALE)	1	200	0
00827	ELEVATOR (PASSENGER/HANDICAPPED)	2	119	0
00831	MUSIC PRACTICE ROOM	6	285	0
00849	VOCATIONAL PROJECT STORAGE	1	340	0
	TOTALS :	550	289,810	2,436

	TOTALS FOR SELECTED DISTRICTS :	550	289,810	2,436
--	---------------------------------	-----	---------	-------

2.3.2 FISH Inventory

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



ORGANIZATION: 6-BROWARD COUNTY SCHOOL DISTRICT
FACILITY: PARKWAY MIDDLE
FACILITY USE: ALL

DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT
FACILITY: 57-A PARKWAY MIDDLE

Primary Use: COMBINATION Grades Housed: 06 - 08 DOE Validation Date: Capital Outlay Classification: SCHOOL RECOMMENDED FOR CONTINUED USE

MASTER SCHOOL ID

MSID	Name	Status
701	PARKWAY MIDDLE SCHOOL	Default

CAPITAL OUTLAY FTE

Year: 2013 / 2014

PK: 0.00	01: 0.00	03: 12.50	05: 31.00	07: 558.50	09: 0.00	11: 0.00	PK-12: 1624.96
KG: 0.00	02: 0.00	04: 16.95	06: 574.01	08: 432.00	10: 0.00	12: 0.00	Adult: 0.00
							Total: 1624.96

SCHOOL CAPACITY

SCHOOL CAPACITY	YEAR ROUND CAPACITY	UTILIZATION FACTOR	PRIMARY USE
2,192	2,630	0.90	COMBINATION

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



PARCEL: 58	
3600 NW 5TH COURT LAUDERHILL, FL 33311	
Parking: DEVELOPED	Owner: SCHOOL BOARD
Athletic: INCLUDED WITH SITE	Water: PUBLIC
Sewage: PUBLIC	Fire: 8
Landscape: PARTIALLY DEVELOPED	Police: COUNTY
Date Acquired: 1/1/1955	Drainage: ADEQUATE
	Acreege: 15.00
	Lease Expiration Date:

DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 57-A PARKWAY MIDDLE
BUILDING: 1 - Building Number 00001

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: MIDDLE	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1958	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified: 1991	Educational TV: FIXED SERVICE TRANSMITTER/RECEIVER	Heat Capacity: ADEQUATE
Average Age NSF: 1958	Intercom: TWO WAY COMPLETE	Walls: STUCCO
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: COMBINATION OF 1-3
Stories: 1		Corridor: SINGLE OUTSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
100	2940	701	COVERED WALKWAY	0	01	CONCRETE	1958	SATISFACTORY	1	58	57
100A	1440	701	COVERED WALKWAY	0	01	CONCRETE	1958	SATISFACTORY	1	58	57
101	240	309	VAULT/STUDENT RECORDS	0	01	COMPOSITION TILE	1958	SATISFACTORY	1	58	57

Report Date: 3/6/2015 4:20:34 PM

Page 2 of 59

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



101A	80	309	VAULT/STUDENT RECORDS	0	01	1958	SATISFACTORY	1	58	57
101B	123	314	ITINERANT OFFICE	0	01	1958	SATISFACTORY	1	58	57
101C	123	314	ITINERANT OFFICE	0	01	1958	SATISFACTORY	1	58	57
101D	123	314	ITINERANT OFFICE	0	01	1958	SATISFACTORY	1	58	57
101E	27	331	CUSTODIAL SERVICE CLOSET	0	01	1958	SATISFACTORY	1	58	57
101F	68	308	GENERAL SCHOOL STORAGE	0	01	1958	SATISFACTORY	1	58	57
101G	184	301	ASSISTANT PRINCIPAL/OTHER OFFICE	0	01	1958	SATISFACTORY	1	58	57
101H	184	301	ASSISTANT PRINCIPAL/OTHER OFFICE	0	01	1958	SATISFACTORY	1	58	57
101J	184	301	ASSISTANT PRINCIPAL/OTHER OFFICE	0	01	1958	SATISFACTORY	1	58	57
101K	236	306	CONFERENCE ROOM	0	01	1958	SATISFACTORY	1	58	57
101L	406	313	CAREERS ROOM	0	01	1958	SATISFACTORY	1	58	57
101M	208	700	INSIDE CIRCULATION	0	01	1958	SATISFACTORY	1	58	57
102	654	304	RECEPTION AREA	0	01	1958	SATISFACTORY	1	58	57
102A	76	702	MECHANICAL ROOM	0	01	1958	SATISFACTORY	1	58	57
102B	32	703	ELECTRICAL ROOM	0	01	1958	SATISFACTORY	1	58	57
102C	499	304	RECEPTION AREA	0	01	1958	SATISFACTORY	1	58	57
102D	236	306	CONFERENCE ROOM	0	01	1958	SATISFACTORY	1	58	57
102E	287	300	PRINCIPAL/DIRECTOR OFFICE	0	01	1958	SATISFACTORY	1	58	57
102F	399	303	SECRETARIAL SPACE	0	01	1958	SATISFACTORY	1	58	57
102G	140	302	BOOKKEEPING OFFICE	0	01	1958	SATISFACTORY	1	58	57
102H	125	312	COMPUTER AREA	0	01	1958	SATISFACTORY	1	58	57
102J	112	309	VAULT/STUDENT RECORDS	0	01	1958	SATISFACTORY	1	58	57
102K	173	301	ASSISTANT PRINCIPAL/OTHER OFFICE	0	01	1958	SATISFACTORY	1	58	57
102L	63	702	MECHANICAL ROOM	0	01	1958	SATISFACTORY	1	58	57

Report Date: 3/6/2015 4:20:34 PM

Page 3 of 59

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



Room No.	Room Description	0	01	CERAMIC TILE	1958	SATISFACTORY	1	58	57
102M 30	STAFF RESTROOM (FEMALE)	0	01	CERAMIC TILE	1958	SATISFACTORY	1	58	57
102N 36	CUSTODIAL SERVICE CLOSET	0	01	CERAMIC TILE	1958	SATISFACTORY	1	58	57
102P 45	STAFF RESTROOM (MALE)	0	01	CERAMIC TILE	1958	SATISFACTORY	1	58	57
103 100	INSIDE CIRCULATION	0	01	COMPOSITION TILE	1958	SATISFACTORY	1	58	57
103A 186	ASSISTANT PRINCIPAL/OTHER OFFICE	0	01	CARPET	1958	SATISFACTORY	1	58	57
103B 181	CLINIC	0	01	COMPOSITION TILE	1958	SATISFACTORY	1	58	57
103C 182	ASSISTANT PRINCIPAL/OTHER OFFICE	0	01	COMPOSITION TILE	1958	SATISFACTORY	1	58	57
103D 53	STUDENT RESTROOM (FEMALE)	0	01	CERAMIC TILE	1958	SATISFACTORY	1	58	57
103E 182	CLINIC	0	01	COMPOSITION TILE	1958	SATISFACTORY	1	58	57
103F 496	PRODUCTION WORKROOM	0	01	COMPOSITION TILE	1958	SATISFACTORY	1	58	57
103G 51	STUDENT RESTROOM (MALE)	0	01	CERAMIC TILE	1958	SATISFACTORY	1	58	57
103H 360	GENERAL SCHOOL STORAGE	0	01	CARPET	1958	SATISFACTORY	1	58	57
103J 125	ASSISTANT PRINCIPAL/OTHER OFFICE	0	01	CARPET	1958	SATISFACTORY	1	58	57
103K 125	ASSISTANT PRINCIPAL/OTHER OFFICE	0	01	CARPET	1958	SATISFACTORY	1	58	57
103L 123	ASSISTANT PRINCIPAL/OTHER OFFICE	0	01	CARPET	1958	SATISFACTORY	1	58	57
103M 480	RECEPTION AREA	0	01	COMPOSITION TILE	1958	SATISFACTORY	1	58	57

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	12,117	0	0	0	0	0	0	0
TOTAL	12,117	0	0	0	0	0	0	0

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 57-A PARKWAY MIDDLE

BUILDING: 2 - Building Number 00002

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: MIDDLE	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1958	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational T.V. FIXED SERVICE TRANSMITTER/RECEIVER	Heat Capacity: ADEQUATE
Average Age NSF: 1958	Intercom: TWO WAY COMPLETE	Walls: STUCCO
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: COMBINATION OF 1-3
Stories: 1		Corridor: SINGLE OUTSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
104	4658	340	DINING AREA A	0	01	COMPOSITION TILE	1958	SATISFACTORY	2	58	57
104A	1062	363	STAGE	0	01	WOOD	1958	SATISFACTORY	2	58	57
104B	80	707	TELEPHONE EQUIPMENT/COMMUNICATION CLOSET	0	01	WOOD	1958	SATISFACTORY	2	58	57
105	1209	346	KITCHEN FOOD PREPARATION	0	01	QUARRY TILE	1958	SATISFACTORY	2	58	57
105A	85	816	STUDENT RESTROOM (FEMALE)	0	01	CERAMIC TILE	1958	SATISFACTORY	2	58	57
105B	270	342	KITCHEN DRY STORAGE	0	01	QUARRY TILE	1958	SATISFACTORY	2	58	57
105C	42	700	INSIDE CIRCULATION	0	01	CERAMIC TILE	1958	SATISFACTORY	2	58	57
105D	91	815	STUDENT RESTROOM (MALE)	0	01	CERAMIC TILE	1958	SATISFACTORY	2	58	57
105E	387	347	KITCHEN DISH WASHING	0	01	QUARRY TILE	1958	SATISFACTORY	2	58	57
105F	130	344	KITCHEN GARBAGE WASH	0	01	QUARRY TILE	1958	SATISFACTORY	2	58	57
105G	90	350	OTHER FOOD SERVICE	0	01	CONCRETE	1958	SATISFACTORY	2	58	57

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



Room No.	Room Name	Code	Count	Material	Year	Count	Room No.
105H 91	INSIDE CIRCULATION	01	0	CARPET	1958	2	57
105J 57	TEACHER LOUNGE/DINING	01	0	COMPOSITION TILE	1958	2	57
105K 21	STAFF RESTROOM (BOTH SEXES)	01	0	CERAMIC TILE	1958	2	57
105L 121	KITCHEN OFFICE	01	0	CARPET	1958	2	57
105M 21	INSIDE CIRCULATION	01	0	CERAMIC TILE	1958	2	57
106 63	MECHANICAL ROOM	01	0	CONCRETE	1958	2	57
200 2297	COVERED WALKWAY	01	0	CONCRETE	1958	2	57

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	10,775	0	0	0	0	0	0	0
TOTAL	10,775	0	0	0	0	0	0	0

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 57-A PARKWAY MIDDLE

BUILDING: 3 - Building Number 00003

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: MIDDLE	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1971	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational T.V. FIXED SERVICE TRANSMITTER/RECEIVER	Heat Capacity: ADEQUATE
Average Age NSF: 1971	Intercom: TWO WAY COMPLETE	Walls: STUCCO
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: COMBINATION OF 1-3
Stories: 1		Corridor: SINGLE OUTSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
107	3649	380	LIBRARY (READING ROOM/STACKS)	0	01	CARPET	1971	SATISFACTORY	3	58	57
107A	147	306	CONFERENCE ROOM	0	01	CARPET	1971	SATISFACTORY	3	58	57
107B	114	301	ASSISTANT PRINCIPAL/OTHER OFFICE	0	01	COMPOSITION TILE	1971	SATISFACTORY	3	58	57
108	136	815	STUDENT RESTROOM (MALE)	0	01	CERAMIC TILE	1971	SATISFACTORY	3	58	57
109	138	816	STUDENT RESTROOM (FEMALE)	0	01	CERAMIC TILE	1971	SATISFACTORY	3	58	57
110	1087	387	MEDIA PRODUCTION LAB	0	01	COMPOSITION TILE	1971	SATISFACTORY	3	58	57
110A	700	306	CONFERENCE ROOM	0	01	COMPOSITION TILE	1971	SATISFACTORY	3	58	57
111	158	702	MECHANICAL ROOM	0	01	CONCRETE	1971	SATISFACTORY	3	58	57

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



Permanent	300	5515	701	COVERED WALKWAY	0	01	CONCRETE	1971	SATISFACTORY	3	58	57
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
	11,644	0	0	0	0	0	0	0	0	0	0	0
TOTAL	11,644	0	0	0	0	0	0	0	0	0	0	0

Report Date: 3/6/2015 4:20:34 PM

Page 8 of 59

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 57-A PARKWAY MIDDLE

BUILDING: 4 - Building Number 00004

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: MIDDLE	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1958	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational T.V. FIXED SERVICE TRANSMITTER/RECEIVER	Heat Capacity: ADEQUATE
Average Age NSF: 1958	Intercom: TWO WAY COMPLETE	Walls: STUCCO
Relocatable Units: 0	Telephone: NONE	Struct Comp: COMBINATION OF 1-3
Stories: 1		Corridor: SINGLE OUTSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
112	824	2	INTERMEDIATE MIDDLE CLASSROOM (4-8)	22	01	CARPET	1958	SATISFACTORY	4	58	57
112A	288	810	MATERIAL STORAGE (LARGE)	0	01	COMPOSITION TILE	1958	SATISFACTORY	4	58	57
112B	1181	11	INTERMEDIATE MIDDLE SKILLS LAB (4-8)	22	01	COMPOSITION TILE	1958	SATISFACTORY	4	58	57
113	197	702	MECHANICAL ROOM	0	01	CONCRETE	1958	SATISFACTORY	4	58	57
114	1243	51	ART - MIDDLE	30	01	COMPOSITION TILE	1958	SATISFACTORY	4	58	57
114A	200	810	MATERIAL STORAGE (LARGE)	0	01	COMPOSITION TILE	1958	SATISFACTORY	4	58	57
114B	150	812	PROJECT STORAGE	0	01	COMPOSITION TILE	1958	SATISFACTORY	4	58	57
114C	60	805	KILN	0	01	COMPOSITION TILE	1958	SATISFACTORY	4	58	57
114D	100	301	ASSISTANT PRINCIPAL/OTHER OFFICE	0	01	COMPOSITION TILE	1958	SATISFACTORY	4	58	57
115	267	304	RECEPTION AREA	0	01	CARPET	1958	SATISFACTORY	4	58	57
115A	77	301	ASSISTANT PRINCIPAL/OTHER OFFICE	0	01	COMPOSITION TILE	1958	SATISFACTORY	4	58	57
115B	77	301	ASSISTANT PRINCIPAL/OTHER OFFICE	0	01	COMPOSITION TILE	1958	SATISFACTORY	4	58	57

Report Date: 3/6/2015 4:20:34 PM

Page 9 of 59

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



Room No.	Room Description	Area	Room No.	Room Description	Area	Material	Year	Condition	Area	Room No.	Room Description	Area	Material	Year	Condition	Area	Scheduled For Replacement																																		
																	Square Feet	Student Stations																																	
115C	245	316	TEACHER LOUNGEDINING	0	01	COMPOSITION TILE	1958	SATISFACTORY	4	58	57																																								
115E	53	820	STAFF RESTROOM (FEMALE)	0	01	CERAMIC TILE	1958	SATISFACTORY	4	58	57																																								
115F	53	819	STAFF RESTROOM (MALE)	0	01	CERAMIC TILE	1958	SATISFACTORY	4	58	57																																								
116	1190	230	HOME ECONOMICS EXPLORATION LAB	17	01	COMPOSITION TILE	1958	SATISFACTORY	4	58	57																																								
117	1134	230	HOME ECONOMICS EXPLORATION LAB	16	01	COMPOSITION TILE	1958	SATISFACTORY	4	58	57																																								
118	205	272	VOCATIONAL LAB SUPPORT SPACE	0	01	COMPOSITION TILE	1958	SATISFACTORY	4	58	57																																								
118A	23	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1958	SATISFACTORY	4	58	57																																								
119	28	820	STAFF RESTROOM (FEMALE)	0	01	CERAMIC TILE	1958	SATISFACTORY	4	58	57																																								
120	28	331	CUSTODIAL SERVICE CLOSET	0	01	CERAMIC TILE	1958	SATISFACTORY	4	58	57																																								
121	104	703	ELECTRICAL ROOM	0	01	CONCRETE	1958	SATISFACTORY	4	58	57																																								
122	206	703	ELECTRICAL ROOM	0	01	CONCRETE	1958	SATISFACTORY	4	58	57																																								
400	2277	701	COVERED WALKWAY	0	01	CONCRETE	1958	SATISFACTORY	4	58	57																																								
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th rowspan="2"></th> <th colspan="2">Satisfactory</th> <th colspan="2">Unsatisfactory</th> <th colspan="2">Failed Standards</th> <th colspan="2">Scheduled For Replacement</th> </tr> <tr> <th>Square Feet</th> <th>Student Stations</th> <th>Square Feet</th> <th>Student Stations</th> <th>Square Feet</th> <th>Student Stations</th> <th>Square Feet</th> <th>Student Stations</th> </tr> </thead> <tbody> <tr> <td>Permanent</td> <td>10,210</td> <td>107</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> </tr> <tr> <td>TOTAL</td> <td>10,210</td> <td>107</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> </tr> </tbody> </table>																		Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement		Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Permanent	10,210	107	0	0	0	0	0	0	TOTAL	10,210	107	0	0	0	0	0	0
	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement																																												
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations																																											
Permanent	10,210	107	0	0	0	0	0	0																																											
TOTAL	10,210	107	0	0	0	0	0	0																																											

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 57-A PARKWAY MIDDLE

BUILDING: 5 - Building Number 00005

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: MIDDLE	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1958	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational T.V. FIXED SERVICE TRANSMITTER/RECEIVER	Heat Capacity: ADEQUATE
Average Age NSF: 1958	Intercom: TWO WAY COMPLETE	Walls: STUCCO
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: COMBINATION OF 1-3
Stories: 1		Corridor: SINGLE OUTSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
123	711	119	P E GYMNASICS & DANCE	0	01	WOOD	1958	SATISFACTORY	5	58	57
124	608	83	MUSIC RELATED SPACE	0	01	WOOD	1958	SATISFACTORY	5	58	57
124A	55	831	MUSIC PRACTICE ROOM	0	01	COMPOSITION TILE	1958	SATISFACTORY	5	58	57
124B	55	831	MUSIC PRACTICE ROOM	0	01	COMPOSITION TILE	1958	SATISFACTORY	5	58	57
124C	55	831	MUSIC PRACTICE ROOM	0	01	COMPOSITION TILE	1958	SATISFACTORY	5	58	57
125	1213	75	VOCAL MUSIC CLASS (MIDDLE-SR HIGH)	21	01	CARPET	1958	SATISFACTORY	5	58	57
125A	61	820	STAFF RESTROOM (FEMALE)	0	01	CERAMIC TILE	1958	SATISFACTORY	5	58	57
125B	61	819	STAFF RESTROOM (MALE)	0	01	CERAMIC TILE	1958	SATISFACTORY	5	58	57
125C	47	700	INSIDE CIRCULATION	0	01	CARPET	1958	SATISFACTORY	5	58	57
126	1540	76	BAND CLASS (MIDDLE-SR HIGH)	50	01	CARPET	1958	SATISFACTORY	5	58	57
126A	153	315	TEACHER PLANNING OFFICE	0	01	CARPET	1958	SATISFACTORY	5	58	57
126B	280	83	MUSIC RELATED SPACE	0	01	COMPOSITION TILE	1958	SATISFACTORY	5	58	57

Report Date: 3/6/2015 4:20:34 PM

Page 11 of 59

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



500	2881	701	COVERED WALKWAY	0	01	CONCRETE	1958		SATISFACTORY	5	58	57
							Failed Standards	Scheduled For Replacement				
			Satisfactory	Unsatisfactory		Failed Standards		Scheduled For Replacement				
			Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet
Permanent			71	7,720	0	0	0	0	0	0	0	0
TOTAL			71	7,720	0	0	0	0	0	0	0	0

Report Date: 3/6/2015 4:20:34 PM

Page 12 of 59

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 57-A PARKWAY MIDDLE

BUILDING: 6 - Building Number 00006

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: MIDDLE	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1958	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified: 1991	Educational T.V. FIXED SERVICE TRANSMITTER/RECEIVER	Heat Capacity: INADEQUATE
Average Age NSF: 1958	Intercom: TWO WAY COMPLETE	Walls: STUCCO
Relocatable Units: 0	Telephone: NONE	Struct Comp: COMBINATION OF 1-3
Stories: 1		Corridor: SINGLE OUTSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
060	65	700	INSIDE CIRCULATION	0	01	COMPOSITION TILE	1958	SATISFACTORY	6	58	57
127	2142	240	TECHNOLOGY/INDUSTRY EXPLORATION LAB	22	01	COMPOSITION TILE	1958	SATISFACTORY	6	58	57
127A	154	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1958	SATISFACTORY	6	58	57
128	1195	51	ART - MIDDLE	28	01	CARPET	1958	SATISFACTORY	6	58	57
128A	27	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1958	SATISFACTORY	6	58	57
128B	67	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1958	SATISFACTORY	6	58	57
128C	67	707	TELEPHONE EQUIPMENT/COMMUNICATION CLOSET	0	01	CONCRETE	1958	SATISFACTORY	6	58	57
129	111	808	MATERIAL STORAGE	0	01	CONCRETE	1958	SATISFACTORY	6	58	57
130	391	330	CUSTODIAL RECEIVING	0	01	CONCRETE	1958	SATISFACTORY	6	58	57
130A	360	334	CUSTODIAL EQUIPMENT STORAGE	0	01	CONCRETE	1958	SATISFACTORY	6	58	57
130B	72	332	CUSTODIAL WORK AREA	0	01	COMPOSITION TILE	1958	SATISFACTORY	6	58	57

Report Date: 3/6/2015 4:20:34 PM

Page 13 of 59

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



130C	70	700	INSIDE CIRCULATION	0	01	COMPOSITION TILE	1958	SATISFACTORY	6	58	57
130E	35	819	STAFF RESTROOM (MALE)	0	01	CERAMIC TILE	1958	SATISFACTORY	6	58	57
131	525	702	MECHANICAL ROOM	0	01	CONCRETE	1958	SATISFACTORY	6	58	57
600	1550	701	COVERED WALKWAY	0	01	CONCRETE	1958	SATISFACTORY	6	58	57

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	6,866	50	0	0	0	0	0	0
TOTAL	6,866	50	0	0	0	0	0	0

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 57-A PARKWAY MIDDLE

BUILDING: 7 - Building Number 00007

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: MIDDLE	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1958	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational T.V. FIXED SERVICE TRANSMITTER/RECEIVER	Heat Capacity: ADEQUATE
Average Age NSF: 1958	Intercom: TWO WAY COMPLETE	Walls: STUCCO
Relocatable Units: 0	Telephone: NONE	Struct Comp: COMBINATION OF 1-3
Stories: 1		Corridor: SINGLE OUTSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
131	960	2	INTERMEDIATE MIDDLE CLASSROOM (4-8)	22	01	CARPET	1958	SATISFACTORY	7	58	57
131A	102	808	MATERIAL STORAGE	0	01	CARPET	1958	SATISFACTORY	7	58	57
132	967	11	INTERMEDIATE MIDDLE SKILLS LAB (4-8)	22	01	CARPET	1958	SATISFACTORY	7	58	57
132A	102	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1958	SATISFACTORY	7	58	57
133	914	11	INTERMEDIATE MIDDLE SKILLS LAB (4-8)	22	01	CARPET	1958	SATISFACTORY	7	58	57
133A	144	808	MATERIAL STORAGE	0	01	CARPET	1958	SATISFACTORY	7	58	57
700	1399	701	COVERED WALKWAY	0	01	CONCRETE	1958	SATISFACTORY	7	58	57
700B	6200	701	COVERED WALKWAY	0	01	CONCRETE	1958	SATISFACTORY	7	58	57

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	10,788	66	0	0	0	0	0	0
TOTAL	10,788	66	0	0	0	0	0	0

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 57-A PARKWAY MIDDLE

BUILDING: 8 - Building Number 00008

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: MIDDLE	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1958	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational T.V. FIXED SERVICE TRANSMITTER/RECEIVER	Heat Capacity: ADEQUATE
Average Age NSF: 1958	Intercom: TWO WAY COMPLETE	Walls: STUCCO
Relocatable Units: 0	Telephone: NONE	Struct Comp: COMBINATION OF 1-3
Stories: 1		Corridor: SINGLE OUTSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
135	355	313	CAREERS ROOM	0	01	CARPET	1958	SATISFACTORY	8	58	57
136	718	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	1958	SATISFACTORY	8	58	57
137	736	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	1958	SATISFACTORY	8	58	57
137A	736	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	1958	SATISFACTORY	8	58	57
138	718	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	1958	SATISFACTORY	8	58	57
700A	1363	701	COVERED WALKWAY	0	01	CONCRETE	1958	SATISFACTORY	8	58	57

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	4,626	88	0	0	0	0	0	0
TOTAL	4,626	88	0	0	0	0	0	0

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 57-A PARKWAY MIDDLE

BUILDING: 9 - Building Number 00009

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: MIDDLE	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1958	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational T.V. FIXED SERVICE TRANSMITTER/RECEIVER	Heat Capacity: ADEQUATE
Average Age NSF: 1958	Intercom: TWO WAY COMPLETE	Walls: STUCCO
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: COMBINATION OF 1-3
Stories: 1		Corridor: SINGLE OUTSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
139	736	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	1958	SATISFACTORY	9	58	57
139A	736	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	1958	SATISFACTORY	9	58	57
140	718	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	1958	SATISFACTORY	9	58	57
141	718	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	1958	SATISFACTORY	9	58	57
142	294	816	STUDENT RESTROOM (FEMALE)	0	01	CERAMIC TILE	1958	SATISFACTORY	9	58	57
142A	20	702	MECHANICAL ROOM	0	01	CONCRETE	1958	SATISFACTORY	9	58	57
143	22	331	CUSTODIAL SERVICE CLOSET	0	01	CONCRETE	1958	SATISFACTORY	9	58	57
800	2128	701	COVERED WALKWAY	0	01	CONCRETE	1958	SATISFACTORY	9	58	57

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	5,372	88	0	0				
TOTAL	5,372	88	0	0	0	0	0	0

Report Date: 3/6/2015 4:20:34 PM

Page 17 of 59

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 57-A PARKWAY MIDDLE

BUILDING: 10 - Building Number 00010

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: MIDDLE	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1958	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational T.V. FIXED SERVICE TRANSMITTER/RECEIVER	Heat Capacity: ADEQUATE
Average Age NSF: 1958	Intercom: TWO WAY COMPLETE	Walls: STUCCO
Relocatable Units: 0	Telephone: NONE	Struct Comp: COMBINATION OF 1-3
Stories: 1		Corridor: SINGLE OUTSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
144	294	815	STUDENT RESTROOM (MALE)	0	01	CERAMIC TILE	1958	SATISFACTORY	10	58	57
144A	20	702	MECHANICAL ROOM	0	01	CONCRETE	1958	SATISFACTORY	10	58	57
145	22	331	CUSTODIAL SERVICE CLOSET	0	01	CONCRETE	1958	SATISFACTORY	10	58	57
146	804	20	INTERMEDIATE MIDDLE SCIENCE DEMO (4-8)	22	01	COMPOSITION TILE	1958	SATISFACTORY	10	58	57
146A	180	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1958	SATISFACTORY	10	58	57
146B	156	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1958	SATISFACTORY	10	58	57
146C	70	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1958	SATISFACTORY	10	58	57
146D	96	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1958	SATISFACTORY	10	58	57
147	257	315	TEACHER PLANNING OFFICE	0	01	COMPOSITION TILE	1958	SATISFACTORY	10	58	57
147A	264	810	MATERIAL STORAGE (LARGE)	0	01	COMPOSITION TILE	1958	SATISFACTORY	10	58	57
148	1232	20	INTERMEDIATE MIDDLE SCIENCE DEMO (4-8)	22	01	COMPOSITION TILE	1958	SATISFACTORY	10	58	57

Report Date: 3/6/2015 4:20:34 PM

Page 18 of 59

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



	800A	1363	701	COVERED WALKWAY	0	01	CONCRETE	1958	SATISFACTORY	10	58	57
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	4,758	44	0	0	0	0	0	0	0	0	0	0
TOTAL	4,758	44	0	0	0	0	0	0	0	0	0	0

Report Date: 3/6/2015 4:20:34 PM

Page 19 of 59

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 57-A PARKWAY MIDDLE

BUILDING: 12 - Building Number 00012

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: MIDDLE	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1991	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational T.V. FIXED SERVICE TRANSMITTER/RECEIVER	Heat Capacity: ADEQUATE
Average Age NSF: 1991	Intercom: TWO WAY COMPLETE	Walls: STUCCO
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: COMBINATION OF 1-3
Stories: 1		Corridor: SINGLE OUTSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
149	208	315	TEACHER PLANNING OFFICE	0	01	COMPOSITION TILE	1991	SATISFACTORY	12	58	57
149A	416	315	TEACHER PLANNING OFFICE	0	01	CARPET	1991	SATISFACTORY	12	58	57
149B	48	308	GENERAL SCHOOL STORAGE	0	01	COMPOSITION TILE	1991	SATISFACTORY	12	58	57
149C	176	315	TEACHER PLANNING OFFICE	0	01	COMPOSITION TILE	1991	SATISFACTORY	12	58	57
149D	120	703	ELECTRICAL ROOM	0	01	CONCRETE	1991	SATISFACTORY	12	58	57
149E	572	65	E S E RESOURCE	0	01	COMPOSITION TILE	1991	SATISFACTORY	12	58	57
149F	108	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1991	SATISFACTORY	12	58	57
150	395	65	E S E RESOURCE	0	01	COMPOSITION TILE	1991	SATISFACTORY	12	58	57
150A	108	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1991	SATISFACTORY	12	58	57
151	799	61	E S E PART-TIME	15	01	COMPOSITION TILE	1991	SATISFACTORY	12	58	57
151A	80	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1991	SATISFACTORY	12	58	57
152	799	61	E S E PART-TIME	15	01	COMPOSITION TILE	1991	SATISFACTORY	12	58	57

Report Date: 3/6/2015 4:20:34 PM

Page 20 of 59

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



Item ID	Room Number	Description	Material	Quantity	Unit	Year	Condition	Count	Room Number
152A	80	MATERIAL STORAGE	COMPOSITION TILE	0	01	1991	SATISFACTORY	12	58
153	799	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	COMPOSITION TILE	22	01	1991	SATISFACTORY	12	58
153A	80	MATERIAL STORAGE	COMPOSITION TILE	0	01	1991	SATISFACTORY	12	58
154	799	E S E P ART -TIME	COMPOSITION TILE	15	01	1991	SATISFACTORY	12	58
154A	80	MATERIAL STORAGE	COMPOSITION TILE	0	01	1991	SATISFACTORY	12	58
155	128	CUSTODIAL WORK AREA	CONCRETE	0	01	1991	SATISFACTORY	12	58
155A	229	TELEPHONE EQUIPMENT/COMMUNICATION CLOSET	COMPOSITION TILE	0	01	1991	SATISFACTORY	12	58
800B	2430	COVERED WALKWAY	CONCRETE	0	01	1991	SATISFACTORY	12	58

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	8,454	67	0	0	0	0	0	0
TOTAL	8,454	67	0	0	0	0	0	0

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 57-A PARKWAY MIDDLE

BUILDING: 13 - Building Number 00013

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: MIDDLE	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1958	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational T.V. FIXED SERVICE TRANSMITTER/RECEIVER	Heat Capacity: ADEQUATE
Average Age NSF: 1958	Intercom: TWO WAY COMPLETE	Walls: STUCCO
Relocatable Units: 0	Telephone: NONE	Struct Comp: COMBINATION OF 1-3
Stories: 1		Corridor: SINGLE OUTSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
156	351	810	MATERIAL STORAGE (LARGE)	0	01	COMPOSITION TILE	1958	SATISFACTORY	13	58	57
157	1088	20	INTERMEDIATE/MIDDLE SCIENCE DEMO (4-8)	22	01	COMPOSITION TILE	1958	SATISFACTORY	13	58	57
158	607	810	MATERIAL STORAGE (LARGE)	0	01	COMPOSITION TILE	1958	SATISFACTORY	13	58	57
158A	90	812	PROJECT STORAGE	0	01	COMPOSITION TILE	1958	SATISFACTORY	13	58	57
159	1173	20	INTERMEDIATE/MIDDLE SCIENCE DEMO (4-8)	22	01	COMPOSITION TILE	1958	SATISFACTORY	13	58	57
800C	1363	701	COVERED WALKWAY	0	01	CONCRETE	1958	SATISFACTORY	13	58	57

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	4,672	44	0	0				
TOTAL	4,672	44	0	0	0	0	0	0

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 57-A PARKWAY MIDDLE

BUILDING: 14 - Building Number 00014

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: MIDDLE	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1958	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational T.V. FIXED SERVICE TRANSMITTER/RECEIVER	Heat Capacity: ADEQUATE
Average Age NSF: 1958	Intercom: TWO WAY COMPLETE	Walls: STUCCO
Relocatable Units: 0	Telephone: NONE	Struct Comp: COMBINATION OF 1-3
Stories: 1		Corridor: SINGLE OUTSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
160	718	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	1958	SATISFACTORY	14	58	57
161	736	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	1958	SATISFACTORY	14	58	57
161A	736	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	1958	SATISFACTORY	14	58	57
162	718	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	1958	SATISFACTORY	14	58	57
163	294	816	STUDENT RESTROOM (FEMALE)	0	01	CERAMIC TILE	1958	SATISFACTORY	14	58	57
163A	20	702	MECHANICAL ROOM	0	01	CONCRETE	1958	SATISFACTORY	14	58	57
164	22	331	CUSTODIAL SERVICE CLOSET	0	01	CONCRETE	1958	SATISFACTORY	14	58	57
8000	1350	701	COVERED WALKWAY	0	01	CONCRETE	1958	SATISFACTORY	14	58	57

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	4,594	88	0	0				
TOTAL	4,594	88	0	0	0	0	0	0

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 57-A PARKWAY MIDDLE

BUILDING: 15 - Building Number 00015

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: MIDDLE	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1958	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational T.V. FIXED SERVICE TRANSMITTER/RECEIVER	Heat Capacity: ADEQUATE
Average Age NSF: 1958	Intercom: TWO WAY COMPLETE	Walls: STUCCO
Relocatable Units: 0	Telephone: NONE	Struct Comp: COMBINATION OF 1-3
Stories: 1		Corridor: SINGLE OUTSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
165	294	815	STUDENT RESTROOM (MALE)	0	01	CERAMIC TILE	1958	SATISFACTORY	15	58	57
166	22	331	CUSTODIAL SERVICE CLOSET	0	01	CONCRETE	1958	SATISFACTORY	15	58	57
167	718	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	1958	SATISFACTORY	15	58	57
168	736	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	1958	SATISFACTORY	15	58	57
168A	736	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	1958	SATISFACTORY	15	58	57
169	718	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	1958	SATISFACTORY	15	58	57
800E	1363	701	COVERED WALKWAY	0	01	CONCRETE	1958	SATISFACTORY	15	58	57

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	4,587	88	0	0				
TOTAL	4,587	88	0	0	0	0	0	0

Report Date: 3/6/2015 4:20:34 PM

Page 24 of 59

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 57-A PARKWAY MIDDLE

BUILDING: 16 - Building Number 00016

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: MIDDLE	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1958	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational T.V. FIXED SERVICE TRANSMITTER/RECEIVER	Heat Capacity: ADEQUATE
Average Age NSF: 1958	Intercom: TWO WAY COMPLETE	Walls: STUCCO
Relocatable Units: 0	Telephone: NONE	Struct Comp: COMBINATION OF 1-3
Stories: 1		Corridor: SINGLE OUTSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
170	718	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	1958	SATISFACTORY	16	58	57
171	718	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	1958	SATISFACTORY	16	58	57
172	736	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	1958	SATISFACTORY	16	58	57
172A	736	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	1958	SATISFACTORY	16	58	57
173	294	816	STUDENT RESTROOM (FEMALE)	0	01	CERAMIC TILE	1958	SATISFACTORY	16	58	57
173A	20	702	MECHANICAL ROOM	0	01	CONCRETE	1958	SATISFACTORY	16	58	57
174	22	331	CUSTODIAL SERVICE CLOSET	0	01	CONCRETE	1958	SATISFACTORY	16	58	57
800F	1350	701	COVERED WALKWAY	0	01	CONCRETE	1958	SATISFACTORY	16	58	57

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	4,594	88	0	0				
TOTAL	4,594	88	0	0	0	0	0	0

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 57-A PARKWAY MIDDLE

BUILDING: 17 - Building Number 00017

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: MIDDLE	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1958	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational T.V. FIXED SERVICE TRANSMITTER/RECEIVER	Heat Capacity: ADEQUATE
Average Age NSF: 1958	Intercom: TWO WAY COMPLETE	Walls: STUCCO
Relocatable Units: 0	Telephone: NONE	Struct Comp: COMBINATION OF 1-3
Stories: 1		Corridor: SINGLE OUTSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
175	294	815	STUDENT RESTROOM (MALE)	0	01	CERAMIC TILE	1958	SATISFACTORY	17	58	57
176	22	331	CUSTODIAL SERVICE CLOSET	0	01	CONCRETE	1958	SATISFACTORY	17	58	57
177	718	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	1958	SATISFACTORY	17	58	57
178	718	62	E S E FULL-TIME	10	01	CARPET	1958	SATISFACTORY	17	58	57
179	352	65	E S E RESOURCE	0	01	CARPET	1958	SATISFACTORY	17	58	57
180	448	65	E S E RESOURCE	0	01	CARPET	1958	SATISFACTORY	17	58	57
180A	635	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	1958	SATISFACTORY	17	58	57
800G	1363	701	COVERED WALKWAY	0	01	CONCRETE	1958	SATISFACTORY	17	58	57

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	4,550	54	0	0				
TOTAL	4,550	54	0	0	0	0	0	0

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 57-A PARKWAY MIDDLE

BUILDING: 18 - Building Number 00018

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: NONE
Use: MIDDLE	Mech Vent: NONE	Heat Source: NONE
Year Constructed: 1971	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: NO HEAT PROVIDED
Year Modified:	Educational T.V: NONE	Heat Capacity: NONE
Average Age NSF: 1971	Intercom: NONE	Walls: STUCCO
Relocatable Units: 0	Telephone: NONE	Struct Comp: COMBINATION OF 1-3
Stories: 1		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
181	212	334	CUSTODIAL EQUIPMENT STORAGE	0	01	CONCRETE	1971	SATISFACTORY	18	58	57
182	465	702	MECHANICAL ROOM	0	01	CONCRETE	1971	SATISFACTORY	18	58	57

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	677	0	0	0				
TOTAL	677	0	0	0	0	0	0	0

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 57-A PARKWAY MIDDLE

BUILDING: 19 - Building Number 00019

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: MIDDLE	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1958	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational T.V. FIXED SERVICE TRANSMITTER/RECEIVER	Heat Capacity: ADEQUATE
Average Age NSF: 1958	Intercom: TWO WAY COMPLETE	Walls: STUCCO
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: COMBINATION OF 1-3
Stories: 1		Corridor: SINGLE OUTSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
183	1415	90	P E DRESSING ROOM (MALE)	0	01	CERAMIC TILE	1958	SATISFACTORY	19	58	57
183A	213	315	TEACHER PLANNING OFFICE	0	01	CERAMIC TILE	1958	SATISFACTORY	19	58	57
183B	95	98	P E STORAGE (MIDDLE-SR HIGH)	0	01	CERAMIC TILE	1958	SATISFACTORY	19	58	57
183C	264	815	STUDENT RESTROOM (MALE)	0	01	CERAMIC TILE	1958	SATISFACTORY	19	58	57
183D	449	94	P E SHOWER (MALE)	0	01	CERAMIC TILE	1958	SATISFACTORY	19	58	57
183E	72	700	INSIDE CIRCULATION	0	01	CERAMIC TILE	1958	SATISFACTORY	19	58	57
184	1415	91	P E DRESSING ROOM (FEMALE)	0	01	CERAMIC TILE	1958	SATISFACTORY	19	58	57
184A	204	315	TEACHER PLANNING OFFICE	0	01	CERAMIC TILE	1958	SATISFACTORY	19	58	57
184B	108	700	INSIDE CIRCULATION	0	01	CERAMIC TILE	1958	SATISFACTORY	19	58	57
184C	86	98	P E STORAGE (MIDDLE-SR HIGH)	0	01	CERAMIC TILE	1958	SATISFACTORY	19	58	57
184D	264	816	STUDENT RESTROOM (FEMALE)	0	01	CERAMIC TILE	1958	SATISFACTORY	19	58	57
184E	425	95	P E SHOWER (FEMALE)	0	01	CERAMIC TILE	1958	SATISFACTORY	19	58	57

Report Date: 3/6/2015 4:20:34 PM

Page 28 of 59

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



	184F	218	702	MECHANICAL ROOM	0	01	CONCRETE	1958	SATISFACTORY	19	58	57
800H	1980	700	INSIDE CIRCULATION	0	01	CONCRETE	1958	SATISFACTORY	19	58	57	
		Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement				
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations		
Permanent	7,426	0	0	0	0	0	0	0	0	0	0	
TOTAL	7,426	0	0	0	0	0	0	0	0	0	0	

Report Date: 3/6/2015 4:20:34 PM

Page 29 of 59

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 57-A PARKWAY MIDDLE

BUILDING: 21 - Building Number 00021

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: NONE
Use: MIDDLE	Mech Vent: ADEQUATE	Heat Source: NONE
Year Constructed: 1975	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: NO HEAT PROVIDED
Year Modified:	Educational T.V: NONE	Heat Capacity: NONE
Average Age NSF: 1975	Intercom: NONE	Walls: CONCRETE
Relocatable Units: 0	Telephone: NONE	Struct Comp: CONCRETE
Stories: 1		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
301	102	333	FLAMMABLE STORAGE	0	01	CONCRETE	1975	SATISFACTORY	21	58	57
301 A	62	333	FLAMMABLE STORAGE	0	01	CONCRETE	1975	SATISFACTORY	21	58	57

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	164	0	0	0				
TOTAL	164	0	0	0	0	0	0	0

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 57-A PARKWAY MIDDLE

BUILDING: 22 - Building Number 00022

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: MIDDLE	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1990	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational T.V. FIXED SERVICE TRANSMITTER/RECEIVER	Heat Capacity: ADEQUATE
Average Age NSF: 1990	Intercom: TWO WAY COMPLETE	Walls: STUCCO
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: COMBINATION OF 1-3
Stories: 1		Corridor: DOUBLE INSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
009	42	700	INSIDE CIRCULATION	0	01	CARPET	1990	SATISFACTORY	22	58	57
009B	138	700	INSIDE CIRCULATION	0	01	CARPET	1990	SATISFACTORY	22	58	57
009C	138	700	INSIDE CIRCULATION	0	01	CARPET	1990	SATISFACTORY	22	58	57
020	840	700	INSIDE CIRCULATION	0	01	COMPOSITION TILE	1990	SATISFACTORY	22	58	57
020A	100	700	INSIDE CIRCULATION	0	01	COMPOSITION TILE	1990	SATISFACTORY	22	58	57
020B	160	700	INSIDE CIRCULATION	0	01	COMPOSITION TILE	1990	SATISFACTORY	22	58	57
020C	160	700	INSIDE CIRCULATION	0	01	COMPOSITION TILE	1990	SATISFACTORY	22	58	57
020D	540	700	INSIDE CIRCULATION	0	01	COMPOSITION TILE	1990	SATISFACTORY	22	58	57
020E	806	700	INSIDE CIRCULATION	0	01	COMPOSITION TILE	1990	SATISFACTORY	22	58	57
020F	95	700	INSIDE CIRCULATION	0	01	COMPOSITION TILE	1990	SATISFACTORY	22	58	57
020G	143	700	INSIDE CIRCULATION	0	01	COMPOSITION TILE	1990	SATISFACTORY	22	58	57
020H	80	700	INSIDE CIRCULATION	0	01	COMPOSITION TILE	1990	SATISFACTORY	22	58	57

Report Date: 3/6/2015 4:20:34 PM

Page 31 of 59

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



020J	1023	700	INSIDE CIRCULATION	0	01	COMPOSITION TILE	1990	SATISFACTORY	22	58	57
191	756	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	CARPET	1990	SATISFACTORY	22	58	57
192	1300	11	INTERMEDIATE/MIDDLE SKILLS LAB (4-8)	22	01	CARPET	1990	SATISFACTORY	22	58	57
192A	417	40	RESOURCE ROOM	0	01	CARPET	1990	SATISFACTORY	22	58	57
192B	70	819	STAFF RESTROOM (MALE)	0	01	CERAMIC TILE	1990	SATISFACTORY	22	58	57
192C	70	820	STAFF RESTROOM (FEMALE)	0	01	CERAMIC TILE	1990	SATISFACTORY	22	58	57
192D	139	702	MECHANICAL ROOM	0	01	CONCRETE	1990	SATISFACTORY	22	58	57
192E	428	315	TEACHER PLANNING OFFICE	0	01	CARPET	1990	SATISFACTORY	22	58	57
900	553	701	COVERED WALKWAY	0	01	CONCRETE	1990	SATISFACTORY	22	58	57
900A	420	701	COVERED WALKWAY	0	01	CONCRETE	1990	SATISFACTORY	22	58	57
900B	500	701	COVERED WALKWAY	0	01	CONCRETE	1990	SATISFACTORY	22	58	57
900C	64	701	COVERED WALKWAY	0	01	CONCRETE	1990	SATISFACTORY	22	58	57
900D	30	701	COVERED WALKWAY	0	01	CONCRETE	1990	SATISFACTORY	22	58	57
900E	2614	701	COVERED WALKWAY	0	01	CONCRETE	1990	SATISFACTORY	22	58	57
900F	1140	701	COVERED WALKWAY	0	01	CONCRETE	1990	SATISFACTORY	22	58	57
901	975	370	LOBBY	0	01	CARPET	1990	SATISFACTORY	22	58	57
901A	54	372	TICKET BOOTH	0	01	CERAMIC TILE	1990	SATISFACTORY	22	58	57
901B	127	371	CONCESSIONS	0	01	CERAMIC TILE	1990	SATISFACTORY	22	58	57
901C	127	371	CONCESSIONS	0	01	COMPOSITION TILE	1990	SATISFACTORY	22	58	57
901D	43	331	CUSTODIAL SERVICE CLOSET	0	01	CERAMIC TILE	1990	SATISFACTORY	22	58	57
902	28	700	INSIDE CIRCULATION	0	01	CERAMIC TILE	1990	SATISFACTORY	22	58	57
902A	200	823	PUBLIC USE RESTROOM (FEMALE)	0	01	COMPOSITION TILE	1990	SATISFACTORY	22	58	57
903	28	700	INSIDE CIRCULATION	0	01	CERAMIC TILE	1990	SATISFACTORY	22	58	57
903A	200	822	PUBLIC USE RESTROOM (MALE)	0	01	CERAMIC TILE	1990	SATISFACTORY	22	58	57

Report Date: 3/6/2015 4:20:34 PM

Page 32 of 59

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



904	165	367	CONTROL BOOTH/PROJECTION ROOM	0	01	CARPET	1990	SATISFACTORY	22	58	57
905	195	702	MECHANICAL ROOM	0	01	CONCRETE	1990	SATISFACTORY	22	58	57
906	195	702	MECHANICAL ROOM	0	01	CONCRETE	1990	SATISFACTORY	22	58	57
907	5321	360	AUDITORIUM	0	01	CARPET	1990	SATISFACTORY	22	58	57
907C	362	367	CONTROL BOOTH/PROJECTION ROOM	0	01	COMPOSITION TILE	1990	SATISFACTORY	22	58	57
908	1685	363	STAGE	0	01	WOOD	1990	SATISFACTORY	22	58	57
908A	70	703	ELECTRICAL ROOM	0	01	CONCRETE	1990	SATISFACTORY	22	58	57
908B	959	364	STAGE STORAGE	0	01	CONCRETE	1990	SATISFACTORY	22	58	57
908C	746	364	STAGE STORAGE	0	01	CONCRETE	1990	SATISFACTORY	22	58	57
909	272	370	LOBBY	0	01	COMPOSITION TILE	1990	SATISFACTORY	22	58	57
910	110	366	STAGE DRESSING ROOM (FEMALE)	0	01	COMPOSITION TILE	1990	SATISFACTORY	22	58	57
910A	82	366	STAGE DRESSING ROOM (FEMALE)	0	01	COMPOSITION TILE	1990	SATISFACTORY	22	58	57
911	110	365	STAGE DRESSING ROOM (MALE)	0	01	COMPOSITION TILE	1990	SATISFACTORY	22	58	57
911A	82	365	STAGE DRESSING ROOM (MALE)	0	01	COMPOSITION TILE	1990	SATISFACTORY	22	58	57
912	136	806	REFERENCE	0	01	CARPET	1990	SATISFACTORY	22	58	57
913	595	83	MUSIC RELATED SPACE	0	01	COMPOSITION TILE	1990	SATISFACTORY	22	58	57
913A	43	364	STAGE STORAGE	0	01	COMPOSITION TILE	1990	SATISFACTORY	22	58	57
913B	319	702	MECHANICAL ROOM	0	01	CONCRETE	1990	SATISFACTORY	22	58	57
913C	396	810	MATERIAL STORAGE (LARGE)	0	01	CONCRETE	1990	SATISFACTORY	22	58	57
914	1400	77	ORCHESTRA CLASS (MIDDLE-SR HIGH)	25	01	CARPET	1990	SATISFACTORY	22	58	57
914A	40	831	MUSIC PRACTICE ROOM	0	01	CARPET	1990	SATISFACTORY	22	58	57
914B	40	831	MUSIC PRACTICE ROOM	0	01	CARPET	1990	SATISFACTORY	22	58	57
914C	40	831	MUSIC PRACTICE ROOM	0	01	CARPET	1990	SATISFACTORY	22	58	57
914D	417	83	MUSIC RELATED SPACE	0	01	CARPET	1990	SATISFACTORY	22	58	57

Report Date: 3/6/2015 4:20:34 PM

Page 33 of 59

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



914E	371	83	MUSIC RELATED SPACE	0	01	CARPET	1990	SATISFACTORY	22	58	57
914F	300	83	MUSIC RELATED SPACE	0	01	CARPET	1990	SATISFACTORY	22	58	57
914G	25	331	CUSTODIAL SERVICE CLOSET	0	01	CERAMIC TILE	1990	SATISFACTORY	22	58	57
915	34	815	STUDENT RESTROOM (MALE)	0	01	CERAMIC TILE	1990	SATISFACTORY	22	58	57
916	25	331	CUSTODIAL SERVICE CLOSET	0	01	CERAMIC TILE	1990	SATISFACTORY	22	58	57
917	1562	78	GENERAL MUSIC CLASS (MIDDLE-SR HIGH)	30	01	COMPOSITION TILE	1990	SATISFACTORY	22	58	57
917A	1670	78	GENERAL MUSIC CLASS (MIDDLE-SR HIGH)	30	01	COMPOSITION TILE	1990	SATISFACTORY	22	58	57
917B	400	83	MUSIC RELATED SPACE	0	01	COMPOSITION TILE	1990	SATISFACTORY	22	58	57
917C	117	365	STAGE DRESSING ROOM (MALE)	0	01	COMPOSITION TILE	1990	SATISFACTORY	22	58	57
917D	120	364	STAGE STORAGE	0	01	COMPOSITION TILE	1990	SATISFACTORY	22	58	57
917E	117	364	STAGE STORAGE	0	01	COMPOSITION TILE	1990	SATISFACTORY	22	58	57
917F	120	366	STAGE DRESSING ROOM (FEMALE)	0	01	COMPOSITION TILE	1990	SATISFACTORY	22	58	57
918	34	816	STUDENT RESTROOM (FEMALE)	0	01	CERAMIC TILE	1990	SATISFACTORY	22	58	57
919	25	331	CUSTODIAL SERVICE CLOSET	0	01	CERAMIC TILE	1990	SATISFACTORY	22	58	57
920	571	75	VOCAL MUSIC CLASS (MIDDLE-SR HIGH)	10	01	CARPET	1990	SATISFACTORY	22	58	57
922	280	815	STUDENT RESTROOM (MALE)	0	01	CERAMIC TILE	1990	SATISFACTORY	22	58	57
923	280	816	STUDENT RESTROOM (FEMALE)	0	01	CERAMIC TILE	1990	SATISFACTORY	22	58	57
924	27	331	CUSTODIAL SERVICE CLOSET	0	01	CERAMIC TILE	1990	SATISFACTORY	22	58	57
925	1040	119	P E G YMNASTICS & DANCE	0	01	WOOD	1990	SATISFACTORY	22	58	57
926	1122	119	P E G YMNASTICS & DANCE	0	01	WOOD	1990	SATISFACTORY	22	58	57
926A	245	83	MUSIC RELATED SPACE	0	01	COMPOSITION TILE	1990	SATISFACTORY	22	58	57
926B	245	810	MATERIAL STORAGE (LARGE)	0	01	COMPOSITION TILE	1990	SATISFACTORY	22	58	57
927	628	702	MECHANICAL ROOM	0	01	CONCRETE	1990	SATISFACTORY	22	58	57
928	1265	51	ART - MIDDLE	30	01	COMPOSITION TILE	1990	SATISFACTORY	22	58	57

Report Date: 3/6/2015 4:20:34 PM

Page 34 of 59

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



928A	293	272	VOCATIONAL LAB SUPPORT SPACE	0	01	CARPET	1990	SATISFACTORY	22	58	57
928B	186	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1990	SATISFACTORY	22	58	57
928C	112	805	KILN	0	01	COMPOSITION TILE	1990	SATISFACTORY	22	58	57
928D	90	315	TEACHER PLANNING OFFICE	0	01	CARPET	1990	SATISFACTORY	22	58	57
928E	660	701	COVERED WALKWAY	0	01	CONCRETE	1990	SATISFACTORY	22	58	57
928F	135	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1990	SATISFACTORY	22	58	57
929	1265	51	ART - MIDDLE	30	01	COMPOSITION TILE	1990	SATISFACTORY	22	58	57
929A	293	272	VOCATIONAL LAB SUPPORT SPACE	0	01	COMPOSITION TILE	1990	SATISFACTORY	22	58	57
929B	137	803	INSTRUCTIONAL DARKROOM	0	01	COMPOSITION TILE	1990	SATISFACTORY	22	58	57
929C	15	803	INSTRUCTIONAL DARKROOM	0	01	COMPOSITION TILE	1990	SATISFACTORY	22	58	57
929D	90	315	TEACHER PLANNING OFFICE	0	01	CARPET	1990	SATISFACTORY	22	58	57
929E	340	849	VOCATIONAL PROJECT STORAGE	0	01	COMPOSITION TILE	1990	SATISFACTORY	22	58	57
929F	660	701	COVERED WALKWAY	0	01	CONCRETE	1990	SATISFACTORY	22	58	57
929G	135	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1990	SATISFACTORY	22	58	57
930	30	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1990	SATISFACTORY	22	58	57
931	30	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1990	SATISFACTORY	22	58	57
932	25	331	CUSTODIAL SERVICE CLOSET	0	01	CERAMIC TILE	1990	SATISFACTORY	22	58	57
933	442	315	TEACHER PLANNING OFFICE	0	01	CARPET	1990	SATISFACTORY	22	58	57
934	80	304	RECEPTION AREA	0	01	CARPET	1990	SATISFACTORY	22	58	57
934A	89	315	TEACHER PLANNING OFFICE	0	01	CARPET	1990	SATISFACTORY	22	58	57

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



	934B	175	306	CONFERENCE ROOM		0	01	CARPET	1990	SATISFACTORY		22	58	57
				Square Feet	Student Stations					Square Feet	Student Stations			
				Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement				
				Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations			
Permanent				44,233	199	0	0							
TOTAL				44,233	199	0	0	0	0	0	0			0

Report Date: 3/6/2015 4:20:34 PM

Page 36 of 59

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 57-A PARKWAY MIDDLE

BUILDING: 23 - Building Number 00023

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: NONE
Use: MIDDLE	Mech Vent: ADEQUATE	Heat Source: NONE
Year Constructed: 1990	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: NO HEAT PROVIDED
Year Modified:	Educational T.V: NONE	Heat Capacity: NONE
Average Age NSF: 1990	Intercom: NONE	Walls: STUCCO
Relocatable Units: 0	Telephone: NONE	Struct Comp: CONCRETE
Stories: 1		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
935	750	703	ELECTRICAL ROOM	0	01	CONCRETE	1990	SATISFACTORY	23	58	57
936	650	703	ELECTRICAL ROOM	0	01	CONCRETE	1990	SATISFACTORY	23	58	57
936A	100	703	ELECTRICAL ROOM	0	01	CONCRETE	1990	SATISFACTORY	23	58	57
937	900	702	MECHANICAL ROOM	0	01	CONCRETE	1990	SATISFACTORY	23	58	57

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	2,400	0	0	0	0	0	0	0
TOTAL	2,400	0	0	0	0	0	0	0

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 57-A PARKWAY MIDDLE

BUILDING: 24 - Building Number 00024

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: MIDDLE	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1997	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational T.V. FIXED SERVICE RECEIVER	Heat Capacity: ADEQUATE
Average Age NSF: 1997	Intercom: TWO WAY COMPLETE	Walls: STUCCO
Relocatable Units: 0	Telephone: NONE	Struct Comp: COMBINATION OF 1-3
Stories: 2		Corridor: DOUBLE OUTSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
014	434	700	INSIDE CIRCULATION	0	01	CONCRETE	1997	SATISFACTORY	24	58	57
014A	434	700	INSIDE CIRCULATION	0	01	CONCRETE	1997	SATISFACTORY	24	58	57
014B	434	700	INSIDE CIRCULATION	0	01	CONCRETE	1997	SATISFACTORY	24	58	57
014C	45	827	ELEVATOR (PASSENGER/HANDICAPPED)	0	01	COMPOSITION TILE	1997	SATISFACTORY	24	58	57
400A	820	701	COVERED WALKWAY	0	01	CONCRETE	1997	SATISFACTORY	24	58	57
400B	1400	701	COVERED WALKWAY	0	01	CONCRETE	1997	SATISFACTORY	24	58	57
400C	820	701	COVERED WALKWAY	0	01	CONCRETE	1997	SATISFACTORY	24	58	57
400D	1400	701	COVERED WALKWAY	0	01	CONCRETE	1997	SATISFACTORY	24	58	57
425	810	2	INTERMEDIATE MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	1997	SATISFACTORY	24	58	57
425B	60	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1997	SATISFACTORY	24	58	57
426	810	2	INTERMEDIATE MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	1997	SATISFACTORY	24	58	57
426A	71	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1997	SATISFACTORY	24	58	57

Report Date: 3/6/2015 4:20:34 PM

Page 38 of 59

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



427	810	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	1997	COMPOSITION TILE	SATISFACTORY	24	58	57
427A	71	808	MATERIAL STORAGE	0	01	1997	COMPOSITION TILE	SATISFACTORY	24	58	57
428	810	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	1997	COMPOSITION TILE	SATISFACTORY	24	58	57
428A	71	808	MATERIAL STORAGE	0	01	1997	COMPOSITION TILE	SATISFACTORY	24	58	57
429	810	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	1997	COMPOSITION TILE	SATISFACTORY	24	58	57
429A	71	808	MATERIAL STORAGE	0	01	1997	COMPOSITION TILE	SATISFACTORY	24	58	57
430	83	331	CUSTODIAL SERVICE CLOSET	0	01	1997	CONCRETE	SATISFACTORY	24	58	57
431	67	700	INSIDE CIRCULATION	0	01	1997	CERAMIC TILE	SATISFACTORY	24	58	57
431A	138	816	STUDENT RESTROOM (FEMALE)	0	01	1997	CERAMIC TILE	SATISFACTORY	24	58	57
432	67	700	INSIDE CIRCULATION	0	01	1997	CERAMIC TILE	SATISFACTORY	24	58	57
432A	126	815	STUDENT RESTROOM (MALE)	0	01	1997	CERAMIC TILE	SATISFACTORY	24	58	57
433	119	703	ELECTRICAL ROOM	0	01	1997	CONCRETE	SATISFACTORY	24	58	57
434	817	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	1997	COMPOSITION TILE	SATISFACTORY	24	58	57
434A	77	808	MATERIAL STORAGE	0	01	1997	COMPOSITION TILE	SATISFACTORY	24	58	57
435	650	702	MECHANICAL ROOM	0	01	1997	CONCRETE	SATISFACTORY	24	58	57
436	817	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	1997	COMPOSITION TILE	SATISFACTORY	24	58	57
436A	77	808	MATERIAL STORAGE	0	01	1997	COMPOSITION TILE	SATISFACTORY	24	58	57
437	817	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	1997	COMPOSITION TILE	SATISFACTORY	24	58	57
437A	77	808	MATERIAL STORAGE	0	01	1997	COMPOSITION TILE	SATISFACTORY	24	58	57
438	812	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	1997	COMPOSITION TILE	SATISFACTORY	24	58	57
438A	72	808	MATERIAL STORAGE	0	01	1997	COMPOSITION TILE	SATISFACTORY	24	58	57
439	810	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	1997	COMPOSITION TILE	SATISFACTORY	24	58	57
439A	75	808	MATERIAL STORAGE	0	01	1997	COMPOSITION TILE	SATISFACTORY	24	58	57
440	810	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	1997	COMPOSITION TILE	SATISFACTORY	24	58	57

Report Date: 3/6/2015 4:20:34 PM

Page 39 of 59

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



440A	75	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1997	SATISFACTORY	24	58	57
441	810	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	1997	SATISFACTORY	24	58	57
441A	75	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1997	SATISFACTORY	24	58	57
442	810	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	1997	SATISFACTORY	24	58	57
442A	75	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1997	SATISFACTORY	24	58	57
443	700	62	E S E FULL-TIME	10	01	COMPOSITION TILE	1997	SATISFACTORY	24	58	57
443A	70	817	STUDENT RESTROOM & BATH	0	01	COMPOSITION TILE	1997	SATISFACTORY	24	58	57
443B	66	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1997	SATISFACTORY	24	58	57
443C	20	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1997	SATISFACTORY	24	58	57
444	45	820	STAFF RESTROOM (FEMALE)	0	01	CERAMIC TILE	1997	SATISFACTORY	24	58	57
445	45	819	STAFF RESTROOM (MALE)	0	01	CERAMIC TILE	1997	SATISFACTORY	24	58	57
446	50	702	MECHANICAL ROOM	0	01	CONCRETE	1997	SATISFACTORY	24	58	57
447	40	331	CUSTODIAL SERVICE CLOSET	0	01	CERAMIC TILE	1997	SATISFACTORY	24	58	57
400E	1400	701	COVERED WALKWAY	0	02	CONCRETE	1997	SATISFACTORY	24	58	57
400F	820	701	COVERED WALKWAY	0	02	CONCRETE	1997	SATISFACTORY	24	58	57
400G	1400	700	INSIDE CIRCULATION	0	02	CONCRETE	1997	SATISFACTORY	24	58	57
400H	820	701	COVERED WALKWAY	0	02	CONCRETE	1997	SATISFACTORY	24	58	57
450	1530	20	INTERMEDIATE/MIDDLE SCIENCE DEMO (4-8)	22	02	COMPOSITION TILE	1997	SATISFACTORY	24	58	57
451	1030	315	TEACHER PLANNING OFFICE	0	02	COMPOSITION TILE	1997	SATISFACTORY	24	58	57
451A	75	808	MATERIAL STORAGE	0	02	COMPOSITION TILE	1997	SATISFACTORY	24	58	57
452	1530	20	INTERMEDIATE/MIDDLE SCIENCE DEMO (4-8)	22	02	COMPOSITION TILE	1997	SATISFACTORY	24	58	57
453	810	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	02	COMPOSITION TILE	1997	SATISFACTORY	24	58	57
453A	75	808	MATERIAL STORAGE	0	02	COMPOSITION TILE	1997	SATISFACTORY	24	58	57
454	67	700	INSIDE CIRCULATION	0	02	CERAMIC TILE	1997	SATISFACTORY	24	58	57

Report Date: 3/6/2015 4:20:34 PM

Page 40 of 59

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



454A	96	816	STUDENT RESTROOM (FEMALE)	0	02	CERAMIC TILE	1997	SATISFACTORY	24	58	57
455	67	700	INSIDE CIRCULATION	0	02	CERAMIC TILE	1997	SATISFACTORY	24	58	57
455A	126	815	STUDENT RESTROOM (MALE)	0	02	CERAMIC TILE	1997	SATISFACTORY	24	58	57
456	84	703	ELECTRICAL ROOM	0	02	CONCRETE	1997	SATISFACTORY	24	58	57
457	811	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	02	COMPOSITION TILE	1997	SATISFACTORY	24	58	57
457A	55	808	MATERIAL STORAGE	0	02	COMPOSITION TILE	1997	SATISFACTORY	24	58	57
458	54	331	CUSTODIAL SERVICE CLOSET	0	02	CONCRETE	1997	SATISFACTORY	24	58	57
459	811	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	02	COMPOSITION TILE	1997	SATISFACTORY	24	58	57
459A	55	808	MATERIAL STORAGE	0	02	COMPOSITION TILE	1997	SATISFACTORY	24	58	57
460	40	331	CUSTODIAL SERVICE CLOSET	0	02	CONCRETE	1997	SATISFACTORY	24	58	57
461	346	702	MECHANICAL ROOM	0	02	CONCRETE	1997	SATISFACTORY	24	58	57
462	812	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	02	COMPOSITION TILE	1997	SATISFACTORY	24	58	57
462A	77	808	MATERIAL STORAGE	0	02	COMPOSITION TILE	1997	SATISFACTORY	24	58	57
463	810	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	02	COMPOSITION TILE	1997	SATISFACTORY	24	58	57
463A	75	808	MATERIAL STORAGE	0	02	COMPOSITION TILE	1997	SATISFACTORY	24	58	57
464	810	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	02	COMPOSITION TILE	1997	SATISFACTORY	24	58	57
464A	75	808	MATERIAL STORAGE	0	02	COMPOSITION TILE	1997	SATISFACTORY	24	58	57
465	1530	20	INTERMEDIATE/MIDDLE SCIENCE DEMO (4-8)	22	02	COMPOSITION TILE	1997	SATISFACTORY	24	58	57
466	339	702	MECHANICAL ROOM	0	02	CONCRETE	1997	SATISFACTORY	24	58	57
466A	38	331	CUSTODIAL SERVICE CLOSET	0	02	CONCRETE	1997	SATISFACTORY	24	58	57
467	1530	20	INTERMEDIATE/MIDDLE SCIENCE DEMO (4-8)	22	02	COMPOSITION TILE	1997	SATISFACTORY	24	58	57
468	45	820	STAFF RESTROOM (FEMALE)	0	02	CERAMIC TILE	1997	SATISFACTORY	24	58	57
469	45	819	STAFF RESTROOM (MALE)	0	02	CERAMIC TILE	1997	SATISFACTORY	24	58	57

Report Date: 3/6/2015 4:20:34 PM

Page 41 of 59

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



	470	50	334	CUSTODIAL EQUIPMENT STORAGE	0	02	CONCRETE	1997	SATISFACTORY	24	58	57
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	37,911	516	0	0	0	0	0	0	0	0	0	0
TOTAL	37,911	516	0	0	0	0	0	0	0	0	0	0

Report Date: 3/6/2015 4:20:34 PM

Page 42 of 59

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 57-A PARKWAY MIDDLE

BUILDING: 25

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: MIDDLE	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 2010	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational T.V. FIXED SERVICE RECEIVER	Heat Capacity: ADEQUATE
Average Age NSF: 2010	Intercom: TWO WAY COMPLETE	Walls: COMBINATION OF 1-5
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: COMBINATION OF 1-3
Stories: 3		Corridor: DOUBLE INSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
025	2997	700	INSIDE CIRCULATION	0	01	COMPOSITION TILE	2010	SATISFACTORY	25	58	57
025A	74	827	ELEVATOR (PASSENGER/HANDICAPPED)	0	01	COMPOSITION TILE	2010	SATISFACTORY	25	58	57
2500	5000	701	COVERED WALKWAY	0	01	CONCRETE	2010	SATISFACTORY	25	58	57
2500A	1635	701	COVERED WALKWAY	0	01	CONCRETE	2010	SATISFACTORY	25	58	57
2500B	1635	701	COVERED WALKWAY	0	01	CONCRETE	2010	SATISFACTORY	25	58	57
2500C	2391	701	COVERED WALKWAY	0	01	CONCRETE	2010	SATISFACTORY	25	58	57
2501	816	2	INTERMEDIATE MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	2010	SATISFACTORY	25	58	57
2502	816	2	INTERMEDIATE MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	2010	SATISFACTORY	25	58	57
2503	814	2	INTERMEDIATE MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	2010	SATISFACTORY	25	58	57
2504	771	2	INTERMEDIATE MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	2010	SATISFACTORY	25	58	57
2505	780	2	INTERMEDIATE MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	2010	SATISFACTORY	25	58	57
2506	780	2	INTERMEDIATE MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	2010	SATISFACTORY	25	58	57

Report Date: 3/6/2015 4:20:34 PM

Page 43 of 59

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH) FACILITY INVENTORY REPORT



2507	170	301	ASSISTANT PRINCIPAL/OFFICE	0	01	2010	COMPOSITION TILE	SATISFACTORY	25	58	57
2508	30	707	TELEPHONE EQUIPMENT/COMMUNICATION CLOSET	0	01	2010	CONCRETE	SATISFACTORY	25	58	57
2509	278	816	STUDENT RESTROOM (FEMALE)	0	01	2010	CERAMIC TILE	SATISFACTORY	25	58	57
2509A	47	700	INSIDE CIRCULATION	0	01	2010	COMPOSITION TILE	SATISFACTORY	25	58	57
2510	278	815	STUDENT RESTROOM (MALE)	0	01	2010	CERAMIC TILE	SATISFACTORY	25	58	57
2511	37	331	CUSTODIAL SERVICE CLOSET	0	01	2010	CERAMIC TILE	SATISFACTORY	25	58	57
2512	448	702	MECHANICAL ROOM	0	01	2010	CONCRETE	SATISFACTORY	25	58	57
2513	43	819	STAFF RESTROOM (MALE)	0	01	2010	CERAMIC TILE	SATISFACTORY	25	58	57
2514	43	820	STAFF RESTROOM (FEMALE)	0	01	2010	CERAMIC TILE	SATISFACTORY	25	58	57
2515	46	703	ELECTRICAL ROOM	0	01	2010	CONCRETE	SATISFACTORY	25	58	57
2516	186	368	TEXTBOOK STORAGE	0	01	2010	COMPOSITION TILE	SATISFACTORY	25	58	57
2517	404	40	RESOURCE ROOM	0	01	2010	COMPOSITION TILE	SATISFACTORY	25	58	57
2518	412	40	RESOURCE ROOM	0	01	2010	COMPOSITION TILE	SATISFACTORY	25	58	57
2519	775	62	E S E FULL-TIME	10	01	2010	COMPOSITION TILE	SATISFACTORY	25	58	57
2519A	44	814	STUDENT RESTROOM (BOTH SEXES)	0	01	2010	CERAMIC TILE	SATISFACTORY	25	58	57
2520	830	210	BUSINESS EXPLORATION LAB	15	01	2010	COMPOSITION TILE	SATISFACTORY	25	58	57
2521	830	210	BUSINESS EXPLORATION LAB	15	01	2010	COMPOSITION TILE	SATISFACTORY	25	58	57
2522	825	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	2010	COMPOSITION TILE	SATISFACTORY	25	58	57
2523	815	62	E S E FULL-TIME	10	01	2010	COMPOSITION TILE	SATISFACTORY	25	58	57
025B	2997	700	INSIDE CIRCULATION	0	02	2010	COMPOSITION TILE	SATISFACTORY	25	58	57
2531	816	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	02	2010	COMPOSITION TILE	SATISFACTORY	25	58	57
2532	409	40	RESOURCE ROOM	0	02	2010	COMPOSITION TILE	SATISFACTORY	25	58	57
2533	409	40	RESOURCE ROOM	0	02	2010	COMPOSITION TILE	SATISFACTORY	25	58	57

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



2534	814	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	02	COMPOSITION TILE	2010	SATISFACTORY	25	58	57
2535	771	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	02	COMPOSITION TILE	2010	SATISFACTORY	25	58	57
2536	824	61	E S E PART-TIME	15	02	COMPOSITION TILE	2010	SATISFACTORY	25	58	57
2537	780	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	02	COMPOSITION TILE	2010	SATISFACTORY	25	58	57
2538	174	301	ASSISTANT PRINCIPAL/OTHER OFFICE	0	02	COMPOSITION TILE	2010	SATISFACTORY	25	58	57
2539	30	707	TELEPHONE EQUIPMENT/COMMUNICATION CLOSET	0	02	CONCRETE	2010	SATISFACTORY	25	58	57
2540	278	816	STUDENT RESTROOM (FEMALE)	0	02	CERAMIC TILE	2010	SATISFACTORY	25	58	57
2540A	47	700	INSIDE CIRCULATION	0	02	COMPOSITION TILE	2010	SATISFACTORY	25	58	57
2541	278	815	STUDENT RESTROOM (MALE)	0	02	CERAMIC TILE	2010	SATISFACTORY	25	58	57
2541A	47	700	INSIDE CIRCULATION	0	02	COMPOSITION TILE	2010	SATISFACTORY	25	58	57
2542	37	331	CUSTODIAL SERVICE CLOSET	0	02	CERAMIC TILE	2010	SATISFACTORY	25	58	57
2543	448	702	MECHANICAL ROOM	0	02	CONCRETE	2010	SATISFACTORY	25	58	57
2544	43	819	STAFF RESTROOM (MALE)	0	02	CERAMIC TILE	2010	SATISFACTORY	25	58	57
2545	43	820	STAFF RESTROOM (FEMALE)	0	02	CERAMIC TILE	2010	SATISFACTORY	25	58	57
2546	46	703	ELECTRICAL ROOM	0	02	CONCRETE	2010	SATISFACTORY	25	58	57
2547	186	368	TEXTBOOK STORAGE	0	02	COMPOSITION TILE	2010	SATISFACTORY	25	58	57
2549	780	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	02	COMPOSITION TILE	2010	SATISFACTORY	25	58	57
2550	926	20	INTERMEDIATE/MIDDLE SCIENCE DEMO (4-8)	22	02	COMPOSITION TILE	2010	SATISFACTORY	25	58	57
2550A	358	315	TEACHER PLANNING OFFICE	0	02	COMPOSITION TILE	2010	SATISFACTORY	25	58	57
2551	926	20	INTERMEDIATE/MIDDLE SCIENCE DEMO (4-8)	22	02	COMPOSITION TILE	2010	SATISFACTORY	25	58	57
2552	825	62	E S E FULL-TIME	10	02	COMPOSITION TILE	2010	SATISFACTORY	25	58	57
2553	772	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	02	COMPOSITION TILE	2010	SATISFACTORY	25	58	57
025C	2997	700	INSIDE CIRCULATION	0	03	COMPOSITION TILE	2010	SATISFACTORY	25	58	57

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



2561	816	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	03	COMPOSITION TILE	2010	SATISFACTORY	25	58	57
2562	409	40	RESOURCE ROOM	0	03	COMPOSITION TILE	2010	SATISFACTORY	25	58	57
2563	409	40	RESOURCE ROOM	0	03	COMPOSITION TILE	2010	SATISFACTORY	25	58	57
2564	814	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	03	COMPOSITION TILE	2010	SATISFACTORY	25	58	57
2565	771	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	03	COMPOSITION TILE	2010	SATISFACTORY	25	58	57
2566	779	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	03	COMPOSITION TILE	2010	SATISFACTORY	25	58	57
2567	780	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	03	COMPOSITION TILE	2010	SATISFACTORY	25	58	57
2568	174	301	ASSISTANT PRINCIPAL/OTHER OFFICE	0	03	COMPOSITION TILE	2010	SATISFACTORY	25	58	57
2569	30	707	TELEPHONE EQUIPMENT/COMMUNICATION CLOSET	0	03	CONCRETE	2010	SATISFACTORY	25	58	57
2570	278	816	STUDENT RESTROOM (FEMALE)	0	03	CERAMIC TILE	2010	SATISFACTORY	25	58	57
2570A	47	700	INSIDE CIRCULATION	0	03	COMPOSITION TILE	2010	SATISFACTORY	25	58	57
2571	278	815	STUDENT RESTROOM (MALE)	0	03	CERAMIC TILE	2010	SATISFACTORY	25	58	57
2571A	47	700	INSIDE CIRCULATION	0	03	COMPOSITION TILE	2010	SATISFACTORY	25	58	57
2572	37	331	CUSTODIAL SERVICE CLOSET	0	03	CERAMIC TILE	2010	SATISFACTORY	25	58	57
2573	448	702	MECHANICAL ROOM	0	03	CONCRETE	2010	SATISFACTORY	25	58	57
2574	43	819	STAFF RESTROOM (MALE)	0	03	CERAMIC TILE	2010	SATISFACTORY	25	58	57
2575	43	820	STAFF RESTROOM (FEMALE)	0	03	CERAMIC TILE	2010	SATISFACTORY	25	58	57
2576	46	703	ELECTRICAL ROOM	0	03	CONCRETE	2010	SATISFACTORY	25	58	57
2577	186	368	TEXTBOOK STORAGE	0	03	COMPOSITION TILE	2010	SATISFACTORY	25	58	57
2578	780	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	03	COMPOSITION TILE	2010	SATISFACTORY	25	58	57
2579	925	20	INTERMEDIATE/MIDDLE SCIENCE DEMO (4-8)	22	03	COMPOSITION TILE	2010	SATISFACTORY	25	58	57
2579A	400	315	TEACHER PLANNING OFFICE	0	03	COMPOSITION TILE	2010	SATISFACTORY	25	58	57
2580	925	20	INTERMEDIATE/MIDDLE SCIENCE DEMO (4-8)	22	03	COMPOSITION TILE	2010	SATISFACTORY	25	58	57

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



	2581	825	61	E S E P ART-TIME	15	03	COMPOSITION TILE	2010	SATISFACTORY	25	58	57																																			
													2582	772	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	03	COMPOSITION TILE	2010	SATISFACTORY	25	58	57																							
	<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th rowspan="2"></th> <th colspan="2">Satisfactory</th> <th colspan="2">Unsatisfactory</th> <th colspan="2">Failed Standards</th> <th colspan="2">Scheduled For Replacement</th> </tr> <tr> <th>Square Feet</th> <th>Student Stations</th> <th>Square Feet</th> <th>Student Stations</th> <th>Square Feet</th> <th>Student Stations</th> <th>Square Feet</th> <th>Student Stations</th> </tr> </thead> <tbody> <tr> <td>Permanent</td> <td>53,173</td> <td>618</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> </tr> <tr> <td>TOTAL</td> <td>53,173</td> <td>618</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> </tr> </tbody> </table>													Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement		Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Permanent	53,173	618	0	0	0	0	0	0	TOTAL	53,173	618	0	0	0	0	0	0
	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement																																								
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations																																							
Permanent	53,173	618	0	0	0	0	0	0																																							
TOTAL	53,173	618	0	0	0	0	0	0																																							

Report Date: 3/6/2015 4:20:34 PM

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 57-A PARKWAY MIDDLE

BUILDING: 26

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: MIDDLE	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 2010	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational T.V. FIXED SERVICE RECEIVER	Heat Capacity: ADEQUATE
Average Age NSF: 2010	Intercom: TWO WAY COMPLETE	Walls: COMBINATION OF 1-5
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: COMBINATION OF 1-3
Stories: 2		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
026	124	700	INSIDE CIRCULATION	0	01	COMPOSITION TILE	2010	SATISFACTORY	26	58	57
026A	118	700	INSIDE CIRCULATION	0	01	COMPOSITION TILE	2010	SATISFACTORY	26	58	57
2600	3945	701	COVERED WALKWAY	0	01	CONCRETE	2010	SATISFACTORY	26	58	57
2600A	1750	701	COVERED WALKWAY	0	01	CONCRETE	2010	SATISFACTORY	26	58	57
2601	730	370	LOBBY	0	01	CARPET	2010	SATISFACTORY	26	58	57
2601A	44	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	2010	SATISFACTORY	26	58	57
2602	85	372	TICKET BOOTH	0	01	COMPOSITION TILE	2010	SATISFACTORY	26	58	57
2603	210	371	CONCESSIONS	0	01	COMPOSITION TILE	2010	SATISFACTORY	26	58	57
2604	225	815	STUDENT RESTROOM (MALE)	0	01	CERAMIC TILE	2010	SATISFACTORY	26	58	57
2604A	88	700	INSIDE CIRCULATION	0	01	CERAMIC TILE	2010	SATISFACTORY	26	58	57
2605	350	816	STUDENT RESTROOM (FEMALE)	0	01	CERAMIC TILE	2010	SATISFACTORY	26	58	57
2605A	64	700	INSIDE CIRCULATION	0	01	CERAMIC TILE	2010	SATISFACTORY	26	58	57

Report Date: 3/6/2015 4:20:34 PM

Page 48 of 59

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)
FACILITY INVENTORY REPORT



2606	10463	111	JR HIGH GYMNASIUM	160	01	WOOD	2010	SATISFACTORY	26	58	57
2606A	63	331	CUSTODIAL SERVICE CLOSET	0	01	CERAMIC TILE	2010	SATISFACTORY	26	58	57
2607	1914	110	P E MULTIPURPOSE ROOM (MIDDLE-SR HIGH)	0	01	COMPOSITION TILE	2010	SATISFACTORY	26	58	57
2608	1077	98	P E STORAGE (MIDDLE-SR HIGH)	0	01	COMPOSITION TILE	2010	SATISFACTORY	26	58	57
2608A	90	707	TELEPHONE EQUIPMENT/COMMUNICATION CLOSET	0	01	COMPOSITION TILE	2010	SATISFACTORY	26	58	57
2608B	103	703	ELECTRICAL ROOM	0	01	CONCRETE	2010	SATISFACTORY	26	58	57
2609	697	90	P E DRESSING ROOM (MALE)	0	01	QUARRY TILE	2010	SATISFACTORY	26	58	57
2609A	60	700	INSIDE CIRCULATION	0	01	QUARRY TILE	2010	SATISFACTORY	26	58	57
2609B	412	94	P E SHOWER (MALE)	0	01	QUARRY TILE	2010	SATISFACTORY	26	58	57
2609C	75	700	INSIDE CIRCULATION	0	01	QUARRY TILE	2010	SATISFACTORY	26	58	57
2610	101	315	TEACHER PLANNING OFFICE	0	01	COMPOSITION TILE	2010	SATISFACTORY	26	58	57
2610A	60	99	P E TEACHERS SHOWER (MALE)	0	01	QUARRY TILE	2010	SATISFACTORY	26	58	57
2611	200	114	P E LAUNDRY	0	01	QUARRY TILE	2010	SATISFACTORY	26	58	57
2612	655	91	P E DRESSING ROOM (FEMALE)	0	01	QUARRY TILE	2010	SATISFACTORY	26	58	57
2612A	60	700	INSIDE CIRCULATION	0	01	QUARRY TILE	2010	SATISFACTORY	26	58	57
2612B	412	95	P E SHOWER (FEMALE)	0	01	QUARRY TILE	2010	SATISFACTORY	26	58	57
2612C	50	700	INSIDE CIRCULATION	0	01	QUARRY TILE	2010	SATISFACTORY	26	58	57
2613	101	315	TEACHER PLANNING OFFICE	0	01	COMPOSITION TILE	2010	SATISFACTORY	26	58	57
2613A	60	100	P E TEACHERS SHOWER (FEMALE)	0	01	QUARRY TILE	2010	SATISFACTORY	26	58	57
2614	265	115	P E FIRST AID	0	01	QUARRY TILE	2010	SATISFACTORY	26	58	57
2615	171	702	MECHANICAL ROOM	0	01	CONCRETE	2010	SATISFACTORY	26	58	57

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)
FACILITY INVENTORY REPORT



	2620	568	702	MECHANICAL ROOM	0	02	COMPOSITION TILE		2010	SATISFACTORY		26	58	57
							Square Feet	Student Stations		Square Feet	Student Stations			
							Failed Standards			Scheduled For Replacement				
							Square Feet	Student Stations		Square Feet	Student Stations			
Permanent				180	0	0								
TOTAL				180	0	0								

Report Date: 3/6/2015 4:20:34 PM

Page 50 of 59

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 57-A PARKWAY MIDDLE

BUILDING: 27 - Building Number 00027

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: NONE
Use: MIDDLE	Mech Vent: ADEQUATE	Heat Source: NONE
Year Constructed: 1991	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: NO HEAT PROVIDED
Year Modified:	Educational T.V: NONE	Heat Capacity: NONE
Average Age NSF: 1991	Intercom: NONE	Walls: WOOD
Relocatable Units: 0	Telephone: NONE	Struct Comp: WOOD
Stories: 1		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
2701	121	701	COVERED WALKWAY	0	01	CONCRETE	1991	SATISFACTORY	27	58	57

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	121	0	0	0	0	0	0	0
TOTAL	121	0	0	0	0	0	0	0

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 57-A PARKWAY MIDDLE

BUILDING: 28 - Building Number 00028

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: NONE
Use: MIDDLE	Mech Vent: ADEQUATE	Heat Source: NONE
Year Constructed: 1991	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: NO HEAT PROVIDED
Year Modified:	Educational T.V: NONE	Heat Capacity: NONE
Average Age NSF: 2009	Intercom: NONE	Walls: WOOD
Relocatable Units: 0	Telephone: NONE	Struct Comp: WOOD
Stories: 1		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
2801	121	701	COVERED WALKWAY	0	01	CONCRETE	2009	SATISFACTORY	28	58	57

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	121	0	0	0	0	0	0	0
TOTAL	121	0	0	0	0	0	0	0

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 57-A PARKWAY MIDDLE

BUILDING: 29

Owner: SCHOOL BOARD	Light: NONE	Cooling: NONE
Use: MIDDLE	Mech Vent: NONE	Heat Source: NONE
Year Constructed: 2009	Artificial Lighting: NONE	Heat Distribution: NO HEAT PROVIDED
Year Modified:	Educational T.V: NONE	Heat Capacity: NONE
Average Age NSF: 2010	Intercom: NONE	Walls: CONCRETE
Relocatable Units: 0	Telephone: NONE	Struct Comp: CONCRETE
Stories: 1		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
2902	369	703	ELECTRICAL ROOM	0	01	CONCRETE	2010	SATISFACTORY	29	58	57
2903	250	703	ELECTRICAL ROOM	0	01	CONCRETE	2010	SATISFACTORY	29	58	57
2904	250	703	ELECTRICAL ROOM	0	01	CONCRETE	2010	SATISFACTORY	29	58	57
2905	250	703	ELECTRICAL ROOM	0	01	CONCRETE	2010	SATISFACTORY	29	58	57

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	1,119	0	0	0	0	0	0	0
TOTAL	1,119	0	0	0	0	0	0	0

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 57-A PARKWAY MIDDLE

BUILDING: 30

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: NONE
Use: MIDDLE	Mech Vent: NONE	Heat Source: NONE
Year Constructed: 2009	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: NO HEAT PROVIDED
Year Modified:	Educational T.V: NONE	Heat Capacity: NONE
Average Age NSF: 2009	Intercom: NONE	Walls: FACTORY BUILT
Relocatable Units: 0	Telephone: NONE	Struct Comp: PERMANENT METAL
Stories: 1		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
3001	768	811	OUTSIDE STORAGE	0	01	CONCRETE	2009	SATISFACTORY	30	58	57

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Modular	768	0	0	0	0	0	0	0
TOTAL	768	0	0	0	0	0	0	0

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT



**STUDENT STATIONS BY DESIGN CODE FOR:
FACILITY: PARKWAY MIDDLE**

Design Code	Design Code Description	Satis Stu Sta			Unsat Stu Sta			Sat Tot	Unsat Tot	Satis Rooms			Unsat Rooms			Fall Std Repl Rooms	Repl Rooms
		Perm	Mod	Relo	Perm	Mod	Relo			Perm	Mod	Relo	Perm	Mod	Relo		
00002	INTERMEDIATE MIDDLE CLASSROOM (4-8)	1430	0	0	0	0	0	1430	0	65	0	0	0	0	0	0	0
00011	INTERMEDIATE MIDDLE SKILLS LAB (4-8)	88	0	0	0	0	88	0	4	0	0	0	0	0	0	0	0
00020	INTERMEDIATE MIDDLE SCIENCE DEMO (4-8)	264	0	0	0	0	264	0	12	0	0	0	0	0	0	0	0
00040	RESOURCE ROOM	0	0	0	0	0	0	0	7	0	0	0	0	0	0	0	0
00051	ART - MIDDLE	118	0	0	0	0	118	0	4	0	0	0	0	0	0	0	0
00061	ES E PART-TIME	75	0	0	0	0	75	0	5	0	0	0	0	0	0	0	0
00062	ES E FULL-TIME	50	0	0	0	0	50	0	5	0	0	0	0	0	0	0	0
00065	ES E RESOURCE	0	0	0	0	0	0	0	4	0	0	0	0	0	0	0	0
00075	VOCAL MUSIC CLASS (MIDDLE-SR HIGH)	31	0	0	0	0	31	0	2	0	0	0	0	0	0	0	0
00076	BAND CLASS (MIDDLE-SR HIGH)	50	0	0	0	0	50	0	1	0	0	0	0	0	0	0	0
00077	ORCHESTRA CLASS (MIDDLE-SR HIGH)	25	0	0	0	0	25	0	1	0	0	0	0	0	0	0	0
00078	GENERAL MUSIC CLASS (MIDDLE-SR HIGH)	60	0	0	0	0	60	0	2	0	0	0	0	0	0	0	0
00083	MUSIC RELATED SPACE	0	0	0	0	0	0	0	8	0	0	0	0	0	0	0	0
00090	PE DRESSING ROOM (MALE)	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0
00091	PE DRESSING ROOM (FEMALE)	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0
00094	PE SHOWER (MALE)	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0
00095	PE SHOWER (FEMALE)	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0
00098	PE STORAGE (MIDDLE-SR HIGH)	0	0	0	0	0	0	0	3	0	0	0	0	0	0	0	0
00099	PE TEACHERS SHOWER (MALE)	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0
00100	PE TEACHERS SHOWER (FEMALE)	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0
00110	PE MULTIPURPOSE ROOM (MIDDLE-SR HIGH)	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0
00111	JR HIGH GYMNASIUM	160	0	0	0	0	160	0	1	0	0	0	0	0	0	0	0
00114	PE LAUNDRY	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0
00115	PE FIRST AID	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0

Report Date: 3/6/2015 4:20:34 PM

Page 55 of 59

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH) FACILITY INVENTORY REPORT



Design Code	Design Code Description	Satis Stu Sta			Unsat Stu Sta			Sat Tot	Unsat Tot	Satis Rooms			Unsat Rooms			Fall Std Stu Sta	Repl Stu Sta	Fall Std Rooms	Repl Rooms
		Perm	Mod	Relo	Perm	Mod	Relo			Perm	Mod	Relo	Perm	Mod	Relo				
00119	P E GYMNASTICS & DANCE	0	0	0	0	0	0	0	0	3	0	0	0	0	0	0	0	0	
00210	BUSINESS EXPLORATION LAB	30	0	0	0	0	30	0	0	2	0	0	0	0	0	0	0	0	
00230	HOME ECONOMICS EXPLORATION LAB	33	0	0	0	0	33	0	0	2	0	0	0	0	0	0	0	0	
00240	TECHNOLOGY/INDUSTRY EXPLORATION LAB	22	0	0	0	0	22	0	0	1	0	0	0	0	0	0	0	0	
00272	VOCATIONAL LAB SUPPORT SPACE	0	0	0	0	0	0	0	0	3	0	0	0	0	0	0	0	0	
00300	PRINCIPAL/DIRECTOR OFFICE	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	
00301	ASSISTANT PRINCIPAL/OTHER OFFICE	0	0	0	0	0	0	0	0	16	0	0	0	0	0	0	0	0	
00302	BOOKKEEPING OFFICE	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	
00303	SECRETARIAL SPACE	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	
00304	RECEPTION AREA	0	0	0	0	0	0	0	0	5	0	0	0	0	0	0	0	0	
00305	PRODUCTION WORKROOM	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	
00306	CONFERENCE ROOM	0	0	0	0	0	0	0	0	5	0	0	0	0	0	0	0	0	
00307	CLINIC	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	
00308	GENERAL SCHOOL STORAGE	0	0	0	0	0	0	0	0	3	0	0	0	0	0	0	0	0	
00309	VAULT/STUDENT RECORDS	0	0	0	0	0	0	0	0	3	0	0	0	0	0	0	0	0	
00312	COMPUTER AREA	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	
00313	CAREERS ROOM	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	
00314	ITINERANT OFFICE	0	0	0	0	0	0	0	0	3	0	0	0	0	0	0	0	0	
00315	TEACHER PLANNING OFFICE	0	0	0	0	0	0	0	0	17	0	0	0	0	0	0	0	0	
00316	TEACHER LOUNGE/DINING	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	
00330	CUSTODIAL RECEIVING	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	
00331	CUSTODIAL SERVICE CLOSET	0	0	0	0	0	0	0	0	24	0	0	0	0	0	0	0	0	
00332	CUSTODIAL WORK AREA	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	
00333	FLAMMABLE STORAGE	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	
00334	CUSTODIAL EQUIPMENT STORAGE	0	0	0	0	0	0	0	0	3	0	0	0	0	0	0	0	0	
00340	DINING AREA	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	

Report Date: 3/6/2015 4:20:34 PM

Page 56 of 59

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH) FACILITY INVENTORY REPORT



Design Code	Design Code Description	Satisfy Stu Sta			Unsat Stu Sta			Sat Tot	Unsat Tot	Satisfy Rooms			Unsat Rooms			Fall Std Stu Sta	Repl Stu Sta	Fall Std Rooms	Repl Rooms
		Perm	Mod	Relo	Perm	Mod	Relo			Perm	Mod	Relo	Perm	Mod	Relo				
00342	KITCHEN DRY STORAGE	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	
00343	KITCHEN OFFICE	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	
00344	KITCHEN GARBAGE WASH	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	
00346	KITCHEN FOOD PREPARATION	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	
00347	KITCHEN DISH WASHING	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	
00350	OTHER FOOD SERVICE	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	
00360	AUDITORIUM	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	
00363	STAGE	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	
00364	STAGE STORAGE	0	0	0	0	0	0	0	0	5	0	0	0	0	0	0	0	0	
00365	STAGE DRESSING ROOM (MALE)	0	0	0	0	0	0	0	0	3	0	0	0	0	0	0	0	0	
00366	STAGE DRESSING ROOM (FEMALE)	0	0	0	0	0	0	0	0	3	0	0	0	0	0	0	0	0	
00367	CONTROL BOOTH/PROJECTION ROOM	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	
00368	TEXTBOOK STORAGE	0	0	0	0	0	0	0	0	3	0	0	0	0	0	0	0	0	
00370	LOBBY	0	0	0	0	0	0	0	0	3	0	0	0	0	0	0	0	0	
00371	CONCESSIONS	0	0	0	0	0	0	0	0	3	0	0	0	0	0	0	0	0	
00372	TICKET BOOTH	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	
00380	LIBRARY (READING ROOM/STACKS)	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	
00387	MEDIA PRODUCTION LAB	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	
00700	INSIDE CIRCULATION	0	0	0	0	0	0	0	0	50	0	0	0	0	0	0	0	0	
00701	COVERED WALKWAY	0	0	0	0	0	0	0	0	42	0	0	0	0	0	0	0	0	
00702	MECHANICAL ROOM	0	0	0	0	0	0	0	0	28	0	0	0	0	0	0	0	0	
00703	ELECTRICAL ROOM	0	0	0	0	0	0	0	0	18	0	0	0	0	0	0	0	0	
00707	TELEPHONE EQUIPMENT/COMMUNICATION CLOSET	0	0	0	0	0	0	0	0	7	0	0	0	0	0	0	0	0	
00803	INSTRUCTIONAL DARKROOM	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	
00805	KILN	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	
00806	REFERENCE	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	

Report Date: 3/6/2015 4:20:34 PM

Page 57 of 59

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)
FACILITY INVENTORY REPORT




Design Code	Design Code Description	Satis Stu Sta			Unsat Stu Sta			Sat Tot	Unsat Tot	Satis Rooms			Unsat Rooms			Fail Std Stu Sta	Repl Stu Sta	Fail Std Rooms	Repl Rooms
		Perm	Mod	Relo	Perm	Mod	Relo			Perm	Mod	Relo	Perm	Mod	Relo				
00808	MATERIAL STORAGE	0	0	0	0	0	0	0	0	43	0	0	0	0	0	0	0	0	
00810	MATERIAL STORAGE (LARGE)	0	0	0	0	0	0	0	0	7	0	0	0	0	0	0	0	0	
00811	OUTSIDE STORAGE	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	
00812	PROJECT STORAGE	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	
00814	STUDENT RESTROOM (BOTH SEXES)	0	0	0	0	0	0	0	0	4	0	0	0	0	0	0	0	0	
00815	STUDENT RESTROOM (MALE)	0	0	0	0	0	0	0	0	15	0	0	0	0	0	0	0	0	
00816	STUDENT RESTROOM (FEMALE)	0	0	0	0	0	0	0	0	15	0	0	0	0	0	0	0	0	
00817	STUDENT RESTROOM & BATH	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	
00819	STAFF RESTROOM (MALE)	0	0	0	0	0	0	0	0	10	0	0	0	0	0	0	0	0	
00820	STAFF RESTROOM (FEMALE)	0	0	0	0	0	0	0	0	11	0	0	0	0	0	0	0	0	
00821	STAFF RESTROOM (BOTH SEXES)	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	
00822	PUBLIC USE RESTROOM (MALE)	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	
00823	PUBLIC USE RESTROOM (FEMALE)	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	
00827	ELEVATOR (PASSENGER/HANDICAPPED)	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	
00831	MUSIC PRACTICE ROOM	0	0	0	0	0	0	0	0	6	0	0	0	0	0	0	0	0	
00849	VOCATIONAL PROJECT STORAGE	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	
Totals:		2436	0	0	0	0	0	2436	0	549	1	0	0	0	0	0	0	0	


FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)
FACILITY INVENTORY REPORT





2.3.3 FISH Site Plan



2.3.4 FISH Building Plan







2.4.0 Facility Assessments and Budgetary Documentation

This section includes facility condition assessments and budgetary documentation that has been completed over recent years regarding the General Obligation Bond funding and approved budgetary construction scope of work.

2.3.1 Adopted District Educational Facilities Plan

The ADEFP is the most recent approved budget for each campus of Broward County Schools. Construction scope is itemized including changes to the initial deficiency listings for each campus. It is the responsibility of the Design/Build Contractor to reconcile any differences between the ADEFP and additional budgetary or facility condition assessments.

2.3.2 SMART Campus Summary

The SMART Campus Summary is the most recent facility condition assessment completed for each campus. The summary provides existing building applicable dates and square footage, in addition to deficiency listings broken down into Safety & Security, Music & Arts, Athletics, Renovations, and Technology (SMART) categories to organize the approved funding in terms of programs that are affected.

The Campus Summary does not represent the final approved funding, and is for information purposes only.

2.3.3 MAPPS Deficiency Listing

The MAPPS Deficiency Listing is a detailed facility condition assessment conducted by Jacobs over recent years. The deficiency listing is presented as an itemized list of deficiencies on a site and building specific level organized by discipline. Note that all deficiency items are not in the scope of work. Items initialed "GOB" are included in the initial General Obligation Bond, prior to final approval of ADEFP.

The MAPPS Deficiency Listing does not represent the final approved funding, and is for information purposes only.

2.3.4 MAPPS Detailed List

The MAPPS Detailed List is raw database information in tabular format. The purpose of the Detailed List is to provide additional notes and quantity to cost estimate information. It is important to note that the Detailed List does not include all items from the approved budget. Additional items may occur and should be confirmed with the ADEFP.

2.3.5 MAPPS Deficiency Detail

The MAPPS Deficiency Detail report is raw database information with a breakdown of the cost estimate including construction adjustments and soft cost adjustments. As is with the Detail List, budget confirmation with the ADEFP is required.

2.4.1 Adopted District Educational Facilities Plan (DEFP)

Parkway Middle School

Adopted District Educational Facilities Plan							
Project	Carryover (2014-15)	Year 1 (2015-16)	Year 2 (2016-17)	Year 3 (2017-18)	Year 4 (2018-19)	Total	Scope
Building Envelope	-1,620,000					-1,620,000	Roof Replacement
ADEFP Sub-Total	0	0	0	0	0	0	

SMART Program							
Project	Carryover (2014-15)	Year 1 (2015-16)	Year 2 (2016-17)	Year 3 (2017-18)	Year 4 (2018-19)	Total	Scope
Safety & Security	45,000					45,000	Fire Sprinklers
Renovation			149,000			149,000	Wireless Network Upgrade
Renovation	100,000					100,000	School Choice Enhancement
Renovation	337,000					337,000	Media Center improvements
Renovation	1,036,000					1,036,000	HVAC Improvements
Renovation			30,000			30,000	CAT 6 Data port Upgrade
Renovation	2,503,000					2,503,000	Building Envelope Improvements (Roof, Window, Ext Wall, etc.)
Technology			9,000			9,000	Technology Infrastructure (Servers, Racks, etc.) Upgrade
SMART Sub-Total	4,021,000	0	188,000	0	0	4,209,000	

	Carryover (2014-15)	Year 1 (2015-16)	Year 2 (2016-17)	Year 3 (2017-18)	Year 4 (2018-19)	Total	
School Total	4,021,000	0	188,000	0	0	4,209,000	

2.4.2 SMART Campus Summary



2014 Facility Condition Assessment
Campus Summary

0701 Parkway Middle School			
3600 NW 5th Court Lauderhill FL 33311			
Year Open		1958	
Other Years	1971, 1975, 1990, 1991, 1997, 2009,	2010	
Perm. Bldgs/SF	28	223,546	
Port. Bldgs/SF	0	0	
Current FCI Need		13,294,008	
Replacement Value	÷	56,217,432	
Facility Condition Index	=	23.6 %	



Facility Condition Index



GOB Bond / Construction Projects

Safety & Security	Budget	Fund Yr.	Status
Parkway Middle School Fire Sprinklers	\$45,000	2015	2014 GOB
	\$45,000		
Music & Arts	Budget	Fund Yr.	Status
None Identified			
Athletics	Budget	Fund Yr.	Status
None Identified			
Renovations	Budget	Fund Yr.	Status
Parkway Middle School Envelope	\$89,000	2015	2014 GOB
Parkway Middle School Roofing	\$1,486,000	2015	2014 GOB
Parkway Middle School HVAC	\$263,000	2015	2014 GOB
Parkway MS School Choice Enhancement	\$100,000	2015	2014 GOB
Parkway Middle School Other Envelope Improvements	\$924,000	2015	2014 GOB
Parkway Middle School Other HVAC Improvements	\$773,000	2015	2014 GOB
Parkway Middle School Media Center Renovations	\$337,000	2015	2014 GOB
Roof Replacement	\$29,000	2014	Construction
	\$4,001,000		
Technology	Budget	Fund Yr.	Status
Parkway MS Technology Infrastructure (Servers, Racks, etc.)	\$9,000	2017	2014 GOB
Parkway MS CAT 6 Dataport	\$30,000	2017	2014 GOB
Parkway MS Wireless Network	\$149,000	2017	2014 GOB
	\$188,000		
Total In-Progress and Planned	\$4,234,000		
Total Unplanned Need	\$11,960,855		



2014 Facility Condition Assessment
Campus Summary

Unplanned Need	
Safety & Security	Budget
None Identified	
	\$0
Music & Arts	Budget
Parkway Middle School Music / Art Renovations	\$551,617
	\$551,617
Athletics	Budget
None Identified	
	\$0
Renovations	Budget
Cafeteria Expansion	\$366,289
Media Center Expansion	\$463,746
Various maintenance projects throughout campus	
Parkway Middle School STEM Lab Renovations	\$876,792
Parkway Middle School Cafeteria Renovations	\$470,480
Misc Maintenance Improvements at Parkway MS	\$2,220,419
Misc Site Improvements at Parkway MS	\$2,199,492
Misc Interior Improvements at Parkway MS	\$3,612,688
Misc Plumbing Improvements at Parkway MS	\$351,265
Misc Specialties Improvements at Parkway MS	\$635,450
	\$11,196,621
Technology	Budget
Fiber Optic Network (10GB) Upgrade at Parkway MS	\$212,618
	\$212,618
Total Unplanned Need \$11,960,855	

2.4.3 MAPPS Deficiency Listing

Broward County Public Schools

School Deficiency Listing

0701	Parkway Middle School
-------------	------------------------------

9/2/2014 9:39 AM

Site Level Deficiencies

Site

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Asphalt Paving Is Damaged And Requires Replacement	Capital Renewal	800	CAR	4	\$2,155,640	211739
Playground Equipment Requires Replacement	Capital Renewal	1	Ea.	4	\$1,668	211144
Sub Total for System		2	items		\$2,157,307	

Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Aluminum Covered Walkways Require Replacement	Capital Renewal	4,380	SF	2	\$26,960	314533 GOB
Aluminum Covered Walkways Require Replacement	Capital Renewal	2,297	SF	2	\$14,139	314534 GOB
Aluminum Covered Walkways Require Replacement	Capital Renewal	5,515	SF	2	\$33,946	314535 GOB
Aluminum Covered Walkways Require Replacement	Capital Renewal	2,277	SF	2	\$14,016	314536 GOB
Aluminum Covered Walkways Require Replacement	Capital Renewal	2,881	SF	2	\$17,733	314537 GOB
Aluminum Covered Walkways Require Replacement	Capital Renewal	1,550	SF	2	\$9,541	314538 GOB
Aluminum Covered Walkways Require Replacement	Capital Renewal	7,599	SF	2	\$46,774	314539 GOB
Aluminum Covered Walkways Require Replacement	Capital Renewal	1,363	SF	2	\$8,390	314540 GOB
Aluminum Covered Walkways Require Replacement	Capital Renewal	2,430	SF	2	\$14,957	314541 GOB
Aluminum Covered Walkways Require Replacement	Capital Renewal	1,363	SF	2	\$8,390	314542 GOB
Aluminum Covered Walkways Require Replacement	Capital Renewal	1,350	SF	2	\$8,310	314543 GOB
Aluminum Covered Walkways Require Replacement	Capital Renewal	1,363	SF	2	\$8,390	314544 GOB
Aluminum Covered Walkways Require Replacement	Capital Renewal	1,350	SF	2	\$8,310	314545 GOB
Aluminum Covered Walkways Require Replacement	Capital Renewal	1,363	SF	2	\$8,390	314546 GOB
Aluminum Covered Walkways Require Replacement	Capital Renewal	600	SF	3	\$3,847	211318
Sub Total for System		15	items		\$232,090	

Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Computer room lacks independent AC.	Educational Adequacy	1	Ea.	2	\$41,041	250149
Sub Total for System		1	items		\$41,041	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
School site lacks appropriate lighting.	Educational Adequacy	4	Ea.	3	\$19,876	255335
Sub Total for System		1	items		\$19,876	

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
School lacks appropriate number of surveillance cameras.	Functional Deficiency	16	Ea.	2	\$78,561	255249
CAT-6 wiring to WAP needs to be provided	Functional Deficiency	107	Ea.	3	\$84,397	225158 GOB
School requires technology infrastructure (servers, racks, etc).	Functional Deficiency	1	LS	3	\$8,640	313377 GOB
School requires Wireless Access Point hardware	Functional Deficiency	1	LS	3	\$64,628	313586 GOB
Sub Total for System		4	items		\$236,226	

Other

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
School requires additional media center space	New Construction	1,855	SF	1	\$463,746	314779
School Selected Educational Adequacy Enhancement	Educational Adequacy	1	LS	2	\$100,000	314121 GOB
School needs more dining room capacity	New Construction	1,221	SF	4	\$366,289	314700
Sub Total for System		3	items		\$930,035	
Sub Total for School and Site Level		26	items		\$3,616,575	

Broward County Public Schools

School Deficiency Listing

9/2/2014 9:39 AM

0701	Parkway Middle School
-------------	------------------------------

Building: 01 - Building 1

Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Reroofing with new Decking Required (Broward CPS)	Capital Renewal	8,124	SF	2	\$98,848	224079 GOB
The Roof Requires Cleaning	Deferred Maintenance	150	SF	4	\$1,864	224078
Sub Total for System		2	Items		\$100,712	

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Aluminum Window Is Damaged And Requires Replacement	Capital Renewal	56	SF	2	\$8,356	211796 GOB
The Exterior Requires Painting	Capital Renewal	10,000	SF Wall	3	\$33,748	211806 GOB
The Metal Exterior Door Requires Repair	Deferred Maintenance	13	Door	3	\$6,451	211793 GOB
Exterior Metal Door Requires Repainting	Deferred Maintenance	13	Door	4	\$2,008	211795
Sub Total for System		4	Items		\$50,561	

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Interior Doors Require Repair	Deferred Maintenance	31	Door	3	\$27,919	211803
The Acoustical Ceilings Tiles Require Replacement	Capital Renewal	2,000	SF	3	\$11,149	211797
The Carpet Flooring Requires Replacement	Capital Renewal	3,400	SF	3	\$35,405	211802
Interior Ceramic Walls Require Repair Or Replacement	Capital Renewal	1,000	SF Wall	4	\$18,841	211801
Interior Gypboard Walls Require Repair	Deferred Maintenance	9,000	SF Wall	4	\$48,166	211798
The Interior Door Hardware Requires Replacement	Capital Renewal	26	Door	4	\$57,368	211804
Interior Gypboard Walls Require Repainting	Deferred Maintenance	9,000	SF Wall	5	\$29,990	211799
Sub Total for System		7	Items		\$228,838	

Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Air Handler HVAC Component Requires Replacement	Capital Renewal	2	Ea.	3	\$111,008	210999 GOB
The Air Handler HVAC Component Requires Replacement	Capital Renewal	1	Ea.	3	\$55,504	211002 GOB
Sub Total for System		2	Items		\$166,512	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The 1 X 4 Interior Fluorescent Light Fixture Requires Replacement	Capital Renewal	10	Ea.	3	\$3,566	210783
The 2 X 2 Interior Fluorescent Lighting Requires Replacement	Capital Renewal	28	Ea.	3	\$10,087	210785
The 2 X 4 Interior Fluorescent Lighting Requires Replacement	Capital Renewal	110	Ea.	3	\$62,412	210787
Sub Total for System		3	Items		\$76,065	
Sub Total for Building 01 - Building 1		18	Items		\$622,689	

Building: 02 - Building 2

Site

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Site Drainage is Inadequate and Installation of Drainage Piping	Deferred Maintenance	100	LF	3	\$2,888	211758
Sub Total for System		1	Items		\$2,888	

Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Reroofing with new Decking Required (Broward CPS)	Capital Renewal	8,902	SF	2	\$108,314	224080 GOB
Sub Total for System		1	Items		\$108,314	

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Aluminum Window Is Damaged And Requires Replacement	Capital Renewal	31	SF	2	\$4,625	211748 GOB

Rev 1 Sept 2014

Parkway Middle School 0701

M•A•P•P•S ©, Jacobs 2014

Page 2 of 26

Broward County Public Schools

School Deficiency Listing

9/2/2014 9:39 AM

0701	Parkway Middle School
-------------	------------------------------

Building: 02 - Building 2

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID	
Exterior Door Hardware Requires Replacement	Deferred Maintenance	13	Ea.	3	\$37,044	211747	GOB
The Exterior Requires Painting	Capital Renewal	10,000	SF Wall	3	\$33,748	211743	GOB
Exterior Metal Door Requires Repainting	Deferred Maintenance	8	Door	4	\$1,235	211745	
Sub Total for System		4	items		\$76,662		

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID	
The Wood Exterior Door Is Damaged And Requires Replacement	Capital Renewal	5	Door	2	\$20,838	211744	GOB
Classroom doors lack appropriate signs.	Educational Adequacy	1	Ea.	3	\$171	Rollup	
The Acoustical Ceilings Tiles Require Replacement	Capital Renewal	3,000	SF	3	\$16,724	211749	
The Carpet Flooring Requires Replacement	Capital Renewal	8,900	SF	3	\$92,879	211754	
The Vinyl Composition Tile Requires Replacement	Capital Renewal	100	SF	3	\$887	211755	
The Wood Flooring Requires Replacement	Capital Renewal	1,200	SF	3	\$24,684	211756	
Interior Gypboard Walls Require Repair	Deferred Maintenance	3,000	SF Wall	4	\$18,055	211751	
Room lacks appropriate sound control	Educational Adequacy	1,637	SF	4	\$51,344	Rollup	
The Overhead Door Is Damaged And Requires Repair	Deferred Maintenance	1	Door	4	\$944	211746	
The Terrazzo Flooring Is Damaged And Requires Replacement	Capital Renewal	1,100	SF	4	\$47,968	211778	
Interior Doors Require Repainting	Deferred Maintenance	18	Door	5	\$1,119	211757	
Interior Gypboard Walls Require Repainting	Deferred Maintenance	3,000	SF Wall	5	\$9,997	211752	
Interior Gypboard Walls Require Repainting	Deferred Maintenance	9,200	SF Wall	5	\$30,858	211753	
The Plaster Ceilings Are Damaged And Requires Repainting	Deferred Maintenance	3,200	SF	5	\$6,801	211750	
Vinyl/Fabric Wall Covering Requires Replacement	Capital Renewal	2,000	SF	5	\$9,024	213435	
Sub Total for System		16	items		\$329,888		

Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID	
Complete Kitchen HVAC Installation For Non-Air-Conditioned Facility?	Functional Deficiency	2,500	SF	2	\$66,570	211005	GOB
Duct Heater Requires Replacement	Capital Renewal	1	Ea.	3	\$5,163	211007	GOB
The Air Handler HVAC Component Requires Replacement	Capital Renewal	1	Ea.	3	\$55,504	211008	GOB
Sub Total for System		3	items		\$127,238		

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID	
The 1 X 4 Interior Fluorescent Light Fixture Requires Replacement	Capital Renewal	60	Ea.	3	\$21,398	210794	
The 2 X 4 Interior Fluorescent Lighting Requires Replacement	Capital Renewal	54	Ea.	3	\$30,638	210796	
The Incandescent Lighting Is Damaged And Should Be Replaced	Capital Renewal	30	Ea.	3	\$11,753	210798	
Room does not have tamper-proof light switching.	Educational Adequacy	1	Ea.	5	\$486	Rollup	
Sub Total for System		4	items		\$64,275		

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID	
Site Drainage Requires Regrading	Deferred Maintenance	800	SF	3	\$568	211759	
The Custodial Mop Or Service Sink Requires Replacement	Deferred Maintenance	1	Ea.	4	\$1,684	211008	
Sub Total for System		2	items		\$2,252		

Broward County Public Schools

School Deficiency Listing

9/2/2014 9:39 AM

0701	Parkway Middle School
-------------	------------------------------

Building: 02 - Building 2

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Computer Closet Requires Fiber Optic Access to CER	Functional Deficiency	525	LF	2	\$11,812	Rollup
Sub Total for System		1	Items		\$11,812	

Other

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Renovate / Remodel Cafeteria	Deferred Maintenance	1	LS	2	\$470,480	316872
Sub Total for System		1	Items		\$470,480	
Sub Total for Building 02 - Building 2		32	Items		\$1,193,796	

Building: 03 - Media Center

Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Reroofing with new Decking Required (Broward CPS)	Capital Renewal	6,435	SF	2	\$78,297	224081 GOB
Sub Total for System		1	Items		\$78,297	

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Interior CMU Walls Require Repair	Deferred Maintenance	500	SF	3	\$13,104	211733
The Exterior Requires Painting	Capital Renewal	8,000	SF Wall	3	\$26,998	211738 GOB
The Exterior Requires Painting (Bldg SF)	Capital Renewal	8,000	SF	3	\$40,099	211726 GOB
Exterior Metal Door Requires Repainting	Deferred Maintenance	5	Door	4	\$772	211728
The Exterior Requires Cleaning	Deferred Maintenance	8,000	SF Wall	5	\$15,995	211725
Sub Total for System		5	Items		\$96,967	

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Acoustical Ceilings Tiles Require Replacement	Capital Renewal	2,000	SF	3	\$11,149	211729
The Carpet Flooring Requires Replacement	Capital Renewal	3,800	SF	3	\$39,571	211734
The Ceramic Tile Flooring Requires Replacement	Capital Renewal	300	SF	3	\$5,281	211736
The Concrete Flooring Is Damaged And Requires Replacement	Capital Renewal	150	SF	3	\$1,148	211737
The Vinyl Composition Tile Requires Replacement	Capital Renewal	2,000	SF	3	\$17,736	211735
The Wood Exterior Door Requires Repainting	Deferred Maintenance	2	Door	3	\$723	211727 GOB
Room has insufficient tackboard area.	Educational Adequacy	1	Ea.	4	\$385	Rollup
Room lacks appropriate amount of teacher storage.	Educational Adequacy	7	Ea.	4	\$4,234	Rollup
Room lacks appropriate sound control.	Educational Adequacy	1,449	SF	4	\$45,448	Rollup
Interior Ceramic Walls Require Repainting	Deferred Maintenance	1,000	SF Wall	5	\$2,630	211732
Interior Gypboard Walls Require Repainting	Deferred Maintenance	6,500	SF Wall	5	\$21,859	211731
The Plaster Ceilings Are Damaged And Requires Repainting	Deferred Maintenance	750	SF	5	\$1,594	211730
Sub Total for System		12	Items		\$151,554	

Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Air Handler HVAC Component Requires Replacement	Capital Renewal	1	Ea.	3	\$55,504	211015 GOB
Sub Total for System		1	Items		\$55,504	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The 1 X 4 Interior Fluorescent Light Fixture Requires Replacement	Capital Renewal	150	Ea.	3	\$53,496	210811

Rev 1 Sept 2014

Parkway Middle School 0701

M•A•P•P•S ©, Jacobs 2014

Page 4 of 26

Broward County Public Schools

School Deficiency Listing

9/2/2014 9:39 AM

0701	Parkway Middle School
-------------	------------------------------

Building: 03 - Media Center

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The 2 X 4 Interior Fluorescent Lighting Requires Replacement	Capital Renewal	20	Ea.	3	\$11,348	210813
The Incandescent Lighting Is Damaged And Should Be Replaced	Capital Renewal	12	Ea.	3	\$4,701	210816
Room does not have tamper-proof light switching.	Educational Adequacy	1	Ea.	5	\$488	Rollup
Sub Total for System		4	items		\$70,030	

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	2	Ea.	2	\$2,713	Rollup
Sub Total for System		1	items		\$2,713	

Fire and Security

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Install Fire Sprinklers	Code Compliance	274	SF	1	\$2,363	Rollup GOB
Sub Total for System		1	items		\$2,363	

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks Fixed Projector	Educational Adequacy	1	Ea.	2	\$3,684	Rollup
Room lacks Interactive White Board	Educational Adequacy	1	Ea.	2	\$2,722	Rollup
The Computer Closet Requires Fiber Optic Access to CER	Functional Deficiency	525	LF	2	\$11,812	Rollup
Room lacks access to video distribution	Educational Adequacy	1	Ea.	5	\$665	Rollup
Sub Total for System		4	items		\$18,883	

Other

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Media Center requires renovation based on condition of room(s)	Capital Renewal	1	LS	2	\$268,968	316297 GOB
Provide renovation of restrooms associated with educational adequacy renovations	Capital Renewal	1	LS	2	\$68,500	316351 GOB
Sub Total for System		2	items		\$337,468	
Sub Total for Building 03 - Media Center		31	items		\$813,779	

Building: 04 - Building 4

Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Reroofing with new Decking Required (Broward CFS)	Capital Renewal	8,320	SF	2	\$101,354	224082 GOB
Sub Total for System		1	items		\$101,354	

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Exterior Requires Painting	Capital Renewal	10,000	SF Wall	3	\$33,748	211720 GOB
The Exterior Requires Painting (Bldg SF)	Capital Renewal	10,000	SF	3	\$50,123	211702 GOB
Exterior Metal Door Requires Repainting	Deferred Maintenance	14	Door	4	\$2,161	211704
The Exterior Requires Cleaning	Deferred Maintenance	10,000	SF Wall	5	\$19,993	211700
Sub Total for System		4	items		\$106,025	

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Classroom Door Requires Vision Panel	Educational Adequacy	1	Ea.	3	\$373	Rollup
Classroom doors lack appropriate signs.	Educational Adequacy	4	Ea.	3	\$684	Rollup
Interior Toilet Partition Requires Repair	Deferred Maintenance	32	Ea.	3	\$13,891	211711

Broward County Public Schools

School Deficiency Listing

9/2/2014 9:39 AM

0701	Parkway Middle School
-------------	------------------------------

Building: 04 - Building 4

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient writing area.	Educational Adequacy	1	Ea.	3	\$1,039	Rollup
The Acoustical Ceilings Tiles Require Replacement	Capital Renewal	2,000	SF	3	\$11,149	211707
The Suspended Ceiling Grid and Tiles Require Replacement	Capital Renewal	200	SF	3	\$1,787	211708
Room has insufficient tackboard area.	Educational Adequacy	5	Ea.	4	\$1,927	Rollup
Room lacks appropriate amount of teacher storage.	Educational Adequacy	5	Ea.	4	\$3,024	Rollup
The Interior Door Hardware Requires Replacement	Capital Renewal	12	Door	4	\$26,478	211713
Interior Gypboard Walls Require Repainting	Deferred Maintenance	8,800	SF Wall	5	\$29,324	211710
Interior Walls Require Repainting	Deferred Maintenance	9,400	SF Wall	5	\$27,090	211717
Sub Total for System		11	items		\$116,765	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient electrical outlets.	Educational Adequacy	50	Ea.	3	\$18,290	Rollup
The 1 X 4 Interior Fluorescent Light Fixture Requires Replacement	Capital Renewal	20	Ea.	3	\$7,133	210829
The 2 X 4 Interior Fluorescent Lighting Requires Replacement	Capital Renewal	115	Ea.	3	\$65,248	210830
The Incandescent Lighting Is Damaged And Should Be Replaced	Capital Renewal	12	Ea.	3	\$4,701	210832
Room lacks controls to partially dim lights.	Educational Adequacy	1	Ea.	5	\$779	Rollup
Sub Total for System		5	items		\$96,151	

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	2	Ea.	2	\$2,713	Rollup
Prep room lacks a sink.	Educational Adequacy	1	Ea.	3	\$4,450	Rollup
The Custodial Mop Or Service Sink Requires Replacement	Deferred Maintenance	1	Ea.	4	\$1,684	211031
Sub Total for System		3	items		\$8,847	

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient dataports.	Educational Adequacy	32	Ea.	2	\$5,536	Rollup GOB
Room lacks Fixed Projector	Educational Adequacy	2	Ea.	2	\$7,368	Rollup
Room lacks Interactive White Board	Educational Adequacy	4	Ea.	2	\$10,887	Rollup
The Computer Closet Requires Fiber Optic Access to CER	Functional Deficiency	525	LF	2	\$11,812	Rollup
Sub Total for System		4	items		\$35,603	

Specialties

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks the required demonstration table.	Educational Adequacy	1	Ea.	3	\$7,463	Rollup
Blinds are missing or in poor condition.	Educational Adequacy	25	SF Surf	4	\$707	Rollup
Sub Total for System		2	items		\$8,170	

Other

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Renovate / Remodel Music and Art Rooms	Deferred Maintenance	1	LS	2	\$138,408	316779

Broward County Public Schools

School Deficiency Listing

9/2/2014 9:39 AM

0701	Parkway Middle School
-------------	------------------------------

Building: 04 - Building 4

Other

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
STEM lab requires renovation based on condition of room(s)	Capital Renewal	1	LS	2	\$26,489	318957
Sub Total for System		2	Items		\$164,898	
Sub Total for Building 04 - Building 4		32	Items		\$637,814	

Building: 05 - Building 5

Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Reroofing with new Decking Required (Broward CPS)	Capital Renewal	5,081	SF	2	\$61,822	224083 GOB
Sub Total for System		1	Items		\$61,822	

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Aluminum Window Is Damaged And Requires Replacement	Capital Renewal	10	SF	2	\$1,492	211678 GOB
The Exterior Requires Painting (Bldg SF)	Capital Renewal	7,000	SF	3	\$35,088	211673 GOB
The Exterior Requires Cleaning	Deferred Maintenance	7,000	SF Wall	5	\$13,995	211689
Sub Total for System		3	Items		\$60,574	

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Classroom doors lack appropriate signs.	Educational Adequacy	3	Ea.	3	\$513	Rollup
Room has insufficient writing area.	Educational Adequacy	4	Ea.	3	\$4,154	Rollup
The Carpet Flooring Requires Replacement	Capital Renewal	3,000	SF	3	\$31,240	211693
The Suspended Ceiling Grid and Tiles Require Replacement	Capital Renewal	300	SF	3	\$2,680	211685
Interior Ceramic Walls Require Repair Or Replacement	Capital Renewal	400	SF Wall	4	\$7,536	211689
Interior CMU Walls Require Repainting	Capital Renewal	6,600	SF	4	\$9,391	211691
Room has insufficient tackboard area.	Educational Adequacy	2	Ea.	4	\$771	Rollup
Room lacks appropriate amount of teacher storage.	Educational Adequacy	13	Ea.	4	\$7,863	Rollup
Room lacks appropriate sound control.	Educational Adequacy	1,580	SF	4	\$49,555	Rollup
The Interior Door Hardware Requires Replacement	Capital Renewal	8	Door	4	\$17,852	211695
The Wood Flooring Requires Repair	Deferred Maintenance	1,400	SF	4	\$16,936	211694
Sub Total for System		11	Items		\$148,291	

Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Roof Air Handler/Exhaust is Damaged And Requires Replacement	Capital Renewal	2	TonAC	2	\$5,747	211037 GOB
The Air Handler HVAC Component Requires Replacement	Capital Renewal	2	Ea.	3	\$111,008	211039 GOB
Sub Total for System		2	Items		\$116,755	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient electrical outlets.	Educational Adequacy	4	Ea.	3	\$1,464	Rollup
The 1 X 4 Interior Fluorescent Light Fixture Requires Replacement	Capital Renewal	10	Ea.	3	\$3,566	210837
The 2 X 4 Interior Fluorescent Lighting Requires Replacement	Capital Renewal	120	Ea.	3	\$68,085	210839
Sub Total for System		3	Items		\$73,115	

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Prep room lacks a sink.	Educational Adequacy	2	Ea.	3	\$8,899	Rollup

Broward County Public Schools

School Deficiency Listing

9/2/2014 9:39 AM

0701	Parkway Middle School
-------------	------------------------------

Building: 05 - Building 5

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks a drinking fountain.	Educational Adequacy	1	Ea.	5	\$959	Rollup
Sub Total for System		2	items		\$9,859	

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks Fixed Projector	Educational Adequacy	2	Ea.	2	\$7,368	Rollup
Room lacks Interactive White Board	Educational Adequacy	1	Ea.	2	\$2,722	Rollup
The Computer Closet Requires Fiber Optic Access to CER	Functional Deficiency	525	LF	2	\$11,812	Rollup
Sub Total for System		3	items		\$21,902	

Other

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Renovate / Remodel Music and Art Rooms	Deferred Maintenance	1	LS	2	\$274,800	316781
Sub Total for System		1	items		\$274,800	
Sub Total for Building 05 - Building 5		26	items		\$757,119	

Building: 06 - Building 6

Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Reroofing with new Decking Required (Broward CPS)	Capital Renewal	5,582	SF	2	\$67,918	224084 GOB
Sub Total for System		1	items		\$67,918	

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Exterior Door Hardware Requires Replacement	Deferred Maintenance	5	Ea.	3	\$14,248	211645 GOB
The Exterior Requires Painting (Bldg SF)	Capital Renewal	7,000	SF	3	\$35,086	211641 GOB
Exterior Metal Door Requires Repainting	Deferred Maintenance	5	Door	4	\$772	211643
The Exterior Requires Cleaning	Deferred Maintenance	7,000	SF Wall	5	\$13,995	211640
Sub Total for System		4	items		\$64,101	

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Classroom doors lack appropriate signs.	Educational Adequacy	2	Ea.	3	\$342	Rollup
The Acoustical Ceilings Tiles Require Replacement	Capital Renewal	2,000	SF	3	\$11,149	211646
Room has insufficient tackboard area	Educational Adequacy	2	Ea.	4	\$771	Rollup
Room lacks appropriate amount of teacher storage.	Educational Adequacy	9	Ea.	4	\$5,443	Rollup
The Interior Door Hardware Requires Replacement	Capital Renewal	7	Door	4	\$15,445	211647
The Overhead Door Is Damaged And Requires Repair	Deferred Maintenance	2	Door	4	\$1,888	211644
Intenor Walls Require Repainting	Deferred Maintenance	6,800	SF Wall	5	\$19,021	211683
Sub Total for System		7	items		\$64,059	

Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Roof Air Handler/Exhaust is Damaged And Requires Replacement	Capital Renewal	1	TonAC	2	\$2,873	211050 GOB
The Air Handler HVAC Component Requires Replacement	Capital Renewal	1	Ea.	3	\$55,504	211046 GOB
Sub Total for System		2	items		\$68,378	

Broward County Public Schools

School Deficiency Listing

9/2/2014 9:39 AM

0701	Parkway Middle School
-------------	------------------------------

Building: 06 - Building 6

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The 1 X 4 Interior Fluorescent Light Fixture Requires Replacement	Capital Renewal	5	Ea.	3	\$1,783	210853
The 2 X 4 Interior Fluorescent Lighting Requires Replacement	Capital Renewal	88	Ea.	3	\$49,929	210854
Sub Total for System		2	items		\$51,712	

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	3	Ea.	2	\$4,070	Rollup
Prep room lacks a sink.	Educational Adequacy	2	Ea.	3	\$8,899	Rollup
The Custodial Mop Or Service Sink Requires Replacement	Deferred Maintenance	1	Ea.	4	\$1,684	211044
Sub Total for System		3	items		\$14,653	

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient dataports.	Educational Adequacy	19	Ea.	2	\$3,287	Rollup GOB
Room lacks Fixed Projector	Educational Adequacy	1	Ea.	2	\$3,884	Rollup
The Computer Closet Requires Fiber Optic Access to CER	Functional Deficiency	525	LF	2	\$11,812	Rollup
Sub Total for System		3	items		\$18,783	

Specialties

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks the required demonstration table.	Educational Adequacy	1	Ea.	3	\$7,463	Rollup
Sub Total for System		1	items		\$7,463	

Other

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Renovate / Remodel Music and Art Rooms	Deferred Maintenance	1	LS	2	\$138,408	316780
Sub Total for System		1	items		\$138,408	
Sub Total for Building 06 - Building 6		24	items		\$475,477	

Building: 07 - Classroom

Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Reroofing with new Decking Required (Broward CPS)	Capital Renewal	3,348	SF	2	\$40,738	224088 GOB
The Roof Requires Cleaning	Deferred Maintenance	50	SF	4	\$621	224085
Sub Total for System		2	items		\$41,358	

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Exterior Door Hardware Requires Replacement	Deferred Maintenance	2	Ea.	3	\$5,899	211615 GOB
The Aluminum Window Requires Repair	Deferred Maintenance	36	Ea.	3	\$6,225	211616 GOB
The Exterior Requires Painting	Capital Renewal	4,000	SF Wall	3	\$13,499	211611 GOB
Exterior Metal Door Requires Repainting	Deferred Maintenance	5	Door	4	\$772	211614
The Exterior Requires Cleaning	Deferred Maintenance	4,000	SF Wall	5	\$7,997	211610
Sub Total for System		5	items		\$34,192	

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
------------	----------	-----	-----	----------	-------------	----

Broward County Public Schools

School Deficiency Listing

9/2/2014 9:39 AM

0701	Parkway Middle School
-------------	------------------------------

Building: 07 - Classroom

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient writing area.	Educational Adequacy	2	Ea.	3	\$2,077	Rollup
The Acoustical Ceilings Tiles Require Replacement	Capital Renewal	2,000	SF	3	\$11,149	211617
Interior Gypboard Walls Require Repair	Deferred Maintenance	2,000	SF Wall	4	\$10,704	211618
Room lacks appropriate amount of teacher storage.	Educational Adequacy	7	Ea.	4	\$4,234	Rollup
The Interior Door Hardware Requires Replacement	Capital Renewal	4	Door	4	\$8,826	211622
Interior Gypboard Walls Require Repainting	Deferred Maintenance	2,000	SF Wall	5	\$6,864	211619
Sub Total for System		6	items		\$43,654	

Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Fan Coil (Chilled Water) HVAC Component Requires Replacement	Capital Renewal	6	Ea.	3	\$11,869	211061 GOB
Sub Total for System		1	items		\$11,869	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The 2 X 4 Interior Fluorescent Lighting Requires Replacement	Capital Renewal	81	Ea.	3	\$45,958	210855
Sub Total for System		1	items		\$45,958	

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient dataports.	Educational Adequacy	44	Ea.	2	\$7,612	Rollup GOB
Room lacks Interactive White Board	Educational Adequacy	3	Ea.	2	\$8,165	Rollup
The Computer Closet Requires Fiber Optic Access to CER	Functional Deficiency	525	LF	2	\$11,812	Rollup
Sub Total for System		3	items		\$27,589	

Other

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
STEM lab requires renovation based on condition of room(s)	Capital Renewal	1	LS	2	\$52,979	316956
Sub Total for System		1	items		\$52,979	
Sub Total for Building 07 - Classroom		19	items		\$257,598	

Building: 08 - Building 8

Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Reroofing with new Decking Required (Broward CPS)	Capital Renewal	3,263	SF	2	\$39,702	224088 GOB
The Roof Requires Cleaning	Deferred Maintenance	100	SF	4	\$1,243	224087
Sub Total for System		2	items		\$40,945	

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Exterior Door Hardware Requires Replacement	Deferred Maintenance	6	Ea.	3	\$17,097	211584 GOB
The Aluminum Window Requires Repair	Deferred Maintenance	32	Ea.	3	\$5,533	211589 GOB
The Exterior Requires Painting	Capital Renewal	4,000	SF Wall	3	\$13,499	211583 GOB
The Exterior Requires Cleaning	Deferred Maintenance	4,000	SF Wall	5	\$7,997	211582
Sub Total for System		4	items		\$44,127	

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Acoustical Ceilings Tiles Require Replacement	Capital Renewal	1,600	SF	3	\$8,920	211585

Rev 1 Sept 2014

Parkway Middle School 0701

M•A•P•P•S ©, Jacobs 2014

Page 10 of 26

Broward County Public Schools

School Deficiency Listing

9/2/2014 9:39 AM

0701	Parkway Middle School
-------------	------------------------------

Building: 08 - Building 8

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Suspended Ceiling Grid and Tiles Require Replacement	Capital Renewal	3,300	SF	3	\$29,482	211586
Interior Gypboard Walls Require Repair	Deferred Maintenance	2,000	SF Wall	4	\$10,704	211587
Room lacks appropriate amount of teacher storage.	Educational Adequacy	32	Ea.	4	\$19,354	Rollup
Interior Wood Walls Require Repainting	Deferred Maintenance	4,000	SF Wall	5	\$8,213	211588
Sub Total for System		6	Items		\$76,673	

Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Fan Coil (Chilled Water) HVAC Component Requires Replacement	Capital Renewal	5	Ea	3	\$9,890	211089 GOB
Sub Total for System		1	Items		\$9,890	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient electrical outlets.	Educational Adequacy	20	Ea.	3	\$7,317	Rollup
The 2 X 4 Interior Fluorescent Lighting Requires Replacement	Capital Renewal	90	Ea.	3	\$51,064	210856
Sub Total for System		2	Items		\$68,381	

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Computer Closet Requires Fiber Optic Access to CER	Functional Deficiency	525	LF	2	\$11,812	Rollup
Sub Total for System		1	Items		\$11,812	
Sub Total for Building 08 - Building 8		16	Items		\$241,828	

Building: 09 - Building 9

Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Reroofing with new Decking Required (Broward CPS)	Capital Renewal	3,244	SF	2	\$39,471	224090 GOB
The Roof Requires Cleaning	Deferred Maintenance	50	SF	4	\$821	224089
Sub Total for System		2	Items		\$40,092	

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Aluminum Window Is Damaged And Requires Replacement	Capital Renewal	32	SF	2	\$4,775	211559 GOB
Exterior Door Hardware Requires Replacement	Deferred Maintenance	3	Ea.	3	\$6,549	211558 GOB
The Exterior Requires Painting (Bldg SF)	Capital Renewal	4,000	SF	3	\$20,049	211557 GOB
The Exterior Requires Cleaning	Deferred Maintenance	4,000	SF Wall	5	\$7,997	211556
Sub Total for System		4	Items		\$41,370	

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient writing area.	Educational Adequacy	1	Ea.	3	\$1,039	Rollup
The Acoustical Ceilings Tiles Require Replacement	Capital Renewal	1,500	SF	3	\$8,362	211560
The Suspended Ceiling Grid and Tiles Require Replacement	Capital Renewal	2,950	SF	3	\$26,355	211581
Interior Gypboard Walls Require Repair	Deferred Maintenance	2,000	SF Wall	4	\$10,704	211583
Room lacks appropriate amount of teacher storage.	Educational Adequacy	30	Ea.	4	\$18,145	Rollup
Interior Gypboard Walls Require Repainting	Deferred Maintenance	2,000	SF Wall	5	\$6,664	211582
Sub Total for System		6	Items		\$71,268	

Rev 1 Sept 2014

Parkway Middle School

0701

M•A•P•P•S ©, Jacobs 2014

Page 11 of 26

Broward County Public Schools

School Deficiency Listing

9/2/2014 9:39 AM

0701	Parkway Middle School
-------------	------------------------------

Building: 09 - Building 9

Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Fan Coil (Chilled Water) HVAC Component Requires Replacement	Capital Renewal	4	Ea	3	\$7,912	211077 GOB
Sub Total for System		1	Items		\$7,912	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The 1 X 4 Interior Fluorescent Light Fixture Requires Replacement	Capital Renewal	8	Ea.	3	\$2,853	210859
The 2 X 4 Interior Fluorescent Lighting Requires Replacement	Capital Renewal	80	Ea.	3	\$45,390	210860
Sub Total for System		2	Items		\$48,243	

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Refrigerated Water Cooler Requires Replacement	Capital Renewal	1	Ea.	3	\$2,408	211078
The Custodial Mop Or Service Sink Requires Replacement	Deferred Maintenance	1	Ea.	4	\$1,684	211080
Sub Total for System		2	Items		\$4,092	

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Computer Closet Requires Fiber Optic Access to CER	Functional Deficiency	525	LF	2	\$11,812	Rollup
Sub Total for System		1	Items		\$11,812	
Sub Total for Building 09 - Building 9		18	Items		\$224,791	

Building: 10 - Building 10

Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Reroofing with new Decking Required (Broward CPS)	Capital Renewal	3,565	SF	2	\$43,377	224092 GOB
The Roof Requires Cleaning	Deferred Maintenance	50	SF	4	\$821	224091
Sub Total for System		2	Items		\$43,998	

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Aluminum Window Is Damaged And Requires Replacement	Capital Renewal	32	SF	2	\$4,775	211535 GOB
Exterior Door Hardware Requires Replacement	Deferred Maintenance	3	Ea.	3	\$8,549	211536 GOB
The Exterior Requires Painting	Capital Renewal	4,000	SF Wall	3	\$13,499	211534 GOB
The Exterior Requires Cleaning	Deferred Maintenance	4,000	SF Wall	5	\$7,997	211533
Sub Total for System		4	Items		\$34,820	

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Classroom doors lack appropriate signs.	Educational Adequacy	1	Ea.	3	\$171	Rollup
Room has insufficient writing area.	Educational Adequacy	2	Ea.	3	\$2,077	Rollup
The Acoustical Ceilings Tiles Require Replacement	Capital Renewal	1,500	SF	3	\$8,362	211538
Interior Gypboard Walls Require Repair	Deferred Maintenance	1,500	SF Wall	4	\$8,028	211539
Interior Wood Walls Require Repair	Deferred Maintenance	1,500	SF Wall	4	\$5,352	211540
Room lacks appropriate amount of teacher storage.	Educational Adequacy	23	Ea.	4	\$13,911	Rollup
The Interior Door Hardware Requires Replacement	Capital Renewal	3	Door	4	\$6,619	211537
Sub Total for System		7	Items		\$44,520	

Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Fan Coil (Chilled Water) HVAC Component Requires Replacement	Capital Renewal	4	Ea.	3	\$7,912	211095 GOB

Rev 1 Sept 2014

Parkway Middle School

0701

M•A•P•P•S ©, Jacobs 2014

Page 12 of 26

Broward County Public Schools

School Deficiency Listing

9/2/2014 9:39 AM

0701	Parkway Middle School
-------------	------------------------------

Building: 10 - Building 10

		Sub Total for System	1 items		\$7,912
Electrical					
Deficiency	Category	Qty	UoM	Priority	Repair Cost ID
Room has insufficient electrical outlets.	Educational Adequacy	6	Ea.	3	\$2,195 Rollup
The 1 X 4 Interior Fluorescent Light Fixture Requires Replacement	Capital Renewal	8	Ea.	3	\$2,853 210861
The 2 X 4 Interior Fluorescent Lighting Requires Replacement	Capital Renewal	80	Ea.	3	\$45,390 210862
		Sub Total for System	3 items		\$50,438
Plumbing					
Deficiency	Category	Qty	UoM	Priority	Repair Cost ID
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	3	Ea.	2	\$4,070 Rollup
		Sub Total for System	1 items		\$4,070
Technology					
Deficiency	Category	Qty	UoM	Priority	Repair Cost ID
Room lacks Fixed Projector	Educational Adequacy	2	Ea.	2	\$7,368 Rollup
		Sub Total for System	1 items		\$7,368
Specialties					
Deficiency	Category	Qty	UoM	Priority	Repair Cost ID
Lab lacks an air exchange system.	Educational Adequacy	1	Ea.	2	\$14,313 Rollup
		Sub Total for System	1 items		\$14,313
Other					
Deficiency	Category	Qty	UoM	Priority	Repair Cost ID
STEM lab requires renovation based on condition of room(s)	Capital Renewal	1	LS	2	\$398,662 318954
		Sub Total for System	1 items		\$398,662
		Sub Total for Building 10 - Building 10	21 items		\$606,102

Building: 12 - Building 12

Roofing					
Deficiency	Category	Qty	UoM	Priority	Repair Cost ID
Reroofing with new Decking Required (Broward CPS)	Capital Renewal	6,325	SF	2	\$76,959 224093 GOB
		Sub Total for System	1 items		\$76,959
Exterior					
Deficiency	Category	Qty	UoM	Priority	Repair Cost ID
The Aluminum Window Is Damaged And Requires Replacement	Capital Renewal	4	SF	2	\$585 211494 GOB
Exterior Door Hardware Requires Replacement	Deferred Maintenance	7	Ea.	3	\$19,561 211490 GOB
The Exterior Requires Painting	Capital Renewal	7,500	SF Wall	3	\$24,822 211488 GOB
The Exterior Requires Cleaning	Deferred Maintenance	7,500	SF Wall	5	\$14,705 211487
		Sub Total for System	4 items		\$69,673
Interior					
Deficiency	Category	Qty	UoM	Priority	Repair Cost ID
Classroom Door Requires Vision Panel	Educational Adequacy	5	Ea.	3	\$1,866 Rollup
Classroom doors lack appropriate signs.	Educational Adequacy	8	Ea.	3	\$1,369 Rollup
Room has insufficient writing area.	Educational Adequacy	4	Ea.	3	\$4,154 Rollup
The Acoustical Ceilings Tiles Require Replacement	Capital Renewal	2,000	SF	3	\$10,934 211495
The Carpet Flooring Requires Replacement	Capital Renewal	450	SF	3	\$4,595 211498
Room has insufficient tackboard area	Educational Adequacy	4	Ea.	4	\$1,541 Rollup

Broward County Public Schools

School Deficiency Listing

9/2/2014 9:39 AM

0701	Parkway Middle School
-------------	------------------------------

Building: 12 - Building 12

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks appropriate amount of teacher storage.	Educational Adequacy	4	Ea.	4	\$2,419	Rollup
The Interior Door Hardware Requires Replacement	Capital Renewal	4	Door	4	\$8,855	211498
Interior Walls Require Repainting	Deferred Maintenance	7,500	SF Wall	5	\$21,196	211521
Sub Total for System		9	items		\$66,731	

Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Fan Coil (Chilled Water) HVAC Component Requires Replacement	Capital Renewal	7	Ea.	3	\$13,579	211102 GOB
Sub Total for System		1	items		\$13,579	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient electrical outlets.	Educational Adequacy	20	Ea.	3	\$7,315	Rollup
The 1 X 4 Interior Fluorescent Light Fixture Requires Replacement	Capital Renewal	15	Ea.	3	\$5,246	210888
The 2 X 4 Interior Fluorescent Lighting Requires Replacement	Capital Renewal	127	Ea.	3	\$70,864	210890
Room does not have tamper-proof light switching.	Educational Adequacy	5	Ea.	5	\$2,428	Rollup
Sub Total for System		4	items		\$85,653	

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks a private shower area.	Educational Adequacy	3	Ea.	4	\$27,398	Rollup
Room lacks private toilets.	Educational Adequacy	3	Ea.	4	\$33,850	Rollup
Sub Total for System		2	items		\$61,049	

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks Fixed Projector	Educational Adequacy	5	Ea.	2	\$18,421	Rollup
Room lacks Interactive White Board	Educational Adequacy	2	Ea.	2	\$5,443	Rollup
The Computer Closet Requires Fiber Optic Access to CER	Functional Deficiency	525	LF	2	\$11,812	Rollup
Sub Total for System		3	items		\$35,677	

Specialties

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room does not have sufficient cubbies.	Educational Adequacy	58	Ea.	5	\$2,414	Rollup
Room has an insufficient number of coat hooks.	Educational Adequacy	36	Ea.	5	\$420	Rollup
Sub Total for System		2	items		\$2,834	
Sub Total for Building 12 - Building 12		26	items		\$392,153	

Building: 13 - Building 13

Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Reroofing with new Decking Required (Broward CPS)	Capital Renewal	3,474	SF	2	\$42,269	224094 GOB
Sub Total for System		1	items		\$42,269	

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Aluminum Window is Damaged And Requires Replacement	Capital Renewal	27	SF	2	\$4,029	211461 GOB
Exterior Door Hardware Requires Replacement	Deferred Maintenance	3	Ea.	3	\$8,549	211460 GOB

Broward County Public Schools

School Deficiency Listing

9/2/2014 9:39 AM

0701	Parkway Middle School
-------------	------------------------------

Building: 13 - Building 13

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Exterior Requires Painting	Capital Renewal	4,000	SF Wall	3	\$13,499	211459 GOB
The Exterior Requires Cleaning	Deferred Maintenance	4,000	SF Wall	5	\$7,997	211458
Sub Total for System		4	items		\$34,074	

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Acoustical Ceilings Tiles Require Replacement	Capital Renewal	1,000	SF	3	\$5,575	211462
Room lacks appropriate amount of teacher storage.	Educational Adequacy	16	Ea.	4	\$9,877	Rollup
The Interior Door Hardware Requires Replacement	Capital Renewal	3	Door	4	\$6,619	211464
Interior Walls Require Repairing	Deferred Maintenance	4,000	SF Wall	5	\$11,528	211483
Sub Total for System		4	items		\$33,399	

Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The F an Coil (Chilled Water) HVAC Component Requires Replacement	Capital Renewal	6	Ea.	3	\$11,869	211117 GOB
Sub Total for System		1	items		\$11,869	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The 2 X 4 Interior Fluorescent Lighting Requires Replacement	Capital Renewal	68	Ea.	3	\$49,929	210908
Sub Total for System		1	items		\$49,929	

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	4	Ea.	2	\$5,426	Rollup
Sub Total for System		1	items		\$5,426	

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks Fixed Projector	Educational Adequacy	2	Ea.	2	\$7,368	Rollup
Sub Total for System		1	items		\$7,368	

Specialties

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Lab lacks an air exchange system.	Educational Adequacy	2	Ea.	2	\$28,627	Rollup
Sub Total for System		1	items		\$28,627	

Other

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
STEM lab requires renovation based on condition of room(s)	Capital Renewal	1	LS	2	\$398,662	316955
Sub Total for System		1	items		\$398,662	
Sub Total for Building 13 - Building 13		15	items		\$611,823	

Building: 14 - Building 14

Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Reroofing with new Decking Required (Broward CPS)	Capital Renewal	3,406	SF	2	\$41,442	224095 GOB
Sub Total for System		1	items		\$41,442	

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Aluminum Window Is Damaged And Requires Replacement	Capital Renewal	32	SF	2	\$4,775	211432 GOB

Broward County Public Schools

School Deficiency Listing

9/2/2014 9:39 AM

0701	Parkway Middle School
-------------	------------------------------

Building: 14 - Building 14

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Exterior Door Hardware Requires Replacement	Deferred Maintenance	1	Ea.	3	\$2,850	211430 GOB
The Exterior Requires Painting	Capital Renewal	4,000	SF Wall	3	\$13,499	211429 GOB
The Exterior Requires Cleaning	Deferred Maintenance	4,000	SF Wall	5	\$7,997	211427
Sub Total for System		4	items		\$29,121	

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Acoustical Ceilings Tiles Require Replacement	Capital Renewal	1,000	SF	3	\$5,575	211439
Room lacks appropriate amount of teacher storage.	Educational Adequacy	30	Ea.	4	\$18,145	Rollup
Interior Gypboard Walls Require Repainting	Deferred Maintenance	2,800	SF Wall	5	\$9,330	211444
Interior Wood Walls Require Repainting	Deferred Maintenance	400	SF Wall	5	\$821	211447
Sub Total for System		4	items		\$33,871	

Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Fan Coil (Chilled Water) HVAC Component Requires Replacement	Capital Renewal	4	Ea.	3	\$7,912	211128 GOB
Sub Total for System		1	items		\$7,912	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The 1 X 4 Interior Fluorescent Light Fixture Requires Replacement	Capital Renewal	5	Ea.	3	\$1,783	210912
The 2 X 4 Interior Fluorescent Lighting Requires Replacement	Capital Renewal	80	Ea.	3	\$45,390	210915
Sub Total for System		2	items		\$47,173	

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Custodial Mop Or Service Sink Requires Replacement	Deferred Maintenance	1	Ea.	4	\$1,684	211129
Sub Total for System		1	items		\$1,684	
Sub Total for Building 14 - Building 14		13	items		\$161,203	

Building: 15 - Building 15

Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Reroofing with new Decking Required (Broward CPS)	Capital Renewal	3,385	SF	2	\$41,187	224097 GOB
The Roof Requires Cleaning	Deferred Maintenance	50	SF	4	\$621	224096
Sub Total for System		2	items		\$41,808	

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Aluminum Window Is Damaged And Requires Replacement	Capital Renewal	36	SF	2	\$5,371	211412 GOB
Exterior Door Hardware Requires Replacement	Deferred Maintenance	4	Ea.	3	\$11,398	211410 GOB
The Exterior Requires Painting	Capital Renewal	4,000	SF Wall	3	\$13,499	211409 GOB
The Exterior Requires Cleaning	Deferred Maintenance	4,000	SF Wall	5	\$7,997	211408
Sub Total for System		4	items		\$38,266	

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Acoustical Ceilings Tiles Require Replacement	Capital Renewal	1,500	SF	3	\$8,382	211413
Room lacks appropriate amount of teacher storage.	Educational Adequacy	32	Ea.	4	\$19,354	Rollup

Rev 1 Sept 2014

Parkway Middle School 0701

M•A•P•P•S ©, Jacobs 2014

Page 16 of 26

Broward County Public Schools

School Deficiency Listing

9/2/2014 9:39 AM

0701	Parkway Middle School
-------------	------------------------------

Building: 15 - Building 15

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Interior Ceramic Walls Require Repainting	Deferred Maintenance	800	SF Wall	5	\$2,104	211416
Interior Gypboard Walls Require Repainting	Deferred Maintenance	3,200	SF Wall	5	\$10,663	211415
Sub Total for System		4	items		\$40,483	

Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Fan Coil (Chilled Water) HVAC Component Requires Replacement	Capital Renewal	4	Ea.	3	\$7,912	211138 GOB
Sub Total for System		1	items		\$7,912	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The 1 X 4 Interior Fluorescent Light Fixture Requires Replacement	Capital Renewal	5	Ea.	3	\$1,783	210919
The 2 X 4 Interior Fluorescent Lighting Requires Replacement	Capital Renewal	80	Ea.	3	\$45,390	210920
Sub Total for System		2	items		\$47,173	

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks Interactive White Board	Educational Adequacy	1	Ea.	2	\$2,722	Rollup
The Computer Closet Requires Fiber Optic Access to CER	Functional Deficiency	525	LF	2	\$11,812	Rollup
Sub Total for System		2	items		\$14,534	
Sub Total for Building 15 - Building 15		16	items		\$190,177	

Building: 16 - Building 16

Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Reroofing with new Decking Required (Broward CPS)	Capital Renewal	3,406	SF	2	\$41,442	224099 GOB
The Roof Requires Cleaning	Deferred Maintenance	200	SF	4	\$2,488	224098
Sub Total for System		2	items		\$43,928	

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Aluminum Window Is Damaged And Requires Replacement	Capital Renewal	32	SF	2	\$4,775	211354 GOB
Exterior Door Hardware Requires Replacement	Deferred Maintenance	3	Ea.	3	\$8,549	211352 GOB
The Exterior Requires Painting	Capital Renewal	4,000	SF Wall	3	\$13,499	211349 GOB
The Exterior Requires Cleaning	Deferred Maintenance	4,000	SF Wall	5	\$7,997	211347
Sub Total for System		4	items		\$34,820	

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Classroom Door Requires Vision Panel	Educational Adequacy	1	Ea.	3	\$373	Rollup
Classroom doors lack appropriate signs.	Educational Adequacy	1	Ea.	3	\$171	Rollup
Room has insufficient writing area.	Educational Adequacy	1	Ea.	3	\$1,039	Rollup
The Acoustical Ceilings Tiles Require Replacement	Capital Renewal	1,000	SF	3	\$5,575	211357
The Ceramic Tile Flooring Requires Replacement	Capital Renewal	300	SF	3	\$5,281	211375
The Concrete Flooring Is Damaged And Requires Replacement	Capital Renewal	50	SF	3	\$382	211378
The Suspended Ceiling Grid and Tiles Require Replacement	Capital Renewal	2,900	SF	3	\$25,908	211361
The Vinyl Composition Tile Requires Replacement	Capital Renewal	2,900	SF	3	\$25,717	211371
Interior Wood Walls Require Repair	Deferred Maintenance	800	SF Wall	4	\$2,855	211369

Rev 1 Sept 2014

Parkway Middle School 0701

M•A•P•P•S ©, Jacobs 2014

Page 17 of 26

Broward County Public Schools

School Deficiency Listing

9/2/2014 9:39 AM

0701	Parkway Middle School
-------------	------------------------------

Building: 16 - Building 16

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient tackboard area	Educational Adequacy	2	Ea.	4	\$771	Rollup
Room lacks appropriate amount of teacher storage.	Educational Adequacy	29	Ea.	4	\$17,540	Rollup
Interior Gypboard Walls Require Repainting	Deferred Maintenance	3,200	SF Wall	5	\$10,663	211366
Sub Total for System		12	items		\$96,274	

Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Fan Coil (Chilled Water) HVAC Component Requires Replacement	Capital Renewal	4	Ea.	3	\$7,912	211139 GOB
Sub Total for System		1	items		\$7,912	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient electrical outlets	Educational Adequacy	24	Ea.	3	\$8,760	Rollup
The 1 X 4 Interior Fluorescent Light Fixture Requires Replacement	Capital Renewal	5	Ea.	3	\$1,783	210922
The 2 X 4 Interior Fluorescent Lighting Requires Replacement	Capital Renewal	80	Ea.	3	\$45,390	210931
Room lacks controls to partially dim lights.	Educational Adequacy	1	Ea.	5	\$779	Rollup
Sub Total for System		4	items		\$56,733	

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Custodial Mop Or Service Sink Requires Replacement	Deferred Maintenance	1	Ea.	4	\$1,684	211140
Sub Total for System		1	items		\$1,684	

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks Interactive White Board	Educational Adequacy	1	Ea.	2	\$2,722	Rollup
Sub Total for System		1	items		\$2,722	
Sub Total for Building 16 - Building 16		25	items		\$244,073	

Building: 17 - Building 17

Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Reroofing with new Decking Required (Broward CPS)	Capital Renewal	3,346	SF	2	\$40,712	224101 GOB
The Roof Requires Cleaning	Deferred Maintenance	100	SF	4	\$1,243	224100
Sub Total for System		2	items		\$41,955	

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Aluminum Window Is Damaged And Requires Replacement	Capital Renewal	32	SF	2	\$4,775	211333 GOB
Exterior Door Hardware Requires Replacement	Deferred Maintenance	3	Ea.	3	\$8,549	211332 GOB
The Exterior Requires Painting	Capital Renewal	4,000	SF Wall	3	\$13,499	211331 GOB
The Exterior Requires Cleaning	Deferred Maintenance	4,000	SF Wall	5	\$7,997	211330
Sub Total for System		4	items		\$34,820	

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Classroom Door Requires Vision Panel	Educational Adequacy	1	Ea.	3	\$373	Rollup
Classroom doors lack appropriate signs.	Educational Adequacy	2	Ea.	3	\$342	Rollup

Rev 1 Sept 2014

Parkway Middle School 0701

M•A•P•P•S ©, Jacobs 2014

Page 18 of 26

Broward County Public Schools

School Deficiency Listing

9/2/2014 9:39 AM

0701	Parkway Middle School
-------------	------------------------------

Building: 17 - Building 17

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient writing area.	Educational Adequacy	4	Ea.	3	\$4,154	Rollup
The Acoustical Ceilings Tiles Require Replacement	Capital Renewal	1,500	SF	3	\$8,362	211334
Interior Ceramic Walls Require Repair Or Replacement	Capital Renewal	800	SF Wall	4	\$15,072	211339
Interior Gypboard Walls Require Repair	Deferred Maintenance	1,000	SF Wall	4	\$5,352	211337
Interior Wood Walls Require Repair	Deferred Maintenance	1,550	SF Wall	4	\$5,531	211338
Room has insufficient tackboard area.	Educational Adequacy	2	Ea.	4	\$771	Rollup
Room lacks appropriate amount of teacher storage.	Educational Adequacy	18	Ea.	4	\$10,887	Rollup
Room lacks appropriate sound control.	Educational Adequacy	643	SF	4	\$20,166	Rollup
Room lacks a changing table.	Educational Adequacy	1	Ea.	5	\$2,488	Rollup
Sub Total for System		11	items		\$73,499	

Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Fan Coil (Chilled Water) HVAC Component Requires Replacement	Capital Renewal	3	Ea.	3	\$5,934	211141 GOB
Sub Total for System		1	items		\$5,934	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient electrical outlets.	Educational Adequacy	36	Ea.	3	\$13,169	Rollup
The 1 X 4 Interior Fluorescent Light Fixture Requires Replacement	Capital Renewal	5	Ea.	3	\$1,783	210926
The 2 X 4 Interior Fluorescent Lighting Requires Replacement	Capital Renewal	60	Ea.	3	\$45,390	210927
Room does not have tamper-proof light switching.	Educational Adequacy	3	Ea.	5	\$1,457	Rollup
Room lacks controls to partially dim lights.	Educational Adequacy	1	Ea.	5	\$779	Rollup
Sub Total for System		5	items		\$62,579	

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	1	Ea.	2	\$1,357	Rollup
Room lacks a private shower area.	Educational Adequacy	1	Ea.	4	\$9,133	Rollup
Room lacks private toilets.	Educational Adequacy	1	Ea.	4	\$11,217	Rollup
Room lacks a drinking fountain.	Educational Adequacy	1	Ea.	5	\$959	Rollup
Sub Total for System		4	items		\$22,665	

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks Fixed Projector	Educational Adequacy	3	Ea.	2	\$11,053	Rollup
Room lacks Interactive White Board	Educational Adequacy	4	Ea.	2	\$10,887	Rollup
The Computer Closet Requires Fiber Optic Access to CER	Functional Deficiency	525	LF	2	\$11,812	Rollup
Sub Total for System		3	items		\$33,751	

Specialties

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks an appropriate refrigerator.	Educational Adequacy	1	Ea.	3	\$5,253	Rollup

Broward County Public Schools

School Deficiency Listing

9/2/2014 9:39 AM

0701	Parkway Middle School
-------------	------------------------------

Building: 17 - Building 17

Specialties

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks an appropriate stove.	Educational Adequacy	1	Ea.	3	\$7,171	Rollup
Room does not have sufficient cubbies.	Educational Adequacy	30	Ea.	5	\$1,249	Rollup
Room has an insufficient number of coat hooks.	Educational Adequacy	12	Ea.	5	\$140	Rollup
Sub Total for System		4	items		\$13,814	
Sub Total for Building 17 - Building 17		34	items		\$289,017	

Building: 18 - Building 18

Site

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Concrete Walks Require Replacement	Capital Renewal	600	SF	3	\$8,155	211328
Sub Total for System		1	items		\$8,155	

Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Reroofing with new Decking Required (Broward CPS)	Capital Renewal	677	SF	2	\$8,237	224103 GOB
The Roof Requires Cleaning	Deferred Maintenance	50	SF	4	\$621	224102
Sub Total for System		2	items		\$8,859	

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Exterior Door Hardware Requires Replacement	Deferred Maintenance	1	Ea.	3	\$2,950	211329 GOB
Sub Total for System		1	items		\$2,950	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The 1 X 4 Interior Fluorescent Light Fixture Requires Replacement	Capital Renewal	8	Ea.	3	\$2,853	210936
Sub Total for System		1	items		\$2,853	
Sub Total for Building 18 - Building 18		5	items		\$22,716	

Building: 19 - Building 19

Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Reroofing with new Decking Required (Broward CPS)	Capital Renewal	7,146	SF	2	\$86,948	224105 GOB
The Roof Requires Cleaning	Deferred Maintenance	400	SF	4	\$4,971	224104
Sub Total for System		2	items		\$91,919	

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Aluminum Window Is Damaged And Requires Replacement	Capital Renewal	68	SF	2	\$10,146	211296 GOB
Exterior Door Hardware Requires Replacement	Deferred Maintenance	2	Ea.	3	\$5,699	211294 GOB
The Exterior Requires Painting	Capital Renewal	10,000	SF Wall	3	\$33,748	211287 GOB
The Metal Exterior Door Requires Repair	Deferred Maintenance	5	Door	3	\$2,481	211292 GOB
The Exterior Requires Cleaning	Deferred Maintenance	10,000	SF Wall	5	\$19,993	211285
Sub Total for System		5	items		\$72,068	

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Wood Exterior Door Is Damaged And Requires Replacement	Capital Renewal	2	Door	2	\$8,334	211290 GOB

Broward County Public Schools

School Deficiency Listing

9/2/2014 9:39 AM

0701	Parkway Middle School
-------------	------------------------------

Building: 19 - Building 19

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Classroom doors lack appropriate signs.	Educational Adequacy	2	Ea.	3	\$342	Rollup
Interior Doors Require Repair	Deferred Maintenance	7	Door	3	\$6,304	211300
The Plaster Ceilings Are Damaged And Requires Repair	Deferred Maintenance	8,000	SF	3	\$106,480	211297
Interior Wood Walls Require Repair	Deferred Maintenance	2,800	SF Wall	4	\$9,991	211298
Interior Wood Walls Require Repainting	Deferred Maintenance	2,800	SF Wall	5	\$5,749	211299
Sub Total for System		6	items		\$137,201	

Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Air Handler HVAC Component Requires Replacement	Capital Renewal	2	Ea.	3	\$11,008	210991 GOB
The Fan Coil (Chilled Water) HVAC Component Requires Replacement	Capital Renewal	2	Ea.	3	\$3,956	210992 GOB
The Mechanical / HVAC Piping / System Is Beyond Its Useful Life	Deferred Maintenance	7,797	SF	3	\$57,186	210994 GOB
The Window AC Unit Component Requires Replacement	Capital Renewal	2	Ea.	3	\$4,280	210993 GOB
Sub Total for System		4	items		\$176,430	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The 1 X 4 Interior Fluorescent Light Fixture Requires Replacement	Capital Renewal	34	Ea.	3	\$12,126	210942
Sub Total for System		1	items		\$12,126	

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Toilets Plumbing Fixtures Require Replacement	Capital Renewal	6	Ea.	2	\$13,524	210996
The Urinal Plumbing Fixtures Require Replacement	Capital Renewal	3	Ea.	2	\$5,420	210997
The Rest Room Lavatories Plumbing Fixtures Require Replacement	Capital Renewal	6	Ea.	3	\$14,769	210985
Sub Total for System		3	items		\$33,713	

Specialties

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Replace metal student lockers	Deferred Maintenance	80	Ea.	4	\$96,256	211306
Sub Total for System		1	items		\$96,256	
Sub Total for Building 19 - Building 19		22	items		\$619,713	

Building: 21 - Storage

Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Reroofing with new Decking Required (Broward CPS)	Capital Renewal	172	SF	2	\$2,093	224106 GOB
Sub Total for System		1	items		\$2,093	

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Exterior Requires Cleaning	Deferred Maintenance	800	SF Wall	5	\$1,599	211282
Sub Total for System		1	items		\$1,599	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Incandescent Lighting Is Damaged And Should Be Replaced	Capital Renewal	4	Ea.	3	\$1,567	210875
Sub Total for System		1	items		\$1,567	
Sub Total for Building 21 - Storage		3	items		\$5,259	

Broward County Public Schools

School Deficiency Listing

9/2/2014 9:39 AM

0701	Parkway Middle School
-------------	------------------------------

Building: 22 - Building 22

Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Reroofing with new Decking Required (Broward CPS)	Capital Renewal	2,400	SF	2	\$29,202	224107
Sub Total for System		1	Items		\$29,202	

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Aluminum Window Is Damaged And Requires Replacement	Capital Renewal	7	SF	2	\$1,024	211252 GOB
Exterior Door Hardware Requires Replacement	Deferred Maintenance	6	Ea.	3	\$16,767	211249 GOB
Interior CMU Walls Require Repair	Deferred Maintenance	36,000	SF	3	\$925,227	211280
The Exterior Requires Cleaning	Deferred Maintenance	50,000	SF Wall	5	\$98,034	211248
Sub Total for System		4	Items		\$1,041,061	

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Classroom Door Requires Vision Panel	Educational Adequacy	3	Ea.	3	\$1,120	Rollup
Classroom doors lack appropriate signs.	Educational Adequacy	7	Ea.	3	\$1,198	Rollup
Room has insufficient writing area.	Educational Adequacy	5	Ea.	3	\$5,193	Rollup
The Acoustical Ceilings Tiles Require Replacement	Capital Renewal	25,000	SF	3	\$136,673	211253
The Carpet Flooring Requires Replacement	Capital Renewal	9,200	SF	3	\$93,950	211262
The Concrete Flooring Is Damaged And Requires Replacement	Capital Renewal	3,300	SF	3	\$24,731	211270
The Vinyl Composition Tile Requires Replacement	Capital Renewal	18,900	SF	3	\$164,363	211264
Interior Ceramic Walls Require Repair Or Replacement	Capital Renewal	3,000	SF Wall	4	\$55,429	211258
Interior Gypboard Walls Require Repair	Deferred Maintenance	6,000	SF Wall	4	\$31,490	211255
Interior Wood Walls Require Repair	Deferred Maintenance	5,000	SF Wall	4	\$17,496	211256
Room has insufficient tackboard area.	Educational Adequacy	14	Ea.	4	\$5,395	Rollup
Room lacks appropriate amount of teacher storage.	Educational Adequacy	37	Ea.	4	\$22,378	Rollup
Room lacks appropriate sound control.	Educational Adequacy	2,524	SF	4	\$79,162	Rollup
The Interior Door Hardware Requires Replacement	Capital Renewal	53	Door	4	\$114,682	211271
The Wood Flooring Requires Repair	Deferred Maintenance	5,000	SF	4	\$59,315	211266
Sub Total for System		15	Items		\$812,574	

Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Air Handler HVAC Component Requires Replacement	Capital Renewal	1	Ea.	3	\$54,431	210950 GOB
Sub Total for System		1	Items		\$54,431	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient electrical outlets	Educational Adequacy	68	Ea.	3	\$24,874	Rollup
Stage Lighting Is Damaged, Broken Or Deficient	Functional Deficiency	30	Ea.	3	\$38,286	210867
The 1 X 4 Interior Fluorescent Light Fixture Requires Replacement	Capital Renewal	127	Ea.	3	\$44,417	210864
The 2 X 4 Interior Fluorescent Lighting Requires Replacement	Capital Renewal	260	Ea.	3	\$144,666	210865
The H.I.D. Lighting Is Damaged And Should Be Replaced	Capital Renewal	83	Ea.	3	\$64,508	210866
Room lacks controls to partially dim lights.	Educational Adequacy	2	Ea.	5	\$1,559	Rollup
Sub Total for System		6	Items		\$318,310	

Broward County Public Schools

School Deficiency Listing

9/2/2014 9:39 AM

0701	Parkway Middle School
-------------	------------------------------

Building: 22 - Building 22

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	4	Ea.	2	\$5,428	Rollup
Prep room lacks a sink.	Educational Adequacy	4	Ea.	3	\$17,799	Rollup
The Rest Room Lavatories Plumbing Fixtures Require Replacement	Capital Renewal	2	Ea.	3	\$4,828	210951
Room lacks a drinking fountain.	Educational Adequacy	5	Ea.	5	\$4,795	Rollup
Sub Total for System		4	items		\$32,848	

Fire and Security

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Install Fire Sprinklers	Code Compliance	4,838	SF	1	\$40,909	Rollup GOB
Sub Total for System		1	items		\$40,909	

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient dataports.	Educational Adequacy	30	Ea.	2	\$5,190	Rollup GOB
Room lacks Fixed Projector	Educational Adequacy	3	Ea.	2	\$11,053	Rollup
Room lacks Interactive White Board	Educational Adequacy	7	Ea.	2	\$19,052	Rollup
The Computer Closet Requires Fiber Optic Access to CER	Functional Deficiency	1,050	LF	2	\$23,624	Rollup
Sub Total for System		4	items		\$58,918	

Specialties

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks the required demonstration table.	Educational Adequacy	2	Ea.	3	\$14,927	Rollup
Blinds are missing or in poor condition.	Educational Adequacy	150	SF Surf	4	\$4,239	Rollup
Sub Total for System		2	items		\$19,166	
Sub Total for Building 22 - Building 22		38	items		\$2,407,409	

Building: 23 - Building Support

Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Reroofing Required (Broward CPS)	Capital Renewal	18,755	SF	2	\$196,723	224108 GOB
Sub Total for System		1	items		\$196,723	

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Exterior Door Hardware Requires Replacement	Deferred Maintenance	2	Ea.	3	\$5,589	211237 GOB
Sub Total for System		1	items		\$5,589	

Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Chiller HVAC Component Is Damaged And Requires Replacement	Capital Renewal	2	Ea.	2	\$188,223	210969 GOB
Sub Total for System		1	items		\$188,223	
Sub Total for Building 23 - Building Support		3	items		\$390,535	

Building: 24 - Building 24

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Classroom doors lack appropriate signs.	Educational Adequacy	1	Ea.	3	\$171	Rollup
The Acoustical Ceilings Tiles Require Replacement	Capital Renewal	14,000	SF	3	\$74,877	211185

Broward County Public Schools

School Deficiency Listing

9/2/2014 9:39 AM

0701	Parkway Middle School
-------------	------------------------------

Building: 24 - Building 24

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Carpet Flooring Requires Replacement	Capital Renewal	5,000	SF	3	\$49,952	211189
Interior Gypboard Walls Require Repair	Deferred Maintenance	6,000	SF Wall	4	\$30,807	211186
Interior Wood Walls Require Repair	Deferred Maintenance	31,400	SF Wall	4	\$107,491	211188
Room lacks appropriate amount of teacher storage.	Educational Adequacy	185	Ea.	4	\$111,891	Rollup
Room lacks appropriate sound control.	Educational Adequacy	634	SF	4	\$19,885	Rollup
Sub Total for System		7	items		\$395,074	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room does not have tamper-proof light switching.	Educational Adequacy	1	Ea.	5	\$486	Rollup
Sub Total for System		1	items		\$486	

Fire and Security

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Install Fire Sprinklers	Code Compliance	268	SF	1	\$2,217	Rollup GOB
Sub Total for System		1	items		\$2,217	

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks Fixed Projector	Educational Adequacy	4	Ea.	2	\$14,737	Rollup
The Computer Closet Requires Fiber Optic Access to CER	Functional Deficiency	525	LF	2	\$11,812	Rollup
Sub Total for System		2	items		\$26,549	

Specialties

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks the required demonstration table.	Educational Adequacy	4	Ea.	3	\$29,954	Rollup
Room does not have sufficient cubbies.	Educational Adequacy	14	Ea.	5	\$582	Rollup
Room has an insufficient number of coat hooks.	Educational Adequacy	12	Ea.	5	\$140	Rollup
Sub Total for System		3	items		\$30,576	
Sub Total for Building 24 - Building 24		14	items		\$454,902	

Building: 25 - Building 25

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Exterior Requires Painting	Capital Renewal	56,000	SF Wall	3	\$181,337	211146 GOB
The Exterior Requires Cleaning	Deferred Maintenance	56,000	SF Wall	5	\$107,416	211145
Sub Total for System		2	items		\$288,753	

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Classroom doors lack appropriate signs.	Educational Adequacy	2	Ea.	3	\$342	Rollup
Room has insufficient writing area.	Educational Adequacy	4	Ea.	3	\$4,154	Rollup
The Carpet Flooring Requires Replacement	Capital Renewal	600	SF	3	\$5,994	211169
Room has insufficient tackboard area.	Educational Adequacy	1	Ea.	4	\$385	Rollup
Room lacks appropriate amount of teacher storage.	Educational Adequacy	93	Ea.	4	\$58,248	Rollup

Broward County Public Schools

School Deficiency Listing

9/2/2014 9:39 AM

0701	Parkway Middle School
-------------	------------------------------

Building: 25 - Building 25

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks appropriate sound control.	Educational Adequacy	2,042	SF	4	\$64,045	Rollup
Room lacks a changing table.	Educational Adequacy	3	Ea.	5	\$7,465	Rollup
Sub Total for System		7	items		\$138,634	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient electrical outlets.	Educational Adequacy	132	Ea.	3	\$48,282	Rollup
Room does not have tamper-proof light switching.	Educational Adequacy	5	Ea.	5	\$2,428	Rollup
Sub Total for System		2	items		\$50,710	

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	44	Ea.	2	\$59,887	Rollup
Room lacks a private shower area.	Educational Adequacy	4	Ea.	4	\$36,531	Rollup
Room lacks private toilets.	Educational Adequacy	4	Ea.	4	\$44,867	Rollup
Room lacks a drinking fountain.	Educational Adequacy	3	Ea.	5	\$2,877	Rollup
Sub Total for System		4	items		\$143,962	

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient dataports.	Educational Adequacy	50	Ea.	2	\$8,650	Rollup G-OB
The Computer Closet Requires Fiber Optic Access to CER	Functional Deficiency	1,575	LF	2	\$35,436	Rollup
Sub Total for System		2	items		\$44,086	

Specialties

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Lab lacks an air exchange system.	Educational Adequacy	4	Ea.	2	\$57,254	Rollup
Room lacks an appropriate refrigerator.	Educational Adequacy	3	Ea.	3	\$15,760	Rollup
Room lacks an appropriate stove.	Educational Adequacy	3	Ea.	3	\$21,514	Rollup
Room lacks the required demonstration table.	Educational Adequacy	4	Ea.	3	\$29,854	Rollup
Blinds are missing or in poor condition.	Educational Adequacy	180	SF Surf	4	\$5,086	Rollup
Room does not have sufficient cubbies.	Educational Adequacy	70	Ea.	5	\$2,912	Rollup
Room has an insufficient number of coat hooks.	Educational Adequacy	60	Ea.	5	\$700	Rollup
Sub Total for System		7	items		\$133,079	
Sub Total for Building 25 - Building 25		24	items		\$799,224	

Building: 26 - Gymnasium

Site

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Play Field Requires Regrading	Deferred Maintenance	25,000	SF	5	\$30,576	211142
Sub Total for System		1	items		\$30,576	

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
------------	----------	-----	-----	----------	-------------	----

Rev 1 Sept 2014
M•A•P•P•S ©, Jacobs 2014

Parkway Middle School 0701

Page 25 of 26

Broward County Public Schools

School Deficiency Listing

9/2/2014 9:39 AM

0701	Parkway Middle School
-------------	------------------------------

Building: 26 - Gymnasium

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Exterior Requires Painting	Capital Renewal	20,000	SF Wall	3	\$84,763	213447 GOB
The Exterior Requires Cleaning	Deferred Maintenance	20,000	SF Wall	5	\$38,363	211143
Sub Total for System		2	Items		\$103,126	

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Classroom doors lack appropriate signs.	Educational Adequacy	2	Ea.	3	\$342	Rollup
Room has insufficient writing area.	Educational Adequacy	1	Ea.	3	\$1,039	Rollup
Room has insufficient tackboard area.	Educational Adequacy	2	Ea.	4	\$771	Rollup
Room lacks appropriate amount of teacher storage	Educational Adequacy	5	Ea.	4	\$3,024	Rollup
Sub Total for System		4	Items		\$5,176	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient electrical outlets.	Educational Adequacy	2	Ea.	3	\$731	Rollup
Room does not have tamper-proof light switching.	Educational Adequacy	1	Ea.	5	\$486	Rollup
Sub Total for System		2	Items		\$1,217	

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	1	Ea.	2	\$1,357	Rollup
Room lacks a drinking fountain.	Educational Adequacy	1	Ea.	5	\$959	Rollup
Sub Total for System		2	Items		\$2,316	

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks Fixed Projector	Educational Adequacy	1	Ea.	2	\$3,684	Rollup
Room lacks Interactive White Board	Educational Adequacy	1	Ea.	2	\$2,722	Rollup
The Computer Closet Requires Fiber Optic Access to CER	Functional Deficiency	525	LF	2	\$11,812	Rollup
Sub Total for System		3	Items		\$18,218	
Sub Total for Building 26 - Gymnasium		14	Items		\$160,628	
Total for Permanent Buildings		513	Items		\$16,196,199	
Total for Portable Buildings					\$0	
Total for Campus					\$16,196,199	

2.4.4 MAPPS Deficiency Data

1	2	3	4	5	6	7	8	9	10	13	14	20	21	22	23	27	28	29
Def Asmt ID	Site Name	Building Number	Building Name	Building Number	Deficiency Description	Def Note	System ID	System Name	Uniformat Description	Category Description	Priority	Priority Description	Quantity	Unit	TTL Cost	GOB		
65330	Parway Middle School	22	Building 22	Install Fire Sprinklers	RY1011 INSTALL FIRE SPRINKLERS IN GROUP RES TROOV Bk4-3-25APR11MM	9	Fire and Security	Water-Based Fire-Suppression	Code Compliance	1	Mission Critical Concerns	4800	SF	\$40,090	GOB			
65339	Parway Middle School	03	Media Center	Install Fire Sprinklers	RY1011 INSTALL FIRE SPRINKLERS IN GROUP RES TROOV Bk4-3-25APR11MM	9	Fire and Security	Water-Based Fire-Suppression	Code Compliance	1	Mission Critical Concerns	108	SF	\$1,170	GOB			
65340	Parway Middle School	03	Media Center	Install Fire Sprinklers	RY1011 INSTALL FIRE SPRINKLERS IN GROUP RES TROOV Bk4-3-25APR11MM	9	Fire and Security	Water-Based Fire-Suppression	Code Compliance	1	Mission Critical Concerns	108	SF	\$1,190	GOB			
65341	Parway Middle School	24	Building 24	Install Fire Sprinklers	RY1011 INSTALL FIRE SPRINKLERS IN GROUP RES TROOV Bk4-3-25APR11MM	9	Fire and Security	Water-Based Fire-Suppression	Code Compliance	1	Mission Critical Concerns	67	SF	\$654	GOB			
65342	Parway Middle School	24	Building 24	Install Fire Sprinklers	RY1011 INSTALL FIRE SPRINKLERS IN GROUP RES TROOV Bk4-3-25APR11MM	9	Fire and Security	Water-Based Fire-Suppression	Code Compliance	1	Mission Critical Concerns	67	SF	\$654	GOB			
65343	Parway Middle School	24	Building 24	Install Fire Sprinklers	RY1011 INSTALL FIRE SPRINKLERS IN GROUP RES TROOV Bk4-3-25APR11MM	9	Fire and Security	Water-Based Fire-Suppression	Code Compliance	1	Mission Critical Concerns	67	SF	\$654	GOB			
65344	Parway Middle School	24	Building 24	Install Fire Sprinklers	RY1011 INSTALL FIRE SPRINKLERS IN GROUP RES TROOV Bk4-3-25APR11MM	9	Fire and Security	Water-Based Fire-Suppression	Code Compliance	1	Mission Critical Concerns	67	SF	\$654	GOB			
210950	Parway Middle School	22	Building 22	The Air Handler HVAC Component Requires Replacement	RY1011 INSTALL FIRE SPRINKLERS IN GROUP RES TROOV Bk4-3-25APR11MM	6	Mechanical	Decentralized Cooling	Capital Renewal	3	Short Term Conditions (2-3 Years)	1	Ea.	\$54,431	GOB			
210969	Parway Middle School	23	Building Support	The Other HVAC Component's Damaged And Requires Replacement	RY1011 INSTALL FIRE SPRINKLERS IN GROUP RES TROOV Bk4-3-25APR11MM	6	Mechanical	Central Cooling	Capital Renewal	2	Inherent Impact to Mission (1 Year)	1	Ea.	\$188,229	GOB			
210991	Parway Middle School	19	Building 19	The Air Handler HVAC Component Requires Replacement	RY1011 INSTALL FIRE SPRINKLERS IN GROUP RES TROOV Bk4-3-25APR11MM	6	Mechanical	Decentralized Cooling	Capital Renewal	3	Short Term Conditions (2-3 Years)	2	Ea.	\$111,008	GOB			
210992	Parway Middle School	19	Building 19	The Fan Coil (Chilled Water) HVAC Component Requires Replacement	RY1011 INSTALL FIRE SPRINKLERS IN GROUP RES TROOV Bk4-3-25APR11MM	6	Mechanical	Decentralized Cooling	Capital Renewal	3	Short Term Conditions (2-3 Years)	2	Ea.	\$3,996	GOB			
210993	Parway Middle School	19	Building 19	The Mechanical Unit Component Requires Replacement	RY1011 INSTALL FIRE SPRINKLERS IN GROUP RES TROOV Bk4-3-25APR11MM	6	Mechanical	Decentralized Cooling	Capital Renewal	3	Short Term Conditions (2-3 Years)	2	Ea.	\$4,390	GOB			
210994	Parway Middle School	19	Building 19	The Mechanical Piping / System is Beyond Its Useful Life	RY1011 INSTALL FIRE SPRINKLERS IN GROUP RES TROOV Bk4-3-25APR11MM	6	Mechanical	Facility Hydraulic Distribution	Deferred Maintenance	3	Short Term Conditions (2-3 Years)	7797	SF	\$67,196	GOB			
210999	Parway Middle School	01	Building 1	The Air Handler HVAC Component Requires Replacement	RY1011 INSTALL FIRE SPRINKLERS IN GROUP RES TROOV Bk4-3-25APR11MM	6	Mechanical	Decentralized Cooling	Capital Renewal	3	Short Term Conditions (2-3 Years)	2	Ea.	\$111,008	GOB			
211003	Parway Middle School	01	Building 1	The Air Handler HVAC Component Requires Replacement	RY1011 INSTALL FIRE SPRINKLERS IN GROUP RES TROOV Bk4-3-25APR11MM	6	Mechanical	Decentralized Cooling	Capital Renewal	3	Short Term Conditions (2-3 Years)	1	Ea.	\$66,604	GOB			
211005	Parway Middle School	02	Building 2	Complete Non-Term HVAC Installation For Non-Air-Conditioned Facility	RY1011 INSTALL FIRE SPRINKLERS IN GROUP RES TROOV Bk4-3-25APR11MM	2	Inherent Impact to Mission (1 Year)	Functional Deficiency	Functional Deficiency	2	Inherent Impact to Mission (1 Year)	2200	SF	\$66,270	GOB			
211006	Parway Middle School	02	Building 2	The Air Handler HVAC Component Requires Replacement	RY1011 INSTALL FIRE SPRINKLERS IN GROUP RES TROOV Bk4-3-25APR11MM	6	Mechanical	Decentralized Cooling	Capital Renewal	3	Short Term Conditions (2-3 Years)	1	Ea.	\$66,604	GOB			
211007	Parway Middle School	02	Building 2	Duct Heater Requires Replacement	RY1011 INSTALL FIRE SPRINKLERS IN GROUP RES TROOV Bk4-3-25APR11MM	6	Mechanical	Decentralized Heating Equipment	Capital Renewal	3	Short Term Conditions (2-3 Years)	1	Ea.	\$6,163	GOB			
211015	Parway Middle School	03	Media Center	The Air Handler HVAC Component Requires Replacement	RY1011 INSTALL FIRE SPRINKLERS IN GROUP RES TROOV Bk4-3-25APR11MM	6	Mechanical	Decentralized Cooling	Capital Renewal	3	Short Term Conditions (2-3 Years)	1	Ea.	\$66,604	GOB			

Deficiency Data Grid
Thursday, October 22,
2015 7:38 AM

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29
Def/Asset ID	Site Name	Building Number	Building Name	Deficiency Description	Def Note	System ID	System Name	Uniformat Description	Category Description	Priority	Priority Description	Quantity	Unit	TTL Cost	GOB													
211037	Parkway Middle School	05	Building 5	The Fan Coil (Chilled Water) HVAC Component Requires Replacement	4@8=10,000CFM	6	Mechanical	Decentralized Cooling	Capital Renewal	2	Indirect Impact to Mission (1 Year)	2	10x10x4	\$6,747	GOB													
211038	Parkway Middle School	05	Building 5	The Air Handler HVAC Component Requires Replacement	2@5=10,000CFM	6	Mechanical	Decentralized Cooling	Capital Renewal	2	Short Term Conditions (2-3 Years)	2	Ea.	\$11,008	GOB													
211040	Parkway Middle School	06	Building 6	The Air Handler HVAC Component Requires Replacement	1@10,000=10,000CFM	6	Mechanical	Decentralized Cooling	Capital Renewal	1	Short Term Conditions (2-3 Years)	1	Ea.	\$66,004	GOB													
211050	Parkway Middle School	06	Building 6	The Fan Coil (Chilled Water) HVAC Component Requires Replacement	1@10,000=10,000CFM	6	Mechanical	Decentralized Cooling	Capital Renewal	1	Indirect Impact to Mission (1 Year)	1	10x10x4	\$2,373	GOB													
211051	Parkway Middle School	07	Classroom	The Fan Coil (Chilled Water) HVAC Component Requires Replacement	6@3=18,000CFM	6	Mechanical	Decentralized Cooling	Capital Renewal	3	Short Term Conditions (2-3 Years)	3	Ea.	\$11,889	GOB													
211059	Parkway Middle School	08	Building 8	The Fan Coil (Chilled Water) HVAC Component Requires Replacement	5@3=15,000CFM	6	Mechanical	Decentralized Cooling	Capital Renewal	3	Short Term Conditions (2-3 Years)	3	Ea.	\$9,850	GOB													
211077	Parkway Middle School	09	Building 9	The Fan Coil (Chilled Water) HVAC Component Requires Replacement	4@3=12,000CFM	6	Mechanical	Decentralized Cooling	Capital Renewal	3	Short Term Conditions (2-3 Years)	4	Ea.	\$7,912	GOB													
211090	Parkway Middle School	10	Building 10	The Fan Coil (Chilled Water) HVAC Component Requires Replacement	4@3=12,000CFM	6	Mechanical	Decentralized Cooling	Capital Renewal	3	Short Term Conditions (2-3 Years)	4	Ea.	\$7,912	GOB													
211100	Parkway Middle School	12	Building 12	The Fan Coil (Chilled Water) HVAC Component Requires Replacement	7@3=21,000CFM	6	Mechanical	Decentralized Cooling	Capital Renewal	3	Short Term Conditions (2-3 Years)	7	Ea.	\$13,579	GOB													
211117	Parkway Middle School	13	Building 13	The Fan Coil (Chilled Water) HVAC Component Requires Replacement	6@3=18,000CFM	6	Mechanical	Decentralized Cooling	Capital Renewal	3	Short Term Conditions (2-3 Years)	6	Ea.	\$11,889	GOB													
211120	Parkway Middle School	14	Building 14	The Fan Coil (Chilled Water) HVAC Component Requires Replacement	4@3=12,000CFM	6	Mechanical	Decentralized Cooling	Capital Renewal	3	Short Term Conditions (2-3 Years)	4	Ea.	\$7,912	GOB													
211130	Parkway Middle School	15	Building 15	The Fan Coil (Chilled Water) HVAC Component Requires Replacement	4@3=12,000CFM	6	Mechanical	Decentralized Cooling	Capital Renewal	3	Short Term Conditions (2-3 Years)	4	Ea.	\$7,912	GOB													
211138	Parkway Middle School	16	Building 16	The Fan Coil (Chilled Water) HVAC Component Requires Replacement	4@3=12,000CFM	6	Mechanical	Decentralized Cooling	Capital Renewal	3	Short Term Conditions (2-3 Years)	4	Ea.	\$7,912	GOB													
211141	Parkway Middle School	17	Building 17	The Fan Coil (Chilled Water) HVAC Component Requires Replacement	6@3=18,000CFM	6	Mechanical	Decentralized Cooling	Capital Renewal	3	Short Term Conditions (2-3 Years)	3	Ea.	\$6,904	GOB													
211146	Parkway Middle School	25	Building 25	The Exterior Requires Repair		4	Exterior	Exterior Wall	Capital Renewal	3	Short Term Conditions (2-3 Years)	56000	SF Wall	\$181,307	GOB													
211207	Parkway Middle School	23	Building Support	Exterior Door Hardware Requires Replacement		4	Exterior	Exterior Entrance Doors	Capital Renewal	3	Short Term Conditions (2-3 Years)	2	Ea.	\$6,089	GOB													
211249	Parkway Middle School	22	Building 22	Exterior Door Hardware Requires Replacement		4	Exterior	Exterior Entrance Doors	Capital Renewal	3	Short Term Conditions (2-3 Years)	6	Ea.	\$16,767	GOB													
211252	Parkway Middle School	22	Building 22	The Aluminum Window Is Damaged And Requires Replacement	5(L)X 6(W)	4	Exterior	Exterior Fixed Windows	Capital Renewal	2	Indirect Impact to Mission (1 Year)	7	SF	\$1,024	GOB													
211267	Parkway Middle School	19	Building 19	The Exterior Requires Repair		4	Exterior	Exterior Wall	Capital Renewal	3	Short Term Conditions (2-3 Years)	10000	SF Wall	\$332,468	GOB													

Def/Asset ID	Site Name	Building Number	Building Name	Deficiency Description	Def/Note	System ID	System Name	Uniformat Description	Category Description	Priority	Priority Description	Quantity	Unit	TTL-Cost
211290	Parkway Middle School	19	Building 19	The Wood Exterior Door Is Damaged And Requires Replacement.	7(L) X 2(W)	4	Exterior	Exterior Sliding Doors	Capital Renewal	2	Indirect Impact to Mission (1 Year)	2	Door	\$8,334
211292	Parkway Middle School	19	Building 19	The Metal Exterior Door Requires Repair.	7(L) X 2(W)	4	Exterior	Exterior Entrance Doors	Deferred Maintenance	3	Short Term Conditions (2-3 Years)	5	Door	\$2,481
211294	Parkway Middle School	19	Building 19	Exterior Door Hardware Requires Replacement.		4	Exterior	Exterior Entrance Doors	Deferred Maintenance	3	Short Term Conditions (2-3 Years)	2	Ea.	\$6,656
211296	Parkway Middle School	19	Building 19	The Aluminum Window Is Damaged And Requires Replacement.	3(L) X 2(W)	4	Exterior	Exterior Fixed Windows	Capital Renewal	2	Indirect Impact to Mission (1 Year)	68	SF	\$10,146
211319	Parkway Middle School		Roofing	Aluminum Soffit Material Requires Replacement.		2	Roofing	Canopy Roofing	Capital Renewal	3	Short Term Conditions (2-3 Years)	600	SF	\$3,047
211320	Parkway Middle School	18	Building 18	Exterior Door Hardware Requires Replacement.		4	Exterior	Exterior Entrance Doors	Deferred Maintenance	3	Short Term Conditions (2-3 Years)	1	Ea.	\$2,880
211331	Parkway Middle School	17	Building 17	The Exterior Requires Paraling.		4	Exterior	Exterior Wall Venter	Capital Renewal	3	Short Term Conditions (2-3 Years)	4000	SF Wall	\$13,459
211332	Parkway Middle School	17	Building 17	Exterior Door Hardware Requires Replacement.		4	Exterior	Exterior Entrance Doors	Deferred Maintenance	3	Short Term Conditions (2-3 Years)	3	Ea.	\$8,549
211333	Parkway Middle School	17	Building 17	The Aluminum Window Is Damaged And Requires Replacement.	6(L) X 2(W) Jaming	4	Exterior	Exterior Fixed Windows	Capital Renewal	2	Indirect Impact to Mission (1 Year)	32	SF	\$4,776
211343	Parkway Middle School	16	Building 16	The Exterior Requires Paraling.		4	Exterior	Exterior Wall Venter	Capital Renewal	3	Short Term Conditions (2-3 Years)	4000	SF Wall	\$13,459
211352	Parkway Middle School	16	Building 16	Exterior Door Hardware Requires Replacement.		4	Exterior	Exterior Entrance Doors	Deferred Maintenance	3	Short Term Conditions (2-3 Years)	3	Ea.	\$8,549
211354	Parkway Middle School	16	Building 16	The Aluminum Window Is Damaged And Requires Replacement.	6(L) X 2(W)	4	Exterior	Exterior Fixed Windows	Capital Renewal	2	Indirect Impact to Mission (1 Year)	32	SF	\$4,776
211409	Parkway Middle School	15	Building 15	The Exterior Requires Paraling.		4	Exterior	Exterior Wall Venter	Capital Renewal	3	Short Term Conditions (2-3 Years)	4000	SF Wall	\$13,459
211410	Parkway Middle School	15	Building 15	Exterior Door Hardware Requires Replacement.		4	Exterior	Exterior Entrance Doors	Deferred Maintenance	3	Short Term Conditions (2-3 Years)	4	Ea.	\$11,286
211412	Parkway Middle School	15	Building 15	The Aluminum Window Is Damaged And Requires Replacement.	6(L) X 2(W)	4	Exterior	Exterior Fixed Windows	Capital Renewal	2	Indirect Impact to Mission (1 Year)	36	SF	\$6,371
211429	Parkway Middle School	14	Building 14	The Exterior Requires Paraling.		4	Exterior	Exterior Wall Venter	Capital Renewal	3	Short Term Conditions (2-3 Years)	4000	SF Wall	\$13,459
211430	Parkway Middle School	14	Building 14	Exterior Door Hardware Requires Replacement.		4	Exterior	Exterior Entrance Doors	Deferred Maintenance	3	Short Term Conditions (2-3 Years)	1	Ea.	\$2,880
211432	Parkway Middle School	14	Building 14	The Aluminum Window Is Damaged And Requires Replacement.	Jaming 6(L) X 3(W)	4	Exterior	Exterior Fixed Windows	Capital Renewal	2	Indirect Impact to Mission (1 Year)	32	SF	\$4,776
211459	Parkway Middle School	13	Building 13	The Exterior Requires Paraling.		4	Exterior	Exterior Wall Venter	Capital Renewal	3	Short Term Conditions (2-3 Years)	4000	SF Wall	\$13,459
211460	Parkway Middle School	13	Building 13	Exterior Door Hardware Requires Replacement.		4	Exterior	Exterior Entrance Doors	Deferred Maintenance	3	Short Term Conditions (2-3 Years)	3	Ea.	\$8,549
211461	Parkway Middle School	13	Building 13	The Aluminum Window Is Damaged And Requires Replacement.	Jaming 6(L) X 4(W)	4	Exterior	Exterior Fixed Windows	Capital Renewal	2	Indirect Impact to Mission (1 Year)	27	SF	\$4,029
211488	Parkway Middle School	12	Building 12	The Exterior Requires Paraling.		4	Exterior	Exterior Wall Venter	Capital Renewal	3	Short Term Conditions (2-3 Years)	7600	SF Wall	\$24,822
211490	Parkway Middle School	12	Building 12	Exterior Door Hardware Requires Replacement.		4	Exterior	Exterior Entrance Doors	Deferred Maintenance	3	Short Term Conditions (2-3 Years)	7	Ea.	\$19,951
211494	Parkway Middle School	12	Building 12	The Aluminum Window Is Damaged And Requires Replacement.	Jaming 6(L) X 4(W)	4	Exterior	Exterior Fixed Windows	Capital Renewal	2	Indirect Impact to Mission (1 Year)	4	SF	\$986
211534	Parkway Middle School	10	Building 10	The Exterior Requires Paraling.		4	Exterior	Exterior Wall Venter	Capital Renewal	3	Short Term Conditions (2-3 Years)	4000	SF Wall	\$13,459

Deficiency Data Grid
Thursday, October 22,
2015 7:38 AM

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29
Def/Assess ID	Site Name	Building Number	Building Name	Deficiency Description	Def Note	System ID	System Name	Uniformed Description	Category Description	Priority	Priority Description	Quantity	Unit	TTL Cost														
211658	Palway Middle School	10	Building 10	The Aluminum Window Is Damaged And Requires Replacement	Awning 6(L) X 3(W)	4	Exterior	Exterior Fixed Windows	Capital Renewal	2	Indirect Impact to Mission (1 Year)	32	SF	\$4,778														
211659	Palway Middle School	10	Building 10	Exterior Door Hardware Requires Replacement		4	Exterior	Exterior Entrance Doors	Deferred Maintenance	3	Short Term Conditions (2-3 Years)	3	Ea.	\$8,549														
211657	Palway Middle School	09	Building 9	The Exterior Requires Painting (Bldg SF)		4	Exterior	Exterior Wall Veneer	Capital Renewal	3	Short Term Conditions (2-3 Years)	4000	SF	\$20,049														
211656	Palway Middle School	09	Building 9	Exterior Door Hardware Requires Replacement		4	Exterior	Exterior Entrance Doors	Deferred Maintenance	3	Short Term Conditions (2-3 Years)	3	Ea.	\$8,549														
211655	Palway Middle School	09	Building 9	The Aluminum Window Is Damaged And Requires Replacement	Awning 6(L) X 3(W)	4	Exterior	Exterior Fixed Windows	Capital Renewal	2	Indirect Impact to Mission (1 Year)	32	SF	\$4,778														
211653	Palway Middle School	08	Building 8	The Exterior Requires Painting		4	Exterior	Exterior Wall Veneer	Capital Renewal	3	Short Term Conditions (2-3 Years)	4000	SF Wall	\$13,499														
211654	Palway Middle School	08	Building 8	Exterior Door Hardware Requires Replacement		4	Exterior	Exterior Entrance Doors	Deferred Maintenance	3	Short Term Conditions (2-3 Years)	6	Ea.	\$17,097														
211652	Palway Middle School	08	Building 8	The Aluminum Window Requires Repair	6(L) X 4(W)	4	Exterior	Exterior Fixed Windows	Deferred Maintenance	3	Short Term Conditions (2-3 Years)	32	Ea.	\$6,530														
211611	Palway Middle School	07	Classroom	The Exterior Requires Painting (Bldg SF)		4	Exterior	Exterior Wall Veneer	Capital Renewal	3	Short Term Conditions (2-3 Years)	4000	SF Wall	\$13,499														
211610	Palway Middle School	07	Classroom	Exterior Door Hardware Requires Replacement		4	Exterior	Exterior Entrance Doors	Deferred Maintenance	3	Short Term Conditions (2-3 Years)	2	Ea.	\$6,889														
211618	Palway Middle School	07	Classroom	The Aluminum Window Requires Repair	6(L) X 3(W)	4	Exterior	Exterior Fixed Windows	Deferred Maintenance	3	Short Term Conditions (2-3 Years)	32	Ea.	\$6,225														
211641	Palway Middle School	06	Building 6	The Exterior Requires Painting (Bldg SF)		4	Exterior	Exterior Wall Veneer	Capital Renewal	3	Short Term Conditions (2-3 Years)	7000	SF	\$36,086														
211642	Palway Middle School	06	Building 6	Exterior Door Hardware Requires Replacement		4	Exterior	Exterior Entrance Doors	Deferred Maintenance	3	Short Term Conditions (2-3 Years)	5	Ea.	\$14,248														
211673	Palway Middle School	05	Building 5	The Exterior Requires Painting (Bldg SF)		4	Exterior	Exterior Wall Veneer	Capital Renewal	3	Short Term Conditions (2-3 Years)	7000	SF	\$36,086														
211675	Palway Middle School	05	Building 5	The Aluminum Window Is Damaged And Requires Replacement	6(L) X 4(W)	4	Exterior	Exterior Fixed Windows	Capital Renewal	2	Indirect Impact to Mission (1 Year)	10	SF	\$1,492														
211700	Palway Middle School	04	Building 4	The Exterior Requires Painting (Bldg SF)		4	Exterior	Exterior Wall Veneer	Capital Renewal	3	Short Term Conditions (2-3 Years)	10000	SF	\$50,120														
211720	Palway Middle School	04	Building 4	The Exterior Requires Painting		4	Exterior	Exterior Wall Veneer	Capital Renewal	3	Short Term Conditions (2-3 Years)	10000	SF Wall	\$50,748														
211726	Palway Middle School	03	Media Center	The Exterior Requires Painting (Bldg SF)		4	Exterior	Exterior Wall Veneer	Capital Renewal	3	Short Term Conditions (2-3 Years)	8000	SF	\$40,099														
211727	Palway Middle School	03	Media Center	Exterior Door Hardware Requires Replacement		4	Exterior	Exterior Entrance Doors	Deferred Maintenance	3	Short Term Conditions (2-3 Years)	2	Door	\$720														
211738	Palway Middle School	03	Media Center	The Exterior Requires Painting		4	Exterior	Exterior Wall Veneer	Capital Renewal	3	Short Term Conditions (2-3 Years)	8000	SF Wall	\$39,496														
211743	Palway Middle School	02	Building 2	The Exterior Requires Painting		4	Exterior	Exterior Wall Veneer	Capital Renewal	3	Short Term Conditions (2-3 Years)	10000	SF Wall	\$50,748														
211744	Palway Middle School	02	Building 2	The Wood Exterior Door Is Damaged And Requires Replacement	7(L) X 2(W)	4	Exterior	Interior Sliding Doors	Capital Renewal	2	Indirect Impact to Mission (1 Year)	5	Door	\$20,836														
211747	Palway Middle School	02	Building 2	Exterior Door Hardware Requires Replacement		4	Exterior	Exterior Entrance Doors	Deferred Maintenance	3	Short Term Conditions (2-3 Years)	13	Ea.	\$37,044														
211748	Palway Middle School	02	Building 2	The Aluminum Window Is Damaged And Requires Replacement	Awning 2(L) X 4(W)	4	Exterior	Exterior Fixed Windows	Capital Renewal	2	Indirect Impact to Mission (1 Year)	31	SF	\$4,626														
211750	Palway Middle School	01	Building 1	The Metal Exterior Door Requires Repair	7(L) X 2(W)	4	Exterior	Exterior Entrance Doors	Deferred Maintenance	3	Short Term Conditions (2-3 Years)	13	Door	\$6,451														
211756	Palway Middle School	01	Building 1	The Aluminum Window Is Damaged And Requires Replacement	5(L) X 2(W)	4	Exterior	Exterior Fixed Windows	Capital Renewal	2	Indirect Impact to Mission (1 Year)	56	SF	\$8,306														
211805	Palway Middle School	01	Building 1	The Exterior Requires Painting		4	Exterior	Exterior Wall Veneer	Capital Renewal	3	Short Term Conditions (2-3 Years)	10000	SF Wall	\$50,748														
213443	Palway Middle School	26	Gymnasium	The Exterior Requires Painting		4	Exterior	Exterior Wall Veneer	Capital Renewal	3	Short Term Conditions (2-3 Years)	20000	SF Wall	\$64,195														

Deficiency Data Grid
Thursday, October 22,
2015 7:34 AM

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29
Def/Assess ID	Site Name	Building Number	Building Name	Deficiency Description	Def Note	System ID	System Name	Uniformed Description	Category Description	Priority	Priority Description	Quantity	Unit	TTL Cost														
224073	Parkway Middle School	01	Building 1	Roofing with new Decking Required (Broward CPS)		2	Roofing	Low-Slope Roofing	Capital Renewal	2	Indirect Impact to Mission (Year)	8124	SF	\$86,946														
224080	Parkway Middle School	02	Building 2	Roofing with new Decking Required (Broward CPS)		2	Roofing	Low-Slope Roofing	Capital Renewal	2	Indirect Impact to Mission (Year)	8902	SF	\$108,314														
224081	Parkway Middle School	03	Media Center	Roofing with new Decking Required (Broward CPS)		2	Roofing	Low-Slope Roofing	Capital Renewal	2	Indirect Impact to Mission (Year)	6435	SF	\$78,297														
224082	Parkway Middle School	04	Building 4	Roofing with new Decking Required (Broward CPS)		2	Roofing	Low-Slope Roofing	Capital Renewal	2	Indirect Impact to Mission (Year)	8300	SF	\$101,364														
224083	Parkway Middle School	05	Building 5	Roofing with new Decking Required (Broward CPS)		2	Roofing	Low-Slope Roofing	Capital Renewal	2	Indirect Impact to Mission (Year)	5081	SF	\$61,822														
224084	Parkway Middle School	06	Building 6	Roofing with new Decking Required (Broward CPS)		2	Roofing	Low-Slope Roofing	Capital Renewal	2	Indirect Impact to Mission (Year)	5492	SF	\$67,918														
224086	Parkway Middle School	07	Classroom	Roofing with new Decking Required (Broward CPS)		2	Roofing	Low-Slope Roofing	Capital Renewal	2	Indirect Impact to Mission (Year)	3348	SF	\$40,736														
224088	Parkway Middle School	08	Building 8	Roofing with new Decking Required (Broward CPS)		2	Roofing	Low-Slope Roofing	Capital Renewal	2	Indirect Impact to Mission (Year)	3263	SF	\$39,702														
224090	Parkway Middle School	09	Building 9	Roofing with new Decking Required (Broward CPS)		2	Roofing	Low-Slope Roofing	Capital Renewal	2	Indirect Impact to Mission (Year)	3244	SF	\$39,471														
224092	Parkway Middle School	10	Building 10	Roofing with new Decking Required (Broward CPS)		2	Roofing	Low-Slope Roofing	Capital Renewal	2	Indirect Impact to Mission (Year)	3965	SF	\$49,377														
224093	Parkway Middle School	12	Building 12	Roofing with new Decking Required (Broward CPS)		2	Roofing	Low-Slope Roofing	Capital Renewal	2	Indirect Impact to Mission (Year)	6325	SF	\$76,969														
224094	Parkway Middle School	13	Building 13	Roofing with new Decking Required (Broward CPS)		2	Roofing	Low-Slope Roofing	Capital Renewal	2	Indirect Impact to Mission (Year)	3474	SF	\$42,289														
224096	Parkway Middle School	14	Building 14	Roofing with new Decking Required (Broward CPS)		2	Roofing	Low-Slope Roofing	Capital Renewal	2	Indirect Impact to Mission (Year)	3408	SF	\$41,442														
224097	Parkway Middle School	15	Building 15	Roofing with new Decking Required (Broward CPS)		2	Roofing	Low-Slope Roofing	Capital Renewal	2	Indirect Impact to Mission (Year)	3382	SF	\$41,187														
224098	Parkway Middle School	16	Building 16	Roofing with new Decking Required (Broward CPS)		2	Roofing	Low-Slope Roofing	Capital Renewal	2	Indirect Impact to Mission (Year)	3408	SF	\$41,442														
224101	Parkway Middle School	17	Building 17	Roofing with new Decking Required (Broward CPS)		2	Roofing	Low-Slope Roofing	Capital Renewal	2	Indirect Impact to Mission (Year)	3348	SF	\$40,712														
224103	Parkway Middle School	18	Building 18	Roofing with new Decking Required (Broward CPS)		2	Roofing	Low-Slope Roofing	Capital Renewal	2	Indirect Impact to Mission (Year)	677	SF	\$8,237														
224105	Parkway Middle School	19	Building 19	Roofing with new Decking Required (Broward CPS)		2	Roofing	Low-Slope Roofing	Capital Renewal	2	Indirect Impact to Mission (Year)	7148	SF	\$86,946														
224106	Parkway Middle School	21	Storage	Roofing with new Decking Required (Broward CPS)		2	Roofing	Low-Slope Roofing	Capital Renewal	2	Indirect Impact to Mission (Year)	172	SF	\$2,089														
224108	Parkway Middle School	23	Building Support	Roofing Required (Broward CPS)		2	Roofing	Low-Slope Roofing	Capital Renewal	2	Indirect Impact to Mission (Year)	18795	SF	\$186,720														
314633	Parkway Middle School			Aluminum Covered Walkways Require Replacement	Originally part of roof replacement. Pured out separate to reflect overhead canopy pricing.	2	Roofing	Canopy Roofing	Capital Renewal	2	Indirect Impact to Mission (Year)	4380	SF	\$38,960														
314634	Parkway Middle School			Aluminum Covered Walkways Require Replacement	Originally part of roof replacement. Pured out separate to reflect overhead canopy pricing.	2	Roofing	Canopy Roofing	Capital Renewal	2	Indirect Impact to Mission (Year)	2297	SF	\$14,139														
314635	Parkway Middle School			Aluminum Covered Walkways Require Replacement	Originally part of roof replacement. Pured out separate to reflect overhead canopy pricing.	2	Roofing	Canopy Roofing	Capital Renewal	2	Indirect Impact to Mission (Year)	561	SF	\$33,946														

Deficiency Data Grid
Thursday, October 22,
2015 7:38 AM

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29
Def/Assess ID	Site Name	Building Number	Building Name	Deficiency Description	Def Note	System ID	System Name	Uniformed Description	Category Description	Priority	Priority Description	Quantity	Unit	TTL Cost														
314539	Parkway Middle School			Aluminum Covered Walkways Require Replacement	Originally part of roof replacement deficiency. Puled out separate to reflect coveredwalk canopy pricing	2	Roofing	Canopy Roofing	Capital Renewal	2	Indirect Impact to Mission (Year)	2273	SF	\$14,016														
314537	Parkway Middle School			Aluminum Covered Walkways Require Replacement	Originally part of roof replacement deficiency. Puled out separate to reflect coveredwalk canopy pricing	2	Roofing	Canopy Roofing	Capital Renewal	2	Indirect Impact to Mission (Year)	2088	SF	\$17,736														
314538	Parkway Middle School			Aluminum Covered Walkways Require Replacement	Originally part of roof replacement deficiency. Puled out separate to reflect coveredwalk canopy pricing	2	Roofing	Canopy Roofing	Capital Renewal	2	Indirect Impact to Mission (Year)	1850	SF	\$9,541														
314539	Parkway Middle School			Aluminum Covered Walkways Require Replacement	Originally part of roof replacement deficiency. Puled out separate to reflect coveredwalk canopy pricing	2	Roofing	Canopy Roofing	Capital Renewal	2	Indirect Impact to Mission (Year)	799	SF	\$4,674														
314540	Parkway Middle School			Aluminum Covered Walkways Require Replacement	Originally part of roof replacement deficiency. Puled out separate to reflect coveredwalk canopy pricing	2	Roofing	Canopy Roofing	Capital Renewal	2	Indirect Impact to Mission (Year)	1363	SF	\$8,390														
314541	Parkway Middle School			Aluminum Covered Walkways Require Replacement	Originally part of roof replacement deficiency. Puled out separate to reflect coveredwalk canopy pricing	2	Roofing	Canopy Roofing	Capital Renewal	2	Indirect Impact to Mission (Year)	2432	SF	\$14,957														
314542	Parkway Middle School			Aluminum Covered Walkways Require Replacement	Originally part of roof replacement deficiency. Puled out separate to reflect coveredwalk canopy pricing	2	Roofing	Canopy Roofing	Capital Renewal	2	Indirect Impact to Mission (Year)	1363	SF	\$8,390														
314543	Parkway Middle School			Aluminum Covered Walkways Require Replacement	Originally part of roof replacement deficiency. Puled out separate to reflect coveredwalk canopy pricing	2	Roofing	Canopy Roofing	Capital Renewal	2	Indirect Impact to Mission (Year)	1367	SF	\$8,310														
314544	Parkway Middle School			Aluminum Covered Walkways Require Replacement	Originally part of roof replacement deficiency. Puled out separate to reflect coveredwalk canopy pricing	2	Roofing	Canopy Roofing	Capital Renewal	2	Indirect Impact to Mission (Year)	1363	SF	\$8,390														
314545	Parkway Middle School			Aluminum Covered Walkways Require Replacement	Originally part of roof replacement deficiency. Puled out separate to reflect coveredwalk canopy pricing	2	Roofing	Canopy Roofing	Capital Renewal	2	Indirect Impact to Mission (Year)	1350	SF	\$8,310														
314546	Parkway Middle School			Aluminum Covered Walkways Require Replacement	Originally part of roof replacement deficiency. Puled out separate to reflect coveredwalk canopy pricing	2	Roofing	Canopy Roofing	Capital Renewal	2	Indirect Impact to Mission (Year)	1363	SF	\$8,390														
315297	Parkway Middle School	03	Media Center	Wood Ceilings requires replacement (condition of room 01)	Room design = 8159616	26	Other	Educational Enhancement Improvements	Capital Renewal	2	Indirect Impact to Mission (Year)	1	LS	\$260,598														
315351	Parkway Middle School	03	Media Center	Provide renovation of restrooms associated with the additional adequacy renovations	Room design = 8159616	26	Other	Educational Enhancement Improvements	Capital Renewal	2	Indirect Impact to Mission (Year)	1	LS	\$68,500														

2.4.5 MAPPS Deficiency Detail

Broward County Public Schools

Deficiency Detail

290 Parkway Middle School

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 22->1st->907-Auditorium**

Deficiency:

Assess ID **65338** Surveyor/Update
Deficiency Code ID **BP20-01**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Install Fire Sprinklers**

Category **Code Compliance** System **Fire and Security**

Priority **1-Mission Critical Concerns** Functional Adequacy **Non Related**

Correction **Install Fire Sprinkler System** Quantity / UoM

Project(s) Note **FY10/11 INSTALL FIRE SPRINKLERS UNDERSOUNDPROOF MATERIAL IN MAIN AUDITORIUM/B#22-F907 *UPD NEEDS TO GO TO FAC PER MARTIN MICHAELS. 1/20/11.....**

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	095123100400	Suspended acoustic ceiling tiles, fiberglass boards, film faced, 2' x 2' or 2' x 4' x 3/4" thick	1,344	SF	2.84	\$3,817
U	090505101200	Ceiling demolition, suspended ceiling, mineral fiber, 2 x 2 or 2 x 4, remove	1,344	SF	0.64	\$860
A	D40104101100	Wet pipe sprinkler systems, steel, ordinary hazard, 1 floor, 50,000 SF	4,838	SF	4.02	\$19,449
Sub Total						\$24,125
Construction Adjustment 35%						8,323
Construction Cost						\$32,449
Adjustment Factor 0%						0
Soft Cost Adjustment 46%						14,790
Total Estimated Amount						\$47,239

Broward County Public Schools

Deficiency Detail

290 Parkway Middle School

1/28/2016 4:04 PM

Location: **Parkway MS->Media Ctr->1st->108-Student Restroom (Male)**

Deficiency:

Assess ID **65339** Surveyor/Update
Deficiency Code ID **BP20-01**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Install Fire Sprinklers**

Category **Code Compliance** System **Fire and Security**

Priority **1-Mission Critical Concerns** Functional Adequacy **Non Related**

Correction **Install Fire Sprinkler System** Quantity / UoM

Project(s) Note **FY10/11 INSTALL FIRE SPRINKLERS IN GROUP RESTROOM/ B# 3-F108*PDM1>AA PER M.MICHAELS 26APR11MM**

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	095123100400	Suspended acoustic ceiling tiles, fiberglass boards, film faced, 2' x 2' or 2' x 4' x 3/4" thick	38	SF	2.84	\$107	
U	090505101200	Ceiling demolition, suspended ceiling, mineral fiber, 2 x 2 or 2 x 4, remove	38	SF	0.64	\$24	
A	D40104101100	Wet pipe sprinkler systems, steel, ordinary hazard, 1 floor, 50,000 SF	136	SF	4.02	\$547	
Sub Total						\$678	
Construction Adjustment						35%	234
Construction Cost						\$912	
Adjustment Factor						0%	0
Soft Cost Adjustment						48%	442
Total Estimated Amount						\$1,354	

Broward County Public Schools

Deficiency Detail

290 Parkway Middle School

1/26/2016 4:04 PM

Location: **Parkway MS->Media Ctr->1st->109-Student Restroom (Female)**

Deficiency:

Assess ID **65340** Surveyor/Update
Deficiency Code ID **BP20-01**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Install Fire Sprinklers**

Category **Code Compliance** System **Fire and Security**

Priority **1-Mission Critical Concerns** Functional Adequacy **Non Related**

Correction **Install Fire Sprinkler System** Quantity / UoM

Project(s) Note **FY10/11 INSTALL FIRE SPRINKLERS IN GROUP RESTROOM/ B# 3-F109*PDM1>AA PER M.MICHAELS 26APR11MM**

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	095123100400	Suspended acoustic ceiling tiles, fiberglass boards, film faced, 2' x 2' or 2' x 4' x 3/4" thick	38	SF	2.84	\$109	
U	090505101200	Ceiling demolition, suspended ceiling, mineral fiber, 2 x 2 or 2 x 4, remove	38	SF	0.64	\$25	
A	D40104101100	Wet pipe sprinkler systems, steel, ordinary hazard, 1 floor, 50,000 SF	138	SF	4.02	\$555	
Sub Total						\$688	
					Construction Adjustment	35%	237
Construction Cost						\$926	
					Adjustment Factor	0%	0
					Soft Cost Adjustment	48%	448
Total Estimated Amount						\$1,374	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 24->1st->431-Inside Circulation**

Deficiency:

Assess ID **65341** Surveyor/Update
Deficiency Code ID **BP20-01**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Install Fire Sprinklers**
Category **Code Compliance** System **Fire and Security**
Priority **1-Mission Critical Concerns** Functional Adequacy **Non Related**
Correction **Install Fire Sprinkler System** Quantity / UoM
Project(s) Note **FY10/11 INSTALL FIRE SPRINKLERS IN GROUP RESTROOM/ B#24-F431*PDM1>AA PER M.MICHAELS 26APR11MM**

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	095123100400	Suspended acoustic ceiling tiles, fiberglass boards, film faced, 2' x 2' or 2' x 4' x 3/4" thick	19	SF	2.84	\$53	
U	090505101200	Ceiling demolition, suspended ceiling, mineral fiber, 2 x 2 or 2 x 4, remove	19	SF	0.64	\$12	
A	D40104101100	Wet pipe sprinkler systems, steel, ordinary hazard, 1 floor, 50,000 SF	67	SF	4.02	\$269	
Sub Total						\$334	
					Construction Adjustment	35%	115
Construction Cost						\$449	
					Adjustment Factor	0%	0
					Soft Cost Adjustment	42%	191
Total Estimated Amount						\$640	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 24->1st->432-Inside Circulation**

Deficiency:

Assess ID **65342** Surveyor/Update
Deficiency Code ID **BP20-01**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Install Fire Sprinklers**

Category **Code Compliance** System **Fire and Security**

Priority **1-Mission Critical Concerns** Functional Adequacy **Non Related**

Correction **Install Fire Sprinkler System** Quantity / UoM

Project(s) Note **FY10/11 INSTALL FIRE SPRINKLERS IN GROUP RESTROOM/ B#24-F432*PDM1>AA PER M.MICHAELS 26APR11MM**

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	095123100400	Suspended acoustic ceiling tiles, fiberglass boards, film faced, 2' x 2' or 2' x 4' x 3/4" thick	19	SF	2.84	\$53
U	090505101200	Ceiling demolition, suspended ceiling, mineral fiber, 2 x 2 or 2 x 4, remove	19	SF	0.64	\$12
A	D40104101100	Wet pipe sprinkler systems, steel, ordinary hazard, 1 floor, 50,000 SF	67	SF	4.02	\$269
Sub Total						\$334
Construction Adjustment					35%	115
Construction Cost						\$449
Adjustment Factor					0%	0
Soft Cost Adjustment					42%	191
Total Estimated Amount						\$640

Broward County Public Schools

Deficiency Detail

290 Parkway Middle School

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 24->2nd->454-Inside Circulation**

Deficiency:

Assess ID **65343** Surveyor/Update
Deficiency Code ID **BP20-01**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Install Fire Sprinklers**

Category **Code Compliance** System **Fire and Security**

Priority **1-Mission Critical Concerns** Functional Adequacy **Non Related**

Correction **Install Fire Sprinkler System** Quantity / UoM

Project(s) Note **FY10/11 INSTALL FIRE SPRINKLERS IN GROUP RESTROOM/ B#24-F454*PDM1>AA PER M.MICHAELS 26APR11MM**

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	095123100400	Suspended acoustic ceiling tiles, fiberglass boards, film faced, 2' x 2' or 2' x 4' x 3/4" thick	19	SF	2.84	\$53
U	090505101200	Ceiling demolition, suspended ceiling, mineral fiber, 2 x 2 or 2 x 4, remove	19	SF	0.64	\$12
A	D40104101100	Wet pipe sprinkler systems, steel, ordinary hazard, 1 floor, 50,000 SF	67	SF	4.02	\$269
Sub Total						\$334
Construction Adjustment					35%	115
Construction Cost						\$449
Adjustment Factor					0%	0
Soft Cost Adjustment					42%	191
Total Estimated Amount						\$640

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 24->2nd->455-Inside Circulation**

Deficiency:

Assess ID **65344** Surveyor/Update
Deficiency Code ID **BP20-01**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Install Fire Sprinklers**

Category **Code Compliance** System **Fire and Security**

Priority **1-Mission Critical Concerns** Functional Adequacy **Non Related**

Correction **Install Fire Sprinkler System** Quantity / UoM

Project(s) Note **FY10/11 INSTALL FIRE SPRINKLERS IN GROUP RESTROOM/ B#24-F455*PDM1>AA PER M.MICHAELS 26APR11MM**

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	095123100400	Suspended acoustic ceiling tiles, fiberglass boards, film faced, 2' x 2' or 2' x 4' x 3/4" thick	19	SF	2.84	\$53
U	090505101200	Ceiling demolition, suspended ceiling, mineral fiber, 2 x 2 or 2 x 4, remove	19	SF	0.64	\$12
A	D40104101100	Wet pipe sprinkler systems, steel, ordinary hazard, 1 floor, 50,000 SF	67	SF	4.02	\$269
Sub Total						\$334
Construction Adjustment					35%	115
Construction Cost						\$449
Adjustment Factor					0%	0
Soft Cost Adjustment					42%	191
Total Estimated Amount						\$640

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 22**

Deficiency:

Assess ID **210950** Surveyor/Update **Sherry Sims**
Deficiency Code ID **M57-02C**
Status **Estimated** FCI **Yes**
Life Cycle **46434**

Deficiency **The Air Handler HVAC Component Requires Replacement**
Category **Capital Renewal** System **Mechanical**
Priority **3-Short Term Conditions (2-3 Years)** Functional Adequacy **Non Related**
Correction **Replace 5000 CFM Air Handler** Quantity / UoM
Project(s) Note **15,000CFM**

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	237313202340	Central station air handling unit, packaged indoor, variable air volume, 5000 CFM, cooling coils may be chilled water or DX, heating coils may be hot water, steam or electric	1	Ea.	26,000.00	\$26,000
U	230505100400	Central station air handler, up thru 15 ton, selective demolition	1	Ea.	820.00	\$820
U	015419500100	Crane crew, daily use for small jobs, 12-ton truck-mounted hydraulic crane, portal to portal	1	Day	1,600.00	\$1,600
U	233113131030	Metal ductwork, fabricated rectangular, 500 to 1000 lb., stainless steel, type 304, includes fittings, joints, supports and allow for a flexible connections field sketches, excludes as-built drawings and insulation	250	Lb	13.40	\$3,350
U	260580101590	Motor connections, flexible conduit and fittings, 3 phase, 460 volt, 100 HP motor	1	Ea.	330.00	\$330
Sub Total						\$32,100
					Construction Adjustment	35% 11,074
Construction Cost						\$43,174
					Adjustment Factor	0% 0
					Soft Cost Adjustment	46% 19,679
Total Estimated Amount						\$62,853

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Bldg Support**

Deficiency:

Assess ID	210969	Surveyor/Update	Sherry Sims
Deficiency Code ID	M57-04C		
Status	Estimated	FCI	Yes
Life Cycle	46519		

Deficiency	The Chiller HVAC Component Is Damaged And Requires Replacement		
Category	Capital Renewal	System	Mechanical
Priority	2-Indirect Impact to Mission (1 Year)	Functional Adequacy	Non Related
Correction	Replace 50 Ton Chiller	Quantity / UoM	
Project(s) Note	2@300=600TonAC		

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	260580101530	Motor connections, flexible conduit and fittings, 3 phase, 460 volt, 25 HP motor	2	Ea.	126.00	\$252	
U	236419101100	Water chiller, reciprocating, multiple compressor, semi-hermetic, water cooled, 50 ton cooling, includes standard controls, excludes water tower	2	Ea.	50,000.00	\$100,000	
U	230505108010	Water chiller, 15 thru 100 ton, selective demolition	2	Ea.	4,250.00	\$8,500	
U	015436502200	Mobilization or demobilization, crane, crawler-mounted, up to 75 ton	2	Ea.	1,125.00	\$2,250	
Sub Total						\$111,002	
					Construction Adjustment	35%	38,296
Construction Cost						\$149,298	
					Adjustment Factor	0%	0
					Soft Cost Adjustment	46%	68,050
Total Estimated Amount						\$217,348	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 19**

Deficiency:

Assess ID	210991	Surveyor/Update	Sherry Sims
Deficiency Code ID	M57-02C		
Status	Estimated	FCI	Yes
Life Cycle	46727		

Deficiency **The Air Handler HVAC Component Requires Replacement**

Category **Capital Renewal** System **Mechanical**

Priority **3-Short Term Conditions (2-3 Years)** Functional Adequacy **Non Related**

Correction **Replace 5000 CFM Air Handler** Quantity / UoM

Project(s) Note **2@2,000=4,000CFM**

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	237313202340	Central station air handling unit, packaged indoor, variable air volume, 5000 CFM, cooling coils may be chilled water or DX, heating coils may be hot water, steam or electric	2	Ea.	26,000.00	\$52,000	
U	230505100400	Central station air handler, up thru 15 ton, selective demolition	2	Ea.	820.00	\$1,640	
U	015419500100	Crane crew, daily use for small jobs, 12-ton truck-mounted hydraulic crane, portal to portal	2	Day	1,600.00	\$3,200	
U	233113131030	Metal ductwork, fabricated rectangular, 500 to 1000 lb., stainless steel, type 304, includes fittings, joints, supports and allow for a flexible connections field sketches, excludes as-built drawings and insulation	500	Lb	13.40	\$6,700	
U	260580101590	Motor connections, flexible conduit and fittings, 3 phase, 460 volt, 100 HP motor	2	Ea.	330.00	\$660	
Sub Total						\$64,200	
					Construction Adjustment	35%	22,149
Construction Cost						\$86,349	
					Adjustment Factor	0%	0
					Soft Cost Adjustment	48%	41,836
Total Estimated Amount						\$128,185	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 19**

Deficiency:

Assess ID	210992	Surveyor/Update	Sherry Sims
Deficiency Code ID	M57-03CW		
Status	Estimated	FCI	Yes
Life Cycle	46724		

Deficiency	The Fan Coil (Chilled Water) HVAC Component Requires Replacement		
Category	Capital Renewal	System	Mechanical
Priority	3-Short Term Conditions (2-3 Years)	Functional Adequacy	Non Related
Correction	Replace Fan Coil - Chilled Water (1/2 ton)	Quantity / UoM	
Project(s) Note	2@3=6TonAC		

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	230505102150	Fan coil air conditioner, chilled water, up thru 7-1/2 ton, selective demolition	2	Ea.	94.00	\$188
U	238219100100	Fan coil A.C., cabinet mounted, chilled water, 1/2 ton cooling, includes filters and controls	2	Ea.	1,050.00	\$2,100
Sub Total						\$2,288
					Construction Adjustment	35% 789
Construction Cost						\$3,077
					Adjustment Factor	0% 0
					Soft Cost Adjustment	48% 1,491
Total Estimated Amount						\$4,568

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 19**

Deficiency:

Assess ID	210993	Surveyor/Update	Sherry Sims
Deficiency Code ID	M57-12c		
Status	Estimated	FCI	Yes
Life Cycle	46723		

Deficiency	The Window AC Unit Component Requires Replacement		
Category	Capital Renewal	System	Mechanical
Priority	3-Short Term Conditions (2-3 Years)	Functional Adequacy	Non Related
Correction	Replace Window AC Unit	Quantity / UoM	
Project(s) Note	2@2Ton		

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	230505108400	Window air conditioner, selective demolition	2	Ea.	37.50	\$75	
U	238119104780	Window/thru-the-wall unit air conditioner, grounded receptacle required, 15 amp 230 V, 18,000 BTUH	2	Ea.	1,200.00	\$2,400	
Sub Total						\$2,475	
					Construction Adjustment	35%	854
Construction Cost						\$3,329	
					Adjustment Factor	0%	0
					Soft Cost Adjustment	48%	1,613
Total Estimated Amount						\$4,942	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 19**

Deficiency:

Assess ID	210994	Surveyor/Update	Sherry Sims
Defecency Code ID	M80-03		
Status	Estimated	FCI	Yes
Life Cycle	46725		

Deficiency	The Mechanical / HVAC Piping / System Is Beyond Its Useful Life		
Category	Deferred Maintenance	System	Mechanical
Priority	3-Short Term Conditions (2-3 Years)	Functional Adequacy	Non Related
Correction	Replace HVAC Piping System (4-Pipe)	Quantity / UoM	

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	220719107568	Insulation, pipe covering (price copper tube one size less than I.P.S.), fiberglass with all service jacket, 2-1/2" wall, 1-1/2" iron pipe size	619	LF	10.60	\$6,559	
U	220719107578	Insulation, pipe covering (price copper tube one size less than I.P.S.), fiberglass with all service jacket, 2-1/2" wall, 4" iron pipe size	124	LF	15.75	\$1,949	
U	221113440590	Pipe, steel, black, threaded, 1-1/4" diameter, schedule 40, Spec. A-53, includes coupling and clevis hanger assembly sized for covering, 10' OC	619	LF	21.00	\$12,995	
U	221113440650	Pipe, steel, black, threaded, 4" diameter, schedule 40, Spec. A-53, includes coupling and clevis hanger assembly sized for covering, 10' OC	124	LF	66.00	\$8,168	
U	024113460100	Selective demolition, steel pipe with insulation, 3/4"-4", excludes excavation	743	LF	4.58	\$3,401	
Sub Total						\$33,073	
					Construction Adjustment	35%	11,410
Construction Cost						\$44,483	
					Adjustment Factor	0%	0
					Soft Cost Adjustment	48%	21,552
Total Estimated Amount						\$66,035	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 1**

Deficiency:

Assess ID	210999	Surveyor/Update	Sherry Sims
Deficiency Code ID	M57-02C		
Status	Estimated	FCI	Yes
Life Cycle	46759		

Deficiency **The Air Handler HVAC Component Requires Replacement**

Category **Capital Renewal** System **Mechanical**

Priority **3-Short Term Conditions (2-3 Years)** Functional Adequacy **Non Related**

Correction **Replace 5000 CFM Air Handler** Quantity / UoM

Project(s) Note **8,000CFM**

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	237313202340	Central station air handling unit, packaged indoor, variable air volume, 5000 CFM, cooling coils may be chilled water or DX, heating coils may be hot water, steam or electric	2	Ea.	26,000.00	\$52,000	
U	230505100400	Central station air handler, up thru 15 ton, selective demolition	2	Ea.	820.00	\$1,640	
U	015419500100	Crane crew, daily use for small jobs, 12-ton truck-mounted hydraulic crane, portal to portal	2	Day	1,600.00	\$3,200	
U	233113131030	Metal ductwork, fabricated rectangular, 500 to 1000 lb., stainless steel, type 304, includes fittings, joints, supports and allow for a flexible connections field sketches, excludes as-built drawings and insulation	500	Lb	13.40	\$6,700	
U	260580101590	Motor connections, flexible conduit and fittings, 3 phase, 460 volt, 100 HP motor	2	Ea.	330.00	\$660	
Sub Total						\$64,200	
					Construction Adjustment	35%	22,149
Construction Cost						\$86,349	
					Adjustment Factor	0%	0
					Soft Cost Adjustment	48%	41,836
Total Estimated Amount						\$128,185	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 1**

Deficiency:

Assess ID **211002** Surveyor/Update **Sherry Sims**
Deficiency Code ID **M57-02C**
Status **Estimated** FCI **Yes**
Life Cycle **46760**

Deficiency **The Air Handler HVAC Component Requires Replacement**
Category **Capital Renewal** System **Mechanical**
Priority **3-Short Term Conditions (2-3 Years)** Functional Adequacy **Non Related**
Correction **Replace 5000 CFM Air Handler** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	237313202340	Central station air handling unit, packaged indoor, variable air volume, 5000 CFM, cooling coils may be chilled water or DX, heating coils may be hot water, steam or electric	1	Ea.	26,000.00	\$26,000
U	230505100400	Central station air handler, up thru 15 ton, selective demolition	1	Ea.	820.00	\$820
U	015419500100	Crane crew, daily use for small jobs, 12-ton truck-mounted hydraulic crane, portal to portal	1	Day	1,600.00	\$1,600
U	233113131030	Metal ductwork, fabricated rectangular, 500 to 1000 lb., stainless steel, type 304, includes fittings, joints, supports and allow for a flexible connections field sketches, excludes as-built drawings and insulation	250	Lb	13.40	\$3,350
U	260580101590	Motor connections, flexible conduit and fittings, 3 phase, 460 volt, 100 HP motor	1	Ea.	330.00	\$330
Sub Total						\$32,100
					Construction Adjustment	35% 11,074
Construction Cost						\$43,174
					Adjustment Factor	0% 0
					Soft Cost Adjustment	48% 20,918
Total Estimated Amount						\$64,093

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Bldg 2**

Deficiency:

Assess ID **211005** Surveyor/Update **Sherry Sims**
Deficiency Code ID **M51-01**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Complete Kitchen HVAC Installation For Non-Air-Conditioned Facility**
Category **Functional Deficiency** System **Mechanical**
Priority **2-Indirect Impact to Mission (1 Year)** Functional Adequacy **Non Related**
Correction **Add Air Conditioning To Food Service Area.** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
A	D30501703760	Split system, air cooled condensing unit, restaurants, 1,000 SF, 5.00 ton	2,500	SF	15.40	\$38,500
Sub Total						\$38,500
Construction Adjustment						35% 13,282
Construction Cost						\$51,782
Adjustment Factor						0% 0
Soft Cost Adjustment						48% 25,089
Total Estimated Amount						\$76,871

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 2**

Deficiency:

Assess ID	211006	Surveyor/Update	Sherry Sims
Deficiency Code ID	M57-02C		
Status	Estimated	FCI	Yes
Life Cycle	46790		

Deficiency	The Air Handler HVAC Component Requires Replacement		
Category	Capital Renewal	System	Mechanical
Priority	3-Short Term Conditions (2-3 Years)	Functional Adequacy	Non Related
Correction	Replace 5000 CFM Air Handler	Quantity / UoM	
Project(s) Note	1@5,000=5,000TonAC		

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	237313202340	Central station air handling unit, packaged indoor, variable air volume, 5000 CFM, cooling coils may be chilled water or DX, heating coils may be hot water, steam or electric	1	Ea.	26,000.00	\$26,000
U	230505100400	Central station air handler, up thru 15 ton, selective demolition	1	Ea.	820.00	\$820
U	015419500100	Crane crew, daily use for small jobs, 12-ton truck-mounted hydraulic crane, portal to portal	1	Day	1,600.00	\$1,600
U	233113131030	Metal ductwork, fabricated rectangular, 500 to 1000 lb., stainless steel, type 304, includes fittings, joints, supports and allow for a flexible connections field sketches, excludes as-built drawings and insulation	250	Lb	13.40	\$3,350
U	260580101590	Motor connections, flexible conduit and fittings, 3 phase, 460 volt, 100 HP motor	1	Ea.	330.00	\$330
Sub Total						\$32,100
					Construction Adjustment	35% 11,074
Construction Cost						\$43,174
					Adjustment Factor	0% 0
					Soft Cost Adjustment	48% 20,918
Total Estimated Amount						\$64,093

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Bldg 2**

Deficiency:

Assess ID	211007	Surveyor/Update	Sherry Sims
Deficiency Code ID	M57-21c		
Status	Estimated	FCI	Yes
Life Cycle			

Deficiency	Duct Heater Requires Replacement		
Category	Capital Renewal	System	Mechanical
Priority	3-Short Term Conditions (2-3 Years)	Functional Adequacy	Learning Environment
Correction	Replace Duct Heater	Quantity / UoM	

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	238216200360	Duct heater, electric, finned tubular insert, 480 V, 3Ph., 500Deg.F, 26.7 kW, 12" wide x 24" high	1	Ea.	2,825.00	\$2,825
U	230505101850	Air conditioner, duct heater, electric strip, selective demolition, minimum labor/equipment charge	1	Job	161.00	\$161
Sub Total						\$2,986
					Construction Adjustment	35% 1,030
Construction Cost						\$4,016
					Adjustment Factor	0% 0
					Soft Cost Adjustment	48% 1,946
Total Estimated Amount						\$5,962

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Media Ctr**

Deficiency:

Assess ID **211015** Surveyor/Update **Sherry Sims**
Deficiency Code ID **M57-02C**
Status **Estimated** FCI **Yes**
Life Cycle **46804**

Deficiency **The Air Handler HVAC Component Requires Replacement**
Category **Capital Renewal** System **Mechanical**
Priority **3-Short Term Conditions (2-3 Years)** Functional Adequacy **Non Related**
Correction **Replace 5000 CFM Air Handler** Quantity / UoM
Project(s) Note **1@5,000=5,000CFM**

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	237313202340	Central station air handling unit, packaged indoor, variable air volume, 5000 CFM, cooling coils may be chilled water or DX, heating coils may be hot water, steam or electric	1	Ea.	26,000.00	\$26,000
U	230505100400	Central station air handler, up thru 15 ton, selective demolition	1	Ea.	820.00	\$820
U	015419500100	Crane crew, daily use for small jobs, 12-ton truck-mounted hydraulic crane, portal to portal	1	Day	1,600.00	\$1,600
U	233113131030	Metal ductwork, fabricated rectangular, 500 to 1000 lb., stainless steel, type 304, includes fittings, joints, supports and allow for a flexible connections field sketches, excludes as-built drawings and insulation	250	Lb	13.40	\$3,350
U	260580101590	Motor connections, flexible conduit and fittings, 3 phase, 460 volt, 100 HP motor	1	Ea.	330.00	\$330
Sub Total						\$32,100
					Construction Adjustment	35% 11,074
Construction Cost						\$43,174
					Adjustment Factor	0% 0
					Soft Cost Adjustment	48% 20,918
Total Estimated Amount						\$64,093

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 5**

Deficiency:

Assess ID **211037** Surveyor/Update **Sherry Sims**
Deficiency Code ID **M23-03**
Status **Estimated** FCI **Yes**
Life Cycle **46853**

Deficiency **The Roof Air Handler/Exhaust is Damaged And Requires Replacement**
Category **Capital Renewal** System **Mechanical**
Priority **2-Indirect Impact to Mission (1 Year)** Functional Adequacy **Non Related**
Correction **Replace Rooftop Air Handler/Exhaust** Quantity / UoM
Project(s) Note **2@5,000=10,000CFM**

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	237433101200	Rooftop air conditioner, single zone, electric cool, gas heat, 20 ton cooling, 360 MBH heating, includes, standard controls, curb and economizer	0	Ea.	30,300.00	\$3,030	
M	015433602500	Rent crane truck mounted, hydraulic, 25 ton capacity	0	Day	615.31	\$62	
U	260580102055	Motor connections, flexible conduit and fittings, 3 phase, sealtite, 460 volt, 150 HP motor	0	Ea.	480.00	\$96	
U	230505109000	HVAC, selective demolition, minimum labor/equipment charge	0	Job	680.00	\$136	
Sub Total						\$3,324	
					Construction Adjustment	35%	1,147
Construction Cost						\$4,470	
					Adjustment Factor	0%	0
					Soft Cost Adjustment	48%	2,166
Total Estimated Amount						\$6,636	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 5**

Deficiency:

Assess ID **211039** Surveyor/Update **Sherry Sims**
Deficiency Code ID **M57-02C**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **The Air Handler HVAC Component Requires Replacement**
Category **Capital Renewal** System **Mechanical**
Priority **3-Short Term Conditions (2-3 Years)** Functional Adequacy **Non Related**
Correction **Replace 5000 CFM Air Handler** Quantity / UoM
Project(s) Note **2@5,000=10,000CFM**

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	237313202340	Central station air handling unit, packaged indoor, variable air volume, 5000 CFM, cooling coils may be chilled water or DX, heating coils may be hot water, steam or electric	2	Ea.	26,000.00	\$52,000	
U	230505100400	Central station air handler, up thru 15 ton, selective demolition	2	Ea.	820.00	\$1,640	
U	015419500100	Crane crew, daily use for small jobs, 12-ton truck-mounted hydraulic crane, portal to portal	2	Day	1,600.00	\$3,200	
U	233113131030	Metal ductwork, fabricated rectangular, 500 to 1000 lb., stainless steel, type 304, includes fittings, joints, supports and allow for a flexible connections field sketches, excludes as-built drawings and insulation	500	Lb	13.40	\$6,700	
U	260580101590	Motor connections, flexible conduit and fittings, 3 phase, 460 volt, 100 HP motor	2	Ea.	330.00	\$660	
Sub Total						\$64,200	
					Construction Adjustment	35%	22,149
Construction Cost						\$86,349	
					Adjustment Factor	0%	0
					Soft Cost Adjustment	48%	41,836
Total Estimated Amount						\$128,185	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 6**

Deficiency:

Assess ID **211046** Surveyor/Update **Sherry Sims**
Deficiency Code ID **M57-02C**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **The Air Handler HVAC Component Requires Replacement**
Category **Capital Renewal** System **Mechanical**
Priority **3-Short Term Conditions (2-3 Years)** Functional Adequacy **Non Related**
Correction **Replace 5000 CFM Air Handler** Quantity / UoM
Project(s) Note **1@10,000=10,000CFM**

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	237313202340	Central station air handling unit, packaged indoor, variable air volume, 5000 CFM, cooling coils may be chilled water or DX, heating coils may be hot water, steam or electric	1	Ea.	26,000.00	\$26,000
U	230505100400	Central station air handler, up thru 15 ton, selective demolition	1	Ea.	820.00	\$820
U	015419500100	Crane crew, daily use for small jobs, 12-ton truck-mounted hydraulic crane, portal to portal	1	Day	1,600.00	\$1,600
U	233113131030	Metal ductwork, fabricated rectangular, 500 to 1000 lb., stainless steel, type 304, includes fittings, joints, supports and allow for a flexible connections field sketches, excludes as-built drawings and insulation	250	Lb	13.40	\$3,350
U	260580101590	Motor connections, flexible conduit and fittings, 3 phase, 460 volt, 100 HP motor	1	Ea.	330.00	\$330
Sub Total						\$32,100
					Construction Adjustment	35% 11,074
Construction Cost						\$43,174
					Adjustment Factor	0% 0
					Soft Cost Adjustment	48% 20,918
Total Estimated Amount						\$64,093

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 6**

Deficiency:

Assess ID **211050** Surveyor/Update **Sherry Sims**
Deficiency Code ID **M23-03**
Status **Estimated** FCI **Yes**
Life Cycle **46872**

Deficiency **The Roof Air Handler/Exhaust is Damaged And Requires Replacement**
Category **Capital Renewal** System **Mechanical**
Priority **2-Indirect Impact to Mission (1 Year)** Functional Adequacy **Non Related**
Correction **Replace Rooftop Air Handler/Exhaust** Quantity / UoM
Project(s) Note **1@10,000=10,000CFM**

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	237433101200	Rooftop air conditioner, single zone, electric cool, gas heat, 20 ton cooling, 360 MBH heating, includes, standard controls, curb and economizer	0	Ea.	30,300.00	\$1,515	
M	015433602500	Rent crane truck mounted, hydraulic, 25 ton capacity	0	Day	615.31	\$31	
U	260580102055	Motor connections, flexible conduit and fittings, 3 phase, sealtite, 460 volt, 150 HP motor	0	Ea.	480.00	\$48	
U	230505109000	HVAC, selective demolition, minimum labor/equipment charge	0	Job	680.00	\$68	
Sub Total						\$1,662	
					Construction Adjustment	35%	573
Construction Cost						\$2,235	
					Adjustment Factor	0%	0
					Soft Cost Adjustment	48%	1,083
Total Estimated Amount						\$3,318	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->CR**

Deficiency:

Assess ID	211061	Surveyor/Update	Sherry Sims
Deficiency Code ID	M57-03CW		
Status	Estimated	FCI	Yes
Life Cycle	46889		

Deficiency	The Fan Coil (Chilled Water) HVAC Component Requires Replacement		
Category	Capital Renewal	System	Mechanical
Priority	3-Short Term Conditions (2-3 Years)	Functional Adequacy	Non Related
Correction	Replace Fan Coil - Chilled Water (1/2 ton) Quantity / UoM		
Project(s) Note	6@3=18TonAC		

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	230505102150	Fan coil air conditioner, chilled water, up thru 7-1/2 ton, selective demolition	6	Ea.	94.00	\$564	
U	238219100100	Fan coil A.C., cabinet mounted, chilled water, 1/2 ton cooling, includes filters and controls	6	Ea.	1,050.00	\$6,300	
Sub Total						\$6,864	
					Construction Adjustment	35%	2,368
Construction Cost						\$9,232	
					Adjustment Factor	0%	0
					Soft Cost Adjustment	48%	4,473
Total Estimated Amount						\$13,705	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 8**

Deficiency:

Assess ID	211069	Surveyor/Update	Sherry Sims
Deficiency Code ID	M57-03CW		
Status	Estimated	FCI	Yes
Life Cycle	46892		

Deficiency	The Fan Coil (Chilled Water) HVAC Component Requires Replacement		
Category	Capital Renewal	System	Mechanical
Priority	3-Short Term Conditions (2-3 Years)	Functional Adequacy	Non Related
Correction	Replace Fan Coil - Chilled Water (1/2 ton) Quantity / UoM		
Project(s) Note	5@3=15TonAC		

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	230505102150	Fan coil air conditioner, chilled water, up thru 7-1/2 ton, selective demolition	5	Ea.	94.00	\$470
U	238219100100	Fan coil A.C., cabinet mounted, chilled water, 1/2 ton cooling, includes filters and controls	5	Ea.	1,050.00	\$5,250
Sub Total						\$5,720
Construction Adjustment					35%	1,973
Construction Cost						\$7,693
Adjustment Factor					0%	0
Soft Cost Adjustment					48%	3,727
Total Estimated Amount						\$11,421

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 9**

Deficiency:

Assess ID	211077	Surveyor/Update	Sherry Sims
Deficiency Code ID	M57-03CW		
Status	Estimated	FCI	Yes
Life Cycle	46916		

Deficiency	The Fan Coil (Chilled Water) HVAC Component Requires Replacement		
Category	Capital Renewal	System	Mechanical
Priority	3-Short Term Conditions (2-3 Years)	Functional Adequacy	Non Related
Correction	Replace Fan Coil - Chilled Water (1/2 ton)	Quantity / UoM	
Project(s) Note	4@3=12TonAC		

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	230505102150	Fan coil air conditioner, chilled water, up thru 7-1/2 ton, selective demolition	4	Ea.	94.00	\$376	
U	238219100100	Fan coil A.C., cabinet mounted, chilled water, 1/2 ton cooling, includes filters and controls	4	Ea.	1,050.00	\$4,200	
Sub Total						\$4,576	
					Construction Adjustment	35%	1,579
					Construction Cost		\$6,155
					Adjustment Factor	0%	0
					Soft Cost Adjustment	48%	2,982
					Total Estimated Amount		\$9,137

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 10**

Deficiency:

Assess ID	211095	Surveyor/Update	Sherry Sims
Deficiency Code ID	M57-03CW		
Status	Estimated	FCI	Yes
Life Cycle	46937		

Deficiency	The Fan Coil (Chilled Water) HVAC Component Requires Replacement		
Category	Capital Renewal	System	Mechanical
Priority	3-Short Term Conditions (2-3 Years)	Functional Adequacy	Non Related
Correction	Replace Fan Coil - Chilled Water (1/2 ton)	Quantity / UoM	
Project(s) Note	4@3=12TonAC		

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	230505102150	Fan coil air conditioner, chilled water, up thru 7-1/2 ton, selective demolition	4	Ea.	94.00	\$376	
U	238219100100	Fan coil A.C., cabinet mounted, chilled water, 1/2 ton cooling, includes filters and controls	4	Ea.	1,050.00	\$4,200	
Sub Total						\$4,576	
					Construction Adjustment	35%	1,579
					Construction Cost		\$6,155
					Adjustment Factor	0%	0
					Soft Cost Adjustment	48%	2,982
					Total Estimated Amount		\$9,137

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Bldg 12**

Deficiency:

Assess ID	211102	Surveyor/Update	Sherry Sims
Deficiency Code ID	M57-03CW		
Status	Estimated	FCI	Yes
Life Cycle	46978		

Deficiency	The Fan Coil (Chilled Water) HVAC Component Requires Replacement		
Category	Capital Renewal	System	Mechanical
Priority	3-Short Term Conditions (2-3 Years)	Functional Adequacy	Non Related
Correction	Replace Fan Coil - Chilled Water (1/2 ton)	Quantity / UoM	
Project(s) Note	7@3=21TonAC		

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	230505102150	Fan coil air conditioner, chilled water, up thru 7-1/2 ton, selective demolition	7	Ea.	94.00	\$658	
U	238219100100	Fan coil A.C., cabinet mounted, chilled water, 1/2 ton cooling, includes filters and controls	7	Ea.	1,050.00	\$7,350	
Sub Total						\$8,008	
					Construction Adjustment	35%	2,763
Construction Cost						\$10,771	
					Adjustment Factor	0%	0
					Soft Cost Adjustment	46%	4,909
Total Estimated Amount						\$15,680	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 13**

Deficiency:

Assess ID	211117	Surveyor/Update	Sherry Sims
Deficiency Code ID	M57-03CW		
Status	Estimated	FCI	Yes
Life Cycle	46987		

Deficiency	The Fan Coil (Chilled Water) HVAC Component Requires Replacement		
Category	Capital Renewal	System	Mechanical
Priority	3-Short Term Conditions (2-3 Years)	Functional Adequacy	Non Related
Correction	Replace Fan Coil - Chilled Water (1/2 ton)	Quantity / UoM	
Project(s) Note	6@3-18TonAC		

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	230505102150	Fan coil air conditioner, chilled water, up thru 7-1/2 ton, selective demolition	6	Ea.	94.00	\$564	
U	238219100100	Fan coil A.C., cabinet mounted, chilled water, 1/2 ton cooling, includes filters and controls	6	Ea.	1,050.00	\$6,300	
Sub Total						\$6,864	
					Construction Adjustment	35%	2,368
Construction Cost						\$9,232	
					Adjustment Factor	0%	0
					Soft Cost Adjustment	48%	4,473
Total Estimated Amount						\$13,705	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 14**

Deficiency:

Assess ID	211128	Surveyor/Update	Sherry Sims
Deficiency Code ID	M57-03CW		
Status	Estimated	FCI	Yes
Life Cycle	47001		

Deficiency	The Fan Coil (Chilled Water) HVAC Component Requires Replacement		
Category	Capital Renewal	System	Mechanical
Priority	3-Short Term Conditions (2-3 Years)	Functional Adequacy	Non Related
Correction	Replace Fan Coil - Chilled Water (1/2 ton) Quantity / UoM		
Project(s) Note	4@3=12TonAC		

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	230505102150	Fan coil air conditioner, chilled water, up thru 7-1/2 ton, selective demolition	4	Ea.	94.00	\$376	
U	238219100100	Fan coil A.C., cabinet mounted, chilled water, 1/2 ton cooling, includes filters and controls	4	Ea.	1,050.00	\$4,200	
Sub Total						\$4,576	
					Construction Adjustment	35%	1,579
Construction Cost						\$6,155	
					Adjustment Factor	0%	0
					Soft Cost Adjustment	48%	2,982
Total Estimated Amount						\$9,137	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 15**

Deficiency:

Assess ID	211138	Surveyor/Update	Sherry Sims
Deficiency Code ID	M57-03CW		
Status	Estimated	FCI	Yes
Life Cycle	47025		

Deficiency	The Fan Coil (Chilled Water) HVAC Component Requires Replacement		
Category	Capital Renewal	System	Mechanical
Priority	3-Short Term Conditions (2-3 Years)	Functional Adequacy	Non Related
Correction	Replace Fan Coil - Chilled Water (1/2 ton)	Quantity / UoM	
Project(s) Note	4@3=12TonAC		

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	230505102150	Fan coil air conditioner, chilled water, up thru 7-1/2 ton, selective demolition	4	Ea.	94.00	\$376	
U	238219100100	Fan coil A.C., cabinet mounted, chilled water, 1/2 ton cooling, includes filters and controls	4	Ea.	1,050.00	\$4,200	
Sub Total						\$4,576	
					Construction Adjustment	35%	1,579
Construction Cost						\$6,155	
					Adjustment Factor	0%	0
					Soft Cost Adjustment	48%	2,982
Total Estimated Amount						\$9,137	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 16**

Deficiency:

Assess ID	211139	Surveyor/Update	Sherry Sims
Deficiency Code ID	M57-03CW		
Status	Estimated	FCI	Yes
Life Cycle	47032		

Deficiency	The Fan Coil (Chilled Water) HVAC Component Requires Replacement		
Category	Capital Renewal	System	Mechanical
Priority	3-Short Term Conditions (2-3 Years)	Functional Adequacy	Non Related
Correction	Replace Fan Coil - Chilled Water (1/2 ton) Quantity / UoM		
Project(s) Note	4@3=12TonAC		

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	230505102150	Fan coil air conditioner, chilled water, up thru 7-1/2 ton, selective demolition	4	Ea.	94.00	\$376	
U	238219100100	Fan coil A.C., cabinet mounted, chilled water, 1/2 ton cooling, includes filters and controls	4	Ea.	1,050.00	\$4,200	
Sub Total						\$4,576	
					Construction Adjustment	35%	1,579
Construction Cost						\$6,155	
					Adjustment Factor	0%	0
					Soft Cost Adjustment	48%	2,982
Total Estimated Amount						\$9,137	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Bldg 17**

Deficiency:

Assess ID	211141	Surveyor/Update	Sherry Sims
Deficiency Code ID	M57-03CW		
Status	Estimated	FCI	Yes
Life Cycle	47039		

Deficiency	The Fan Coil (Chilled Water) HVAC Component Requires Replacement		
Category	Capital Renewal	System	Mechanical
Priority	3-Short Term Conditions (2-3 Years)	Functional Adequacy	Non Related
Correction	Replace Fan Coil - Chilled Water (1/2 ton)	Quantity / UoM	
Project(s) Note	6@3=18TonAC		

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	230505102150	Fan coil air conditioner, chilled water, up thru 7-1/2 ton, selective demolition	3	Ea.	94.00	\$282	
U	238219100100	Fan coil A.C., cabinet mounted, chilled water, 1/2 ton cooling, includes filters and controls	3	Ea.	1,050.00	\$3,150	
Sub Total						\$3,432	
					Construction Adjustment	35%	1,184
Construction Cost						\$4,616	
					Adjustment Factor	0%	0
					Soft Cost Adjustment	48%	2,236
Total Estimated Amount						\$6,853	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 25**

Deficiency:

Assess ID **211146** Surveyor/Update **Sherry Sims**
Deficiency Code ID **A26-01**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **The Exterior Requires Painting**

Category **Capital Renewal** System **Exterior**

Priority **3-Short Term Conditions (2-3 Years)** Functional Adequacy **Non Related**

Correction **Paint Building Exterior** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	099123528400	Paints & coatings, miscellaneous interior, cornice, ornate design, paint 1 coat, oil base, brushwork	8,267	SF	1.57	\$12,979
U	099113601800	Paints & coatings, siding, exterior, Texture 1-111 or clapboard, oil base, primer coat, brushwork	56,000	SF	0.93	\$52,080
U	099103300080	Surface preparation, exterior, doors, per side, wire brush, metal, flush, excl. frames or trim	56,000	SF	0.79	\$44,240
Sub Total						\$109,299
Construction Adjustment						35% 37,708
Construction Cost						\$147,007
Adjustment Factor						0% 0
Soft Cost Adjustment						42% 62,390
Total Estimated Amount						\$209,396

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Bldg Support**

Deficiency:

Assess ID **211237** Surveyor/Update **Sherry Sims**
Deficiency Code ID **A45-03**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Exterior Door Hardware Requires Replacement**
Category **Deferred Maintenance** System **Exterior**
Priority **3-Short Term Conditions (2-3 Years)** Functional Adequacy **Non Related**
Correction **Replace exterior door with ADA compliant hardware** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	080505105585	Door demolition, panic device, remove	2	Ea.	48.00	\$96	
U	087120152250	Door hardware, school, single, exterior, incl. lever, panic device	2	Door	1,600.00	\$3,200	
Sub Total						\$3,296	
					Construction Adjustment	35%	1,137
					Construction Cost		\$4,433
					Adjustment Factor	0%	0
					Soft Cost Adjustment	46%	2,021
					Total Estimated Amount		\$6,454

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Bldg 22**

Deficiency:

Assess ID **211249** Surveyor/Update **Sherry Sims**
Deficiency Code ID **A45-03**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Exterior Door Hardware Requires Replacement**
Category **Deferred Maintenance** System **Exterior**
Priority **3-Short Term Conditions (2-3 Years)** Functional Adequacy **Non Related**
Correction **Replace exterior door with ADA compliant hardware** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	080505105585	Door demolition, panic device, remove	6	Ea.	48.00	\$288	
U	087120152250	Door hardware, school, single, exterior, incl. lever, panic device	6	Door	1,600.00	\$9,600	
Sub Total						\$9,888	
					Construction Adjustment	35%	3,411
					Construction Cost		\$13,299
					Adjustment Factor	0%	0
					Soft Cost Adjustment	46%	6,062
Total Estimated Amount						\$19,361	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Bldg 22**

Deficiency:

Assess ID **211252** Surveyor/Update **Sherry Sims**
Deficiency Code ID **A40-03**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **The Aluminum Window Is Damaged And Requires Replacement**
Category **Capital Renewal** System **Exterior**
Priority **2-Indirect Impact to Mission (1 Year)** Functional Adequacy **Non Related**
Correction **Replace Aluminum Frame Window** Quantity / UoM
Project(s) Note **5"(L) X 6"(W)**

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	062213506000	Moldings, window & door, window trim sets, 2-1/2" wide, maximum	1	OPNG	169.00	\$99	
U	085113203920	Windows, aluminum, commercial grade, stock units, awning type, insulating glass, 3'-0" x 4'-0" opening, incl. frame and glazing	1	Ea.	770.00	\$449	
U	080505200280	Window demolition, aluminum, to 50 S.F.	1	Ea.	96.50	\$56	
Sub Total						\$604	
					Construction Adjustment	35%	208
Construction Cost						\$812	
					Adjustment Factor	0%	0
					Soft Cost Adjustment	46%	370
Total Estimated Amount						\$1,183	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 19**

Deficiency:

Assess ID	211287	Surveyor/Update	Sherry Sims
Deficiency Code ID	A26-01		
Status	Estimated	FCI	Yes
Life Cycle	47372		

Deficiency **The Exterior Requires Painting**

Category	Capital Renewal	System	Exterior
----------	------------------------	--------	-----------------

Priority	3-Short Term Conditions (2-3 Years)	Functional Adequacy	Non Related
----------	--	---------------------	--------------------

Correction	Paint Building Exterior	Quantity / UoM	
------------	--------------------------------	----------------	--

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	099123528400	Paints & coatings, miscellaneous interior, cornice, ornate design, paint 1 coat, oil base, brushwork	1,476	SF	1.57	\$2,318
U	099113601800	Paints & coatings, siding, exterior, Texture 1-111 or clapboard, oil base, primer coat, brushwork	10,000	SF	0.93	\$9,300
U	099103300080	Surface preparation, exterior, doors, per side, wire brush, metal, flush, excl. frames or trim	10,000	SF	0.79	\$7,900
Sub Total						\$19,518
					Construction Adjustment	35% 6,734
Construction Cost						\$26,251
					Adjustment Factor	0% 0
					Soft Cost Adjustment	48% 12,719
Total Estimated Amount						\$38,970

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Bldg 19**

Deficiency:

Assess ID	211290	Surveyor/Update	Sherry Sims
Deficiency Code ID	A35-03		
Status	Estimated	FCI	Yes
Life Cycle	47375		

Deficiency	The Wood Exterior Door Is Damaged And Requires Replacement		
Category	Capital Renewal	System	Exterior
Priority	2-Indirect Impact to Mission (1 Year)	Functional Adequacy	Non Related
Correction	Replace Wood Exterior Door	Quantity / UoM	
Project(s) Note	7"(L) X 3"(W)		

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	081313131360	Doors, commercial, steel, flush, half glass, hollow core, hollow metal, 18 ga., 3'-0" x 7'-0" x 1-3/4" thick	2	Ea.	780.00	\$1,560	
U	087120152250	Door hardware, school, single, exterior, incl. lever, panic device	2	Door	1,600.00	\$3,200	
U	080505100200	Door demolition, exterior door, single, 3' x 7' high, 1-3/4" thick, remove	2	Ea.	30.00	\$60	
Sub Total						\$4,820	
					Construction Adjustment	35%	1,663
Construction Cost						\$6,483	
					Adjustment Factor	0%	0
					Soft Cost Adjustment	48%	3,141
Total Estimated Amount						\$9,624	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Bldg 19**

Deficiency:

Assess ID **211292** Surveyor/Update **Sherry Sims**
Deficiency Code ID **A36-02**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **The Metal Exterior Door Requires Repair**
Category **Deferred Maintenance** System **Exterior**
Priority **3-Short Term Conditions (2-3 Years)** Functional Adequacy **Non Related**
Correction **Repair Metal Exterior Door** Quantity / UoM
Project(s) Note **7"(L) X 3"(W)**

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	099103409010	Surface preparation, interior, minimum labor/equipment charge	3	Job	169.00	\$423
U	099123339900	Paints & coatings, doors & windows, interior, alkyd (oil base), minimum labor/equipment charge	3	Job	254.00	\$635
U	081313209000	Doors, minimum labor/equipment charge	3	Job	151.00	\$378
Sub Total						\$1,435
					Construction Adjustment	35% 495
Construction Cost						\$1,930
					Adjustment Factor	0% 0
					Soft Cost Adjustment	48% 935
Total Estimated Amount						\$2,865

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Bldg 19**

Deficiency:

Assess ID **211294** Surveyor/Update **Sherry Sims**
Deficiency Code ID **A45-03**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Exterior Door Hardware Requires Replacement**
Category **Deferred Maintenance** System **Exterior**
Priority **3-Short Term Conditions (2-3 Years)** Functional Adequacy **Non Related**
Correction **Replace exterior door with ADA compliant hardware** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	080505105585	Door demolition, panic device, remove	2	Ea.	48.00	\$96	
U	087120152250	Door hardware, school, single, exterior, incl. lever, panic device	2	Door	1,600.00	\$3,200	
Sub Total						\$3,296	
					Construction Adjustment	35%	1,137
					Construction Cost		\$4,433
					Adjustment Factor	0%	0
					Soft Cost Adjustment	48%	2,148
					Total Estimated Amount		\$6,581

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Bldg 19**

Deficiency:

Assess ID	211296	Surveyor/Update	Sherry Sims
Deficiency Code ID	A40-03		
Status	Estimated	FCI	Yes
Life Cycle	47374		

Deficiency	The Aluminum Window Is Damaged And Requires Replacement		
Category	Capital Renewal	System	Exterior
Priority	2-Indirect Impact to Mission (1 Year)	Functional Adequacy	Non Related
Correction	Replace Aluminum Frame Window	Quantity / UoM	
Project(s) Note	3"(L) X 4"(W)		

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	062213506000	Moldings, window & door, window trim sets, 2-1/2" wide, maximum	6	OPNG	169.00	\$958	
U	085113203920	Windows, aluminum, commercial grade, stock units, awning type, insulating glass, 3'-0" x 4'-0" opening, incl. frame and glazing	6	Ea.	770.00	\$4,363	
U	080505200280	Window demolition, aluminum, to 50 S.F.	6	Ea.	96.50	\$547	
Sub Total						\$5,868	
					Construction Adjustment	35%	2,024
Construction Cost						\$7,892	
					Adjustment Factor	0%	0
					Soft Cost Adjustment	48%	3,824
Total Estimated Amount						\$11,716	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS**

Deficiency:

Assess ID	211318	Surveyor/Update	Sherry Sims
Deficiency Code ID	A14-02		
Status	Estimated	FCI	Yes
Life Cycle	47401		

Deficiency **Aluminum Covered Walkways Require Replacement**

Category	Capital Renewal	System	Roofing
----------	------------------------	--------	----------------

Priority	3-Short Term Conditions (2-3 Years)	Functional Adequacy	Non Related
----------	--	---------------------	--------------------

Correction	Replace Aluminum Walkway	Quantity / UoM	
------------	---------------------------------	----------------	--

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	074113100600	Aluminum roof panels, corrugated, on steel frame, painted, .018" thick	600	SF	3.71	\$2,226
Sub Total						\$2,226
					Construction Adjustment	35% 768
Construction Cost						\$2,994
					Adjustment Factor	0% 0
					Soft Cost Adjustment	48% 1,448
Total Estimated Amount						\$4,442

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Bldg 18**

Deficiency:

Assess ID **211329** Surveyor/Update **Sherry Sims**
Deficiency Code ID **A45-03**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Exterior Door Hardware Requires Replacement**
Category **Deferred Maintenance** System **Exterior**
Priority **3-Short Term Conditions (2-3 Years)** Functional Adequacy **Non Related**
Correction **Replace exterior door with ADA compliant hardware** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	080505105585	Door demolition, panic device, remove	1	Ea.	48.00	\$48	
U	087120152250	Door hardware, school, single, exterior, incl. lever, panic device	1	Door	1,600.00	\$1,600	
Sub Total						\$1,648	
					Construction Adjustment	35%	569
Construction Cost						\$2,217	
					Adjustment Factor	0%	0
					Soft Cost Adjustment	48%	1,074
Total Estimated Amount						\$3,290	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 17**

Deficiency:

Assess ID	211331	Surveyor/Update	Sherry Sims
Deficiency Code ID	A26-01		
Status	Estimated	FCI	Yes
Life Cycle	47514		

Deficiency **The Exterior Requires Painting**

Category	Capital Renewal	System	Exterior
----------	-----------------	--------	----------

Priority	3-Short Term Conditions (2-3 Years)	Functional Adequacy	Non Related
----------	-------------------------------------	---------------------	-------------

Correction	Paint Building Exterior	Quantity / UoM	
------------	-------------------------	----------------	--

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	099123528400	Paints & coatings, miscellaneous interior, cornice, ornate design, paint 1 coat, oil base, brushwork	590	SF	1.57	\$927
U	099113601800	Paints & coatings, siding, exterior, Texture 1-111 or clapboard, oil base, primer coat, brushwork	4,000	SF	0.93	\$3,720
U	099103300080	Surface preparation, exterior, doors, per side, wire brush, metal, flush, excl. frames or trim	4,000	SF	0.79	\$3,160
Sub Total						\$7,807
Construction Adjustment						35% 2,693
Construction Cost						\$10,500
Adjustment Factor						0% 0
Soft Cost Adjustment						48% 5,087
Total Estimated Amount						\$15,588

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Bldg 17**

Deficiency:

Assess ID **211332** Surveyor/Update **Sherry Sims**
Deficiency Code ID **A45-03**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Exterior Door Hardware Requires Replacement**
Category **Deferred Maintenance** System **Exterior**
Priority **3-Short Term Conditions (2-3 Years)** Functional Adequacy **Non Related**
Correction **Replace exterior door with ADA compliant hardware** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	080505105585	Door demolition, panic device, remove	3	Ea.	48.00	\$144	
U	087120152250	Door hardware, school, single, exterior, incl. lever, panic device	3	Door	1,600.00	\$4,800	
Sub Total						\$4,944	
					Construction Adjustment	35%	1,706
					Construction Cost		\$6,650
					Adjustment Factor	0%	0
					Soft Cost Adjustment	48%	3,222
					Total Estimated Amount		\$9,871

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Bldg 17**

Deficiency:

Assess ID	211333	Surveyor/Update	Sherry Sims
Deficiency Code ID	A40-03		
Status	Estimated	FCI	Yes
Life Cycle	47516		

Deficiency	The Aluminum Window Is Damaged And Requires Replacement		
Category	Capital Renewal	System	Exterior
Priority	2-Indirect Impact to Mission (1 Year)	Functional Adequacy	Non Related
Correction	Replace Aluminum Frame Window	Quantity / UoM	
Project(s) Note	6"(L) X 3"(W) Awning		

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	062213506000	Moldings, window & door, window trim sets, 2-1/2" wide, maximum	3	OPNG	169.00	\$451	
U	085113203920	Windows, aluminum, commercial grade, stock units, awning type, insulating glass, 3'-0" x 4'-0" opening, incl. frame and glazing	3	Ea.	770.00	\$2,053	
U	080505200280	Window demolition, aluminum, to 50 S.F.	3	Ea.	96.50	\$257	
Sub Total						\$2,761	
					Construction Adjustment	35%	953
					Construction Cost		\$3,714
					Adjustment Factor	0%	0
					Soft Cost Adjustment	48%	1,799
					Total Estimated Amount		\$5,513

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 16**

Deficiency:

Assess ID	211349	Surveyor/Update	Sherry Sims
Deficiency Code ID	A26-01		
Status	Estimated	FCI	Yes
Life Cycle	47541		

Deficiency **The Exterior Requires Painting**

Category	Capital Renewal	System	Exterior
----------	------------------------	--------	-----------------

Priority	3-Short Term Conditions (2-3 Years)	Functional Adequacy	Non Related
----------	--	---------------------	--------------------

Correction	Paint Building Exterior	Quantity / UoM	
------------	--------------------------------	----------------	--

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	099123528400	Paints & coatings, miscellaneous interior, cornice, ornate design, paint 1 coat, oil base, brushwork	590	SF	1.57	\$927	
U	099113601800	Paints & coatings, siding, exterior, Texture 1-111 or clapboard, oil base, primer coat, brushwork	4,000	SF	0.93	\$3,720	
U	099103300080	Surface preparation, exterior, doors, per side, wire brush, metal, flush, excl. frames or trim	4,000	SF	0.79	\$3,160	
Sub Total						\$7,807	
Construction Adjustment						35%	2,693
Construction Cost						\$10,500	
Adjustment Factor						0%	0
Soft Cost Adjustment						48%	5,087
Total Estimated Amount						\$15,588	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Bldg 16**

Deficiency:

Assess ID **211352** Surveyor/Update **Sherry Sims**
Deficiency Code ID **A45-03**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Exterior Door Hardware Requires Replacement**
Category **Deferred Maintenance** System **Exterior**
Priority **3-Short Term Conditions (2-3 Years)** Functional Adequacy **Non Related**
Correction **Replace exterior door with ADA compliant hardware** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	080505105585	Door demolition, panic device, remove	3	Ea.	48.00	\$144	
U	087120152250	Door hardware, school, single, exterior, incl. lever, panic device	3	Door	1,600.00	\$4,800	
Sub Total						\$4,944	
					Construction Adjustment	35%	1,706
					Construction Cost		\$6,650
					Adjustment Factor	0%	0
					Soft Cost Adjustment	48%	3,222
					Total Estimated Amount		\$9,871

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Bldg 16**

Deficiency:

Assess ID	211354	Surveyor/Update	Sherry Sims
Deficiency Code ID	A40-03		
Status	Estimated	FCI	Yes
Life Cycle	47543		

Deficiency	The Aluminum Window Is Damaged And Requires Replacement		
Category	Capital Renewal	System	Exterior
Priority	2-Indirect Impact to Mission (1 Year)	Functional Adequacy	Non Related
Correction	Replace Aluminum Frame Window	Quantity / UoM	
Project(s) Note	6"(L) X 3"(W)		

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	062213506000	Moldings, window & door, window trim sets, 2-1/2" wide, maximum	3	OPNG	169.00	\$451	
U	085113203920	Windows, aluminum, commercial grade, stock units, awning type, insulating glass, 3'-0" x 4'-0" opening, incl. frame and glazing	3	Ea.	770.00	\$2,053	
U	080505200280	Window demolition, aluminum, to 50 S.F.	3	Ea.	96.50	\$257	
Sub Total						\$2,761	
					Construction Adjustment	35%	953
Construction Cost						\$3,714	
					Adjustment Factor	0%	0
					Soft Cost Adjustment	48%	1,799
Total Estimated Amount						\$5,513	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 15**

Deficiency:

Assess ID	211409	Surveyor/Update	Sherry Sims
Deficiency Code ID	A26-01		
Status	Estimated	FCI	Yes
Life Cycle	47606		

Deficiency **The Exterior Requires Painting**

Category	Capital Renewal	System	Exterior
----------	------------------------	--------	-----------------

Priority	3-Short Term Conditions (2-3 Years)	Functional Adequacy	Non Related
----------	--	---------------------	--------------------

Correction	Paint Building Exterior	Quantity / UoM	
------------	--------------------------------	----------------	--

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	099123528400	Paints & coatings, miscellaneous interior, cornice, ornate design, paint 1 coat, oil base, brushwork	590	SF	1.57	\$927	
U	099113601800	Paints & coatings, siding, exterior, Texture 1-111 or clapboard, oil base, primer coat, brushwork	4,000	SF	0.93	\$3,720	
U	099103300080	Surface preparation, exterior, doors, per side, wire brush, metal, flush, excl. frames or trim	4,000	SF	0.79	\$3,160	
Sub Total						\$7,807	
Construction Adjustment						35%	2,693
Construction Cost						\$10,500	
Adjustment Factor						0%	0
Soft Cost Adjustment						48%	5,087
Total Estimated Amount						\$15,588	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Bldg 15**

Deficiency:

Assess ID **211410** Surveyor/Update **Sherry Sims**
Deficiency Code ID **A45-03**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Exterior Door Hardware Requires Replacement**
Category **Deferred Maintenance** System **Exterior**
Priority **3-Short Term Conditions (2-3 Years)** Functional Adequacy **Non Related**
Correction **Replace exterior door with ADA compliant hardware** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	080505105585	Door demolition, panic device, remove	4	Ea.	48.00	\$192	
U	087120152250	Door hardware, school, single, exterior, incl. lever, panic device	4	Door	1,600.00	\$6,400	
Sub Total						\$6,592	
					Construction Adjustment	35%	2,274
Construction Cost						\$8,866	
					Adjustment Factor	0%	0
					Soft Cost Adjustment	48%	4,296
Total Estimated Amount						\$13,162	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Bldg 15**

Deficiency:

Assess ID	211412	Surveyor/Update	Sherry Sims
Deficiency Code ID	A40-03		
Status	Estimated	FCI	Yes
Life Cycle	47608		

Deficiency	The Aluminum Window Is Damaged And Requires Replacement		
Category	Capital Renewal	System	Exterior
Priority	2-Indirect Impact to Mission (1 Year)	Functional Adequacy	Non Related
Correction	Replace Aluminum Frame Window	Quantity / UoM	
Project(s) Note	6"(L) X 4"(W)		

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	062213506000	Moldings, window & door, window trim sets, 2-1/2" wide, maximum	3	OPNG	169.00	\$507	
U	085113203920	Windows, aluminum, commercial grade, stock units, awning type, insulating glass, 3'-0" x 4'-0" opening, incl. frame and glazing	3	Ea.	770.00	\$2,310	
U	080505200280	Window demolition, aluminum, to 50 S.F.	3	Ea.	96.50	\$290	
Sub Total						\$3,107	
					Construction Adjustment	35%	1,072
Construction Cost						\$4,178	
					Adjustment Factor	0%	0
					Soft Cost Adjustment	48%	2,024
Total Estimated Amount						\$6,203	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Bldg 14**

Deficiency:

Assess ID	211429	Surveyor/Update	Sherry Sims
Deficiency Code ID	A26-01		
Status	Estimated	FCI	Yes
Life Cycle	47660		

Deficiency **The Exterior Requires Painting**

Category	Capital Renewal	System	Exterior
----------	------------------------	--------	-----------------

Priority	3-Short Term Conditions (2-3 Years)	Functional Adequacy	Non Related
----------	--	---------------------	--------------------

Correction	Paint Building Exterior	Quantity / UoM	
------------	--------------------------------	----------------	--

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	099123528400	Paints & coatings, miscellaneous interior, cornice, ornate design, paint 1 coat, oil base, brushwork	590	SF	1.57	\$927	
U	099113601800	Paints & coatings, siding, exterior, Texture 1-111 or clapboard, oil base, primer coat, brushwork	4,000	SF	0.93	\$3,720	
U	099103300080	Surface preparation, exterior, doors, per side, wire brush, metal, flush, excl. frames or trim	4,000	SF	0.79	\$3,160	
Sub Total						\$7,807	
Construction Adjustment						35%	2,693
Construction Cost						\$10,500	
Adjustment Factor						0%	0
Soft Cost Adjustment						48%	5,087
Total Estimated Amount						\$15,588	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Bldg 14**

Deficiency:

Assess ID **211430** Surveyor/Update **Sherry Sims**
Deficiency Code ID **A45-03**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Exterior Door Hardware Requires Replacement**
Category **Deferred Maintenance** System **Exterior**
Priority **3-Short Term Conditions (2-3 Years)** Functional Adequacy **Non Related**
Correction **Replace exterior door with ADA compliant hardware** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	080505105585	Door demolition, panic device, remove	1	Ea.	48.00	\$48	
U	087120152250	Door hardware, school, single, exterior, incl. lever, panic device	1	Door	1,600.00	\$1,600	
Sub Total						\$1,648	
					Construction Adjustment	35%	569
					Construction Cost		\$2,217
					Adjustment Factor	0%	0
					Soft Cost Adjustment	48%	1,074
					Total Estimated Amount		\$3,290

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Bldg 14**

Deficiency:

Assess ID	211432	Surveyor/Update	Sherry Sims
Deficiency Code ID	A40-03		
Status	Estimated	FCI	Yes
Life Cycle	47662		

Deficiency	The Aluminum Window Is Damaged And Requires Replacement		
Category	Capital Renewal	System	Exterior
Priority	2-Indirect Impact to Mission (1 Year)	Functional Adequacy	Non Related
Correction	Replace Aluminum Frame Window	Quantity / UoM	
Project(s) Note	Awning 6"(L) X 3"(W)		

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	062213506000	Moldings, window & door, window trim sets, 2-1/2" wide, maximum	3	OPNG	169.00	\$451	
U	085113203920	Windows, aluminum, commercial grade, stock units, awning type, insulating glass, 3'-0" x 4'-0" opening, incl. frame and glazing	3	Ea.	770.00	\$2,053	
U	080505200280	Window demolition, aluminum, to 50 S.F.	3	Ea.	96.50	\$257	
Sub Total						\$2,761	
					Construction Adjustment	35%	953
Construction Cost						\$3,714	
					Adjustment Factor	0%	0
					Soft Cost Adjustment	48%	1,799
Total Estimated Amount						\$5,513	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 13**

Deficiency:

Assess ID	211459	Surveyor/Update	Sherry Sims
Deficiency Code ID	A26-01		
Status	Estimated	FCI	Yes
Life Cycle	47749		

Deficiency **The Exterior Requires Painting**

Category	Capital Renewal	System	Exterior
----------	------------------------	--------	-----------------

Priority	3-Short Term Conditions (2-3 Years)	Functional Adequacy	Non Related
----------	--	---------------------	--------------------

Correction	Paint Building Exterior	Quantity / UoM	
------------	--------------------------------	----------------	--

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	099123528400	Paints & coatings, miscellaneous interior, cornice, ornate design, paint 1 coat, oil base, brushwork	590	SF	1.57	\$927	
U	099113601800	Paints & coatings, siding, exterior, Texture 1-111 or clapboard, oil base, primer coat, brushwork	4,000	SF	0.93	\$3,720	
U	099103300080	Surface preparation, exterior, doors, per side, wire brush, metal, flush, excl. frames or trim	4,000	SF	0.79	\$3,160	
Sub Total						\$7,807	
Construction Adjustment						35%	2,693
Construction Cost						\$10,500	
Adjustment Factor						0%	0
Soft Cost Adjustment						48%	5,087
Total Estimated Amount						\$15,588	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Bldg 13**

Deficiency:

Assess ID **211460** Surveyor/Update **Sherry Sims**
Deficiency Code ID **A45-03**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Exterior Door Hardware Requires Replacement**
Category **Deferred Maintenance** System **Exterior**
Priority **3-Short Term Conditions (2-3 Years)** Functional Adequacy **Non Related**
Correction **Replace exterior door with ADA compliant hardware** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	080505105585	Door demolition, panic device, remove	3	Ea.	48.00	\$144
U	087120152250	Door hardware, school, single, exterior, incl. lever, panic device	3	Door	1,600.00	\$4,800
Sub Total						\$4,944
					Construction Adjustment	35% 1,706
Construction Cost						\$6,650
					Adjustment Factor	0% 0
					Soft Cost Adjustment	48% 3,222
Total Estimated Amount						\$9,871

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Bldg 13**

Deficiency:

Assess ID	211461	Surveyor/Update	Sherry Sims
Deficiency Code ID	A40-03		
Status	Estimated	FCI	Yes
Life Cycle	47750		

Deficiency	The Aluminum Window Is Damaged And Requires Replacement		
Category	Capital Renewal	System	Exterior
Priority	2-Indirect Impact to Mission (1 Year)	Functional Adequacy	Non Related
Correction	Replace Aluminum Frame Window	Quantity / UoM	
Project(s) Note	Awning 6"(L) X 4"(W)		

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	062213506000	Moldings, window & door, window trim sets, 2-1/2" wide, maximum	2	OPNG	169.00	\$380	
U	085113203920	Windows, aluminum, commercial grade, stock units, awning type, insulating glass, 3'-0" x 4'-0" opening, incl. frame and glazing	2	Ea.	770.00	\$1,733	
U	080505200280	Window demolition, aluminum, to 50 S.F.	2	Ea.	96.50	\$217	
Sub Total						\$2,330	
					Construction Adjustment	35%	804
					Construction Cost		\$3,134
					Adjustment Factor	0%	0
					Soft Cost Adjustment	48%	1,518
					Total Estimated Amount		\$4,652

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Bldg 12**

Deficiency:

Assess ID **211488** Surveyor/Update **Sherry Sims**
Deficiency Code ID **A26-01**
Status **Estimated** FCI **Yes**
Life Cycle **47837**

Deficiency **The Exterior Requires Painting**

Category **Capital Renewal** System **Exterior**

Priority **3-Short Term Conditions (2-3 Years)** Functional Adequacy **Non Related**

Correction **Paint Building Exterior** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	099123528400	Paints & coatings, miscellaneous interior, cornice, ornate design, paint 1 coat, oil base, brushwork	1,107	SF	1.57	\$1,738
U	099113601800	Paints & coatings, siding, exterior, Texture 1-111 or clapboard, oil base, primer coat, brushwork	7,500	SF	0.93	\$6,975
U	099103300080	Surface preparation, exterior, doors, per side, wire brush, metal, flush, excl. frames or trim	7,500	SF	0.79	\$5,925
Sub Total						\$14,638
					Construction Adjustment	35% 5,050
Construction Cost						\$19,688
					Adjustment Factor	0% 0
					Soft Cost Adjustment	46% 8,974
Total Estimated Amount						\$28,662

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Bldg 12**

Deficiency:

Assess ID **211490** Surveyor/Update **Sherry Sims**
Deficiency Code ID **A45-03**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Exterior Door Hardware Requires Replacement**
Category **Deferred Maintenance** System **Exterior**
Priority **3-Short Term Conditions (2-3 Years)** Functional Adequacy **Non Related**
Correction **Replace exterior door with ADA compliant hardware** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	080505105585	Door demolition, panic device, remove	7	Ea.	48.00	\$336	
U	087120152250	Door hardware, school, single, exterior, incl. lever, panic device	7	Door	1,600.00	\$11,200	
Sub Total						\$11,536	
					Construction Adjustment	35%	3,980
					Construction Cost		\$15,516
					Adjustment Factor	0%	0
					Soft Cost Adjustment	46%	7,072
Total Estimated Amount						\$22,588	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Bldg 12**

Deficiency:

Assess ID	211494	Surveyor/Update	Sherry Sims
Deficiency Code ID	A40-03		
Status	Estimated	FCI	Yes
Life Cycle	47840		

Deficiency	The Aluminum Window Is Damaged And Requires Replacement		
Category	Capital Renewal	System	Exterior
Priority	2-Indirect Impact to Mission (1 Year)	Functional Adequacy	Non Related
Correction	Replace Aluminum Frame Window	Quantity / UoM	
Project(s) Note	Awning 6"(L) X 4"(W)		

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	062213506000	Moldings, window & door, window trim sets, 2-1/2" wide, maximum	0	OPNG	169.00	\$56	
U	085113203920	Windows, aluminum, commercial grade, stock units, awning type, insulating glass, 3'-0" x 4'-0" opening, incl. frame and glazing	0	Ea.	770.00	\$257	
U	080505200280	Window demolition, aluminum, to 50 S.F.	0	Ea.	96.50	\$32	
Sub Total						\$345	
					Construction Adjustment	35%	119
					Construction Cost		\$464
					Adjustment Factor	0%	0
					Soft Cost Adjustment	46%	212
					Total Estimated Amount		\$676

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 10**

Deficiency:

Assess ID	211534	Surveyor/Update	Sherry Sims
Deficiency Code ID	A26-01		
Status	Estimated	FCI	Yes
Life Cycle	47915		

Deficiency **The Exterior Requires Painting**

Category	Capital Renewal	System	Exterior
----------	------------------------	--------	-----------------

Priority	3-Short Term Conditions (2-3 Years)	Functional Adequacy	Non Related
----------	--	---------------------	--------------------

Correction	Paint Building Exterior	Quantity / UoM	
------------	--------------------------------	----------------	--

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	099123528400	Paints & coatings, miscellaneous interior, cornice, ornate design, paint 1 coat, oil base, brushwork	590	SF	1.57	\$927	
U	099113601800	Paints & coatings, siding, exterior, Texture 1-111 or clapboard, oil base, primer coat, brushwork	4,000	SF	0.93	\$3,720	
U	099103300080	Surface preparation, exterior, doors, per side, wire brush, metal, flush, excl. frames or trim	4,000	SF	0.79	\$3,160	
Sub Total						\$7,807	
Construction Adjustment						35%	2,693
Construction Cost						\$10,500	
Adjustment Factor						0%	0
Soft Cost Adjustment						48%	5,087
Total Estimated Amount						\$15,588	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Bldg 10**

Deficiency:

Assess ID	211535	Surveyor/Update	Sherry Sims
Deficiency Code ID	A40-03		
Status	Estimated	FCI	Yes
Life Cycle	47917		

Deficiency	The Aluminum Window Is Damaged And Requires Replacement		
Category	Capital Renewal	System	Exterior
Priority	2-Indirect Impact to Mission (1 Year)	Functional Adequacy	Non Related
Correction	Replace Aluminum Frame Window	Quantity / UoM	
Project(s) Note	Awning 6"(L) X 3"(W)		

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	062213506000	Moldings, window & door, window trim sets, 2-1/2" wide, maximum	3	OPNG	169.00	\$451	
U	085113203920	Windows, aluminum, commercial grade, stock units, awning type, insulating glass, 3'-0" x 4'-0" opening, incl. frame and glazing	3	Ea.	770.00	\$2,053	
U	080505200280	Window demolition, aluminum, to 50 S.F.	3	Ea.	96.50	\$257	
Sub Total						\$2,761	
					Construction Adjustment	35%	953
Construction Cost						\$3,714	
					Adjustment Factor	0%	0
					Soft Cost Adjustment	48%	1,799
Total Estimated Amount						\$5,513	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Bldg 10**

Deficiency:

Assess ID **211536** Surveyor/Update **Sherry Sims**
Deficiency Code ID **A45-03**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Exterior Door Hardware Requires Replacement**
Category **Deferred Maintenance** System **Exterior**
Priority **3-Short Term Conditions (2-3 Years)** Functional Adequacy **Non Related**
Correction **Replace exterior door with ADA compliant hardware** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	080505105585	Door demolition, panic device, remove	3	Ea.	48.00	\$144	
U	087120152250	Door hardware, school, single, exterior, incl. lever, panic device	3	Door	1,600.00	\$4,800	
Sub Total						\$4,944	
					Construction Adjustment	35%	1,706
					Construction Cost		\$6,650
					Adjustment Factor	0%	0
					Soft Cost Adjustment	48%	3,222
					Total Estimated Amount		\$9,871

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 9**

Deficiency:

Assess ID **211557** Surveyor/Update **Sherry Sims**
Deficiency Code ID **A26-05**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **The Exterior Requires Painting (Bldg SF)**
Category **Capital Renewal** System **Exterior**
Priority **3-Short Term Conditions (2-3 Years)** Functional Adequacy **Non Related**
Correction **Paint Exterior Walls (Bldg SF)** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	015423701350	Scaffolding, steel tubular, regular, frame, buy, 7'-6" high x 6' wide	40	Ea.	173.00	\$6,920
U	099103300770	Surface preparation, exterior, siding, wire brush, aluminum, heavy	1,600	SF	1.15	\$1,840
U	099113429000	Paints & coatings, misc. exterior, minimum labor/equipment charge	4	Job	254.00	\$1,016
U	099713236810	Paints and protective coatings, latex primer, sprayed	1,600	SF	0.41	\$656
U	099713236830	Paints and protective coatings, latex topcoat, sprayed	1,600	SF	0.46	\$736
U	099113800180	Paints & coatings, trim, exterior, fascia, latex paint, 1 coat coverage, brushwork, 1" x 12"	160	LF	0.88	\$141
U	099113800410	Paints & coatings, trim, exterior, molding, primer + 2 coats exterior latex, brushwork, up to 14" wide	160	LF	1.79	\$286
Sub Total						\$11,595
					Construction Adjustment	35% 4,000
Construction Cost						\$15,596
					Adjustment Factor	0% 0
					Soft Cost Adjustment	48% 7,556
Total Estimated Amount						\$23,152

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Bldg 9**

Deficiency:

Assess ID **211558** Surveyor/Update **Sherry Sims**
Deficiency Code ID **A45-03**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Exterior Door Hardware Requires Replacement**
Category **Deferred Maintenance** System **Exterior**
Priority **3-Short Term Conditions (2-3 Years)** Functional Adequacy **Non Related**
Correction **Replace exterior door with ADA compliant hardware** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	080505105585	Door demolition, panic device, remove	3	Ea.	48.00	\$144	
U	087120152250	Door hardware, school, single, exterior, incl. lever, panic device	3	Door	1,600.00	\$4,800	
Sub Total						\$4,944	
					Construction Adjustment	35%	1,706
					Construction Cost		\$6,650
					Adjustment Factor	0%	0
					Soft Cost Adjustment	48%	3,222
					Total Estimated Amount		\$9,871

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Bldg 9**

Deficiency:

Assess ID	211559	Surveyor/Update	Sherry Sims
Deficiency Code ID	A40-03		
Status	Estimated	FCI	Yes
Life Cycle	47965		

Deficiency	The Aluminum Window Is Damaged And Requires Replacement		
Category	Capital Renewal	System	Exterior
Priority	2-Indirect Impact to Mission (1 Year)	Functional Adequacy	Non Related
Correction	Replace Aluminum Frame Window	Quantity / UoM	
Project(s) Note	Awning 6"(L) X 3"(W)		

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	062213506000	Moldings, window & door, window trim sets, 2-1/2" wide, maximum	3	OPNG	169.00	\$451	
U	085113203920	Windows, aluminum, commercial grade, stock units, awning type, insulating glass, 3'-0" x 4'-0" opening, incl. frame and glazing	3	Ea.	770.00	\$2,053	
U	080505200280	Window demolition, aluminum, to 50 S.F.	3	Ea.	96.50	\$257	
Sub Total						\$2,761	
					Construction Adjustment	35%	953
Construction Cost						\$3,714	
					Adjustment Factor	0%	0
					Soft Cost Adjustment	48%	1,799
Total Estimated Amount						\$5,513	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 8**

Deficiency:

Assess ID	211583	Surveyor/Update	Sherry Sims
Deficiency Code ID	A26-01		
Status	Estimated	FCI	Yes
Life Cycle	48010		

Deficiency **The Exterior Requires Painting**

Category	Capital Renewal	System	Exterior
----------	------------------------	--------	-----------------

Priority	3-Short Term Conditions (2-3 Years)	Functional Adequacy	Non Related
----------	--	---------------------	--------------------

Correction	Paint Building Exterior	Quantity / UoM	
------------	--------------------------------	----------------	--

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	099123528400	Paints & coatings, miscellaneous interior, cornice, ornate design, paint 1 coat, oil base, brushwork	590	SF	1.57	\$927
U	099113601800	Paints & coatings, siding, exterior, Texture 1-111 or clapboard, oil base, primer coat, brushwork	4,000	SF	0.93	\$3,720
U	099103300080	Surface preparation, exterior, doors, per side, wire brush, metal, flush, excl. frames or trim	4,000	SF	0.79	\$3,160
Sub Total						\$7,807
Construction Adjustment						35% 2,693
Construction Cost						\$10,500
Adjustment Factor						0% 0
Soft Cost Adjustment						48% 5,087
Total Estimated Amount						\$15,588

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Bldg 8**

Deficiency:

Assess ID **211584** Surveyor/Update **Sherry Sims**
Deficiency Code ID **A45-03**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Exterior Door Hardware Requires Replacement**
Category **Deferred Maintenance** System **Exterior**
Priority **3-Short Term Conditions (2-3 Years)** Functional Adequacy **Non Related**
Correction **Replace exterior door with ADA compliant hardware** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	080505105585	Door demolition, panic device, remove	6	Ea.	48.00	\$288	
U	087120152250	Door hardware, school, single, exterior, incl. lever, panic device	6	Door	1,600.00	\$9,600	
Sub Total						\$9,888	
					Construction Adjustment	35%	3,411
					Construction Cost		\$13,299
					Adjustment Factor	0%	0
					Soft Cost Adjustment	48%	6,444
					Total Estimated Amount		\$19,743

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 8**

Deficiency:

Assess ID	211589	Surveyor/Update	Sherry Sims
Defeciency Code ID	A40-02		
Status	Estimated	FCI	Yes
Life Cycle	48012		

Deficiency	The Aluminum Window Requires Repair		
Category	Deferred Maintenance	System	Exterior
Priority	3-Short Term Conditions (2-3 Years)	Functional Adequacy	Non Related
Correction	Fix Aluminum Windows (Single Hung)	Quantity / UoM	
Project(s) Note	6"(L) X 4"(W)		

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	080505205020	Window demolition, window, remove and reset, minimum	32	Ea.	100.00	\$3,200	
Sub Total						\$3,200	
					Construction Adjustment	35%	1,104
Construction Cost						\$4,304	
					Adjustment Factor	0%	0
					Soft Cost Adjustment	48%	2,085
Total Estimated Amount						\$6,389	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->CR**

Deficiency:

Assess ID	211611	Surveyor/Update	Sherry Sims
Deficiency Code ID	A26-01		
Status	Estimated	FCI	Yes
Life Cycle	48081		

Deficiency **The Exterior Requires Painting**

Category	Capital Renewal	System	Exterior
----------	------------------------	--------	-----------------

Priority	3-Short Term Conditions (2-3 Years)	Functional Adequacy	Non Related
----------	--	---------------------	--------------------

Correction	Paint Building Exterior	Quantity / UoM	
------------	--------------------------------	----------------	--

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	099123528400	Paints & coatings, miscellaneous interior, cornice, ornate design, paint 1 coat, oil base, brushwork	590	SF	1.57	\$927
U	099113601800	Paints & coatings, siding, exterior, Texture 1-111 or clapboard, oil base, primer coat, brushwork	4,000	SF	0.93	\$3,720
U	099103300080	Surface preparation, exterior, doors, per side, wire brush, metal, flush, excl. frames or trim	4,000	SF	0.79	\$3,160
Sub Total						\$7,807
Construction Adjustment						35% 2,693
Construction Cost						\$10,500
Adjustment Factor						0% 0
Soft Cost Adjustment						48% 5,087
Total Estimated Amount						\$15,588

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->CR**

Deficiency:

Assess ID **211615** Surveyor/Update **Sherry Sims**
Deficiency Code ID **A45-03**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Exterior Door Hardware Requires Replacement**
Category **Deferred Maintenance** System **Exterior**
Priority **3-Short Term Conditions (2-3 Years)** Functional Adequacy **Non Related**
Correction **Replace exterior door with ADA compliant hardware** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	080505105585	Door demolition, panic device, remove	2	Ea.	48.00	\$96	
U	087120152250	Door hardware, school, single, exterior, incl. lever, panic device	2	Door	1,600.00	\$3,200	
Sub Total						\$3,296	
					Construction Adjustment	35%	1,137
					Construction Cost		\$4,433
					Adjustment Factor	0%	0
					Soft Cost Adjustment	48%	2,148
Total Estimated Amount						\$6,581	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->CR**

Deficiency:

Assess ID	211616	Surveyor/Update	Sherry Sims
Defeciency Code ID	A40-02		
Status	Estimated	FCI	Yes
Life Cycle	48082		

Deficiency	The Aluminum Window Requires Repair		
Category	Deferred Maintenance	System	Exterior
Priority	3-Short Term Conditions (2-3 Years)	Functional Adequacy	Non Related
Correction	Fix Aluminum Windows (Single Hung)	Quantity / UoM	
Project(s) Note	6"(L) X 3"(W)		

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	080505205020	Window demolition, window, remove and reset, minimum	36	Ea.	100.00	\$3,600	
Sub Total						\$3,600	
					Construction Adjustment	35%	1,242
					Construction Cost	\$4,842	
					Adjustment Factor	0%	0
					Soft Cost Adjustment	48%	2,346
					Total Estimated Amount	\$7,188	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 6**

Deficiency:

Assess ID **211641** Surveyor/Update **Sherry Sims**
Deficiency Code ID **A26-05**
Status **Estimated** FCI **Yes**
Life Cycle **48146**

Deficiency **The Exterior Requires Painting (Bldg SF)**
Category **Capital Renewal** System **Exterior**
Priority **3-Short Term Conditions (2-3 Years)** Functional Adequacy **Non Related**
Correction **Paint Exterior Walls (Bldg SF)** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	015423701350	Scaffolding, steel tubular, regular, frame, buy, 7'-6" high x 6' wide	70	Ea.	173.00	\$12,110
U	099103300770	Surface preparation, exterior, siding, wire brush, aluminum, heavy	2,800	SF	1.15	\$3,220
U	099113429000	Paints & coatings, misc. exterior, minimum labor/equipment charge	7	Job	254.00	\$1,778
U	099713236810	Paints and protective coatings, latex primer, sprayed	2,800	SF	0.41	\$1,148
U	099713236830	Paints and protective coatings, latex topcoat, sprayed	2,800	SF	0.46	\$1,288
U	099113800180	Paints & coatings, trim, exterior, fascia, latex paint, 1 coat coverage, brushwork, 1" x 12"	280	LF	0.88	\$246
U	099113800410	Paints & coatings, trim, exterior, molding, primer + 2 coats exterior latex, brushwork, up to 14" wide	280	LF	1.79	\$501
Sub Total						\$20,292
					Construction Adjustment	35% 7,001
Construction Cost						\$27,292
					Adjustment Factor	0% 0
					Soft Cost Adjustment	48% 13,223
Total Estimated Amount						\$40,515

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Bldg 6**

Deficiency:

Assess ID **211645** Surveyor/Update **Sherry Sims**
Deficiency Code ID **A45-03**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Exterior Door Hardware Requires Replacement**
Category **Deferred Maintenance** System **Exterior**
Priority **3-Short Term Conditions (2-3 Years)** Functional Adequacy **Non Related**
Correction **Replace exterior door with ADA compliant hardware** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	080505105585	Door demolition, panic device, remove	5	Ea.	48.00	\$240	
U	087120152250	Door hardware, school, single, exterior, incl. lever, panic device	5	Door	1,600.00	\$8,000	
Sub Total						\$8,240	
					Construction Adjustment	35%	2,843
					Construction Cost		\$11,083
					Adjustment Factor	0%	0
					Soft Cost Adjustment	48%	5,370
Total Estimated Amount						\$16,452	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 5**

Deficiency:

Assess ID **211673** Surveyor/Update **Sherry Sims**
Deficiency Code ID **A26-05**
Status **Estimated** FCI **Yes**
Life Cycle **48207**

Deficiency **The Exterior Requires Painting (Bldg SF)**
Category **Capital Renewal** System **Exterior**
Priority **3-Short Term Conditions (2-3 Years)** Functional Adequacy **Non Related**
Correction **Paint Exterior Walls (Bldg SF)** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	015423701350	Scaffolding, steel tubular, regular, frame, buy, 7'-6" high x 6' wide	70	Ea.	173.00	\$12,110
U	099103300770	Surface preparation, exterior, siding, wire brush, aluminum, heavy	2,800	SF	1.15	\$3,220
U	099113429000	Paints & coatings, misc. exterior, minimum labor/equipment charge	7	Job	254.00	\$1,778
U	099713236810	Paints and protective coatings, latex primer, sprayed	2,800	SF	0.41	\$1,148
U	099713236830	Paints and protective coatings, latex topcoat, sprayed	2,800	SF	0.46	\$1,288
U	099113800180	Paints & coatings, trim, exterior, fascia, latex paint, 1 coat coverage, brushwork, 1" x 12"	280	LF	0.88	\$246
U	099113800410	Paints & coatings, trim, exterior, molding, primer + 2 coats exterior latex, brushwork, up to 14" wide	280	LF	1.79	\$501
Sub Total						\$20,292
					Construction Adjustment	35% 7,001
Construction Cost						\$27,292
					Adjustment Factor	0% 0
					Soft Cost Adjustment	48% 13,223
Total Estimated Amount						\$40,515

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Bldg 5**

Deficiency:

Assess ID	211678	Surveyor/Update	Sherry Sims
Deficiency Code ID	A40-03		
Status	Estimated	FCI	Yes
Life Cycle	48209		

Deficiency	The Aluminum Window Is Damaged And Requires Replacement		
Category	Capital Renewal	System	Exterior
Priority	2-Indirect Impact to Mission (1 Year)	Functional Adequacy	Non Related
Correction	Replace Aluminum Frame Window	Quantity / UoM	
Project(s) Note	3"(L) X 4"(W)		

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	062213506000	Moldings, window & door, window trim sets, 2-1/2" wide, maximum	1	OPNG	169.00	\$141
U	085113203920	Windows, aluminum, commercial grade, stock units, awning type, insulating glass, 3'-0" x 4'-0" opening, incl. frame and glazing	1	Ea.	770.00	\$642
U	080505200280	Window demolition, aluminum, to 50 S.F.	1	Ea.	96.50	\$80
Sub Total						\$863
Construction Adjustment					35%	298
Construction Cost						\$1,161
Adjustment Factor					0%	0
Soft Cost Adjustment					48%	562
Total Estimated Amount						\$1,723

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 4**

Deficiency:

Assess ID **211702** Surveyor/Update **Sherry Sims**
Deficiency Code ID **A26-05**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **The Exterior Requires Painting (Bldg SF)**
Category **Capital Renewal** System **Exterior**
Priority **3-Short Term Conditions (2-3 Years)** Functional Adequacy **Non Related**
Correction **Paint Exterior Walls (Bldg SF)** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	015423701350	Scaffolding, steel tubular, regular, frame, buy, 7'-6" high x 6' wide	100	Ea.	173.00	\$17,300
U	099103300770	Surface preparation, exterior, siding, wire brush, aluminum, heavy	4,000	SF	1.15	\$4,600
U	099113429000	Paints & coatings, misc. exterior, minimum labor/equipment charge	10	Job	254.00	\$2,540
U	099713236810	Paints and protective coatings, latex primer, sprayed	4,000	SF	0.41	\$1,640
U	099713236830	Paints and protective coatings, latex topcoat, sprayed	4,000	SF	0.46	\$1,840
U	099113800180	Paints & coatings, trim, exterior, fascia, latex paint, 1 coat coverage, brushwork, 1" x 12"	400	LF	0.88	\$352
U	099113800410	Paints & coatings, trim, exterior, molding, primer + 2 coats exterior latex, brushwork, up to 14" wide	400	LF	1.79	\$716
Sub Total						\$28,988
					Construction Adjustment	35% 10,001
Construction Cost						\$38,989
					Adjustment Factor	0% 0
					Soft Cost Adjustment	48% 18,890
Total Estimated Amount						\$57,879

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 4**

Deficiency:

Assess ID	211720	Surveyor/Update	Sherry Sims
Deficiency Code ID	A26-01		
Status	Estimated	FCI	Yes
Life Cycle	48250		

Deficiency **The Exterior Requires Painting**

Category	Capital Renewal	System	Exterior
----------	-----------------	--------	----------

Priority	3-Short Term Conditions (2-3 Years)	Functional Adequacy	Non Related
----------	-------------------------------------	---------------------	-------------

Correction	Paint Building Exterior	Quantity / UoM	
------------	-------------------------	----------------	--

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	099123528400	Paints & coatings, miscellaneous interior, cornice, ornate design, paint 1 coat, oil base, brushwork	1,476	SF	1.57	\$2,318
U	099113601800	Paints & coatings, siding, exterior, Texture 1-111 or clapboard, oil base, primer coat, brushwork	10,000	SF	0.93	\$9,300
U	099103300080	Surface preparation, exterior, doors, per side, wire brush, metal, flush, excl. frames or trim	10,000	SF	0.79	\$7,900
Sub Total						\$19,518
					Construction Adjustment	35% 6,734
Construction Cost						\$26,251
					Adjustment Factor	0% 0
					Soft Cost Adjustment	48% 12,719
Total Estimated Amount						\$38,970

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Media Ctr**

Deficiency:

Assess ID **211726** Surveyor/Update **Sherry Sims**
Deficiency Code ID **A26-05**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **The Exterior Requires Painting (Bldg SF)**
Category **Capital Renewal** System **Exterior**
Priority **3-Short Term Conditions (2-3 Years)** Functional Adequacy **Non Related**
Correction **Paint Exterior Walls (Bldg SF)** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	015423701350	Scaffolding, steel tubular, regular, frame, buy, 7'-6" high x 6' wide	80	Ea.	173.00	\$13,840
U	099103300770	Surface preparation, exterior, siding, wire brush, aluminum, heavy	3,200	SF	1.15	\$3,680
U	099113429000	Paints & coatings, misc. exterior, minimum labor/equipment charge	8	Job	254.00	\$2,032
U	099713236810	Paints and protective coatings, latex primer, sprayed	3,200	SF	0.41	\$1,312
U	099713236830	Paints and protective coatings, latex topcoat, sprayed	3,200	SF	0.46	\$1,472
U	099113800180	Paints & coatings, trim, exterior, fascia, latex paint, 1 coat coverage, brushwork, 1" x 12"	320	LF	0.88	\$282
U	099113800410	Paints & coatings, trim, exterior, molding, primer + 2 coats exterior latex, brushwork, up to 14" wide	320	LF	1.79	\$573
Sub Total						\$23,190
					Construction Adjustment	35% 8,001
Construction Cost						\$31,191
					Adjustment Factor	0% 0
					Soft Cost Adjustment	48% 15,112
Total Estimated Amount						\$46,303

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Media Ctr**

Deficiency:

Assess ID **211727** Surveyor/Update **Sherry Sims**
Deficiency Code ID **A35-04**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **The Wood Exterior Door Requires Repainting**
Category **Deferred Maintenance** System **Exterior**
Priority **3-Short Term Conditions (2-3 Years)** Functional Adequacy **Non Related**
Correction **Repaint Exterior Wood Door** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	099113700360	Paints & coatings, exterior doors, panel, both sides, roll & brush, primer + 1 coat, exterior latex, incl. frame & trim	2	Ea.	181.00	\$362	
U	099103200520	Paint preparation, sanding & puttying interior trim, surface protection, placement & removal, masking w/paper	84	SF	0.67	\$56	
Sub Total						\$418	
					Construction Adjustment	35%	144
Construction Cost						\$563	
					Adjustment Factor	0%	0
					Soft Cost Adjustment	48%	273
Total Estimated Amount						\$835	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Media Ctr**

Deficiency:

Assess ID **211738** Surveyor/Update **Sherry Sims**
Deficiency Code ID **A26-01**
Status **Estimated** FCI **Yes**
Life Cycle **48305**

Deficiency **The Exterior Requires Painting**

Category **Capital Renewal** System **Exterior**

Priority **3-Short Term Conditions (2-3 Years)** Functional Adequacy **Non Related**

Correction **Paint Building Exterior** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	099123528400	Paints & coatings, miscellaneous interior, cornice, ornate design, paint 1 coat, oil base, brushwork	1,181	SF	1.57	\$1,854
U	099113601800	Paints & coatings, siding, exterior, Texture 1-111 or clapboard, oil base, primer coat, brushwork	8,000	SF	0.93	\$7,440
U	099103300080	Surface preparation, exterior, doors, per side, wire brush, metal, flush, excl. frames or trim	8,000	SF	0.79	\$6,320
Sub Total						\$15,614
Construction Adjustment						35% 5,387
Construction Cost						\$21,001
Adjustment Factor						0% 0
Soft Cost Adjustment						48% 10,175
Total Estimated Amount						\$31,176

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 2**

Deficiency:

Assess ID	211743	Surveyor/Update	Sherry Sims
Deficiency Code ID	A26-01		
Status	Estimated	FCI	Yes
Life Cycle	48333		

Deficiency **The Exterior Requires Painting**

Category	Capital Renewal	System	Exterior
----------	------------------------	--------	-----------------

Priority	3-Short Term Conditions (2-3 Years)	Functional Adequacy	Non Related
----------	--	---------------------	--------------------

Correction	Paint Building Exterior	Quantity / UoM	
------------	--------------------------------	----------------	--

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	099123528400	Paints & coatings, miscellaneous interior, cornice, ornate design, paint 1 coat, oil base, brushwork	1,476	SF	1.57	\$2,318
U	099113601800	Paints & coatings, siding, exterior, Texture 1-111 or clapboard, oil base, primer coat, brushwork	10,000	SF	0.93	\$9,300
U	099103300080	Surface preparation, exterior, doors, per side, wire brush, metal, flush, excl. frames or trim	10,000	SF	0.79	\$7,900
Sub Total						\$19,518
Construction Adjustment						35% 6,734
Construction Cost						\$26,251
Adjustment Factor						0% 0
Soft Cost Adjustment						48% 12,719
Total Estimated Amount						\$38,970

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Bldg 2**

Deficiency:

Assess ID	211744	Surveyor/Update	Sherry Sims
Deficiency Code ID	A35-03		
Status	Estimated	FCI	Yes
Life Cycle	48336		

Deficiency	The Wood Exterior Door Is Damaged And Requires Replacement		
Category	Capital Renewal	System	Exterior
Priority	2-Indirect Impact to Mission (1 Year)	Functional Adequacy	Non Related
Correction	Replace Wood Exterior Door	Quantity / UoM	
Project(s) Note	7"(L) X 3"(W)		

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	081313131360	Doors, commercial, steel, flush, half glass, hollow core, hollow metal, 18 ga., 3'-0" x 7'-0" x 1-3/4" thick	5	Ea.	780.00	\$3,900	
U	087120152250	Door hardware, school, single, exterior, incl. lever, panic device	5	Door	1,600.00	\$8,000	
U	080505100200	Door demolition, exterior door, single, 3' x 7' high, 1-3/4" thick, remove	5	Ea.	30.00	\$150	
Sub Total						\$12,050	
					Construction Adjustment	35%	4,157
Construction Cost						\$16,207	
					Adjustment Factor	0%	0
					Soft Cost Adjustment	48%	7,852
Total Estimated Amount						\$24,060	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Bldg 2**

Deficiency:

Assess ID	211747	Surveyor/Update	Sherry Sims
Defeciency Code ID	A45-03		
Status	Estimated	FCI	Yes
Life Cycle			

Deficiency	Exterior Door Hardware Requires Replacement		
Category	Deferred Maintenance	System	Exterior
Priority	3-Short Term Conditions (2-3 Years)	Functional Adequacy	Non Related
Correction	Replace exterior door with ADA compliant hardware	Quantity / UoM	

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	080505105585	Door demolition, panic device, remove	13	Ea.	48.00	\$624	
U	087120152250	Door hardware, school, single, exterior, incl. lever, panic device	13	Door	1,600.00	\$20,800	
Sub Total						\$21,424	
					Construction Adjustment	35%	7,391
Construction Cost						\$28,815	
					Adjustment Factor	0%	0
					Soft Cost Adjustment	48%	13,961
Total Estimated Amount						\$42,776	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Bldg 2**

Deficiency:

Assess ID	211748	Surveyor/Update	Sherry Sims
Deficiency Code ID	A40-03		
Status	Estimated	FCI	Yes
Life Cycle	48335		

Deficiency	The Aluminum Window Is Damaged And Requires Replacement		
Category	Capital Renewal	System	Exterior
Priority	2-Indirect Impact to Mission (1 Year)	Functional Adequacy	Non Related
Correction	Replace Aluminum Frame Window	Quantity / UoM	
Project(s) Note	Awning 2"(L) X 4"(W)		

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	062213506000	Moldings, window & door, window trim sets, 2-1/2" wide, maximum	3	OPNG	169.00	\$437	
U	085113203920	Windows, aluminum, commercial grade, stock units, awning type, insulating glass, 3'-0" x 4'-0" opening, incl. frame and glazing	3	Ea.	770.00	\$1,989	
U	080505200280	Window demolition, aluminum, to 50 S.F.	3	Ea.	96.50	\$249	
Sub Total						\$2,675	
					Construction Adjustment	35%	923
					Construction Cost		\$3,598
					Adjustment Factor	0%	0
					Soft Cost Adjustment	48%	1,743
					Total Estimated Amount		\$5,341

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 1**

Deficiency:

Assess ID **211793** Surveyor/Update **Sherry Sims**
Deficiency Code ID **A36-02**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **The Metal Exterior Door Requires Repair**
Category **Deferred Maintenance** System **Exterior**
Priority **3-Short Term Conditions (2-3 Years)** Functional Adequacy **Non Related**
Correction **Repair Metal Exterior Door** Quantity / UoM
Project(s) Note **7"(L) X 3"(W)**

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	099103409010	Surface preparation, interior, minimum labor/equipment charge	7	Job	169.00	\$1,099
U	099123339900	Paints & coatings, doors & windows, interior, alkyd (oil base), minimum labor/equipment charge	7	Job	254.00	\$1,651
U	081313209000	Doors, minimum labor/equipment charge	7	Job	151.00	\$982
Sub Total						\$3,731
					Construction Adjustment	35% 1,287
Construction Cost						\$5,018
					Adjustment Factor	0% 0
					Soft Cost Adjustment	48% 2,431
Total Estimated Amount						\$7,450

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Bldg 1**

Deficiency:

Assess ID	211796	Surveyor/Update	Sherry Sims
Deficiency Code ID	A40-03		
Status	Estimated	FCI	Yes
Life Cycle			

Deficiency	The Aluminum Window Is Damaged And Requires Replacement		
Category	Capital Renewal	System	Exterior
Priority	2-Indirect Impact to Mission (1 Year)	Functional Adequacy	Non Related
Correction	Replace Aluminum Frame Window	Quantity / UoM	
Project(s) Note	5'(L) X 3'(W)		

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	062213506000	Moldings, window & door, window trim sets, 2-1/2" wide, maximum	5	OPNG	169.00	\$789	
U	085113203920	Windows, aluminum, commercial grade, stock units, awning type, insulating glass, 3'-0" x 4'-0" opening, incl. frame and glazing	5	Ea.	770.00	\$3,593	
U	080505200280	Window demolition, aluminum, to 50 S.F.	5	Ea.	96.50	\$450	
Sub Total						\$4,832	
					Construction Adjustment	35%	1,667
Construction Cost						\$6,499	
					Adjustment Factor	0%	0
					Soft Cost Adjustment	48%	3,149
Total Estimated Amount						\$9,648	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Bldg 1**

Deficiency:

Assess ID	211806	Surveyor/Update	Sherry Sims
Deficiency Code ID	A26-01		
Status	Estimated	FCI	Yes
Life Cycle	48474		

Deficiency **The Exterior Requires Painting**

Category	Capital Renewal	System	Exterior
----------	------------------------	--------	-----------------

Priority	3-Short Term Conditions (2-3 Years)	Functional Adequacy	Non Related
----------	--	---------------------	--------------------

Correction	Paint Building Exterior	Quantity / UoM	
------------	--------------------------------	----------------	--

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	099123528400	Paints & coatings, miscellaneous interior, cornice, ornate design, paint 1 coat, oil base, brushwork	1,476	SF	1.57	\$2,318
U	099113601800	Paints & coatings, siding, exterior, Texture 1-111 or clapboard, oil base, primer coat, brushwork	10,000	SF	0.93	\$9,300
U	099103300080	Surface preparation, exterior, doors, per side, wire brush, metal, flush, excl. frames or trim	10,000	SF	0.79	\$7,900
Sub Total						\$19,518
					Construction Adjustment	35% 6,734
Construction Cost						\$26,251
					Adjustment Factor	0% 0
					Soft Cost Adjustment	48% 12,719
Total Estimated Amount						\$38,970

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Gym**

Deficiency:

Assess ID **213447** Surveyor/Update **Sherry Sims**
Deficiency Code ID **A26-01**
Status **Estimated** FCI **Yes**
Life Cycle **47050**

Deficiency **The Exterior Requires Painting**

Category **Capital Renewal** System **Exterior**

Priority **3-Short Term Conditions (2-3 Years)** Functional Adequacy **Non Related**

Correction **Paint Building Exterior** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	099123528400	Paints & coatings, miscellaneous interior, cornice, ornate design, paint 1 coat, oil base, brushwork	2,952	SF	1.57	\$4,635
U	099113601800	Paints & coatings, siding, exterior, Texture 1-111 or clapboard, oil base, primer coat, brushwork	20,000	SF	0.93	\$18,600
U	099103300080	Surface preparation, exterior, doors, per side, wire brush, metal, flush, excl. frames or trim	20,000	SF	0.79	\$15,800
Sub Total						\$39,035
Construction Adjustment						35% 13,467
Construction Cost						\$52,502
Adjustment Factor						0% 0
Soft Cost Adjustment						42% 22,282
Total Estimated Amount						\$74,784

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 1**

Deficiency:

Assess ID **224079** Surveyor/Update
Deficiency Code ID **BCRoof-02**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Reroofing with new Decking Required (Broward CPS)**
Category **Capital Renewal** System **Roofing**
Priority **2-Indirect Impact to Mission (1 Year)** Functional Adequacy **Non Related**
Correction **Reroof and Replace Decking** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
M		Estimate based of BCPS experience	8,124	SF	7.25	\$58,899
Sub Total						\$58,899
					Construction Adjustment	35% 20,320
Construction Cost						\$79,219
					Adjustment Factor	0% 0
					Soft Cost Adjustment	42% 33,621
Total Estimated Amount						\$112,840

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 2**

Deficiency:

Assess ID **224080** Surveyor/Update
Deficiency Code ID **BCRoof-02**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Reroofing with new Decking Required (Broward CPS)**
Category **Capital Renewal** System **Roofing**
Priority **2-Indirect Impact to Mission (1 Year)** Functional Adequacy **Non Related**
Correction **Reroof and Replace Decking** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
M		Estimate based of BCPS experience	8,902	SF	7.25	\$64,540	
Sub Total						\$64,540	
					Construction Adjustment	35%	22,266
Construction Cost						\$86,806	
					Adjustment Factor	0%	0
					Soft Cost Adjustment	42%	36,840
Total Estimated Amount						\$123,646	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Media Ctr**

Deficiency:

Assess ID **224081** Surveyor/Update
Deficiency Code ID **BCRoof-02**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Reroofing with new Decking Required (Broward CPS)**
Category **Capital Renewal** System **Roofing**
Priority **2-Indirect Impact to Mission (1 Year)** Functional Adequacy **Non Related**
Correction **Reroof and Replace Decking** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
M		Estimate based of BCPS experience	6,435	SF	7.25	\$46,654
Sub Total						\$46,654
					Construction Adjustment	35% 16,096
Construction Cost						\$62,749
					Adjustment Factor	0% 0
					Soft Cost Adjustment	42% 26,631
Total Estimated Amount						\$89,380

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 4**

Deficiency:

Assess ID **224082** Surveyor/Update
Deficiency Code ID **BCRoof-02**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Reroofing with new Decking Required (Broward CPS)**
Category **Capital Renewal** System **Roofing**
Priority **2-Indirect Impact to Mission (1 Year)** Functional Adequacy **Non Related**
Correction **Reroof and Replace Decking** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
M		Estimate based of BCPS experience	8,330	SF	7.25	\$60,393	
Sub Total						\$60,393	
					Construction Adjustment	35%	20,835
Construction Cost						\$81,228	
					Adjustment Factor	0%	0
					Soft Cost Adjustment	42%	34,473
Total Estimated Amount						\$115,701	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Bldg 5**

Deficiency:

Assess ID **224083** Surveyor/Update
Deficiency Code ID **BCRoof-02**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Reroofing with new Decking Required (Broward CPS)**
Category **Capital Renewal** System **Roofing**
Priority **2-Indirect Impact to Mission (1 Year)** Functional Adequacy **Non Related**
Correction **Reroof and Replace Decking** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
M		Estimate based of BCPS experience	5,081	SF	7.25	\$36,837
Sub Total						\$36,837
					Construction Adjustment	35% 12,709
Construction Cost						\$49,546
					Adjustment Factor	0% 0
					Soft Cost Adjustment	42% 21,027
Total Estimated Amount						\$70,573

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 6**

Deficiency:

Assess ID **224084** Surveyor/Update
Deficiency Code ID **BCRoof-02**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Reroofing with new Decking Required (Broward CPS)**
Category **Capital Renewal** System **Roofing**
Priority **2-Indirect Impact to Mission (1 Year)** Functional Adequacy **Non Related**
Correction **Reroof and Replace Decking** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
M		Estimate based of BCPS experience	5,582	SF	7.25	\$40,470
Sub Total						\$40,470
					Construction Adjustment	35% 13,962
Construction Cost						\$54,431
					Adjustment Factor	0% 0
					Soft Cost Adjustment	42% 23,101
Total Estimated Amount						\$77,532

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->CR**

Deficiency:

Assess ID **224086** Surveyor/Update
Deficiency Code ID **BCRoof-02**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Reroofing with new Decking Required (Broward CPS)**
Category **Capital Renewal** System **Roofing**
Priority **2-Indirect Impact to Mission (1 Year)** Functional Adequacy **Non Related**
Correction **Reroof and Replace Decking** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
M		Estimate based of BCPS experience	3,348	SF	7.25	\$24,273
Sub Total						\$24,273
					Construction Adjustment	35% 8,374
Construction Cost						\$32,647
					Adjustment Factor	0% 0
					Soft Cost Adjustment	42% 13,855
Total Estimated Amount						\$46,503

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Bldg 8**

Deficiency:

Assess ID **224088** Surveyor/Update
Deficiency Code ID **BCRoof-02**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Reroofing with new Decking Required (Broward CPS)**
Category **Capital Renewal** System **Roofing**
Priority **2-Indirect Impact to Mission (1 Year)** Functional Adequacy **Non Related**
Correction **Reroof and Replace Decking** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
M		Estimate based of BCPS experience	3,263	SF	7.25	\$23,657
Sub Total						\$23,657
					Construction Adjustment	35% 8,162
Construction Cost						\$31,818
					Adjustment Factor	0% 0
					Soft Cost Adjustment	42% 13,504
Total Estimated Amount						\$45,322

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 9**

Deficiency:

Assess ID **224090** Surveyor/Update
Deficiency Code ID **BCRoof-02**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Reroofing with new Decking Required (Broward CPS)**
Category **Capital Renewal** System **Roofing**
Priority **2-Indirect Impact to Mission (1 Year)** Functional Adequacy **Non Related**
Correction **Reroof and Replace Decking** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
M		Estimate based of BCPS experience	3,244	SF	7.25	\$23,519
Sub Total						\$23,519
					Construction Adjustment	35% 8,114
Construction Cost						\$31,633
					Adjustment Factor	0% 0
					Soft Cost Adjustment	42% 13,425
Total Estimated Amount						\$45,058

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Bldg 10**

Deficiency:

Assess ID **224092** Surveyor/Update
Deficiency Code ID **BCRoof-02**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Reroofing with new Decking Required (Broward CPS)**
Category **Capital Renewal** System **Roofing**
Priority **2-Indirect Impact to Mission (1 Year)** Functional Adequacy **Non Related**
Correction **Reroof and Replace Decking** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
M		Estimate based of BCPS experience	3,565	SF	7.25	\$25,846
Sub Total						\$25,846
					Construction Adjustment	35% 8,917
Construction Cost						\$34,763
					Adjustment Factor	0% 0
					Soft Cost Adjustment	42% 14,754
Total Estimated Amount						\$49,517

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 12**

Deficiency:

Assess ID **224093** Surveyor/Update
Deficiency Code ID **BCRoof-02**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Reroofing with new Decking Required (Broward CPS)**
Category **Capital Renewal** System **Roofing**
Priority **2-Indirect Impact to Mission (1 Year)** Functional Adequacy **Non Related**
Correction **Reroof and Replace Decking** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
M		Estimate based of BCPS experience	6,325	SF	7.25	\$45,856
Sub Total						\$45,856
					Construction Adjustment	35% 15,820
Construction Cost						\$61,677
					Adjustment Factor	0% 0
					Soft Cost Adjustment	42% 26,176
Total Estimated Amount						\$87,852

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 13**

Deficiency:

Assess ID **224094** Surveyor/Update
Deficiency Code ID **BCRoof-02**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Reroofing with new Decking Required (Broward CPS)**
Category **Capital Renewal** System **Roofing**
Priority **2-Indirect Impact to Mission (1 Year)** Functional Adequacy **Non Related**
Correction **Reroof and Replace Decking** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
M		Estimate based of BCPS experience	3,474	SF	7.25	\$25,187
Sub Total						\$25,187
					Construction Adjustment	35% 8,689
Construction Cost						\$33,876
					Adjustment Factor	0% 0
					Soft Cost Adjustment	42% 14,377
Total Estimated Amount						\$48,253

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 14**

Deficiency:

Assess ID **224095** Surveyor/Update
Deficiency Code ID **BCRoof-02**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Reroofing with new Decking Required (Broward CPS)**
Category **Capital Renewal** System **Roofing**
Priority **2-Indirect Impact to Mission (1 Year)** Functional Adequacy **Non Related**
Correction **Reroof and Replace Decking** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
M		Estimate based of BCPS experience	3,406	SF	7.25	\$24,694
Sub Total						\$24,694
					Construction Adjustment	35% 8,519
Construction Cost						\$33,213
					Adjustment Factor	0% 0
					Soft Cost Adjustment	42% 14,095
Total Estimated Amount						\$47,308

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Bldg 15**

Deficiency:

Assess ID **224097** Surveyor/Update
Deficiency Code ID **BCRoof-02**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Reroofing with new Decking Required (Broward CPS)**
Category **Capital Renewal** System **Roofing**
Priority **2-Indirect Impact to Mission (1 Year)** Functional Adequacy **Non Related**
Correction **Reroof and Replace Decking** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
M		Estimate based of BCPS experience	3,385	SF	7.25	\$24,541
Sub Total						\$24,541
					Construction Adjustment	35% 8,467
Construction Cost						\$33,008
					Adjustment Factor	0% 0
					Soft Cost Adjustment	42% 14,009
Total Estimated Amount						\$47,017

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 16**

Deficiency:

Assess ID **224099** Surveyor/Update
Deficiency Code ID **BCRoof-02**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Reroofing with new Decking Required (Broward CPS)**
Category **Capital Renewal** System **Roofing**
Priority **2-Indirect Impact to Mission (1 Year)** Functional Adequacy **Non Related**
Correction **Reroof and Replace Decking** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
M		Estimate based of BCPS experience	3,406	SF	7.25	\$24,694
Sub Total						\$24,694
					Construction Adjustment	35% 8,519
Construction Cost						\$33,213
					Adjustment Factor	0% 0
					Soft Cost Adjustment	42% 14,095
Total Estimated Amount						\$47,308

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 17**

Deficiency:

Assess ID **224101** Surveyor/Update
Deficiency Code ID **BCRoof-02**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Reroofing with new Decking Required (Broward CPS)**
Category **Capital Renewal** System **Roofing**
Priority **2-Indirect Impact to Mission (1 Year)** Functional Adequacy **Non Related**
Correction **Reroof and Replace Decking** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
M		Estimate based of BCPS experience	3,346	SF	7.25	\$24,259
Sub Total						\$24,259
					Construction Adjustment	35% 8,369
Construction Cost						\$32,628
					Adjustment Factor	0% 0
					Soft Cost Adjustment	42% 13,847
Total Estimated Amount						\$46,475

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Bldg 18**

Deficiency:

Assess ID **224103** Surveyor/Update
Deficiency Code ID **BCRoof-02**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Reroofing with new Decking Required (Broward CPS)**
Category **Capital Renewal** System **Roofing**
Priority **2-Indirect Impact to Mission (1 Year)** Functional Adequacy **Non Related**
Correction **Reroof and Replace Decking** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
M		Estimate based of BCPS experience	677	SF	7.25	\$4,908
Sub Total						\$4,908
					Construction Adjustment	35% 1,693
Construction Cost						\$6,602
					Adjustment Factor	0% 0
					Soft Cost Adjustment	42% 2,802
Total Estimated Amount						\$9,403

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg 19**

Deficiency:

Assess ID **224105** Surveyor/Update
Deficiency Code ID **BCRoof-02**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Reroofing with new Decking Required (Broward CPS)**
Category **Capital Renewal** System **Roofing**
Priority **2-Indirect Impact to Mission (1 Year)** Functional Adequacy **Non Related**
Correction **Reroof and Replace Decking** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
M		Estimate based of BCPS experience	7,146	SF	7.25	\$51,809
Sub Total						\$51,809
					Construction Adjustment	35% 17,874
Construction Cost						\$69,682
					Adjustment Factor	0% 0
					Soft Cost Adjustment	42% 29,573
Total Estimated Amount						\$99,256

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Sto**

Deficiency:

Assess ID **224106** Surveyor/Update **Rebecca Jordan**
Deficiency Code ID **BCRoof-02**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Reroofing with new Decking Required (Broward CPS)**
Category **Capital Renewal** System **Roofing**
Priority **2-Indirect Impact to Mission (1 Year)** Functional Adequacy **Non Related**
Correction **Reroof and Replace Decking** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
M		Estimate based of BCPS experience	172	SF	7.25	\$1,247	
Sub Total						\$1,247	
					Construction Adjustment	35%	430
Construction Cost						\$1,677	
					Adjustment Factor	0%	0
					Soft Cost Adjustment	42%	712
Total Estimated Amount						\$2,389	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS->Bldg Support**

Deficiency:

Assess ID **224108** Surveyor/Update
Deficiency Code ID **BCRoof-01**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Reroofing Required (Broward CPS)**
Category **Capital Renewal** System **Roofing**
Priority **2-Indirect Impact to Mission (1 Year)** Functional Adequacy **Non Related**
Correction **Reroof Building** Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
M		Estimate based on BCPS experience	18,755	SF	6.25	\$117,219
Sub Total						\$117,219
					Construction Adjustment	35% 40,440
Construction Cost						\$157,659
					Adjustment Factor	0% 0
					Soft Cost Adjustment	42% 66,911
Total Estimated Amount						\$224,570

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS**

Deficiency:

Assess ID **314533** Surveyor/Update
Deficiency Code ID **A14-02**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Aluminum Covered Walkways Require Replacement**
Category **Capital Renewal** System **Roofing**
Priority **2-Indirect Impact to Mission (1 Year)** Functional Adequacy **Non Related**
Correction **Replace Aluminum Walkway** Quantity / UoM
Project(s) Note **Originally part of roof replacement deficiency. Pulled out separate to reflect covered walk canopy pricing.**

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	074113100600	Aluminum roof panels, corrugated, on steel frame, painted, .018" thick	4,380	SF	3.71	\$16,250
Sub Total						\$16,250
					Construction Adjustment	35% 5,606
Construction Cost						\$21,856
					Adjustment Factor	0% 0
					Soft Cost Adjustment	42% 9,276
Total Estimated Amount						\$31,132

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS**

Deficiency:

Assess ID **314534** Surveyor/Update
Deficiency Code ID **A14-02**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Aluminum Covered Walkways Require Replacement**
Category **Capital Renewal** System **Roofing**
Priority **2-Indirect Impact to Mission (1 Year)** Functional Adequacy **Non Related**
Correction **Replace Aluminum Walkway** Quantity / UoM
Project(s) Note **Originally part of roof replacement deficiency. Pulled out separate to reflect covered walk canopy pricing.**

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	074113100600	Aluminum roof panels, corrugated, on steel frame, painted, .018" thick	2,297	SF	3.71	\$8,522
Sub Total						\$8,522
					Construction Adjustment	35% 2,940
Construction Cost						\$11,462
					Adjustment Factor	0% 0
					Soft Cost Adjustment	42% 4,864
Total Estimated Amount						\$16,326

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS**

Deficiency:

Assess ID **314535** Surveyor/Update
Deficiency Code ID **A14-02**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Aluminum Covered Walkways Require Replacement**
Category **Capital Renewal** System **Roofing**
Priority **2-Indirect Impact to Mission (1 Year)** Functional Adequacy **Non Related**
Correction **Replace Aluminum Walkway** Quantity / UoM
Project(s) Note **Originally part of roof replacement deficiency. Pulled out separate to reflect covered walk canopy pricing.**

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	074113100600	Aluminum roof panels, corrugated, on steel frame, painted, .018" thick	5,515	SF	3.71	\$20,461
Sub Total						\$20,461
					Construction Adjustment	35% 7,059
Construction Cost						\$27,520
					Adjustment Factor	0% 0
					Soft Cost Adjustment	42% 11,679
Total Estimated Amount						\$39,199

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS**

Deficiency:

Assess ID **314536** Surveyor/Update
Deficiency Code ID **A14-02**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Aluminum Covered Walkways Require Replacement**
Category **Capital Renewal** System **Roofing**
Priority **2-Indirect Impact to Mission (1 Year)** Functional Adequacy **Non Related**
Correction **Replace Aluminum Walkway** Quantity / UoM
Project(s) Note **Originally part of roof replacement deficiency. Pulled out separate to reflect covered walk canopy pricing.**

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	074113100600	Aluminum roof panels, corrugated, on steel frame, painted, .018" thick	2,277	SF	3.71	\$8,448
Sub Total						\$8,448
					Construction Adjustment	35% 2,914
Construction Cost						\$11,362
					Adjustment Factor	0% 0
					Soft Cost Adjustment	42% 4,822
Total Estimated Amount						\$16,184

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS**

Deficiency:

Assess ID **314537** Surveyor/Update
Deficiency Code ID **A14-02**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Aluminum Covered Walkways Require Replacement**
Category **Capital Renewal** System **Roofing**
Priority **2-Indirect Impact to Mission (1 Year)** Functional Adequacy **Non Related**
Correction **Replace Aluminum Walkway** Quantity / UoM
Project(s) Note **Originally part of roof replacement deficiency. Pulled out separate to reflect covered walk canopy pricing.**

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	074113100600	Aluminum roof panels, corrugated, on steel frame, painted, .018" thick	2,881	SF	3.71	\$10,689
Sub Total						\$10,689
					Construction Adjustment	35% 3,688
Construction Cost						\$14,376
					Adjustment Factor	0% 0
					Soft Cost Adjustment	42% 6,101
Total Estimated Amount						\$20,477

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS**

Deficiency:

Assess ID **314538** Surveyor/Update
Deficiency Code ID **A14-02**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Aluminum Covered Walkways Require Replacement**
Category **Capital Renewal** System **Roofing**
Priority **2-Indirect Impact to Mission (1 Year)** Functional Adequacy **Non Related**
Correction **Replace Aluminum Walkway** Quantity / UoM
Project(s) Note **Originally part of roof replacement deficiency. Pulled out separate to reflect covered walk canopy pricing.**

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	074113100600	Aluminum roof panels, corrugated, on steel frame, painted, .018" thick	1,550	SF	3.71	\$5,751
Sub Total						\$5,751
					Construction Adjustment	35% 1,984
Construction Cost						\$7,734
					Adjustment Factor	0% 0
					Soft Cost Adjustment	42% 3,282
Total Estimated Amount						\$11,017

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS**

Deficiency:

Assess ID **314539** Surveyor/Update
Deficiency Code ID **A14-02**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Aluminum Covered Walkways Require Replacement**
Category **Capital Renewal** System **Roofing**
Priority **2-Indirect Impact to Mission (1 Year)** Functional Adequacy **Non Related**
Correction **Replace Aluminum Walkway** Quantity / UoM
Project(s) Note **Originally part of roof replacement deficiency. Pulled out separate to reflect covered walk canopy pricing.**

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	074113100600	Aluminum roof panels, corrugated, on steel frame, painted, .018" thick	7,599	SF	3.71	\$28,192
Sub Total						\$28,192
					Construction Adjustment	35% 9,726
Construction Cost						\$37,919
					Adjustment Factor	0% 0
					Soft Cost Adjustment	42% 16,093
Total Estimated Amount						\$54,011

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS**

Deficiency:

Assess ID **314540** Surveyor/Update
Deficiency Code ID **A14-02**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Aluminum Covered Walkways Require Replacement**
Category **Capital Renewal** System **Roofing**
Priority **2-Indirect Impact to Mission (1 Year)** Functional Adequacy **Non Related**
Correction **Replace Aluminum Walkway** Quantity / UoM
Project(s) Note **Originally part of roof replacement deficiency. Pulled out separate to reflect covered walk canopy pricing.**

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	074113100600	Aluminum roof panels, corrugated, on steel frame, painted, .018" thick	1,363	SF	3.71	\$5,057
Sub Total						\$5,057
					Construction Adjustment	35% 1,745
Construction Cost						\$6,801
					Adjustment Factor	0% 0
					Soft Cost Adjustment	42% 2,886
Total Estimated Amount						\$9,688

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/26/2016 4:04 PM

Location: **Parkway MS**

Deficiency:

Assess ID **314541** Surveyor/Update
Deficiency Code ID **A14-02**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Aluminum Covered Walkways Require Replacement**
Category **Capital Renewal** System **Roofing**
Priority **2-Indirect Impact to Mission (1 Year)** Functional Adequacy **Non Related**
Correction **Replace Aluminum Walkway** Quantity / UoM
Project(s) Note **Originally part of roof replacement deficiency. Pulled out separate to reflect covered walk canopy pricing.**

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
U	074113100600	Aluminum roof panels, corrugated, on steel frame, painted, .018" thick	2,430	SF	3.71	\$9,015	
Sub Total						\$9,015	
					Construction Adjustment	35%	3,110
Construction Cost						\$12,126	
					Adjustment Factor	0%	0
					Soft Cost Adjustment	42%	5,146
Total Estimated Amount						\$17,272	

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS**

Deficiency:

Assess ID **314542** Surveyor/Update
Deficiency Code ID **A14-02**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Aluminum Covered Walkways Require Replacement**
Category **Capital Renewal** System **Roofing**
Priority **2-Indirect Impact to Mission (1 Year)** Functional Adequacy **Non Related**
Correction **Replace Aluminum Walkway** Quantity / UoM
Project(s) Note **Originally part of roof replacement deficiency. Pulled out separate to reflect covered walk canopy pricing.**

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	074113100600	Aluminum roof panels, corrugated, on steel frame, painted, .018" thick	1,363	SF	3.71	\$5,057
Sub Total						\$5,057
					Construction Adjustment	35% 1,745
Construction Cost						\$6,801
					Adjustment Factor	0% 0
					Soft Cost Adjustment	42% 2,886
Total Estimated Amount						\$9,688

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS**

Deficiency:

Assess ID **314543** Surveyor/Update
Deficiency Code ID **A14-02**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Aluminum Covered Walkways Require Replacement**
Category **Capital Renewal** System **Roofing**
Priority **2-Indirect Impact to Mission (1 Year)** Functional Adequacy **Non Related**
Correction **Replace Aluminum Walkway** Quantity / UoM
Project(s) Note **Originally part of roof replacement deficiency. Pulled out separate to reflect covered walk canopy pricing.**

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	074113100600	Aluminum roof panels, corrugated, on steel frame, painted, .018" thick	1,350	SF	3.71	\$5,009
Sub Total						\$5,009
					Construction Adjustment	35% 1,728
Construction Cost						\$6,736
					Adjustment Factor	0% 0
					Soft Cost Adjustment	42% 2,859
Total Estimated Amount						\$9,595

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS**

Deficiency:

Assess ID **314544** Surveyor/Update
Deficiency Code ID **A14-02**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Aluminum Covered Walkways Require Replacement**
Category **Capital Renewal** System **Roofing**
Priority **2-Indirect Impact to Mission (1 Year)** Functional Adequacy **Non Related**
Correction **Replace Aluminum Walkway** Quantity / UoM
Project(s) Note **Originally part of roof replacement deficiency. Pulled out separate to reflect covered walk canopy pricing.**

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	074113100600	Aluminum roof panels, corrugated, on steel frame, painted, .018" thick	1,363	SF	3.71	\$5,057
Sub Total						\$5,057
					Construction Adjustment	35% 1,745
Construction Cost						\$6,801
					Adjustment Factor	0% 0
					Soft Cost Adjustment	42% 2,886
Total Estimated Amount						\$9,688

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS**

Deficiency:

Assess ID **314545** Surveyor/Update
Deficiency Code ID **A14-02**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Aluminum Covered Walkways Require Replacement**
Category **Capital Renewal** System **Roofing**
Priority **2-Indirect Impact to Mission (1 Year)** Functional Adequacy **Non Related**
Correction **Replace Aluminum Walkway** Quantity / UoM
Project(s) Note **Originally part of roof replacement deficiency. Pulled out separate to reflect covered walk canopy pricing.**

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	074113100600	Aluminum roof panels, corrugated, on steel frame, painted, .018" thick	1,350	SF	3.71	\$5,009
Sub Total						\$5,009
					Construction Adjustment	35% 1,728
Construction Cost						\$6,736
					Adjustment Factor	0% 0
					Soft Cost Adjustment	42% 2,859
Total Estimated Amount						\$9,595

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS**

Deficiency:

Assess ID **314546** Surveyor/Update
Deficiency Code ID **A14-02**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Aluminum Covered Walkways Require Replacement**
Category **Capital Renewal** System **Roofing**
Priority **2-Indirect Impact to Mission (1 Year)** Functional Adequacy **Non Related**
Correction **Replace Aluminum Walkway** Quantity / UoM
Project(s) Note **Originally part of roof replacement deficiency. Pulled out separate to reflect covered walk canopy pricing.**

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	074113100600	Aluminum roof panels, corrugated, on steel frame, painted, .018" thick	1,363	SF	3.71	\$5,057
Sub Total						\$5,057
					Construction Adjustment	35% 1,745
Construction Cost						\$6,801
					Adjustment Factor	0% 0
					Soft Cost Adjustment	42% 2,886
Total Estimated Amount						\$9,688

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Media Ctr**

Deficiency:

Assess ID **316297** Surveyor/Update **Eric Sheppard**
Deficiency Code ID **EA-Media**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Media Center requires renovation based on condition of room(s)**
Category **Capital Renewal** System **Other**
Priority **2-Indirect Impact to Mission (1 Year)** Functional Adequacy **Other**
Correction **Renovate / Remodel Media Center** Quantity / UoM
Project(s) Note **Room design = 380**

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
M		Allowance for renovation	1	LS	155,647.80	\$155,648
Sub Total						\$155,648
Construction Adjustment						35% 53,698
Construction Cost						\$209,346
Adjustment Factor						0% 0
Soft Cost Adjustment						48% 101,240
Total Estimated Amount						\$310,586

Broward County Public Schools
290 Parkway Middle School

Deficiency Detail

1/28/2016 4:04 PM

Location: **Parkway MS->Media Ctr**

Deficiency:

Assess ID **316351** Surveyor/Update **Eric Sheppard**
Deficiency Code ID **EA-ADARR**
Status **Estimated** FCI **Yes**
Life Cycle

Deficiency **Provide renovation of restrooms associated with educational adequacy renovations**

Category **Capital Renewal** System **Other**

Priority **2-Indirect Impact to Mission (1 Year)** Functional Adequacy **Other**

Correction **Renovate / Remodel related restrooms** Quantity / UoM

Project(s) Note **Room design = 815/816**

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension	
M		Allowance for renovation	1	LS	39,640.00	\$39,640	
Sub Total						\$39,640	
					Construction Adjustment	35%	13,676
Construction Cost						\$53,316	
					Adjustment Factor	0%	0
					Soft Cost Adjustment	48%	25,784
Total Estimated Amount						\$79,099	



Attachment H
The School Board of Broward County, Florida
Office of Facilities & Construction
3775 S.W. 16th Street
Fort Lauderdale, Florida 33312

(754) 321-1500

Consultant's Authorization To Proceed

Project No.: _____ Location No.: _____ Project Title: _____ Facility Name: _____ Project Consultant: _____	Date: _____ SBBC P.O. No.: _____ Line No.: _____ Project Manager: _____ Dir. Capital Planning & Programming _____
--	---

Under the provisions of your contract for professional services, you are hereby authorized to proceed with the following services for the project referenced above.

- | | | |
|---|---|---|
| <input type="checkbox"/> Schematic Design | <input type="checkbox"/> Design Development | <input type="checkbox"/> Construction Documents |
| <input type="checkbox"/> Bidding | <input type="checkbox"/> Construction Contract Administration | <input type="checkbox"/> Warranty |
| <input type="checkbox"/> Other Services: | Attached: _____ | |

This Authorization to Proceed is subject to the following attachments:

- Attachments:
- Professional Services Required
 - Project Schedule
 - Professional Fees
 - Previous ATP's

The scope of the required services is specified on the Professional Services Required with a Fixed Limit of Construction Cost (FLCC) for this project as indicated below:

Original FLCC	Current Cost Estimate	Revised FLCC by ATP
_____	_____	_____

The following professional services will be provided by the Project Consultant as a normal part of its Basic Services for the Project listed above:

Item	Discipline	Description
------	------------	-------------



Attachment H
The School Board of Broward County, Florida
Office of Facilities & Construction
3775 S.W. 16th Street
Fort Lauderdale, Florida 33312

(754) 321-1500

Consultant's Authorization To Proceed (Term Contracts) Cont.

Project Schedule

Project No. & Location No.: _____ Project Title: _____

Facility Name: _____
 Project Consultant: _____

The required project schedule milestones for this project are presented below. (Mandatory)

ACTIVITY	Date Required Or Estimated Time Period	
	Start	Finish
Schematic Design		
Design Development		
Construction Documents Development		
50% Construction Documents		
100% Construction Documents		
Bidding and Award of Contract		
Time for Permitting of Submittals, Prior to the Issuance of the Construction NTP (Part of Contract Administration)		
Construction		
Warranty		



Attachment H
The School Board of Broward County, Florida
Office of Facilities & Construction
3775 S.W. 16th Street
Fort Lauderdale, Florida 33312

(754) 321-1500

Consultant's Authorization To Proceed (Term Contracts)

Professional Fees

Project No. & Location No.: _____ Project Title: _____

Facility Name: _____
 Project Consultant: _____

Phase	Original Basic Fee	Fee Authorized by ATP	Fee Previously Paid	Fee Balance
I (SD) (5%)		%	%	%
II (DD) (10%)		%	%	%
III (CD) (35%/60%)		%	%	%
IV (BID) (65%)		%	%	%
V (CA) (98%)		%	%	%
VI (Warr) (100%)		%	%	%
Other Service Item No. 1		%	%	%
Other Service (Item No. 2)		%	%	%
Other Service (Item No. 3)		%	%	%
Other Service (Item No. 4)		%	%	%
Total:				

Payment for these services shall be made In accordance with the provisions of the Professional Services Agreement.

Approved By Consultant				Recommended By SBBC			
Name: _____				Name: Shelley N. Meloni			
Title: _____				Title: Director, Pre-Construction			
Signature: _____	_____	Date: _____	_____	Signature: _____	_____	Date: _____	_____
Certified By SBBC				Approval by SBBC			
Name: _____				Name: Leo Bobadilla			
Title: _____				Title: Chief Facilities Officer			
Signature: _____	_____	Date: _____	_____	Signature: _____	_____	Date: _____	_____

This document is part of the Professional Services Agreement between The School Board of Broward County, Florida (Owner) and the Design Professional and is incorporated by reference into the terms and conditions of that agreement.