REQUEST FOR QUALIFICATIONS RFQ 16-182C

DESIGN PROFESSIONAL SERVICES

Fairway Elementary School



The School Board of Broward County, Florida

Dr. Rosalind Osgood, Chair Abby M. Freedman, Vice Chair Robin Bartleman Heather P. Brinkworth Patricia Good Donna P. Korn Laurie Rich Levinson Ann Murray Nora Rupert

Robert W. Runcie, Superintendent of Schools

Leo Bobadilla - Chief Facilities Officer Barbara J. Myrick, Interim General Counsel

Office of Facilities and Construction Procurement and Warehousing Services

NOTICES TO ALL BIDDERS Cone of Silence and Lobbyist Activities

For Cone of Silence requirements and for Lobbyist Activities restrictions, refer to Section 4, Introduction and General Information lines labeled 'Cone of Silence and Lobbyist Activities' (lines 4.11 and 4.12).

THE SCHOOL BOARD OF BROWARD COUNTY, FLORIDA
Procurement and Warehousing Services Department
7720 W. Oakland Park Boulevard, Suite 323
Sunrise, Florida 33351-6704

REQUEST FOR QUALIFICATIONS (RFQ) RFQ # 16-182C DESIGN PROFESSIONAL SERVICES

RFQ Issue Date: June 21, 2016

Description of Scope:

Design Services for the following project:

Fairway Elementary School

- Safety / Security Upgrades
- Fire Alarm
- Media Center Improvements
- HVAC Improvements
- Electrical Improvements
- Building Envelope Improvements

NOTICES TO ALL PROPOSERS

Cone of Silence and Lobbyist Activities

For Cone of Silence requirements and for Lobbyist Activity restrictions refer to Section 1, Introduction and General Information lines labeled Cone of Silence and Lobbyist Activities. Line numbers 1.10 and 1.11.

THE SCHOOL BOARD OF BROWARD COUNTY, FLORIDA Procurement and Warehousing Services Department 7720 W. Oakland Park Boulevard, Suite 323 Sunrise, Florida 33351-6704

TABLE OF CONTENTS

<u>Section</u>	<u>Pac</u>
	RFQ Cover Sheet.
	Table of Contents and Attachments
1.0	Introduction and General Information
2.0	Calendar
3.0	RFQ Conditions
4.0	Required Proposal Format and Response Information
5.0	Evaluation of Qualifications
6.0	Project Scope and Schedule10
Attachment Attachment PS	A - M/WBE Participation B - Design Professional and Consultants Staffing C - Sample Professional Services Agreement (With attachments) A Attachment 1: Identified Codes, Regulations and Standards A Attachment 2: Basic Design Phasing Requirements A Attachment 3: Sample Schedule Format/Owner's Initial Schedule – for reference A Attachment 4: Sample Permitting A Attachment 5: Invoice Formats A Attachment 6: Design Fees A Attachment 7: Supplemental Services A Attachment 8: Electronic Media Requirements A Attachment 9: Conflict of Interest Form A Attachment 10: M/WBE Report Form A Attachment 11: IRS form W-9 A Attachment 12: ACH Payment Agreement Form A Attachment 13: Drug-Free Workplace A Attachment 14: Errors and Omissions Process D - Required Response Form
Attachment	E - Scope of Available Services F – Proposers Request for Information Form C - Project Scope of Work
	<u>G</u> – Project Scope of Work <u>H</u> – Authorization to Proceed Form

<u>Page</u>

SECTION 1.0 - INTRODUCTION AND GENERAL INFORMATION

- 1.1 The School Board of Broward County, Florida (hereinafter referred to as "SBBC") desires to receive Qualifications for Design Services as described herein.
- Questions and Interpretations: Any questions, requests for clarifications or interpretations regarding any portion of this RFQ during the Submittal preparation period (or reporting errors, inconsistencies, or ambiguities) shall be received no less than ten (10) days prior to the deadline due date for submitting the completed RFQ response, and no questions or clarifications will be considered after this date. Respondents must submit Document 00220 Bidders Request For Information Form (Attachment F) for all RFI requests and all RFI requests must be typed or printed. Questions not submitted on Document 00220 will not be considered. RFI requests must be for a single RFQ, RFI requests for multiple RFQs may not be considered. Any questions which require a response which amends the RFQ document in any manner will be answered via Addendum by the Procurement and Warehousing Services Department and provided to all Proposers. Address questions or requests for clarifications in writing to:

Vanessa S. Lauchaire
Strategic Sourcing Manager
Procurement & Warehousing Services
7720 West Oakland Park Blvd - Suite 323
Sunrise, FL 33351
754-321-0533 Fax

- 1.3 Any verbal or written information, which is obtained other than by information in this RFQ document or by Addenda, shall not be binding on SBBC.
- 1.4 <u>Contract Term:</u> The term of this contract is anticipated to begin on the Notice to Proceed Date and end one year after final completion of the project.
- 1.5 <u>Proposal Format:</u> The RFQ's submittal shall follow the format and include the information as identified in Section 4.0 of this RFQ.
- 1.6 <u>Evaluation and Award:</u> All Proposals will be evaluated by the Selection Committee based upon the information submitted by Proposers in response to this RFQ and in accordance with the evaluation criteria established in Section 5.0. Based upon the evaluation of Proposals, the Committee will recommend a Proposer(s) to the Superintendent of Schools who may then recommend a Proposer(s) to the SBBC for award.
- 1.7 <u>Irrevocability of Proposal:</u> A Proposal may not be withdrawn before the expiration of 90 days after the date of the Proposal's opening.
- 1.8 Proposal Package Requirements:
 - --- One complete, original hard-copy Proposal (clearly labeled as "original").
 - --- One complete, original electronic version (clearly labeled as "original").
 - --- Five (5) complete, electronic version copies (clearly labeled as "copy").
 - --- Four (4) additional hard-copies (which must be identical to the original Proposal except they shall be labeled as "copy").
 - --- Proposals shall be submitted in a sealed envelope (package, box, etc.) with the RFQ number and description clearly identified by label on the Package along with the Proposers Name.

- 1.9 <u>Gratuities:</u> Proposers shall not provide any gratuities, favors, or anything of monetary value to any official, employee, or agent of SBBC; including any School Board Member, Superintendent of Schools and any Evaluation Committee Members, for any reason during this entire Procurement Process.
- 1.10 Cone of Silence: Any proposer, or lobbyist for a proposer, is prohibited from having any communications (except as provided in this rule) concerning any solicitation for a competitive procurement with any School Board member, the Superintendent, any Evaluation Committee Member, or any other School District employee after the Procurement and Warehousing Services Department releases a solicitation to the General Public. All communications regarding this solicitation shall be directed to the designated Purchasing Agent unless so notified by the Procurement and Warehousing Services Department. This "Cone of Silence" period shall go into effect and shall remain in effect from the time of release of the solicitation until the contract is awarded by the School Board. Further, any vendor, its principals, or their lobbyists shall not offer campaign contributions to School Board Members or offer contributions to School Board Members for campaigns of other candidates for political office during the period in which the vendor is attempting to sell goods or services to the School Board. This period of limitation of offering campaign contributions shall commence at the time of the "cone of silence" period for any solicitation for a competitive procurement as described by School Board Policy 3320, Part II, Section GG as well as School Board Policy 1007, Section 5.4 Campaign Contribution Fundraising. Any vendor or lobbyist who violates this provision shall cause their Proposal (or that of their principal) to be considered non-responsive and therefore be ineligible for award. This prohibition does not apply to:
 - 1. Telephone calls to the Procurement & Warehousing Services staff to request copies of this RFQ, to confirm attendance, or request directions regarding an interview notification received;
 - 2. Delivery of the Respondent's Submittal;
 - 3. Discussion at the interview:
 - 4. Delivery of written questions about the RFQ; and/or Review of background/contract documents at the staff offices.
- 1.11 <u>Lobbyist Activities:</u> In accordance with SBBC Policy 1100B, as currently enacted or as amended from time to time, persons acting as lobbyists must state, at the beginning of their presentation, letter, telephone call, e-mail or facsimile transmission to School Board Members, Superintendent or Members of Senior Management, the group, association, organization or business interest she/he is representing.
 - 1.11.1 A lobbyist is defined as a person who, for immediate or subsequent compensation (e.g., monetary profit/personal gain), represents a public or private group, association, organization or business interest and engages in efforts to influence School Board Members on matters within their official jurisdiction.
 - 1.11.2 A lobbyist is not considered to be a person representing school allied groups (e.g., PTA, DAC, Band Booster Associations, etc.) nor a public official acting in her/his official capacity.
 - 1.11.3 Lobbyists shall annually (July 1) disclose in each instance and for each client prior to any lobbying activities, their identity and activities by completing the lobbyist statement form which can be obtained from official School Board Records, School Board Member's Offices or the Superintendent's Office and will be recorded on SBBC's website, www.browardschools.com.
 - 1.11.4 The lobbyist must disclose any direct business association with any current elected or appointed official or employee of SBBC or any immediate family member of such elected or appointed official or employee of SBBC.
 - 1.11.5 Senior-level employees and/or School Board Members are prohibited from lobbying activities for two years after resignation or retirement or expiration of their term of office.
 - 1.11.6 The Office of the Superintendent shall keep a current list of persons who have submitted the lobbyist statement form.

- 1.12 <u>Preparation Cost of Proposal:</u> Proposer is solely responsible for any and all costs associated with responding to this RFQ. SBBC will not reimburse any Proposer for any costs associated with the preparation and submittal of any Proposal, or for any travel and per diem costs that are incurred by any Proposer.
- 1.13 It is the sole responsibility of the Proposer to assure it has received the entire Proposal and any and all Addendum.
- 1.14 It is the sole responsibility of the Proposer to assure that its Proposal is time stamped in the Procurement and Warehousing Services Department on or before 2:00 p.m. EST on the date due.
- 1.15 No verbal or written information which is obtained other than by information in this document or by Addenda to this RFQ shall be binding on SBBC.
- 1.16 No submissions made after the Proposal opening, amending or supplementing the Proposal, will be considered.

SECTION 2.0 CALENDAR

June 21, 2016 Issuanc	e of RFQ #16-182C
-----------------------	-------------------

July 7, 2016 Written questions due on or before 5:00 p.m. ET

in the Procurement and Warehousing Services Department

7720 West Oakland Park Blvd., Suite 323,

Sunrise, Florida 33351-6704.

July 21, 2016 Proposals due on or before 2:00 p.m. ET

in the Procurement and Warehousing Services Department.

7720 West Oakland Park Blvd., Suite 323,

Sunrise, Florida 33351-6704.

August 10, 2016** Selection Committee reviews Qualifications and

makes a recommendation for Selection in the Procurement and Warehousing Services Department 7720 West Oakland Park Boulevard, Suite 323 Sunrise, Florida 33351-6704 at 9:00 a.m.*

August 16, 2016 Evaluation Committees Posting of Recommendations.

October 4, 2016 Tentative School Board Award Date.

Individuals with disabilities requesting accommodations under the Americans with Disabilities Act (ADA) may call Equal Educational Opportunities (EEO) at 754-321-2150 or Teletype Machine (TTY) 754-321-2158.

**Proposers may be asked to be present at this public meeting to answer questions related to their submittal. Proposers may also be invited to make a presentation to the Selection Committee. If a presentation is requested, it must be limited to information included in their Proposal submitted to SBBC. Details related to the Selection Committee meeting will be provided to the proposers when they are given notice of the meeting.

^{*}These are public meetings. SBBC prohibits any policy or procedure which results in discrimination on the basis of age, color, disability, gender identity, gender expression, national origin, marital status, race, religion, sex or sexual orientation. Individuals who wish to file a discrimination and/or harassment complaint may call the Executive Director, Benefits & EEO Compliance at 754-321-2150 or Teletype Machine (TTY) 754-321-2158.

SECTION 3.0 - RFQ CONDITIONS

- 3.1 <u>Evaluation Committees and Proposals:</u> State Statutes 119.071 and 286.0113 are adhered to by SBBC in the review and awarding of contracts.
- 3.2 <u>Public Record:</u> Proposer acknowledges that all information contained within their Proposal is part of the public domain as defined by the State of Florida Sunshine and Public Record Laws.
- 3.3 <u>Governing Law:</u> This RFQ, and any award(s) resulting from this RFQ, shall be interpreted and construed in accordance with the laws of the State of Florida. Any protests arising from this RFQ shall be subject to Section 120.57(3), Florida Statutes. Any disputes or controversies arising out of a contract awarded under this RFQ shall be submitted to the jurisdiction of the state courts of the Seventeenth Judicial Circuit in and for Broward County, Florida.
- 3.4 <u>Advertising:</u> In submitting an RFQ, Proposer agrees not to use the results therefrom as a part of any commercial advertising without prior written approval of SBBC.
- 3.5 <u>Billing Instructions and Payment:</u> All payments made to the Design Professionals shall be made by ACH (Automated Clearing House). Monthly invoices shall be submitted to the Project Manager for review and approval. Refer to the PSA for the specifics. The ACH Payment Agreement Form is an attachment to the PSA (PSA Attachment 12). This form shall be submitted at the time of the execution of the Contract.
- 3.6 <u>Contract Value:</u> No guarantee is given or implied as to the total dollar value or work as a result of this RFQ. SBBC is not obligated to place any order for services performed as a result of this award. Order placement will be based upon the needs and in the best interest of SBBC.
- 3.7 <u>Conflict of Interest and Conflicting Employment or Contractual Relationship:</u> Section 112.313 (3) and (7), Florida Statutes, sets forth restrictions on the ability of SBBC employees acting in a private capacity to rent, lease, or sell any realty, goods, or services to SBBC. It also places restrictions on SBBC employees concerning outside employment or contractual relationships with any business entity which is doing business with SBBC. Each Proposer is to disclose any employees it has who are also SBBC employees. This Conflict of Interest Form is an attachment to the PSA (PSA attachment 9). This executed document shall be submitted at the time of Contract Execution. Any employees identified by the Proposer, should obtain legal advice as to their obligations and restrictions under Section 112.313 (3) and (7), Florida Statutes.
- 3.8 Disputes:
 - 3.8.1 In the event of a conflict between the documents, the order of priority of the documents shall be as follows:
 - 1. The Agreement resulting from the award of this RFQ (if applicable); then
 - 2. Addenda released for this RFQ, with the latest Addendum taking precedence; then
 - 3. the RFQ Documents; then
 - 4. Awardee's Proposal.
 - 3.8.2 In case of any other doubt or difference of opinion, the decision of SBBC shall be put in writing and shall be final and binding on both parties.
- 3.9 <u>Insurance:</u> Refer to PSA Agreement Part 5 Article 3 for Design Professional Insurance Requirements (RFQ Attachment C).
- 3.10 <u>Public Entity Crimes:</u> Section 287.133(2)(a), Florida Statutes, as currently enacted or as amended from time to time, states that a person or affiliate who has been placed on the convicted vendor list following a conviction for a public entity crime may not submit a Proposal on a contract to provide any goods or services to a public entity, may not submit a Proposal on a contract with a public entity for the construction or repair of a public building or public work, may not submit a Proposal on leases of real property to a public entity, may not be awarded or perform work as a contractor, supplier, subcontractor, or consultant under a contract with any public entity, and may not transact business with any public entity in excess of the threshold amount

RFQ - 16-182C Design Services Revised 05/06/16 provided in Section 287.017 for CATEGORY TWO [currently \$25,000] for a period of 36 months from the date of being placed on the convicted vendor list.

3.12 <u>M/WBE:</u>

- 3.12.1 M/WBE Goals: The Design Professional shall comply with the Owner's current M/WBE policies and procedures. The Design Professional's M/WBE goal for this Contract is 25 percent.
- 3.12.2 Information: SBBC encourages each Proposer to make every reasonable effort to include M/WBE participation on any contract award under this RFQ. An M/WBE is defined by SBBC as any legal entity, other than a joint venture, which is organized to engage in commercial transactions and which is at least 51% owned and controlled by a minority or women and has been Certified by SBBC as an approved M/WBE.
- 3.12.2.1 Any participation by firms not certified by SBBC at the time of proposal will not count in the RFQ evaluation process for the award of points in the Design Professional M/WBE Participation Category. However, firms that are certified by SBBC after the proposal's tentative award, will count towards the Design Professional's M/WBE project goal attainment. Design Professional to contact SDOP to provide the updated information.
- 3.12.2.2 For information on M/WBE Certification, or to obtain information on locating certified M/WBE's, contact SBBC's Supplier Diversity and Outreach Programs at 754-321-0550 or www.broward.k12.fl.us/supply/vendors/mwbe.htm.
- 3.13 <u>Protesting of RFQ Conditions/Specifications:</u> Any person desiring to protest the conditions/specifications in this RFQ, or any Addenda subsequently released thereto, shall file a notice of intent to protest, in writing to the Director of Procurement and Warehousing Services Department. The formal written protest shall be filed within ten calendar days after the date the notice of protest was filed. Saturdays, Sundays, state holidays or days during which the school district administration is closed shall be excluded in the computation of the ten (10) calendar days. The formal written protest must be received on or before 5:00 p.m. EST of the 10th Calendar Day at the office of the Director of Procurement and Warehousing Services Department. Refer to Section 120.57(3)(b), Florida Statutes, as currently enacted or as amended from time to time, for the requirements for the written protest.
 - 3.13.1 Failure to file a notice of protest or to file a formal written protest within the time prescribed by Section 120.57(3), Florida Statutes, or a failure to post the bond or other security required by SBBC Policy 3320, Part VIII, within the time allowed for filing a bond, shall constitute a waiver of proceedings.
- Posting of RFQ Recommendations: RFQ Recommendations will be posted in the Procurement and Warehousing Services Department and on www.demandstar.com as noted on the Calendar (Section 2.0) or as modified by an addendum or by posting in the Procurement and Warehousing Services Department and at www.demandstar.com (under the document section for this RFQ). The Recommendations will remain posted for 72 hours. It is the responsibility of each Proposer to ascertain any revised date for the posting of RFQ Recommendations.
- 3.15 <u>Protest of Intended Decision:</u> Any person desiring to protest the Recommended Decision shall file a notice of protest, in writing, within 72 hours after the posting of the RFQ Recommendation and shall file a formal written protest within ten calendar days after the date the notice of protest was filed. The formal written protest must be received on or before 5:00 p.m. EST of the tenth (10) calendar day. Saturdays, Sundays, state holidays and days during which the school district administration is closed shall be excluded in the computation of the 72 hours.
 - 3.15.1 Failure to file a notice of protest or to file a formal written protest within the time prescribed by Section 120.57(3), Florida Statutes, or a failure to post the bond or other security required by Policy 3320, Part VIII, within the time allowed for filing a bond, shall constitute a waiver of proceedings.
 - 3.15.2 Notices of protests, formal written protests, and the bonds required by Policy 3320, shall be filed at the office of the Director of Procurement and Warehousing Services, 7720 West Oakland Park Boulevard, Suite 323, Sunrise, Florida 33351 Fax filing will not be acceptable for the filing of bonds.

- 3.16 <u>Use of Other Contracts:</u> SBBC reserves the right to utilize any other SBBC contract, any State of Florida Contract, any contract awarded by any other city or county governmental agencies, other school boards, other community college/state university system cooperative agreements, in lieu of any offer received or award made as a result of this RFQ if it is in SBBC's best interest to do so. SBBC also reserves the right to waive irregularities or technicalities in any Proposal received if such action is in the best interest of SBBC. However, such a waiver shall in no way modify the RFQ requirements or excuse the Proposer from full compliance with the RFQ specifications and other contract requirements if the Proposer is awarded a contract.
- 3.17 <u>Assignment:</u> Neither party to the Agreement shall sell, assign or sublet the same without the written consent of the other; nor shall a Design Professional assign any monies due or to become due to the Design Professional, or by reason of the Contract without the previous written consent of the Owner and as approved by the Attorney for the Owner.
- 3.18 <u>Cancellation:</u> In the event any of the provisions of this RFQ are violated by the Awardee, the Director of Procurement and Warehousing Services shall give written notice to the Awardee stating the violations and unless they are corrected within five days, a recommendation will be made to SBBC for cancellation.

3.19 SBBC Photo Identification Badge:

Background Screening: Awardee agrees to comply with all the requirements of Sections 1012.32 and 1012.465, Florida Statutes, and that Awardee and all its personnel who (1) are to be permitted access to school grounds when students are present, (2) will have direct contact with students, or (3) have access or control of school funds will successfully complete the background screening required by the referenced statutes and meet the standards established by the statutes. Personnel shall include employees, representatives, agents or sub-contractors performing duties under the contract to SBBC and who meet any or all of the three requirements identified above. Awardee will bear the cost of acquiring the background screening required under Section 1012.32, Florida Statutes, and any fee imposed by the Florida Department of Law Enforcement to maintain the fingerprints provided with respect to Awardee and its personnel. The Parties agree that the failure of Awardee to perform any of the duties described in this section shall constitute a material breach of this RFQ entitling SBBC to terminate immediately with no further responsibilities or duties to perform under this Agreement. Awardee agrees to indemnify and hold harmless SBBC, its officers and employees of any liability in the form of physical or mental injury, death or property damage resulting in Awardee's failure to comply with the requirements of this section or Sections 1012.32 and 1012.465, Florida Statutes.

- 3.19.1 SBBC issued identification badges must be worn at all times when on SBBC property and must be worn where they are visible and easily readable.
- 3.19.2 Badge Vendor Information shall be provided to the Design Professional at the time of Award.
- 3.20 <u>Withdrawal of RFQ:</u> In the best interest of SBBC, SBBC reserves the right to withdraw this RFQ at any time prior to the time and date specified for the Proposal opening.
- 3.21 <u>Severability:</u> In case of any one or more of the provisions contained in this RFQ shall be for any reason be held to be invalid, illegal, unlawful, unenforceable or void in any respect, the invalidity, illegality, unenforceability or unlawful or void nature of that provision shall not affect any other provision and this provision shall be considered as if such invalid, unlawful, unenforceable or void provision had never been included herein.
- 3.22 It is the sole responsibility of the Proposer to assure it has received the entire Proposal and any and all Addenda.
- 3.23 It is the sole responsibility of the Proposer to assure that its Proposal is time stamped in the Procurement and Warehousing Services Department on or before the due time on the date due. No submissions made after the Proposal opening, amending or supplementing the Proposal, shall be considered.
- 3.24 No verbal or written information which is obtained other than by information in this document or by Addenda to this RFQ shall be binding on SBBC.
- 3.25 <u>Acceptance and Rejection of Proposals:</u>
 - 3.25.1 Acceptance: All Proposals properly completed and submitted will be evaluated in accordance with Section 5.0.

- 3.25.2 Rejection: A Proposal may be rejected if it does not conform to the rules or the requirements contained in this RFQ. Examples for rejection include, but are not limited to, the following:
 - 3.25.2.1 The Proposal is time-stamped at the Procurement and Warehousing Services Department after the deadline specified in the RFQ.
 - 3.25.2.2 Proposers found legally guilty of collusion among Proposers, shall be rejected, and the participants to such shall be barred from future procurement opportunities until such time as they may be reinstated.
 - 3.25.2.3 The Proposal shows non-compliance with applicable laws; or contains any unauthorized additions or deletions; is a conditional Proposal; is an incomplete Proposal; or contains irregularities of any kind.
 - 3.26.2.4 The Proposer adds provisions reserving the right to accept or reject an award or to enter into a contract pursuant to an award or adds provisions contrary to those in the RFQ.
- 3.25.3 SBBC also reserves the right to waive irregularities or technicalities in any Proposal received if such action is in the best interest of SBBC. However, such a waiver shall in no way modify the RFQ requirements or excuse the Proposer from full compliance with the RFQ specifications and other contract requirements if the Proposer is awarded the contract.

3.26 <u>Maintenance of Records</u>:

- 3.26.1 Design Professional shall keep all records and supporting documentation which concern or reflect its Services hereunder. The records and documentation shall be retained by the Design Professional for a period of seven (7) years from the completion date of the project associated with the Authorization to Proceed; or such period of time as required by law. The Owner, or any duly authorized agents or representatives of the Owner, shall have the right to inspect and copy all such records and documentation as often as they deem necessary during the period of this Agreement and during the period noted above in which the records are to be retained. Such activity shall be conducted at the reasonable convenience of the Design Professional.
- 3.27 <u>Liability:</u> Refer to Attachment C Sample Professional Services Agreement (PSA), Part 5 Article 2 Liability Clause.
- 3.28 <u>SBBC Information Security Guidelines:</u> It is the responsibility of the Design/Builder to read and adhere to the SBBC Information Security Guidelines when using any device connected to the SBBC's network. Following the conclusion of the contract term, all of SBBC's confidential information must be removed from the Design/Builder's equipment and all access privileges must be revoked. Final payment will be withheld until the Design/Builder has confirmed, in writing, that all SBBC's confidential information has been purged from any and all electronic technology devices that were used during this contract and were connected to the SBBC's network.

SECTION 4.0 - REQUIRED QUALIFICATIONS FORMAT AND RESPONSE INFORMATION

- 4.1 The SBBC's Procurement and Warehousing Services Department shall determine whether each Proposer has Addressed and provided all RFQ submittal requirements. SBBC's Procurement and Warehousing Department shall identify the status of completion for each Proposer's proposal on a spreadsheet for the Evaluation Committee's use.
- 4.2 It is required that Proposals be organized in the manner specified below and with all the information as identified.
 - 4.2.1 Title Page:
 - Line 1 Include RFQ number and name:
 - Line 2. The RFQ Due Date:
 - Line 3 The name of the Proposer (company/firm name);
 - Line 4 Company/firm address;
 - Line 5 and telephone number.
 - 4.2.2 <u>Section A General</u>
 - <u>Section A1 Table of Contents:</u> Include a clear identification of the material by scoring sections, section number and by page number.
 - <u>Section A2 Letter of Responsibility:</u> Include the names of the persons who will be authorized to make decisions for the Proposer for this proposal, and for the Design efforts that may result from this RFQ. Provide titles, work addresses, telephone numbers and e-mail addresses. Letter to be on Company Letterhead and signed by an Officer of the Company.
 - Section A3 Signed Addenda: Include signed and dated copies of all addenda to verify and acknowledge receipt.
 - 4.2.3 <u>Section B Required Forms, Licenses, certificates, History</u>
 - 4.2.3.1 Required Response Form
 - 4.2.3.1.1 The Required Response Form shall be completed in ink or typewritten. The signed "original" Required Response Form shall be submitted within the Proposal Package labeled as the "original." Refer to Attachment D.
 - 4.2.3.1.2 Required Response Form for Joint Venture Proposals shall follow the following requirements.
 4.2.3.1.2.1 JOINT VENTURES: In the event multiple Proposers submit a joint Proposal in response to the RFQ, a single Proposer shall be identified as the Prime Proposer. If offering a joint Proposal, Prime Proposer must include the name and address of all parties of the joint Proposal. Prime Proposer shall provide all bonding and insurance requirements, execute any Contract, complete the Required Response Form shown herein, and have overall and complete accountability to resolve any dispute arising within this contract. Only a single contract with one Proposer shall be acceptable. Prime Proposer responsibilities shall include, but not be limited to, performing of overall contract administration, preside over other Proposers participating or present at SBBC meetings, oversee preparation of reports and presentations, and file any notice of protest and final protest as described herein. Prime Proposer shall also prepare and present a consolidated invoice(s) for services performed. SBBC shall issue only one check for each consolidated invoice to the Prime Proposer for services performed. Prime Proposer shall remain responsible for performing services associated with response to this RFQ.

Section B1 - Required Response Form:

Modifications or alterations to this form shall not be accepted and will cause the Proposal to be rejected and not reviewed. The Required Response Form, shall be the only acceptable form. The form with the Original

Signature shall be in the Proposal Package labeled "Original". Refer to Attachment D.

Section B2 - Licenses and Registrations (Florida)

- 3.1 All appropriate licenses shall be provided on a list
- 3.2 Firms Architectural License/Registration if applicable
- 3.3 Architectural License/Registration for _____
- 3.4 Architectural License/Registration for
- 3.5 Mechanical License/Registration for
- 3.6 Structural License/Registration for_____
- 3.7 M/WBE Certificate (if applicable) for proposer firm
- 3.8 continue as appropriate

Section B3 - Proposer History

Provide a listing of current and former business entities that the Proposer is operating under and has operated under in the past. Letter to be on Company Letterhead and signed by an officer of the Company.

Section B4 - Litigation

Provide a statement of any litigation or regulatory action that has been filed or is pending against your firm(s) in the last three years. If an action has been filed, state and describe the litigation or regulatory action filed, and identify the court or agency before which the action was instituted, the applicable case or file number, and the status or disposition for such reported action. If no litigation or regulatory action has been filed against your firm(s), provide a statement to that effect. For joint venture or team Proposers, submit the requested information for each member of the joint venture or team.

4.2.4 Section C - Experience and Qualifications (50 maximum points)

<u>Section C1 - Executive Summary / Approach / Current Work Load</u> (20 maximum points)

Executive Summary – (7 maximum points) Submit a brief abstract stating the Proposer's understanding of the nature and scope of the services to be provided and capability to comply with all terms and conditions of RFQ (3 page maximum).

Approach – (7 maximum points) Discuss your approach for delivering this project (2 page maximum).

Current Work Load – (6 maximum points) Demonstrate your ability to perform this work given your current project workload. Provide a list of current projects for SBBC (2 page maximum).

Section C2 - Firm Experience and Qualifications (15 maximum points)

Provide a statement of your firm's qualifications to perform the services requested under this RFQ (3 page maximum).

Section C3 - Relevant Projects / References (15 maximum points)

Provide a list and description of relevant projects (maximum of 5) successfully completed by your firm in the most recent five (5) years. For each project, include:

- Name and location of project
- Scope of work that was performed by your firm

- Summary of the project scope including construction delivery method
- Name, title and contact information for client
- Initial and final construction cost (where not deemed confidential)
- Change order percentage by type, including errors and omissions
- Planned design schedule vs actual design schedule

Include 3 references with contact information, preferably from one of the projects requested above (5 pages maximum for Section C3).

4.2.5 <u>Section D – Team Composition:</u> (40 maximum points)

Section D1 - Team Structure (10 maximum points)

Describe the structure of your team, including all subconsultants. Indicate which professional design services the prime firm offers with in house staff, and indicate which professional design services the firm may opt to utilize consultants. Refer to Attachment E. (3 pages maximum. Attachment E does <u>not</u> count toward page limits)

Section D2 - Key Personnel (30 maximum points)

Design Professional's Staff (15 maximum points)

Provide the names of the Design Professionals staff intended for use on SBBC Projects, including applicable professional qualifications. Identify the Principal to be in charge of SBBC Projects. Identify other key personnel as appropriate, including the Senior Architect and primary production Architect. Not all staff personnel need to be listed. It is understood that staffing requirements will vary from project to project based on project scope and required design time frame. Refer to Attachment B. Resumes for key personnel should be provided.

Consultants' Staffing (15 maximum points)

For each Consultant, provide the names of the Consultants Staff intended for use on SBBC Projects, including professional qualifications. Identify the Principal to be in charge of SBBC Projects. Identify a Senior Engineer for each of the disciplines that each Consultant performs. Refer to Attachment B. Resumes for key personnel should be provided.

4.2.6 Section E - Supplier Diversity and Outreach Program (10 maximum points)

Section E1 - M/WBE Firms for Intended Use (10 maximum points)

Identify the M/WBE firm or firms who may be working with you on this engagement utilizing Attachment A, M/WBE Participation.

SECTION 5.0 - EVALUATION OF QUALIFICATIONS

5.1 Evaluation of Qualifications - The Evaluation Committee shall evaluate all Qualified Proposals by the following Categories.

<u>SECTION</u>		POSSIBLE POINTS
Section A – General		Pass/Fail
Section B – Required Forms		Pass/Fail
Section C - Experience and Qualifications Section C 1 - Executive Summary / Approach / Curre Section C 2 - Firm Experience and Qualifications Section C 3 - Relevant Projects / References	nt Work Load	0 to 20 0 to 15 0 to 15
Section D - Team Composition Section D 1 - Team Structure Section D 2 - Key Personnel		0 to 10 0 to 30
Section E - Supplier Diversity & Outreach Program Section E 1 - M/WBE Participation	<u>n</u>	0 to 10
	TOTAL POSSIBLE POINTS	100

5.1.1 Scoring of M/WBE Participation – Section E1

The SBBC shall award a maximum of ten (10) points for M/WBE Participation as listed in the Evaluation Point Tables below. At the time the proposal is submitted, the proposer shall identify all M/WBE firms (if any) which will be utilized by using the M/WBE Participation Form and Statement of Intent Form. The Letter of Intent submitted with the proposal reflects the intent of the parties (prime and sub-consultant) to establish a business relationship as well as the type of work and percentage of work that the sub-consultant will perform.

	5 Points For M/WBE Designer
M/WBE Designer	5.0 Points

5 Pc	oints For M/WBE Sub-Consultant Participation
≥ 25%	5.0 Points
≥ 20%	4.0 Points
≥ 15%	3.0 Points
≥ 10%	2.0 Points
≥ 5%	1.0 Points

NOTE: Points for Category E shall be provided by the M/WBE Coordinator for use by QSEC members.

Qualification Selection Evaluation Committee ("QSEC") members shall rank proposers based on the total number of points received from QSEC committee member scoring, The proposer receiving the most total points received from all QSEC members shall be considered to be the most qualified proposer ("Firm 1"). All remaining proposers shall be ranked in order based on total points received from all QSEC members (Firm 2, Firm 3, Firm 4, and etc.).

- 5.2.1 The first tie-breaker between identically scored proposers shall be the total number of times the applicable proposers are ranked as the most qualified (Firm 1) by individual QSEC committee members.
- 5.2.2 The second tie-breaker between identically scored proposers shall be the total number of times the applicable proposers are ranked as the second most qualified ("Firm 2") by individual QSEC committee members.
- 5.2.3 The third tie-breaker between identically scored proposers shall be the total number of times the applicable proposers are ranked as the **third most qualified** ("Firm 3") by individual QSEC committee members.
- 5.2.4 The fourth tie-breaker shall be a coin flip, to be called in the air, by the proposer who held its discussions with QSEC first.
- 5.3 Any firm receiving a "Fail" score in Sections A or B shall be deemed non-responsive.
- After scoring has been completed, QSEC shall recommend that District staff negotiate a contract for professional design services with Firm 1 at compensation which staff determines is fair, competitive, and reasonable.
 - 5.4.1 Should staff be unable to negotiate a satisfactory contract with Firm 1, negotiations with Firm 1 shall be formally terminated.
 - 5.4.2 Staff shall then undertake negotiations with Firm 2. Should staff be unable to negotiate a satisfactory contract with Firm 2, staff shall formally terminate negotiations with Firm 2, and then undertake negotiations with Firm 3.
 - 5.4.3 This process shall continue with the remaining, most qualified firms until a satisfactory contract is negotiated. If no negotiations are successful, the procurement shall automatically terminate.
- After successful negotiations with the applicable proposer, an Agreement shall be submitted to the Board for approval and award of a Design contract.
- 5.6 <u>Award:</u> The Agreement resulting from these negotiations shall be governed by the laws of the State of Florida, and shall have venue established in the 17th Court of Broward County, Florida or the United States Court of the Southern District of Florida.

END OF EVALUATION OF QUALIFICATIONS

SECTION 6.0 - PROJECT SCOPE AND SCHEDULE

6.1 <u>Summary Project Scope</u> - The Scope of Work is summarized below.

Fairway Elementary School

- Safety / Security Upgrade
- Fire Alarm
- Media Center Improvements
- HVAC Improvements
- Electrical Improvements
- Building Envelope Improvements

6.2 <u>Project Budget</u> - The Budget for this package is as follows.

Fairway Elementary School

Total Funds from District's approved ADEFP: \$ 4,334,000

Less:

- School Choice and Technology \$ 331,000

Total Project Budget \$ 4,003,000

Less:

- Other Owner Costs \$ 200,150

TOTAL Design, Construction and Soft Cost Funds \$ 3,802,850

6.3 <u>Project Schedule</u> - The Schedule for this project is as follows:

Authorization to Proceed October 25, 2016
Completion of Design July 10, 2017
Final Completion – Construction January 29, 2019

END OF RFQ

M/WBE PARTICIPATION

Complete the following information on the proposed M/WBE participation on this contract.

Proposer's Company Name:	
--------------------------	--

M/WBE Firm Information	Scope and/or Nature of Work to be Performed by the M/WBE	% of M/WBE Participation
Firm Name:		
Contact Person:		
Address:		
Telephone No.:		
Facsimile No.:		
M/WBE Certification No.:		
Certifying Agency Name:		
Address:		
Telephone No.:		
Firm Name:		
Contact Person:		
Address:		
Telephone No.:		
Facsimile No.:		
M/WBE Certification No.:		
Certifying Agency Name:		
Address:		
Telephone No.:		
Firm Name:		
Contact Person:		
Address:		
Telephone No.:		
Facsimile No.:		
M/WBE Certification No.:		
Certifying Agency Name:		
Address:		
Telephone No.:		

Note: percentage amount needs to be provided to receive points.

School Board of Broward County MWBE Forms Revised 12/1/15

Design and Professional Consulting Staff

Prime Firm:

Name	Title	Role	Time Commitment	Florida professional license	Email Address

Subconsultant:

Name	Title	Role	Time Commitment	Florida professional license	Email Address

Subconsultant:

Name	Title	Role	Time Commitment	Florida professional license	Email Address

Subconsultant:

Name	Title	Role	Time Commitment	Florida professional license	Email Address

ATTACHMENT C

Professional Services Agreement

PROFESSIONAL SERVICES AGREEMENT

BETWEEN

THE SCHOOL BOARD OF BROWARD COUNTY, FLORIDA

AND

PROJECT CONSULTANT

FOR

ARCHITECTURAL/ENGINEERING SERVICES

	SAGREEMENT, made this, day of in the year, by and between
THE	SCHOOL BOARD OF BROWARD COUNTY, FLORIDA, hereinafter called the "Owner", and
herea	fter called the "Project Consultant" for the following project:
	Facility:
	Site No.:
	Project Name:
	Project No:
	Fixed Limit Of Construction Cost (FLCC): \$
TT1 6	
The (wher and Project Consultant agree as follows:

TABLE OF CONTENTS

ARTICLE 1	DEFINITIONS

- ARTICLE 2 PROJECT CONSULTANT SERVICES AND RESPONSIBILITIES
- ARTICLE 3 SUB-CONSULTANTS
- ARTICLE 4 THE OWNER'S RESPONSIBILITIES
- ARTICLE 5 BASIS OF COMPENSATION
- ARTICLE 6 PAYMENTS TO THE PROJECT CONSULTANT
- ARTICLE 7 REUSE OF DRAWINGS, SPECIFICATIONS AND OTHER DOCUMENTS
- ARTICLE 8 INDEMNIFICATION
- ARTICLE 9 INSURANCE
- ARTICLE 10 GENERAL PROVISIONS
- ARTICLE 11 INCORPORATION OF DOCUMENTS INTO AGREEMENT

ATTACHMENTS:

Attachment 1: Project Schedule Attachment 2: Project Scope

Attachment 3: Electronic Media Submittal Requirements

Attachment 4: Project Consultant's Invoice Format, Reimbursable and Supplemental Services Format

Attachment 5: List of Project Team Members

Attachment 6: Authorization to Proceed (ATP) Form

Professional Services Required – page 1 of 3

Project Schedule – page 2 of 3 Professional Fee – page 3 of 3

Attachment 7: Document Submittal Checklist

Attachment 8: Document 00455 – Background Screening

Attachment 9: IRS Form W-9

Attachment 10: Truth in Negotiations Certificate

ARTICLE 1 DEFINITIONS

- The Office of Facilities & Construction ("Office" or "OFC"): The Owner's organizational entity which acts as liaison between the Consultant and Owner and provides day to day management and other professional services on the Owner's behalf. Various members of the Office of Facilities and Construction, acting as representatives of the Owner, will meet with the Project Consultant at periodic intervals throughout the preparation of the Contract Documents to assess the progress of the Work in accordance with approved schedules. Office personnel will also examine documents submitted by the Project Consultant, including invoices, and will promptly render decisions and/or recommendations pertaining thereto to avoid unreasonable delay in the progress of the Project Consultant's work. The Project Manager shall be principally responsible for direct communication to the Project Consultant and the Contractor.
- 1.2 **The Chief Facilities & Construction Officer, Office of Facilities & Construction -** An employee of The School Board of Broward County, Florida, who has the authority and responsibility for oversight and management of the specific project for the Owner. Referred to hereinafter as the Chief Facilities & Construction Officer.
- 1.3 **Authorization to Proceed:** A fully executed and approved authorization in the form of Attachment 6 to this Agreement, Authorization to Proceed ("ATP") accompanied by an executed purchase order document issued by the Owner to the Project Consultant, authorizing the performance of specific professional services, authorizing commencement of a Phase as defined in Article 2.1 through Article 2.8, and stating the time for completion and the amount of fee authorized for such services.
- 1.4 **Basic Services**: Those architectural, engineering and other professional design services defined in Article 2.1 through Article 2.8.
- 1.5 **Supplemental Services**: Those architectural, engineering and other professional design services defined in Article 2.9.
- 1.6 **Project Consultant:** The individual, partnership, corporation, association, joint venture, or any combination thereof, of professional architects, engineers or other design professionals properly registered and licensed in Florida, who has entered into a contract with the Owner to provide professional services for development of the design and contract documents for the Work of this Project and provide construction contract administration and warranty services as described in the Project Manual and under this Agreement.
- 1.7 **Project Scope**: The activities necessary to respond to the Owner's requirements for the Project, including but not limited to the full or partial range of design, bidding and construction support services required to meet

- the Owner's educational program, construction standards, project construction support requirements, Project Budget and Project Schedule.
- 1.8 **Project Budget**: The sum, established by the Owner, as available for the entire Project, including but not limited to the construction budget (Fixed Limit of Construction Cost ("FLCC")), land costs, costs of furniture, fixtures and equipment (FF&E), financing costs, compensation for all professional services, costs of Owner-furnished goods and services, contingency allowances and other similar established or estimated costs.
- 1.9 **Project Schedule**: The Owner's requirements for the progress of design and construction activities associated with the Project characterized by milestones signifying the required completion dates for design phases, construction progress, and other significant project events culminating with the completion of the project, issuance of warranties, Owner's occupancy and use of the new or improved facilities.
- 1.10 **The Contract Documents:** The Contract Documents as used herein refer to the Agreement Form, Addenda, Supplementary Conditions, General Conditions, Documents contained in the Project Manual, the Owner's Division 0 and Division 1 documents, Drawings, Specifications, Education Specifications, all modifications thereto, issued before and after execution of the Contract and all Exhibits attached thereto used by the Owner to establish a construction contract with the Contractor. These Contract Documents, and their requirements for the Project Consultant are incorporated by reference into this Agreement.
- 1.11 **Contractor:** The individual, partnership, corporation, association, joint venture, or any combination thereof, who has entered into a contract with the Owner for construction of schools, administrative and support buildings, or various other types of facilities and incidents thereto.
- 1.12 **Program Manager:** An entity hired by the School Board of Broward County to execute the delivery of the projects and act as the Owner's Representative.
- 1.13 **Project Manager**: An employee or designated representative of The School Board of Broward County, Florida, who is assigned by the Chief Facilities and Construction Officer to manage the Project as a direct representative of the Owner.
- 1.14 **The Project:** The design of new construction, remodeling and/or renovation, and all services and incidents thereto, comprising a structure, structures, facility or facilities as contemplated and budgeted by the Owner.
- 1.15 **Sub-Consultant:** A person or organization of professional architects, engineers or other design professionals, registered and licensed in Florida, who has entered into an Agreement with the Project Consultant to provide professional services for the project.
- 1.16 **Superintendent Of Schools:** The duly appointed executive officer of the Owner authorized to act by and through The School Board of Broward County, Florida. Referred to hereinafter as the Superintendent.
- 1.17 **Fixed Limit of Construction Cost:** The Fixed Limit of Construction Cost, referred to hereinafter as the FLCC, is the total dollar value of the sum of the project's anticipated base bid (the project's essential scope) including design contingency.
- 1.18 **Building Code Inspector and Plans Examiners (BCI):** Employees of The School Board of Broward County, Florida, and others designated by the Chief Building Official, who are certified by Florida Statutes 468, 633 and 553 a BCI by the Florida Department of Education to provide plan review, inspections for code compliance and report non-compliant work to the appropriate party.

- 1.19 **Value Engineering:** Value Engineering (VE) is the creative, organized process of analysis of a project as to cost and/or performance with a focus on analysis of the proposed facility (and its systems, assemblies or components) and the elimination or modification of those features which add cost without contributing to that facility's required function or design value.
- 1.20 **Constructability:** Constructability is the creative, organized process of reviewing a project's drawings, specifications and other project documentation with a goal of eliminating design, detailing, and specification problems which might render the construction contract documents unbuildable or requiring extensive Addenda or Change Orders to make them buildable.
- 1.21 **The Project Team** The Owner, Program Manager, and the Project Consultant, collectively the "Project Team", shall work jointly during the design and through the completion of the warranty phase and shall be available thereafter should additional services be required.
- 1.22 **Substantial Completion:** The term Substantial Completion as used herein, shall mean that point at which the Work, or a designated portion thereof, is at a level of completion in substantial compliance with the Contract Documents such that the Owner or its designee can enjoy use or occupancy and can use or operate it in all respects for its intended purpose. In the event the Work includes more than one Phase, the Owner, at its discretion, may set Substantial Completion dates for each Phase and may impose provisions for liquidated damages for each Phase.
- 1.23 **Chief Building Official, Inspections and Code Compliance:** ("CBO") An employee of The School Board of Broward County, Florida, who has the responsibility for oversight and management of the Building Department, and has the authority and responsibility for issuing Building Permits.
- 1.24 Code: The term Code means and refs to all applicable codes, laws and regulations of each governmental entity, as may be amended from time to time, in effect at the time of execution of this Agreement, including all codes and standards referenced therein, including, but not limited to:, the Fifth Edition of the 2014 Florida Building Code (the "FBC"), the Fifth Edition of the Florida Fire Prevention Code, Chapter 1013, Florida Statutes (2015)Florida State Board of Education Regulations ("SREF"), Chapter 6A-2.0111 (Educational Facilities), the 1999 State Requirements for Educational Facilities (2014)Florida Department of Education's State Requirements for Educational Facilities ("SREF")adopted pursuant to Rule 6A-2.0111, Florida Administrative Code, as may be amended from time to time, to the extent such requirements are not in conflict with Section 235.211, Florida Statutes 1995, Americans With Disabilities Act (ADA), in effect at the time of execution of this Agreement, and its referenced codes and standards; Crime Prevention Through Environmental Design (CPTED) (Broward Sheriff's Office), and all guidelines and regulations of the Owner (provided same are not less stringent than applicable codes) with the Owner serving as the interpreter of the intent and meaning of SREF or any other applicable code

ARTICLE 2 PROJECT CONSULTANT SERVICES AND RESPONSIBILITIES

- 2.1 Basic Services
- 2.1.1 The Project Consultant agrees to:

- .1 Provide complete professional architectural, engineering and/or other professional design services set forth in the six Phases enumerated hereinafter and all necessary personnel, equipment and materials to perform such services;
- .2 Complete those design services in accordance with the Project Schedule (Attachment 1 to this Agreement).
- .3 Collaborate in the Owner's programs of Value Engineering at the end of Phases I and II (Schematic Design and Design Development), Constructability Reviews at the end of Phase III (Construction Documents), Statement of Probable Construction Cost at end of each phase, SIT Award Application and other additional basic services as provided in Article 2.1 through Article 2.8.
- 2.1.2 Standard Of Care: The Owner's engagement of the Project Consultant is based upon the Project Consultant's representations to the Owner that:
 - .1 It is an organization of experienced design professionals, registered and licensed to do business in Florida;
 - .2 It is qualified, willing and able to perform architect and engineer of record services for the Project; and that
 - .3 It has the past experience and ability to provide design and engineering services for projects of similar size and scope which will meet the Owner's objectives and requirements.
- 2.1.3 As to all services provided pursuant to this Agreement, the Project Consultant shall furnish services by experienced personnel and under the supervision of experienced professionals licensed in Florida, and shall exercise a degree of care and diligence in the performance of these services in accordance with the customary professional standards currently practiced by firms in Florida and in compliance with any and all applicable codes, laws, ordinances, etc. The Project Consultant shall utilize the same personnel over the course of the Work and shall, if requested by the Owner, replace personnel whom the Owner has found to be incompetent or to whom the Owner otherwise reasonably objects.
- 2.1.4 As to any and all drawings, plans, specifications or other contract documents or materials provided or prepared by Project Consultant or its Sub-Consultants, the Project Consultant agrees same:
 - .1 Are sufficiently complete, accurate, and adequate for bidding, negotiating and constructing the Project and are consistent with the Owner's requirements and Owner approved Project Budget and Project Schedule;
 - .2 Meet the Owner's aesthetic, functional and operational objectives;
 - .3 Are sufficiently fit and proper for the purposes intended;
 - .4 Comply with all applicable laws, statutes, rules and regulations, building codes and Owner's guidelines or regulations, which apply to and govern the Project, and
 - .5 Will, if constructed in accordance with the Project Consultant's Design, result in a complete and properly functioning facility. Any defective drawings, specifications or other document furnished by

Project Consultant shall be promptly corrected by the Project Consultant at no cost to Owner, without limitations to other remedies or rights of Owner. Owner's approval, acceptance or use of or payment for all or any part of Project Consultant's services hereunder or of the project itself shall in no way alter the Project Consultant's obligations or Owner's rights hereunder.

- .6 Further, any approval of drawings or construction documents by Owner and/or other governmental entities having jurisdiction which do not expressly comment and/or interpret a building code requirement shall not relieve the Project Consultant from its obligations to furnish design services pursuant to the applicable building codes nor be the basis for a waiver defense should Owner accept and/or approve any drawings and/or contract documents wherein an error or omission is not discovered during the design process.
- 2.1.5 All professional design services and associated products or instruments of those services provided by the Project Consultant shall:
 - Be in accordance with all applicable codes, laws and regulations of each governmental entity, as may be amended from time to time, in effect at the time of execution of this Agreement, including all codes and standards referenced therein, including, but not limited to: the Fifth Edition of the 2014 Florida Building Code (the "FBC"), the Fifth Edition of the Florida Fire Prevention Code, Chapter 1013, Florida Statutes (2015), the State Requirements for Educational Facilities (2014) ("SREF"), Crime Prevention Through Environmental Design (CPTED) (Broward Sheriff's Office), and all guidelines and regulations of the Owner (provided same are not less stringent than applicable codes) with the Owner serving as the interpreter of the intent and meaning of SREF or any other applicable code (all of the above-referenced codes, laws, regulations and standards referenced therein are herein collectively referred to as "Code");
 - .2 Be provided for the benefit of the Owner and not for the benefit of any other party; and
 - .3 Include all of the design services normally required for a project of this type as listed in the Project Scope (Attachment 2 to this Agreement).
 - .4 Notwithstanding any other provisions of this Agreement to the contrary, any substantially affected person may appeal any building code dispute or interpretation of the Chief Building Official of the School Board of Broward County, Florida to the Florida Building Commission as set forth in section 1013.37, Florida Statutes and the FBC, as amended.
- 2.1.6 The Project Manager shall schedule and conduct a bi-weekly project review meeting with representatives of the Project Consultant throughout Phases I through IV of the Project. At each of these meetings, the Project Consultant and Owner shall review the Project's budget, schedule, and scope along with the Project Consultant's development and progress to date on the respective phases of the Project and any special problems related to the continuing progress of the project. The Project Consultant shall attend weekly meetings during Phase V (Construction) as required elsewhere in this Agreement. For each project review meeting, and as may be otherwise appropriate during any project phase, the Project Consultant shall provide progress sketches and other documents sufficient to illustrate progress and the issues at hand for the Owner's review, which will be made so as to cause no delay to the Project Schedule.
- 2.1.7 The Project Consultant's services shall conform to Owner's specifications, including but not limited to, Owner's Design and Materials Standards Manuals, Design Criteria, Educational Specifications, Document

Submittal Checklist for Plan Review and Owner's Forms for capital projects, provided, however, that in the event of conflict, the provisions of this Agreement shall govern.

- Non-Conforming Work: If the Owner (by way of BCI's or other Owner personnel or consultant) observes or otherwise becomes aware of any fault or defective Work in a project, or other non-conformance with the Contract Documents during the construction phases, the Owner or Program Manager shall give prompt notice thereof to the Project Consultant. However, whether the Owner observes a defect or not, it is the Project Consultant's duty and responsibility to determine whether said Work is defective, faulty, or not in compliance with the Contract Documents. If the Project Consultant determines that the Work is defective, faulty or not in conformance with the Contract Documents, the Project Consultant shall advise the Owner in writing and make recommendations to the Owner concerning correction of the Work. The Owner may then require the Contractor to undertake such corrections as allowed by the Contract Documents. Final determination of whether the Work is defective, faulty or in compliance with the Contract Documents is to be determined by the Owner.
- .2 **Penalty for Non-Conforming Design Documents:** Should the Project Consultant submit drawings, plans, specifications or other documents or materials for review as required herein that are deemed unacceptable as defined by the terms "Revise and Resubmit" by the plan review authority (Building Department, Design Services Department, Peer Plan Review Consultant), the costs, as solely determined by the Owner, for all subsequent reviews after the second review for that Phase shall be borne by the Project Consultant and the Owner will deduct such costs from the Project Consultant's Basic Services Fee.
- 2.1.8 The Project Consultant shall keep the Owner informed of any proposed changes in requirements or in construction materials, systems or equipment as the drawings and specifications are developed. Proposed changes must be reviewed by the Owner and approved in writing by Owner prior to incorporation into the design or construction documents.
- 2.1.9 The Project Consultant shall coordinate with Owner by participating and taking a leadership role in, reviewing and commenting on Constructability and Value Engineering studies performed by Owner, and attending meetings, where the content of design and construction contract documents will be coordinated and reconciled, scheduled during any phase of the project. In the event Owner accepts recommendations from Value Engineering and Constructability studies, the Project Consultant shall implement same, including providing revised drawings and specifications or other documents. In the event the Owner accepts such a recommendation from the Constructability and/or Value Engineering studies and requires substantial revisions by the Project Consultant, as determined at the discretion of the Owner, these revisions shall be considered Supplemental Services.
- 2.1.10 **Approval of Documents**: Owner's approval of or comments on any of the documents submitted to Owner by Project Consultant shall not be deemed the approval of or by another governmental authority having jurisdiction over the project and Project Consultant acknowledges that the aforesaid authorities may require modifications of any of the documents submitted by Project Consultant. Subject to Article 2, such modifications shall be made at no cost to Owner.

2.2 PHASE I - Schematic Design:

- 2.2.1 The Project Consultant shall confer with representatives of the Owner to verify and confirm the Program (as appropriate to the type of project), consisting of a detailed listing of all functions and spaces together with the square footage of each assignable space, gross square footage, and a description of the relationships between and among the principal programmatic elements. (If the project needs are so unique that a special analysis of the requirements is necessary to establish a more detailed program, such services may be authorized as Supplemental Services).
- 2.2.2 The Project Consultant shall, prior to commencing Phase I design activities, receive a fully approved and executed ATP and Purchase order (See 5.2.3), visit and inspect the site to verify if existing conditions conform to those portrayed on information as may have been provided by the Owner:
 - .1 Take photographs and make written documentation, sketches, notes or reports to confirm and record the general condition and age of the existing equipment and site with particular attention to the following building/site elements as appropriate to the Project:
 - .1 All above ceiling areas.
 - .2 Power supplies, switch gear, breaker panels, electrical room, electrical vault, transformers and mechanical room.
 - .3 Major components of existing HVAC systems including chillers, cooling towers, air handling units, and primary ductwork runs.
 - .4 Roofing, waterproofing and building envelope systems.
 - .5 Site drainage systems and water retention characteristics.
 - .6 Determine age and condition of fixed equipment.
 - .7 Life safety, fire alarms, public address, generators and emergency lighting.
 - .8 ADA requirements.
 - .2 Site investigations and inspections and access to concealed areas should be non-destructive except where destructive investigations, tests or means of access are authorized in advance by the Owner.
- 2.2.3 In the event that the Project Consultant believes that the project scope, schedule or budget is not achievable, the Project Consultant shall immediately notify the Owner in writing as to the reasons one or all of them are unreasonable or not achievable immediately upon discovery.
- 2.2.4 The Project Consultant shall review with Owner alternative approaches to design and construction of the project; site use and improvements; selections of materials, building systems and equipment; potential construction methods; and, if requested, shall make a recommendation among such alternatives.
- 2.2.5 The Project Consultant shall prepare, submit and present to Owner for approval by the Owner a Design Concept and Schematics Report, comprised of the SREF requirements for Schematic Design Documents and Schematic Design Studies, including an identification of any special requirement(s) affecting the Project, a Project Development Schedule, and a Statement of Probable Construction Cost, as defined below:

- .1 "Project Transmittal Form" as required by the Facilities and Construction Management Division's Design Services Department.
- .2 OEF form 208(a) "OEF Space Chart Form" formatted to follow the sequence of spaces listed in the SREF Size of Space and Occupant Design Criteria Table.
- .3 A hardcopy and electronic media copy of a site survey with the following information: the legal description of the site, acreage, points of the compass, contours, overall dimensions, vegetation, trees, hardscape elements, adjacent highways and roads, information about ownership and use of adjacent land, locations of on- and off-site utility connections, utility service point entry locations, parking areas, service areas, play areas, athletic fields, bus loop(s), parent drop off, existing buildings with height, mechanical cooling towers and chillers, floor elevations (related to base flood elevation as shown on Flood Insurance Rate Maps), and use. The site survey will be an update of informational surveys provided by the Owner but shall be prepared on electronic media and submitted in both hard and electronic media formats. (Attachment 3 to the Agreement).
- .4 **Schematic Drawings.** These documents shall be schematic drawings responding to the educational specifications and program requirements illustrating the general scope, scale, and relationship of project components. In addition to SREF requirements and information required by the Owner's document submittal checklist for phase I, the documents shall include the following:
 - .1 A site plan showing acreage, points of the compass, scale, contours and general topographical conditions, flood plain elevation and velocity zone, over-all dimensions, adjacent highways, roads, off-site improvements, emergency access, fire hydrants, power transmission lines, ownership and use of adjacent land, walks and paths, vehicle and bike parking areas, accessibility for the disabled, service areas, play areas, athletic fields, bus loop(s), parent drop off, existing buildings and use, location of proposed building(s) and future additions, portable classrooms and other relocatable or temporary structures, community use buildings, phased construction, preliminary soil borings. A statement shall be included on the site plan identifying the FEMA flood plain and velocity zone in which the project is located. The statement shall be signed and dated by the Project Consultant.
 - .2 Evidence, as jointly developed with the Owner, showing that required environmental studies have been completed and sensitive site areas have been identified as required by Florida Law or the Owner or any governmental entity having jurisdiction over the project site.
 - .3 Floor plans showing points of the compass, over-all dimensions, identity of each space, proposed door locations, accessibility for the disabled, Florida Inventory of School House (FISH) numbers, occupant load of each space, proposed passive design and low energy usage features, possible community service areas and instructional spaces that can be converted to community use areas, mechanical and electrical rooms, any existing buildings and use, future additions, and phased construction. Provide a life-safety plan delineating the necessity for and initial decisions concerning exits, accessibility for the disabled, fire walls, protected corridors, smoke partitions, fire alarm systems, fire sprinkler systems, room names and numbers, and any other life-safety features relevant to the facility.
 - .4 Provide elevations and sections of the building to fully illustrate and indicate the mass and character of the facility including fenestration, openings, walkways, preliminary material selections, and other building features and spatial relationships.

- .5 A Preliminary Project Description comprised of a narrative discussion of preliminary material selections, components, assemblies, and systems (including proposed landscape, civil, structural, mechanical, and electrical design elements, components and systems) to be used in the project. Coordinate points of service and preliminary service requirements with Florida Power and Light (FPL), BellSouth, cable TV, water, sewer, storm drainage and other utility services as required by the Project's scope and program. Format Preliminary Project Descriptions to match that specified by the latest edition of the Construction Specification's Institute's "Manual of Practice".
- Mechanical Requirements Specific to Remodeling and Addition Projects: Provide a listing of capacities for existing HVAC equipment and the available tonnage for the new connected load. Provide a survey of the condition of the existing mechanical equipment.
- .7 Electrical Requirements Specific to Remodeling and Addition Projects: Provide an electrical load analysis for the existing facility for existing and new loads. Provide a survey of the condition of the existing electrical equipment and the communication equipment room.
- A **Project Design Schedule:** The Project Consultant shall prepare a schedule of services (Project Design Schedule) in compliance with Project Schedule and for approval by the Owner. Such schedule shall show activities including but not limited to Project Consultant efforts and Owner reviews and approvals required to complete services. This schedule shall initially be submitted to Owner for approval within twenty-one (21) days of execution of this Agreement. As a condition of payment, Project Consultant will submit with each invoice a copy of the approved schedule showing progress (indicated by percentage complete) as of the invoice cutoff date and a forecast of when each phase of Project Consultant's work will be complete. No subsequent payment shall be made if Project Consultant has not obtained approval of his work schedule, the schedule is not updated, or a forecast is not submitted with each invoice (provided that Owner conducts its review promptly and does not withhold its approval unreasonably). The project development schedules shall set forth in detail the following:
 - .1 Include all activities required to complete the design phase of the project.
 - .2 Prepare in a bar chart format, or other format as required by the Owner, which may be further developed and updated for submittal during subsequent phases of the Basic Services.
 - .3 The Project Consultant shall not be permitted to deviate from the milestones indicated on the Project Schedule without specific written authorization from the Owner (Attachment 1 of this Agreement).
- .9 The Statement of Probable Construction Cost: The Consultant shall submit to Owner for review and Owner's approval a schematic design phase estimate of probable construction cost prepared by an independent cost estimator approved by Owner, itemized by major categories and projected to the expected time of bid.
- .10 Twenty-five (25) copies of a Design Concept and Schematics Report which will be utilized to communicate the schematic design and shall include: Reduced color drawings (Site and building plans, elevations, sections, sketch perspectives and miscellaneous diagramming), photographs of massing and building models, a facilities list (including the number of spaces, net/gross square footages, etc.), the Project Development Schedule, and a summary design statement indicating the general design intent, conceptual development, and preliminary material, assembly and system

selections. Provide brochure with heavy stock covers and plastic comb or metal spiral binding. Additional copies of the Schematic Design Brochure if required by the Owner will be compensated as a reimbursable service approved in advance by the Owner.

- 2.2.6 The Project Consultant shall coordinate with the assistance of the Owner to determine the municipal, county and other jurisdictional agency (such as the South Florida Water Management District, etc.) coordination required for the Project and, make applications for site plan and other review as appropriate to this phase of the project. The Project Consultant shall attend and provide representation at all review meetings, workshops, hearings and Commission/Council meetings concerning the project as conducted by any and all other agencies having jurisdiction over the project.
- 2.2.7 The Project Consultant shall submit seven (7) copies of all full size documents required under this Phase, and a completed document submittal checklist, without additional charge, for review and approval by the Owner. The Project Consultant shall not proceed with the next Phase until the completion of all required presentations and reports and receipt of a written Authorization to Proceed with the next phase.
- 2.2.8 The Project Consultant shall provide presentations of the Schematic Design to the Owner's staff, Design Review Committee and to The School Board of Broward County, Florida, as required.

2.3 Phase II - Design Development:

- 2.3.1 Only after receiving a fully approved and executed ATP and Purchase order (See 5.2.3), from Owner and based on the approved Schematic Design Documents and any adjustments authorized by Owner in the Project Scope, Project Schedule or Project Budget, the Consultant shall prepare, submit and present for review and approval by the Owner, Design Development Phase documents, comprised of the SREF requirements for Design Development documents and the following:
 - .1 "Project Transmittal Form" as required by the Facilities and Construction Management Division's Design Section.
 - .2 OEF form 208 (a) "OEF Space Chart Form" formatted to follow the sequence of spaces listed in the SREF Size of Space and Occupant Design Criteria Table.
 - .3 **Documents:** These documents shall be design development drawings corresponding to the educational specifications and program requirements illustrating the general scope, scale, and relationship of project components. In addition to Phase I requirements, SREF requirements, and information required by the Owner's document submittal checklist for phase II, the documents shall include the following:
 - .1 Architectural and Civil site plan(s) showing, in addition to Phase I site survey requirements, landscaping, drainage, water retention ponds, sewage disposal and water supply system, chilled water supply and return piping and such physical features that may adversely affect or enhance the safety, health, welfare, visual environment, or comfort of the occupants.
 - .2 A statement, signed and dated by the Project Consultant or his designated Sub-Consultant, included on the site plan identifying the number of existing trees, the number and size of required trees, and the number of new trees to be planted.

- .3 Soil testing results including a copy of the Geotechnical Engineer's report on the site. When unusual soil conditions or special foundation problems are indicated, submit the proposed method of treatment.
- .4 Plan(s) including, but not be limited to, the following:
 - .1 Floor plan drawn at an architectural scale that will allow the entire facility to be shown on one sheet, without break lines and which indicates project phasing as applicable to the Project.
 - .2 Floor plans drawn at 1/8 inch or larger scale showing typical student occupied spaces or special rooms with dimensions, sanitary facilities, stairs, elevators, and identification of accessible areas for the disabled.
 - .3 Floor plans drawn at 1/4 inch or larger scale showing typical spaces or special rooms with dimensions, equipment and furnishing layouts.
 - .4 Floor plans for additions to an existing facility: Indicate the connections and tie-ins to the existing facilities, including all existing spaces, exits, plumbing fixtures and locations, and any proposed changes thereto. Distinguish between new and existing areas for renovation, remodeling, or an addition.
 - .5 Floor plans drawn at 1/4 inch or larger scale showing typical spaces or special rooms with dimensions, indicating door and window layouts.
 - .6 Reflected ceiling plans drawn at 1/4 inch or larger scale showing typical spaces or special rooms with dimensions, lighting equipment and ceiling panel layouts.
 - .7 Roof plans drawn at 1/4 inch or larger scale showing typical spaces or special rooms with dimensions, equipment layouts.
- .5 Life-safety plans to show exit strategy, rated doors, emergency wall openings, fire walls working stage protection, range and fume hoods, eye wash, emergency showers, ramps and vertical lifts.
 - .1 By symbol, indicate fire extinguishers, fire alarm equipment, smoke vents, master valves and emergency disconnects, emergency lighting, emergency power equipment, fire sprinklers, exit signs, smoke and fire dampers, and other life-safety equipment relevant to the facility.
 - .2 By symbol, indicate connections and tie-ins to existing equipment.
 - .3 For existing facilities where remodeled or renovated spaces are required and where an ADA and code conforming ramp cannot be utilized, document proposed vertical platform lifts or inclined wheelchair lifts and provide the following documents as part of or in addition to the required life safety plans:
 - .1 Sketches of proposed vertical platform lifts, including layout drawings showing the effect of the lift on existing spaces, corridor widths and exiting from the affected facility.

- .2 Sketches of proposed inclined wheel chair lift including layout drawings showing the effect of the lift on the stairway width in the folded and unfolded position, the upper and lower platform storage locations, and the effect on exiting from the affected areas of the facility.
- .6 When planning open space schools or administrative spaces, a floor plan shall be submitted showing the methods used to permanently define the means of egress, such as surface finish or color.
- .7 Plumbing fixture locations and fixture unit calculations.
- .8 All exterior building elevations and sufficient building sections as necessary to fully illustrate and indicate the scale and massing of the facility.
- .9 Typical building sections to show dimensions, proposed construction materials, and relationship of finished floor to finished grades.
- .10 Preliminary Structural Drawings including plans and sections indicating systems, connections and foundations. These drawings may be structural roughs.
- .11 Mechanical Drawings including reflected ceiling plans and a single line diagram of the duct layout, location of grease trap(s), LP gas tank location, and natural gas pipe lay out, tie in to existing utilities. Enhance systems description to include a description of proposed HVAC system equipment including the chiller, pumps, AHU's, cooling tower, electric duct heaters, etc.
- .12 Electrical Drawings including reflected ceiling plans, lighting layouts for the outdoors and interior spaces, and a one line diagram of the electrical distribution showing electrical outlets for all systems in all spaces. Provide layout for energy management, computer networking and security systems. Location of all the main components of the electrical system such as transformers, panels, and main switch board, and emergency generator, location of the intercom console, ITV head end and tower, master clock, fire alarm panel. Also, show locations of mechanical equipment such as chillers, air handler units, etc. and their respective electrical connections.
- .13 **Equipment and Furnishing Schedules:** Indicating equipment and furnishing items that will be provided by the Contractor and those that will be provided by the Owner or others.

.14 **Outline specifications:**

- .1 Organized according to the Specification Section numbering system specified in the Construction Specifications Institute's current edition of Masterformat on the date of execution of the Contract.
- .2 Formatted to conform to the formats for outline specifications as established by the Construction Specifications Institute.
- .3 Complete for Divisions 2 through 17 giving general description of all finishes, materials, and systems including civil, structural, HVAC, electrical, plumbing, and specialty items, including fire sprinklers, alarm systems, electronic controls and computer networking components.
- .15 Office of Educational Facilities Life-Cycle Cost Analysis (LCCA). LCCA shall be submitted to the Owner for review and approval with the Phase II documents. LCCA shall be by a commercially available life-cycle cost analysis program, and as required by the Department of Education and the

Owner. Life Cycle Cost Analysis shall be compared among competing providers in accordance with Ch. 1013.451, Florida Statutes.

- .16 Florida Energy Efficiency Code for Building Construction (FEEC). FEEC forms, including calculations for mechanical systems, documenting energy efficiency ratio rating of HVAC equipment, electrical systems, insulation, and building envelope shall be submitted to the Owner for review and approval with the Phase II documents.
- .17 The Project Consultant shall advise Owner of any adjustments to the Schematic Design Phase estimate of probable construction cost and shall submit to Owner a fully detailed Design Development Phase estimate of probable construction cost, by an independent cost estimator approved by Owner, projected to the expected time of bid and containing sufficient detail to provide information necessary to evaluate compliance with the Project Budget set for this project. Format estimate and provide detail matching the organization and content of the project's Outline Specifications complete for Divisions 2 through 17 including all finishes, materials, and systems including civil, structural, HVAC, electrical, plumbing, and specialty items, including fire sprinklers, alarm systems, electronic controls and computer networking components.

Utilize the current edition of MasterFormat as published by the Construction Specifications Institute to organize the estimate.

- An updated Project Design Schedule reflecting development and anticipated schedules for all subsequent project activities.
- .19 A written response from the Project Consultant and each of the major technical disciplines and any necessary Sub-Consultants explaining how each previous review comment (as generated by the Owner and/or other reviewing agencies) concerning the project have been addressed and/or corrected.
- A simplified single line floor plan of the project; a database format schedule reflecting the room numbers; the name of the room or space; the net square footage of the space and the capacity of the space on electronic media conforming to the Owner's standards for graphics and for electronic media submittals. This drawing and database information will be for use in preparing F.I.S.H. (Florida Inventory of School Houses) information. The Project Consultant shall coordinate with and utilize the Owner's F.I.S.H requirements for room numbers, room name assignments and electronic media (format, layering, etc.) prior to developing final documents for this submittal. Hardcopy graphics shall be suitable for clearly legible half size reductions. Comply with the Owner's requirements for electronic media specified below.
- .21 A letter indicating, after coordination with the Facilities and Construction Management Division's Environmental Section, the extent of any known or suspected asbestos containing materials or other potentially hazardous materials which might require mitigation by the Owner prior to or during construction of the Project. Establish and confirm responsibility for removing the asbestos or other hazardous materials in the design development documents and coordinate with Project Development Schedule, Statement of Probable Construction Cost and other documentation.
- .22 Preliminary colorboards to review the color selections for all finish materials with the Owner.

- .23 Twenty-five (25) copies of a Design Development Brochure which will be utilized to communicate the design as developed to date and shall include updated and enhanced contents of those brochures required at the Schematic Design Phase complete as necessary to illustrate the developed design, schedules, etc. Additional copies of the Design Development Brochure if required by the Owner will be compensated as a reimbursable service approved in advance by the Owner.
- 2.3.2 Staff from each of the Project Consultant's major technical disciplines and Sub-Consultants as necessary shall attend coordination, review and presentation meetings with the Owner to explain the design concept and technical resolution of their respective building or site systems.
- 2.3.3 The Project Consultant shall submit seven (7) sets of all documents required under this Phase (except as otherwise indicated), without additional charge, for review and approval by the Owner, and the Project Consultant shall not proceed with the next Phase until the completion of all required presentations and reports and receipt of a written Authorization to Proceed with the next phase.

2.4 Phase III - Construction Documents Development:

- 2.4.1 Only after receiving a fully approved and executed ATP and Purchase order (See 5.2.3) from Owner and based on the approved Design Development Phase documents and any adjustments in the scope or quality of the project or in the Fixed Limit of Construction Cost authorized by Owner, the Project Consultant shall prepare for approval by Owner and the Florida Department of Education, and in accordance with SREF requirements and the Owner's formats, Final Construction Documents setting forth in detail the requirements for the construction of the Project. The Project Consultant is responsible for the full compliance of the design with all applicable codes.
- 2.4.2 **50% Construction Documents Submittal:** The Project Consultant shall make a 50% Construction Documents submittal, for review and approval by the Owner, which shall include seven (7) sets of the following:
 - .1 "Project Transmittal Form" as required by the Facilities and Construction Management Division's Design Section.
 - .2 An updated OEF form 208(a) "OEF Space Chart Form" formatted to follow the sequence of spaces listed in the SREF Size of Space and Occupant Design Criteria Table.
 - .3 Updated Florida Energy Efficiency Code for Building Construction (FEEC) compliance forms. Submit seven (7) copies signed and sealed by a State of Florida registered design professional with 50% Contract Documents submittal.
 - .4 **Preliminary calculations:** Provide preliminary calculations for structural, mechanical and electrical systems.
 - .5 Drawings: These documents shall be 50% construction drawings corresponding to the educational specifications and program requirements illustrating the general scope, scale, and relationship of project components. In addition to Phase II requirements, SREF requirements, and information required by the Owner's document submittal checklist for phase III 50%, the documents shall include the following:
 - .1 Site Plan(s) and detailing which, in addition to the Phase II requirements, indicate:

- .1 Spot elevations, based on the civil grading plan, for the perimeter of the new additions, sidewalk, or any other areas pertinent to the drainage of rainwater.
- .2 Location of storm water service for new additions roof drainage.
- .3 Parking lot lighting poles location and type.
- .4 Final location for manholes, handholes, pull boxes.
- .5 Layout of underground distribution systems (normal power emergency power, fire alarm, master clock, intercommunication, television, telephone, security, control and spares).
- .6 Locations of all site improvements, playground and athletic equipment, street furniture, planters and other features.
- .7 Details of all curbing, typical parking spaces (regular and handicap accessible), handicap ramps, bus loop(s), parent drop-off, directional signage, site lighting, flagpole and fence foundations, and any other site conditions pertinent to the scope of work.
- .8 Plans of new playcourts, tennis courts, tracks, event pads and other pertinent athletic, physical education or recreational areas provided with court markings and detailing for basketball goals, volleyball sleeves, tennis nets, and other playcourt equipment or accessories.
- .2 A plan to delineate staging areas, site barriers and other area designations to control and separate students, faculty, staff and the public from construction activities and traffic.
- .3 Landscape plans and detail including a plant list clearly noted and cross referenced, details for shrub and tree plantings, identification of plants and trees to remain, be removed or relocated, and other necessary documentation.
- .4 Irrigation plans and details delineating the entire area of the project, and addressing necessary connections, alteration, repair or replacement of any existing irrigation systems.

.5 Full floor plans including:

- .1 All dimensions and any cross references explaining the extent of Work, wall types, or other component, assembly or direction regarding the Construction.
- .2 Note all chases and delineate all rainwater leaders.
- .3 Show structural tie columns and coordinate with the floor plan.
- .4 Cross referenced interior elevations.
- .5 Delineate and note all built-in cabinetry or equipment.
- .6 Identify room (F.I.S.H.) and door numbers with all doors having individual numbers.

- .6 **Demolition Plans:** Indicate required demolition activities. as follows:
 - .1 Provide separate demolition plan(s) and other drawings (elevations, sections, etc.) as necessary if the scope of work includes demolition which is too excessive to indicate drawings depicting new construction.
 - .2 Indicate notes on the extent of the demolition: address dimensions at locations where partial walls are being removed or altered, existing room names and numbers, existing partitions, equipment, plumbing, HVAC or electrical elements.
 - .3 Include notes dealing with protection of existing areas as a result of demolition.
 - .4 Delineate any modifications to existing buildings involving structural elements within the structural documents rather than on the architectural.
- .7 Building elevations developed further than at Phase II and including delineation of building joints (including dimensionally located stucco control joints), material locations, elevation heights, and other building features.
- .8 Building and wall sections to establish vertical controls and construction types for the Project. Include clear graphics, and notes on construction assemblies and systems to be used, dimensions, heights. Provide associated detailing to delineate solutions for difficult connections. Specify details for any fire walls to be constructed.
- .9 Reflected ceiling plans indicating ceiling types, heights, light fixture types, mechanical diffuser locations, and sprinkler heads if area is sprinklered. Delineate and detail any dropped soffits or joint conditions between different materials. Ensure coordination with architectural, electrical, mechanical and plumbing disciplines and work of any applicable Sub-Consultants.

.10 Roof plans:

- .1 Indicating all roof penetrations, including drains, scuppers, mechanical exhaust fans, any other equipment on the roof, slopes of roof with elevations shown, type of roofing system to be used, expansion joints, typical parapet and flashing details.
- .2 Dimensions to locate the items noted previously, and cross references shown.
- .11 Large scale building details as appropriate to this level of document development and as required to establish vertical controls for the Project. Include clear graphics, and notes on construction assemblies and systems to be used, dimensions, heights. Provide associated detailing to delineate solutions for difficult connections.
- .12 Interior elevations of all classroom designs including cross references of cabinetry details, dimensions and heights, notes indicating type of equipment (and whether equipment is in or out of contract), wall materials, finishes, and classroom equipment and accessories.
- .13 Details of casework as necessary to appropriately delineate custom or pre-manufactured casework. Provide appropriate schedules referencing manufacturer's numbers or catalogs, finishes, hardware and other construction characteristics.

.14 Details of the following:

- .1 Door jamb, head and sill conditions.
- .2 Wall and partition types.
- .3 Window head, sill and jamb conditions, and anchorage methods shown, in lieu of referencing to manufacturer's standards.
- .4 Interior signage to include classroom and building identification, emergency exiting and equipment signs, and any other items pertinent to the identification of the project. Coordinate with electrical discipline.
- .5 Interior or exterior expansion control connections.
- .6 Any other specialized items necessary to clearly express the intent of the project design.
- .15 Room finish and door schedules coordinated with the floor plans, developed beyond Phase II.
- .16 Structural foundation and framing plans, with associated diagrams, schedules, notes, detailing and section drawings completed sufficiently to communicate the design intent and coordination with other disciplines.

.17 Mechanical Drawings:

- .1 Provide double line duct work layout and HVAC equipment layout drawings with related diagrams and schematic diagrams, schedules, notes, detailing and section drawings completed sufficiently to communicate the design intent and coordination with other disciplines.
- .2 Provide plumbing equipment and fixture layout drawings with related diagrams, schedules, notes, detailing and section drawings completed sufficiently to communicate the design intent and coordination with other disciplines.
- .3 Provide 1/2 inch scale plans, elevations and sections of the mechanical rooms showing service clearance, room openings, nominal equipment size, ceiling height, duct clearance between bottom of joist and top of ceiling and any ceiling mounted lighting fixtures, electrical equipment or other building assembly or component, etc.
- .18 **Electrical:** Provide drawings for the following systems:
 - .1 Lighting including circuiting and luminaire identification and switching. Also provide illuminance computer printout for all indoor typical indoor spaces and parking lots.
 - .2 Convenience outlets and circuiting, special outlets and circuiting, television outlets, and power systems and equipment. Provide riser diagrams for all electrical systems including master clock, intercom, fire alarm, ITV, computer networking/telephone. Also, provide for emergency and normal power distribution. Provide luminaire schedule.

- .3 Panel schedule may be in preliminary form but circuitry must be included.
- .4 Applicable installation details.
- .5 General legend and list of abbreviations.
- 6 Voltage drop computation for all main feeders.
- .7 Short circuit analysis
- .8 Provide 1/2" scale floor plan and wall elevations for all electrical rooms.
- .9 Indicate surge protector for main switchboard and electrical panels.

.6 **Progress specifications:**

- .1 Provide preliminary Project Manual including front end documents. Completion of fill-in items in Bidding documents and other "Division 0" documents is not required.
- .2 Provide a preliminary Division 1 based upon the standard documents provided by the Owner, and edited by the Project Consultant after consultation with the Owner to establish project specific requirements.
- .3 Include progress set of all other Sections in Divisions 2-17 with each section developed to demonstrate to the Owner an understanding of the project and an appropriate level of developmental progress comparable to that of the drawings.
- .4 Specification sections shall be organized to follow the Construction Specification Institute's (CSI) current edition of MasterFormat with each section developed to include CSI's standard 3-part section and page formats with full paragraph numbering.
- .7 An updated Project Design Schedule, reflecting continued Project development and illustrating anticipated schedules for all subsequent project activities including permitting and submittal coordination with all agencies having jurisdiction on the Project. Format updated schedule as a Bar Chart (Gantt Chart) type schedule with milestones.
- .8 Colorboards illustrating color selections, finishes, textures and aesthetic qualities for all finish materials for final review and approval by the Owner and to establish a final pallet of material selections for development of subsequent specifications, schedules and other requirements for incorporation into the Contract Documents.
- .9 A letter from the Project Consultant and each of the major technical disciplines and any necessary Sub-Consultants or explaining how each previous comment concerning the project has been addressed and/or corrected.

2.4.3 100% Construction Documents Submittal:

.1 Upon receipt of written approval of the Phase III 50 % Construction Documents and a fully approved and executed ATP and Purchase order (See 5.2.3), the Project Consultant shall proceed with the rest

of Phase III Construction Documents.

- .2 Upon 100% completion of the Construction Documents, the Project Consultant shall submit to the Owner seven (7) copies of check sets of the Drawings, Specifications, reports, programs, a final updated Project Development Schedule, a final updated Statement of Probable Construction Cost and such other documents as reasonably required by Owner. The 100% construction documents shall conform to SREF requirements, all mandatory requirements cited by the Florida Department of Education (or the designated reviewer) and those listed below.
- .3 All documents for this phase shall be provided in both hard copy and in electronic media. The Owner will review and approve Phase III documents for submission to the Department of Education (or designated reviewing agency) for review and approval. The following Phase III contract documents shall be included with the Phase III submittal:
 - .1 "Project Transmittal Form" as required by the Facilities and Construction Management Division's Design Section.
 - .2 OEF form 208 "OEF Project Transmittal Form".
 - .3 OEF form 208 (a) "OEF Space Chart Form" formatted to follow the sequence of spaces listed in the SREF Size of Space and Occupant Design Criteria Table.

.4 General Requirements.

- .1 **Record Set.** This submittal is the official record set and shall be the bid documents.
- .2 **Signed and Sealed/Statements of Compliance:** Only complete documents, properly signed and sealed by the Project Consultant and respective Sub-Consultants, will be accepted for review; in addition, these documents shall contain a statement of compliance by the architect or engineer of record that "To the best of my knowledge and belief these drawings and the project manual are complete, and comply with the State Requirements for Educational Facilities and all applicable and referenced building codes".
- .3 When requested by the Owner, engineering calculations for mechanical, electrical, and structural systems shall be submitted separately from drawings and the project manual.
- .6 **Drawings.** These documents shall be 100% construction drawings corresponding to the educational specifications and program requirements illustrating the general scope, scale, and relationship of project components. In addition to Phase III 50% requirements, SREF requirements, and information required by the Owner's document submittal checklist for phase III 100%, the documents shall include the following:
 - .1 Site plans including, but not limited to, area location map, legal description of property, demolition, excavation, utilities, finish grading, landscaping, mechanical, electrical, civil/structural, and architectural site plans.
 - .2 Plans and details including, but not limited to:

- .1 Title sheets including listing of Project Consultant, Program Manager, School Board of Broward County, a table of contents and statement of compliance by the architect or engineer of record. Each discipline shall have a list of abbreviations, schedule of material indications, and schedule of notations and symbols at the beginning of their section of the plans.
- .2 Architectural sheets including floor plans, door, window and finish schedules, roof plans, elevations, sections, and details.
- .3 Civil/Structural sheets including paving; bus loops; parent drop; service drive; parking; drainage; foundation plans; floor plans; roof plans; structural plans; sections; details; and, pipe, culvert, beam and column schedules.
- .4 Mechanical sheets including floor plans; sections; details; riser diagrams; kitchen exhaust hoods; and, equipment, fan, and fixture schedules.
- .5 Electrical sheets including floor plans; sections; details; riser diagrams; and, fixture and panel schedules.
- .6 The drawings should indicate that the approved mechanical/electrical systems, from the Phase II FEEC/LCCA analysis, have been incorporated into the documents.
- .6 **Project Manual.** The Project Consultant, in its leadership capacity, shall review and coordinate with the Owner regarding the preparation of the following:
 - .1 The necessary bidding information, the bidding forms, the conditions of the contract and Division 1 with respect to the foregoing documents and regarding any other Agreements necessary for construction of the project. However, in no case will Project Consultant amend or delete items from these documents without prior review and written approval from Owner.
 - .2 A project specific set of Division 1 specifications based upon master documents provided by the Owner, including all schedules, lists and inventories as required to complete the Owner's master documents including Contractor's Submittal schedules, warranty schedules, salvage schedules, preliminary construction schedule, etc.
 - .3 Final specification sections for Divisions 2 through 17 organized and formatted as required for the set of Phase III, 50% progress specifications.
 - .4 Approved alternate bid items, if required and authorized by the Owner, to bring the project within the Fixed Limit of Construction Cost (FLCC) which would permit Owner in its sole discretion to accept or reject portions of the construction of the project. No additional compensation shall be provided for bid alternates if they are part of the original scope of work.
- .7 A threshold building inspection plan, prepared by the Project Consultant, and the name of a certified threshold building inspector, as set forth in Section 553.79(5), Florida Statutes (2004) as amended from time to time, shall be submitted to the Owner and the Department of Education (as applicable) for review and approval with Phase III documents. Threshold building inspection plan documents shall be submitted for:

- .1 Any building greater than three (3) stories or fifty (50) feet in height, or
- .2 Any building with an assembly space that exceeds five thousand (5000) square feet in area, and an occupant load of five hundred (500) or more persons.
- .8 An Updated Statement of Probable Construction Cost as indicated by time factor, changes in requirements, or general market conditions.
- .9 A letter from the Project Consultant and each of the major technical disciplines and any necessary Sub-Consultants explaining how each previous review comment (as generated by the Owner and/or other reviewing agencies) concerning the project has been addressed and/or corrected.
- .4 If the Latest Statement of Probable Construction Cost exceeds the Fixed Limit of Construction Cost for construction, the Project Consultant shall review the materials, equipment, component systems and types of construction included in the Contract Documents with the Owner and may recommend changes in such items and/or reasonable adjustments in the scope of the Project (to be made at no additional cost to the Owner).
- .5 The Project Consultant shall make all required changes or additions and resolve all questions on the documents. The 100% complete Check Set shall be returned to the Owner. Upon final review and approval by the Owner the Project Consultant shall furnish seven (7) copies, signed and sealed of all Drawings and Specifications to the Owner without additional charge.
- .6 The Project Consultant shall, with the Owner's assistance, file the required documents for approval by governmental authorities having jurisdiction over the Project (including Broward County and municipalities and their constituent departments, the South Florida Water Management District, and other state, local or federal agency with jurisdictional authority over some aspect of the Project) and obtain certifications of "permit approval" by reviewing authorities prior to the commencement of Phase IV and early enough to ensure that the eventual contractors is not delayed by permit processing by Broward County, a municipality or other jurisdictional agency. The Project Consultant shall provide the original documents or reproducible copies as may be required for submittal to any and all governmental authorities. The Project Consultant shall attend and provide representation at all review meetings, workshops, hearings and Commission/Council meetings concerning the project as conducted by other jurisdictional agencies. Project Consultant shall assure the Owner that all mandatory requirements are complete prior to the bidding, included, but not limited to, those that may have a financial impact on the Project.
- .7 Staff from each of the Project Consultant's major technical disciplines and Sub-Consultants as necessary shall attend coordination, review and presentation meetings with the Owner to explain the development of the design concept and technical resolution of their respective building or site systems for both the Phase III, 50% and Phase III, 100% Submittals.
- .8 The Owner's review and approval of the drawings, specifications, calculations and other construction documents shall not relieve the Project Consultant of any responsibility for their accuracy, adequacy and completeness.

2.4.4 The Project Consultant shall make all changes to the documents as required by the Owner's review of the documents by issuing a written recommendation to the Owner, at no additional cost and resolve initially all questions of constructability, code compliance, coordination across disciplines, clarity of documents, compliance with Owner standards, or other issues raised by the Owner during their reviews of the documents. The Owner will retain the documents submitted at this phase.

2.5 Phase IV - Bidding and Award of Contract

- 2.5.1 **Bid Documents Approvals and Printing:** Upon obtaining a fully approved and executed ATP and Purchase order (See 5.2.3), and all necessary approvals of the Construction Documents, and review and, approval by the Owner of the latest Statement of Probable Construction Cost, the Project Consultant shall assist Owner in obtaining bids and awarding construction contracts. The Project Consultant will provide reproductions of the drawings and specifications for bidding purposes at no additional cost to the Owner.
- 2.5.2 The Owner will issue the Bid Documents to prospective bidders and keep a complete "List of Bidders."
- 2.5.3 The Project Consultant shall render initial interpretations and clarifications of the drawings and specifications in a written format, supplemented by appropriate graphics. The Owner shall make all final determinations and/or interpretations as it relates to building code issues.
- 2.5.4 The Project Consultant shall attend a pre-bid conference as requested by the Owner.
- 2.5.5 The Project Consultant shall prepare addenda, if any are required, for the Owner to issue to all prospective bidders. No addenda shall be issued without the Owner's approval and if dimensional changes or extensive graphic changes are required the drawing sheets shall be revised and issued as addendum drawings as directed by Owner.
- 2.5.6 The Project Consultant shall be present at the opening of bids with the Owner's staff.
- 2.5.7 The Project Consultant shall participate with Owner in evaluating the bids and shall provide a written recommendation for bid award.
- 2.5.8 If the lowest responsive Base Bid received exceeds the Fixed Limit of Construction Cost the Owner will either:
 - .1 Approve the increase of Project costs and award a contract or,
 - .2 Reject all bids and rebid the Project within a reasonable time with no change in the Project,
 - .3 Direct the Project Consultant to revise the Project scope or quality, or both, as approved by the Owner, and rebid the Project, or
 - .4 Suspend or abandon the Project, or
- 2.5.9 Under Article 2.5.6.2 above, the Project Consultant shall, without additional compensation, modify the Construction Documents as necessary to bring the project within the Fixed Limit of Construction Cost. The providing of such service shall be the limit of the Project Consultant's responsibility in this regard and having done so, the Project Consultant shall be compensated in accordance with this Agreement. The Owner may

recognize exceptional construction market cost fluctuations before exercising the option provided in Article 2.5.6.2 above. The Owner agrees to discuss this issue with the Project Consultant prior to exercising this option.

2.5.10 If an estimate or cost analysis is required by the Owner for this phase, the Project Consultant shall utilize the previously established independent cost estimator, or a replacement acceptable to the Owner, to analyze bids and to assist in the preparation of any modified bidding documents or re-bid documents that may be required to ensure successful bidding within the Fixed Limit of Construction Cost.

2.6 Phase V - Administration of the Construction Contract:

- 2.6.1 The Construction Administration Phase will begin with the award of the Construction Contract and will end when the Contractor's final Payment Certificate is approved by the Owner and after the one (1) year warranty period has expired. During this period, the Project Consultant shall provide Administration of the Construction Contract as set forth in the construction contract documents (hereafter referred to and defined as the "Contract Documents") between the Owner and the Contractor, as basic services.
- 2.6.2 The Project Consultant, as a representative of the Owner during the Construction Phase, shall advise and consult with the Owner within the limits established by this Agreement and the Contract Documents. The Project Consultant shall contemporaneously provide Owner with copies of all communications between Project Consultant and others concerning matters material to the cost, time, sequence, scope, performance or requirements of the project.
- 2.6.3 The Project Consultant and the Project Consultant's respective Sub-Consultants shall attend all key construction events as necessary to ascertain the progress of the Project and to determine in general if the Work is proceeding in accordance with the Contract Documents and the Project Schedule. A minimum of at least one site visit per week will be required by the Project Consultant. The Sub-Consultant will be required to visit the site at least once a week when their respective portion of the work is in progress.
 - The Project Consultant shall visit the site at least once per week to become familiar with the progress and quality of the Work and to determine if the Work is proceeding in accordance with the Contract Documents and Project Schedule. The Project Consultant shall coordinate the timing of these visits with the Owner's Representative so as to permit joint observations of the progress of the Work and discussions about project issues. On the basis of on-site observations as a Consultant, the Project Consultant shall keep Owner informed of the progress and quality of the Work. The Project Consultant shall promptly submit to Owner a detailed written report of the results of each visit to the site, and copies of all field reports and notes of meetings with contractor, subcontractors of any tier or suppliers.
 - .2 The Project Consultant shall, based upon its on-site visits, promptly report to Owner any defects and deficiencies in the Work coming to the attention of Project Consultant and shall endeavor to guard the Owner against defects and deficiencies in the Work. This obligation is not reduced or limited by the fact that others, such as the UBCI, are undertaking inspection for or on behalf of the Owner. The Project Consultant shall make on-site observations utilizing the same personnel over the course of the Work. The Project Consultant shall assist the Owner in determining the cost of additional inspections due to the Contractor's failure to perform. Any changes in personnel must be in writing and issued to the Owner.

- .3 The Project Consultant shall not have control over or charge of and shall not be responsible for construction means, methods, techniques, sequences or procedures, or for safety precautions and programs in connection with the Work.
- 2.6.4 The Project Consultant shall at all times have access to the Work where ever it is in preparation or progress. The Project Consultant and the Sub-Consultants shall review and advise the Owner as to whether the Contractor is making timely, accurate, and complete notations on the "Project Record Documents" and maintaining various other administrative records as required by the Contract Documents. In addition, the Owner may at its discretion require the Project Consultant and all Sub-Consultants to submit additional written materials or forms to the Owner relating to or regarding the Project or its progress. Complete notations to the "as built" drawings shall include, but not be limited to all changes due to RFI's, ASI's, COD's, and CO's, in addition to the changes recorded by the Contractor, as noted above.
- 2.6.5 The Project Consultant shall initially interpret matters and provide recommendations concerning performance of Owner and Contractor under the requirements of the Contract Documents upon written request of Owner. The Project Consultant's response to such requests shall be made with reasonable promptness and within any time limits agreed upon. The Project Consultant shall render written advisory decisions, only upon the Owner's request, within a reasonable time, on all claims, disputes and other matters in question between Owner and Contractor relating to the execution or progress of the Work or the interpretation of the Contract Documents.
- 2.6.6 All initial interpretations and advisory decisions of the Project Consultant shall be consistent with the intent of, and reasonably inferable from, the Contract Documents and shall be in writing or in the form of drawings. In the capacity of interpreter the Project Consultant shall endeavor to secure faithful performance by both the Owner and Contractor, and shall not show partiality to either. The Owner shall be the final interpreter of any and all matters pertaining to the performance of the Project Consultant and Contractor.
- 2.6.7 The Project Consultant shall have authority to recommend rejection of Work which does not conform to the Contract Documents. The Project Consultant shall not have authority to stop the Work without approval of the Owner. Whenever, in the Project Consultant's reasonable opinion, it is necessary or advisable for the implementation of the intent of the Contract Documents, Project Consultant may recommend special inspection or testing of the Work in accordance with the provisions of the Contract Documents, whether or not such Work is to be fabricated, installed or completed, but Project Consultant shall take such action only after consultation with Owner. The Project Consultant's monitoring of such additional special testing or inspections is a part of the Basic Services. Owner shall furnish all such tests, inspections and reports that are required by law or by the Contract Documents or that it has previously approved in writing, without waiving its right to reimbursement from Contractor. However, neither this authority of the Project Consultant nor a decision made in good faith either to exercise or not to exercise such authority shall give rise to a duty of responsibility of the Project Consultant to Contractor or other third parties performing portions of the Work.
- 2.6.8 The Project Consultant shall promptly review, and take other appropriate action upon Contractor's submittals such as shop drawings, product data and samples, but only for conformance with the design concept of the Contract Documents. Such action shall be taken within fourteen (14) days of receipt by Project Consultant unless Ownerand Project Consultant otherwise mutually agree. Project Consultant's review shall not constitute review or approval of safety precautions or of construction means, methods, techniques, sequences or procedures. Project Consultant shall maintain a log of all submittals made and shall compare the submittals with Contractor's progress schedule. The Consultant shall not approve changes to the contract or substitutions through the regular submittal process but will utilize those respective methods specified in the Contract Documents. The Project Consultant shall be compensated for reviewing re-submittals after the first

- re-submittal of a respective submittal as a reimbursable expense with the Owner reimbursed by the Contractor under provisions of the Contract Documents.
- 2.6.9 The Project Consultant shall coordinate with the Owner concerning the Owner's required review of Request for Proposals, Change Orders and Construction Change Directives. The Project Consultant shall:
 - .1 Meet with the Owner prior to the preparation and execution of Request for Proposals, Contingency Use Directives and Change Order items to ensure that proposed changes comply with the intent of the Project's scope and construction schedule and whether the Contractor is entitled to additional sums or contract time for the proposed Work.
 - .2 Reconcile the Project Consultant's analysis of Request for Proposals, Contingency Use Directives and Change Order amounts with an analysis provided by Owner's chosen independent cost estimator and provide the Owner with a recommendation concerning the respective cost studies.
 - .3 Submit written and graphic information documenting proposed changes for formal review by the Owner.
 - .4 Review and indicate concurrence through signing Request for Proposals for Owner's authorization in accordance with the Contract Documents, shall have authority to order minor changes in the Work not involving an adjustment in the contract sum or an extension of the contract time and which are not inconsistent with the intent of the Contract Documents. Such minor changes shall be implemented through an Architect's Supplemental Instructions (ASI) issued through Owner. The Basic Services shall include providing recommendations concerning Request for Proposals, Contingency Use Directives and Change Orders, and the preparation, permitting and processing of Request for Proposals, Change Orders and Construction Change Directives. This Article shall not supersede Articles 2.9.1.14 or 2.9.1.16.
 - .5 Process, prepare and issue contract modification documents, Request for Proposals, Contingency Use Directives and Change Orders, in a timely manner and not allow the period required for evaluation, preparation or to issue such documents to exceed fourteen (14) days. The Project Consultant shall provide written notification to the Owner concerning those modification documents requiring more than fourteen (14) days processing time with an attached explanation of the circumstances requiring longer processing time.
 - .6 All final decisions with respect to substitutions, Request for Proposals, Change Orders, and other contract modifications shall be at the sole determination of the Owner.
- 2.6.10 The Project Consultant shall conduct thorough site observations, make recommendations and otherwise assist Owner in determining the dates of Substantial Completion and Final Completion, shall review, approve and forward to Owner for Owner's review, written warranties and related documents required by the Contract Documents and assembled by Contractor, and shall certify a final certificate for payment. At substantial completion, the Project Consultant shall prepare a punch list of observed items requiring correction, completion or replacement by Contractor. The Project Consultant shall administer the Contractor's submittal of various closeout submittals including warranty documents, operations and maintenance materials, extra materials, and other closeout submittals as required by the Contract Documents. The Project Consultant and the Sub-Consultants shall verify and confirm the Contractor's successful demonstration of equipment and systems and the training of the Owner's personnel as required by the Contract Documents. Project Consultant shall inspect the Project upon final completion to determine compliance with the Contract Documents and,

- upon so determining, prepare and execute the required forms and other documents indicating that the Work is completed in compliance with the Contract Documents.
- 2.6.11 The Project Consultant shall within sixty (60) days of final acceptance provide the Owner with prints and electronic media copies of the original drawings, which the Project Consultant has revised to conditions based on information furnished by the Contractor as Project Record Documents. These prints and electronic media copies shall become the property of the Owner. Submittal of these documents to the Owner is a condition of final payment of construction support fees to the Project Consultant.
- 2.6.12 The Project Consultant shall assist Owner in determining amounts owing to Contractor based on observation at the site and an evaluation of Contractor's applications for payment and shall certify Certificates for Payment of such amounts as provided in the contract documents and in such forms as the Owner may request. The certification of the Certificate for Payment shall constitute the representation by Project Consultant to Owner based on Project Consultant's observation at the site and the data comprising Contractor's applications for payment, that the work has progressed to the point indicated; the quality of the work is in substantial accordance with the contract documents (subject to an evaluation of the work for substantial conformance with the contract documents upon substantial completion, to the results of any subsequent test by or performed under the contract documents, to minor deviations from the contract documents cited prior to completion, and to any specific qualification stated in the Certificate for Payment); and that the Contractor is entitled to the amount certified. However, the certification of the Certificate of Payment shall not be a representation that Project Consultant has made any examination, other than information which has come to Project Consultant's attention, to ascertain how and for what purpose Contractor has used the monies paid by the Owner.

2.7 Phase VI - Warranty Administration:

2.7.1 Upon receiving a fully approved and executed ATP and Purchase order (See 5.2.3), and for one year following substantial completion of the construction project, the Project Consultant shall assist Owner, without additional compensation, in securing correction of defects, and shall in the sixth and eleventh months make inspections of the project with the Owner and report observed discrepancies to Owner.

2.8 Other Basic Services:

2.8.1 The Project Consultant shall render to Owner without additional compensation, any proper and reasonable assistance which Owner may require as a result of any claim or any action brought relating to Project Consultant's services. Preparation of detailed analysis or documentation (if requested by Owner) shall be a supplemental service under Article 2.9.1.21 with a fully approved and executed ATP and Purchase order (See 5.2.3).

2.9 Supplemental Services

- 2.9.1 The services listed below are normally considered to be beyond the scope of Basic Services as defined in this Agreement, and if authorized in advance by having received a fully approved and executed ATP and Purchase order (See 5.2.3), will be compensated for as provided under Articles 5.7 and 6.2:
 - .1 Providing special analyses of the Owner's needs, and special detailed programming requirements for a project.
 - .2 Providing financial feasibility, or other special studies.

- .3 Providing planning surveys, site evaluations, or comparative studies of prospective sites.
- .4 Providing services relative to future facilities, systems and equipment which are not intended to be constructed as during the construction phase.
- .5 Providing services to make measured drawings of the existing site or facilities.
- .6 Providing the services of a cost estimating firm beyond the services required during Phases I-III to verify cost of the work as designed. The choice of the firm, qualifications of the firm and the terms of employment of the firm shall be approved in writing in advance by the Owner.
- .7 Providing interior design services required for or in connection with the selection of furniture or furnishings, except equipment included in the Construction Contract and identified in the educational specifications.
- .8 Providing investigations and making detailed appraisals and valuations of existing facilities, and surveys or inventories required in connection with construction performed by the Owner.
- .10 Providing the services of one or more full-time Construction Inspector during construction; including the services of a Special Threshold Inspector.
- .11 Providing extended assistance beyond that provided under Basic Services for the initial start-up, testing, adjusting and balancing of any equipment or system; extended training of Owner's personnel in operation and maintenance of equipment and systems, and consultation during such training; and preparation of operating and maintenance manuals, other than those provided by the Contractor, subcontractor, or equipment manufacturer.
- .12 Providing consultation concerning replacement of any Work damaged or built inconsistent with the Contract Drawings, providing the cause is found by the Owner to be other than by fault of the Project Consultant.
- .13 Providing consultation concerning replacement of any Work damaged by fire or other cause during construction, and furnishing services as may be required in connection with the replacement of such Work.
- .14 Preparing revisions of Schematic Design, Design Development, and Construction Document Phase Documents previously approved in writing by Owner, when so directed in writing by Owner, provided, however, that no compensation for Supplemental Services shall be paid for revisions which may be required when due to errors or omissions by the Consultant or when due to the fact that the lowest Bona Fide construction bid exceeds the "fixed limit of construction cost".
- .15 Providing services made necessary by the default of the Contractor, or any major unanticipated defects or deficiencies in the Work of the Contractor or any subcontractor not attributable in any way to an Error and/or Omission of the Project Consultant.
- .16 Preparing change orders and related documents provided the changes are significant changes (whether increases or decreases) in the scope of the project and are requested by the Owner and not for any changes due to any other reasons such as error or omission of the Project Consultant.

- .17 Providing revisions in drawings, specifications or other documents required by the enactment or revision of codes, laws or regulations subsequent to the preparation of such documents.
- .18 Preparing to serve or serving as an expert witness in connection with any public hearing, arbitration proceeding or legal proceeding.
- .19 Providing services after certification to the Owner of that Final Certificate for payment, and said payment has been made to the Contractor except those services that are a result of errors, omissions. or conflicts in documents prepared by the Project Consultant or are warranty related services.
- .21 Review of extensive claims by the Contractor or others relating to the Project. However, there shall be no additional charges to Owner from Project Consultant in the event the claims are not extensive or in the event the claims are determined by the Owner to be based upon the failure of the Project Consultant or Sub-Consultant to properly perform its services or to comply with the provisions of this Agreement.

ARTICLE 3 SUB-CONSULTANTS

3.1 Sub-Consultants' Relations

- 3.1.1 All services provided by the Sub-Consultant shall be pursuant to appropriate Agreements between the Project Consultant and the Sub-Consultants which shall contain provisions that preserve and protect the rights of the Owner and the Project Consultant under this Agreement. All such Agreements shall provide that the Project Consultant may assign or transfer to Owner any and all claims or causes of action which the Project Consultant has or may have against a Sub-Consultant as a result of or relating to any acts of omission or commission of that Sub-Consultant.
- 3.1.2 Nothing contained in this Agreement shall create any contractual relationship between the Owner and the Sub-Consultants. However the Project Consultant is at all times liable for any and all negligent acts of omission or commission of its Sub-Consultants relating to or regarding this Agreement or the Project which is the subject of this Agreement. The Owner may, at any time, require the Project Consultant to assign or transfer to the Owner any claims or causes of action which Project Consultant has or may have against one or more of its Sub-Consultants as it relates to these contract obligations regarding or relating to this Project. Upon such request, the Project Consultant shall execute a written assignment or transfer in a form to be provided by the Owner. In the event the Owner requires the Project Consultant to assign or transfer said claims or causes of action then the Owner agrees to indemnify and hold the Project Consultant harmless from any claim or cause of action brought by a Sub-Consultant against the Project Consultant directly related to the claim of cause of action brought by the Owner against a Sub-Consultant as a result of such assignment.

3.2 Proposed Sub-Consultants

- 3.2.1 The Project Consultant proposes to utilize the following Sub-Consultants: Per Attachment 5 (Project Team Members)
- 3.2.2 The Project Consultant shall not change any Sub-Consultant without written prior approval by the Owner.

3.2.3 The Project Consultant, not later than ten (10) calendar days after the date of this Agreement, shall submit a list of contact information for Sub-Consultants which includes contact names, firm addresses, phone and fax numbers and internet (or other internet e-mail service provider) e-mail addresses.

ARTICLE 4 THE OWNER'S RESPONSIBILITIES

4.1 Information, Documents, And Services

- 4.1.1 Owner shall consult with Project Consultant and provide such information regarding requirements for the project, including a Project Scope, Budget and Schedule which shall set forth Owner's contemplated design objectives, constraints and criteria, including educational specifications, facilities lists, space requirements and relationships, flexibility and expandability, special equipment and site requirements as are reasonably necessary for Project Consultant to perform its services.
- 4.1.2 The Owner shall furnish a legal description and a certified land survey of the site. When possible, the Owner shall supply the certified land survey in hardcopy and electronic media formats. The certified land survey shall provide boundary dimensions, locations of existing structures and/or trees, the grade and line of street, pavement and adjoining properties, the rights, restrictions, easements, boundaries, topographic data and information relative to sewer, water, gas and electrical services.
- 4.1.3 Owner shall furnish the services of soil engineers or other consultants if such services are necessary and requested in writing by Project Consultant. Such services may include test borings, test pits, soil bearing values, percolation tests, air and water pollution tests, ground corrosion and resistivity tests, including necessary operations for determining subsoil, air and water conditions, tests for hazardous materials, chemical, mechanical, structural or other tests with reports and appropriate professional recommendations.
- 4.1.4 Owner shall furnish a Project Schedule for the project showing all activities and critical dates necessary to complete the project within the allotted time.
- 4.1.5 Owner shall furnish a Construction Budget which is the portion of the Project Budget allocated for the construction cost of a project and will be based upon the Fixed Limit of Construction Cost with an appropriate contingency factor. This contingency factor includes but is not limited to the demolition, destructive testing and repairs, directed by the Project Consultant, to adequately investigate and document the existing conditions of the facility.
- 4.1.6 **As-Built Documentation:** When available, drawings and other available documents which were purported to represent "as-built" conditions at the time of original construction will be furnished to the Project Consultant; however, they are not warranted to represent conditions as of this date. The Project Consultant shall perform non-destructive field investigations as necessary to obtain sufficient information to perform his services and as required by field conditions, or the Owner to verify wall assemblies, construction types or other basic information as required to develop the design and documentation necessary for the project. The demolition and repairs associated with the destructive testing shall be compensated as a reimbursable expense. The Owner encourages the use of destructive testing techniques (with prior approval) to retrieve information that can be utilized by the Project Consultant to clearly indicate the disposition of the existing facility and incorporate this information into the Contract Documents.

4.1.7 District Standards and Submittal Checklist

- .1 Design And Material Standards: The Owner will furnish an electronic copy of Design and Material standards for the Project Consultant's use in developing designs and documentation for the project. These documents are technical specifications and the intent of these documents is to convey basic Owner preferences to the Project Consultant. The Project Consultant shall review the content of the Design and Material Standards provided by the Owner and may consult with the Owner concerning discrepancies, errors or suggestions for the improvement of the provided documents. The Project Consultant remains responsible for the technical content and accuracy of documents produced under the terms of this Agreement.
- .2 **Design Criteria:** The Owner will furnish an electronic copy of the Design Criteria for the Project Consultant's use in developing designs for the project. These criteria are guidelines, which address owner related issues; including but not limited to, ease of maintenance, life cycle costing, and functionality of the facility.
- .3 **Document Submittal Checklist:** The checklist is a guideline indicating minimum requirements for the submittal of contract documents for each phase of the design process. The completed checklist form will be required with each submission for all applicable disciplines.
- 4.1.8 **Standard Construction Bidding And Contract Documents:** The Owner shall furnish the Project Consultant with sample bidding and contract requirements and general requirements containing the basic provisions and requirements of Owner. These documents are comprised of the Bidding Requirements, Contracting Requirements, and Division 1 Specification Sections that will be utilized by the Project Consultant to develop the construction contract documents required under the terms of this Agreement. The Project Consultant acknowledges that these Owner Standard Documents will be made available by the Owner and shall be reviewed and analyzed by the Project Consultant and that these documents shall serve as the basis for the Project Consultant's development of bidding documents for the Owner.
- 4.1.9 Owner shall arrange and pay for the required advertisements for bid.
- 4.1.10 Owner, assisted by Project Consultant, shall issue the bid documents to bidders, maintain the planholders list, and issue addenda.
- 4.1.11 Owner shall be responsible for issuance of formal notices to proceed (if any) to the Contractor.

4.2 Owner Furnished Items

- 4.2.1 The services, information, surveys and reports specified by Article 4.1 shall be furnished at the Owner's expense, and the Project Consultant shall be entitled to rely upon the accuracy and completeness thereof. However, if the Project Consultant reviews all of the information provided by the Owner (such as surveys, soil borings and "as-built" documentation) and determines additional information and/or testing is required to properly design the project, the Project Consultant shall request same from the Owner.
- 4.2.2 When documents, services, or other materials furnished by the Owner for the Project Consultant's use are deemed by the Project Consultant as inappropriate, inaccurate, or otherwise unreasonable, the Project Consultant shall notify the Owner immediately upon discovery of same. Failure of the Project Consultant to so notify the Owner shall result in the Project Consultant's being responsible for any costs, expenses, or damages incurred by the Owner and forfeiture of claims for damages, delays or other compensation related to the use of those Owner furnished materials.

4.2.3 The Owner shall furnish the above information or authorize the Project Consultant to provide it, as a supplemental service (except where otherwise stipulated), as expeditiously as possible for the orderly progress and development of the Project.

ARTICLE 5 BASIS OF COMPENSATION

5.1 Professional Service Fees:

5.1.1 The Owner agrees to pay the Project Consultant, and the Project Consultant agrees to accept for services rendered pursuant to this Agreement a fixed fee (as computed by the Fixed Fee method below) of:

	Dollars. (\$.00)
Reuse Fee		
(Fee Written Out)	(\$)
Site Adaptation Fee		
(Fee Written Out)	(\$)
(Other – Description) Fee		
(Fee Written Out)	(\$)

5.2 Fixed Fee:

- 5.2.1 The Fixed Fee listed above is based on the scope of services for a project of this scope, size, complexity and Fixed Limit of Construction Cost (FLCC) of Construction of the project.
- 5.2.2 If the Owner authorizes a significant increase or decrease in the scope of the project, the Fixed Fee may be adjusted as mutually agreed upon. Changes in the FLCC, or, a Construction Contract awarded by the Owner in excess of the FLCC, shall not entitle the Project Consultant to additional Basic Services Fees, and, a Construction Contract awarded by the Owner that is less than the FLCC shall not entitle the Owner to a decrease in Basic Services Fees.
- 5.2.3 The Project Consultant shall not perform Professional Services, Supplemental Services, or Reimbursable Services until a written Purchase Order with the appropriate "line number" has been issued by the Supply Management and Logistics Department together with a fully executed Authorization to Proceed. <a href="MVNER SHALL HAVE NO OBLIGATION TO COMPENSATE PROJECT CONSULTANT FOR ANY WORK PERFORMED BY THE PROJECT CONSULTANT PRIOR TO RECEIPT OF A FULLY EXECUTED WRITTEN AUTHORIZATION TO PROCEED AND PURCHASE ORDER.

5.3 Not Used

5.4 Fee for Additive Alternates:

- 5.4.1 The design of alternates within the Owner's total allocated funds for construction will be a Basic Service.
- 5.4.2 The design of additive alternates, not included in the original project scope, in excess of Fixed Limit of Construction Cost of Construction must be authorized by the Chief Facilities and Construction Officer, and will be considered supplemental services, subject to negotiation.
- 5.4.3 Fees for the design of additive alternates, not included in the original project scope, will be negotiated and issued by a fully approved and executed ATP and Purchase order (See 5.2.3), . The Owner will pay one

hundred (100%) percent of the negotiated fee for alternates accepted and only pay for the design portions of the (Phases I through III) for alternates rejected.

5.5 Raw Labor Rate:

5.5.1

5.5.1 Raw Labor is defined as the raw salary rate, as determined from salaries reported to the Director of Internal Revenue, of the personnel engaged directly on a project.

5.6 Fees for Reimbursables

- 5.6.1 Reimbursables are those items pre-approved in writing by a fully approved and executed ATP and Purchase order (See 5.2.3), and authorized by the Owner in addition to the Basic and Supplemental Services and consist of actual expenditures made by the Project Consultant and the Project Consultants' employees and Sub-Consultants in the interest of the Work.
- 5.6.2 Authorized travel outside the Dade, Broward and Palm Beach County area, lodging and meals in connection with a project (subject to the limitations imposed by Chapter 112.06l, Florida Statutes); fees paid for securing approval of authorities having jurisdiction over the Work; reproductions (outside of Basic Services and with prior written Owner approval in the form of a fully approved and executed ATP and Purchase order (See 5.2.3); postage and handling of Drawings, Specifications and other documents, excluding reproductions for the office use of the Project Consultant and check sets required by the Owner; data processing and photographic production techniques when used in connection with Supplemental Services.
- 5.6.3 The Owner will reimburse the Project Consultant for authorized Reimbursables as verified by appropriate bills, invoices or statements.
- 5.6.4 Any authorized reimbursable shall not include charges for office rent or overhead expenses of any kind, including but not limited to local telephone, cell phone and utility charges, overtime or any discretionary labor benefits, office and drafting supplies, depreciation of equipment, professional dues, subscriptions, etc., reproduction of drawings and specifications, mailing, stenographic, clerical, or other employees time or travel and subsistence not directly related to a project. Authorized reproductions in excess of sets required at each phase of the work will be a Reimbursable.

5.7 Fees for Supplemental Services

5.7.1 The Consultant may be authorized by its receipt of a fully approved and executed ATP and Purchase order (See 5.2.3), to perform Supplemental Services described under Article 2.9 and negotiated in accordance with Article 2.8.2. The fee for such services will be Time Spent plus reimbursable expenses with a Guaranteed Maximum Price based on Raw Salary Rates times a fixed multiplier. The fixed multiplier shall cover mandatory personnel expenses, overhead and profit and shall be set at ______ times Raw Salary Rates and shall be included in the Guaranteed Maximum. Where a mutually agreeable Guaranteed Maximum cannot be arrived at, the Owner may secure services from an independent source or from the Owner's resources. The Consultant shall provide any information and/or copies of project documentation necessary to facilitate the provision of said supplemental services by others.

ARTICLE 6 PAYMENTS TO THE PROJECT CONSULTANT

6.1 Payment for Basic Services

- 6.1.1 Payments for Basic Services may be requested monthly in proportion to services performed during each Phase of the Work and provision of all required insurance policies is a condition precedent to becoming due any such payments to the Project Consultant. Said payments shall, in the aggregate, not exceed the percentage of the estimated total Basic Compensation, or 90% for Phases I, II, or II prior to approval of the submitted design documents, indicated below for each Phase:
 - .1 Fifteen (15%) percent of the total fee upon completion and approval of Phase I.
 - .2 Fifteen (15%) percent of the total fee upon completion and approval of Phase II.
 - .3 Twenty (20%) percent of the total fee upon submittal and approval of 50% of Phase III.
 - .4 Fifteen (15%) percent of the total fee upon completion and approval of Phase III.
 - .5 Five (5%) percent of the total fee upon 100% completion of Phase IV.
 - .6 Twenty-eight (28%) percent of the total fee upon completion of Phase V
 - .7 Two (2%) percent of the total fee upon completion of Phase VI (Warranty) and approval of all Work and audit of account, as per Article 5.
- 6.1.2 Partial payments may be made in Phase V (but not in excess of ninety (90%) percent of the aggregate of Phase V) in monthly increments which are proportioned to match the Work's percentage complete reflected by the Contractor's monthly Applications for Payment. If the Owner's required Substantial Completion date for Phase V is extended through no fault of the Project Consultant, the Project Consultant shall be reasonably compensated for any required professional services and/or expenses not otherwise compensated for in connection with such time extension(s), in accordance with Article 6.2. If the Owner's required Substantial Completion date for Phase V is extended due to an action or inaction of the Project Consultant to the detriment of the Owner, no additional payments or time shall be due to Project Consultant. The Project Consultant shall include with its billing, in either electronic or hard copy format, the following supporting information, and any additional supporting information required by the Owner: time sheets for any fees based upon Raw Salary Rates, subcontractors invoices, invoices for reimbursable expenses and time sheets, subcontractor invoices for reimbursables made necessary by the performance of Work. The invoice shall be totaled and care shall be taken to assure previously paid charges are not duplicated.
- 6.1.3 If the project reaches Final Completion (as defined by the Construction Contract Documents) prior to the expiration of the Anticipated Construction Time, then full payment shall be made at that time provided the Project Consultant has completed all obligations for submittals and other services (including Project Record Documents) as required by this Agreement.
- 6.1.4 No payments shall be due to Project Consultant unless and until all materials, forms and documents required by this Agreement have been provided by Project Consultant and its Sub-Consultant to Owner, or others whom are to receive same. The Owner retains the right to withhold payment from the Project Consultant for non-performance of the Project Consultant during any phase of the Project.
- 6.1.5 The Project Consultant shall submit invoices in the Owner's required invoice format as provided.

- 6.1.6 All Submitted invoices shall have copies of referenced ATP's attached.
- 6.1.7 During project Phases I through III, the Project Consultant shall submit an updated Project Schedule reflecting the Project Consultant's scheduled and actual progress with each submitted invoice. As an attachment to the Project Schedule, the Project Consultant shall provide a progress report giving percentage of completion of the Project development.
- 6.1.8 Project Consultant shall submit a monthly MWBE Sub-Consultant Utilization Report with the monthly request for payment, on forms provided by the Owner.
- 6.1.9 Payments are due and payable thirty (30) days from receipt of the Project Consultant's invoice provided it is in accord with the requirements of this Agreement.

6.2 Payment for Supplemental Services / Reimbursables

- 6.2.1 Payment for Supplemental Services and/or Reimbursables may be requested monthly (on the Owner's standard invoice format) in proportion to the services performed. When such services are authorized, the Project Consultant shall submit for approval by the Chief Facilities and Construction Officer, a duly certified invoice, attaching to the invoice all supporting data for payments made to Sub-Consultants engaged on the project or task.
- 6.2.2 Payments are due and payable thirty (30) days from receipt of the Project Consultant's invoice.

6.3 Project Suspension

- 6.3.1 If the project is suspended for the convenience of the Owner for more than three months or terminated in whole or in part, during any Phase, the Project Consultant shall be paid for services authorized by an Authorization To Proceed which were performed prior to such suspension or termination, together with the cost of Reimbursable Services and expenses then due.
- 6.3.2 If the Project is resumed after having been suspended for more than three months, the Project Consultant's further compensation shall be adjusted by the addition of Project Resumption Expenses. Project Resumption Expenses are in addition to compensation for Basic and Supplemental Services, and are full compensation for all damages and expenses which are directly or indirectly attributable to resumption of the Project Consultant's services after a Project Suspension. Project Resumption Expenses are applicable only to a Project Suspension by the Owner and shall be computed as a percentage of the total compensation for Basic Services and Supplemental Services earned to the time of termination, as follows:
 - .1 Two (2%) percent of the total compensation for Basic and Supplemental Services earned to the date of Project Suspension for the respective schematic or design development Phase only, if Project Suspension occurs before or during the design development design phase; or
 - .2 Five (5%) percent of the total compensation for Basic and Supplemental Services earned to the date of Project Suspension for the construction documents phase only, if Project Suspension occurs during the construction documents phase development phase; or
 - .3 Five (5%) percent of the total compensation for Basic and Supplemental Services scheduled for the construction contract administration phase only, if Project Suspension occurs during the construction support phase.

ARTICLE 7 REUSE OF DRAWINGS, SPECIFICATIONS AND OTHER DOCUMENTS

7.1 Scope of Services

- 7.1.1 It is understood that all Professional Service Agreements for design and other services include the provision for the Owner's optional re-use of drawings, specifications and other documents (including Phase V of Basic Services described in Article 2); and that the Project Consultant agrees to such re-use in accordance with this provision.
- 7.1.2 If the Owner elects to re-use the drawings, specifications and other documents, in whole or in part, prepared for the project for other projects on other sites, the Project Consultant will be paid a re-use fee, for Basic Services described in Article 2 for Phases I through VI, in the amounts of:
 - .1 Twenty (20%) percent of the original fee for Basic Services for Phases I through III.
 - .2 Thirty-eight (38%) percent of the original fee for Basic Services for Phases IV, V and VI.

Alternatively, the Owner agrees to pay the Project Consultant, and the Project Consultant agrees to accept, a flat reuse fee of:

This flat reuse fee will only apply if an actual dollar amount is listed above.

- 7.1.3 For each re-use the Project Consultant shall review the final as-built design of any prior reuse or reuses and shall include all Basic Services rendered under the reuse(s) and incorporate all modifications to the drawings, specifications and other documents resulting from Change-Orders, Errors and Omissions, Code revisions and Code corrections made during the prior reuse(s), and, modifications normally required to suit the new site. (This does not include preparation of reverse plans, changes to the program, subsequent code revisions or exceptional site conditions). The stipulations and conditions of this Agreement shall remain in force for each re-use project, unless otherwise agreed. Reuse fees do not include preparation of documents for offsite improvements.
- 7.1.4 If a reuse project commences in excess of three years from the acceptance of the design development documents by the Owner then Owner shall negotiate the fees to be paid to Project Consultant.

ARTICLE 8 INDEMNIFICATION

8.1 Indemnification

8.1.1 To the fullest extent permitted by law, the Project Consultant shall indemnify, defend and hold harmless the Owner, its members, officers, employees and agents (hereinafter collectively "Related Parties") from and against any and all liability, claims, causes of action (by whomever brought or alleged and regardless of the legal theories upon which the liability, claims or causes of action are based), losses, damage, costs, expenses and fees (including but not limited to reasonable fees of attorneys, expert witnesses and other consultants), which are or may be imposed upon, incurred by or asserted against Owner and/or the Related Parties to the extent said liability, claims, causes of action, losses, damages, costs, expenses and/or fees are caused by any errors, omissions or negligent acts of the Project Consultant, any sub-consultant or sub-sub-consultant, any

- supplier and any individual or entity directly or indirectly employed by any of them.
- 8.1.2 In any and all claims against the Owner by any employee of the Project Consultant, or anyone for whose acts the Project Consultant may be liable, the obligations for Project Consultant to indemnify Owner under this contract shall not be limited in any way by any limitation on the amount or type of damages, compensation, or benefits payable by or for the Project Consultant under workman's compensation acts, disability acts, or other employee benefit acts.
- 8.1.3 In the event that any claims are brought or actions filed against the Owner with respect to the indemnity contained herein, the Project Consultant agrees to defend against any such claims or actions regardless of whether such claims or actions are rightfully or wrongfully brought or filed. The Project Consultant agrees that the Owner may select the attorneys to appear and defend such claims or actions on behalf of the Owner. The Project Consultant further agrees to pay, at the sole expense of the Project Consultant, the attorney's fees and cost incurred by those attorneys selected by the Owner to appear and defend such claims or actions on behalf of the Owner. However, if the claims or actions are covered by insurance and such coverage is acknowledged by the insurance company in writing to the Owner, then, in that case, the insurance company shall choose counsel, direct the defense and be the judge of the acceptability of any compromise or settlement of any such claims or actions against the Owner which are within the insurance policy limits and are paid by the insurance company solely. Otherwise, if the claims or actions are not covered by insurance, then, at its sole option the Owner shall have the sole authority for the direction of the defense, and shall be the sole judge of the acceptability of any compromise or settlement of any claims or actions asserted against the Owner.
- 8.1.4 The Project Consultant recognizes the nature of the indemnification obligations imposed under this contract and voluntarily makes these covenants. The obligation imposed upon the Project Consultant under this Indemnification Agreement shall survive termination of this contract.

ARTICLE 9 INSURANCE

9.1 General Insurance Requirements

- 9.1.1 The Project Consultant shall not start work under this Agreement until the Project Consultant has obtained all insurance required hereunder and such insurance has been approved by the Owner.
- 9.1.2 All insurance policies shall be issued by companies authorized to do business under the laws of the State of Florida. All insurance companies providing policies required under this Agreement shall have at least an "A-" rating and a financial rating of no less than VI in the current A. M. Best Manual or hold a Moody's Investors Service Financial Strength of "Aa3" or better.
- 9.1.3 Insurance policies required under this Agreement shall be endorsed to be primary of all other valid and collectible coverages maintained by The School Board of Broward County, Florida.
- 9.1.4 The Project Consultant shall furnish certificates of insurance to the Owner for review and approval at the time of execution of this Contract and shall maintain same at all times during the term of this Agreement.
- 9.1.5 All Certificates of Insurance shall be in the form as approved by Insurance Standards Office (ISO), unless approved by Owner and shall clearly indicate that the Project Consultant has obtained insurance of the type, amount and classification required by these provisions, in excess of any pending claims at the time of contract award to the Project Consultant. No material change or cancellation of the insurance shall be effective

without a thirty (30) day prior written notice to and approval by the Owner. All Certificates shall list the Owner's project number and full project title (including applicable facility name).

9.1.6 Certificates of Insurance must clearly list any and all deductibles by coverages.

9.2 Insurance Required:

- 9.2.1 Automobile Liability Insurance: The Project Consultant shall maintain Automobile Liability Insurance covering all owned, non-owned and hired vehicles used in connection with this Agreement in amounts not less than One Million (\$1,000,000) Dollars per occurrence for bodily injury and property damage combined single limit and shall not be less than the standard ISO Business Auto Policy CA 00 01.
- 9.2.2 Professional Liability (Errors and Omissions): The Project Consultant shall procure Professional Liability Insurance in the manner described herein. The deductible shall not be more than Fifty Thousand (\$50,000) Dollars for each policy and must be indicated on the certificate of insurance. The insurance policy shall be non-cancelable and the limits of the Professional Liability Insurance Policy shall be as follows:
- 9.2.2.1 Not used.
- 9.2.2.2. Projects require a practice policy with a per claim/annual aggregate in accordance with the specifications delineated below relative to the cumulative construction value of all projects:
 - .1 One Million (\$1,000,000) Dollars on a per claim/One Million (\$1,000,000) Dollars annual aggregate basis for Project Consultants whose cumulative construction value for all Board contracts is less than Five Million (\$5,000,000) Dollars.
 - .2 One Million (\$1,000,000) Dollars on a per claim/Three Million (\$3,000,000) Dollars annual aggregate basis for Project Consultants whose cumulative construction value for all Board contracts is between Five Million One (\$5,000,001) Dollars to Ten Million (\$10,000,000) Dollars.
 - .3 One Million (\$1,000,000) Dollars on a per claim/Five Million (\$5,000,000) Dollars annual aggregate basis for Project Consultants whose cumulative construction value for all Board contracts is greater than Ten Million One (\$10,000,001) Dollars.

The Project Consultant shall be required to maintain the practice policy in accordance with the above specifications for a period commencing with execution of this contract and terminating three years after final completion of said projects. Should additional projects or change orders be added that increase the cumulative construction value to another tier shown above, the Project Consultant will be required to show proof of coverage at the higher limit / aggregate. In addition, the project consultant shall provide information regarding the total claims against said practice policy on an annual basis for the term of the contract upon and terminating three years after final completion of the project (Claims/Loss history should be forwarded to the Risk Management Department), as The School Board of Broward County, Florida, deems appropriate.

The Professional Liability insurance must provide for all sums which the Project Consultant shall be legally obligated to pay as damages for claims arising out of or relating to the negligent services performed by the Project Consultant or any person employed or acting on the Project Consultant's

behalf (including, but not limited to, Sub-Consultants) in connection with this Agreement. If the Owner, at its sole discretion, agrees that such coverage is not commercially reasonably available, the Owner may, at its discretion, authorize the Project Consultant to alter the coverage by substituting a lower aggregate or changing any other terms and conditions of the coverage (including but not limited to deductible amounts) based upon the scope of the project.

- 9.2.3 Workers' Compensation Insurance: The Project Consultant shall maintain Workers' Compensation Insurance in compliance with Florida Statutes, Chapter 440 and Employer's Liability Limit of not less than Five Hundred Thousand (\$500,000) Dollars per Occurrence.
- 9.2.4 General Liability Insurance: The Project Consultant shall maintain General Liability Insurance, including Contractual Liability to cover the "Hold Harmless Agreement" set forth herein, with bodily injury limits of not less than One Million (\$1,000,000) Dollars per occurrence combined single limit for bodily injury and property damage and not less than the Two Million (\$2,000,000) General Aggregate such coverage shall apply separately to each project. The School Board of Broward County, Florida, its members, officers, employees, and agents shall be named as an additional insured under the General Liability policy.

ARTICLE 10 GENERAL PROVISIONS

10.1 Performance

- 10.1.1 **Performance and Delegation:** The services to be performed hereunder shall be performed by the Project Consultant's and Sub-Consultant's own staff, unless otherwise approved by the Owner in writing. Said approval shall not be construed as constituting an Agreement between the Owner and said other person or firm.
- 10.1.2 **Term of Agreement:** The term of this Agreement shall start upon execution by the parties hereto and extend until the completion of Phase VI (Warranty) activities as set forth above except as may be otherwise agreed to in writing by the parties hereto, or as provided further herein under Article 10 and Article 7.
- 10.1.3 **Time for Performance:** The Project Consultant agrees to start all work hereunder upon receipt of an Authorization to Proceed issued by the Chief Facilities and Construction Officer or his designee and to complete each Phase within the time stipulated in the Authorization To Proceed (Attachment 6 to this Agreement ("ATP")) and as required by the Project Schedule (Attachment 1 to this Agreement). The Project Consultant acknowledges that failure to perform timely may cause the Owner to sustain loss and damages and will be responsible for same. The Consultant agrees that Owner is entitled to recover no less than One Hundred Dollars (\$100) per consecutive calendar day of unexcused delay caused by the Consultant's failure to comply with the times set forth in the fully executed ATP. Owner shall have the right to deduct such amounts from payments due and owing to the Consultant.
- 10.1.4 **Time Extensions**: A reasonable extension of time for completion of various Phases may be granted by the Owner should there be a delay on the part of the Owner in fulfilling its obligations pursuant to this Agreement. Such extension shall not be the basis or cause for any claims or causes of action by the Project Consultant for additional or extra compensation. Under no circumstances shall the Project Consultant be entitled to additional compensation or payment as a result of or relating to delays on the Project.
- 10.1.5 Time is of the essence with regard to the performance of this Contract.

10.1.6 **Excess Funds:** Any party receiving funds paid by the School Board of Broward County, Florida under this Agreement agrees to promptly notify the School Board of Broward County, Florida of any funds erroneously received from the School Board of Broward County, Florida of upon the discovery of such erroneous payment or overpayment. Interest shall be calculated using the interest rate for judgments under Section 55.03, Florida Statutes, as amended, applicable at the time the erroneous payment or overpayment was made by the School Board of Broward County, Florida. The erroneous payment and/or overpayment will be promptly transmitted and returned to the School Board of Broward County, Florida with applicable interest as set forth herein.

10.2 Termination Of Agreement

- 10.2.1 **Right to Terminate:** The Owner has the right to terminate this Agreement for its own convenience on seven days written notice. Upon termination of this Agreement, the Project Consultant shall be paid in accordance with Article 10.2.5. To receive payment, all charts, sketches, studies, drawings, and other documents or other materials related to work authorized under this Agreement, whether finished or not, must be turned over to the Owner.
- 10.2.2 The Consultant may terminate this Agreement only for a material breach of the Agreement and provided the Project Consultant has given the Owner written notice of the material breach and ten (10) days to cure that breach. In the event of any dispute regarding or relating to performance pursuant to this Agreement, or payment hereunder, then in that event, the Project Consultant is obligated to continue performance in accordance with the terms of this Agreement unless instructed by the Owner to suspend or delay performance.
- 10.2.3 Owner may terminate this Agreement for cause, which may include, but not be limited to any of the following; failure of Project Consultant to comply with any of its material obligations under this Agreement; a decrease in the projected, available Capital Outlay funds which renders continuation of the design or construction of the Project impossible or impractical; or conditions which arise that constitute Force Majeure under Article 10.2.8 of this Agreement. In such event Project Consultant shall not be entitled to any additional payments and may be liable to Owner for any damages or losses incurred or suffered as a result of Project Consultant's failure to properly perform pursuant to the terms of this Agreement. In the event it is later determined that the Owner was not justified in terminating the Agreement for cause, then it shall be deemed to be a termination for convenience pursuant to Article 10.2.1 above, and the Project Consultant's sole compensation shall be compensation in accordance with that paragraph.
- 10.2.4 Whether or not this Agreement is so terminated, Project Consultant shall be liable to Owner for any damage or loss resulting from such failure or violation by Project Consultant, including, but not limited to, costs in addition to those agreed to herein for prosecuting professional services to completion and delay damages paid or incurred by Owner. The rights and remedies of Owner provided by this paragraph are cumulative with and in addition to any other rights and remedies provided by law or this Agreement.
- 10.2.5 **Termination Expenses:** Termination Expenses are in addition to compensation for Basic and Supplemental Services, and are full compensation for all damages and expenses which are directly or indirectly attributable to termination. Termination Expenses are applicable only to a termination for convenience by Owner and shall be computed as a percentage of the total compensation for Basic Services and Supplemental Services earned to the time of termination, as follows:
 - .1 Twenty (20%) percent of the total compensation for Basic and Supplemental Services earned to the date of termination, if termination occurs before or during the schematic design phase; or

- .2 Ten (10%) percent of the total compensation for Basic and Supplemental Services earned to the date of termination, if termination occurs during the design development phase; or
- .3 Five (5%) percent of the total compensation for Basic and Supplemental Services earned to the date of termination, if termination occurs during any subsequent phase.
- 10.2.6 **Annulment:** The Project Consultant warrants that no one has been employed or retained other than an employee working solely for the Project Consultant, to solicit or secure this Agreement; and that the Project Consultant has not paid, nor agreed to pay, any company or other person any fee, commission, gift or other consideration contingent upon the making of this Agreement. For breach or violation of this warranty, the Owner has the right to annul this Agreement without liability.
- 10.2.7 **Fixed Fees Exceeding \$50,000:** For all Fixed Fees or other "lump-sum" fees for professional service Agreements over Fifty Thousand (\$50,000) Dollars the Project Consultant shall execute a truth-innegotiations certificate as in accordance with 287.05 and all required language set forth therein. Requirements of Florida Statute 287.055 (2004), as amended, are incorporated herein by reference.
- 10.2.8 **Force Majeure:** The Owner's or Consultant's failure to perform any term or condition of this Agreement as a result of conditions beyond its control such as, but not limited to, war, strikes, fires, floods, acts of God, governmental restrictions, power failures, or damage or destruction of any network facilities or servers, shall not be deemed a breach of this Agreement.

10.3 Project Consultant's Accounting Records and Right to Audit Provisions

- 10.3.1 Project Consultant's records which shall include any and all records reasonably requested by Owner that relate to performance of services by Project Consultant or Sub-Consultants. Records include but are not limited to information, materials and data of every kind and character (hard copy, as well as computer readable data if it exists), books, papers, documents subscriptions, recordings, estimates, price quotations, agreements purchase orders, leases, contracts, commitments, arrangements, notes, daily diaries, superintendent reports, drawings, receipts, vouchers, monthly, quarterly, yearly or other financial statements, accounting records, payroll time sheets, job cost reports, job cost history, margin analysis, written policies and procedures, all Sub-Consultant files (including proposals of successful and unsuccessful Sub-Consultants, contracts, correspondence), original estimates, estimating worksheets, computer records, disks and software, videos, photography, correspondence, change order files (including documentation covering negotiated settlements), constructability or peer reviews, coordination documents, logs and supporting documentation, general ledger entries, insurance information, and any other supporting evidence necessary to substantiate charges related to this contract (all the foregoing hereinafter referred to as "records") shall be open to inspection and subject to audit and/or reproduction, during normal working hours, by Owner's agent or its authorized representative to the extent necessary to adequately permit evaluation and verification of any invoices, payments or claims submitted by the contractor or any of his payees pursuant to the execution of the contract. Such records subject to examination shall also include, but not be limited to, those records necessary to evaluate and verify direct and indirect costs (including overhead allocations), fees, reimbursable services, etc. as they may apply to costs, matters or items associated with this contract.
- 10.3.2 For the purpose of such audits, inspections, examinations and evaluations, the Owner's agent or authorized representative shall have access to said records from the effective date of this contract, for the duration of the work, and until five (5) years after the date of final payment by Owner to Project Consultant pursuant to this contract. All costs which the Consultant is unable to provide support or documentation to substantiate that it was incurred as represented by the original estimated breakdown of cost or found not to be in compliance

- with provisions of this contract, shall be reimbursed to the Owner.
- 10.3.3 Owner's agent or its authorized representative shall have access to the Project Consultant's facilities, shall have access to all necessary records, and shall be provided adequate and appropriate work space, in order to conduct audits in compliance with this article. Owner's agent or its authorized representative shall give auditees reasonable advance notice of intended audits.
- 10.3.4 Project Consultant shall require all Sub-Consultants and insurance agents, to comply with the provisions of this article by insertion of the requirements hereof in any written contract Agreement. Failure to obtain such written contracts which include such provisions shall be reason to exclude some or all of the related costs from amounts payable to the Project Consultant pursuant to this contract.
- 10.3.5 If an audit inspection or examination in accordance with this article, discloses overcharges (of any nature) by the Project Consultant to the Owner in excess of \$25,000 the actual cost of the Owner's audit shall be paid by the Project Consultant.

10.4 Ownership of Documents

- 10.4.1 The Schematic Design and Design Development documents developed under this Contract shall become and be the sole property of the Owner whether the Project for which they were developed is executed or not. The Project Consultant may maintain copies thereof for its records and for its future professional endeavors although the Owner shall bear no liability or any responsibility whatsoever for such use of said documents by the Project Consultant. All or part of the Schematic Design and Design Development documents prepared by the Project Consultant for this project may be used as a prototype for other facilities by the Owner. Any reuse of Schematic Design or Design Development documents developed under this Contract by the Owner or others as permitted by the Owner shall be at the sole discretion of the Owner and at the Owner's sole risk.
- 10.4.2 Provided the Project Consultant has complied with the terms of this Agreement, construction working drawings, specifications and other documents or materials developed after the completion of the design development phase are and shall remain the property of the Project Consultant whether the Project for which they are made is executed or not.
- 10.4.3 The Owner shall be permitted to retain copies, including reproducible and electronic media copies, of drawings, specifications and other documents or materials developed after the Design Development Phase for various informational and reference purposes related to management, maintenance and operation of facilities, establishing construction standards, and various other archival functions without limitation and without subsequent notice to the Project Consultant.
- 10.4.4 The drawings and specifications may be used by the Owner on other projects, or for any other purpose included, but not limited to, for completion of the Project's construction in the event the Project Consultant's services are terminated as per other provisions of this Contract.
- 10.4.5 Submission or distribution to meet official regulatory requirements or for other purposes in connection with the Project is not to be construed as publication in derogation of the Project Consultant's rights.
- 10.4.6 In the event of the Project Consultant's termination under other provisions of this Agreement, the Owner shall receive all original documents prepared to the date of termination and shall have the right to use those documents and any reproductions in any way necessary to complete the Project, or for any other purpose.

- 10.4.7 In the event Owner requests any such documents or materials referred to in this Article and Project Consultant fails to provide same as requested by Owner, then Project Consultant acknowledges that Owner will be irreparably harmed and subject to an injunction to provide same.
- 10.4.8 The Owner will not modify or distribute the documents, including electronic media versions, to third parties except for those purposes listed above without the expressed permission and consent of the Project Consultant. The Owner will delete any title blocks or other marks identifying the originating Project Consultant from any materials so distributed. The Owner will indemnify the Project Consultant against any claims that result from the modification of data and disks by the Owner.

10.5 Electronic Media

10.5.1 Where this Agreement or referenced provisions in the Contract Documents require the Project Consultant to provide information or documents in either electronic or magnetic media, the preparation and format of that media shall conform to the Owner's Electronic Media Submittal Requirements (Attachment 3 to this Agreement).

10.6 Attachments and References

10.6.1 The following named attachments are made an integral part of this Agreement:

.1 Attachment 1: Project Schedule.2 Attachment 2: Project Scope

.3 Attachment 3: Electronic Media Submittal Requirements

.4 Attachment 4: Project Consultant's Invoice Format, Reimbursable and Supplemental

Services Format

.5 Attachment 5: List of Project Team Members

.6 Attachment 6: Authorization to Proceed (ATP) Form

Professional Services Required – page 1 of 3

Project Schedule – page 2 of 3 Professional Fee – page 3 of 3

.7 Attachment 7: Document Submittal Checklist

.8 Attachment 8: Document 00455 – Background Screening

.9 Attachment 9: IRS Form W-9

.10 Attachment 10: Truth in Negotiations Certificate

10.6.2 Online Documents: The following documents shall be downloaded by the Project Consultant and are considered as Attachments to this Contract:

Design Standards

http://www.broward.k12.fl.us/facilities_construction/DSS/DS_Docs/DesignStandards.htm

- Design Criteria
- Design and Material Standards Division 1 thru Division 17
- Document Submittal Checklist for Plan Review

http://www.broward.k12.fl.us/constructioncontracts/D0docs.html

• Specifications – Division 0

State Requirements for Educational Facilities (SREF) latest edition

http://www.fldoe.org/edfacil/sref.asp

• F.I.S.H. layering system for AutoCAD: Note: the laying system is not posted on line. It will need to be requested thru:

Facility Planning and Real Estate 600 SE 3rd Avenue Fort Lauderdale, FL 33312 754-321-1932

10.7 Extent of Agreement:

- 10.7.1 This Agreement represents the entire and integrated Agreement between the Owner and the Project Consultant and supersedes all prior negotiations, representations or agreements, written or oral.
- 10.7.2 This Agreement may not be amended, changed, modified, or otherwise altered in any particular, at any time after the execution hereof, except by resolution of The School Board of Broward County, Florida.
- 10.7.3 This Agreement is for the benefit of the parties to the Agreement and is not for the benefit of any other parties nor shall it create a contractual relationship with any other party.
- 10.7.4 This Agreement shall be governed by the laws of the State of Florida Venue of any action arising out of this Agreement shall be in Broward County, Florida. The parties are encouraged to participate in mediation of any dispute before engaging in litigation.

10.8 Strict Performance:

10.8.1 The failure of either party to insist upon or enforce strict performance by the other party of any of the provisions of this Agreement or to exercise any rights under this Agreement shall not be construed as a waiver or relinquishment to any extent of its rights to assert or rely upon any such provisions or rights in that or any other instance.

10.9 Prompt and Satisfactory Correction:

10.9.1 The Owner, at its sole discretion, may direct the Project Consultant, at no additional cost to the Owner, to promptly and satisfactorily correct any services found to be defective or not in compliance with the requirements of this Agreement or the requirements of any governmental authority, law, regulations or ordinances.

10.10 Successors and Assigns:

- 10.10.1 The performance of this Agreement shall not be delegated or assigned by the Project Consultant without the written consent of the Owner.
- 10.10.2 The Project Consultant and the Owner each binds one another, their partners, successors, legal representatives and assigns to the other party of this Agreement and to the partners, successors, legal representatives and assigns of such party in respect to all covenants of this Agreement.

10.11 Certification Regarding Debarment, Suspension, Ineligibility or Voluntary Exclusion:

10.11.1 Lower Tier Covered Transactions: Executive Order 12549 provides that, to the extent permitted by law, Executive departments and agencies shall participate in a government-wide system for non-procurement debarment and suspension. A person who is debarred or suspended shall be excluded from Federal financial and non-financial assistance and benefits under Federal programs and activities. Except as provided in ß 85.200, Debarment or Suspension, ß 85.201, Treatment of Title IV HEA participation, and ß85.215, Exception provision, debarment or suspension of a participant in a program by one agency shall have government-wide effect. A lower tier covered transaction is, in part, any transaction between a participant [SBBC] and a person other than a procurement contract for goods or services, regardless of type, under a primary covered transaction; and any procurement contract for goods or services between a participant and a person, regardless of type, expected to equal or exceed the Federal procurement small purchase threshold fixed at 10 U.S.C. 2304(g) and 41 U.S.C. 253(g) (currently \$100,000) under a primary covered transaction. A participant may rely upon the certification of a prospective participant in a lower tier covered transaction that it and its principals are not debarred, suspended, proposed for debarment under 48 CFR part 9, subpart 9.4, ineligible, or voluntarily excluded from the covered transaction, unless it knows that the certification is erroneous. Each participant shall require participants in lower tier covered transactions to include the following certification for it and its principals in any proposal submitted in connection with such lower tier covered transactions.

10.11.2 Certification and Disclosure

- .1 The lower tier participant (Project Consultant) certifies, by entering this Agreement, that neither it nor its principals is presently debarred, suspended, proposed for debarment, declared ineligible, or voluntarily excluded from participation in this transaction by any Federal department or agency.
- .2 Where the lower tier participant (Project Consultant) is unable to certify to any of the statements in this certification, such participant shall provide an explanation to the Owner.
- .3 The Consultant warrants that he or she has not employed or retained any company or person, other than a bona fide employee working solely for the Consultant to solicit or secure this Agreement and that he or she has not paid or agreed to pay any person, company, corporation, individual, or firm, other than a bona fide employee working solely for the Consultant any fee, commission, percentage, gift, or other consideration contingent upon or resulting from the award or making of this agreement. For the breach or violation of this provision, the Owner shall have the right to terminate the Agreement without liability and, at its discretion, to deduct from the fees due and owing to the Consultant, or otherwise recover, the full amount of such fee, commission, percentage, gift, or consideration. (Ch. 287.055, F.S.)

10.12 Non-Discrimination, EEO, and ADAAA

- 10.12.1 **Non-Discrimination -** The School Board of Broward County, Florida prohibits any policy or procedure which results in discrimination on the basis of age, color, disability, gender, national origin, marital status, race, religion or sexual orientation.
- 10.12.2 Equal Employment Opportunity (EEO) The School Board of Broward County, Florida, prohibits any

policy or procedure which results in discrimination on the basis of age, color, disability, gender identity, gender expression, national origin, marital status, race, religion, sex or sexual orientation. Individuals who wish to file a discrimination and/or harassment complaint may call the Executive Director, Benefits & EEO Compliance at 754-321-2150 or Teletype Machine (TTY) 754-321-2158.

10.12.3 Americans with Disabilities Act Amendments Act of 2008 - Individuals with disabilities requesting accommodations under the Americans with Disabilities Act Amendments Act of 2008, (ADAAA) may call Equal Educational Opportunities (EEO) at 754-321-2150 or Teletype Machine (TTY) 754-321-2158.

10.13 Captions

10.13.1 Captions – The captions, section numbers, article numbers, title and headings appearing in this Agreement are inserted only as a matter of convenience and in no way define, limit, construe or describe the scope or intent of such articles or sections of this Agreement, nor in any way effect this Agreement and shall not be construed to create a conflict with the provisions of this Agreement.

10.14 Authority

10.14.1 **Authority Provision:** Each person signing this agreement on behalf of either party individually warrants that he or she has full legal power to execute this Agreement on behalf of the party for whom he or she is signing, and to bind and obligate such party with respect to all provisions contained in this Agreement.

10.15 Notice

Notice Provision: When any of the parties desire to give notice to the other, such notice must be in writing, sent by US Mail, postage prepaid, addressed to the party for whom it is intended at the place last specified; the place for giving notice shall remain such until it is changed by written notice in compliance with the provisions of the paragraph. For the present, the parties designate the following as the respective places for giving notice.

To SBBC: Superintendent of Schools

The School Board of Broward County, Florida

600 Southeast Third Avenue Fort Lauderdale, Florida 33301

With a Copy to: Office of the Chief Facilities Officer

600 SE 3 Avenue

Fort Lauderdale, FL 33312 **Attn: Leo Bobadilla** Chief Facilities Officer

With a Copy to: Office of Facilities and Construction

3775 SW 16th St

Fort Lauderdale, FL 33312 **Attn: Shelley N. Meloni**

Director, Pre-Construction Office of Facilities and Construction

And

Heery International, Owners Representative

811 Ponce de Leon Boulevard Coral Gables, FL 33134

Attn: Robert Corbin

Program Director/Vice President

To Design Professional: Insert Name and Address Provided by Other Party

With a Copy to: Insert Name and Address Provided by Other Party

10.16 Excess Funds

10.16.1 Any party receiving funds paid by The School Board of Broward County, Florida (SBBC) under this Agreement agrees to promptly notify SBBC of any funds erroneously received from SBBC upon the discovery of such erroneous payment or overpayment. Any such excess funds shall be refunded to SBBC with interest calculated from the date of the erroneous payment or overpayment. Interest shall be calculated using the interest rate for judgments under Section 55.03, Florida Statutes, applicable at the time the erroneous payment or overpayment was made by SBBC.

10.17 Background Screening

10.17.1 **Background Screening**. Project Consultant agrees to comply with all requirements of Sections 1012.32 and 1012.465, Florida Statutes, and that Project Consultant, its agents, subconsultants and all of its personnel who (1) are to be permitted access to school grounds when students are present, (2) will have direct contact with students, or (3) have access or control of school funds will successfully complete the background screening required by the referenced statutes and meet the standards established by the statutes. This background screening will be conducted by SBBC in advance of Project Consultant or its personnel providing any services under the conditions described in the previous sentence. Project Consultant will bear the cost of acquiring the background screening required by Section 1012.32, Florida Statutes, and any fee imposed by the Florida Department of Law Enforcement to maintain the fingerprints provided with respect to Project Consultant and its personnel. The Parties agree that the failure of Project Consultant to perform any of the duties described in this section shall constitute a material breach of this Agreement entitling SBBC to terminate immediately with no further responsibilities or duties to perform under this Agreement.

Project Consultant agrees to indemnify and hold harmless SBBC, its officers and employees from any liability in the form of physical or mental injury, death or property damage resulting from Project Consultant's failure to comply with the requirement of this Section or Section 1012.32 and Section 1012.465, Florida Statutes in addition to any other indemnification obligations that may be imposed upon Project Consultant pursuant to Article 8 of this Agreement and the laws of Florida.

10.18 Errors and Omissions

10.18.1 The Project Consultant shall be responsible for any errors, inconsistencies or omissions in the drawings, specifications, and other documents. The Project Consultant will correct the drawings and specifications at no additional design cost to the Owner for any and all errors and omissions in the drawings, specifications prepared by the Project Consultant. The Project Consultant further agrees, at no additional cost, to render assistance to the Owner in resolving problems relating to the design or specified materials.

10.18.2 Deductions may be made from the Project Consultant's Basic Services Compensation on account of errors and omissions in the drawings, specifications and other documents prepared by the Project Consultant or in the Project Consultant's performance of its obligations under this Agreement.

ARTICLE 11 INCORPORATION OF RFQ INTO AGREEMENT

11.1 In addition to those Attachments and References identified and made part of this Agreement in Article 10.6.1, the provisions of RFQ No. XXX ("TYPE OF SERVICE") (the "RFQ") are hereby incorporated into this Agreement. In the event of conflict between the provisions contained in this Agreement and the RFQ, the more stringent provision shall prevail. If this Agreement is silent on an issue that is contained with the RFQ, the provisions of the RFQ shall be followed.

IN WITNESS WHEREOF, The School Board of Broward County, Florida, has caused this Agreement to be executed by the undersigned and the seal of the School Board to be set hereto; and the said Project Consultant has caused this Agreement to be executed by the undersigned and the seal of the Project Consultant set hereto on this day and year first above written.

THE SCHOOL BOARD OF BROWARD COUNTY, FLORIDA

(SEAL)	
ATTEST THE SCHOOL BOARD OF BROWARD COUNTY, FLORIDA	
Robert W. Runcie, Superintendent of Schools	Dr. Rosalind Osgood, Chair
Approved as to Form and Legal Content:	
Office of the General Counsel	
DELETE THE SIGNA	TURE SECTIONS NOT USED
WHEN THE PROJECT CONSULTANT IS A	CORPORATION OR PROFESSIONAL ASSOCIATION
(Corporate Seal)	
(ATTEST)	(Type Name of Firm Here) Legal Name of Corporation

Secretary, (Type Name Here)
(Type Registration Number Here)
Project Consultant's
Registration Number

WHEN THE PROJECT CONSULTANT IS AN INDIVIDUAL OR PARTNERSHIP

(ATTEST)	
Witness (Type Name Here)	Legal Name of Individual or Partnership
Witness (Type Name Here)	By: Signature (Type Name Here)
	Project Consultant's Registration Number
WHEN THE PROJEC	T CONSULTANT IS A JOINT VENTURE
(Corporate Seal)	(Corporate Seal)
Firm's Legal Name	Firm's Legal Name
By:	By:Signature (Type Name Here)

	Project Consultant's Registration Number			
(ATTEST)				
Witness (Type Name Here)	Witness (Type Name Here)			
Witness (Type Name Here)	Witness (Type Name Here)			

ACKNOWLEDGEMENT

STATE OF FLORIDA COUNTY OF BROWARD

BEFORE ME this	day of	,	, aj	ppeared	, and,	
		personally know	wn to me to be t	he persons desc	cribed in and who	executed
the foregoing contract and	d acknowledge th	nat he executed t	the same as his	free act and dec	ed for the purpos	es therein
expressed.						
WITNESS my hand ar	nd official seal	in the County	and State la	st official this	s	day of
	, 201					
Notary Public State of Flo	orida					
My Commission Expires:						

				Owner's Initial Schooling	
Activity ID	Activity Name	Remaining	Start	Finish	oute 2014 2015 2016
		Duration			A S O N D J F M A M J Jul A S O N D J F M A M
SCHEDULE		324	08-Jul-14	02-Jun-15	Q2-Jun-15, SCHEDULE
DESIGN		26	08-Jul-14	13-Oct-14	13-Oct-14, DESIGN
A1000	Pre-Design	7	08-Jul-14	14-Jul-14	Pre-Design
A1010	Authorization to Proceed (ATP)	0	15-Jul-14		Authorization to Proceed (ATP)
A1020	Schematic Design (30%)	21	15-Jul-14	04-Aug-14	Schematic Design (30%)
A1030	Plan Review - Schematic Design	2	05-Aug-14	09-Aug-14	Plan Review - Schematic Design
A1040	Design Development (60%)	28	10-Aug-14	07-Sep-14	Design Development (60%)
A1050	Plan Review - Design Development	2	08-Sep-14	12-Sep-14	Plan Review - Design Development
A1060	90% Constuction Documents	41	13-Sep-14	26-Sep-14	90% Constuction Documents
A1070	Plan Review - 90% Construction Documents	2	27-Sep-14	01-Oct-14	Plan: Review - 90% Construction Documents
A1080	100% Construction Documents	7	02-Oct-14	08-Oct-14	100% Construction Documents
A1090	Plan Review - 100% Construction Documents	2	09-Oct-14	13-Oct-14	Plan Review - 100% Construction Documents
A1100	Submittal of 100% CDs to Building Dept.	0		13-Oct-14	Submittal of 100% CDs to Building Dept.
PERMITTING	ING	26	14-Oct-14	08-Nov-14	V8-Nov-14, PERMITTING
A1110	Building Deparment Initial Plan Review	41	14-Oct-14	27-0ot-14	Building Department Initial Plan Review
A1120	Plan Revisions by Design Professional	7	28-Oct-14	03-Nov-14	Plan Revisions by Design Professional
A1130	Resubmittal of revised Plans to Building Dept.	0	04-Nov-14		Resubmittal of revised Plans to Building Dept.
A1140	Building Department 2nd Plan Review	5	04-Nov-14	08-Nov-14	Building Department 2nd Plan Review
A1150	Permit Approval	0		08-Nov-14	Permit Approval
PROCUREMENT	EMENT	21	09-Nov-14	01-Dec-14	OI-DEC-14, PROCUREMENT.
A1160	Procurement	21	09-Nov-14	01-Dec-14	Procurement
CONSTRUCTION	UCTION	180	02-Dec-14	02-Jun-15	▼ C2-Jun-15, CONSTRUCTION
A1170	Construction & Closeout	180	02-Dec-14	02-Jun-15	Gonstruction & Closeout

Electronic Media Requirements

All Work product for all projects, requires hard copies, electronic copies (PDF) and electronic original copies. The electronic media requirements are as listed below.

ELECTRONIC MEDIA

1.0 General Information

1.1 The School Board of Broward County, Florida contracts with one or more Internet bid advertising and distribution services. The Design Professional shall post the complete bid package to these services upon written notification by the Owner. The posted documents shall be read only documents and the file format shall be PDF.

2.0 Software Requirements

- 2.1 Word Processing
 - 2.1.1 Provide word processing files in Microsoft Word for Windows compatible file formats including all information necessary for remote printing.
- 2.2 Spreadsheets
 - 2.2.1 Provide spreadsheet files in Microsoft Excel for windows compatible file formats including all information necessary for remote printing.
- 2.3 Computer aided Design and Drafting
 - 2.3.1 Provide all CADD files as AutoCAD 2010 files, Window's version.

3.0 CAD Standards

- 3.1 Standard plotted drawing size: 24 inch x 36 inch or 30 inch x 42 inch sheets.
 - 3.1.1 All sheets within a set shall be the same size unless pre-approved otherwise. (for example survey sheets)
- 3.2 Design Professional shall provide to the Owner the standard file naming Protocol they will be utilizing.
- 3.3 CAD File Layering
 - 3.3.1 Conform to the most up to date guidelines defined by the American Institute of Architects (AIA) standard document, "CAD Layer Guidelines."
 - 3.3.2 Provide the required Layering for the Florida Inventory of Schoolhouses (F.I.S.H.) documents
 - 3.3.1.1 The F.I.S.H. layering scheme is not available on-line. It can be requested through:

- 3.3.3 Provide a separate list of all layers which do not conform to the standard AIA CAD Layer Guidelines or the FISH layering scheme.
- 3.4 No custom hatch patterns shall be utilized.
- 3.5 All symbols and blocks to have descriptive names
- 4.0 Electronic Media Delivery Requirements
 - 4.1 Transmittals shall include the following
 - 4.1.1 The Project Number, Project Title and date
 - 4.1.2 The Facility Name
 - 4.1.3 The submittal type
 - 4.1.4 The format and version of the software.
 - 4.1.5 An attached Listing of file names with the latest document publish dates
 - 4.2 All electronic media shall contain an attached label which shall identify 4.1.1, 4.1.2, and 4.1.3.
 - 4.3 Document clean-up
 - 4.3.1 Before a CADD file is placed on the delivery electronic digital media, the following procedures shall be performed:
 - 4.3.1.1 Purge all files and remove all extraneous graphics outside the border area.
 - 4.3.1.2 Make sure all reference files are attached without device path
 - 4.3.1.3 All required project files both graphic and nongraphic, shall include color tables, pen tables, font libraries, block libraries, user command files, plot files, etc. All project related blocks must be provided to the Owner as a part of the electronic digital deliverables.
 - 4.3.1.4 Make sure that all support files such as those listed above are in the same directory and that references to those files do not include device Path.
 - 4.4 The following Plot File Development and Project Documentation Information shall be submitted as an enclosure or attachment to the transmittal letter provided with each electronic digital media submittal.
 - 4.4.1 Documentation of the plot files for each drawing which will be needed to be able to allow identical plotting by the Owner at a later date. This documentation shall include the plotter configuration (e.g., name and model of plotter), pen settings, drawing orientation, drawing

size, and any other special instructions.

- 4.4.2 Instructions concerning how to generate plotted, drawings from the provided plot files.
- 4.5 Provide all symbols and blocks used in the project in a separate files.
- 4.6 List of all database/spreadsheet files associated with each drawing, as well as a description and documentation of the database format.
- 5.0 Ownership: Refer to Agreement for specific Owner and Design Professional's rights.
- 6.0 Documents for the Construction Contractor:
 - 6.1 The Owner and the Design Professional shall make various electronic information available to the Contractor during the Construction phase of the Project.
- 7.0 Where electronic media submittals of final site surveys are required: Provide electronic copies of any existing site survey data already on electronic media.
- 8.0 At the Contractors option, the Design Professional will provide the Contractor one set of AutoCAD (.dwg) electronic file format contract drawings, to be used for as built drawings at the Contractor's option. Note that the Architect's name and information to be removed.

Design Professionals Invoice Format

The School Board of Broward County, Florida requires submittal of the Design Professional's invoice on the District's standard invoice forms attached to a transmittal form or letter on the Design Professional's company letterhead. Include the information and attachments described below:

- 1. Letterhead Containing Firm Information
 - A. Firm Name
 - B. Address
 - C. Telephone and FAX Numbers
 - D. Consultant's Invoice Reference Number
- 2. Address Transmittal/Letter to:

Office of Facilities and Construction The School Board of Broward County, Florida 3775 SW 16th Street Fort Lauderdale, FL 33312 Attention: Name of Project Manager

- 3. Ensure that Transmittal/Letter references the following information:
 - A. Date of submittal.
 - B. The Invoice Number for ATP Number (example: Invoice No. 01 for ATP No. 01).
 - C. The School Board of Broward County's Purchase Order No.: (Which will be provided by the Facilities Project Manager at the beginning of the project.)
 - D. Name of Facility (and Facility Number).
 - E. Name of Project
 - F. School Board Project Number
- 4. Ensure attachment of the following documents to the Transmittal/Letter:
 - A. Design Professional's Invoice Form
 - B. Design Professional's Reimbursable Invoice Form
 - C. Copy of signature page (page 3 of 3) of the Design Professional's Authorization to Proceed.



The School Board of Broward County, Florida Florida Facilities and Construction Management Department 3775 SW 16th Street Fort Lauderdale, FL 33312 (754) 321-1500

Design Professional	Date:
Design Professional	Date.

(Name)

Project No: Facility Name: Invoice No: Project Title: SBBC PO No. Design Professional's ATP No. Remit to address: Invoice From:

Project Manager

Original Basic Fee	\$
Current basic fee	\$

INVOICE TOTALS:

Summary	Current Fee	Previously Billed	This Invoice	Balance
Basic Services	\$	\$	\$	\$
Reimbursable	\$	\$	\$	\$
Total:	\$	\$	\$	\$

BASIC FEE TOTALS:

Period	Fee	Previously Bille	ed .		This	Invoice	Balance	
From to dates	\$	\$	%	\$		%	\$	%
	\$	\$	%	\$		%	\$	%
	\$	\$	%	\$		%	\$	%
	\$	\$	%	\$		%	\$	%
	\$	\$	%	\$		%	\$	%
Other Services	\$	\$	%	\$		%	\$	%
Total Previously	Billed:	\$						 _
Total Amount T	his Invoice:			\$				
Total Balance:				•				\$

Submitted By: Name:	Certified By: Name: Title:	Recommended By:	Approved By:
Title: Date: (Signature)	Project Manager Date:	Name: Title: Date:	Name: Title: Date:
	(Signature)	(Signature)	(Signature)



The School Board of Broward County, Florida Florida Facilities and Construction Management Department 3775 SW 16th Street Fort Lauderdale, FL 33312 (754) 321-1500

Design Professional's Reimbursable Invoice
--

Project No:	Facility Name: Invoice No:	
Project Title:	SBBC PO No.	
Design Professional's:	ATP No.	
Remit to address:	Invoice From:	
	Project Manager:	

Item No.	Date	Reimbursable Item	Amount
		Invoice Total	\$

Receipts for each Item must be attached.

Current Contract Amount:

Total This Invoice:

Total Previously Billed:

Total Balance:

Submitted By: Name:	Certified By: Name: Title:	Recommended By:	Approved By: Name: Title:
Title: Date:	Project Manager Date:	Name: Title: Date:	Date:
(Signature)	(Signature)	(Signature)	(Signature)

PSA Attachment 6



The School Board of Broward County, Florida **Office of Facilities & Construction** 3775 S.W. 16th Street

Fort Lauderdale, Florida 33312

(754) 321-1500

	(Consultant's Authorization	To Proceed		
Project No.:		Date:			
Location No.:		SDDC D C. N.			
Project Title:		SBBC P.O. No.:			
		Line No.:			
Facility Name:		Project Manager:			
Project Consultant:		Dir. Capital Planni	Dir. Capital Planning & Programming		
Under the mor	visions of vov	a contract for professional convices	you are housey outhonized to mucoood with the		
		ject referenced above.	you are hereby authorized to proceed with the		
following service	ees for the pro	jeet referenced above.			
Schematic Design	Design	n Development	Construction Documents		
Bidding		ruction Contract Administration	Warranty		
Other Services:	Other Services: Attached:				
_	-				
This Authorizat	tion to Proceed	l is subject to the following attachmen	ts:		
A ++ = = 1	D. f	and Camina Damina			
Attachments:	Project S	onal Services Required			
	Profession				
	Previous	ATP's			
			onal Services Required with a Fixed Limit of		
Construction Co	ost (FLCC) to	r this project as indicated below:			
Original FLCO	C	Current Cost Estimate	Revised FLCC by ATP		
31-6-1111					
			•		
		ervices will be provided by the Project	Consultant as a normal part of its Basic Services		
for the Project 1	isted above:				
Item	Discipline	Description			
пеш	Discipline	Description			

PSA Attachment 6



The School Board of Broward County, Florida Office of Facilities & Construction 3775 S.W. 16th Street Fort Lauderdale, Florida 33312

(754) 321-1500

Consultant's Authorization To Proceed (Term Contracts) Cont.

	Project Schedule		
Project No. & Location No.:	Project Title:		
Facility Name: Project Consultant:			
The required project schedule milestones for th	is project are presented below. (N	Iandatory)	
ACTIVITY Schematic Design		Date Required Or Estin Start	nated Time Period Finish
Design Development			
Construction Documents Development			
50% Construction Documents			
100% Construction Documents			
Bidding and Award of Contract			
Time for Permitting of Submittals, Prior to the Issuance of the Construction NTP (Part of Contract Administration)		
Construction			
Warranty			

PSA Attachment 6



The School Board of Broward County, Florida Office of Facilities & Construction 3775 S.W. 16th Street

Fort Lauderdale, Florida 33312

(754) 321-1500

	Consultant's	s Authorization To	Proceed (Term C	Contracts)		
		Profession	nal Fees			
Project No. & Location No.:	Project Title:					
Facility Name: Project Consultant:						
Phase	Original Basic Fee	Fee Authorized by ATP	Fee Previously Paid	Fee Balance		
I (SD) (5%)		%	%	%		
II (DD) (10%)		%	%	%		
III (CD) (35%/60%)		%	%	%		
IV (BID) (65%)		%	%	%		
V (CA) (98%)		%	%	%		
VI (Warr) (100%)		%	%	%		
Other Service		%	%	%		
Item No. 1						
Other Service		%	%	%		
(Item No. 2)						
Other Service		%	%	%		
(Item No. 3)						
Other Service		%	%	%		
(Item No. 4)						
Total:						
Payment for	these services shall	be made In accordance with	h the provisions of the Prot	fessional Services Agreement.		

Approved By Consultant			Recommended By SBBC			
Name:			Name: Shelley N. Meloni			
Title:			Title: Director, Pre-Construction			
Signature:		Date:		Signature:		Date
Certified By SBBC			Approval by SBBC			
Name:			Name: Leo Bobadilla			
Title:			Title: Chief Facilities Officer			
Signature:		Date:		Signature:		Date

This document is part of the Professional Services Agreement between The School Board of Broward County, Florida (Owner) and the Design Professional and is incorporated by reference into the terms and conditions of that agreement.

Form W-9 (Flow, August 2013) Department of the Treasury

Request for Taxpayer Identification Number and Certification

Give Form to the requester. Do not send to the IRS.

internal	Rayenua Sarvice		
	Name (as shown o	on your income tax return)	,
ci e	Business name/dis	sregarded entity name, if different from above	
e bad uo si	Check appropriate	e box for federal tax classification: le proprietor	Examptions (see Instructions):
Print or type See Specific Instructions on	Limited liabili	Ifty company. Enter the tax classification (C–C corporation, S–S corporation, P−partnership) ►	Examption from FATCA reporting code (if any)
돌트	Other (see in	ostructions) >	A ***
affic.			ame and address (optional)
See Spe	City, state, and Zit	P code	
"	List account numb	ber(s) here (optional)	
Par	Tayna	aver Identification Number (TIN)	
			al security number
to avo	id backup withho nt alien, sole proj	olding. For Individuals, this is your social security number (SSN). However, for a prietor, or disregarded entity, see the Part I Instructions on page 3. For other over identification number (EIN). If you do not have a number, see How to get a	□-□-□
Note.		In more than one name, see the chart on page 4 for guidelines on whose	oyer identification number
Part	Certifi	ication	
Under	penalties of perju	ury, I certify that:	
1. The	e number shown	on this form is my correct taxpayer identification number (or I am waiting for a number to b	e issued to me), and
Ser	rvice (IRS) that I a	backup withholding because: (a) I am exempt from backup withholding, or (b) I have not be am subject to backup withholding as a result of a failure to report all interest or dividends, o backup withholding, and	
3. I an	n a U.S. citizen o	or other U.S. person (defined below), and	
4. The	FATCA code(s) e	entered on this form (if any) indicating that I am exempt from FATCA reporting is correct.	
Interes genera Instruc	se you have falle st paid, acquisitio ally, payments ot ctions on page 3.	ons. You must cross out Item 2 above if you have been notified by the IRS that you are our of to report all interest and dividends on your tax return. For real estate transactions, Item 2 on or abandonment of secured property, cancellation of debt, contributions to an individual ther than interest and dividends, you are not required to sign the certification, but you must	does not apply. For mortgage I retirement arrangement (IRA), and
Sign Here			
		A DECEMBER OF THE PROPERTY OF	

General Instructions

Section references are to the Internal Revenue Code unless otherwise noted.

Future developments. The IRS has created a page on IRS.gov for information about Form W-9, at www.hs.gov/w9. Information about any future developments affecting Form W-9 (such as legislation enacted after we release it) will be posted on that page.

Purpose of Form

A person who is required to flie an information return with the IRS must obtain your correct taxpayer identification number (TIN) to report, for example, income paid to you, payments made to you in settlement of payment card and third party network transactions, real estate transactions, mortgage interest you paid, acquisition or abandonment of secured property, cancellation of debt, or contributions you made to an IRA.

Use Form W-9 only if you are a U.S. person (including a resident aller), to provide your correct TIN to the person requesting It (the requester) and, when applicable, to:

- Cortify that the TIN you are giving is correct (or you are waiting for a number to be issued),
- 2. Certify that you are not subject to backup withholding, or
- Claim exemption from backup withholding if you are a U.S. exempt payee. If applicable, you are also certifying that as a U.S. person, your allocable share of any partnership income from a U.S. trade or business is not subject to the

withholding tax on foreign partners' share of effectively connected income, and 4. Certify that FATCA code(s) entered on this form (if any) indicating that you are exempt from the FATCA reporting, is correct.

Note. If you are a U.S. person and a requester gives you a form other than Form W-9 to request your TIN, you must use the requester's form if it is substantially similar to this Form W-9.

Definition of a U.S. person. For federal tax purposes, you are considered a U.S. person if you are:

- . An individual who is a U.S. citizan or U.S. resident allen,
- A partnership, corporation, company, or association created or organized in the United States or under the laws of the United States,
- . An estate (other than a foreign estate), or
- A domestic trust (as defined in Regulations section 301.7701-7).

Special rules for partnerships. Partnerships that conduct a trade or business in the United States are generally required to pay a withholding tax under section 1446 on any foreign partners' share of offschiely connected taxable income from such business. Further, in certain cases where a Form W-9 has not been received, the rules under section 1446 require a partnership to presume that a partner is a foreign person, and pay the section 1446 withholding tax. Therefore, if you are a U.S. person that is a partner in a partnership conducting a trade or business in the United States, provide Form W-9 to the partnership to establish your U.S. status and avoid section 1446 withholding on your share of partnership income.

Cat. No. 10231X Form W-9 (Flov. 8-2013)

Page 2 Form W-9 (Rev. 8-2013)

In the cases below, the following person must give Form W-9 to the partnership for purposes of establishing its U.S. status and avoiding withholding on its allocable share of not income from the partnership conducting a trade or business in the United States:

- In the case of a disregarded entity with a U.S. owner, the U.S. owner of the disregarded entity and not the entity,
- In the case of a grantor trust with a U.S. grantor or other U.S. owner, generally, the U.S. grantor or other U.S. owner of the grantor trust and not the trust, and
- In the case of a U.S. trust (other than a granter trust), the U.S. trust (other than a granter trust) and not the beneficiaries of the trust.

Foreign person, if you are a foreign person or the U.S. branch of a foreign bank that has elected to be treated as a U.S. person, do not use Form W.9. Instead, u the appropriate Form W-8 or Form 8233 (see Publication 515, Withholding of Tax on Normaldent Allens and Foreign Entities).

Nonresident alien who becomes a resident alien. Generally, only a nonresident alien individual may use the terms of a tax treatly to reduce or eliminate U.S. tax or certain types of income. However, most tax treatles contain a provision known as a "serving clause." Exceptions specified in the saving clause may permit an examption from tax to continue for certain types of income even after the payee has otherwise become a U.S. resident alien for tax purposes.

If you are a U.S. resident allen who is relying or an exception contained in the saving clause of a tax treaty to claim an exemption from U.S. tax on certain types of income, you must attach a statement to Form W-9 that specifies the following flive itams:

- The treaty country. Generally, this must be the same treaty under which you claimed exemption from tax as a nonresident alien.
- 2. The treaty article addressing the income.
- 3. The article number (or location) in the tax treaty that contains the saving clause and its exceptions.
- 4. The type and amount of income that qualifies for the exemption from tax.
- 5. Sufficient facts to justify the examption from tax under the terms of the treaty

Example. Article 20 of the U.S.-China income tax treaty allows an exemption from tax for scholarship income received by a Chinese student temporarity present in the United States. Under U.S. taw, this student will become a resident allen for tax purposes if his or her stay in the United States exceeds 5 calander years. However, paragraph 2 of the first Protocol to the U.S.-China treaty (dated April 30, However, paragraph 2 of the inter Protocol to the U.S.-China treaty (cased April 30, 1984) allows the provisions of Article 20 to continue to apply even after the Chinese student becomes a resistent alien of the United States. A Chinese student who qualifies for this exception (under paragraph 2 of the first protocol) and is relying on this exception to claim an exemption from tax on his or her scholarship or fallowship income would attach to Form W-9 a statement that includes the information described above to support that exemption.

If you are a norresident alien or a foreign entity, give the requester the ppropriate completed Form W-8 or Form 8233.

appropriate completed Form W-8 or Form 8233.

What is backup withholding? Persons making certain payments to you must under certain conditions withhold and pay to the IRS a percentage of such payments. This is called "backup withholding." Payments that may be subject to backup withholding include interest, tax-exemple interest, dividends, broker and barter exchange transactions, rants, royalties, nonemployee pay, payments made in softlement of payments and third party network transactions, and certain payments from fishing boat operators. Real estate transactions are not subject to backup withholding.

You will not be subject to backup withholding on payments you receive if you give the requester your correct TIN, make the proper certifications, and report all your taxable interest and dividends on your tax return.

Payments you receive will be subject to backup withholding if:

- 1. You do not furnish your TIN to the requester,
- 2. You do not certify your TIN when required (see the Part II instructions on page
- 3. The IRS tells the requester that you furnished an incorrect TIN,
- The IRS tells you that you are subject to backup withholding because you did not report all your interest and dividends on your tax return (for reportable interest and dividends only), or
- You do not cartify to the requester that you are not subject to backup withholding under 4 above (for reportable interest and dividend accounts opened after 1983 only).

Certain payoes and payments are exempt from backup withholding. See Exempt payoe code on page 3 and the separate instructions for the Requester of Form W-9 for more information.

Also see Special rules for partnerships on page 1.

What is FATCA reporting? The Foreign Account Tax Compilance Act (FATCA) requires a participating foreign financial institution to report all United States account holders that are specified United States persons. Certain payees are exempt from FATCA reporting. See Exemption from FATCA reporting code on page 3 and the Instructions for the Requester of Form W-9 for more information.

Updating Your Information

You must provide updated information to any person to whom you claimed to be an axempt payee if you are no longer an exempt payee and anticipate receiving reportable payments in the future from this person. For example, you may need to provide updated information if you are a C corporation that elects to be an S corporation, or if you no longer are tax exempt. In addition, you must furnish a new Form W-9 if the name or TIN changes for the account, for example, if the grantor of a strately that they of a grantor trust dies.

Failure to furnish TIN. If you fail to furnish your correct TIN to a requester, you are subject to a penalty of \$50 for each such failure unless your failure is due to reasonable cause and not to willful neglect.

Civil penalty for false information with respect to withholding. If you make a false statement with no reasonable basis that results in no backup withholding, you are subject to a \$500 penalty.

Criminal penalty for faisitying information. Willfully faisitying certifications or affirmations may subject you to criminal penalties including fines and/or imprisonment.

suse of TINs, if the requester discloses or uses TINs in violation of federal law, requester may be subject to civil and criminal penalties.

Specific Instructions

if you are an individual, you must generally enter the name shown on your income tax return. However, if you have changed your last name, for instance, due to marriage without informing the Social Security Administration of the name change, enter your first name, the last name shown on your social security card, and your now last name.

If the account is in joint names, list first, and then circle, the name of the person or entity whose number you entered in Part I of the form.

Sole proprietor. Enter your individual name as shown on your income tax return on the "Name" line. You may enter your business, trade, or "doing business as (DBA)" name on the "Business name/disregarded entity name" line.

Partnership, C Corporation, or S Corporation. Enter the entity's name on the "Name" line and any business, trade, or "doing business as (DBA) name" on the "Business name/disregarded entity name" line.

Disregarded entity. For U.S. toderal tax purposes, an entity that is disregarded as an entity separate from its owner is treated as a "disregarded entity." See Regulation section 301.7701-2(c)(2)(ii). Enter the owner's name on the "Name" line. The name of the entity entered on the "Name" line should never be a disregarded entity. The name on the "Name" line must be the name shown on the disregarded ontity. The name on the "Name" line must be the name shown on the income tax return on which the income should be reported. For example, if a foreign LLC that is treated as a disregarded entity for U.S. federal tax purposes has a single cowner that is a U.S. person, the U.S. owner's name is required to be provided on the "Name" line. If the direct owner of the entity is also a disregarded entity, enter the first owner that is not disregarded for federal tax purposes. Enforthed disregarded entity's name on the "Business name/disregarded entity name" line. If the owner of the disregarded entity is a foreign person, the owner must complete an appropriate Form W.-8 instead of a Form W.-9. This is the case even if the foreign person person have a U.S. Till. the foreign person has a U.S. TIN.

Note. Chack the appropriate box for the U.S. federal tax classification of the person whose name is entered on the "Name" line (Individual/sole proprietor, Partnership, C Corporation, S Corporation, Trust/estate).

Partnership, C Corporation, S Corporation, Trust/estate).

Limited Liability Company (LLC). If the person identified on the "Name" line is an LLC, check the "Limited liability company" box only and enter the appropriate code for the U.S. federal tax classification in the space provided, if you are an LLC that is treated as a partnership for U.S. federal tax purposes, enter "P" for partnership. If you are an LLC that has filed a Form 8832 or a Form 2553 to be taxed as a corporation, enter "C" for C corporation or "S" for S corporation, as appropriate. If you are an LLC that is disregarded as an entity separate from its owner under Regulation section 301.7701-3 (except for employment and excise tax), do not check the LLC box unless the owner of the LLC (regulared to be identified on the "Name" line) is another LLC that is not disregarded for U.S. footral fax purposes. If the LLC is disregarded as an entity separate from its owner, enter the appropriate tax classification of the owner identified on the "Name" line) in the lack of the owner identified on the "Name" line). "Name" line.

Other entitles. Enter your business name as shown on required U.S. federal tax documents on the "Name" line. This name should match the name shown on the charter or other legal document creating the entity. You may enter any business, trade, or DBA name on the "Business name/disregarded entity name" line.

Exemptions

If you are exempt from backup withholding and/or FATCA reporting, enter in the Exemptions box, any code(s) that may apply to you. See Exempt payee code and Exemption from FATCA reporting code on page 3.

Form W-0 (Rev. 8-2013) Page 3

Exempt payee code. Generally, individuals (including sole proprietors) are not exampt from backup withholding. Corporations are exempt from backup withholding for certain paymonts, such as interest and dividends. Corporations are not exampt from backup withholding for payments made in settlement of payment card or third party network transactions.

Note. If you are exampt from backup withholding, you should still complete this form to avoid possible erroneous backup withholding.

The following codes identify payees that are exempt from backup withholding:

- 1—An organization exempt from tax under section 501(a), any IRA, or a custodial account under section 403(b)(7) if the account satisfies the requirements of section 401(f)(2)
- 2-The United States or any of its agencies or instrumentalities
- 3—A state, the District of Columbia, a possession of the United States, or any of their political subdivisions or instrumentalities
- 4—A foreign government or any of its political subdivisions, agencies, or instrumentalities
- 5-A corporation
- 6—A dealer in securities or commodities required to register in the United States, the District of Columbia, or a possession of the United States
- 7—A futures commission merchant registered with the Commodity Futures Trading Commission
- 8-A real estate investment trust
- $9-\text{An ontity registered at all times during the tax year under the investment Company Act of 1940$
 - 10-A common trust fund operated by a bank under section 584(a)
 - 11-A financial institution
- 12—A middleman known in the investment community as a nominee or custodian
- 13-A trust exampt from tax under section 664 or described in section 4947

The following chart shows types of payments that may be exempt from backup withholding. The chart applies to the exempt payees listed above, 1 through 13.

IF the payment is for	THEN the payment is exempt for		
Interest and dividend payments	All exempt payees except for 7		
Broker transactions	Exempt payees 1 through 4 and 6 through 11 and all C corporations. S corporations must not enter an exempt payee code because they are exempt only for sales of noncovered securities acquired prior to 2012.		
Barter exchange transactions and patronage dividends	Exempt payous 1 through 4		
Payments over \$600 required to be reported and direct sales over \$5,000 f	Generally, exempt payees 1 through 5 ²		
Payments made in settlement of payment card or third party network transactions	Exempt payees 1 through 4		

See Form 1009-MISC, Miscellaneous Income, and its instructions.

Examption from FATCA reporting code. The following codes identify payees that are exempt from reporting under FATCA. These codes apply to persons submitting this form for accounts maintained outside of the United States by certain foreign financial institutions. Therefore, if you are only submitting this form for an account you hold in the United States, you may leave this field blank. Consult with the person requesting this form if you are uncertain if the financial institution is subject to these requirements.

- A-An organization exampt from tax under section 501(a) or any individual retirement plan as defined in section 7701(a)(37)
 - B-The United States or any of its agencies or instrumentalities
- C—A state, the District of Columbia, a possession of the United States, or any of their political subdivisions or instrumentalities
- D.—A corporation the stock of which is regularly traded on one or more established securities markets, as described in Reg. section 1.1472-1 (c)(1)(i)
- E—A corporation that is a member of the same expanded affiliated group as a corporation described in Reg. section 1.1472-1(c)(1)(1)
- F—A dealer in securities, commodities, or derivative financial instruments (including notional principal contracts, futures, forwards, and options) that is registered as such under the laws of the United States or any state

- G-A real estate investment trust
- H—A regulated investment company as defined in section 861 or an entity registered at all times during the tax year under the investment Company Act of 1640
- I-A common trust fund as defined in section 584(a)
- J-A bank as defined in section 581
- K-A broker
- L-A trust exempt from tax under section 664 or described in section 4947(a)(1)
- M-A tax exempt trust under a section 403(b) plan or section 457(g) plan

Part I. Taxpaver Identification Number (TIN)

Enter your TIN in the appropriate box. If you are a resident alian and you do not have and are not eligible to get an SSN, your TIN is your IRS individual taxpayer identification number of TIN). Enter it in the social security number box. If you do not have an ITIN, see How to get a TIN below.

If you are a sole proprietor and you have an EIN, you may enter either your SSN or EIN. However, the IRS prefers that you use your SSN.

If you are a single-member LLC that is disregarded as an entity separate from its owner (see Limited Liability Company (LLC) on page 2), enter the owner's SSN for EIN, if the owner has one). Do not enter the disregarded entity's EIN. If the LLC is classified as a corporation or partnership, enter the entity's EIN.

Note. See the chart on page 4 for further clarification of name and TIN combinations.

How to get a TIN. If you do not have a TIN, apply for one immediately. To apply for an SSN, get Form SS-5, Application for a Social Security Card, from your local Social Security Administration office or get this form online at www.ssa.gov. You may also get this form by calling 1-800-772-1213. Use Form W-7, Application for IRS individual Taxpayer Identification Number, to apply for an ITIN, or Form SS-4, Application for Employer Identification Number, to apply for an ITIN, or Form SS-4, for an ITIN online by accessing the IRS wobsite at www.ins.gov/businesses and clicking on Employer Identification Number (EIN) under Starting a Business. You can get Form W-7 and SS-4 from the IRS by visiting IRS.gov or by calling 1-800-TAX-FORM (1-800-829-3676).

If you are asked to complete Form W-9 but do not have a TIN, apply for a TIN and write "Applied For" in the space for the TIN, sign and date the form, and give it to the requestor. For interest and dividend payments, and cortain payments made with respect to readily tradable instruments, generally you will have 60 days to get a TIN and give it to the requisator before you are subject to backup withholding on payments. The 60-day rule does not apply to other types of payments. You will be subject to backup withholding on all such payments until you provide your TIN to the requisition.

Note. Entering "Applied For" means that you have already applied for a TIN or that you intend to apply for one soon.

Caution: A disregarded U.S. entity that has a foreign owner must use the appropriate Form W-8.

Part II. Certification

To establish to the withholding agent that you are a U.S. person, or resident allen, sign Form W-2, You may be requested to sign by the withholding agent even if items 1, 4, or 5 below indicate otherwise.

For a joint account, only the person whose TIN is shown in Part I should sign (when required), in the case of a disregarded entity, the person identified on the "Name" line must sign. Exempt payees, see Exempt payee code earlier.

Signature requirements. Complete the certification as indicated in items 1 through 5 below.

- Interest, dividend, and barter exchange accounts opened before 1984 and broker accounts considered active during 1983. You must give your correct TIN, but you do not have to sign the certification.
- 2. Interest, dividend, broker, and barter exchange accounts opened after 1983 and broker accounts considered inactive during 1983. You must sign the certification or backup withholding will apply. If you are subject to backup withholding and you are marely providing your correct TIN to the requester, you must cross out item 2 in the certification before signing the form.
- Real estate transactions. You must sign the certification. You may cross out item 2 of the certification.
- 4. Other payments. You must give your correct TIN, but you do not have to sign the certification unless you have been notified that you have previously given an incorrect TIN. "Other payments" include payments made in the course of the requester's trade or business for rents, reyalties, goods (other than bills for merchandise), medical and health care services (including payments to corporations), payment to a nonemployee for services, payments made in settlement of payment card and third party network transactions, payments to certain fishing boat crew members and fishermen, and gross proceeds paid to attorneys (including payments to corporations).
- Mortgage interest paid by you, acquisition or abandonment of secured property, cancellation of debt, qualified tuition program payments (under section 529), IRA, Coverdell ESA, Archer MSA or HSA contributions or distributions, and pension distributions. You must give your correct TIN, but you do not have to sign the certification.

² However, the following payments made to a corporation and reportable on Form 1009-MISC are not exempt from backup withholding: medical and health care payments, attorneys' feet, gross proceeds paid to an attorney, and payments for services paid by a tederal executive agency.

Form W-9 (Flav. 8-2013) Page 4

What Name and Number To Give the Requester

For this type of account:	Give name and SSN of:
1. Individual	The Individual
 Two or more individuals (joint account) 	The actual owner of the account or, if combined funds, the first
	Individual on the account '
Custodian account of a minor (Uniform Gift to Minors Act)	The minor "
 a. The usual revocable savings trust (grantor is also trustee) 	The grantor-trustee '
 So-called trust account that is not a legal or valid trust under state law 	The actual owner *
 Sole proprietorship or disregarded entity owned by an individual 	The owner*
 Grantor trust filing under Optional Form 1000 Filing Method 1 (see Regulation section 1.671-4(b)(2)()(A)) 	The grantor*
For this type of account:	Give name and EIN of:
 Disregarded entity not owned by an individual 	The owner
8. A valid trust, estate, or pension trust	Logal entity *
 Corporation or LLC electing corporate status on Form 8832 or Form 2553 	The corporation
 Association, club, religious, charitable, educational, or other tax-exempt organization 	The organization
11. Partnership or multi-member LLC	The partnership
12. A broker or registered nominee	The broker or nominee
 Account with the Department of Agriculture in the name of a public entity (such as a state or local government, school district, or prison) that receives agricultural program payments 	The public entity
 Granfor trust filing under the Form 1041 Filing Method or the Optional Form 1099 Filing Method 2 (see Regulation section 1.671–4(b)(2)(f(8)) 	The trust

¹ List first and circle the name of the person whose number you furnish. If only one person on a joint account has an SSN, that person's number must be furnished.

Note. If no name is circled when more than one name is listed, the number will be considered to be that of the first name listed.

Secure Your Tax Records from Identity Theft

Identify theft occurs when someone uses your personal information such as your name, social security number (SSN), or other identifying information, without your permission, to commit fraud or other crimes. An identify their may use your SSN to get a job or may file a tax return using your SSN to receive a retund.

To reduce your risk:

- · Protect your SSN,
- . Ensure your employer is protecting your SSN, and
- . Be careful when choosing a tax preparer.

If your tax records are affected by identity theft and you receive a notice from the IRS, respond right away to the name and phone number printed on the IRS notice or lotter.

If your tax records are not currently affected by identity theft but you think you are at risk due to a lost or stoken purse or wallet, questionable credit card activity or credit report, centact the IRS identity Theft Hottine at 1-800-908-4490 or submit Form 14039.

For more information, see Publication 4535, Identity Theft Prevention and Victim Assistance.

Victims of identity theft who are experiencing economic harm or a system problem, or are seeking help in resolving tax problems that have not been resolved through normal channels, may be eligible for Taxpayer Advocate Service (TAS) assistance. You can reach TAS by calling the TAS toll-free case Intake line at 1-877-777-4778 or TTY/TDO 1-800-829-4059.

Protect yourself from suspicious emails or phishing schemes. Phishing is the creation and use of email and websites designed to mimic legitimate business emails and websites. The most common act is sending an email to a user falsely claiming to be an established legitimate enterprise in an attempt to scarm the user into surrendering private information that will be used for identify theft.

The IRS does not initiate contacts with texpayers via smalls. Also, the IRS does not request personal detailed information through small or ask texpayers for the PIN numbers, passwords, or similar secret access information for their credit card, bank, or other financial accounts.

If you receive an unsolicited email claiming to be from the IRS, forward this message to phishing@irs.gov. You may also report insuse of the IRS name, logo, or other IRS property to the Treasury inspector General for Tax Administration at 1-800-306-4484. You can forward suspicious emails to the Federal Trade Commission at spam@iuce.gov or contact them at www.flc.gov/kdtheft or 1-877-IDTHEFT (1-877-438-4338).

Visit IRS.gov to learn more about identity theft and how to reduce your risk.

Privacy Act Notice

Section 6109 of the Internal Revenue Code requires you to provide your correct TIN to persons (including federal agencies) who are required to file information returns with the IRS to report interest, dividends, or certain other income paid to your mortgage interest you paid; the acquisition or abandomment of secured property; the cancellation of debt; or contributions you made to an IRA, Archer MSA, or HSA. The person collecting this form uses the information on the form to file information in shurns with the IRS, reporting the above information. Pourtine uses of this information information in shurns with the IRS, or Columbia, and U.S. commonwealths and possessions for use in administering their laws. The information also may be disclosed to other countries under a treaty, to federal and state agencies to enforce civil and criminal laws, or to federal law enforcement and intelligence agencies to combat terrorism. You must provide your TIN whether or not you are required to file a tax return. Under section 3406, payers must generally withhold a percentage of taxable interest, dividend, and certain other payments to a payee who does not give a TIN to the payer. Certain penalties may also apply for providing take or fraudulent information.

² Circle the minor's name and furnish the minor's SSN.

⁵ You must show your individual name and you may also enter your business or "DBA" name on the "Business name/deragarded entity" name line. You may use either your SSN or EIN (if you have one), but the IRS encourages you to use your SSN.
⁶ List first and circle the name of the trust, estatio, or pension brust. (Do not furnish the TIN of the

^{*}List first and dicta the name of the trust, estate, or pension trust. (Do not furnish the TIN of the personal representative or trustee unless the logal entity itself is not designated in the account title.) Also see Special rules for partnerships on page 1.

[&]quot;Note. Crantor also must provide a Form W-e to trustee of trust

REQUIRED RESPONSE FORM - Proposer Information

RFQ Issued Date:	Title of Request or Solicita	ution:
	Note: For Joint Venture Proposals, see ins PROPOSER INFO	
PROPOSER'S (COMPANY) NA	ME:	
STREET ADDRESS:		
PROPOSER TELEPHONE:	PROPOSE	ER FAX:
CONTACT PERSON:		
		T FAX:
E-MAIL ADDRESS TO SEND P	URCHASE ORDERS TO:	
INTERNET E-MAIL ADDRESS:	INTE	RNET URL:
	TIFICATION NUMBER:	
I hereby certify that:	Proposal Cert	ification
 Proposer has not discussed, of the Proposer is attempting to qualify of silence" period for any solicita School Board Policy School Board Policy Proposer acknowledges that Records Laws. All responses, data and inform Proposer agrees to acceptant all issued Addenda. Proposer agrees to be boundattachments. 	eir lobbyists has not provided any campaign of the provide Design Services to the School Botton for a competitive procurement as described and a 3320, Part II, Section HH of 1007, Section 5.4 Campaign Contribution Fur all information contained herein is part of the nation contained in this Proposal are true and a ce of the contents of all pages in this Request and to all terms, conditions and requirement	contributions to School Board Members during the period in which the coard. This period of limitation shall commence at the time of the "cone ed by: Indicate the coard of the coard of the "cone ed by: Indicate the coard of the coard o
Signature of Proposer's Office	er (blue ink preferred on original)	Date
Name of Proposer's Officer		Title of Proposer's Officer.

<u>JOINT VENTURES:</u> In the event multiple Proposers submit a joint Proposal in response to the RFQ, a single Proposer shall be identified as the Prime Proposer. If offering a joint Proposal, Prime Proposer must include the name and address of all parties of the joint Proposal. Prime Proposer shall provide all bonding and insurance requirements, execute any Contract, complete the <u>REQUIRED RESPONSE FORM</u> shown herein, have overall and complete accountability to resolve any dispute arising within this contract. Only a single contract with one Proposer shall be acceptable. Prime Proposer responsibilities shall include, but not be limited to, performing of overall contract administration, preside over other Proposers participating or present at SBBC meetings, oversee preparation of reports and presentations, and file any notice of protest and final protest as described herein. Prime Proposer shall also prepare and present a consolidated invoice(s) for services performed. SBBC shall issue only one check for each consolidated invoice to the Prime Proposer for services performed. Prime Proposer shall remain responsible for performing services associated with response to this RFQ.

RFQ #:						
Scope of Available Se	ervices Form					
(Both of these columns can be yes)						
Scope of Services	In House Services		Consultant			
Architecture						
Civil Engineering						
Electrical Engineering						
Land Surveying						
Mechanical Engineering						
Structural Engineering						
Landscape Design						
Site Analysis and Planning						
Plumbing Design						
Other						

Firm:



The School Board of Broward County, Florida Procurement and Warehousing Department 7720 W. Oakland Park Blvd., Suite 323 Sunrise, Florida 33351

(754) 321-0505

D	Document 00220a: Proposer's Request for Information				
To:	Purchasing Agent Procurement and War 7720 W. Oakland Park Sunrise, Florida 3335	k Blvd., Suite 323	Date:		
	Sumise, Florida 5000	•	(For Owner's Use Only) Bidder's RFI No.:		
Proje	ect:	Project Nur Location Nu			
Facil	ity Name:	Project Con	oject Consultant:		
	Category: Information not shown or Interpretation of RFQ Doc Conflict in RFQ Requirem Coordination	cuments			
Desc	cription:				
Atta	chments:				
Bid	ler: npany Name & Address:	Ву:	Signature		
	Phone:		Title		

Attachment G - Project Scope of Work

Fairway Elementary School 7850 Fairway Boulevard Miramar FL 33023

Project Number: P-0016xx (TBD)

Project Description: Design & Renovation

RFQ Number: 16-182C

Prepared for: The School Board of Broward County

600 SE 3rd Ave Ft Lauderdale, FL 33301

Prepared by: **HEERY**

A group of professional service practices 999 Peachtree St, NE Atlanta, Georgia 30309

Contents

Attachment G - Project Scope of Work	1
1.0.0 Executive Summary	3
2.0.0 Fairway Elementary School	4
2.1.0 Project Scope of Work	4
2.2.0 Site Summary	€
2.3.0 FISH Documents	7
2.3.1 FISH Summary Report	7
2.3.2 FISH Inventory	10
2.3.3 FISH Site Plan	47
2.3.4 FISH Building Plan	48
2.4.0 Facility Assessments and Budgetary Documentation	49
2.4.1 Adopted District Educational Facilities Plan (DEFP)	50
2.4.2 SMART Campus Summary	51
2.4.3 MAPPS Deficiency Listing	53
2.4.4 MAPPS Deficiency Data	67
2.4.5 MAPPS Deficiency Detail	72

1.0.0 Executive Summary

On November 4, 2014, Broward County voters approved a General Obligation Bond (Bond) referendum that provides critically needed funding for Broward's students. Broward County Public Schools has committed to investing the funding to enhance students' learning environments by focusing on improvements in Safety, Music, Art, Athletics, Renovations and Technology (SMART).

To ensure equity among schools regarding Broward County Public Schools SMART initiative, a comprehensive Facility Needs Assessment was conducted Districtwide. The Needs Assessment provided an objective, data-driven overview of the District as a whole, as well as a strategic planning tool for prioritizing the most critical needs facing our schools for safety and security; repairs and renovations; and technology and technology infrastructure.

Based on the Facility Needs Assessment, Fairway Elementary School was found to require renovations to multiple facility components. The key objectives are 1) to thoroughly plan the work to allow normal school activities to continue without interruption with a focus on safety and completing work as soon as possible, and 2) to capitalize on 2017 Summer break to complete portions of scope when students are not on campus.

Included in this project scope of work is:

Fairway Elementary School

- Safety / Security Upgrade
- Fire Alarm
- Media Center Improvements
- HVAC Improvements
- Electrical Improvements
- Building Envelope Improvements

2.0.0 Fairway Elementary School

2.1.0 Project Scope of Work

The scope of work is broken down in accordance with the Approved District Educational Facility Plan SMART Program. The scope is presented as overall site deficiencies with specific trades called out when possible. Additionally, the scope of services specific to each campus building is itemized in section 2.4.0 facility assessment reports with specific trades called out when possible for reference purposes only. The Design Team is responsible for confirming all areas within the scope of work and necessary quantities and component sizes relevant to the campus renovations. The scope of work is limited to that which is being funded by the General Obligation Bond or agreed upon alternatives with the designated representatives of the school district.

The Design Team shall be responsible for the full design of a complete replacement Fire Alarm System for the entire campus, which shall meet all applicable codes and SREF design requirements. The fire detection and alarm system is viewed as a mission critical concern of the highest priority level. Additionally, the Design team shall be responsible for the design of renovations to the emergency exit signage and emergency lighting in multiple buildings throughout the campus. Refer to Section 2.4.0 for identified safety and security deficiencies.

The Design Team shall be responsible for the full design of Media Center improvements. The Designer shall work with the designated representatives of the school district to identify and perform remodeling of this space. These renovations may include but are not limited to typical design disciplines and may require specialty trades. Refer to Section 2.4.1 ADEFP for budgeted SMART program allocation. The Designer shall coordinate the overall ADEFP budget with individual Building replacements and Media Center renovation. See Section 2.3.3 and 2.3.4 for room designations, and 2.3.2 FISH Inventory for relevant Design Code for room coordination.

The facility condition assessment determined various envelope and building systems to require replacement. This scope includes, but is not limited to replacement and new electrical, HVAC, and building envelope improvements. The electrical system scope of service includes, but is not limited to, the replacement of pole lighting, mounted building lighting, and canopy lighting throughout the campus. The mechanical system scope of service includes, but is not limited to, the replacement of mechanical equipment in multiple buildings on the campus, replacement of the exhaust fan and registers in Building 1, test and balance of the HVAC system in multiple buildings, and replacement of the HVAC controls system in multiple buildings with a DDC controls system.

The scope includes, but is not limited to the reroofing of multiple campus buildings. The Design Team shall provide a full design of complete replacement of the existing roofing system with new decking requirements per County standards. Moreover, some existing roof areas will need to be raised to provide positive drainage and new minimum roof R-Values and may necessitate the need to raise existing equipment, utilities and other construction to accommodate new flashing heights.


Additionally, the scope includes the reroofing of aluminum covered walkways throughout the campus. Covered walkway replacement shall be coordinated with a designated representative of the school district per the facility condition assessment.

Prepared by: **HEERY**

In addition to the identified deficiencies found in section 2.4.0, the Design Team is responsible for working with the designated representatives of the school district to identify additional deficiencies related to the envelope, indoor air quality, lighting, and HVAC systems. The facility assessment reports stand as initial budgeted concerns, but does not serve as the limits of scope of work for the project renovation.

2.2.0 Site Summary

Fairway Elementary School is an existing school originally built in 1968 with expansions and renovations having taken place in 1991, 2001, 2004, and 2005. The campus currently encompasses eleven (11) buildings with an approximate square footage of 113,091 SF.



P-0016xx RFQ Number: 16-182C

2.3.0 FISH Documents

2.3.1 FISH Summary Report



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FLORIDA DEPARTMENT OF EDUCATION EDUCATIONAL FACILITIES AGENCY NSF/STUDENT STATIONS SUMMARY REPORT

ORGANIZATION: 6-BROWARD COUNTY SCHOOL DISTRICT

FACILITY: FAIRWAY ELEMENTARY

FACILITY USE: All STRUCTURE TYPE: All

CONDITION: 1-SATISFACTORY

GROUP BY: DISTRICT

District: 6 - BROWARD COUNTY SCHOOL DISTRICT

DESIGN CODE	ROOM DESIGN CODE	TOTAL ROOMS	NET SQ FT	STUDENT STATIONS
00001	PRIMARY CLASSROOM (K-3)	45	46,192	810
00002	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	5	6,296	110
00010	PRIMARY SKILLS LAB (K-3)	2	2,015	0
00013	ELEMENTARY P E STORAGE	2	663	0
00014	ELEMENTARY COVERED PLAY ARE A	1	627	0
00040	RESOURCE ROOM	1	530	0
00050	ART - ELEMENTARY	1	1,169	0
00055	MUSIC - ELEMENTARY	1	1,530	0
00061	E S E P ART-TIME	2	2,002	30
00062	E S E FULL-TIME	2	1,593	20
00065	E S E RESOURCE	1	595	0
00300	PRINCIPAL/DIRECTOR OFFICE	1	243	0
00301	ASSISTANT PRINCIPAL/OTHER OFFICE	7	1,251	0
00302	BOOKKEEPING OFFICE	1	135	0
00303	SECRETARIAL SPACE	1	660	0
00304	RECEPTION AREA	2	793	0
00305	PRODUCTION WORKROOM	1	382	0
00306	CONFERENCE ROOM	3	560	0
00307	CLINIC	1	187	0
00308	GENERAL SCHOOL STORAGE	6	688	0
00309	VAULT/STUDENT RECORDS	2	192	0
00312	COMPUTER AREA	1	135	0
00314	ITINERANT OFFICE	3	645	0
00315	TEACHER PLANNING OFFICE	3	468	0

PAGE:1 of3 Report Date: 9/4/2015 10:34:02 AM



FLORIDA DEPARTMENT OF EDUCATION EDUCATIONAL FACILITIES AGENCY NSF/STUDENT STATIONS SUMMARY REPORT

District: 6 - BROWARD COUNTY SCHOOL DISTRICT

DESIGN CODE	ROOM DESIGN CODE	TOTAL ROOMS	NET SQ FT	STUDENT STATIONS
00316	TEACHER LOUNGE/DINING	3	566	0
00331	CUSTODIAL SERVICE CLOSET	12	498	0
00333	FLAMMABLE STORAGE	2	523	0
00340	DINING AREA	1	3,600	0
00342	KITCHEN DRY STORAGE	1	190	0
00343	KITCHEN OFFICE	1	89	0
00344	KITCHEN GARBAGE WASH	2	117	0
00345	KITCHEN NONFOOD STORAGE	1	88	0
00346	KITCHEN FOOD PREPARATION	1	1,602	0
00350	OTHER FOOD SERVICE	3	220	0
00361	MULTIPURPOSE ROOM (DINING)	1	1,896	0
00363	STAGE	1	805	0
00364	STAGE STORAGE	3	859	0
00365	STAGE DRESSING ROOM (MALE)	1	250	0
00366	STAGE DRESSING ROOM (FEMALE)	1	250	0
00368	TEXTBOOK STORAGE	1	92	0
00380	LIBRARY (READING ROOM/STACKS)	1	2,331	0
00383	AUDIO VISUAL STORAGE	1	540	0
00385	CLOSED CIRCUIT TV LAB	1	600	0
00386	CLOSED CIRCUIT STORAGE	1	400	0
00387	MEDIA PRODUCTION LAB	1	1,630	0
00700	INSIDE CIRCULATION	20	12,232	0
00701	COVERED WALKWAY	19	18,970	0
00702	MECHANICAL ROOM	19	2,858	0
00703	ELECTRICAL ROOM	9	843	0
00707	TELEPHONE EQUIPMENT/COMMUNICATION CLOSET	2	156	0
00805	KILN	1	65	0
00806	REFERENCE	1	153	0
00808	MATERIAL STORAGE	6	680	0
00811	OUTSIDE STORAGE	5	263	0
00814	STUDENT RESTROOM (BOTH SEXES)	52	2,259	0

PAGE:2 of3 Report Date: 9/4/2015 10:34:02 AM



FLORIDA DEPARTMENT OF EDUCATION EDUCATIONAL FACILITIES AGENCY NSF/STUDENT STATIONS SUMMARY REPORT

District: 6 - BROWARD COUNTY SCHOOL DISTRICT

		ROOMS		STUDENT STATIONS
00815	STUDENT RESTROOM (MALE)	5	294	0
00816	STUDENT RESTROOM (FEMALE)	5	368	0
00819	STAFF RESTROOM (MALE)	3	283	0
00820	STAFF RESTROOM (FEMALE)	3	271	0
00821	STAFF RESTROOM (BOTH SEXES)	4	168	0
00822	PUBLIC USE RESTROOM (MALE)	1	34	0
00823	PUBLIC USE RESTROOM (FEMALE)	1	34	0
00831	MUSIC PRACTICE ROOM	1	50	0
	TOTALS:	292	126,678	970

TOTA	S FOR SELECTED DISTRICTS :	292	126,678	970
------	----------------------------	-----	---------	-----

PAGE:3 of3 Report Date: 9/4/2015 10:34:02 AM

2.3.2 FISH Inventory

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

ORGANIZATION: 6-BROWARD COUNTY SCHOOL DISTRICT FAIRWAY ELEMENTARY FACILITY:

₹ FACILITY USE: DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 108-A FAIRWAY ELEMENTARY

Grades Housed: PK - 05 Primary Use: ELEMENTARY

DOE Validation Date:

Capital Outlay Classification: SCHOOL RECOMMENDED FOR CONTINUED USE

MASTER SCHOOLID

Status Default FAIRWAY ELEMENTARY SCHOOL Name MSID 1641

CAPITAL OUTLAY FTE

00:0:60 10: 0.00 00'0 :20 08: 0.00 05: 116.00 06: 0.00 03: 124.00 04: 96.00 01: 124.69 02: 111.00 Year: 2014 / 2015 KG: 101.50 PK: 36.56

PK-12: 709.75

11: 0.00 12: 0.00

Total: 709.75 Adult: 0.00

SCHOOL CAPACITY

PRIMARY USE	ELEMENTARY	
UTILIZATION FACTOR	1.00	
YEAR ROUND CAPACITY	1,164	
SCHOOL CAPACITY	026	

Report Date: 9/4/2015 10:32:57 AM

FACILITY INVENTORY REPORT

PARCEL: 109
₹
ت ا
ខ្ល

7850 FAIRWAY BOULEVARD

MIRAMAR, FL 33023

Parking: DEVELOPED	Owner: SCHOOL BOARD	Fire: 8
Athletic NO ATHLETIC FACILITY	Water PUBLIC	Police: COMBINATION
Sewage: PUBLIC	Plan: COMP.ACT	Drainage: ADEQUATE
Landscape: DEVELOPED	Playground: INCLUDED WITH SITE	Асевде: 11.00
Date Acquired 1MM966		Lease Expiration Date:

DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 108-A FAIRWAY ELEMENTARY

BUILDING: 1 - Building Number 00001

	,		
Owner, SCHOOL BOARD	BO ARD	Light: ADEQUATE	Cooling: CENTRAL
YAA.TUEMENTARY	۲۸	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1968	1968	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:		Educational TV: FIXED SERVICE TRANSMITTER/RECEIVER	Heat Capacity. ADEQUATE
Average Age NSF: 1968	: 1968	Intercom: TWO WAY P ARTIAL	Walls STUCCO
Retocatable Units: 0	0.	Telephone: P.ARTIAL SYSTEM	Struct Comp. COMBINATION OF 1-3
Stories: 1			Corridor. DOUBLE INSIDE

-	NET SQ FT	ROOM NET SQ DE SIGN FT CODE	DESCRIPTION	STU	FR	FLOOR COVER	YEAR CONST	соивілои	BLDG	PAR	FAC
536		200	INSIDE CIRCULATION		Б	COMPOSITION TILE	1968	SATISFACTORY	-	109	108
349		200	INSIDE CIRCULATION		Б	COMPOSITION TILE	1968	SATISFACTORY	-	109	108
₽ 0	4307	200	INSIDE CIRCULATION	0	М	COMPOSITION TILE	1968	SATISFACTORY	-	109	108

Page 2 of 30

Report Date: 9/4/2015 10:32:57 AM

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

100	432	704	COVERED WALKWAY	0	М	CONCRETE	1968	SATISFACTORY	-	109	108
101	340	304	RECEPTION AREA		Б	CARPET	1968	SATISFACTORY	-	109	108
101A	82	308	GENERAL SCHOOL STORAGE		Б	CARPET	1968	SATISFACTORY	-	109	108
102	130	314	ITINER.ANT OFFICE		Б	CARPET	1968	SATISFACTORY	-	109	108
103	115	309	VAULT/STUDENT RECORDS		Б	CARPET	1968	SATISFACTORY	-	109	108
104	185	306	CONFERENCE ROOM		Б	CARPET	1968	SATISFACTORY	-	109	108
105	27	308	GENERAL SCHOOL STORAGE	0	Б	CERAMIC TILE	1968	SATISFACTORY	-	109	108
901	189	301	ASSISTANT PRINCIPAL/OTHER OFFICE		Б	CARPET	1968	SATISFACTORY	-	109	108
107	189	301	ASSISTANT PRINCIPAL/OTHER OFFICE		Б	CARPET	1968	SATISFACTORY	-	109	108
108	871	-	PRIMARY CLASSROOM (K-3)	18	Б	CARPET	1968	SATISFACTORY	-	109	108
108A	78	814	STUDENT RESTROOM (BOTH SEXES)		Б	CERAMIC TILE	1968	SATISFACTORY	-	109	108
109	635	62	E S E FULL-TIME	10	Б	CARPET	1968	SATISFACTORY	-	109	108
110	936	9	ESEPART-TIME	15	Б	CARPET	1968	SATISFACTORY	-	109	108
110A	33	814	STUDENT RESTROOM (BOTH SEXES)		Б	CERAMIC TILE	1968	SATISFACTORY	-	109	108
111	595	99	E S E RESOURCE		Б	CARPET	1968	SATISFACTORY	-	109	108
111A	78	814	STUDENT RESTROOM (BOTH SEXES)		Б	CERAMIC TILE	1968	SATISFACTORY	-	109	108
112	230	40	RESOURCE ROOM	o	Б	CARPET	1968	SATISFACTORY	-	109	108
112A	78	814	STUDENT RESTROOM (BOTH SEXES)		Б	CERAMIC TILE	1968	SATISFACTORY	-	109	108
112B	82	200	INSIDE CIRCULATION		Б	COMPOSITION TILE	1968	SATISFACTORY	-	109	108
113	1169	99	ART - ELEMENTARY		Б	COMPOSITION TILE	1968	SATISFACTORY	-	109	108
114	92	805	KILN		Б	COMPOSITION TILE	1968	SATISFACTORY	-	109	108
115	265	315	TE ACHER PLANNING OFFICE	0	10	COMPOSITION TILE	1968	SATISFACTORY	-	109	108
116	156	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1968	SATISFACTORY	1	109	108
117	240	314	ITINERANT OFFICE	0	Ю	CARPET	1968	SATISFACTORY	-	109	108



108 108 108

Report Date: 9/4/2015 10:32:57 AM

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

109 9 109 8 SATISFACTORY SATISFACTORY SATISFACTORY SATISFACTORY SATISFACTORY 1968 1968 1968 CONCRETE CONCRETE CONCRETE CARPET CARPET δ Б δ Б δ CUSTODIAL SERVICE CLOSET TEXTBOOK STORAGE MECHANICAL ROOM MECHANICAL ROOM ELECTRICAL ROOM 702 388 702 331 22 8 Б 9 13 123 2 7

122 7	75 75	702 1 702 1 Sadi	MECHANICAL ROOM MECHANICAL ROOM Satisfactory	0 0 Unsatisfactory	0 0 iactory	<u>δ</u> <u>δ</u>	CONCRETE 1966 CONCRETE 1966 Failed Standards	1968 1968 ndards	1968 SATISFACTORY 1968 SATISFACTORY ands	ORY 1 109 ORY 1 109 Scheduled For Replacement	For Rep	109 109	108
	Squi	Square Feet	Student Stations	Square Feet	Student Stations	ations	Square Feet	Student Stations	ations	Square Feet	- T	Student Stations	Suo
Permanent		13,011	43	0		0							
TOTAL		13,011	43	0		0	0		0		0		0





FACILITY INVENTORY REPORT

DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 108-A FAIRWAY ELEMENTARY

BUILDING: 2 - Building Number 00002

Owner. SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: ELEMENTARY	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1968	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational TV: FIXED SERVICE TRANSMITTER/RECEIVER	Heat Capacity. ADEQUATE
Average Age NSF: 1968	Intercom: TWO WAY P ARTIAL	Wall≲ STUCCO
Relocatable Units: 0	Telephone: P.ARTIAL SYSTEM	Struct Comp. COMBINATION OF 1-3
Stories: 1		Corridor. DOUBLE INSIDE

ROOM	ROOM NET SQ FT	DE SIGN CODE	DESCRIPTION	STU STA	FF. Coc	FLOOR COVER	YEAR	СОИВІЛОИ	эспа	PAR	FAC
9004	872	200	INSIDE CIRCULATION	0	Б	COMPOSITION TILE	1968	SATISFACTORY	2	109	108
200	1795	701	COVERED WALKWAY	0	Б	CONCRETE	1968	SATISFACTORY	2	109	108
201	1066	61	ESEPART-TIME	15	Б	CARPET	1968	SATISFACTORY	2	109	108
201A	æ	814	STUDENT RESTROOM (BOTH SEXES)	0	Б	CERAMIC TILE	1968	SATISFACTORY	2	109	108
202	1148	-	PRIMARY CLASSROOM (K-3)	18	Б	CARPET	1968	SATISFACTORY	2	109	108
202A	æ	814	STUDENT RESTROOM (BOTH SEXES)	0	Б	CERAMIC TILE	1968	SATISFACTORY	2	109	108
203	1116	-	PRIMARY CLASSROOM (K-3)	18	Б	CARPET	1968	SATISFACTORY	2	109	108
203A	28	814	STUDENT RESTROOM (BOTH SEXES)	0	Б	CERAMIC TILE	1968	SATISFACTORY	2	109	108
204	1116	-	PRIMARY CLASSROOM (K-3)	18	Б	CARPET	1968	SATISFACTORY	2	109	108
204A	28	814	STUDENT RESTROOM (BOTH SEXES)	0	Б	CERAMIC TILE	1968	SATISFACTORY	2	109	108
205	1116	1	PRIMARY CLASSROOM (K-3)	18	Б	CARPET	1968	SATISFACTORY	2	109	108
205A	28	814	STUDENT RESTROOM (BOTH SEXES)	0	Б	CERAMIC TILE	1968	SATISFACTORY	2	109	108

Report Date: 9/4/2015 10:32:57 AM



FACILITY INVENTORY REPORT

DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 108-A FAIRWAY ELEMENTARY BUILDING: 2 - Building Number 00002

Owner: SCHOOL BO ARD	Light: ADEQUATE	Cooling: CENTR.AL
USE: ELEMENTARY	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1968	Artificial Lighting: SHELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational TV: FIXED SERVICE TRANSMITTER/RECEIVER	Heat Capacity. ADEQUATE
Average Age NSF: 1968	Intercom: TWIO WAY P ARTIAL	Wall≲ STUCCO
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp.: COMBINATION OF 1-3
Stories: 1		Comidor. DOUBLE INSIDE

ROOM	ROOM NET SQ FT	DE SIGN CODE	DESCRIPTION	STU	FLR	FLOOR COVER	YEAR CONST	соиршом	вше	PAR	FAC
900	872	200	INSIDE CIRCULATION	0	01	COMPOSITION TILE	1968	SATISFACTORY	2	109	108
200	1795	701	COVERED WALKWAY		М	CONCRETE	1968	SATISFACTORY	2	109	108
201	1066	64	E S E PART-TIME	15	М	CARPET	1968	SATISFACTORY	2	109	108
201A	æ	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1968	SATISFACTORY	2	109	108
202	1148	-	PRIMARY CLASSROOM (K-3)	18	М	CARPET	1968	SATISFACTORY	2	109	108
202A	88	814	STUDENT RESTROOM (BOTH SEXES)		01	CERAMIC TILE	1968	SATISFACTORY	2	109	108
203	1116	-	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1968	SATISFACTORY	2	109	108
203A	78	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1968	SATISFACTORY	2	109	108
204	1116	-	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1968	SATISFACTORY	2	109	108
204A	28	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1968	SATISFACTORY	2	109	108
205	1116	-	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1968	SATISFACTORY	2	109	108
205A	28	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1968	SATISFACTORY	2	109	108

Report Date: 9/4/2015 10:32:57 AM



Student Stations

Square Feet

Student Stations

Square Feet

Student Stations

Square Feet

Student Stations

Square Feet

Satisfactory

Unsatisfactory

0 0

0 0

169 169

14,358 14,358

Permanent TOTAL

Failed Standards

Scheduled For Replacement

Report Date: 9/4/2015 10:32:57 AM

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

8 8 8 108 8 8 8 8 8 8 8 8 8 109 8 8 8 8 8 8 8 8 8 8 89 8 Ø 2 SATISFACTORY 1968 1968 1968 1968 1968 198 1968 1968 1988 1968 1968 1968 88 1968 1 COMPOSITION TILE COMPOSITION CERAMIC TILE CERAMIC TILE CERAMIC TILE CONCRETE CONCRETE CARPET CARPET CARPET CARPET CARPET CARPET CARPET δ 5 δ δ δ δ Б δ δ δ δ δ φ φ ∞ 9 9 0 0 STUDENT RESTROOM (BOTH SEXES) STUDENT RESTROOM (BOTH SEXES) STUDENT RESTROOM (BOTH SEXES) GENERAL SCHOOL STORAGE CUSTODIAL SERVICE CLOSET PRIMARY CLASSROOM (K-3) PRIMARY CLASSROOM (K-3) PRIMARY CLASSROOM (K-3) PRIMARY CLASSROOM (K-3) MATERIAL STORAGE MATERIAL STORAGE MECHANICAL ROOM ELECTRICAL ROOM E S E FULL-TIME 808 8 702 703 <u>8</u> 8 뛵 8 1118 1118 928 88 242 120 5 8 ဓ္တ æ 8 2 27 210A 208B 206A 208A 209A 80 210 212 8 8





Student Stations

Square Feet

Student Stations

Square Feet

Student Stations

Square Feet

Student Stations

Square Feet

Satisfactory

0

<u>8</u> 8

14,358 14,358

Permanent TOTAL

Unsatisfactory

Failed Standards

Scheduled For Replacement

Report Date: 9/4/2015 10:32:57 AM

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

206A 28 814 STUDENT RESTROOM (#G) 0 CERAMIC TILE 1968 SATISFACTORY 2 109 106 207 1118 1 PRIMARY CLASSROOM (#G) 18 01 CARPET 1968 SATISFACTORY 2 109 106 207A 36 814 STUDENT RESTROOM (#G) 18 01 CERAMIC TILE 1968 SATISFACTORY 2 109 106 208A 36 814 STUDENT RESTROOM (#G) 16 0 0 CERAMIC TILE 1968 SATISFACTORY 2 109 106 208A 36 814 STUDENT RESTROOM (#G) 0 0 CERAMIC TILE 1968 SATISFACTORY 2 109 106 208B 82 82 ES FULL-TIME 0 0 CARPET 1968 SATISFACTORY 2 109 106 209B 70 308 GENERAL SCHOOL STORAGE 0 0 CARPET 1968 SATISFACTORY 2	206	1116	-	PRIMARY CLASSROOM (K-3)	18	М	CARPET	1968	SATISFACTORY	2	109	108
1118 1 PRIMARY CLASSROOM (K-3) 18 01 CARPET 1968 SATISFACTORY 2 109 36 814 STUDENT RESTROOM (BOTH SEXES) 0 01 CERAMIC TILE 1968 SATISFACTORY 2 109 36 814 STUDENT RESTROOM (BOTH SEXES) 0 01 CERAMIC TILE 1968 SATISFACTORY 2 109 366 82 814 STUDENT RESTROOM (R-3) 0 01 CARPET 1968 SATISFACTORY 2 109 90 808 MATERIAL STORAGE 0 01 COMPOSITION TILE 1968 SATISFACTORY 2 109 70 308 GENERAL SCHOOL STORAGE 0 01 CARPET 1968 SATISFACTORY 2 109 833 1 PRIMARY CLASSROOM (K-3) 18 0 01 COMPOSITION TILE 1968 SATISFACTORY 2 109 242 702 MECHANICAL ROOM 0 01 CONCRETE 1968	206A	28	814		0	Б		1968	SATISFACTORY	2	109	108
36 914 STUDENT RESTROOM (BOTH SEXES) 0 OT CERAMIC TILE 1968 SATISFACTORY 2 109 1118 1 PRIMARY CLASSROOM (K-3) 18 01 CARPET 1968 SATISFACTORY 2 109 368 62 E S F F LLL-TIME 10 01 CARPET 1968 SATISFACTORY 2 109 90 808 MATERIAL STORAGE 0 01 CARPET 1968 SATISFACTORY 2 109 70 308 MATERIAL STORAGE 0 01 CARPET 1968 SATISFACTORY 2 109 893 1 PRIMARY CLASSROOM (K-3) 18 01 CARPET 1968 SATISFACTORY 2 109 121 808 MECHANICAL ROOM 0 01 CONCRETE 1968 SATISFACTORY 2 109 242 702 MECHANICAL ROOM 0 0 CONCRETE 1968 SATISFACTORY 2 109	207	1118	-	OOM (K-3)	18	Б		1968	SATISFACTORY	2	109	108
1118 1 PRIMARY CLASSROOM (4.3) 18 01 CARPET 1968 SATISFACTORY 2 109 36 814 STUDENT RESTROOM (BOTH SEXES) 0 01 CERAMIC TILE 1968 SATISFACTORY 2 109 968 62 E S E FULL-TIME 0 01 CARPET 1968 SATISFACTORY 2 109 70 308 GENERAL STORAGE 0 01 CARPET 1968 SATISFACTORY 2 109 833 1 PRIMARY CLASSROOM (4.3) 18 01 CARPET 1968 SATISFACTORY 2 109 121 808 MATERIAL STORAGE 0 01 CONCRETE 1968 SATISFACTORY 2 109 242 702 MECHANICAL ROOM 0 01 CONCRETE 1968 SATISFACTORY 2 109 27 331 CUSTODIAL SERVICE CLOSET 0 01 CONCRETE 1968 SATISFACTORY 2 109 <	207A	98	814	STUDENT RESTROOM (BOTH SEXES)	0	Б		1968	SATISFACTORY	2	109	108
36 814 STUDENT RESTROOM (BOTH SEXES) 0 0T CERAMIC TILE 168 SATISFACTORY 2 108 958 62 E S E FULL-TIME 10 0T CARPET 1968 SATISFACTORY 2 108 90 808 MATERIAL STORAGE 0 0T COMPOSITION TILE 1968 SATISFACTORY 2 109 893 1 PRIMARY CLASSROOM (K-3) 18 0T CARPET 1968 SATISFACTORY 2 109 121 808 MATERIAL STORAGE 0 0T CARPET 1968 SATISFACTORY 2 109 242 702 MECHANICAL ROOM 0 0T CONCRETE 1968 SATISFACTORY 2 109 27 331 CUSTODIAL SERVICE CLOSET 0 0T CONCRETE 1968 SATISFACTORY 2 109 120 703 ELECTRICAL ROOM 0 0T CONCRETE 1968 SATISFACTORY 2 109 </td <td>208</td> <td>1118</td> <td>-</td> <td>OOM (K-3)</td> <td>18</td> <td>Б</td> <td></td> <td>1968</td> <td>SATISFACTORY</td> <td>2</td> <td>109</td> <td>108</td>	208	1118	-	OOM (K-3)	18	Б		1968	SATISFACTORY	2	109	108
958 62 E SE FULL-TIME 10 01 CARPET 1968 SATISFACTORY 2 109 90 808 MATERIAL STORAGE 0 01 COMPOSITION TILE 1968 SATISFACTORY 2 109 893 1 PRIMARY CLASSROOM (K-3) 18 01 CARPET 1968 SATISFACTORY 2 109 121 808 MATERIAL STORAGE 0 01 CARPET 1968 SATISFACTORY 2 109 242 702 MECHANICAL ROOM 0 01 CONCRETE 1968 SATISFACTORY 2 109 27 331 CUSTODIAL SERVICE CLOSET 0 01 CONCRETE 1968 SATISFACTORY 2 109 120 73 CUSTODIAL SERVICE CLOSET 0 01 CONCRETE 1968 SATISFACTORY 2 109 120 73 CUSTODIAL SERVICE CLOSET 0 01 CONCRETE 1968 SATISFACTORY 2 109 <td>208A</td> <td>98</td> <td>814</td> <td></td> <td>0</td> <td>Б</td> <td></td> <td>1968</td> <td>SATISFACTORY</td> <td>2</td> <td>109</td> <td>108</td>	208A	98	814		0	Б		1968	SATISFACTORY	2	109	108
90 808 MATERIAL STORAGE 0 01 COMPOSITION TILE 1968 SATISFACTORY 2 109 70 308 GENERAL SCHOOL STORAGE 0 01 CARPET 1968 SATISFACTORY 2 109 121 808 MATERIAL STORAGE 0 01 CARPET 1968 SATISFACTORY 2 109 242 702 MECHANICAL ROOM 0 01 CONCRETE 1968 SATISFACTORY 2 109 27 331 CUSTODIAL SERVICE CLOSET 0 0 CONPOSITION TILE 1968 SATISFACTORY 2 109 120 703 ELECTRICAL ROOM 0 0 CONCRETE 1968 SATISFACTORY 2 109	209	928	62	S E FULL-TIME	10	Б		1968	SATISFACTORY	2	109	108
70 308 GENERAL SCHOOL STORAGE 0 01 CARPET 1968 SATISFACTORY 2 109 893 1 PRIMARY CLASSROOM (K-3) 18 01 CARPET 1968 SATISFACTORY 2 109 121 808 MATERIAL STORAGE 0 01 CARPET 1968 SATISFACTORY 2 109 242 702 MECHANICAL ROOM 0 01 CONCRETE 1968 SATISFACTORY 2 109 27 331 CUSTODIAL SERVICE CLOSET 0 01 CONCRETE 1968 SATISFACTORY 2 109 120 733 ELECTRICAL ROOM 0 01 CONCRETE 1968 SATISFACTORY 2 109	209A	8	808	MATERIAL STORAGE	0	Б		1968	SATISFACTORY	2	109	108
893 1 PRIMARY CLASSROOM (K-3) 18 01 CARPET 1968 SATISFACTORY 2 109 121 808 MATERIAL STORAGE 0 01 CARPET 1968 SATISFACTORY 2 109 27 331 CUSTODIAL SERVICE CLOSET 0 01 CONPOSITION TILE 1968 SATISFACTORY 2 109 120 703 ELECTRICAL ROOM 0 0 CONCRETE 1968 SATISFACTORY 2 109	209B	22	308	1 .	0	Б		1968	SATISFACTORY	2	109	108
121 808 MATERIAL STORAGE 0 01 CARPET 1968 SATISFACTORY 2 109 242 702 MECHANICAL ROOM 0 0 CONCRETE 1968 SATISFACTORY 2 109 27 331 CUSTODIAL SERVICE CLOSET 0 01 CONCRETE 1968 SATISFACTORY 2 109 120 703 TORAGE 0 0 CONCRETE 1968 SATISFACTORY 2 109	210	883	-	OOM (K-3)	18	Б		1968	SATISFACTORY	2	109	108
242 702 MECHANICAL ROOM 0 01 CONCRETE 1968 SATISFACTORY 2 109 27 331 CUSTODIAL SERWCE CLOSET 0 01 COMPOSITION TILE 1968 SATISFACTORY 2 109 120 703 ELECTRICAL ROOM 0 01 CONCRETE 1968 SATISFACTORY 2 109	210A	121	808	MATERIAL STORAGE	0	Б		1968	SATISFACTORY	2	109	108
27 331 CUSTODIAL SERVICE CLOSET 0 01 COMPOSITION TILE 1968 SATISFACTORY 2 109 120 703 ELECTRICAL ROOM 0 01 CONCRETE 1968 SATISFACTORY 2 109	211	242	702	MECHANICAL ROOM	0	Б		1968	SATISFACTORY	2	109	108
120 703 ELECTRICAL ROOM 0 01 CONCRETE 1968 SATISFACTORY 2 109	212	27	331	CUSTODIAL SERVICE CLOSET	0	Б		1968	SATISFACTORY	2	109	108
	213	120	703	ELECTRICAL ROOM	0	Б		1968	SATISFACTORY	2	109	108

CREAT SE



FACILITY INVENTORY REPORT

DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 108-A FAIRWAY ELEMENTARY

BUILDING: 3 - Building Number 00003

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: ELEMENTARY	Mech Vent: ADEQUATE	HeatSource: ELECTRIC
Year Constructed: 1968	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational TV: FIXED SERVICE TRANSMITTER/RECEIVER	Heat Capacity. ADEQUATE
Average Age NSF: 1968	Intercom: TWO WAY P ARTIAL	Walls STUCCO
Relocatable Units: 0	Telephone: P.ARTI.AL SYSTEM	Struct Comp. COMBINATION OF 1-3
Stories: 1		Corridor. DOUBLE INSIDE

ROOM	ROOM NET SQ FT	DESIGN	DESCRIPTION	STU	FLR	FLOOR COVER	YEAR CONST	СОИВІЛОИ	вше	PAR	FAC
900	872	200	INSIDE CIRCULATION	0	ы	COMPOSITION TILE	1968	SATISFACTORY	6	109	108
300	1200	701	COVERED WALKWAY	0	М	CONCRETE	1968	SATISFACTORY	С	109	108
300A	9	701	COVERED WALKWAY	0	ы	CONCRETE	1968	SATISFACTORY	С	109	108
301	1256	-	PRIMARY CLASSROOM (K-3)	18	ы	CARPET	1968	SATISFACTORY	е	109	108
301A	34	814	STUDENT RESTROOM (BOTH SEXES)	0	ы	CERAMIC TILE	1968	SATISFACTORY	6	109	108
301B	82	200	INSIDE CIRCULATION	0	ы	CARPET	1968	SATISFACTORY	9	109	108
302	1256	-	PRIMARY CLASSROOM (K-3)	18	ы	CARPET	1968	SATISFACTORY	9	109	108
302A	34	814	STUDENT RESTROOM (BOTH SEXES)	0	ы	CERAMIC TILE	1968	SATISFACTORY	6	109	108
303	275	314	ITINER ANT OFFICE	0	ы	CARPET	1968	SATISFACTORY	6	109	108
304	1235	-	PRIMARY CLASSROOM (K-3)	18	ы	CARPET	1968	SATISFACTORY	е	109	108
304A	34	815	STUDENT RESTROOM (MALE)	0	М	CERAMIC TILE	1968	SATISFACTORY	е	109	108
304B	34	816	STUDENT RESTROOM (FEMALE)	0	М	CERAMIC TILE	1968	SATISFACTORY	9	109	108

Report Date: 9/4/2015 10:32:57 AM

Page 7 of 30



FACILITY INVENTORY REPORT

DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 108-A FAIRWAY ELEMENTARY

BIIII DING: 3 - Building Number

DULLDING: 3 - Building Multiper 00003		
Owner. SCHOOL BO ARD	Light: ADEQUATE	Cooling: CENTRAL
Use: ELEMENTARY	Mech Vent: ADEQUATE	HeatSource: ELECTRIC
Year Constructed: 1968	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational TV: FIXED SERVICE TRANSMITTER/RECEIVER	Heat Capacity. ADEQUATE
Average Age NSF: 1968	Intercom: TWO W/AY P ARTIAL	Walls STUCCO
Relocatable Units: 0	Telephone: P.ARTI.AL SYSTEM	Struct Comp. COMBINATION OF 1-3
Stories: 1		Corridor. DOUBLE INSIDE

ROOM	ROOM NET SQ FT	DE SIGN CODE	DESCRIPTION	STU	FR	FLOOR COVER	YEAR CONST	соивілом	вше	PAR	FAC
900	872	200	INSIDE CIRCULATION	0	Б	COMPOSITION TILE	1968	SATISFACTORY	n	109	108
300	1200	701	COVERED WALKWAY	0	Б	CONCRETE	1968	SATISFACTORY	m	109	108
300A	100	701	COVERED WALKWAY		Б	CONCRETE	1968	SATISFACTORY	m	109	108
301	1256	-	PRIMARY CLASSROOM (K-3)	18	Б	CARPET	1968	SATISFACTORY	ო	109	108
301A	34	814	STUDENT RESTROOM (BOTH SEXES)	0	Б	CERAMIC TILE	1968	SATISFACTORY	m	109	108
301B	82	200	INSIDE CIRCULATION		Б	CARPET	1968	SATISFACTORY	m	109	108
302	1256	-	PRIMARY CLASSROOM (K-3)	18	Б	CARPET	1968	SATISFACTORY	m	109	108
302A	34	814	STUDENT RESTROOM (BOTH SEXES)	0	Б	CERAMIC TILE	1968	SATISFACTORY	ო	109	108
303	275	314	ITINER ANT OFFICE		Б	CARPET	1968	SATISFACTORY	ო	109	108
304	1235	-	PRIMARY CLASSROOM (K-3)	18	Б	CARPET	1968	SATISFACTORY	ო	109	108
304A	34	815	STUDENT RESTROOM (MALE)	0	М	CERAMIC TILE	1968	SATISFACTORY	n	109	108
304B	34	816	STUDENT RESTROOM (FEMALE)	0	01	CERAMIC TILE	1968	SATISFACTORY	က	109	108

Report Date: 9/4/2015 10:32:57 AM

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

305	1258	2	INTERMEDIATE.MIDDLE CLASSROOM (4-8)	22	М	CARPET	1968	SATISFACTORY	က	109	108
305A	34	815	STUDENT RESTROOM (MALE)		Б	CERAMIC TILE	1968	SATISFACTORY	m	109	108
305B	34	816	STUDENT RESTROOM (FEMALE)	0	Б	CERAMIC TILE	1968	SATISFACTORY	m	109	108
306	1262	2	INTERMEDIATE MIDDLE CLASSROOM (4-8)	22	Б	CARPET	1968	SATISFACTORY	ю	109	108
306A	78	814	STUDENT RESTROOM (BOTH SEXES)		Б	CERAMIC TILE	1968	SATISFACTORY	т	109	108
306B	82	200	INSIDE CIRCULATION	0	Б	CARPET	1968	SATISFACTORY	m	109	108
307	1259	2	INTERMEDIATE MIDDLE CLASSROOM (4-8)	22	Б	CARPET	1968	SATISFACTORY	М	109	108
307A	78	814	STUDENT RESTROOM (BOTH SEXES)	0	Б	CERAMIC TILE	1968	SATISFACTORY	т	109	108
307B	82	200	INSIDE CIRCULATION	0	Б	CARPET	1968	SATISFACTORY	т	109	108
308	1258	2	INTERMEDIATEMIDDLE CLASSROOM (4-8)	22	Б	CARPET	1968	SATISFACTORY	n	109	108
308A	78	814	STUDENT RESTROOM (BOTH SEXES)	0	Б	CERAMIC TILE	1968	SATISFACTORY	т	109	108
309	1259	2	INTERMEDIATE MIDDLE CLASSROOM (4-8)	22	Б	CARPET	1968	SATISFACTORY	т	109	108
309A	78	814	STUDENT RESTROOM (BOTH SEXES)	0	Б	CERAMIC TILE	1968	SATISFACTORY	m	109	108
310	955	10	PRIMARY SKILLS LAB (K-3)	0	Б	CARPET	1968	SATISFACTORY	m	109	108
310A	105	808	MATERIAL STORAGE		Б	CARPET	1968	SATISFACTORY	т	109	108
311	1060	10	PRIMARY SKILLS LAB (K-3)		Б	CARPET	1968	SATISFACTORY	ю	109	108
312	26	331	CUSTODIAL SERVICE CLOSET		Б	COMPOSITION TILE	1968	SATISFACTORY	т	109	108
313	215	816	STUDENT RESTROOM (FEMALE)	0	Б	CERAMIC TILE	1968	SATISFACTORY	т	109	108
314	160	815	STUDENT RESTROOM (MALE)	0	Б	CERAMIC TILE	1968	SATISFACTORY	m	109	108
315	288	702	MECHANICAL ROOM	0	Б	CONCRETE	1968	SATISFACTORY	m	109	108
316	27	331	CUSTODIAL SERMCE CLOSET	0	Б	COMPOSITION TILE	1968	SATISFACTORY	m	109	108
317	27	331	CUSTODIAL SERMCE CLOSET	0	Ю	COMPOSITION TILE	1968	SATISFACTORY	n	109	108



Prepared by: **HEERY**

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

										ŀ	
305	1258	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	Б	CARPET	1968	SATISFACTORY	ო	109	108
305A	34	815	STUDENT RESTROOM (MALE)	0	б	CERAMIC TILE	1968	SATISFACTORY	т	109	108
305B	34	816	STUDENT RESTROOM (FEMALE)	0	б	CERAMIC TILE	1968	SATISFACTORY	т	109	108
306	1262	2	INTERMEDIATE MIDDLE CLASSROOM (4-8)	22	Б	CARPET	1968	SATISFACTORY	т	109	108
306A	78	814	STUDENT RESTROOM (BOTH SEXES)	0	Б	CERAMIC TILE	1968	SATISFACTORY	т	109	108
3068	82	200	INSIDE CIRCULATION	0	Б	CARPET	1968	SATISFACTORY	т	109	108
307	1259	2	INTERMEDIATE MIDDLE CLASSROOM (4-8)	22	Б	CARPET	1968	SATISFACTORY	т	109	108
307A	78	814	STUDENT RESTROOM (BOTH SEXES)	0	Б	CERAMIC TILE	1968	SATISFACTORY	т	109	108
307B	82	200	INSIDE CIRCULATION	0	Б	CARPET	1968	SATISFACTORY	т	109	108
308	1258	2	INTERMEDIATE MIDDLE CLASSROOM (4-8)	22	Б	CARPET	1968	SATISFACTORY	m	109	108
308A	78	814	STUDENT RESTROOM (BOTH SEXES)	0	Б	CERAMIC TILE	1968	SATISFACTORY	n	109	108
309	1259	2	INTERMEDIATE MIDDLE CLASSROOM (4-8)	22	Б	CARPET	1968	SATISFACTORY	т	109	108
309A	78	814	STUDENT RESTROOM (BOTH SEXES)	0	Б	CERAMIC TILE	1968	SATISFACTORY	т	109	108
310	955	10	PRIMARY SKILLS LAB (K-3)	0	Б	CARPET	1968	SATISFACTORY	т	109	108
310A	105	808	MATERIAL STORAGE	0	Б	CARPET	1968	SATISFACTORY	т	109	108
311	1060	10	PRIMARY SKILLS LAB (K-3)	0	Б	CARPET	1968	SATISFACTORY	т	109	108
312	56	331	CUSTODIAL SERMCE CLOSET	0	Б	COMPOSITION TILE	1968	SATISFACTORY	т	109	108
313	215	816	STUDENT RESTROOM (FEMALE)	0	Б	CERAMIC TILE	1968	SATISFACTORY	т	109	108
314	160	815	STUDENT RESTROOM (MALE)	0	Б	CERAMIC TILE	1968	SATISFACTORY	m	109	108
315	288	702	MECHANICAL ROOM	0	О	CONCRETE	1968	SATISFACTORY	m	109	108
316	27	331	CUSTODIAL SERVICE CLOSET	0	б	COMPOSITION TILE	1968	SATISFACTORY	m	109	108
317	27	331	CUSTODIAL SERVICE CLOSET	0	Б	COMPOSITION TILE	1968	SATISFACTORY	n	109	108



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

318	299	702	MECHANICAL ROOM		0	М	CONCRETE	1968	1968 SATISFACTORY	CORY	е	109	108
		Sati	Satisfactory	Unsatie	Unsatisfactory		Failed Standards	andards		Scheduled For Replacement	or Repl	acement	
	Š	Square Feet	Student Stations	Square Feet	Student Stations	tations	Square Feet	Student Stations	ations	Square Feet		Student Stations	SE
Permanent	ıt.	16,225	164	0		0							
TOTAL		16,225	164	0		0	0		0		0		0



Page 9 of 30

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

318	299	702	MECHANICAL ROOM		0	Б	CONCRETE	1968	1968 SATISFACTORY	STORY	е	109	108
		Sati	Satisfactory	Unsatisfactory	factory		Failed Standards	andards		Scheduled For Replacement	ForRepl	acement	
	Š	quare Feet	Square Feet Student Stations	Square Feet	Student Stations	ations	Square Feet	Student Stations	ations	Square Feet		Student Stations	ø
Pemanent	#	16,225	164	0		0							
TOTAL		16,225	164	0		0	0		0		0		0



Page 9 of 30

FACILITY INVENTORY REPORT

DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 108-A FAIRWAY ELEMENTARY

ᇴ
õ
8
ਙ
ä
7
5
ž
6
_
₩
≡
Ξ
Ξ.
÷
~
Ö
z
5
_
5
面

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: ELEMENTARY	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1968	Artificial Lighting: SHELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational TV: FIXED SERVICE TRANSMITTER/RECEIVER	Heat Capacity. ADEQUATE
Average Age NSF: 1968	Intercom: TW/O W/AY P ARTIAL	Walls STUCCO
Relocatable Units: 0	Telephone: P.ARTI.AL SYSTEM	Struct Comp. COMBINATION OF 1-3
Stories: 1		Corridor. DOUBLE INSIDE

ROOM	ROOM NET SQ FT	DE SIGN CODE	DESCRIPTION	STU	FLR	FLOOR COVER	YEAR CONST	соирішои	вше	PAR	FAC
400	1560	701	COVERED WALKWAY		Б	CONCRETE	1968	SATISFACTORY	4	109	108
401	2331	380	LIBRARY (READING ROOM/STACKS)		М	CARPET	1968	SATISFACTORY	4	109	108
403	198	306	CONFERENCE ROOM		М	CARPET	1968	SATISFACTORY	4	109	108
404	168	301	ASSISTANT PRINCIPAL/OTHER OFFICE		М	CARPET	1968	SATISFACTORY	4	109	108
405	34	821	STAFF RESTROOM (BOTH SEXES)		Б	CERAMIC TILE	1968	SATISFACTORY	4	109	108
406	26	331	CUSTODIAL SERVICE CLOSET		М	CERAMIC TILE	1968	SATISFACTORY	4	109	108
407	1630	387	MEDIA PRODUCTION LAB		М	CERAMIC TILE	1968	SATISFACTORY	4	109	108
410	009	385	CLOSED CIRCUIT TV LAB		М	CERAMIC TILE	1968	SATISFACTORY	4	109	108
411	540	383	AUDIO VISUAL STORAGE		ы	CERAMIC TILE	1968	SATISFACTORY	4	109	108
412	400	386	CLOSED CIRCUIT STORAGE		Б	CONCRETE	1968	SATISFACTORY	4	109	108
413	88	811	OUTSIDE STORAGE		М	CONCRETE	1968	SATISFACTORY	4	109	108
414	72	503	ELECTRICAL ROOM	0	01	CONCRETE	1968	SATISFACTORY	4	109	108

Report Date: 9/4/2015 10:32:57 AM

FACILITY INVENTORY REPORT

DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 108-A FAIRWAY ELEMENTARY

BUILDING: 4 - Building Number 00004

Owner. SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: ELEMENTARY	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1968	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational TV: FIXED SERVICE TRANSMITTER/RECEIVER	Heat Capacity. ADEQUATE
Average Age NSF: 1968	Intercom: TWIO WAY P ARTIAL	Wall≲ STUCCO
Relocatable Units: 0	Telephone: P.ARTIAL SYSTEM	Struct Comp. COMBINATION OF 1-3
Stories: 1		Corridor. DOUBLE INSIDE

ROOM	ROOM NET SQ FT	DE SIGN CODE	DESCRIPTION	STU	F. 20	FLOOR COVER	YEAR	соивілом	вше	PAR	FAC
400	1560	701	COVERED WALKWAY	0	Б	CONCRETE	1968	SATISFACTORY	4	109	108
401	2331	380	LIBRARY (READING ROOM/STACKS)	0	Б	CARPET	1968	SATISFACTORY	4	109	108
403	198	306	CONFERENCE ROOM	0	Б	CARPET	1968	SATISFACTORY	4	109	108
404	168	301	ASSISTANT PRINCIPAL/OTHER OFFICE	0	Б	CARPET	1968	SATISFACTORY	4	109	108
405	34	821	STAFF RESTROOM (BOTH SEXES)	0	Б	CERAMIC TILE	1968	SATISFACTORY	4	109	108
406	26	331	CUSTODIAL SERMCE CLOSET	0	Б	CERAMIC TILE	1968	SATISFACTORY	4	109	108
407	1630	387	MEDIA PRODUCTION LAB	0	Б	CERAMIC TILE	1968	SATISFACTORY	4	109	108
410	009	385	CLOSED CIRCUIT TV LAB	0	Б	CERAMIC TILE	1968	SATISFACTORY	4	109	108
411	540	383	AUDIO VISUAL STORAGE	0	Б	CERAMIC TILE	1968	SATISFACTORY	4	109	108
412	400	386	CLOSED CIRCUIT STORAGE	0	Б	CONCRETE	1968	SATISFACTORY	4	109	108
413	88	811	OUTSIDE STORAGE	0	Б	CONCRETE	1968	SATISFACTORY	4	109	108
414	72	503	ELECTRICAL ROOM	0	10	CONCRETE	1968	SATISFACTORY	4	109	108

Report Date: 9/4/2015 10:32:57 AM

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

415	155	702	MECHANICAL ROOM	0	ы	CONCRETE	1968	SATISFACTORY	4	109	108
416	316	13	ELEMENTARYP E STORAGE	0	М	CERAMIC TILE	1968	SATISFACTORY	4	109	108
417	72	821	STAFF RESTROOM (BOTH SEXES)	0	Ю	CERAMIC TILE	1968	SATISFACTORY	4	109	108
418	34	822	PUBLICUSE RESTROOM (MALE)	0	Ю	CERAMIC TILE	1968	SATISFACTORY	4	109	108
419	34	823	PUBLICUSE RESTROOM (FEMALE)	0	01	CERAMIC TILE	1968	SATISFACTORY	4	109	108
420	103	315	TE ACHER PLANNING OFFICE	0	01	CARPET	1968	SATISFACTORY	4	109	108
421	627	14	ELEMENTARY COVERED PLAY AREA	0	01	CONCRETE	1968	SATISFACTORY	4	109	108

Satisfactory Unsatisfactory Failed Standards Scheduled For Replacement	121 OZY 14 FEETWEIN 121 COVENED TO 01 CONSCIENT 1200 SATISTACION 1	Replacement Student St	Scheduled For	andards Student Stations	Failed St.	nt Stations	Unsatis Square Feet	sfactory Student Stations	Square Feet 8,988	manen
Olisational Paris I alica Stational Co	Honofinfontone Enlard Chandrado	Student Star	Square Feet 0	Student Stations	\$ 	Student Stations 0	Square Feet 0		Square Feet 8,988 8,988	Permanent TOTAL





FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

							L				
415	155	702	MECHANICAL ROOM	0	δ	CONCRETE	1968	SATISFACTORY	4	109	108
416	316	13	ELEMENTARYP E STORAGE		О	CERAMIC TILE	1968	SATISFACTORY	4	109	108
417	72	821	STAFF RESTROOM (BOTH SEXES)		Ю	CERAMIC TILE	1968	SATISFACTORY	4	109	108
418	34	822	PUBLIC USE RESTROOM (MALE)		М	CERAMIC TILE	1968	SATISFACTORY	4	109	108
419	34	823	PUBLIC USE RESTROOM (FEMALE)		О	CERAMIC TILE	1968	SATISFACTORY	4	109	108
420	103	315	TE ACHER PLANNING OFFICE	0	01	CARPET	1968	SATISFACTORY	4	109	108
421	627	14	ELEMENTARY COVERED PLAY AREA	0	01	CONCRETE	1968	SATISFACTORY	4	109	108

Student Stations

Square Feet

Student Stations

Square Feet

Student Stations

Square Feet

Student Stations

Square Feet

8,988

Permanent TOTAL

Satisfactory

Unsatisfactory

Failed Standards

Scheduled For Replacement

N S	LORID	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1

OB
TABA

Prepared by: **HEERY**

FACILITY INVENTORY REPORT

DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 108-A FAIRWAY ELEMENTARY

BUILDING: 5 - Building Number 00005

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: ELEMENTARY	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1991	Artificial Lighting: SHELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational TV: FIXED SERVICE TRANSMITTER/RECEIVER	Heat Capacity, ADEQUATE
Average Age NSF: 1991	Intercom: TW/O W/AY COMPLETE	Walls STUCCO
Relocatable Units: 0	Telephone: P.ARTIAL SYSTEM	Struct Comp. COMBINATION OF 1-3
Stories: 1		Corridor. DOUBLE INSIDE

ROOM	NET SQ FT	DE SIGN CODE	DESCRIPTION	STU	FLR	FLOOR COVER	YEAR CONST	СОИВІЛОИ	вше	PAR	FAC
900	1098	200	INSIDE CIRCULATION	0	ы	CARPET	1991	SATISFACTORY	5	109	108
200	374	200	INSIDE CIRCULATION	0	ы	CARPET	1991	SATISFACTORY	5	109	108
800	395	200	INSIDE CIRCULATION	0	ы	CARPET	1991	SATISFACTORY	5	109	108
200	3650	701	COVERED WALKWAY	0	ы	CONCRETE	1991	SATISFACTORY	5	109	108
500A	525	701	COVERED WALKWAY	0	ы	CONCRETE	1991	SATISFACTORY	5	109	108
200C	008	701	COVERED WALKWAY	0	ы	CONCRETE	1991	SATISFACTORY	5	109	108
2000	88	701	COVERED WALKWAY	0	ы	CONCRETE	1991	SATISFACTORY	5	109	108
501	1068	-	PRIMARY CLASSROOM (K-3)	18	ы	CARPET	1991	SATISFACTORY	5	109	108
501A	8	814	STUDENT RESTROOM (BOTH SEXES)	0	ы	CERAMIC TILE	1991	SATISFACTORY	5	109	108
502	1068	-	PRIMARY CLASSROOM (K-3)	18	Б	CARPET	1991	SATISFACTORY	5	109	108
502A	8	814	STUDENT RESTROOM (BOTH SEXES)	0	ы	CERAMIC TILE	1991	SATISFACTORY	5	109	108
503	1068	-	PRIMARY CLASSROOM (K-3)	18	ы	CARPET	1991	SATISFACTORY	5	109	108

Report Date: 9/4/2015 10:32:57 AM

FACILITY INVENTORY REPORT

8 108 8 8 8 8 8 8 8 8 8 8 18 8 109 109 8 8 8 8 8 8 8 8 8 8 50 50 50 50 40 50 50 ۱Ç. 3 50 50 50 30 SATISFACTORY 1991 1991 991 991 1991 9 1991 99 98 1991 1991 1991 99 99 1991 99 98 99 99 9 9 9 9 99 CERAMIC TILE CONCRETE CONCRETE CONCRETE CARPET δ δ δ 5 δ δ 5 8 8 8 5 5 Б 5 8 8 δ Б Б 5 δ ∞ ₽ <u>0</u> ∞ ∞ φ ∞ 9 9 ∞ ∞ 0 0 0 0 0 0 SEXES) SEXES) SEXES) SEXES) STUDENT RESTROOM (BOTH SEXES) CUSTODIAL SERVICE CLOSET STUDENT RESTROOM (BOTH PRIMARY CLASSROOM (K-3) MECHANICAL ROOM MECHANICAL ROOM <u>8</u> <u>%</u> <u>%</u> <u>%</u> <u>%</u> <u>%</u> <u>8</u> <u>%</u> 914 24 702 702 贸 1128 1068 1089 1125 1067 1068 1068 1088 187 187 8 8 8 8 8 8 8 8 8 8 \$ ñ 511A 513A 507A 510A 512A 504A 506A 508A 503A 505A 509A 8 209 510 212 513 8 514 8



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

108 108 Student Stations Scheduled For Replacement 109 8 5 Square Feet SATISFACTORY SATISFACTORY SATISFACTORY Student Stations 1991 1991 1991 ailed Standards 0 234 22,637 22,637 Permanent TOTAL 517 518 520

Fa		factory	Unsatisfactory	Satisfactory	Sat		
				•			
CERAMIC TILE	М	0	эотн ѕехеѕ)	STUDENT RESTROOM (BOTH SEXES)	814	300	0
CONCRETE	Б	0	AGE.	ELEMENTARYP E STORAGE	13	347	
CONCRETE	М	0		ELECTRICAL ROOM	203	103	7
						150	



FACILITY INVENTORY REPORT

DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 108-A FAIRWAY ELEMENTARY

BUILDING: 6 - Building Number 00006

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: ELEMENTARY	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Construded: 1991	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational TV: FIXED SERVICE TRANSMITTER, RECEIVER	Heat Capacity. ADEQUATE
Average Age NSF: 1991	Intercom: TWIO WAY COMPLETE	Wall≲ STUCCO
Relocatable Unit≲ 0	Telephone: PARTIAL SYSTEM	Struct Comp. COMBINATION OF 1-3
Stories: 1		Comidor: DOUBLE INSIDE

ROOM	ROOM NET SQ FT	DE SIGN CODE	DESCRIPTION	STU	F. P.	FLOOR COVER	YEAR CONST	соивілои	вше	PAR	FAC
009	3217	701	COVERED WALKWAY		Б	CONCRETE	1991	SATISFACTORY	9	109	108
600A	20	701	COVERED WALKWAY		Б	CONCRETE	1991	SATISFACTORY	9	109	108
8009	22	701	COVERED WALKWAY	o	Б	CONCRETE	1991	SATISFACTORY	9	109	108
900C	675	701	COVERED WALKWAY	o	Б	CONCRETE	1991	SATISFACTORY	9	109	108
0009	22	701	COVERED WALKWAY	o	Б	CONCRETE	1991	SATISFACTORY	9	109	108
900E	125	701	COVERED WALKWAY		Б	CONCRETE	1991	SATISFACTORY	9	109	108
800F	550	701	COVERED WALKWAY	o	Б	CONCRETE	1991	SATISFACTORY	9	109	108
90d	1530	55	MUSIC - ELEMENTARY	o	Б	CARPET	1991	SATISFACTORY	9	109	108
802	100	315	TE ACHER PLANNING OFFICE		Б	CARPET	1991	SATISFACTORY	9	109	108
903	145	808	MATERIAL STORAGE		Б	CARPET	1991	SATISFACTORY	9	109	108
604	153	908	REFERENCE	0	Ю	CARPET	1991	SATISFACTORY	9	109	108
909	519	364	STAGE STORAGE	0	ы	CARPET	1991	SATISFACTORY	9	109	108

Report Date: 9/4/2015 10:32:57 AM

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

909	205	820	STAFF RESTROOM (FEMALE)	0	М	CERAMIC TILE	1991	SATISFACTORY	9	109	108
209	217	819	STAFF RESTROOM (MALE)	0	Б	CERAMIC TILE	1991	SATISFACTORY	9	109	108
809	317	200	INSIDE CIRCULATION	0	Б	CARPET	1991	SATISFACTORY	9	109	108
609	109	702	MECHANICAL ROOM	0	Б	CONCRETE	1991	SATISFACTORY	9	109	108
610	18	364	STAGE STORAGE	0	Б	CARPET	1991	SATISFACTORY	9	109	108
611	802	363	STAGE	0	Б	WOOD	1991	SATISFACTORY	9	109	108
612	20	831	MUSIC PRACTICE ROOM	0	Б	CARPET	1991	SATISFACTORY	9	109	108
613	47	200	INSIDE CIRCULATION	0	Б	COMPOSITION TILE	1991	SATISFACTORY	9	109	108
614	250	386	STAGE DRESSING ROOM (FEMALE)	0	Б	COMPOSITION TILE	1991	SATISFACTORY	9	109	108
614A	34	816	STUDENT RESTROOM (FEMALE)	0	Б	CERAMIC TILE	1991	SATISFACTORY	9	109	108
615	250	365	STAGE DRESSING ROOM (MALE)	0	Б	COMPOSITION TILE	1991	SATISFACTORY	9	109	108
615A	34	815	STUDENT RESTROOM (MALE)	0	Б	COMPOSITION TILE	1991	SATISFACTORY	9	109	108
616A	1896	361	MULTIPURPOSE ROOM (DINING)	0	Б	COMPOSITION TILE	1991	SATISFACTORY	9	109	108
6168	3600	340	DINING AREA	0	Б	COMPOSITION TILE	1991	SATISFACTORY	9	109	108
617	34	819	STAFF RESTROOM (MALE)	0	Б	CONCRETE	1991	SATISFACTORY	9	109	108
818	34	820	STAFF RESTROOM (FEMALE)	0	Б	CONCRETE	1991	SATISFACTORY	9	109	108
619	14	200	INSIDE CIRCULATION	0	Б	COMPOSITION TILE	1991	SATISFACTORY	9	109	108
620	62	316	TE ACHER LOUNGE, DINING	0	Б	COMPOSITION TILE	1991	SATISFACTORY	9	109	108
621	159	364	STAGE STORAGE	0	Б	COMPOSITION TILE	1991	SATISFACTORY	9	109	108
622	402	316	TE ACHER LOUNGE DINING	0	Б	CARPET	1991	SATISFACTORY	9	109	108
623	1602	346	KITCHEN FOOD PREP ARATION	0	Б	QUARRY TILE	1991	SATISFACTORY	9	109	108
624	190	342	KITCHEN DRYSTORAGE	0	Б	QUARRY TILE	1991	SATISFACTORY	9	109	108
625	88	343	KITCHEN OFFICE	0	Б	QUARRY TILE	1991	SATISFACTORY	9	109	108
979	88	345	KITCHEN NONFOOD STORAGE	0	01	QUARRY TILE	1991	SATISFACTORY	9	109	108



Student Stations

Square Feet

Student Stations

Square Feet

Student Stations

Square Feet

Student Stations

Square Feet

20,056 20,056

Permanent TOTAL

Failed Standards

Scheduled For Replacement

Report Date: 9/4/2015 10:32:57 AM

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

6 109 10	109	109	109	109	109	109	109	109	109	109	109		109	109	109	109
												_				
SATISFACTORY	SATISFACTORY	SATISFACTORY	SATISFACTORY	SATISFACTORY	SATISFACTORY	SATISFACTORY	SATISFACTORY	SATISFACTORY	SATISFACTORY	SATISFACTORY	SATISFACTORY		SATISFACTORY	SATISFACTORY SATISFACTORY	SATISFACTORY SATISFACTORY SATISFACTORY	SATISFACTORY SATISFACTORY SATISFACTORY SATISFACTORY
1991	1991	1991	1991	1991	1991	1991	1991	1991	1991	1991	1991		1991	1991	1991	1991
COMPOSITION TILE	QUARRY TILE	QUARRY TILE	QUARRY TILE	CERAMIC TILE	CONCRETE	CARPET	CERAMIC TILE	CERAMIC TILE	CONCRETE	CONCRETE	CONCRETE		COMPOSITION TILE	COMPOSITION TILE	COMPOSITION TILE CERAMIC TILE CARPET	COMPOSITION TILE CERAMIC TILE CARPET QUARRY TILE
М	Б	Б	Б	Б	Б	Б	Б	Б	Б	Б	Б		5_	<u>δ δ</u>	δ δ δ	δ
0				0									,			
CUSTODIAL SERMCE CLOSET	OTHER FOOD SERVICE	OTHER FOOD SERVICE	INSIDE CIRCULATION	KITCHEN GARBAGE WASH	MECHANICAL ROOM	TE ACHER LOUNGE, DINING	INSIDE CIRCULATION	STAFF RESTROOM (BOTH SEXES)	ELECTRICAL ROOM	ELECTRICAL ROOM	MECHANICAL ROOM	INSIDE CIRCULATION		STAFF RESTROOM (BOTH SEXES)		
331	350	350	200	344	702	316	200	821	703	703	702	200		821	821	821 331 344
35	92	95	92	72	150	102	33	32	153	88	200	513		99		
627	628	628A	629	630	831	632	632A	632B	633	634	635	929		636A	636A 636B	636A 636B 637





FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 108-A FAIRWAY ELEMENTARY

BIIII DING: 7 - Building Number

DULLDING: r - Building Mutibes 0000r		
Owner. SCHOOL BO ARD	Light: ADEQUATE	Cooling: CENTRAL
Use: ELEMENTARY	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1991	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational TV: FIXED SERVICE TRANSMITTER/RECEIVER	Heat Capacity. ADEQUATE
Average Age NSF: 1991	Intercom: TWO W/AY COMPLETE	Walls STUCCO
Relocatable Units: 0	Telephone: COMPLETE TO ALL ROOMS	Struct Comp. COMBINATION OF 1-3
Stories: 1		Corridor. NONE

ROOM	ROOM NET SQ FT	DE SIGN CODE	DESCRIPTION	STU	F.R.	FLOOR COVER	YEAR CONST	соирілом	вше	PAR	FAC
600	803	200	INSIDE CIRCULATION	0	Б	CARPET	1991	SATISFACTORY	7	109	108
200	1831	701	COVERED WALKWAY	0	Б	CONCRETE	1991	SATISFACTORY	7	109	108
701	453	304	RECEPTION AREA	0	Б	CARPET	1991	SATISFACTORY	7	109	108
702	099	303	SECRETARIAL SPACE	0	Б	CARPET	1991	SATISFACTORY	7	109	108
203	382	305	PRODUCTION WORKROOM	0	Б	CARPET	1991	SATISFACTORY	7	109	108
704	135	302	BOOKKEEPING OFFICE	0	Б	CARPET	1991	SATISFACTORY	7	109	108
202	135	312	COMPUTER AREA	0	Б	CARPET	1991	SATISFACTORY	7	109	108
902	179	301	ASSISTANT PRINCIPALJOTHER OFFICE	0	Б	CARPET	1991	SATISFACTORY	7	109	108
202	243	300	PRINCIPALDIRECTOR OFFICE	0	Б	CARPET	1991	SATISFACTORY	7	109	108
208	177	301	ASSISTANT PRINCIPALIOTHER OFFICE	0	Б	CARPET	1991	SATISFACTORY	7	109	108
509	177	306	CONFERENCE ROOM	0	Б	CARPET	1991	SATISFACTORY	7	109	108
210	50	703	ELECTRICAL ROOM	0	01	CONCRETE	1991	SATISFACTORY	7	109	108



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

109	109	109	109	109	109	109	109	109	109	109	109	109
2	~	~	~	~	~	~	~	~	~	~	~	2
SATISFACTORY	SATISFACTORY	SATISFACTORY	SATISFACTORY	SATISFACTORY	SATISFACTORY	SATISFACTORY	SATISFACTORY	SATISFACTORY	SATISFACTORY	SATISFACTORY	SATISFACTORY	SATISFACTORY
1991	1991	1991	1991	1991	1991	1991	1991	1991	1991	1991	1991	1991
CONCRETE	CARPET	CARPET	CARPET	CARPET	COMPOSITION TILE	CERAMIC TILE	CERAMIC TILE	CARPET	CARPET	CONCRETE	CERAMIC TILE	CERAMIC TILE
Ю	Б	Б	Б	Б	Б	Б	Б	Б	Б	Б	Б	8
					_	_	_	_	_	_	_	
MECHANICAL ROOM 0	ASSISTANT PRINCIPAL/OTHER OFFICE 0	ASSISTANT PRINCIPAL/OTHER OFFICE 0	GENERAL SCHOOL STORAGE 0	GENERAL SCHOOL STORAGE 0	CLINIC	STUDENT RESTROOM (MALE) 0	STUDENT RESTROOM (FEMALE) 0	VAULT/STUDENT RECORDS 0	GENERAL SCHOOL STORAGE 0	CUSTODIAL SERVICE CLOSET 0	STAFF RESTROOM (MALE) 0	STAFF RESTROOM (FEMALE)
702	304	304	308	308	307	815	816	308	308	331	819	820
92	176	173	198	133	187	32	51	22	178	8	32	32
711	712	713	714	715	716	716A	7168	717	718	719	720	721

108

	Sati	Satisfactory	Unsati	Unsatisfactory	Failed Standards	andards	S
	Square Feet	Square Feet Student Stations	Square Feet	Square Feet Student Stations	Square Feet	Student Stations	nbs
Permanent	6,616	0	0	0			
TOTAL	6,616	0	0	0	0	0	

Student Stations

uare Feet

Scheduled For Replacement



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 108-A FAIRWAY ELEMENTARY

BUILDING: 8 - Building Number 00008

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: NONE
Use: ELEMENTARY	Mech Vent: ADEQUATE	Heat Source: NONE
Year Constructed: 1991	Artificial Lighting: NONE	Heat Distribution: NO HE AT PROVIDED
Year Modified:	Educational TV: NONE	Heat Capacity: NONE
Average Age NSF: 1991	Intercom: NONE	Wall≈ STUCCO
Relocatable Units: 0	Telephone: NONE	Struct Comp. COMBINATION OF 1-3
Stories: 1		Corridor. NONE

ROOM	NET SQ FT	ROOM NET SQ DE SIGN FT CODE	DESCR	DESCRIPTION	STU	FLR	FLOOR COVER	YEAR	соивілои	BLDG	PAR	FAC
801	187	333	FLAMMABLE STORAGE		0	Б	CONCRETE	1991	SATISFACTORY	80	109	108
802	336	333	FLAMMABLE STORAGE		0	Б	CONCRETE	1991	SATISFACTORY	8	109	108
									_			
		Sat	Satisfactory	Unsatisfactory	actory		Failed Standards	rdards	Schedu	Scheduled For Replacement	placement	
	Sq	Square Feet	Student Stations	Square Feet	Student Stations	ations	Square Feet	Student Stations	ations Square Feet		Student Stations	dions
Permanent	ŧ	523	0	0		0						



Prepared by: **HEERY**

FACILITY INVENTORY REPORT

DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 108-A FAIRWAY ELEMENTARY

DOLLDING. 13 - Durung named cool 3		
Owner, SCHOOL BOARD	Light: ADEQUATE	Cooling: INDIVIDUAL UNITS
USE: ELEMENTARY	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 2001	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational TV: FIXED SERVICE RECEIVER	Heat Capacity: ADEQUATE
Average Age NSF: 2001	Intercom: TWO WAY COMPLETE	Wall≲ CONCRETE
Refocatable Units 0	Telephone: COMPLETE TO ALL ROOMS	Struct Comp. CONCRETE
Stories 1		Corridor, NONE

ROOM	NET SQ FT	DE SIGN CODE	DESCRIPTION	STU	FLR LOC	FLOOR COVER	YEAR	соирілом	вше	PAR	FAC
700M	1300	701	COVERED WALKWAY		М	CONCRETE	2001	SATISFACTORY	22	109	108
751	286	-	PRIMARY CLASSROOM (K-3)	18	Б	COMPOSITION TILE	2001	SATISFACTORY	75	109	108
751A	55	814	STUDENT RESTROOM (BOTH SEXES)		Б	CERAMIC TILE	2001	SATISFACTORY	75	109	108
752	8	702	MECHANICAL ROOM		Ю	CONCRETE	2001	SATISFACTORY	75	109	108
753	20	811	OUTSIDE STORAGE		Б	COMPOSITION TILE	2001	SATISFACTORY	75	109	108
754	286	-	PRIMARY CLASSROOM (K-3)	18	ы	COMPOSITION TILE	2001	SATISFACTORY	75	109	108
754A	55	814	STUDENT RESTROOM (BOTH SEXES)		ы	CERAMIC TILE	2001	SATISFACTORY	75	109	108
252	286	-	PRIMARY CLASSROOM (K-3)	18	ы	COMPOSITION TILE	2001	SATISFACTORY	75	109	108
755A	55	814	STUDENT RESTROOM (BOTH SEXES)		ы	CERAMIC TILE	2001	SATISFACTORY	75	109	108
952	8	702	MECHANICAL ROOM	0	Ю	CONCRETE	2001	SATISFACTORY	22	109	108
757	20	703	ELECTRICAL ROOM		Ю	CONCRETE	2001	SATISFACTORY	22	109	108
952	286	-	PRIMARY CLASSROOM (K-3)	18	01	COMPOSITION TILE	2001	SATISFACTORY	22	109	108

Report Date: 9/4/2015 10:32:57 AM

8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8

8 8

75

SATISFACTORY

빌

COMPOSITION

₽

PRIMARY CLASSROOM (K-3)

702

8

769A

98 8

767

770A

2

98

Prepared by: **HEERY**

2001 2001

CONCRETE

δ δ

Report Date: 9/4/2015 10:32:57 AM

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

109 8 109 8 8 8 8 8 8 8 8 8 8 8 9 8 8 8 75 75 75 75 22 75 22 75 75 75 75 75 75 75 75 22 75 75 75 22 SATISFACTORY 2001 2001 2001 2001 ğ 2001 2001 2001 2001 2001 2001 2001 2001 2001 2001 8 2001 2001 200 COMPOSITION TILE COMPOSITION TILE 1 COMPOSITION TILE COMPOSITION TILE COMPOSITION CERAMIC TILE COMPOSITION COMPOSITION CERAMIC TILE CERAMIC TILE COMPOSITION CERAMIC TILE CERAMIC TILE COMPOSITION CERAMIC TILE CONCRETE CONCRETE CONCRETE CONCRETE 8 8 8 δ δ 5 5 8 5 5 δ Б Б δ δ 8 8 δ δ φ φ 9 9 9 0 0 0 0 0 TELEPHONE EQUIPMENT/COMMUNICATION CLOSET STUDENT RESTROOM (BOTH SEXES) CUSTODIAL SERVICE CLOSET PRIMARY CLASSROOM (K-3) MECHANICAL ROOM MECHANICAL ROOM MECHANICAL ROOM OUTSIDE STORAGE MECHANICAL ROOM OUTSIDE STORAGE OUTSIDE STORAGE 702 702 <u>%</u> <u>8</u> 707 702 2 <u>8</u> <u>8</u> 2 33 2 987 987 987 98 984 22 Q 22 22 2 33 22 8 88 55 88 8 8



758A

59A

g

765A

8

8

764A

764

82 8

õ

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

773A 55	55	814	STUDENT RESTROOM (OOM (BOTH SEXES)	0	Б	CERAMIC TILE	2001 SATISFACTORY	SATISFAC	TORY	52	109	108
		Sat	Satisfactory	Unsati	Unsatisfactory		Failed Standards	indards		Scheduled For Replacement	or Repla	cement	
	S	Square Feet	Student Stations	Square Feet	Student Stations	tations	Square Feet	Student Stations	rtions	Square Feet	Stri	Student Stations	22
Permanent	#	12,470	180	0		0							
TOTAL		12,470	180	0		0	0		0				0



Page 23 of 30

FACILITY INVENTORY REPORT

DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT

FACILITY: 108-A FAIRWAY ELEMENTARY

BUILDING: 78 - Building Number 00078

Owner. SCHOOL BOARD	Light: ADEQUATE	Cooling: INDIVIDUAL UNITS
Use: ELEMENTARY	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 2005	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: INDIMDUAL UNIT REVERSE CYCLE
Year Modified:	Educational TV: FIXED SERVICE RECEIVER	Heat Capacity: ADEQUATE
Average Age NSF: 2005	Intercom: TW/O W/AY COMPLETE	Wall≲ CONCRETE
Relocatable Units: 0	Telephone: P.ARTIAL SYSTEM	Struct Comp. CONCRETE
Stories: 1		Corridor. NONE

RO OM	NET SQ FT	ROOM NET SQ DE SIGN FT CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	соивілои	вше	PAR	FAC
082	911	-	PRIMARY CLASSROOM (K-3)	9	Б	COMPOSITION TILE	2005	SATISFACTORY	82	109	108
780A	49	814	STUDENT RESTROOM (BOTH SEXES)	0	Б	CERAMIC TILE	2005	SATISFACTORY	82	109	108
784	911	-	PRIMARY CLASSROOM (K-3)	92	Б	COMPOSITION TILE	2005	SATISFACTORY	82	109	108
781A	49	814	STUDENT RESTROOM (BOTH SEXES)	0	Б	CERAMIC TILE	2005	SATISFACTORY	28	109	108

Square Feet St	Student Stations	Unsatis Square Feet	Unsatisfactory set Student Stations	Failed Standards Square Feet Studer	andards Student Stations	Square Feet Student Sta	Replacement Student Stations
	8 8	, 0	0	0	0	0	

Report Date: 9/4/2015 10:32:57 AM

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 6 BROWARD COUNTY SCHOOL DISTRICT FACILITY: 108-A FAIRWAY ELEMENTARY

BUILDING: 80 - Building Number 00080

Owner. SCHOOL BOARD	Light: ADEQUATE	Cooling: INDIVIDUAL UNITS
USS: ELEMENTARY	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 2004	Artificial Lighting: SHELDED FLORESCENT	Heat Distribution: INDIVIDUAL UNIT REVERSE CYCLE
Year Modified:	Educational TV: FIXED SERVICE RECEIVER	Heat Capacity. ADEQUATE
Average Age NSF: 2004	Intercom: TWO WAY COMPLETE	Mall≈ CONCRETE
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp. CONCRETE
Stories: 1		Corridor. NONE

ROOM	ROOM NET SQ FT	DE SIGN CODE	DESCRIPTION	STU	F. F. F.	FLOOR COVER	YEAR	соирілои	вше	PAR	FAC
M080	1284	200	INSIDE CIRCULATION		Б	COMPOSITION TILE	2004	SATISFACTORY	8	109	108
M008	930	701	COVERED WALKWAY	0	Б	CONCRETE	2004	SATISFACTORY	8	109	108
850	288	1	PRIMARY CLASSROOM (K-3)	91	Б	COMPOSITION TILE	2004	SATISFACTORY	80	109	108
850A	45	814	STUDENT RESTROOM (BOTH SEXES)	0	Б	CERAMIC TILE	2004	SATISFACTORY	80	109	108
851	288	1	PRIMARY CLASSROOM (K-3)	92	Б	COMPOSITION TILE	2004	SATISFACTORY	80	109	108
851A	45	814	STUDENT RESTROOM (BOTH SEXES)	0	10	CERAMIC TILE	2004	SATISFACTORY	80	109	108
852	863	1	PRIMARY CLASSROOM (K-3)	18	10	COMPOSITION TILE	2004	SATISFACTORY	08	109	108
852A	46	814	STUDENT RESTROOM (BOTH SEXES)	0	10	CERAMIC TILE	2004	SATISFACTORY	80	109	108
853	863	1	PRIMARY CLASSROOM (K-3)	18	10	COMPOSITION TILE	2004	SATISFACTORY	80	109	108
853A	46	814	STUDENT RESTROOM (BOTH SEXES)	0	10	CERAMIC TILE	2004	SATISFACTORY	80	109	108
854	98	202	TELEPHONE EQUIPMENT/COMMUNICATION CLOSET	0	Б	COMPOSITION TILE	2004	SATISFACTORY	80	109	108



8

8 8 108 8 8

Report Date: 9/4/2015 10:32:57 AM

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

109 8 8 109 8 8 8 89 109 8 8 8 8 8 80 8 8 8 8 8 8 SATISFACTORY 2004 2004 2004 2004 2004 2004 2004 2004 2004 2004 2004 COMPOSITION TILE COMPOSITION TILE COMPOSITION TILE COMPOSITION TILE COMPOSITION TILE COMPOSITION CERAMIC TILE CERAMIC TILE CERAMIC TILE CERAMIC TILE CERAMIC TILE 5 Б δ Б 5 δ Б δ δ δ δ φ ∞ ∞ 9 0 0 0 STUDENT RESTROOM (BOTH SEXES) STUDENT RESTROOM (BOTH SEXES) STUDENT RESTROOM (BOTH SEXES) STUDENT RESTROOM (BOTH SEXES) CUSTODIAL SERVICE CLOSET PRIMARY CLASSROOM (K-3) PRIMARY CLASSROOM (K-3) PRIMARY CLASSROOM (K-3) PRIMARY CLASSROOM (K-3) MATERIAL STORAGE ELECTRICAL ROOM 703 <u>%</u> <u>%</u> 24 8 <u>8</u> 뛵 862 862 88 \$ 88 8 46 46 \$ 88 8 861A 859A 860A 358A 88 8 8 8

9 8 9

861A 45	5 814	STUDENT RESTROOM (BOTH SEXES)	ротн sexes)	0 01	CERAMIC TILE	2004	2004 SATISFACTORY	80	109	108
	š	Satisfactory	Unsatisfactory	actory	Failed Standards	andards	Sch	Scheduled For Replacement	placement	
	Square Feet	Square Feet Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	ions Square Feet		Student Stations	ions
Permanent	9,874	74 144	0		0					
TOTAL	9,874	74 144	0		0 0		0	0		0



Page 26 of 30

Prepared by: **HEERY**

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

STUDENT STATIONS BY DESIGN CODE FOR: FACILITY: FAIRWAY ELEMENTARY

		Sati	Sattis Stu Sta	ā	Unsa	Unsat Stu Sta	Tã	Sat	Unsat	Sati	Satis Rooms		Unsatis Rooms	Rooms	Fail Std Stu Sta	Repl Stu Sta	Fail Std Rooms	Repl Rooms
Design Code	Design Code Description	Perm	Mod	Se Se	Pem T	Mod	Selo	ξ	₽ E	Pem	Mod	Relo Per	erm Mod	d Relo	Relo	Relo	Relo	Relo
00004	PRIMARY CLASSROOM (K-3)	99	0	0	0	-	0	930	0	45	-	0	0	0	0	0	0	0
00002	INTERMEDIATE MIDDLE CLASSROOM (4-8)	110	0	0	0	0	0	110	0	s	0	0	0	0	0	0	0	0
000010	PRIMARY SKILLS LAB (K-3)	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0
00013	ELEMENTARYP E STORAGE	0	0	0	0	-	0	0	0	2	-	0	0	0	0	0	0	0
4000	ELEMENTARY COVERED PLAY AREA	0	0	0	0	0	0	0	0	-	0	0	0	0	0	0	0	0
00040	RESOURCE ROOM	0	0	0	0	0	0	0	0	-	0	0	0	0	0	0	0	0
0000	ART - ELEMENTARY	0	0	0	0	0	0	0	0	-	0	0	0	0	0	0	0	0
9900	MUSIC - ELEMENTARY	0	0	0	0	0	0	0	0	-	0	0	0	0	0	0	0	0
1900	E S E PART-TIME	R	0	0	0	0	0	8	0	2	0	0	0	0	0	0	0	0
00062	E S E FULL-TIME	8	0	0	0	0	0	8	0	2	0	0	0	0	0	0	0	0
9000	E S E RESOURCE	0	0	0	0	0	0	0	0	-	0	0	0	0	0	0	0	0
00300	PRINCIPAL/DIRECTOR OFFICE	0	0	0	0	0	0	0	0	1	0	0 0	0	0	0	0	0	0
90304	ASSISTANT PRINCIPAL/OTHER OFFICE	0	0	0	-	0	0	0	-	2	0	0	0	0	0	0	0	0
00302	BOOKKEEPING OFFICE	0	0	0	0	0	0	0	0	-	0	0	0	0	0	0	0	0
00303	SECRETARIAL SPACE	0	0	0	0	0	0	0	0	,	0	0 0	0	0	0	0	0	0
40000	RECEPTION AREA	0	0	0	0	0	0	0	0	2	0	0 0	0	0	0	0	0	0
90302	PRODUCTION WORKROOM	0	0	0	0	0	0	0	0	-	0	0 0	0	0	0	0	0	0
90200	CONFERENCE ROOM	0	0	0	0	0	0	0	0	m	0	0	0	0	0	0	0	0
2000	CLINIC	0	0	0	0	0	0	0	0	-	0	0	0	0	0	0	0	0
80200	GENERAL SCHOOL STORAGE	0	0	0	0	0	0	0	0	9	0	0 0	0	0	0	0	0	0
60000	VAULT/STUDENT RECORDS	0	0	0	0	0	0	0	0	2	0	0 0	0	0	0	0	0	0
00312	COMPUTER AREA	0	0	0	0	0	0	0	0	-	0	0 0	0	0	0	0	0	0
41800	ITINER ANT OFFICE	0	0	0	0	0	0	0	0	3	0	0 0	0	0	0	0	0	0
S	00315 TE ACHER PLANNING OFFICE	0	0	0	0	0	0	0	0	m	0	0	0	0	0	0	0	0

Prepared by: **HEERY**



FACILITY INVENTORY REPORT

Rooms Se Se Fail Std Rooms <u>용</u> Repl Stu Sta 용 Fail Std Stu Sta Relo Unsatis Rooms g M Perm Relo Satis Rooms Ø ₩ Реш m N σ ø N Unsat ĕ Sat ğ Relo Unsat Stu Sta g M Реш Relo Satis Stu Sta Μod Perm TELEPHONE EQUIPMENT/COMMUNICATION CLOSET Design Code Description LIBRARY (READING ROOM/STACKS) STAGE DRESSING ROOM (FEMALE) STAGE DRESSING ROOM (MALE) MULTIPURPOSE ROOM (DINING) KITCHEN NONFOOD STORAGE KITCHEN FOOD PREP ARATION CUSTODIAL SERVICE CLOSET CLOSED CIRCUIT STORAGE TE ACHER LOUNGE DINING KITCHEN GARBAGE WASH CLOSED CIRCUIT TV LAB MEDIA PRODUCTION LAB AUDIO MSUAL STORAGE KITCHEN DRY STORAGE FLAMMABLE STORAGE OTHER FOOD SERVICE TE XTBOOK STORAGE INSIDE CIRCULATION COVERED WALKWAY MECHANICAL ROOM ELECTRICAL ROOM KITCHEN OFFICE STAGE STORAGE DINING AREA STAGE



FACILITY INVENTORY REPORT

Se Se Fail Std Rooms <u>용</u> Repl Stu Sta Fail Std Stu Sta 용 Unsatis Rooms g M Perm Relo Satis Rooms Mod Pell ω w w w Unsat ğ Sat ğ Relo Unsat Stu Sta g M Реш Relo Satis Stu Sta Mod Perm STUDENT RESTROOM (BOTH SEXES) Design Code Description PUBLIC USE RESTROOM (FEMALE) STAFF RESTROOM (BOTH SEXES) PUBLIC USE RESTROOM (MALE) STUDENT RESTROOM (FEMALE) STUDENT RESTROOM (MALE) STAFF RESTROOM (FEMALE) STAFF RESTROOM (MALE) MUSIC PRACTICE ROOM MATERIAL STORAGE OUTSIDE STORAGE REFERENCE




FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT




Prepared by: **HEERY**

2.3.3 FISH Site Plan



2.3.4 FISH Building Plan



2.4.0 Facility Assessments and Budgetary Documentation

This section includes facility condition assessments and budgetary documentation that has been completed over recent years regarding the General Obligation Bond funding and approved budgetary construction scope of work.

2.3.1 Adopted District Educational Facilities Plan

The ADEFP is the most recent approved budget for each campus of Broward County Schools. Construction scope is itemized including changes to the initial deficiency listings for each campus. It is the responsibility of the Design/Build Contractor to reconcile any differences between the ADEFP and additional budgetary or facility condition assessments.

2.3.2 SMART Campus Summary

The SMART Campus Summary is the most recent facility condition assessment completed for each campus. The summary provides existing building applicable dates and square footage, in addition to deficiency listings broken down into Safety & Security, Music & Arts, Athletics, Renovations, and Technology (SMART) categories to organize the approved funding in terms of programs that are affected.

The Campus Summary does not represent the final approved funding, and is for information purposes only.

2.3.3 MAPPS Deficiency Listing

The MAPPS Deficiency Listing is a detailed facility condition assessment conducted by Jacobs over recent years. The deficiency listing is presented as an itemized list of deficiencies on a site and building specific level organized by discipline. Note that all deficiency items are not in the scope of work. Items initialed "GOB" are included in the initial General Obligation Bond, prior to final approval of ADEFP.

The MAPPS Deficiency Listing does not represent the final approved funding, and is for information purposes only.

2.3.4 MAPPS Detailed List

The MAPPS Detailed List is raw database information in tabular format. The purpose of the Detailed List is to provide additional notes and quantity to cost estimate information. It is important to note that the Detailed List does not include all items from the approved budget. Additional items may occur and should be confirmed with the ADEFP.

2.3.5 MAPPS Deficiency Detail

The MAPPS Deficiency Detail report is raw database information with a breakdown of the cost estimate including construction adjustments and soft cost adjustments. As is with the Detail List, budget confirmation with the ADEFP is required.



2.4.1 Adopted District Educational Facilities Plan (DEFP)

Fairway Elementary School

	Ado	pted Dis	trict Edu	ıcationa	l Facilitie	s Plan	
Project	Carryover (2014-15)	Year 1 (2015-16)	Year 2 (2016-17)	Year 3 (2017-18)	Year 4 (2018-19)	Total	Scope
There are no ADEFP p	projects for this loca	ation.					

			SMART	Program			
Project	Carryover (2014-15)	Year 1 (2015-16)	Year 2 (2016-17)	Year 3 (2017-18)	Year 4 (2018-19)	Total	Scope
Safety & Security		193,000				193,000	Safety / Security Upgrade
Safety & Security		294,000				294,000	Fire Alarm
Renovation		89,000				89,000	Wireless Network Upgrade
Renovation		100,000				100,000	School Choice Enhancement
Renovation		172,000				172,000	Media Center improvements
Renovation		1,570,000				1,570,000	HVAC Improvements
Renovation		366,000				366,000	Electrical Improvements
Renovation		4,000				4,000	CAT 6 Data port Upgrade
Renovation		1,408,000				1,408,000	Building Envelope Improvements {Roof, Window, Ext Wall, etc.}
Technology		138,000				138,000	Additional computers to close computer gap
SMART Sub-Total	0	4,334,000	0	0	0	4,334,000	
	Carryover (2014-15)	Year 1 (2015-16)	Year 2 (2016-17)	Year 3 (2017-18)	Year 4 (2018-19)	Total	
School Total	0	4,334,000	0	0	0	4,334,000	-

P-0016xx RFQ Number: 16-182C

2.4.2 SMART Campus Summary



1641 Fairway Elementary School

7850 Fairway Boulevard Miramar FL 33023

Year Open 1968 Other Years 1991, 2001, 2004, 2005 Perm. Bldgs/SF 11 113,091 Port. Bldgs/SF 0 0

Current FCI Need 8,091,241 Replacement Value 19,901,334 Facility Condition Index 40.7%

2014 Facility Condition Assessment **Campus Summary**



Facility Condition Index

\$8,091,241 Current Need \$19,901,334 Replacement Value 40.7 % FCI

GOB Bond / Construction Projects

Safety & Security	Budget	Fund Yr.	Status
Fairway Elementary School Fire Alarm	\$294,000	2016	2014 GOB
Fairway Elementary School Safety / Security	\$193,000	2016	2014 GOB
	\$497,000		

Music & Arts Budget Fund Yr. Status None Identified

Athletics Budget Fund Yr. Status None Identified

Renovations	Budget	Fund Yr.	Status
Fairway Elementary School Roofing	\$1,408,000	2016	2014 GOB
Fairway Elementary School HVAC	\$545,000	2016	2014 GOB
Fairway ES School Choice Enhancement	\$100,000	2016	2014 GOB
Fairway Elementary School Other HVAC Improvements	\$1,025,000	2016	2014 GOB
Fairway Elementary School Electrical Improvements	\$366,000	2016	2014 GOB
Repair of exterior wall at building 75 at Fairway ES	\$30,000	2014	Construction
Fairway Elementary School Media Center Renovations	\$172,000	2016	2014 GOB

\$3,646,000

Technology	Budget	Fund Yr.	Status
Fairway ES Computer Gap	\$138,000	2016	2014 GOB
Fairway ES CAT 6 Dataport	\$4,000	2016	2014 GOB
Fairway ES Wireless Network	\$89,000	2016	2014 GOB
	\$231,000		

Total In-Progress and Planned \$4,364,000

Total Unplanned Need \$4,480,574





2014 Facility Condition Assessment **Campus Summary**

Unplanned Need

Safety & Security	Budget
None Identified	
	\$0
Music & Arts	Budge
Fairway Elementary School Music / Art Renovations	\$136,489
	\$136,489
Athletics	Budgel
None Identified	
	\$0
Renovations	Budgel
Media Center Expansion	\$118,027
Other Electrical improvements at Fairway Elementary School	\$94,221
Various maintenance projects throughout campus	
Fairway Elementary School STEM Lab Renovations	\$51,026
Misc Maintenance Improvements at Fairway ES	\$797,817
Misc Site Improvements at Fairway ES	\$2,268,521
Misc Interior Improvements at Fairway ES	\$521,523
Misc Plumbing Improvements at Fairway ES	\$87,694
Misc Specialties Improvements at Fairway ES	\$181,893
Misc Other Improvements at Fairway ES	\$169,365
	\$4,290,087
Technology	Budgel
Fiber Optic Network (10GB) Upgrade at Fairway ES	\$53,998
	\$53,998

Total Unplanned Need \$4,480,574



P-0016xx RFQ Number: 16-182C

1641

2.4.3 MAPPS Deficiency Listing

Broward County Public Schools

Fairway Elementary School

School Deficiency Listing

\$2,268,520

\$7,709

Repair Cost ID

9/2/2014 9:08 AM

Site Level Deficiencies

Site

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Playground Requires Impact Resistant Material	Educational Adequacy	1	Ea.	3	\$5,722	226616
Asphalt Paving Is Damaged And Requires Replacement	Capital Renewal	500	CAR	4	\$1,252,306	73903
Asphalt Paving Is Damaged And Requires Replacement	Capital Renewal	284	CAR	4	\$785,671	312610
Paved Play Requires Recoating And Resurfacing	Deferred Maintenance	8,000	SF	5	\$113,906	73901
Paved Play Requires Recoating And Resurfacing	Deferred Maintenance	8,000	SF	5	\$110,916	312609

Roofing

Deficiency	Category	Qty UoM	Priority	Repair Cost ID	
Aluminum Covered Walkways Require Replacement	Capital Renewal	5,055 SF	2	\$31,115 314380	GOB
Aluminum Covered Walkways Require Replacement	Capital Renewal	4.767 SF	2	\$29,342 314381	GOB
Aluminum Covered Walkways Require Replacement	Capital Renewal	1,831 SF	2	\$11,270 314382	GOB
Aluminum Covered Walkways Require Replacement	Capital Renewal	1,560 SF	2	\$9,602 314641	GOB
	Sub Total for System	4 items		\$81,329	

Sub Total for System

Sub Total for System

5 items

Qty UoM

Electrical

Deficiency	Category	Qty UoM	Priority	Repair Cost ID	
The Canopy Lighting Requires Replacement	Deferred Maintenance	4 Ea.	2	\$7,709 71735	GOB

Fire and Security

To also also we						
	Sub Total for System	2 items		\$301,412		
The Exterior Security Camera Is Damaged And Should Be Replaced	Capital Renewal	2 Ea.	2	\$7,717	71854	
Location: Main/Portable						
Entire Fire Alarm System Needs to be Replaced	Capital Renewal	1 LS	1	\$293,695	220832	GOB
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	

Technology Deficiency

School requires Wireless Access Point hardware	Functional Deficiency	1	LS	2	\$38,656	313466	GOB
CAT-6 wiring to WAP needs to be provided	Functional Deficiency	64	Ea.	3	\$50,481	225093	GOB
	Sub Total for System	3	items		\$227,037		
Other							
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID	
School Selected Educational Adequacy Enhancement	Educational Adequacy	1	LS	2	\$100,000	314243	GOB
School requires additional media center space	New Construction	472	SF	3	\$118,026	314742	
Provide Elementary School Music Room	New Construction	1	Ea.	5	\$169,365	226509	
	Sub Total for System	3	items		\$387,391		
	Sub Total for School and Site Level	18	items		\$3,273,399		

Building: 01 - Classroom

School requires computers to close accessibility gap

Site

Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
The Canopy Lighting Is Missing And Needed	Functional Deficiency	5 Ea.	2	\$10,458	70722	GOB
The Mounted Building Lighting Is Damaged And Should Be Replaced	Capital Renewal	6 Ea.	2	\$5,985	70724	GOB
The Pole Lighting Is Damaged And Should Be Replaced	Capital Renewal	14 Ea.	2	\$74,738	70721	GOB
The Pole Lighting Is Missing And Needed	Functional Deficiency	6 Ea.	2	\$72,681	70719	GOB

Rev 1 Sept 2014 M-A-P-P-S ©, Jacobs 2014 Fairway Elementary School

1641

Page 1 of 14



Broward County Public Schools

Fairway Elementary School

School Deficiency Listing

\$164,950

\$56,156

\$162,411

9/2/2014 9:08 AM

Building: 01 - Classroom

Site

	Sub Total for System	6	items		\$167,504	
The Pole Lighting Requires Repair	Deferred Maintenance	2	Ea.	3	\$3,640	70720
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID

Roofing

Deficiency	Category	Qty UoM	Priority	Repair Cost ID	
Reroofing with new Decking Required (Broward CPS)	Capital Renewal	13,046 SF	2	\$158,735 223665	GOB
The Roof Requires Cleaning	Deferred Maintenance	500 SF	4	\$6,214 223664	

Sub Total for System

2 items

10 items

7 items

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Classroom doors lack appropriate signs.	Educational Adequacy	6	Ea.	3	\$1,026	Rollup
The Acoustical Ceilings Tiles Require Replacement	Capital Renewal	1,000	SF	3	\$5,639	73906
The Carpet Flooring Requires Replacement	Capital Renewal	600	SF	3	\$6,320	73909
The Concrete Flooring Requires Repair or Repainting	Deferred Maintenance	300	SF	3	\$798	73911
The Vinyl Composition Tile Requires Replacement	Capital Renewal	1,500	SF	3	\$13,455	73910
Interior Gypboard Walls Require Repair	Deferred Maintenance	150	SF Wall	4	\$812	73908
Room has insufficient tackboard area.	Educational Adequacy	16	Ea.	4	\$6,166	Rollup
Room lacks appropriate sound control.	Educational Adequacy	604	SF	4	\$18,945	Rollup
Interior Gypboard Walls Require Repainting	Deferred Maintenance	150	SF Wall	5	\$506	73907
Room lacks a changing table.	Educational Adequacy	1	Ea.	5	\$2,488	Rollup

Mechanical

Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
The 2 X 2 Exhausts/Hoods Require Replacement	Deferred Maintenance	2 Ea.	2	\$13,485	73272	GOB
Controls Are Inadequate And Should Be Replaced With DDC Controls	Capital Renewal	13,208 SF	3	\$56,324	73276	GOB
Duct Heater Requires Replacement	Capital Renewal	1 Ea.	3	\$5,223	73281	GOB
Exhaust Fan Ventilation Requires Replacement	Capital Renewal	1 Ea.	3	\$2,108	73274	GOB
Package Roof Top Unit Requires Replacement	Capital Renewal	1 Ea.	3	\$18,026	73273	GOB
The Air Handler HVAC Component Requires Replacement	Capital Renewal	1 Ea.	3	\$56,145	73279	GOB
Duct Cleaning Required	Deferred Maintenance	13,208 SF	5	\$11,100	73277	

Sub Total for System

Sub Total for System

Electrical

Liectrical							
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID	
Emergency Exit Signage Requires Replacement	Deferred Maintenance	5	Ea.	2	\$3,667	70727	GOB
Emergency Lighting Is Inadequate Or Not Present And Should Be Installed	Code Compliance	13,208	SF	2	\$21,264	70726	GOB
The GFCI Electrical Receptacles Are Inadequate And More Are Needed	Deferred Maintenance	4	Ea.	2	\$1,698	70728	GOB
Room does not have tamper-proof light switching.	Educational Adequacy	3	Ea.	5	\$1,457	Rollup	
	Sub Total for System	4	items		\$28,085		
Plumbing							
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID	
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	1	Ea.	2	\$1,357	Rollup	

Rev 1 Sept 2014 Fairway Elementary School 1641 M-A-P-P-S ©, Jacobs 2014

Page 2 of 14

Broward County Public Schools

School Deficiency Listing

1641 Fairway Elementary School	ol					9/2/2014	
Building: 01 - Classroom				_			
Plumbing							
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID	
Room lacks a private shower area.	Educational Adequacy	2	Ea.	4	\$18,266	Rollup	
Room lacks private toilets.	Educational Adequacy	1	Ea.	4	\$11,217	Rollup	
Room lacks a drinking fountain.	Educational Adequacy	1	Ea.	5	\$959	Rollup	
	Sub Total for System	4	items		\$31,798		
Гесhnology							
Deficiency	Category		UoM	Priority	Repair Cost	ID	
Room lacks Fixed Projector	Educational Adequacy	5	Ea.	2	\$18,421	Rollup	
Room lacks Interactive White Board	Educational Adequacy	6	Ea.	2	\$16,330	Rollup	
	Sub Total for System	2	items		\$34,751		
Specialties							
Deficiency	Category		UoM -	Priority	Repair Cost	ID	
com lacks an appropriate refrigerator.	Educational Adequacy	1	Ea.	3	\$5,253	Rollup	
Room lacks an appropriate stove.	Educational Adequacy	1	Ea.	3	\$7,171	Rollup	
coom lacks the required demonstration table.	Educational Adequacy	1	Ea.	3	\$7,463	Rollup	
llinds are missing or in poor condition.	Educational Adequacy	24	SF Surf	4	\$677	Rollup	
oom does not have sufficient cubbies.	Educational Adequacy	62	Ea.	5	\$2,582	Rollup	
coom has an insufficient number of coat hooks.	Educational Adequacy	48	Ea.	5	\$558	Rollup	
	Sub Total for System	6	items		\$23,705		
Other							
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID	
enovate / Remodel Music and Art Rooms	Deferred Maintenance	1	LS	2	\$136,489	316733	
	Sub Total for System	1	items		\$136,489		
	Sub Total for Building 01 - Classroom	41	items		\$805,848		
Building: 02 - Classroom							
Site							
Deficiency	Category	Qtv	UoM	Priority	Repair Cost	ID	
he Mounted Building Lighting Is Damaged And Should Be Replaced	Capital Renewal		Ea.	2	\$5,985	70729	GOB
	Sub Total for System	1	items		\$5,985		
Roofing					Repair Cost	ID	
	Category	Qty	UoM	Priority			
eficiency	Category Capital Renewal	Qty 13,083		Prionty 2	\$159,186		GOE
reficiency eroofing with new Decking Required (Broward CPS)			SF		\$159,186		GOE
reficiency eroofing with new Decking Required (Broward CPS)	Capital Renewal Deferred	13,083 500	SF	2	\$159,186	223667	GOE
Deficiency Reroofing with new Decking Required (Broward CPS) The Roof Requires Cleaning	Capital Renewal Deferred Maintenance Sub Total for System	13,083 500 2	SF SF items	2 4	\$159,186 \$6,214 \$165,400	223667 223666	GOE
reficiency reforming with new Decking Required (Broward CPS) he Roof Requires Cleaning nterior	Capital Renewal Deferred Maintenance Sub Total for System Category	13,083 500 2 Qty	SF SF items	2 4 Priority	\$159,186 \$6,214 \$165,400 Repair Cost	223667 223666 ID	GOB
reficiency reforming with new Decking Required (Broward CPS) he Roof Requires Cleaning nterior	Capital Renewal Deferred Maintenance Sub Total for System	13,083 500 2 Qty	SF SF items	2 4	\$159,186 \$6,214 \$165,400	223667 223666	GOE
reficiency reroofing with new Decking Required (Broward CPS) the Roof Requires Cleaning Interior reficiency Ilassroom doors lack appropriate signs	Capital Renewal Deferred Maintenance Sub Total for System Category Educational	13,083 500 2 Qty	SF SF items UoM Ea.	2 4 Priority	\$159,186 \$6,214 \$165,400 Repair Cost	223667 223666 ID	GOE
eficiency eroofing with new Decking Required (Broward CPS) he Roof Requires Cleaning nterior eficiency lassroom doors lack appropriate signs he Acoustical Ceilings Tiles Require Replacement	Capital Renewal Deferred Maintenance Sub Total for System Category Educational Adequacy	13,083 500 2 Qty	SF SF items UoM Ea. SF	2 4 Priority 3	\$159,186 \$6,214 \$165,400 Repair Cost \$1,369 \$5,639 \$13,455	223667 223666 ID Rollup 73949 73952	GOE
eficiency eroofing with new Decking Required (Broward CPS) he Roof Requires Cleaning nterior eficiency lassroom doors lack appropriate signs he Acoustical Ceilings Tiles Require Replacement he Vinyl Composition Tile Requires Replacement	Capital Renewal Deferred Maintenance Sub Total for System Category Educational Adequacy Capital Renewal	13,083 500 2 Qty 8 1,000 1,500	SF SF items UoM Ea. SF	2 4 Priority 3	\$159,186 \$6,214 \$165,400 Repair Cost \$1,369 \$5,639 \$13,455	223667 223666 ID Rollup 73949	GOB
Recofing Deficiency Reroofing with new Decking Required (Broward CPS) The Roof Requires Cleaning Interior Deficiency Classroom doors lack appropriate signs. The Acoustical Ceilings Titles Require Replacement The Vinyl Composition Title Requires Replacement Interior Gypboard Walls Require Repair	Capital Renewal Deferred Maintenance Sub Total for System Category Educational Adequacy Capital Renewal Capital Renewal Deferred	13,083 500 2 Qty 8 1,000 1,500	SF SF items UoM Ea. SF SF SF Wall	Priority 3 3 4	\$159,186 \$6,214 \$165,400 Repair Cost \$1,369 \$5,639 \$13,455	223667 223666 ID Rollup 73949 73952 73951	G0B

School Deficiency Listing

1641	Eginyoy Elementery School	N		\neg		9/2/2014	9:08 AM
	Fairway Elementary School)i					
Building: 0	2 - Classroom						
Interior							
Deficiency		Category	Qty UoN	1 Priority	Repair Cost	ID	
Room has insufficient l	ackboard area.	Educational Adequacy	32 Ea.	4	\$12,331	Rollup	
Room lacks appropriat	e sound control.	Educational Adequacy	742 SF	4	\$23,272	Rollup	
nterior Gypboard Wall	s Require Repainting	Deferred Maintenance	150 SF	Wall 5	\$506	73950	
Room lacks a changin	g table.	Educational Adequacy	1 Ea.	5	\$2,488	Rollup	
		Sub Total for System	8 item	ns	\$59,872		
Mechanical							
Deficiency		Category	Qty UoN	1 Priority	Repair Cost	ID	
Complete HVAC Syste	em Wide Replacement	Capital Renewal	13,191 SF	2	\$446,107	73296	GOB
		Sub Total for System	1 item	15	\$446,107		
Electrical							
Deficiency		Category	Qty UoN	1 Priority	Repair Cost	ID	
Emergency Exit Signa	ge Requires Replacement	Deferred Maintenance	6 Ea.	2	\$4,400	70732	GOB
Emergency Lighting Is	Inadequate Or Not Present And Should Be Install	ed Code Compliance	13 SF	2	\$21	70731	GOB
The GFCI Electrical Re	eceptacles Are Inadequate And More Are Needed	Deferred Maintenance	4 Ea.	2	\$1,698	70733	GOB
Room does not have t	amper-proof light switching.	Educational Adequacy	2 Ea.	5	\$971	Rollup	
	Sub Total for System	4 item	15	\$7,090			
Plumbing							
Deficiency		Category	Qty UoN	1 Priority	Repair Cost	ID	
The Refrigerated Wate	r Cooler Requires Replacement	Capital Renewal	4 Ea.	3	\$9,744	73300	
Room lacks a private s	shower area	Educational Adequacy	2 Ea.	4	\$18,266	Rollup	
Room lacks private toil	ets.	Educational Adequacy	1 Ea.	4	\$11,217	Rollup	
Room lacks a drinking	fountain.	Educational Adequacy	1 Ea.	5	\$959	Rollup	
		Sub Total for System	4 item	ıs	\$40,185		
Technology							
Deficiency		Category	Qty UoN	1 Priority	Repair Cost	ID	
Room lacks Fixed Proj	ector	Educational Adequacy	9 Ea.	2	\$33,158	Rollup	
Room lacks Interactive	White Board	Educational Adequacy	7 Ea.	2	\$19,052	Rollup	
		Sub Total for System	2 item	ıs	\$52,210		
Specialties							
Deficiency		Category	Qty UoN	1 Priority	Repair Cost	ID	
Room lacks an approp	riate refrigerator.	Educational Adequacy	1 Ea.	3	\$5,253	Rollup	
Room lacks an approp	riate stove.	Educational Adequacy	1 Ea.	3	\$7,171	Rollup	
Room does not have s	ufficient cubbies.	Educational Adequacy	54 Ea.	5	\$2,248	Rollup	
Room has an insufficie	ent number of coat hooks.	Educational Adequacy	216 Ea.	5	\$2,506	Rollup	
		Sub Total for System	4 item	ıs	\$17,179		

Rev 1 Sept 2014 M•A•P•P•S ©, Jacobs 2014 Fairway Elementary School

1641

Page 4 of 14

School Deficiency Listing

Fairway Elementary School Building: 03 - Classroom Site Deficiency Qty UoM Priority Repair Cost Category The Canopy Lighting Requires Replacement Deferred Maintenance \$8,035 71736 GOB The Mounted Building Lighting Is Damaged And Should Be Replaced Capital Renewal 6 Ea \$5,985 71739 GOB Sub Total for System 2 items \$14.020 Roofing Deficiency Qty UoM Priority Repair Cost Category Reroofing with new Decking Required (Broward CPS) Capital Renewal 16,400 SF 2 \$199,545 223668 GOB Sub Total for System \$199,545 1 items Interior Qty UoM Deficiency Category Classroom doors lack appropriate signs. Educational 10 Ea. \$1,711 Rollup Adequacy Room has insufficient writing area. Educational 3 Ea. 3 \$3,116 Rollup The Acoustical Ceilings Tiles Require Replacement Capital Renewal 700 SF 3 \$3.947 73953 The Vinyl Composition Tile Requires Replacement Capital Renewal 2,000 SF \$17,941 73956 300 SF Wall Interior Gypboard Walls Require Repair Deferred 4 \$1,624 73955 Room has insufficient tackboard area Educational 23 Ea. \$8,863 Rollup Educational Room lacks appropriate amount of teacher storage 5 Ea. \$3,024 Rollup Adequacy Interior Gypboard Walls Require Repainting Deferred 300, SE Wall \$1.011 73954 Sub Total for System 8 items \$41.237 Mechanical s Are Inadequate And Should Be Replaced With DDC Controls \$15,668 73318 Duct Heater Requires Replacement Capital Renewal 3 Ea. 3 GOB 15,671 SF \$21,977 73314 Test And Balancing Required Deferred GOB Maintenance The Air Handler HVAC Component Requires Replacement Capital Renewal \$169,135 73317 Duct Cleaning Required Deferred 15,671 SF \$13,170 73316 Maintenance Sub Total for System 5 items \$286,777 **Electrical** Repair Cost Category Qtv UoM Priority Emergency Exit Signage Requires Replacement Deferred Maintenance Emergency Lighting Is Inadequate Or Not Present And Should Be Installed Code Compliance 15,671 SF 2 \$25,229 71740 GOB \$2.547 71742 The GFCI Electrical Receptacles Are Inadequate And More Are Needed Deferred 6 Ea. 2 GOB Maintenance \$21.948 Rollup Room has insufficient electrical outlets Educational 60 Ea. Sub Total for System \$55,591 4 items **Plumbing** Category Qty UoM Repair Cost The Refrigerated Water Cooler Requires Replacement Capital Renewal 2 Ea. \$4,872 73319 Sub Total for System 1 items \$4,872 Technology Category Qty UoM Repair Cost Room has insufficient dataports. Educational 22 Ea. 2 \$3,806 Rollup GOB Room lacks Fixed Projector Educational Adequac 5 Ea. 2 \$18,421 Rollup

1641

Page 5 of 14

Fairway Elementary School

Rev 1 Sept 2014

M-A-P-P-S ©, Jacobs 2014

School Deficiency Listing

ool				9/2/2014	9:08 AM
Category	Qtv. UoM	Priority	Repair Cost	ID	
Educational	10 Ea.	2	\$27,217	Rollup	
Adequacy					
Sub Total for System	3 items		\$49,444		
Category	Qty UoM	Priority	Repair Cost	ID	
Educational Adequacy	78 Ea.	5	\$3,250	Rollup	
Educational Adequacy	48 Ea.	5	\$556	Rollup	
Sub Total for System	2 items		\$3,807		
Category	Qty UoM	Priority	Repair Cost	ID	
Capital Renewal	1 LS	2	\$51,026	316929	
Sub Total for System	1 items		\$51,026		
Sub Total for Building 03 - Classroom	27 items		\$706,319		
Category	Qty UoM	Priority	Repair Cost	ID	
Deferred Maintenance	6 Ea.	2	\$12,053	71797	GOB
Capital Renewal	6 Ea.	2	\$5,985	71798	GOB
Sub Total for System	2 items		\$18, 03 8		
Category	Qty UoM	Priority	Repair Cost	ID	
Capital Renewal	7,799 SF	2	\$94,893	223669	GOB
Sub Total for System	1 items		\$94,893		
Category	Qty UoM	Priority	Repair Cost	ID	
Educational	1 Ea.	3	\$373	Rollup	
Educational	3 Ea.	3	\$513	Rollup	
	950 SF	3	\$5.357	73963	
Educational	16 Ea.	4	\$9,677	Rollup	
Adequacy		Δ			
	1,700 0	4		конир	
' '			674 OFG		
Sub Total for System	5 items		\$71,059		
Sub Total for System		Delection		ır	
Sub Total for System Category	Qty UoM	Priority 2	Repair Cost	ID 73335	GOR
Sub Total for System		Priority 2		ID 73335	GOB
Sub Total for System Category Deferred	Qty UoM	2	Repair Cost		GOB GOB
Sub Total for System Category Deferred Maintenance Capital Renewal Capital Renewal	Qty UoM 2 Ea. 7,799 SF 1 Ea.	2 3 3	Repair Cost \$13,485 \$33,258 \$5,223	73335 73339 73342	GOB GOB
Category Deferred Maintenance Capital Renewal Capital Renewal Capital Renewal	Qty UoM 2 Ea. 7,799 SF 1 Ea. 1 Ea.	2 3 3 3	Repair Cost \$13,485 \$33,258 \$5,223 \$18,026	73335 73339 73342 73336	GOB GOB GOB
Sub Total for System Category Deferred Maintenance Capital Renewal Capital Renewal	Qty UoM 2 Ea. 7,799 SF 1 Ea.	2 3 3	Repair Cost \$13,485 \$33,258 \$5,223	73335 73339 73342	GOB GOB
Category Defemed Maintenance Capital Renewal Capital Renewal Capital Renewal Defemed	Qty UoM 2 Ea. 7,799 SF 1 Ea. 1 Ea.	2 3 3 3	Repair Cost \$13,485 \$33,258 \$5,223 \$18,026	73335 73339 73342 73336	GOB GOB GOB
Category Deferred Maintenance Capital Renewal Capital Renewal Capital Renewal Deferred Maintenance Capital Renewal	Oty UoM 2 Ea. 7,799 SF 1 Ea. 1 Ea. 7,799 SF	2 3 3 3 3	Repair Cost \$13,485 \$33,258 \$5,223 \$18,026 \$10,937	73335 73339 73342 73336 73338	GOB GOB GOB
Category Deferred Maintenance Capital Renewal Capital Renewal Capital Renewal Deferred Maintenance Capital Renewal Deferred Maintenance Deferred Maintenance	Oty UoM 2 Ea. 7,799 SF 1 Ea. 1 Ea. 7,799 SF	2 3 3 3 3 3	Repair Cost \$13,485 \$33,258 \$5,223 \$18,026 \$10,937 \$56,145	73335 73339 73342 73336 73338 73341	GOB GOB GOB
Category Deferred Maintenance Capital Renewal Capital Renewal Capital Renewal Deferred Maintenance Capital Renewal Deferred Maintenance Deferred Maintenance	Oty UoM 2 Ea. 7,799 SF 1 Ea. 1 Ea. 7,799 SF 1 Ea. 1,799 SF	2 3 3 3 3 3 3	Repair Cost \$13,485 \$33,258 \$5,223 \$18,026 \$10,937 \$56,145 \$70,648	73335 73339 73342 73336 73338 73341 71799	GOB GOB GOB
Category Deferred Maintenance Capital Renewal Capital Renewal Capital Renewal Deferred Maintenance Capital Renewal Deferred Maintenance Deferred Maintenance	Oty UoM 2 Ea. 7,799 SF 1 Ea. 1 Ea. 7,799 SF 1 Ea. 7,799 SF 1 Ea. 150 Ea. 7,799 SF	2 3 3 3 3 3 3	Repair Cost \$13,485 \$33,258 \$5,223 \$18,026 \$10,937 \$56,145 \$70,848	73335 73339 73342 73336 73338 73341 71799	GOB GOB GOB
	Category Educational Adequacy Sub Total for System Category Educational Adequacy Educational Adequacy Sub Total for System Category Capital Renewal Sub Total for System Sub Total for System Sub Total for System Category Capital Renewal Sub Total for System Category Deferred Maintenance Capital Renewal Sub Total for System Category Capital Renewal Educational Adequacy Capital Renewal Educational Adequacy Capital Renewal Educational Adequacy Educational	Category	Category	Category City UoM Priority Repair Cost	Category City UoM Priority Repair Cost ID

Page 6 of 14

M-A-P-P-S ©, Jacobs 2014

Fairway Elementary School

School Deficiency Listing

Repair Cost ID

Repair Cost ID

\$171,818

\$615,302

\$193,639

9/2/2014 9:08 AM

Building:	04 -	Building 4

Electrical

1641

Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
Emergency Exit Signage Requires Replacement	Deferred Maintenance	4 Ea.	2	\$2,933	71801	GOB
Emergency Lighting Is Inadequate Or Not Present And Should Be Installed	Code Compliance	7,799 SF	2	\$12,556	71800	GOB
The GFCI Electrical Receptacles Are Inadequate And More Are Needed	Deferred Maintenance	5 Ea.	2	\$2,123	71802	GOB
Room has insufficient electrical outlets	Educational Adequacy	10 Ea.	3	\$3,658	Rollup	
Room does not have tamper-proof light switching.	Educational Adequacy	2 Ea.	5	\$971	Rollup	
	Sub Total for System	5 items		\$22,241		
Plumbing						

Category

Qty UoM Priority

1 items

1 items

The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	2	Ea.	2	\$2,713	Rollup
	Sub Total for System	1	items		\$2,713	
Technology						
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks Fixed Projector	Educational Adequacy	2	Ea.	2	\$7,368	Rollup
Room lacks Interactive White Board	Educational Adequacy	1	Ea.	2	\$2,722	Rollup
The Computer Closet Requires Fiber Optic Access to CER	Functional Deficiency	400	LF	2	\$9,000	Rollup
Room lacks access to video distribution.	Educational Adequacy	1	Ea.	5	\$665	Rollup
	Sub Total for System	4	items		\$19,765	

Specialties Deficiency

Blinds are missing or in poor condition.	Educational Adequacy	18 SF Surf	4	\$508 Rollup	
	Sub Total for System	1 items		\$508	
Other					
Deficiency	Category	Qty UoM	Priority	Repair Cost ID	
Media Center requires renovation based on condition of room(s)	Capital Renewal	1 LS	2	\$171,818 316275	GOB

Sub Total for Building 04 - Building 4

Category

Sub Total for System

Sub Total for System

Building: 05 - Building 5

Site

Category	Qty UoM	Priority	Repair Cost	ID	
Functional Deficiency	9 Ea.	2	\$18,461	71809	GOB
Capital Renewal	16 Ea.	2	\$15,652	71811	GOB
Sub Total for System	2 items		\$34,113		
Category	Qty UoM	Priority	Repair Cost	ID	
Capital Renewal	18,461 SF	2	\$193,639	223670	GOB
	Functional Deficiency Capital Renewal Sub Total for System Category	Functional Deficiency 9 Ea. Capital Renewal 16 Ea. Sub Total for System 2 items	Functional Deficiency	Functional Deficiency 9 Ea. 2 \$18,461 Capital Renewal 16 Ea. 2 \$15,652 Sub Total for System 2 items \$34,113 Category Qty UoM Priority Repair Cost	Functional Deficiency 9 Ea. 2 \$18,461 71809 Capital Renewal 16 Ea. 2 \$15,652 71811 Sub Total for System 2 items \$34,113 Category Qly UoM Priority Repair Cost ID

Interior

Deficiency	Category	Qty UoM	Priority	Repair Cost ID	
Classroom doors lack appropriate signs.	Educational Adequacy	11 Ea.	3	\$1,882 Rollup	
The Acoustical Ceilings Tiles Require Replacement	Capital Renewal	3,000 SF	3	\$16,590 73970	
Room has insufficient tackboard area.	Educational Adequacy	52 Ea.	4	\$20,038 Rollup	

Rev 1 Sept 2014

Fairway Elementary School

1641

M-A-P-P-S ©, Jacobs 2014

Page 7 of 14

School Deficiency Listing

1641 Fairway Elementary School						9/2/2014	+ 5.00 r
Building: 05 - Building 5				_			
nterior							
eficiency	Category	Qty	UoM	Priority	Repair Cost	ID	
nterior Gypboard Walls Require Repainting	Deferred Maintenance	4,600	SF Wall	5	\$15,205	73972	
	Sub Total for System	4	items		\$53,716		
Mechanical							
eficiency	Category	Qty	UoM	Priority	Repair Cost	ID	
ontrols Are Inadequate And Should Be Replaced With DDC Controls	Capital Renewal	18,461	SF	3	\$77,203	73349	GOE
uct Heater Requires Replacement	Capital Renewal	2	Ea.	3	\$10,243	73352	GO
est And Balancing Required	Deferred Maintenance	18,461	SF	3	\$25,389	73348	GOE
he Air Handler HVAC Component Requires Replacement	Capital Renewal	2	Ea.	3	\$110,119	73351	GOE
uct Cleaning Required	Deferred Maintenance	18,461	SF	5	\$15,215	73350	
	Sub Total for System	5	items		\$238,170		
Electrical							
eficiency	Category		UoM	Priority	Repair Cost	ID	
mergency Exit Signage Requires Replacement	Deferred Maintenance	6	Ea.	2	\$4,315	71813	GO
mergency Lighting Is Inadequate Or Not Present And Should Be Installed	Code Compliance	18,461		2	\$29,146	71812	GOE
	Sub Total for System	2	items		\$33,461		
Plumbing							
eficiency	Category	Qty	UoM	Priority	Repair Cost	ID	
he Refrigerated Water Cooler Requires Replacement	Capital Renewal	3	Ea.	3	\$7,167	73353	
	Sub Total for System	1	items		\$7,167		
Гесhnology							
Deficiency	Category	Qtv	UoM	Priority	Repair Cost	ID	
Room lacks Fixed Projector	Educational	13		2	\$47,895	Rollup	
	Adequacy						
coom lacks Interactive White Board	Educational Adequacy	12	Ea.	2	\$32,660	Rollup	
he Computer Closet Requires Fiber Optic Access to CER	Functional Deficiency	400	LF	2	\$9,000	Rollup	
	Sub Total for System	3	items		\$89,555		
Specialties							
De ficiency	Category	Qty	UoM	Priority	Repair Cost	ID	
toom has an insufficient number of coat hooks.	Educational Adequacy	228	Ea.	5	\$2,640	Rollup	
	Sub Total for System	1	items		\$2,640		
Sub	Total for Building 05 - Building 5	19	items		\$652,461		
Building: 06 - Building 6							
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID	
he Exterior Security Camera Is Damaged And Should Be Replaced	Capital Renewal	4	Ea.	2	\$15,777	71824	
	Sub Total for System	0	items		\$15,777		
Site							
eficiency	Category	Qty	UoM	Priority	Repair Cost	ID	
he Canopy Lighting Is Missing And Needed	Functional Deficiency	12	Ea.	2	\$24,615	71819	GOE
he Mounted Building Lighting Is Damaged And Should Be Replaced	Capital Renewal	14	Ea.	2	\$13,696	71821	GOE
	Sub Total for System	2	items		\$38,310		
Roofing							
eficiency	Category	Qty	UoM	Priority	Repair Cost	ID	
teroofing Required (Broward CPS)	Capital Renewal	16,053	SF	2	\$168,382	223672	GOE

Rev 1 Sept 2014

Fairway Elementary School

1641

M•A•P•P•S ©, Jacobs 2014

Page 8 of 14



School Deficiency Listing

9/2/2014 9:08 AM

1641 Fairway Elementary School

Building: 06 - Building 6

Roofing

9							
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID	
The Roof Requires Cleaning	Deferred Maintenance	150	SF	4	\$1,864	223671	
	Sub Total for System	2	items		\$170,246		
nterior							
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID	
Classroom Door Requires Vision Panel	Educational Adequacy	1	Ea.	3	\$373	Rollup	
Classroom doors lack appropriate signs.	Educational Adequacy	9	Ea.	3	\$1,540	Rollup	
Room has insufficient writing area.	Educational Adequacy	1	Ea.	3	\$1,039	Rollup	
The Carpet Flooring Requires Replacement	Capital Renewal	2,821	SF	3	\$29,141	73987	
The Ceramic Tile Flooring Requires Replacement	Capital Renewal	25	SF	3	\$437	73989	
Fhe Concrete Flooring Requires Repair or Repainting	Deferred Maintenance	150	SF	3	\$391	73994	
The Stone/Quarry Flooring Is Damaged And Requires Replacement	Capital Renewal	150	SF	3	\$5,539	73992	
The Suspended Ceiling Grid and Tiles Require Replacement	Capital Renewal	8,000	SF	3	\$70,899	73984	
nterior Ceramic Walls Require Repair Or Replacement	Capital Renewal	20	SF Wall	4	\$374	73986	
Room has insufficient tackboard area.	Educational Adequacy	6	Ea.	4	\$2,312	Rollup	
Room lacks appropriate amount of teacher storage.	Educational Adequacy	10	Ea.	4	\$6,048	Rollup	
Room lacks appropriate sound control.	Educational Adequacy	2,378	SF	4	\$74,584	Rollup	
nterior Doors Require Repainting	Deferred Maintenance	20	Door	5	\$1,233	73997	
Interior Gypboard Walls Require Repainting	Deferred Maintenance	10,000	SF Wall	5	\$33,055	73985	
	Sub Total for System	14	items		\$226,964		
Mechanical							
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID	
Kitchen Air/Exhaust is missing and is needed	Functional Deficiency	1	Ea.	2	\$50,751	73447	GOB
he 2 X 2 Exhausts/Hoods Require Replacement	Deferred Maintenance	2	Ea.	2	\$13,225	73444	GOB
Controls Are Inadequate And Should Be Replaced With DDC Controls	Capital Renewal	16,053	SF	3	\$67,133	73451	GOB
Duct Heater Requires Replacement	Capital Renewal	1	Ea.	3	\$5,122	73458	GOB
Exhaust Fan Ventilation Requires Replacement	Capital Renewal	1	Ea.	3	\$2,067	73445	GOB
Fest And Balancing Required	Deferred Maintenance	16,053	SF	3	\$22,078	73448	GOB
The Air Handler HVAC Component Requires Replacement	Capital Renewal	1	Ea.	3	\$55,060	73456	GOB
Duct Cleaning Required	Deferred Maintenance	16,053	SF	5	\$13,230	73454	
	Sub Total for System	8	items		\$228,664		
Electrical							
Deficiency	Category	Otv	HoM	Priority	Repair Cost	ID	

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID	
Emergency Exit Signage Requires Replacement	Deferred Maintenance	6	Ea.	2	\$4,315	71833	GOB
Emergency Lighting Is Inadequate Or Not Present And Should Be Installed	Code Compliance	16,053	SF	2	\$25,344	71832	GOB
The GFCI Electrical Receptacles Are Inadequate And More Are Needed	Deferred Maintenance	6	Ea.	2	\$2,498	71836	GOB
Room has insufficient electrical outlets.	Educational Adequacy	16	Ea.	3	\$5,853	Rollup	
Stage Lighting Is Damaged, Broken Or Deficient	Functional Deficiency	6	Ea.	3	\$7,746	71831	
The 1 X4 Interior Fluorescent Light Fixture Requires Replacement	Capital Renewal	54	Ea.	3	\$19,104	71829	
The 2 X 4 Interior Fluorescent Lighting Requires Replacement	Capital Renewal	208	Ea.	3	\$117,069	71830	
The Electrical Receptacles Require Replacement	Capital Renewal	5	Ea.	3	\$1,273	71835	

Rev 1 Sept 2014

Fairway Elementary School

1641

M-A-P-P-S ©, Jacobs 2014

Page 9 of 14

School Deficiency Listing

1641 Fairway Elementary Scho	ol				9/2/2014	1 9:08 AM
Building: 06 - Building 6						
Electrical						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
Room does not have tamper-proof light switching.	Educational	1 Ea.	5	\$486	Rollup	
	Adequacy		-			
Room lacks controls to partially dim lights.	Educational Adequacy	1 Ea.	5	\$779	Rollup	
	Sub Total for System	10 items		\$184,467		
Plumbing						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
Room lacks a drinking fountain.	Educational	1 Ea.	5	\$959	Rollup	
	Adequacy					
	Sub Total for System	1 items		\$959		
Technology						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
Room lacks Fixed Projector	Educational	1 Ea.	2	\$3,684	Rollup	
Room lacks Interactive White Board	Adequacy Educational	1 Ea.	2	en 7nn	Dolling	
Woolilisevs lifelsering salife Dosig	Educational Adequacy	1 E8.	2	\$2,722	Rollup	
The Computer Closet Requires Fiber Optic Access to CER	Functional Deficiency	400 LF	2	\$9,000	Rollup	
	Sub Total for System	3 items		\$15,406		
	Sub Total for Building 06 - Building 6	40 items		\$880,793		
Deficiency The Exterior Security Camera is Damaged And Should Be Replaced	Category Capital Renewal	Qty UoM 4 Ea.	Priority 2	Repair Cost \$15,777	ID 71851	
The Exterior Security Carriera is Damaged And Should be Replaced	Sub Total for System	0 items	-	\$15,777	7 103 1	
6:4-		0 1101110		¥10,111		
Site						
Deficiency The Canopy Lighting Is Missing And Needed	Category Functional Deficiency	Qity UoM 6 Ea.	Priority 2	Repair Cost \$12,307	ID 71848	GOB
The Callopy cignling is Missing And Needed The Mounted Building Lighting Is Damaged And Should Be Replaced	Capital Renewal	13 Ea.	2	\$12,717	71850	GOB
The Modified Ballating Eighting is Dalhaged And Orload Bettepraced	Sub Total for System	2 items		\$25,025	7 1000	000
Poofing				,,,		
Roofing	0.1					
Deficiency Reroofing Required (Broward CPS)	Category Capital Renewal	Qty UoM 5,024 SF	Priority 2	Repair Cost \$52,697	ID 223673	GOB
Relocaling Required (Drowald CP-3)	Sub Total for System	1 items	- 4	\$52,697	223073	000
Interior				¥02,001		
Interior						
Deficiency The Associated Collins Title Boards Boards	Category	Qty UoM	Priority	Repair Cost	ID 74050	
The Acoustical Ceilings Tiles Require Replacement	Capital Renewal	750 SF	3	\$4,148 \$4,148	74059	
A. a. b. a. d. a. d.	Sub Total for System	1 items		94,140		
Mechanical						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
Controls Are Inadequate And Should Be Replaced With DDC Controls	Capital Renewal	5,024 SF	3	\$21,010	73529	GOB
Duct Heater Requires Replacement	Capital Renewal	1 Ea.	3	\$5,122	73537	GOB
Test And Balancing Required	Deferred Maintenance	5,024 SF	3	\$6,909	73527	GOB
The Air Handler HVAC Component Requires Replacement	Capital Renewal	1 Ea.	3	\$55,060	73536	GOB
The Small Diameter Exhausts/Hoods Require Replacement	Deferred	2 Ea.	3	\$4,959	73524	GOB
Duct Classing Paguired	Maintenance Deferred	5,024 SF	5	21 111	73533	
Duct Cleaning Required	Maintenance	0,024 SF	J	\$4,141	10000	
	Sub Total for System	6 items		\$97,200		
Electrical						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	

Rev 1 Sept 2014 M-A-P-P-S ©, Jacobs 2014 Fairway Elementary School

1641

Page 10 of 14



School Deficiency Listing

P-0016xx RFQ Number: 16-182C

Broward County Public Schools

9/2/2014 9:08 AM Fairway Elementary School Building: 07 - Building 7 **Electrical** Qty UoM Repair Cost Category Emergency Lighting Is Inadequate Or Not Present And Should Be Installed Code Compliance 5,024 SF \$7,932 71853 GOB \$7.932 Sub Total for System 1 items Technology Category Deficiency The Computer Closet Requires Fiber Optic Access to CER Functional Deficiency 400 LF \$9,000 Rollup Sub Total for System 1 items \$9,000 Sub Total for Building 07 - Building 7 12 items \$211,778 Building: 08 - Storage Category Qtv UoM Priority Repair Cost ID The Exterior Security Camera Is Damaged And Should Be Repaired Deferred Maintenance \$927 71856 Sub Total for System 0 items \$927 Site Deficiency Qtv UoM Priority Repair Cost The Mounted Building Lighting Is Missing And Needed Functional Deficiency 4 Ea. \$6,883 71855 Sub Total for System 1 items \$6,883 Roofing Deficiency Category Qty UoM Priority Repair Cost Reroofing Required (Broward CPS) Capital Renewal 523 SF \$5,486 223674 GOB Sub Total for System 1 items \$5,486 Mechanical Category Deficiency Qty UoM Priority Repair Cost Exhaust Fan Ventilation Requires Replacement Capital Renewal \$4,134 73584 GOB 2 Ea. Duct Cleaning Required Deferred Maintenance 549 SF \$452 73585 Sub Total for System 2 items \$4,586 Sub Total for Building 08 - Storage \$17,882 4 items Building: 75 - Classroom Priority Repair Cost The Exterior Security Camera Is Damaged And Should Be Replaced Capital Renewal 6 Ea. \$23,152 71859 Sub Total for System 0 items \$23,152 Site Qtv UoM Repair Cost The Mounted Building Lighting Is Missing And Needed Functional Deficiency \$13,467 71858 GOB 8 Ea. Sub Total for System 1 items \$13,467 Roofing Deficiency Qtv UoM Category Reroofing Required (Broward CPS) \$136,652 223675 Capital Renewal 13,028 SF Sub Total for System 1 items \$136,652 Structural Qtv UoM Category The Stucco Exterior Requires Repair Deferred 15,260 SF Wall \$105,285 74062 Maintenance Sub Total for System \$105,285 Exterior Deficiency Category Qty UoM Priority Repair Cost Rev 1 Sept 2014 Fairway Elementary School 1641

Page 11 of 14

M-A-P-P-S ©, Jacobs 2014

School Deficiency Listing

9/2/2014 9:08 AM

1641 Fairway Elementary School

Building: 75 - Classroom

Exterior

Exterior							
Deficiency	Category		UoM	Priority	Repair Cost	ID	
The Exterior Requires Painting	Capital Renewal		SF Wall	3	\$52,062	74061	GOB
he Exterior Requires Cleaning	Deferred Maintenance	15,260	SF Wall	5	\$29,609	74060	
	Sub Total for System	2	items		\$81,671		
Interior							
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID	
The Acoustical Ceilings Tiles Require Replacement	Capital Renewal	3,000	SF	3	\$16,230	74063	
The Ceramic Tile Flooring Requires Replacement	Capital Renewal	50	SF	3	\$854	74066	
Room has insufficient tackboard area.	Educational Adequacy	9	Ea.	4	\$3,468	Rollup	
Room lacks appropriate amount of teacher storage.	Educational Adequacy	10	Ea.	4	\$6,048	Rollup	
Interior Ceramic Walls Require Repainting	Deferred Maintenance	200	SF Wall	5	\$510	74065	
Interior Gypboard Walls Require Repainting	Deferred Maintenance	9,800	SF Wall	5	\$31,691	74064	
	Sub Total for System	6	items		\$58,803		
Mechanical							
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID	
The Exterior Condenser Requires Replacement	Capital Renewal		Ea.	1	\$4,036	73601	GOB
The Package Unit HVAC Component Requires Replacement	Capital Renewal	4	TonAC	3	\$9,214	73605	GOB
Ouct Cleaning Required	Deferred Maintenance	11,728	SF	5	\$9,456	73602	
	Sub Total for System	3	items		\$22,706		
Electrical							
Deficiency	Category	Otv	UoM	Priority	Repair Cost	ID	
Emergency Exit Signage Requires Replacement	Deferred		Ea.	2	\$3,518	71863	GOB
	Maintenance	44.700	0.5		*10.111	71000	
Emergency Lighting Is Inadequate Or Not Present And Should Be Installed		11,728		2	\$18,114	71862	GOB
The GFCI Electrical Receptacles Are Inadequate And More Are Needed	Deferred Maintenance	٥	Ea.	2	\$3,258	71864	GOB
Panelboard is not Labeled per code	Code Compliance	8	Ea.	3	\$2,683	71860	
	Sub Total for System	4	items		\$27,573		
Technology							
Deficiency	Category	Qtv	UoM	Priority	Repair Cost	ID	
Room lacks Fixed Projector	Educational Adequacy	10	Ea.	2	\$36,842	Rollup	
Room lacks Interactive White Board	Educational Adequacy	10	Ea.	2	\$27,217	Rollup	
The Computer Closet Requires Fiber Optic Access to CER	Functional Deficiency	400	LF	2	\$9,000	Rollup	
	Sub Total for System	3	items		\$73,059		
Specialties							
■ Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID	
Blinds are missing or in poor condition.	Educational Adequacy	600		4	\$16,952	Rollup	
Room does not have sufficient cubbies.	Educational Adequacy	146	Ea.	5	\$6,084	Rollup	
Room has an insufficient number of coat hooks.	Educational Adequacy	184	Ea.	5	\$2,132	Rollup	
	Sub Total for System	3	items		\$25,169		

Rev 1 Sept 2014 M•A•P•P•S ©, Jacobs 2014 Fairway Elementary School

1641

Page 12 of 14



Fairway Elementary School

School Deficiency Listing

9/2/2014 9:08 AM

Building: 78 - Classroom

Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
he Exterior Security Camera Is Damaged And Should Be Replaced	Capital Renewal	4 Ea.	2	\$15,435	71867	
	Sub Total for System	0 items		\$15,435		
Site						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
he Mounted Building Lighting Is Missing And Needed	Functional Deficiency	4 Ea.	2	\$6,733	71866	GOE
	Sub Total for System	1 items		\$6,733		
nterior						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
Room has insufficient tackboard area.	Educational Adequacy	4 Ea.	4	\$1,541	Rollup	
Room lacks appropriate amount of teacher storage.	Educational Adequacy	2 Ea.	4	\$1,210	Rollup	
	Sub Total for System	2 items		\$2,761		
Mechanical						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
The Exterior Condenser Requires Replacement	Capital Renewal	1 Ea.	1	\$4,036	73626	GOE
The Exterior Electrical Enclosure Is Darmaged And Should Be Repaired	Deferred Maintenance	200 Ea.	3	\$90,372	71868	
The Package Unit HVAC Component Requires Replacement	Capital Renewal	4 TonAC		\$9,214	73628	GOE
Ouct Cleaning Required	Deferred Maintenance	2,016 SF	5	\$1,625	73627	
	Sub Total for System	4 items		\$105,248		
Electrical						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
Emergency Exit Signage Is Missing And Needed	Deferred Maintenance	2 Ea.	2	\$2,122	71870	GOB
Emergency Lighting Is Inadequate Or Not Present And Should Be Installed	Code Compliance	2,016 SF	2	\$3,114	71869	GOE
The GFCI Electrical Receptacles Are Inadequate And More Are Needed	Deferred Maintenance	2 Ea.	2	\$815	71871	GOE
	Sub Total for System	3 items		\$6,050		
Technology						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
Room lacks Fixed Projector	Educational Adequacy	2 Ea.	2	\$7,368	Rollup	
Room lacks Interactive White Board	Educational Adequacy	2 Ea.	2	\$5,443	Rollup	
	Sub Total for System	2 items		\$12,812		
Specialties						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
Room does not have sufficient cubbies.	Educational Adequacy	8 Ea.	5	\$332	Rollup	
Room has an insufficient number of coat hooks.	Educational Adequacy	48 Ea.	5	\$556	Rollup	
	Sub Total for System	2 items		\$888		
Sub To	otal for Building 78 - Classroom	14 items		\$149,917		
Building: 80 - Classroom						
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID	
The Exterior Security Camera Is Damaged And Should Be Replaced	Capital Renewal	4 Ea.	2	\$15,435	71880	
	0.1.7.1.5.0.1	a :		A45 405		
	Sub Total for System	0 items		\$15,435		

Rev 1 Sept 2014 M•A•P•P•S ©, Jacobs 2014 Fairway Elementary School

1641

Page 13 of 14



School Deficiency Listing

9/2/2014 9:08 AM Fairway Elementary School Building: 80 - Classroom Site Deficiency Qty UoM Priority Category Repair Cost The Mounted Building Lighting Is Missing And Needed Functional Deficiency 8 Ea. \$13,467 71879 GOB Sub Total for System \$13,467 1 items Roofing Qty UoM Deficiency Category Repair Cost Roof Equipment requires Cabling Code Compliance 4 Ea. \$699 223677 Sub Total for System \$699 1 items Interior Deficiency Category Qty UoM Room has insufficient tackboard area. Educational 16 Ea. \$6,166 Rollup Adequacy Room lacks appropriate amount of teacher storage Educational 40 Ea. 4 \$24,193 Rollup Adequacy Sub Total for System 2 items \$30,358 **Electrical** Category Qty UoM Priority Repair Cost Deferred Maintenance Emergency Exit Signage Requires Replacement 6 Ea \$4,221 71884 GOB Emergency Lighting Is Inadequate Or Not Present And Should Be Installed Code Compliance 9.391 SF 2 \$14,505 71882 GOB The GFCI Electrical Receptacles Are Inadequate And More Are Needed Deferred 8 Ea. 2 \$3,258 71886 GOB Maintenance \$6,235 Rollup Room lacks controls to partially dim lights. Educational 5 8 Ea. Sub Total for System \$28,219 4 items Technology Qty UoM Category Repair Cost Educational Adequacy Room lacks Fixed Projector 8 Ea. \$29,474 Rollup Room lacks Interactive White Board Educational 6 Ea. 2 \$16,330 Rollup The Computer Closet Requires Fiber Optic Access to CER Functional Deficiency 400 LF 2 \$9.000 Rollup Sub Total for System 3 items \$54,803 **Specialties** Repair Cost Category Qty UoM Priority 480 SF Surf Blinds are missing or in poor condition Educational 4 \$13,562 Rollup Adequacy Room does not have sufficient cubbies Educational 208 Ea. 5 \$8,668 Rollup Adequacy Room has an insufficient number of coat hooks Educational 192 Ea. \$2,226 Rollup Sub Total for System \$24,455 3 items

Rev 1 Sept 2014 M•A•P•P•S ©, Jacobs 2014 Fairway Elementary School

14 items

267 items

1641

Page 14 of 14

\$167,437 \$8.842.703

\$8,842,703

\$0

Sub Total for Building 80 - Classroom

Total for Permanent Buildings

Total for Portable Buildings

Total for Campus

2.4.4 MAPPS Deficiency Data

6	809	808	800		80 80 80 80			800	808 808	808		809	800	809 809	80 80 80 80	80 B	508 G08	808	808 808			508 508	
	TTL Cost	\$72,68	\$74,738	\$10,458	\$8.58 \$6	\$21,284	\$3,687	\$1,688	38,38	ä	24,400	\$1,689	87.78	\$8,005	\$8,36	\$25,229	786,88	\$2 PM	\$12,063	\$5,58	\$12,556	\$2,900	\$2,123
27 28	Quantity Unit	6 Ea.	14 E3.	S Ea.	6 Ea.	13208 SF	5 Ea.	4 E3.	6 E3	85 87	6 Ea.	4 Ea.	4 Ea.	4 Ea.	6 Ea.	15671 SF	8 Ea.	6 Ea.	6 Ea.	6 Ea.	7799 SF	4 Ea.	S Ea.
23	Priority Description Qu	2 Indirect Impact to Mission (1 Year)	2 Indirect Impact to Mission (1 Year)	2 Indirect Impact to Mission (1 Year)	2 Indirect Impact to Mission (1 Year)	2 Indirect Impact to Mission (1 Year)	2 Indirect Impact to Mission (1 Year)	2 indirect impact to Mission (1 Year)	2 Indirect Impact to Mission (1 Year)	2 Indirect Impact to Mission (1 Year)	2 Indirect Impact to Mission (1 Year)	2 Indirect Impact to Mission (1 Year)	2 Indirect Impact to Mission (1 Year)	2 Indirect Impact to Mission (1 Year)	2 Indirect Impact to Mission (1 Year)	2 Indirect Impact to Mission (1 Year)	2 Indirect Impact to Mission (1 Year)	2 Indirect Impact to Mission (1 Year)	2 Indirect Impact to Mission (1 Year)	2 Indirect Impact to Mission (1 Year)	2 Indirect Impact to Mission (1 Year)	2 Indirect Impact to Mission (1 Year)	2 indirect impact to Mission (1
21	Category Priority Description	Functional Deficiency	Capital Renewal	Functional Deficiency	Capital Renewal	Code Compliance	Deferred Maintenance	Deferred Maintenance	Capital Renewal	Code Compliance	Deferred Maintenance	Deferred Maintenance	Deferred Maintenance	Deferred Maintenance	Capital Renewal	Code Compliance	Deferred Maintenance	Deferred Maintenance	Deferred Maintenance	Capital Renewal	Code Compliance	Deferred Maintenance	Deferred
	Uniformat Description	Parking Lot Lighting	Parking Lot Lighting	Flood Lighting	Flood Lighting	Lighting Fixtures	Lighting Fixtures	Facility Grounding	Flood Lighting	Lighting Fixtures	Lighting Fixtures	Facility Grounding	Flood Lighting	Flood Lighting	Flood Lighting	Lighting Fixtures	Lighting Fixtures	Facility Grounding	Flood Lighting	Flood Lighting	Lighting Fixtures	Lighting Fixtures	Facility Grounding
14	ysem Name	lectrical	Bectrical	Slectrical	Slectrical	ire and Security	ire and Security	Sectrical	Slectrical	lire and Security	ire and Security	Sectrical	Sectrical	Electrical	Sectrical	ire and Security	ire and Security	Sectrical	Electrical	Slectrical	ire and Security	fire and Security	Electrical
13	SytemID	7	7	7 8	10 10	6	6	E .	7 8	e e	6	7 8	18	7	7 81	<u>г</u>	6	F.	7	F.	in	6	7
co.	Deficiency Description Def Note	The Pole Lighting is Missing And Needed	The Pole Lighting Is Damaged And Shauld Be Replaced	The Canopy Lighting is Missing And Needed	The Mounte d Building Lighting is Damages And Should Be Replaced	Emergency Lighting is insdequate Or Not Present And Should Be installed	Emergency Exit Signage Requires Replacement	The GFCI Electrical Receptations Ave Inadequate And More Are	The Mounte o Building Lighting is Damaged And Should Be Replaced	Emergency Lighting is madequate Or Not Present And Should Be finfalled	Emergency Exit Signage Requires Replacement	The GFCI Electrical Recognitions Are Inadequate And More Are Needed	The Canopy Lighting Requires Replacement	The Canopy Lighting Requires Replacement	The Mounted Building Lighting is Damaged And Should Be Replaced	Emergency Lighting is and addiquate Or Not Present And Snould Be installed	Emergency Exit Signage Requires Replacement	The GFCI Electrical Receptacles Ave Inadequate And More Are	The Canopy Lighting Requires Replacement	The Mounted Building Lighting is Damaged And Should Be Replaced	Emergency Lighting Is insdequate On Not Present And Should Be	Emergency Exit Signage Requires Replacement	The GFCI Electrical
	Building Name	Classroom	Classroom		Classroom	Classroom	Classroom	Classroom	Classroom	Classroom	Classroom	Classroom		Classroom	Classroom	Classroom	Classroom	Classroom	Building 4	Building 4	Buiding 4	Buiding 4	Building 4
2	Building Number	10	10	б	ы	10	Б	5	8	25	20	20		83	83	88	22	8	B	8	8	B	8
3	Site Name	arway Elementary chool	Farway Elementary School	Farmay Elementary School	nway Elementary nool	Fairway Elementary School	anway Elementary	Farway Bernentary School	Faiway Elementary School	Farway Elementary School	Farway Elementary School	Farway Elementary School	aiway Elementary chool	way Elementary col	Farway Elementary School	Fanway Elementary School	way Elementary ool	Panway Elementary School	Farway Elementary School	Farway Elementary School	Farway Bementary School	anway Elementary School	2 Fairway Elementary

1897 Farway Elementary 05 Building Building 05 05 05 05 05 05 05 0	Perciency Description The Canopy Lighting Is The Massing January Heeged The Mountain Heeged The Mountain Lighting Is before the Straud Be Repaired Energy Lighting Is before the Straud Be Repaired Energy Lighting Is before the Straud Be Ferry And Should Be Ferry And	System Name 2 Sectrical 2 Sectrical 3 Sectrical 9 Fire and Security 9 Fire and Security 7 Sectrical	Uniformat Description Flood Lighting Flood Lighting	Category Priority Description Functional Deficiently Capital Renewal	Priority Description 2 Indirect Impact to Mission (1 Year) 2 Indirect Impact to Mission (1 Indirect Impact Imp	Quantity Unit 9 E3.	\$18,461 GOB
Name of Building 5 School Favory Beneritary 05 School Favory Beneritary 05 School Favory Beneritary 05 Favory Beneritary 05 Favory Beneritary 05 School Favory Beneritary 07 Favory Beneritary	Massing Audituring is Massing Audituring is Massing Audituring is The Nounced Bellating Ustman is Dama and Massing Audituring is The earth And Should Be Requires Englatement in The Nounced Bellating in Carango Ustman is Dama and Massing Audituring is Dama and Audituring is Dama and Massing is Dama and Massing Audituring is Dama and Massing	7 Electrical 7 Electrical 9 The and Security 9 The and Security 7 Electrical 7 Electrical	- Bu	on f enewal	2 2		
Farway Benetriany 05 Building 5 School Senetriany 05 Building 5 School Senetriany 05 Building 5 School Senetriany 05 Building 6 School	Missing Authorities in Missing Authorities in Missing Authorities in Park Authorities in Park Authorities in Smort die Repraced Auffrag is Genegency, Buldfreg is Genegency, Buldfreg is Fersert And Should Be Repraced Child Resert And Should Be Repraced Child Resert And Should Be Require Sequence Signate Recognite Sequence of Missing Australia (2) The Norwing Buldfreg is Character and Should Be Registed And Stould Be Registed And Stou	7 Electrical 7 Electrical 9 Fire and Security 9 Fee and Security 7 Electrical 7 Electrical		unchanal periolency apital Renewal	2 Indirect Impact to Misson (1 Year) 2 Indirect Impact to Mission (1		
School Benetrary 05 Building 5 School Benetrary 05 Building 5 School Benetrary 05 Building 5 School Building 6 School Benetrary 05 Building 6 School Building 7 School Building 8 School Building 8 School Building 9 School Buildin	The Nouvegellaling The Nouvegellaling Should Be Replace Should Be Replace Emergency Lighting Is Invasepale of roll of Presert And Should Be Replace of the Nouvegellaling This change of the Nouvegellaling Missing And Need bit Missing And Need bit Missing And Need bit Missing And Need bit The Nouvegellaling Should Be Replaced Should Be Replaced Emergency Lighting Is Fresert And Should Be Fresere	7 Section 9 The and Security 9 The and Security 7 Section 7 Section		apital Renewal	2 Indirect Impact to Mission (1	16 E3.	
School Servicy Elementary 05 Building 6 School School Building 6 School Building 6 School Building 6 School Building 7 School Bui	er eregency. Lighting is most grant of the interaction of the interact	9 Fire and Security 9 Fire and Security 7 Electrical 7 Electrical	Ť		Year)		\$16,662 GDB
School Benetrary 05 Building 5 School Benetrary 05 Building 6 School Building 6 School Building 6 School Building 7 S	ein regency Exc. (Signage Rocques Seguiscenent The Canopy Uptimog is The Canopy Uptimog is The Nounde Bellering Missing And Needeel Missing And Ne	9 Fire and Security 7 Electrical 7 Electrical		Code Compliance	2 Indirect Impact to Mission (1 Year)	18461 SF	
Service Beneartay 06 Building 6 Service Beneartay 07 Building 7 Service Building 7 Se	The Canopy Lighting is Missing Audit Weeter Missing Aud Needer Missing Aud Needer Missing Aud Needer Missing Aud Needer Missing Audit Needer Missing Audit Missing Audit Be Registed Audit Be Registed Audit Be Registed Cit Needer And Should Be Re	7 Electrical 7 Electrical	Lighting Fixtures	Deferred Maintenance	2 Indirect Impact to Mission (1 Year)	6 Ea.	\$4,315 GOB
School Benetrary 06 Building 6 School Benetrary 06 Building 6 School Building 6 School Benetrary 06 Building 6 School Building 6 School Building 7 School Bu	The Nounded Building Should Be Replaced Should Be Replaced Should Be Replaced Feer And Should Be Feer Bedong	7 Electrical		Functional Defidency	2 Indirect Impact to Mission (1 Year)	12 Ea.	\$24,615
School Seneratary 06 Building 6	Erreptory Lydfird Is Freeser And Should Be Freeser And Should Be Erreptory Erreptory Strange Stranger of Erreptory Brown The Great The Great Sections		Flood Lighting	Capital Renewal	2 Indirect Impact to Mission (1 Year)	14 Ea.	\$13,696
School Benetray 06 Building 6 School Building 6 School Building 7 School Benetray 07 School Building 7	Emergency Exit Signage Requires Replacement The GFC! Electrical	9 Fire and Security	Lighting Flictures	Code Compliance	2 Indirect Impact to Mission (1 Year)	16053 SF	\$25,344
School Building 6	The GFCI Electrical	9 Fire and Security		Deferred Maintenance	2 Indirect Impact to Mission (1 Year)	6 Ea.	\$4,315 GOB
Building 7 Building 7 Building 7 Building 7 Building 7 Building 7 School Building 7 Building 7 School Building 7	Receptables Are Inadequate And More Are Nected	7 Electrical	Bug	Deferred Maintenance	2 Indirect Impact to Mission (1 Year)	6 Еа.	\$2,498 608
School Sc	The Canopy Lighting Is Missing And Needed	7 Electrical	FloodLighting	Functional	2 Indirect Impact to Mission (1 Year)	6 Ea.	\$12,307
Fairway Elementary 07 Building 7 School	The Mounted Building Lighting is Damaged And Snould Be Repisced	7 Electrical	Flood Lighting	apital Renewal	2 Indirect Impact to Misson (1 Year)	13Ea.	\$12,717
	Emergency Lighting is Imasequate Or Not Present And Should Be Installed	9 Fire and Security	Ughting Fixtures	Code Compliance	2 Indirect Impact to Misson (1 Year)	5024 SF	\$7, 502
Storage Storage School	The Mounted Building Lighting Is Missing And Needed	7 Electrical	Flood Lighting	Functional	2 Indrect Impact to Mission (1 Year)	4 Ea.	\$6,883
75 Classroom	The Mounted Building Lighting Is Missing And Needed	7 Electrical		Functional Deficiency	2 Indirect Impact to Mission (1 Year)	8 E3.	\$13,467
School Classroom School	Enegercy Lighting is Insateguate Or Not Inseart And Should Be Installed	9 Fire and Security		Code Compliance	2 Indirect Impact to Mission (1 Year)	11728 SF	\$18,114
Fairway Elementary 75 Classroom School	Emergency Exit Signage Requires Replacement	9 Fire and Security	Lighting Fixtures	Deferred Maintenance	2 Indirect Impact to Mission (1 Year)	5 Ea.	809 608
. 75 Classroom	The GFCI Electrical Receptates Are Insocquate And More Are Needeg	? Electrical	gug	Deferred Maintenance	2 Indirect Impact to Mission (1 Year)	8 Ea.	\$3,258 608
School	The Mounted Building Lighting Is Missing And Needed	? Electrical		Functional Deficiency	2 Indrect Impact to Mission (1 Year)	4 E3.	96,733
78 Classroom	Enegercy Lighting is Insafequale Or Not Present And Should Be Installed	9 Fire and Security		Code Compliance	2 Indirect Impact to Mission (1 Year)	2016 SF	\$3,114 608
Fairway Elementary 78 Classroom School	Emergency Exit Signage Is Missing And Needed	9 Fire and Security		Deferred Maintenance	2 Indirect Impact to Mission (1 Year)	2 Ea.	\$2,122 GOB
	The GFCI Electrical Receptacles Are Inadequate And More Are	7 Electrical	Facility Grounding	Deferred Maintenance	2 Indirect Impact to Mission (1 Year)	cs Ea	\$815

_					9	3	P		77	07	97	
Dof Breeze	Ste Name	Building	Suildien Manne	Deficiance Description		Sussem Name	Indormat	Catanone	i		- Period	11 Cont
	DI INC.) Activities of	Description					809
71879 Fa	Fairway Elementary School	8	Classroom	The Mounted Building Lighting Is Missing And Needed	13	Electrical	Flood Lighting	Functional Deficiency	2 Indirecti Year)	ndrect Impact to Mission (1 rear)	8 E3.	\$13,467
71882 Fa	Fairway Elementary School	8		Emergency Lighting is inadequate Or Not Present And Should Be installed	6	ire and Security	Lighting Fixtures	Code Compliance	2 Indrect Year)	ndrettimpact to Mission (1 Year)	9391 SF	\$14,505
71884 Fa	ainway Elementary chool	08		Emergency Exit Signage Requires Replacement	on on	ire and Security	Ughting Fixtures	Deferred Maintenance	2 Indirect Year)	ndirect Impact to Mission (1 'ear)	6 Ea.	
71886 Fa	School	8	Classroom	The GFCI Electrical Receptacies Are Inadequate And More Are Needed	2	Electrical	Facility Grounding	Deferred Maintenance	2 Indirect Year)	ndirect Impact to Mission (1 Year)	8 E3.	88
73272 Fai	Fairway Elementary School	10		The 2 X 2 Exhausts/Hoods Require Replacement	9	Mechanical	Exhaust Air	Deferred Maintenance	2 Indirect Year)	ndirect Impact to Mission (1 Year)	2 Ea.	\$13,486
73273 Fa	Painway Elementary School	10		Package Roof Top Unit Requires Replacement	9	Mechanical	Decembalized	Capital Renewal	3 Short Te Years)	Short Term Conditions (2-3 Years)	1 Ea.	\$18,026 GOB
73274 Fa	ainway Elementary shool	10		Exhaust Fan Ventilation Requires Replacement	6 M	Mechanical	Decembalized Coaling	Capital Renewal	3 Short Te Years)	Shart Term Conditions (2-3 (ears)	1 Ea.	
73276 Fa	Fairway Elementary School	10		Controls Are Inadequate And Should Be Replaced With DDC Controls	9	Wechanical	Decentralized Cooling	Capital Renewal	3 Short Te Years)	Short Term Conditions (2-3 Years)	13208 SF	\$56,324
73279 Fa	Fairway Elementary School	10		The Air Handler HVAC Component Requires Replacement	9	Mechanical	Decentralized Coding	0	3 Short Te Years)	Short Term Conditions (2-3 Years)	- E3.	\$56,145 GOB
73281 Fa	Fairway Elementary School	10		Duct Heater Requires Replacement	9	Mechanical	Decentralized Heating Equipment		3 Short Te Years)	Short Term Conditions (2-3 Years)	1 Ea.	
73296 Fa	ainway Elementary Shool	20		Complete HVAC System Wide Replacement	9	Mechanical	Decentralized	Capital Renewal	2 Indirect Year)	ndirect Impact to Mission (1 (ear)	13191 SF	\$446,107
73314 Fa	ainway Elementary	8		Test And Balancing Required	9	Aechanical	Decentralized	Deferred Maintenance	3 Short Te	Short Term Conditions (2-3 Years)	15671 SF	\$21,977 GOB
73315 Fa	School	88	Classroom	Controls Are Inadequate And Should Be Replaced With DDC Controls	S S	Mechanical	Decentralized	Capital Renewal	3 Short Te Years)	Short Term Conditions (2-3 Years)	15671 SF	\$58,827
73317 Fa	Farway Elementary School	89		The Air Handler HVAC Component Requires Replacement	9	Wechanical	Decentralized Coding	Capital Renewal	3 Short Te Years)	Short Term Conditions (2-3 Years)	3 Ea.	
73318 Fa	ainway Elementary shool	83		Duct Heater Requires Replacement	9	Mechanical	Decentralized Heating Equipment	Capital Renewal	3 Short Years)	Short Term Conditions (2-3 Years)	3 Ea.	
73335 Fa	Fairway Elementary School	3		The 2 X 2 Exhausts/Hoods Require Replacement	9	Mechanical	Exhaust Air	Deferred Maintenance	2 Indirect Year)	ndrect Impact to Mission (1 Year)	2 Ea.	
73336 Fa	Fainway Elementary School	8		Package Roof Top Unit Requires Replacement	9	Mechanical	Decentralized Coding	Capital Renewal	3 Short Te Years)	Short Term Conditions (2-3 rears)	1 Ea.	
73338 Fai	ainway Elementary chool	04		Test And Balancing Required	9	Mechanical	Decembralized Cooling	Deferred Maintenance	3 Short Te Years)	Short Term Conditions (2-3 Years)	7799 SF	\$10,907 608
73339 Fa	School School	8	Bulding 4	Controls Are Inadequate And Should Be Replaced With DDC Controls	<u>s</u>	Mechanical	Decentralized	Capital Renewal	3 Short Te Years)	Short Term Conditions (2-3 Years)	7799 SF	805)
73341 Fa	Fairway Elementary School	8	Bulding 4	The Air Handler HVAC Companent Requires Replacement	9	Mechanical	Decentralized	Capital Renewal	3 Short Te Years)	Short Term Candidons (2-3 Years)	 Eg.	\$56,145 GOB
73342 Fa	Fainway Elementary School	8		Duct Heater Requires Replacement	9	Mechanical	Decentralized Heating Equipment	Capital Renewal	3 Short Te Years)	Short Term Conditions (2-3 rears)	1 Ea.	
73348 Fa	ainway Elementary Shool	88	Building 5	Test And Balancing Required	9	Aechanical	Decentralized Coding	Deferred Maintenance	3 Short Te Years)	Short Term Conditions (2-3 rears)	18461 SF	\$256,389 GOB
73349 Fa	ainway Elementary chool	8	Bulding 5	Controls Are inadequate And Should Be Replaced With DDC Controls	<u>v</u>	Mechanical	Decembalized	Capital Renewal	3 Short Te Years)	Short Term Conditions (2-3 Years)	18461 SF	\$77,203
73351 Fa	Fairway Elementary School	90		The Air Handler HVAC Component Requires Replacement	9	Aechanical	Decentralized Codling		3 Short Te Years)	Shart Term Conditions (2-3 Years)	2 Ea.	
73352 Fa	73352 Fainvay Elementary	99	Districts	Dune George Desiration	2	Wechanical	Canantralizad	Capital Renewal	2 Short Le	Shart Tarm Contilions (2.3	2 E3	\$10.043

	809	808		809	808		1-		809	808	809	809	809	808	808	809				808	SOB	808	809	808	809	809	808	
24	TTL Cost	\$13,228	\$2,067	\$50,751	\$22,078	\$67,133	\$56,060	\$6,122	\$4,969	806'98	\$21,010	\$66,060	\$6,122	\$4,134	\$4,836	\$9,214	\$4,00	\$8,214	\$52,062	\$105,285	\$290,696	\$168,736	\$169,186	\$139,546	\$4,88	\$190,639	\$168,382	\$62,697
	ity Unit	2 Ea.	1 E3.	1E3.	16053 SF	16063 SF	- Ea	1 Ea.	2 Ea.	5024 SF	5024 SF	- E3.	- Ea	2 Ea.	- Ea	4 TonAC	1Ea	4 TonAC	15260 SF Wall	15260 SF Wall	11.5	13046 SF	13083 SF	16400 SF	7799 SF	18461 SF	16053 SF	5024 SF
24	ption Quantity	to Mission (1	Term Conditions (2-3	to Mission (1	of fons (2-3	erm Candillons (2-3	ndrijons (2-3	nditions (2-3	1010ns (2-3	nd/forms (2-3	nations (2-3	adillons (2-3	10/10/ns (2-3	nd floms (2-3	Concerns	nd/lons (2-3	Cancems	ndillons (2-3	10 Tons (2-3	ndrifons (2-3	Concerns	to Mission (1	to Mission (1	to Mission (1	to Mission (1	to Mission (1	to Mission (1	to Mission (1
	Priority Description	2 Indrect Impact to Mission (1 Year)	3 Short Term Cor Years)	2 Indirect Impact to Mission (1 Year)	3 Shart Term Conditions (2-3 Years)	3 Short Term Cor Years)	3 Short Term Conditions (2-3 Years)	3 Short Term Conditions (2-3 Years)	3 Short Term Conditions (2-3 Years)	3 Short Term Conditions (2-3 Years)	3 Short Term Conditions (2-3 Years)	3 Short Term Conditions (2-3 Years)	3 Shart Term Conditions (2-3 Years)	3 Shart Term Conditions (2-3 Years)	1 Mission Critical Concerns	3 Short Term Conditions (2-3 Years)	1 Mission Critical Concerns	3 Short Term Conditions (2-3 Years)	3 Short Term Conditions (2-3 Years)	3 Short Term Conditions (2-3 Years)	1 Mission Critical Concerns	2 Indirect Impact to Mission (1 Year)	2 Indirect Impact to Mission (Year)	2 Indirect Impact to Mission (Year)	2 Indirect Impact to Mission (Year)	2 Indirect Impact to Mission (1 Year)	2 Indirect Impact to Mission (1 Year)	2 Indirect Impact to Mission (1
•	Priority on	931	snewal		J.C.	snewal	enewal	enewal	e0.	an.	enewal	enewal	snewal	mewal	snewai	enewal	snewal	sneval	snewal	ice .	enewal	enewal	enewal	enewal	enewal	enewal	enewal	Showal
	Category Description	Deferred Maintenance	l	l	Deferred Maintenance		Capital Renewal	Capital Renewal	Deferred Maintenance	Deferred Maintenance	Capital Renewal	Capital Renewal	0				- Capital Renewal	Capital Renewal	Capital Renewal	С		iding Capital Renewral	rling Capital Renewa	iling Capital Renewal	rling Capital Renewa	ifing Capital Renewal	ifing Capital Renewal	Ow-Stone Roofing Capital Benevial
	Uniformat Description	Exhaust Air	Decentralized	Exhaust Air	Decentralized	Decentralized Cooling	Decembalized Coding	Decentralized Heating Equipn	Exhaust Air	Decentralized	Decembalized	Decentralized	Decentralized Heating Equipment	Decentralized	Evaporative Air- Cooling	Decentralized Coding	Evaporative Air- Cooling	Decentralized Coding	Exterior Wall Veneer	Perimeter Insulation	Fire Detection and Alarm	Low-Slape Roafing	Law-Stape Roafing	Low-Sigpe Roofing	Low-Stope Roofing	Low-Stope Roofing	Low-Stope Roofing	Low-Stone Dec
ı	System Name	Aechanical	Aechanical	Aechanical	Aechanical	Aechanical	Aechanical	Aechanical	Aechanical	Mechanical	Aechanical	Wechanical	Mechanical	Aechanical	Mechanical	Aechanical	Mechanical	Mechanical	Exterior	Exterior	ire and Security	Roding	Roofing	Roaling	Roafing	Roafing	Roding	Souting
ı	SytemID	9	9	9	9	9	9	9	9	9	9	9	9	9	9	9	9	9	4	4	on .	Ci	64	C	C	22	2	6
	Def Note																				Model: 7100							
п	Deficiency Description	The 2 X 2 Exhausts/Hoods Require Replacement	Exhaust Fan Ventilation Requires Replacement	Kitchen Ain'Exhaust is missing and is needed	Test And Balancing Required	Controls Are Inadequate And Should Be Replaced With DDC Controls	The Air Handler HVAC Component Requires Rediacement	Ouct Heater Requires Replacement	The Small Diameter Exhausts/Hoods Require Replacement	Test.And Balancing Required	Controls Are Inadequate And Should Be Replaced With DDC Controls	The Air Handler HVAC Component Requires Replacement	Duct Heater Requires Replacement	Exhaust Fan Ventilation Requires Replacement	The Exterior Condenser Requires Replacement	The Package Unit HVAC Component Requires Replacement	The Exterior Condenser Requires Replacement	The Package Unit HVAC Component Requires Replacement	The Exterior Requires Painting	The Stucco Exterior Requires Repair	Entire Fire Alarm System Needs to be Replaced	Rerading with new Decking Required (Broward CPS)	Reroding Required (Broward CPS)	Reroding Required (Broward CPS)	Described Decrined			
	Building Name	Bulding 6	Bullding 6	Building 6	Bullding 6	Building 6	Bulding 6	Building 6	3ulding 7	Bullding 7		Building 7	Building 7	Storage	Classroom		Classroam	Classroom		Classroom		Classroom	Classroom	Classroom		Bulding 5	Bullding 6	District 7
Ì	Building Number	90	90	90	90	8	8	90	20	4.0	2.0	20	2.0	80	75	35	38	82	75 0	75 0		10	23	8	8	99	90	2
	Site Name	Fairway Elementary School	Fairway Elementary School	Fairway Elementary School	inway Elementary hool	Fairway Elementary School	Fairway Elementary School	Fairway Elementary School	Fairway Elementary School	Fainvay Elementary School	Fairway Elementary School	Fairway Elementary School	Fainway Elementary School	airway Elementary Ichool	Fainway Elementary School	Fairway Elementary School	Fairway Elementary School	Fairway Elementary School	Fainway Elementary School	Fainway Elementary School	Fairway Elementary School	Fairway Elementary School	Fairway Elementary School	Fairway Elementary School	Fairway Elementary School	Fairway Elementary School	Fairway Elementary School	Patentine Plante and the
	Def Assess Sto	73444 Fai	73445 F3	73447 Fai	73448 Fai	73451 Fail	73456 Fai	73458 Fai	73524 Fal	73527 Fai	73529 Fa	73536 Fa	73537 Fai	73584 Fa	73601 Fal Sct	73605 Fai Sch	73626 Fal	73628 Fail	u or	74052 Fai	220832 Fa	223665 Fa	223667 Fal	223968 Fal	223669 Fai	223670 Fa	223672 Fa	200000 E-

4 of 5

7	

		809		809		809			809			809			809			809			000
07	TTL Cost	0	\$6,486		\$136,662	0	\$31,115			\$29,342			\$11,270		0	\$9,602			\$171,818		
	ž		SF		-SF		SF			PR.			R.			SF			SI		
	Quantity		523 SF		13028 SF		S 9909			4767 SF			1831 SF			1560 SF			-		
24	Priority Description		Indirect Impact to Mission (1	Year)	Indirect Impact to Mission (1	Year)	Indirect Impact to Mission (1	Year)		Indirect Impact to Mission (1	Year)		Indirect Impact to Mission (1	Year)		Indirect Impact to Mission (1	Year)		Indirect Impact to Mission (1	Year)	
4	riority		2		2		2			2			2			2			2		
Ī	Category	Description	Capital Renewal		Capital Renewal		Capital Renewal			Capital Renewal			Capital Renewal			Capital Renewal			Capital Renevral		
02		Description	Low-Stope Roofing Capital Renewal		Low-Stope Roofing Capital Renewal		Canopy Roofing			Canopy Roding			Canopy Roofing			Canopy Roofing			Educational	Enhancement	
	System Name		Roofing		Roofing		Roofing			Roofing			Roofing			Roofing			26 Other		
2	SytemID		2		2		2			2			2			2			88		
2							Originally part of roof replacement	deficiency. Pulled out separate to reflect	covered walk canopy pricing.	Originally part of roof replacement	deficiency. Pulled out separate to reflect	covered walk canopy pricing	Originally part of roof replacement	deficiency. Pulled out separate to reflect	covered walk canopy pricing.	Originally part of roof replacement	deficiency. Pulled out separate to reflect	covered walk canopy pricing.	Room design = 380		
	Deliciency Description Def Note		Reroding Required	(Broward CPS)	Rerouting Required	(Broward CPS)	Aluminum Covered	Walierays Require	Replacement	Aluminum Covered	Wallways Require	Replacement	Aluminum Covered	Wallways Require	Replacement	Auminum Covered	Wallways Require	Replacement	Media Certer requires	renovation based on	
	Building Name		Storage		Classroom									_					Building 4	_	
2	Building	Number	80		75														8		
	Site Name		223674 Fairway Elementary	School	223675 Fairway Elementary	School	314380 Fairway Elementary	School		314381 Fairway Elementary	School		314382 Fairway Elementary	School		314641 Fainvay Elementary	School		316275 Fairway Elementary	School	
-	Der Assess Site Name		223674		223675		314380			314381			314382			314641			316275		

2.4.5 MAPPS Deficiency Detail

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->CR

Deficiency:

290

Assess ID Latasha King 70719 Surveyor/Update

Defeciency Code ID **E01-01**

Status **Estimated** FCI Yes

Life Cycle 22647

Deficiency The Pole Lighting Is Missing And Needed

Fairway Elementary School

Functional Deficiency Electrical Category System

Non Related Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy

Correction Install Pole Lighting Quantity / UoM

Project(s) Note

Estim	ate:				
Type	Number	Description	Qty UoM	Price	Extension
Α	D50102300240	Feeder installation 600 V, including RGS conduit and XHHW wire, 100 A	600 LF	25.80	\$15,480
Α	G40201103120	Site lighting, high pressure sodium, 1000 watt, aluminum pole, 20' high	6 Ea.	3,275.00	\$19,650
U	265613102840	Light poles, anchor base, aluminum, 8' high, excl concrete bases	5 Ea.	930.00	\$4,185
U	312316140200	Excavating, chain trencher, utility trench, common earth, 12 H.P., 4" wide, 24" deep, operator walking	600 LF	0.96	\$576
			Sub Total		\$39,891
		Constru	uction Adjustment	35%	13,762
		Co	onstruction Cost		\$53,653
		A	djustment Factor	0%	0
		Soft	Cost Adjustment	55%	29,316
		Total Es	timated Amount		\$82,970

Fairway Elementary School

290

Page 572 of 624

M-A-P-P-S ©, Jacobs 2016

Broward County Public Schools

Fairway Elementary School

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->CR

Deficiency:

290

Assess ID 70721 Surveyor/Update Latasha King

Defeciency Code ID **E01-03**

Status **Estimated** FCI Yes

Life Cycle

The Pole Lighting Is Damaged And Should Be Replaced Deficiency

Category Capital Renewal System Electrical

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Non Related

Correction Replace Pole Lighting Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
U	260533131870	Rigid galvanized steel conduit, 2" diameter, to 15' H, incl 2 terminations, 2 elbows, 11 beam clamps, and 11 couplings per 100 LF	14 LF	23.00	\$322
U	265613103000	Light poles, anchor base, aluminum, 20' high, excl concrete bases	14 Ea.	1,650.00	\$23,100
U	260505503030	Metal light pole, 20' high, electrical demolition, remove, excl concrete bases	14 Ea.	207.00	\$2,898
U	265636202600	Floodlights, exterior, high pressure sodium, 1000 watt, incl ballast and lamp, excl pole	14 Ea.	1,050.00	\$14,700
			Sub Total		\$41,020
		Constru	iction Adjustment	35%	14,152
		Co	nstruction Cost		\$55,172
		A	djustment Factor	0%	0
		Soft	Cost Adjustment	55%	30,146
		Total Es	timated Amount		\$85,318

Fairway Elementary School

M•A•P•P•S ©, Jacobs 2016

Page 574 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->CR

Deficiency:

290

Assess ID 70722 Surveyor/Update Latasha King

Defeciency Code ID **E03-01**

Status Estimated FCI Yes

Life Cycle

Deficiency The Canopy Lighting Is Missing And Needed

Fairway Elementary School

Category Functional Deficiency System Electrical

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Non Related

Correction Install Canopy Lighting Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
Α	D50102301240	Branch installation 600 V, including EMT conduit and THW wire, 20 A	250 LF	7.36	\$1,840
U	265633108250	Walkway luminaire, exterior, lantern, high pressure sodium, 150 Watt	5 Ea.	780.00	\$3,900
			Sub Total		\$5,740
		Constr	ruction Adjustment	35%	1,980
		c	onstruction Cost		\$7,720
			Adjustment Factor	0%	0
		So	ft Cost Adjustment	55%	4,218
		Total E	stimated Amount		\$11,939

Fairway Elementary School

290

M-A-P-P-S ©, Jacobs 2016

Page 594 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

290 Fairway Elementary School
Location: Fairway ES->CR

Deficiency:

Assess ID 70724 Surveyor/Update Latasha King

Defeciency Code ID **E04-03**

Status Estimated FCI Yes

Life Cycle 21929

Deficiency The Mounted Building Lighting Is Damaged And Should Be Replaced

Category Capital Renewal System Electrical

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Non Related

Correction Replace Exterior Mounted Building Lighting Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty UoM	Price	Extension
U	019313162545	Electrical facilities maintenance, remove and replace or maintain replace other lighting parts	, 6 Ea.	77.50	\$465
U	265623101190	Metal halide fixture, exterior, wall pack, 250 Watt, incl lamps	6 Ea.	470.00	\$2,820
			Sub Total		\$3,285
		Co	nstruction Adjustment	35%	1,133
			Construction Cost		\$4,418
			Adjustment Factor	0%	0
			Soft Cost Adjustment	55%	2,414
		Tota	al Estimated Amount		\$6,832

Fairway Elementary School

290

M-A-P-P-S ©, Jacobs 2016

Page 591 of 624

Broward County Public Schools

Fairway Elementary School

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->CR

Deficiency:

290

Assess ID 70726 Surveyor/Update Latasha King

Defeciency Code ID E93-01

Status **Estimated** FCI Yes

Life Cycle

Emergency Lighting Is Inadequate Or Not Present And Should Be Installed Deficiency

Category Code Compliance System Fire and Security

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Security and Supervision

Correction Install Or Add Emergency Lighting System Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
U	265213100700	Emergency lighting units, nickel cadmium battery operated, twin sealed beam light, 25 W, 6 V each	13 Ea.	890.00	\$11,671
			Sub Total		\$11,671
		Co	nstruction Adjustment	35%	4,026
			Construction Cost		\$15,697
			Adjustment Factor	0%	0
			Soft Cost Adjustment	55%	8,577
		Tota	al Estimated Amount		\$24,274

Fairway Elementary School

Page 317 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->CR

Deficiency:

290

Assess ID 70727 Surveyor/Update Latasha King

Defeciency Code ID **E94-03**

Status **Estimated** FCI Yes

Life Cycle

Deficiency **Emergency Exit Signage Requires Replacement**

Fairway Elementary School

System Category **Deferred Maintenance** Fire and Security

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Security and Supervision

Correction Replace Exit Signage Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
U	265313109000	Exit lighting, minimum labor/equipment charge	3 Job	165.00	\$413
U	265313100260	Exit lighting, LED w/ battery unit, double face, ceiling or wall mount	5 Ea.	320.00	\$1,600
			Sub Total		\$2,013
			Construction Adjustment	35%	694
			Construction Cost		\$2,707
			Adjustment Factor	0%	0
			Soft Cost Adjustment	55%	1,479
			Total Estimated Amount		\$4,186

Fairway Elementary School

Page 300 of 624

M-A-P-P-S ©, Jacobs 2016



Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

290 Fairway Elementary School
Location: Fairway ES->CR

Deficiency:

Assess ID 70728 Surveyor/Update Latasha King

Defeciency Code ID **E58-01**

Status Estimated FCI Yes

Life Cycle

Deficiency The GFCI Electrical Receptacles Are Inadequate And More Are Needed

Category Deferred Maintenance System Electrical

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Technology

Correction Install New GFCI Electrical Receptacle Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
U	260590104380	Receptacle devices, residential, decorator style, GFI with #12/2, type EMT & wire, 20', incl box & cover plate	4 Ea.	233.00	\$932
			Sub Total		\$932
		Consti	Construction Adjustment 35		322
		c	onstruction Cost		\$1,254
			Adjustment Factor	0%	0
		So	t Cost Adjustment	55%	685
		Total E	stimated Amount		\$1,938

Fairway Elementary School

Page 299 of 624

Broward County Public Schools

Fairway Elementary School

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->CR

Deficiency:

290

Assess ID 70729 Surveyor/Update Latasha King

Defeciency Code ID **E04-03**

Status **Estimated** FCI Yes

Life Cycle 21937

The Mounted Building Lighting Is Damaged And Should Be Replaced Deficiency

Category Capital Renewal System Electrical

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Non Related

Correction Replace Exterior Mounted Building Lighting Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty UoM	Price	Extension
U	019313162545	Electrical facilities maintenance, remove and replace or maintain, replace other lighting parts	6 Ea.	77.50	\$465
U	265623101190	Metal halide fixture, exterior, wall pack, 250 Watt, incl lamps	6 Ea.	470.00	\$2,820
			Sub Total		\$3,285
		Cons	truction Adjustment	35%	1,133
			Construction Cost		\$4,418
			Adjustment Factor	0%	0
		s	oft Cost Adjustment	55%	2,414
		Total	Estimated Amount		\$6,832

Fairway Elementary School

Page 592 of 624

Broward County Public Schools

Fairway Elementary School

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->CR

Deficiency:

290

Assess ID 70731 Surveyor/Update Latasha King

Defeciency Code ID **E93-01**

Status Estimated FCI Yes

Life Cycle

Deficiency Emergency Lighting Is Inadequate Or Not Present And Should Be Installed

Category Code Compliance System Fire and Security

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Security and Supervision

Correction Install Or Add Emergency Lighting System Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty UoM	Price	Extension
U	265213100700	Emergency lighting units, nickel cadmium battery operated, twin sealed beam light, 25 W, 6 V each	0 Ea.	890.00	\$11
			Sub Total		\$11
		Cor	struction Adjustment 35%		4
			Construction Cost		\$15
			Adjustment Factor	0%	0
			Soft Cost Adjustment	55%	8
		Tota	I Estimated Amount		\$24

Fairway Elementary School

290

M-A-P-P-S ©, Jacobs 2016

Page 313 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->CR

Deficiency:

290

Assess ID 70732 Surveyor/Update Latasha King

Defeciency Code ID **E94-03**

Status **Estimated** FCI Yes

Life Cycle

Deficiency **Emergency Exit Signage Requires Replacement**

Fairway Elementary School

System Category **Deferred Maintenance** Fire and Security

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Security and Supervision

Correction Replace Exit Signage Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
U	265313109000	Exit lighting, minimum labor/equipment charge	3 Job	165.00	\$495
U	265313100260	Exit lighting, LED w/ battery unit, double face, ceiling or wall mount	6 Ea.	320.00	\$1,920
			Sub Total		\$2,415
			Construction Adjustment	35%	833
			Construction Cost		\$3,248
			Adjustment Factor	0%	0
			Soft Cost Adjustment	55%	1,775
			Total Estimated Amount		\$5,023

Fairway Elementary School

M-A-P-P-S ©, Jacobs 2016

Page 304 of 624

Broward County Public Schools

Fairway Elementary School

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->CR

Deficiency:

290

Assess ID 70733 Surveyor/Update Latasha King

Defeciency Code ID **E58-01**

Status Estimated FCI Yes

Life Cycle

Deficiency The GFCI Electrical Receptacles Are Inadequate And More Are Needed

Category Deferred Maintenance System Electrical

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Technology

Correction Install New GFCI Electrical Receptacle Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
U	260590104380	Receptacle devices, residential, decorator style, GFI with #12/2, type EMT & wire, 20', incl box & cover plate	4 Ea.	233.00	\$932
			Sub Total		\$932
		Con	nstruction Adjustment 35%		322
			Construction Cost		\$1,254
			Adjustment Factor	0%	0
		\$	Soft Cost Adjustment	55%	685
		Total	Estimated Amount		\$1,938

Fairway Elementary School

Page 296 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES

Deficiency:

290

Assess ID 71735 Surveyor/Update Ajai Fraser

Defeciency Code ID **E03-03**

Status Estimated FCI Yes

Life Cycle

Deficiency The Canopy Lighting Requires Replacement

Fairway Elementary School

Category Deferred Maintenance System Electrical

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Non Related

Correction Replace Canopy Lighting Quantity / UoM

Project(s) Note

Estimate:

aie.				
Number	Description	Qty UoM	Price	Extension
019313162545	Electrical facilities maintenance, remove and replace or maintain, replace other lighting parts	4 Ea.	77.50	\$310
265633107830	Walkway luminaire, exterior, square 16", high pressure sodium, 100 Watt	4 Ea.	1,025.00	\$4,100
		Sub Total		\$4,410
	Constr	ruction Adjustment	35%	1,521
	c	onstruction Cost		\$5,931
		Adjustment Factor 0%		0
	So	ft Cost Adjustment	48%	2,868
	Total E	stimated Amount		\$8,800
	Number 019313162545	Number Description 019313162545 Electrical facilities maintenance, remove and replace or maintain, replace other lighting parts 265633107830 Walkway luminaire, exterior, square 16", high pressure sodium, 100 Watt Constr	Number Description Oty UoM 19313162545 Electrical facilities maintenance, remove and replace or maintain, replace other lighting parts 265633107830 Walkway luminaire, exterior, square 16", high pressure sodium, 100 Watt Sub Total Construction Adjustment Construction Cost	Number Description Qty UoM Price 019313162545 Electrical facilities maintenance, remove and replace or maintain, replace other lighting parts 4 Ea. 77.50 265633107830 Walkway luminaire, exterior, square 16", high pressure sodium, 100 Watt 4 Ea. 1,025.00 Sub Total Construction Adjustment 35% Construction Cost Adjustment Factor 0% Soft Cost Adjustment

Fairway Elementary School

Page 584 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->CR

Deficiency:

290

Assess ID 71736 Surveyor/Update Ajai Fraser

Defeciency Code ID **E03-03**

Status Estimated FCI Yes

Life Cycle

Deficiency The Canopy Lighting Requires Replacement

Fairway Elementary School

Category Deferred Maintenance System Electrical

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Non Related

Correction Replace Canopy Lighting Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
U	019313162545	Electrical facilities maintenance, remove and replace or maintain, replace other lighting parts	4 Ea.	77.50	\$310
U	265633107830	Walkway luminaire, exterior, square 16", high pressure sodium, 100 Watt	4 Ea.	1,025.00	\$4,100
			Sub Total		\$4,410
		Constru	uction Adjustment	35%	1,521
		Co	onstruction Cost		\$5,931
		A	Adjustment Factor		0
		Sofi	Cost Adjustment	55%	3,241
		Total Es	stimated Amount	_	\$9,172

Fairway Elementary School

290

M•A•P•P•S ©, Jacobs 2016

Page 585 of 624

Broward County Public Schools

Fairway Elementary School

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->CR

Deficiency:

290

Assess ID 71739 Surveyor/Update Ajai Fraser

Defeciency Code ID **E04-03**

Status **Estimated** FCI Yes

Life Cycle 22296

The Mounted Building Lighting Is Damaged And Should Be Replaced Deficiency

Category Capital Renewal System Electrical

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Non Related

Correction Replace Exterior Mounted Building Lighting Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
U	019313162545	Electrical facilities maintenance, remove and replace or maintain, replace other lighting parts	6 Ea.	77.50	\$465
U	265623101190	Metal halide fixture, exterior, wall pack, 250 Watt, incl lamps	6 Ea.	470.00	\$2,820
			Sub Total		\$3,285
		Cons	struction Adjustment	35%	1,133
			Construction Cost		\$4,418
			Adjustment Factor	0%	0
		s	oft Cost Adjustment	55%	2,414
		Total	Estimated Amount		\$6,832

Fairway Elementary School

M-A-P-P-S ©, Jacobs 2016

Page 588 of 624

Broward County Public Schools

Fairway Elementary School

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->CR

Deficiency:

290

Assess ID 71740 Surveyor/Update Ajai Fraser

Defeciency Code ID E93-01

Status **Estimated** FCI Yes

Life Cycle

Emergency Lighting Is Inadequate Or Not Present And Should Be Installed Deficiency

Category Code Compliance System Fire and Security

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Security and Supervision

Correction Install Or Add Emergency Lighting System Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty UoM	Price	Extension
U	265213100700	Emergency lighting units, nickel cadmium battery operated, twin sealed beam light, 25 W, 6 V each	16 Ea.	890.00	\$13,847
			Sub Total		\$13,847
		Co	nstruction Adjustment	35%	4,777
			Construction Cost		\$18,624
			Adjustment Factor	0%	0
			Soft Cost Adjustment	55%	10,176
		Tota	al Estimated Amount		\$28,800

Fairway Elementary School

Page 314 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

290 **Fairway Elementary School** Location: Fairway ES->CR

Deficiency:

Assess ID 71741 Surveyor/Update Ajai Fraser

Defeciency Code ID **E94-03** Status **Estimated**

FCI Yes

Life Cycle

Deficiency **Emergency Exit Signage Requires Replacement**

System Category **Deferred Maintenance** Fire and Security

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Security and Supervision

Correction Replace Exit Signage Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
U	265313109000	Exit lighting, minimum labor/equipment charge	4 Job	165.00	\$660
U	265313100260	Exit lighting, LED w/ battery unit, double face, ceiling or wall mount	8 Ea.	320.00	\$2,560
			Sub Total		\$3,220
			Construction Adjustment	35%	1,111
			Construction Cost		\$4,331
			Adjustment Factor	0%	0
			Soft Cost Adjustment	55%	2,366
			Total Estimated Amount		\$6,697

Fairway Elementary School

M-A-P-P-S ©, Jacobs 2016

Page 303 of 624

Broward County Public Schools

Fairway Elementary School

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->CR

Deficiency:

290

Assess ID 71742 Surveyor/Update Ajai Fraser

Defeciency Code ID **E58-01**

Status **Estimated** FCI Yes

Life Cycle

Deficiency The GFCI Electrical Receptacles Are Inadequate And More Are Needed

Category **Deferred Maintenance** System Electrical

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Technology

Correction Install New GFCI Electrical Receptacle Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty UoM	Price	Extension
U	260590104380	Receptacle devices, residential, decorator style, GFI with #12/2, type EMT & wire, 20', incl box & cover plate	6 Ea.	233.00	\$1,398
		Sub Total			\$1,398
		Construction Adjustment		35%	482
		c	Construction Cost		\$1,880
		Adjustment Factor		0%	0
	Soft Cost Adjustment Total Estimated Amount		55%	1,027	
			_	\$2,908	

Fairway Elementary School

Page 295 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->Bldg 4

Deficiency:

290

Assess ID 71797 Surveyor/Update Ajai Fraser

Defeciency Code ID **E03-03**

Status Estimated FCI Yes

Life Cycle

Deficiency The Canopy Lighting Requires Replacement

Fairway Elementary School

Category Deferred Maintenance System Electrical

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Non Related

Correction Replace Canopy Lighting Quantity / UoM

Project(s) Note

Estimate:

	ucc.				
Туре	Number	Description	Qty UoM	Price	Extension
U	019313162545	Electrical facilities maintenance, remove and replace or maintain, replace other lighting parts	6 Ea.	77.50	\$465
U	265633107830	Walkway luminaire, exterior, square 16", high pressure sodium, 100 Watt	6 Ea.	1,025.00	\$6,150
			Sub Total		\$6,615
		Constru	uction Adjustment	35%	2,282
		Co	onstruction Cost		\$8,897
		A	djustment Factor	0%	0
		Soft	Soft Cost Adjustment		4,861
		Total Es	timated Amount		\$13,759

Fairway Elementary School

Page 586 of 624

Broward County Public Schools

Fairway Elementary School

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->Bldg 4

Deficiency:

290

Assess ID 71798 Surveyor/Update Ajai Fraser

Defeciency Code ID **E04-03**

Status Estimated FCI Yes

Life Cycle 22312

Deficiency The Mounted Building Lighting Is Damaged And Should Be Replaced

Category Capital Renewal System Electrical

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Non Related

Correction Replace Exterior Mounted Building Lighting Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
U	019313162545	Electrical facilities maintenance, remove and replace or maintain, replace other lighting parts	6 Ea.	77.50	\$465
U	265623101190	Metal halide fixture, exterior, wall pack, 250 Watt, incl lamps	6 Ea.	470.00	\$2,820
			Sub Total		\$3,285
		Cons	truction Adjustment	35%	1,133
			Construction Cost		\$4,418
			Adjustment Factor	0%	0
	Soft Cost Adjustme		oft Cost Adjustment	55%	2,414
		Total	Estimated Amount		\$6,832

Fairway Elementary School

Page 587 of 624

Broward County Public Schools

Fairway Elementary School

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->Bldg 4

Deficiency:

290

Assess ID 71800 Surveyor/Update Ajai Fraser

Defeciency Code ID **E93-01**

Status Estimated FCI Yes

Life Cycle

Deficiency Emergency Lighting Is Inadequate Or Not Present And Should Be Installed

Category Code Compliance System Fire and Security

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Security and Supervision

Correction Install Or Add Emergency Lighting System Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
U	265213100700	Emergency lighting units, nickel cadmium battery operated, twir sealed beam light, 25 W, 6 V each	n 8 Ea.	890.00	\$6,891
			Sub Total		\$6,891
	Construction Adjustment		35%	2,377	
		Construction Cost			\$9,269
	Adjustment Factor Soft Cost Adjustment Total Estimated Amount		0%	0	
			55%	5,064	
				\$14,333	

Fairway Elementary School

Page 312 of 624

Broward County Public Schools

Deficiency Detail

Ajai Fraser

2/4/2016 3:36 PM

290 Fairway Elementary School
Location: Fairway ES->Bldg 4

Deficiency:

Assess ID 71801 Surveyor/Update

Defeciency Code ID **E94-03**

Status Estimated FCI Yes

Life Cycle

Deficiency Emergency Exit Signage Requires Replacement

Category Deferred Maintenance System Fire and Security

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Security and Supervision

Correction Replace Exit Signage Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty UoM	Price	Extension
U	265313109000	Exit lighting, minimum labor/equipment charge	2 Job	165.00	\$330
U	265313100260	Exit lighting, LED w/ battery unit, double face, ceiling or wall mount	4 Ea.	320.00	\$1,280
			Sub Total		\$1,610
			Construction Adjustment	35%	555
			Construction Cost		\$2,165
			Adjustment Factor	0%	0
			Soft Cost Adjustment	55%	1,183
			Total Estimated Amount		\$3,349

Fairway Elementary School

290

Page 305 of 624

M-A-P-P-S ©, Jacobs 2016

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

290 Fairway Elementary School
Location: Fairway ES->Bldg 4

Deficiency:

Assess ID 71802 Surveyor/Update Ajai Fraser

Defeciency Code ID **E58-01**

Status Estimated FCI Yes

Life Cycle 22333

Deficiency The GFCI Electrical Receptacles Are Inadequate And More Are Needed

Category Deferred Maintenance System Electrical

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Technology

Correction Install New GFCI Electrical Receptacle Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
U	260590104380	Receptacle devices, residential, decorator style, GFI with #12/2, type EMT & wire, 20', incl box & cover plate	5 Ea.	233.00	\$1,165
			Sub Total		\$1,165
		Construction Adjustment		35%	402
			Construction Cost		\$1,567
			Adjustment Factor	0%	0
		s	oft Cost Adjustment	55%	856
		Total	Estimated Amount		\$2,423

Fairway Elementary School

290

M-A-P-P-S ©, Jacobs 2016

Page 298 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

290 **Fairway Elementary School** Fairway ES->Bldg 5 Location:

Deficiency:

Assess ID 71809 Surveyor/Update Ajai Fraser

Defeciency Code ID **E03-01**

Status **Estimated** FCI Yes

Life Cycle

The Canopy Lighting Is Missing And Needed Deficiency

Category **Functional Deficiency** System Electrical

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Non Related

Correction Install Canopy Lighting Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
Α	D50102301240	Branch installation 600 V, including EMT conduit and THW wire, 20 A	450 LF	7.36	\$3,312
U	265633108250	Walkway luminaire, exterior, lantern, high pressure sodium, 150 Watt	9 Ea.	780.00	\$7,020
			Sub Total		\$10,332
		Const	ruction Adjustment	35%	3,565
		C	Construction Cost		\$13,897
			Adjustment Factor	0%	0
		Sc	oft Cost Adjustment	52%	7,178
		Total E	stimated Amount		\$21,074

Fairway Elementary School

M•A•P•P•S ©, Jacobs 2016

Page 597 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

290 Fairway Elementary School
Location: Fairway ES->Bldg 5

Deficiency:

Assess ID 71811 Surveyor/Update Ajai Fraser

Defeciency Code ID **E04-03**

Status Estimated FCI Yes

Life Cycle 22365

Deficiency The Mounted Building Lighting Is Damaged And Should Be Replaced

Category Capital Renewal System Electrical

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Non Related

Correction Replace Exterior Mounted Building Lighting Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
U	019313162545	Electrical facilities maintenance, remove and replace or maintain replace other lighting parts	n, 16 Ea.	77.50	\$1,240
U	265623101190	Metal halide fixture, exterior, wall pack, 250 Watt, incl lamps	16 Ea.	470.00	\$7,520
			Sub Total		\$8,760
		Co	onstruction Adjustment	35%	3,022
			Construction Cost		\$11,782
			Adjustment Factor	0%	0
			Soft Cost Adjustment	52%	6,086
		Tota	al Estimated Amount		\$17,868

Fairway Elementary School

290

M-A-P-P-S ©, Jacobs 2016

Page 589 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

290 **Fairway Elementary School** Location: Fairway ES->Bldg 5

Deficiency:

Assess ID 71812 Surveyor/Update Ajai Fraser

Defeciency Code ID E93-01

Status **Estimated** FCI Yes

Life Cycle

Emergency Lighting Is Inadequate Or Not Present And Should Be Installed Deficiency

Category Code Compliance System Fire and Security

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Security and Supervision

Correction Install Or Add Emergency Lighting System Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
U	265213100700	Emergency lighting units, nickel cadmium battery operated, twin sealed beam light, 25 W, 6 V each	18 Ea.	890.00	\$16,312
			Sub Total		\$16,312
	Construction Adjustment	nstruction Adjustment	35%	5,628	
			Construction Cost		\$21,940
			Adjustment Factor	0%	0
			Soft Cost Adjustment	52%	11,332
		Tota	al Estimated Amount		\$33,272

Fairway Elementary School

Page 316 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->Bldg 5

Deficiency:

290

Assess ID 71813 Surveyor/Update Ajai Fraser

Defeciency Code ID **E94-03**

Status Estimated FCI Yes

Life Cycle

Deficiency Emergency Exit Signage Requires Replacement

Fairway Elementary School

Category Deferred Maintenance System Fire and Security

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Security and Supervision

Correction Replace Exit Signage Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
U	265313109000	Exit lighting, minimum labor/equipment charge	3 Job	165.00	\$495
U	265313100260	Exit lighting, LED w/ battery unit, double face, ceiling or wall mount	6 Ea.	320.00	\$1,920
			Sub Total		\$2,415
			Construction Adjustment	35%	833
			Construction Cost		\$3,248
			Adjustment Factor	0%	0
			Soft Cost Adjustment	52%	1,678
			Total Estimated Amount		\$4,926

Fairway Elementary School

Page 301 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

290 **Fairway Elementary School** Location: Fairway ES->Bldg 6

Deficiency:

Assess ID 71819 Surveyor/Update Ajai Fraser

Defeciency Code ID **E03-01**

Status **Estimated** FCI Yes

Life Cycle

The Canopy Lighting Is Missing And Needed Deficiency

Category **Functional Deficiency** System Electrical

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Non Related

Correction Install Canopy Lighting Quantity / UoM

Project(s) Note

Estimate:

	a.c.				
Туре	Number	Description	Qty UoM	Price	Extension
Α	D50102301240	Branch installation 600 V, including EMT conduit and THW wire, 20 A	600 LF	7.36	\$4,416
U	265633108250	Walkway luminaire, exterior, lantern, high pressure sodium, 150 Watt	12 Ea.	780.00	\$9,360
			Sub Total		\$13,776
		Constr	ruction Adjustment	35%	4,753
		c	onstruction Cost		\$18,529
			Adjustment Factor	0%	0
		So	ft Cost Adjustment	52%	9,570
		Total E	stimated Amount		\$28,099
				_	

Fairway Elementary School

Page 595 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

290 Fairway Elementary School
Location: Fairway ES->Bldg 6

Deficiency:

Assess ID **71821**

Surveyor/Update

Ajai Fraser

Defeciency Code ID **E04-03**Status **Estimated**

FCI

Yes

Life Cycle

22455

Deficiency

The Mounted Building Lighting Is Damaged And Should Be Replaced

Category

Capital Renewal

System

Electrical

Priority

Correction

2-Indirect Impact to Mission (1 Year)

Functional Adequacy N

Non Related

Replace Exterior Mounted Building Lighting Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
U	019313162545	Electrical facilities maintenance, remove and replace or maintain, replace other lighting parts	14 Ea.	77.50	\$1,085
U	265623101190	Metal halide fixture, exterior, wall pack, 250 Watt, incl lamps	14 Ea.	470.00	\$6,580
			Sub Total		\$7,665
		Cons	struction Adjustment	35%	2,644
			Construction Cost		\$10,309
			Adjustment Factor	0%	0
		s	oft Cost Adjustment	52%	5,325
		Total	Estimated Amount		\$15,634

Fairway Elementary School

Page 590 of 624

M-A-P-P-S ©, Jacobs 2016

Broward County Public Schools

Fairway Elementary School

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->Bldg 6

Deficiency:

290

Assess ID 71832 Surveyor/Update Ajai Fraser

Defeciency Code ID E93-01

Status **Estimated** FCI Yes

Life Cycle

Emergency Lighting Is Inadequate Or Not Present And Should Be Installed Deficiency

Category Code Compliance System Fire and Security

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Security and Supervision

Correction Install Or Add Emergency Lighting System Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty UoM	Price	Extension
U	265213100700	Emergency lighting units, nickel cadmium battery operated, twin sealed beam light, 25 W, 6 V each	16 Ea.	890.00	\$14,184
			Sub Total		\$14,184
		Co	nstruction Adjustment	35%	4,894
			Construction Cost		\$19,078
			Adjustment Factor	0%	0
			Soft Cost Adjustment	52%	9,854
		Tota	al Estimated Amount		\$28,932

Fairway Elementary School

M-A-P-P-S ©, Jacobs 2016

Page 315 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->Bldg 6

Deficiency:

290

Assess ID 71833 Surveyor/Update Ajai Fraser

Defeciency Code ID **E94-03**

Status Estimated FCI Yes

Life Cycle

Deficiency Emergency Exit Signage Requires Replacement

Fairway Elementary School

Category Deferred Maintenance System Fire and Security

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Security and Supervision

Correction Replace Exit Signage Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
U	265313109000	Exit lighting, minimum labor/equipment charge	3 Job	165.00	\$495
U	265313100260	Exit lighting, LED w/ battery unit, double face, ceiling or wall mount	6 Ea.	320.00	\$1,920
			Sub Total		\$2,415
			Construction Adjustment	35%	833
			Construction Cost		\$3,248
			Adjustment Factor	0%	0
			Soft Cost Adjustment	52%	1,678
			Total Estimated Amount		\$4,926

Fairway Elementary School

Page 302 of 624

M-A-P-P-S ©, Jacobs 2016

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

290 Fairway Elementary School
Location: Fairway ES->Bldg 6

Deficiency:

Assess ID 71836 Surveyor/Update Ajai Fraser

Defeciency Code ID **E58-01**

Status Estimated FCI Yes

Life Cycle

Deficiency The GFCI Electrical Receptacles Are Inadequate And More Are Needed

Category Deferred Maintenance System Electrical

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Technology

Correction Install New GFCI Electrical Receptacle Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
U	260590104380	Receptacle devices, residential, decorator style, GFI with #12/2, type EMT & wire, 20', incl box & cover plate	6 Ea.	233.00	\$1,398
			Sub Total		\$1,398
		Cons	truction Adjustment	35%	482
			Construction Cost		\$1,880
			Adjustment Factor	0%	0
		Sc	oft Cost Adjustment	52%	971
		Total I	Estimated Amount	_	\$2,851

Fairway Elementary School

Page 297 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

290 **Fairway Elementary School** Location: Fairway ES->Bldg 7

Deficiency:

Assess ID 71848 Surveyor/Update Ajai Fraser

Defeciency Code ID **E03-01**

Status **Estimated** FCI Yes

Life Cycle

The Canopy Lighting Is Missing And Needed Deficiency

Category **Functional Deficiency** System Electrical

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Non Related

Correction Install Canopy Lighting Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
Α	D50102301240	Branch installation 600 V, including EMT conduit and THW wire, 20 A	300 LF	7.36	\$2,208
U	265633108250	Walkway luminaire, exterior, lantern, high pressure sodium, 150 Watt	6 Ea.	780.00	\$4,680
			Sub Total		\$6,888
		Cons	truction Adjustment	35%	2,376
		•	Construction Cost		\$9,264
			Adjustment Factor	0%	0
		S	oft Cost Adjustment	52%	4,785
		Total	Estimated Amount	_	\$14,049

Fairway Elementary School

M•A•P•P•S ©, Jacobs 2016

Page 596 of 624

Broward County Public Schools

Fairway Elementary School

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->Bldg 7

Deficiency:

290

Assess ID 71850 Surveyor/Update Ajai Fraser

Defeciency Code ID **E04-03**

Status **Estimated** FCI Yes

Life Cycle 22493

The Mounted Building Lighting Is Damaged And Should Be Replaced Deficiency

Category Capital Renewal System Electrical

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Non Related

Correction Replace Exterior Mounted Building Lighting Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
U	019313162545	Electrical facilities maintenance, remove and replace or maintain, replace other lighting parts	13 Ea.	77.50	\$1,008
U	265623101190	Metal halide fixture, exterior, wall pack, 250 Watt, incl lamps	13 Ea.	470.00	\$6,110
			Sub Total		\$7,118
		Cons	truction Adjustment	35%	2,456
			Construction Cost		\$9,573
			Adjustment Factor	0%	0
		S	oft Cost Adjustment	52%	4,944
		Total I	Estimated Amount		\$14,518

Fairway Elementary School

M-A-P-P-S ©, Jacobs 2016

Page 593 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

290 **Fairway Elementary School** Location: Fairway ES->Bldg 7

Deficiency:

Assess ID 71853 Surveyor/Update Ajai Fraser

Defeciency Code ID E93-01

Status **Estimated** FCI Yes

Life Cycle

Emergency Lighting Is Inadequate Or Not Present And Should Be Installed Deficiency

Category Code Compliance System Fire and Security

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Security and Supervision

Correction Install Or Add Emergency Lighting System Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
U	265213100700	Emergency lighting units, nickel cadmium battery operated, twin sealed beam light, 25 W, 6 V each	5 Ea.	890.00	\$4,439
			Sub Total		\$4,439
		Co	nstruction Adjustment	35%	1,532
			Construction Cost		\$5,971
			Adjustment Factor	0%	0
			Soft Cost Adjustment	52%	3,084
		Tota	I Estimated Amount		\$9,055

Fairway Elementary School

Page 311 of 624

M-A-P-P-S ©, Jacobs 2016



Broward County Public Schools

Fairway Elementary School

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->Sto

Deficiency:

290

Assess ID 71855 Surveyor/Update Ajai Fraser

Defeciency Code ID **E04-01**

Status Estimated FCI Yes

Life Cycle 22516

Deficiency The Mounted Building Lighting Is Missing And Needed

Category Functional Deficiency System Electrical

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Non Related

Correction Install Exterior Mounted Building Lighting Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
Α	D50102301240	Branch installation 600 V, including EMT conduit and THW wire, 20 A	200 LF	7.36	\$1,472
U	260505109000	Electrical demolition, minimum labor/equipment charge	4 Job	165.00	\$660
U	265623101170	High pressure sodium fixture, exterior, wall pack, 150 Watt, incl lamps	4 Ea.	430.00	\$1,720
			Sub Total		\$3,852
		Con	struction Adjustment	35%	1,329
			Construction Cost		\$5,181
			Adjustment Factor	0%	0
		8	Soft Cost Adjustment	52%	2,676
		Total	Estimated Amount	_	\$7,857

Fairway Elementary School

Page 600 of 624

Broward County Public Schools

Fairway Elementary School

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->CR

Deficiency:

290

Assess ID 71858 Surveyor/Update Ajai Fraser

Defeciency Code ID **E04-01**

Status Estimated FCI Yes

Life Cycle

Deficiency The Mounted Building Lighting Is Missing And Needed

Category Functional Deficiency System Electrical

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Non Related

Correction Install Exterior Mounted Building Lighting Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
Α	D50102301240	Branch installation 600 V, including EMT conduit and THW wire, 20 A	400 LF	7.36	\$2,944
U	260505109000	Electrical demolition, minimum labor/equipment charge	8 Job	165.00	\$1,320
U	265623101170	High pressure sodium fixture, exterior, wall pack, 150 Watt, incl lamps	8 Ea.	430.00	\$3,440
			Sub Total		\$7,704
		Con	struction Adjustment	35%	2,658
			Construction Cost		\$10,362
			Adjustment Factor	0%	0
		8	Soft Cost Adjustment	48%	5,011
		Total	Estimated Amount	_	\$15,373

Fairway Elementary School

290

Page 601 of 624

M•A•P•P•S ©, Jacobs 2016

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

290 **Fairway Elementary School** Location: Fairway ES->CR

Deficiency:

Assess ID 71862 Surveyor/Update Ajai Fraser

Defeciency Code ID E93-01

Status **Estimated** FCI Yes

Life Cycle

Emergency Lighting Is Inadequate Or Not Present And Should Be Installed Deficiency

Category Code Compliance System Fire and Security

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Security and Supervision

Correction Install Or Add Emergency Lighting System Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
U	265213100700	Emergency lighting units, nickel cadmium battery operated, twin sealed beam light, 25 W, 6 V each	12 Ea.	890.00	\$10,363
			Sub Total		\$10,363
		Со	nstruction Adjustment	35%	3,575
			Construction Cost		\$13,938
			Adjustment Factor	0%	0
			Soft Cost Adjustment	48%	6,740
		Tota	I Estimated Amount		\$20,679

Fairway Elementary School

M-A-P-P-S ©, Jacobs 2016

Page 309 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->CR

Deficiency:

290

Assess ID 71863 Surveyor/Update Ajai Fraser

Defeciency Code ID **E94-03**

Status Estimated FCI Yes

Life Cycle

Deficiency Emergency Exit Signage Requires Replacement

Fairway Elementary School

Category Deferred Maintenance System Fire and Security

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Security and Supervision

Correction Replace Exit Signage Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty UoM	Price	Extension
U	265313109000	Exit lighting, minimum labor/equipment charge	3 Job	165.00	\$413
U	265313100260	Exit lighting, LED w/ battery unit, double face, ceiling or wall mount	5 Ea.	320.00	\$1,600
			Sub Total		\$2,013
			Construction Adjustment	35%	694
			Construction Cost		\$2,707
			Adjustment Factor	0%	0
			Soft Cost Adjustment	48%	1,309
			Total Estimated Amount		\$4,016

Fairway Elementary School

Page 307 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

290 **Fairway Elementary School** Location: Fairway ES->CR

Deficiency:

Life Cycle

Deficiency

Assess ID 71864 Surveyor/Update

Ajai Fraser

Yes

Defeciency Code ID **E58-01** Status **Estimated**

The GFCI Electrical Receptacles Are Inadequate And More Are Needed

Category **Deferred Maintenance** System

FCI

Electrical

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Technology

Correction

Install New GFCI Electrical Receptacle

Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty UoM	Price	Extension
U	260590104380	Receptacle devices, residential, decorator style, GFI with #12/2, type EMT & wire, 20', incl box & cover plate	8 Ea.	233.00	\$1,864
			Sub Total		\$1,864
		Constru	uction Adjustment	35%	643
		Co	onstruction Cost		\$2,507
		A	Adjustment Factor	0%	0
		Sof	t Cost Adjustment	48%	1,212
		Total Es	stimated Amount		\$3,720

Fairway Elementary School

M-A-P-P-S ©, Jacobs 2016

Page 292 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

290 Fairway Elementary School
Location: Fairway ES->CR

Deficiency:

Assess ID 71866 Surveyor/Update Ajai Fraser

Defeciency Code ID **E04-01**

Status Estimated FCI Yes

Life Cycle

Deficiency The Mounted Building Lighting Is Missing And Needed

Category Functional Deficiency System Electrical

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Non Related

Correction Install Exterior Mounted Building Lighting Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
А	D50102301240	Branch installation 600 V, including EMT conduit and THW wire, 20 A	200 LF	7.36	\$1,472
U	260505109000	Electrical demolition, minimum labor/equipment charge	4 Job	165.00	\$660
U	265623101170	High pressure sodium fixture, exterior, wall pack, 150 Watt, incl lamps	4 Ea.	430.00	\$1,720
			Sub Total		\$3,852
		Con	struction Adjustment	35%	1,329
			Construction Cost		\$5,181
			Adjustment Factor	0%	0
		5	Soft Cost Adjustment	48%	2,506
		Total	Estimated Amount	_	\$7,686

Fairway Elementary School

Page 598 of 624

M-A-P-P-S ©, Jacobs 2016

Broward County Public Schools

Fairway Elementary School

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->CR

Deficiency:

290

Assess ID 71869 Surveyor/Update Ajai Fraser

Defeciency Code ID E93-01

Status **Estimated** FCI Yes

Life Cycle

Emergency Lighting Is Inadequate Or Not Present And Should Be Installed Deficiency

Category Code Compliance System Fire and Security

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Security and Supervision

Correction Install Or Add Emergency Lighting System Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
U	265213100700	Emergency lighting units, nickel cadmium battery operated, twin sealed beam light, 25 W, 6 V each	2 Ea.	890.00	\$1,781
			Sub Total		\$1,781
		Cor	struction Adjustment	35%	615
			Construction Cost		\$2,396
			Adjustment Factor	0%	0
			Soft Cost Adjustment	48%	1,159
		Tota	l Estimated Amount		\$3,555

Fairway Elementary School

M-A-P-P-S ©, Jacobs 2016

Page 310 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->CR

Deficiency:

290

Assess ID 71870 Surveyor/Update Ajai Fraser

Defeciency Code ID **E94-01**

Status Estimated FCI Yes

Life Cycle

Deficiency Emergency Exit Signage Is Missing And Needed

Fairway Elementary School

Category Deferred Maintenance System Fire and Security

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Security and Supervision

Correction Install Exit Sign Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
М	D50102301240	Branch installation 600 V, including EMT conduit and THW wire, 20 A	100 LF	5.74	\$574
U	265313100260	Exit lighting, LED w/ battery unit, double face, ceiling or wall mount	2 Ea.	320.00	\$640
			Sub Total		\$1,214
		Con	struction Adjustment	35%	419
			Construction Cost		\$1,633
			Adjustment Factor	0%	0
		;	Soft Cost Adjustment	48%	790
		Total	l Estimated Amount	_	\$2,422

Fairway Elementary School

290

M-A-P-P-S ©, Jacobs 2016 Page 321 of 624

Broward County Public Schools

Fairway Elementary School

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->CR

Deficiency:

290

Assess ID 71871 Surveyor/Update Ajai Fraser

Defeciency Code ID **E58-01**

Status Estimated FCI Yes

Life Cycle

Deficiency The GFCI Electrical Receptacles Are Inadequate And More Are Needed

Category Deferred Maintenance System Electrical

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Technology

Correction Install New GFCI Electrical Receptacle Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty UoM	Price	Extension
U	260590104380	Receptacle devices, residential, decorator style, GFI with #12/2, type EMT & wire, 20', incl box & cover plate	2 Ea.	233.00	\$466
			Sub Total		\$466
		Con	struction Adjustment	35%	161
			Construction Cost		\$627
			Adjustment Factor	0%	0
		5	Soft Cost Adjustment	48%	303
		Total	Estimated Amount		\$930

Fairway Elementary School

Page 293 of 624

Broward County Public Schools

Fairway Elementary School

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->CR

Deficiency:

290

Assess ID 71879 Surveyor/Update Ajai Fraser

Defeciency Code ID **E04-01**

Status **Estimated** FCI Yes

Life Cycle

The Mounted Building Lighting Is Missing And Needed Deficiency

System Category **Functional Deficiency** Electrical

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Non Related

Correction Install Exterior Mounted Building Lighting Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty	UoM	Price	Extension
Α	D50102301240	Branch installation 600 V, including EMT conduit and THW wire, 20 A	400	LF	7.36	\$2,944
U	260505109000	Electrical demolition, minimum labor/equipment charge	8	Job	165.00	\$1,320
U	265623101170	High pressure sodium fixture, exterior, wall pack, 150 Watt, incl lamps	8	Ea.	430.00	\$3,440
			s	ub Total		\$7,704
		Con	struction Ad	justment	35%	2,658
			Constructi	on Cost		\$10,362
			Adjustmer	nt Factor	0%	0
		5	Soft Cost Ad	justment	48%	5,011
		Total	Estimated	Amount		\$15,373

Fairway Elementary School

M-A-P-P-S ©, Jacobs 2016

Page 599 of 624

Broward County Public Schools

Fairway Elementary School

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->CR

Deficiency:

290

Assess ID 71882 Surveyor/Update Ajai Fraser

Defeciency Code ID **E93-01**

Status Estimated FCI Yes

Life Cycle

Deficiency Emergency Lighting Is Inadequate Or Not Present And Should Be Installed

Category Code Compliance System Fire and Security

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Security and Supervision

Correction Install Or Add Emergency Lighting System Quantity / UoM

Project(s) Note

Estimate:

	uc.				
Type	Number	Description	Qty UoM	Price	Extension
U	265213100700	Emergency lighting units, nickel cadmium battery operated, twir sealed beam light, 25 W, 6 V each	n 9 Ea.	890.00	\$8,298
			Sub Total		\$8,298
		c	onstruction Adjustment	35%	2,863
			Construction Cost		\$11,161
			Adjustment Factor	0%	0
			Soft Cost Adjustment	48%	5,397
		То	tal Estimated Amount		\$16,558

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

290 **Fairway Elementary School** Location: Fairway ES->CR

Deficiency:

Assess ID 71884 Surveyor/Update

Ajai Fraser

Defeciency Code ID **E94-03** Status **Estimated**

FCI

Yes

Life Cycle

Deficiency **Emergency Exit Signage Requires Replacement**

Category **Deferred Maintenance** System

Fire and Security

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy

Security and Supervision

Correction Replace Exit Signage Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
U	265313109000	Exit lighting, minimum labor/equipment charge	3 Job	165.00	\$495
U	265313100260	Exit lighting, LED w/ battery unit, double face, ceiling or wall mount	6 Ea.	320.00	\$1,920
			Sub Total		\$2,415
			Construction Adjustment	35%	833
			Construction Cost		\$3,248
			Adjustment Factor	0%	0
			Soft Cost Adjustment	48%	1,571
			Total Estimated Amount		\$4,819

Fairway Elementary School

M-A-P-P-S ©, Jacobs 2016

Page 306 of 624

Broward County Public Schools

Fairway Elementary School

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->CR

Deficiency:

290

Assess ID 71886 Surveyor/Update Ajai Fraser

Defeciency Code ID **E58-01**

Status **Estimated** FCI Yes

Life Cycle

Deficiency The GFCI Electrical Receptacles Are Inadequate And More Are Needed

Category **Deferred Maintenance** System Electrical

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Technology

Correction Install New GFCI Electrical Receptacle Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
U	260590104380	Receptacle devices, residential, decorator style, GFI with #12/2, type EMT & wire, 20', incl box & cover plate	8 Ea.	233.00	\$1,864
			Sub Total		\$1,864
		Co	nstruction Adjustment	35%	643
			Construction Cost		\$2,507
			Adjustment Factor	0%	0
			Soft Cost Adjustment	48%	1,212
		Tota	al Estimated Amount		\$3,720

Fairway Elementary School

M-A-P-P-S ©, Jacobs 2016

Page 294 of 624

Broward County Public Schools

Fairway Elementary School

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES

Deficiency:

290

Assess ID 72272 Surveyor/Update

Status FCI Yes

Life Cycle

Deficiency Deficiency to support project

Category Functional Deficiency System Other

Priority 5-General Improvements Functional Adequacy Non Related

Correction Correction to support project Quantity / UoM

Project(s) Note From Memorialized Project List | Type = 1 | Replace 18 Air Handlers

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
					\$0
			Sub Total		\$0
			Construction Adjustment	35%	0
			Construction Cost		\$0
			Adjustment Factor	0%	0
			Soft Cost Adjustment	48%	0
			Total Estimated Amount		\$0

Fairway Elementary School

290

M-A-P-P-S ©, Jacobs 2016

Page 614 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES

Deficiency:

290

Assess ID 72274

Fairway Elementary School

Status FCI Yes

Life Cycle

Deficiency Deficiency to support project

Category Functional Deficiency System Other

Priority 5-General Improvements Functional Adequacy Non Related

Correction Correction to support project Quantity / UoM

Project(s) Note From Memorialized Project List | Type = 1 | Install Emerg. Generator & related equip.

Estimate:

Type Number Description Qty UoM Price Extension \$0 Sub Total \$0 Construction Adjustment 0 **Construction Cost** \$0 Adjustment Factor 0% 0 Soft Cost Adjustment 48% 0 **Total Estimated Amount** \$0

Surveyor/Update

Fairway Elementary School

290

M-A-P-P-S ©, Jacobs 2016

Page 616 of 624

Broward County Public Schools

Fairway Elementary School

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES

Deficiency:

290

Assess ID 72276 Surveyor/Update

Status FCI Yes

Life Cycle

Deficiency Deficiency to support project

Category Functional Deficiency System Other

Priority 5-General Improvements Functional Adequacy Non Related

Correction Correction to support project Quantity / UoM

Project(s) Note From Memorialized Project List | Type = 1 | Replace One Mcquay Chiller.

Estimate:

Type Number Description Qty UoM Price Extension \$0 Sub Total \$0 Construction Adjustment 0 **Construction Cost** \$0 Adjustment Factor 0% 0 Soft Cost Adjustment 48% 0 **Total Estimated Amount** \$0

Fairway Elementary School

290

M-A-P-P-S ©, Jacobs 2016

Page 618 of 624

Broward County Public Schools

Fairway Elementary School

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->CR

Deficiency:

290

Assess ID 73279 Surveyor/Update Ajai Fraser

Defeciency Code ID M57-02C

Status Estimated FCI Yes

Life Cycle 22675

Deficiency The Air Handler HVAC Component Requires Replacement

Category Capital Renewal System Mechanical

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Replace 5000 CFM Air Handler Quantity / UoM

Project(s) Note

Estimate:

Lauin	ate.					
Туре	Number	Description	Qty	UoM	Price	Extension
U	237313202340	Central station air handling unit, packaged indoor, variable air volume, 5000 CFM, cooling coils may be chilled water or DX, heating coils may be hot water, steam or electric	1	Ea.	26,000.00	\$26,000
U	230505100400	Central station air handler, up thru 15 ton, selective demolition	1	Ea.	820.00	\$820
U	015419500100	Crane crew, daily use for small jobs, 12-ton truck-mounted hydraulic crane, portal to portal	1	Day	1,600.00	\$1,600
U	233113131030	Metal ductwork, fabricated rectangular, 500 to 1000 lb., stainless steel, type 304, includes fittings, joints, supports and allow for a flexible connections field sketches, excludes as-built drawings and insulation	250	Lb	13.40	\$3,350
U	260580101590	Motor connections, flexible conduit and fittings, 3 phase, 460 volt, 100 HP motor	1	Ea.	330.00	\$330
			s	ub Total		\$32,100
		Constr	uction Ad	ljustment	35%	11,074
		Construction C		ion Cost		\$43,174
		<i>A</i>	Adjustment Factor		0%	0
		Sof	t Cost Ad	ljustment	48%	20,918
		Total Es	stimated	Amount		\$64,093

Fairway Elementary School

Page 266 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->CR

Deficiency:

290

Assess ID 73281 Surveyor/Update Ajai Fraser

Defeciency Code ID M57-21c

Status Estimated FCI Yes

Life Cycle 22676

Deficiency Duct Heater Requires Replacement

Fairway Elementary School

Category Capital Renewal System Mechanical

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Learning Environment

Correction Replace Duct Heater Quantity / UoM

Project(s) Note

Estimate:

_30111	ate.				
Туре	Number	Description	Qty UoM	Price	Extension
U	238216200360	Duct heater, electric, finned tubular insert, 480 V, 3Ph., 500Deg.F, 26.7 kW, 12" wide x 24" high	1 Ea.	2,825.00	\$2,825
U	230505101850	Air conditioner, duct heater, electric strip, selective demolition, minimum labor/equipment charge	1 Job	161.00	\$161
			Sub Total		\$2,986
		Const	ruction Adjustment	35%	1,030
		C	onstruction Cost		\$4,016
			Adjustment Factor	0%	0
		So	ft Cost Adjustment	48%	1,946
		Total E	stimated Amount		\$5,962

Fairway Elementary School

290

M•A•P•P•S ©, Jacobs 2016

Page 223 of 624

RFQ Number: 16-182C

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

290 Fairway Elementary School
Location: Fairway ES->CR

Deficiency:

Assess ID 73296

Surveyor/Update

FCI

Ajai Fraser

Defeciency Code ID M50-03
Status Estimated

Yes

Life Cycle

Deficiency Complete HVAC System Wide Replacement

Category Capital Renewal System Mechanical

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Non Related

Correction Replace HVAC System Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty	UoM	Price	Extension
U	235223203400	Boiler, gas fired, natural or propane, cast iron, hot water, gross output, 3808 MBH, includes standard controls and insulated jacket, packaged	1	Ea.	53,000.00	\$34,956
U	230505101580	Ductwork, aluminum, fabricated, selective demolition	1,493	Lb	2.56	\$3,823
U	019313150830	Ductwork, rectangular, clean, 8" x 16" (max)	3,982	LF	4.91	\$19,553
U	230505100100	Air conditioner, split unit air conditioner, 3 ton, selective demolition	12	Ea.	655.00	\$8,151
U	095123100500	Suspended acoustic ceiling tiles, fiberglass boards, film faced, thermal, 2' x 2' or 2' x 4' x 3" thick, R11	13,191	SF	3.43	\$45,245
U	221113239430	Pipe, sub assemblies used in assembly systems, chilled water distribution piping, per ton, less than 61 ton systems	299	SYSTE M	73.50	\$21,952
U	230713103170	Duct thermal insulation, blanket type, fiberglass, flexible, FSK vapor barrier wrap, .75 lb. density, 1-1/2" thick	13,191	SF	3.95	\$52,104
U	260580100150	Motor connections, flexible conduit and fittings, 3 phase, 230 volt, 15 HP motor	12	Ea.	226.00	\$2,812
U	238219100160	Fan coil A.C., cabinet mounted, chilled water, 2.5 ton cooling, includes filters and controls	12	Ea.	2,225.00	\$27,689
U	220505102050	Pipe, metal pipe, 2" to 3-1/2" diam., selective demolition	1,991	LF	4.79	\$9,537
U	220505102186	Pump, 7-1/2 H.P. thru 15 H.P., selective demolition	7	Ea.	515.00	\$3,845
U	230505109000	HVAC, selective demolition, minimum labor/equipment charge	37	Job	680.00	\$25,386
			s	ub Total		\$255,054
		Cons	truction Ac	ljustment	35%	87,994
			Constructi	ion Cost		\$343,048
			Adjustme	nt Factor	0%	0
		s	oft Cost Ac	ljustment	48%	166,207
		Total	Estimated	Amount		\$509,255

Fairway Elementary School

290

M-A-P-P-S ©, Jacobs 2016

Page 233 of 624

Broward County Public Schools

Fairway Elementary School

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->CR

Deficiency:

290

Assess ID 73314 Surveyor/Update Ajai Fraser

Defeciency Code ID M52-01

Status Estimated FCI Yes

Life Cycle

Deficiency Test And Balancing Required

Category Deferred Maintenance System Mechanical

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Fix HVAC Test/Adjust/Balance Quantity / UoM

Project(s) Note

Estimate:

	acc.					
Туре	Number	Description	Qty	UoM	Price	Extension
U	230593101400	Balancing, air, heating and ventilating equipment, roof exhaust fan, (Subcontractor's quote including material & labor)	6	Ea.	267.00	\$1,674
U	230593103600	Balancing, air conditioning equipment, supply, return, exhaust, registers and diffusers, laboratory fume hood, (Subcontractor's quote including material & labor)		Ea.	400.00	\$2,507
U	230593104500	Balancing, taps into ceiling plenums, (Subcontractor's quote including material & labor)	31	Ea.	100.00	\$3,134
U	230593102400	Balancing, air conditioning equipment, central station, built-up variable volume, (Subcontractor's quote including material & labor)	2	Ea.	1,750.00	\$2,742
U	230593104600	Balancing, air conditioning equipment, supply, return, exhaust, registers and diffusers, variable volume boxes, (Subcontractor quote including material & labor)		Ea.	80.00	\$2,507
			s	ub Total		\$12,565
			Construction Ac	ljustment	35%	4,335
			Constructi	ion Cost		\$16,900
			Adjustme	nt Factor	0%	0
			Soft Cost Ac	ljustment	48%	8,188
		To	tal Estimated	Amount	_	\$25,088
					_	

Fairway Elementary School

290

M-A-P-P-S ©, Jacobs 2016

Page 275 of 624

P-0016xx

RFQ Number: 16-182C Miramar FL 33023

Broward County Public Schools

Fairway Elementary School

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->CR

Deficiency:

290

Assess ID 73315 Surveyor/Update Ajai Fraser

Defeciency Code ID M54-03

Status Estimated FCI Yes

Life Cycle 22750

Deficiency Controls Are Inadequate And Should Be Replaced With DDC Controls

Category Capital Renewal System Mechanical

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Replace DDC HVAC Controls Quantity / UoM

Project(s) Note **Estimate:**

Fairway Elementary School 290
Page 251 of 624

M-A-P-P-S ©, Jacobs 2016

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

290 **Fairway Elementary School** Location: Fairway ES->CR

Deficiency:

Assess ID 73317 Surveyor/Update Abigail Zerbe

Defeciency Code ID M57-02C

Status **Estimated** FCI Yes

Life Cycle 22754

Deficiency The Air Handler HVAC Component Requires Replacement

Category Capital Renewal Mechanical

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Replace 5000 CFM Air Handler Quantity / UoM

Project(s) Note

Estimate:

LJuiii	ate.					
Туре	Number	Description	Qty	UoM	Price	Extension
U	015419500100	Crane crew, daily use for small jobs, 12-ton truck-mounted hydraulic crane, portal to portal	3	Day	1,600.00	\$4,800
U	233113131030	Metal ductwork, fabricated rectangular, 500 to 1000 lb., stainless steel, type 304, includes fittings, joints, supports and allow for a flexible connections field sketches, excludes as-built drawings and insulation	750	Lb	13.40	\$10,050
U	237313202340	Central station air handling unit, packaged indoor, variable air volume, 5000 CFM, cooling coils may be chilled water or DX, heating coils may be hot water, steam or electric	3	Ea.	26,000.00	\$78,000
U	230505100400	Central station air handler, up thru 15 ton, selective demolition	3	Ea.	820.00	\$2,460
U	260580101590	Motor connections, flexible conduit and fittings, 3 phase, 460 volt, 100 HP motor	3	Ea.	330.00	\$990
М		Adjustment	1	Ea.	400.00	\$400
			S	ub Total		\$96,700
		Cons	struction Ad	djustment	35%	33,361
			Construct	ion Cost		\$130,061
			Adjustme	nt Factor	0%	0
		s	oft Cost Ad	djustment	48%	63,015
		Total	Estimated	Amount		\$193,076

Fairway Elementary School

M-A-P-P-S ©, Jacobs 2016

Page 269 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->CR

Deficiency:

290

Assess ID 73318 Surveyor/Update Ajai Fraser

Defeciency Code ID M57-21c

Status Estimated FCI Yes

Life Cycle 22753

Deficiency Duct Heater Requires Replacement

Fairway Elementary School

Category Capital Renewal System Mechanical

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Learning Environment

Correction Replace Duct Heater Quantity / UoM

Project(s) Note

Estimate:

_5um	ale.				
Туре	Number	Description	Qty UoM	Price	Extension
U	238216200360	Duct heater, electric, finned tubular insert, 480 V, 3Ph., 500Deg.F, 26.7 kW, 12" wide x 24" high	3 Ea.	2,825.00	\$8,475
U	230505101850	Air conditioner, duct heater, electric strip, selective demolition, minimum labor/equipment charge	3 Job	161.00	\$483
			Sub Total		\$8,958
		Constr	uction Adjustment	35%	3,091
		C	onstruction Cost		\$12,049
		,	Adjustment Factor	0%	0
		Sof	t Cost Adjustment	48%	5,838
		Total E	stimated Amount		\$17,886

Fairway Elementary School

290

M•A•P•P•S ©, Jacobs 2016

Page 226 of 624

Broward County Public Schools

Deficiency Detail

Ajai Fraser

2/4/2016 3:36 PM

290 **Fairway Elementary School** Location: Fairway ES->Bldg 4

Deficiency:

Assess ID 73335

Defeciency Code ID M20-03

Surveyor/Update

Status **Estimated** FCI Yes

Life Cycle

Deficiency The 2 X 2 Exhausts/Hoods Require Replacement

Category **Deferred Maintenance** Mechanical

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Non Related

Correction Replace Exhaust/Hoods (2'X2') Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
U	230505102120	Fans, up thru 1 H.P. or 2000 CFM, selective demolition	2 Ea.	155.00	\$310
U	233416105520	Fans, industrial exhauster, 1000 CFM, 1-1/2 H.P.	2 Ea.	3,700.00	\$7,400
			Sub Total	Sub Total	
			Construction Adjustment	35%	2,660
			Construction Cost		\$10,370
			Adjustment Factor	0%	0
			Soft Cost Adjustment	48%	5,024
			Total Estimated Amount		\$15,394

Fairway Elementary School

M-A-P-P-S ©, Jacobs 2016

Page 283 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

290 **Fairway Elementary School**

Fairway ES->Bldg 4 Location:

Deficiency:

Assess ID 73336 Surveyor/Update Ajai Fraser

Defeciency Code ID M29-03

Status **Estimated** FCI Yes

Life Cycle 22766

Deficiency Package Roof Top Unit Requires Replacement

Category Capital Renewal System Mechanical

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Replace 5 Ton Packaged RTU Quantity / UoM

Project(s) Note

Estimate:

∟5uiii	ate.					
Туре	Number	Description	Qty	UoM	Price	Extension
U	230505105100	Rooftop air conditioner, up thru 10 ton, selective demolition	1	Ea.	940.00	\$940
U	260580101500	Motor connections, flexible conduit and fittings, 3 phase, 460 volt, 5 HP motor	1	Ea.	91.00	\$91
U	015436502200	Mobilization or demobilization, crane, crawler-mounted, up to 75 ton	1	Ea.	1,125.00	\$1,125
U	237433101140	Rooftop air conditioner, single zone, electric cool, gas heat, 5 ton cooling, 112 MBH heating, includes, standard controls, curb and economizer	1	Ea.	8,150.00	\$8,150
			S	Sub Total		\$10,306
		Constru	uction Ad	djustment	35%	3,556
		Co	onstruct	ion Cost		\$13,862
		A	Adjustme	nt Factor	0%	0
		Sofi	t Cost Ad	djustment	48%	6,716
		Total Es	stimated	Amount		\$20,578

Fairway Elementary School

M-A-P-P-S ©, Jacobs 2016

Page 272 of 624

Broward County Public Schools

Fairway Elementary School

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->Bldg 4

Deficiency:

290

Assess ID 73338 Surveyor/Update Ajai Fraser

Defeciency Code ID M52-01

Status Estimated FCI Yes

Life Cycle

Deficiency Test And Balancing Required

Category Deferred Maintenance System Mechanical

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Fix HVAC Test/Adjust/Balance Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty	UoM	Price	Extension
U	230593101400	Balancing, air, heating and ventilating equipment, roof exhaust fan, (Subcontractor's quote including material & labor)	3	Ea.	267.00	\$833
U	230593103600	Balancing, air conditioning equipment, supply, return, exhaust, registers and diffusers, laboratory fume hood, (Subcontractor's quote including material & labor)	3	Ea.	400.00	\$1,248
U	230593104500	Balancing, taps into ceiling plenums, (Subcontractor's quote including material & labor)	16	Ea.	100.00	\$1,560
U	230593102400	Balancing, air conditioning equipment, central station, built-up variable volume, (Subcontractor's quote including material & labor)	1	Ea.	1,750.00	\$1,365
U	230593104600	Balancing, air conditioning equipment, supply, return, exhaust, registers and diffusers, variable volume boxes, (Subcontractor quote including material & labor)		Ea.	80.00	\$1,248
			s	ub Total		\$6,253
		C	onstruction Ad	justment	35%	2,157
			Constructi	on Cost		\$8,411
			Adjustmer	nt Factor	0%	0
			Soft Cost Ad	justment	48%	4,075
		То	tal Estimated	Amount		\$12,486

Fairway Elementary School

290

M-A-P-P-S ©, Jacobs 2016

Page 276 of 624

Broward County Public Schools

Deficiency Detail

Ajai Fraser

2/4/2016 3:36 PM

290 **Fairway Elementary School** Location: Fairway ES->Bldg 4

Deficiency:

Assess ID 73339

Defeciency Code ID M54-03

Status **Estimated** FCI Yes

Life Cycle 22763

Deficiency Controls Are Inadequate And Should Be Replaced With DDC Controls

Category Capital Renewal System Mechanical

Surveyor/Update

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Replace DDC HVAC Controls Quantity / UoM

Project(s) Note Estimate:

Fairway Elementary School

M-A-P-P-S ©, Jacobs 2016 Page 249 of 624 RFQ Number: 16-182C

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

290 Fairway Elementary School
Location: Fairway ES->Bldg 4

Deficiency:

Assess ID 73341 Surveyor/Update Ajai Fraser

Defeciency Code ID M57-02C

Status Estimated FCI Yes

Life Cycle 22767

Deficiency The Air Handler HVAC Component Requires Replacement

Category Capital Renewal System Mechanical

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Replace 5000 CFM Air Handler Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	237313202340	Central station air handling unit, packaged indoor, variable air volume, 5000 CFM, cooling coils may be chilled water or DX, heating coils may be hot water, steam or electric	1	Ea.	26,000.00	\$26,000
U	230505100400	Central station air handler, up thru 15 ton, selective demolition	1	Ea.	820.00	\$820
U	015419500100	Crane crew, daily use for small jobs, 12-ton truck-mounted hydraulic crane, portal to portal	1	Day	1,600.00	\$1,600
U	233113131030	Metal ductwork, fabricated rectangular, 500 to 1000 lb., stainless steel, type 304, includes fittings, joints, supports and allow for a flexible connections field sketches, excludes as-built drawings and insulation	250	Lb	13.40	\$3,350
U	260580101590	Motor connections, flexible conduit and fittings, 3 phase, 460 volt, 100 HP motor	1	Ea.	330.00	\$330
			s	ub Total		\$32,100
		Constr	uction Ad	ljustment	35%	11,074
		c	onstruct	ion Cost		\$43,174
		,	Adjustme	nt Factor	0%	0
		Sof	ft Cost Ad	djustment	48%	20,918
		Total E	stimated	Amount		\$64,093

Fairway Elementary School

290

M•A•P•P•S ©, Jacobs 2016

Page 270 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->Bldg 4

Deficiency:

290

Assess ID 73342 Surveyor/Update Ajai Fraser

Defeciency Code ID M57-21c

Status Estimated FCI Yes

Life Cycle 22768

Deficiency Duct Heater Requires Replacement

Fairway Elementary School

Category Capital Renewal System Mechanical

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Learning Environment

Correction Replace Duct Heater Quantity / UoM

Project(s) Note

Estimate:

_5uiii	ale.					
Туре	Number	Description	Qty	UoM	Price	Extension
U	238216200360	Duct heater, electric, finned tubular insert, 480 V, 3Ph., 500Deg.F, 26.7 kW, 12" wide x 24" high	1	Ea.	2,825.00	\$2,825
U	230505101850	Air conditioner, duct heater, electric strip, selective demolition, minimum labor/equipment charge	1	Job	161.00	\$161
			8	ub Total		\$2,986
		Constr	uction A	djustment	35%	1,030
		C	onstruct	ion Cost		\$4,016
		,	4djustme	nt Factor	0%	0
		Sof	t Cost A	djustment	48%	1,946
		Total E	stimated	Amount		\$5,962

Fairway Elementary School

290

Page 227 of 624

M•A•P•P•S ©, Jacobs 2016

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

290 Fairway Elementary School
Location: Fairway ES->Bldg 5

Deficiency:

Assess ID 73348

Surveyor/Update

FCI

Ajai Fraser

Defeciency Code ID M52-01
Status Estimated

Yes

Life Cycle

Deficiency Test And Balancing Required

Category Deferred Maintenance System Mechanical

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Fix HVAC Test/Adjust/Balance Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty	UoM	Price	Extension
U	230593101400	Balancing, air, heating and ventilating equipment, roof exhaust fan, (Subcontractor's quote including material & labor)	7	Ea.	267.00	\$1,972
U	230593103600	Balancing, air conditioning equipment, supply, return, exhaust, registers and diffusers, laboratory fume hood, (Subcontractor's quote including material & labor)		Ea.	400.00	\$2,954
U	230593104500	Balancing, taps into ceiling plenums, (Subcontractor's quote including material & labor)	37	Ea.	100.00	\$3,692
U	230593102400	Balancing, air conditioning equipment, central station, built-up variable volume, (Subcontractor's quote including material & labor)	2	Ea.	1,750.00	\$3,231
U	230593104600	Balancing, air conditioning equipment, supply, return, exhaust, registers and diffusers, variable volume boxes, (Subcontractor quote including material & labor)		Ea.	80.00	\$2,954
			s	ub Total		\$14,802
			Construction Ac	ljustment	35%	5,107
			Constructi	ion Cost		\$19,909
			Adjustme	nt Factor	0%	0
			Soft Cost Ac	ljustment	46%	9,074
		Тс	tal Estimated	Amount		\$28,983

Fairway Elementary School

290

M•A•P•P•S ©, Jacobs 2016

Page 277 of 624

RFQ Number: 16-182C

Broward County Public Schools

Fairway Elementary School

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->Bldg 5

Deficiency:

290

Assess ID 73349 Surveyor/Update Ajai Fraser

Defeciency Code ID M54-03

Status Estimated FCI Yes

Life Cycle 22854

Deficiency Controls Are Inadequate And Should Be Replaced With DDC Controls

Category Capital Renewal System Mechanical

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Replace DDC HVAC Controls Quantity / UoM

Project(s) Note **Estimate:**

Fairway Elementary School 290 Page 255 of 624

M-A-P-P-S ©, Jacobs 2016



Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

290 Fairway Elementary School
Location: Fairway ES->Bldg 5

Deficiency:

Assess ID 73351 Surveyor/Update Ajai Fraser

Defeciency Code ID M57-02C

Status Estimated FCI Yes

Life Cycle 22862

Deficiency The Air Handler HVAC Component Requires Replacement

Category Capital Renewal System Mechanical

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Replace 5000 CFM Air Handler Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty	UoM	Price	Extension
U	237313202340	Central station air handling unit, packaged indoor, variable air volume, 5000 CFM, cooling coils may be chilled water or DX, heating coils may be hot water, steam or electric	2	Ea.	26,000.00	\$52,000
U	230505100400	Central station air handler, up thru 15 ton, selective demolition	2	Ea.	820.00	\$1,640
U	015419500100	Crane crew, daily use for small jobs, 12-ton truck-mounted hydraulic crane, portal to portal	2	Day	1,600.00	\$3,200
U	233113131030	Metal ductwork, fabricated rectangular, 500 to 1000 lb., stainless steel, type 304, includes fittings, joints, supports and allow for a flexible connections field sketches, excludes as-built drawings and insulation	500	Lb	13.40	\$6,700
U	260580101590	Motor connections, flexible conduit and fittings, 3 phase, 460 volt, 100 HP motor	2	Ea.	330.00	\$660
			s	ub Total		\$64,200
		Constru	uction Ac	ljustment	35%	22,149
		Co	onstructi	ion Cost		\$86,349
		A	Adjustme	nt Factor	0%	0
		Sofi	t Cost Ac	djustment	46%	39,358
		Total Es	stimated	Amount		\$125,707

Fairway Elementary School

Page 267 of 624

M-A-P-P-S ©, Jacobs 2016

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->Bldg 5

Deficiency:

290

Assess ID 73352 Surveyor/Update Ajai Fraser

Defeciency Code ID M57-21c

Status Estimated FCI Yes

Life Cycle 22863

Deficiency Duct Heater Requires Replacement

Fairway Elementary School

Category Capital Renewal System Mechanical

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Learning Environment

Correction Replace Duct Heater Quantity / UoM

Project(s) Note

Estimate:

_5uiii	ate.				
Type	Number	Description	Qty UoM	Price	Extension
U	238216200360	Duct heater, electric, finned tubular insert, 480 V, 3Ph., 500Deg.F, 26.7 kW, 12" wide x 24" high	2 Ea.	2,825.00	\$5,650
U	230505101850	Air conditioner, duct heater, electric strip, selective demolition, minimum labor/equipment charge	2 Job	161.00	\$322
			Sub Total		\$5,972
		Constr	uction Adjustment	35%	2,060
		С	onstruction Cost		\$8,032
		,	Adjustment Factor 0%		0
		Sot	ft Cost Adjustment	46%	3,661
		Total E	stimated Amount		\$11,693

Fairway Elementary School

290

M-A-P-P-S ©, Jacobs 2016

Page 224 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

290 Fairway Elementary School
Location: Fairway ES->Bldg 6

Deficiency:

Assess ID 73444 Surveyor/Update Ajai Fraser

Defeciency Code ID M20-03

Status Estimated FCI Yes

Life Cycle

Deficiency The 2 X 2 Exhausts/Hoods Require Replacement

Category Deferred Maintenance System Mechanical

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Non Related

Correction Replace Exhaust/Hoods (2'X2') Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
U	230505102120	Fans, up thru 1 H.P. or 2000 CFM, selective demolition	2 Ea.	155.00	\$310
U	233416105520	Fans, industrial exhauster, 1000 CFM, 1-1/2 H.P.	2 Ea.	3,700.00	\$7,400
			Sub Total	Sub Total	
			Construction Adjustment	35%	2,660
			Construction Cost		\$10,370
			Adjustment Factor	0%	0
			Soft Cost Adjustment	46%	4,727
			Total Estimated Amount		\$15,097

Fairway Elementary School

290

M-A-P-P-S ©, Jacobs 2016

Page 282 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

290 Fairway Elementary School
Location: Fairway ES->Bldg 6

Deficiency:

Assess ID 73445 Surveyor/Update Ajai Fraser

Defeciency Code ID M60-03

Status Estimated FCI Yes

Life Cycle

Deficiency Exhaust Fan Ventilation Requires Replacement

Category Capital Renewal System Mechanical

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Replace Exhaust Fan Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
U	230505102120	Fans, up thru 1 H.P. or 2000 CFM, selective demolition	1 Ea.	155.00	\$155
U	233423106180	Fans, propeller exhaust, wall shutter, direct drive, 1/4" S.P., two speed, 3275 CFM, 1/2 H.P.	1 Ea.	1,050.00	\$1,050
			Sub Total		\$1,205
		Construction Adjustment			
			Construction Cost		\$1,621
			Adjustment Factor	0%	0
		Sc	oft Cost Adjustment	46%	739
		Total E	stimated Amount		\$2,359

Fairway Elementary School

290

M-A-P-P-S ©, Jacobs 2016

Page 264 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

290 Fairway Elementary School
Location: Fairway ES->Bldg 6

Deficiency:

Assess ID 73447

Surveyor/Update

Ajai Fraser

Defeciency Code ID M58-01
Status Estimated

FCI

Yes

Life Cycle

Deficiency Kitchen Air/Exhaust is missing and is needed

Category Functional Deficiency System Mechanical

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Non Related

Correction Install Kitchen Air/Exhaust Hood Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty	UoM	Price	Extension
М	015433602400	Rent crane truck mounted, hydraulic, 12 ton capacity	1	Day	595.62	\$298
U	260580102045	Motor connections, flexible conduit and fittings, 3 phase, sealtite, 460 volt, 100 HP motor	2	Ea.	370.00	\$740
U	237423161060	Make-up air unit, indirect-fired, rooftop unit, natural gas, gravity vent, stainless steel exchanger, MBH is output, 70Deg.F temperature rise, 550 MBH, includes standard controls	1	Ea.	20,000.00	\$20,000
U	233813102980	Exhaust hood, commercial kitchen equipment, stainless steel, gutter on all sides, 4' x 4' x 7'	1	Ea.	8,550.00	\$8,550
			s	ub Total		\$29,588
		Con	struction Ad	ljustment	35%	10,208
			Construct	ion Cost		\$39,796
			Adjustme	nt Factor	0%	0
			Soft Cost Ad	ljustment	46%	18,139
		Total	Estimated	Amount		\$57,934

Fairway Elementary School

290

M•A•P•P•S ©, Jacobs 2016

Page 280 of 624

Broward County Public Schools

Fairway Elementary School

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->Bldg 6

Deficiency:

290

Assess ID 73448 Surveyor/Update Ajai Fraser

Defeciency Code ID M52-01

Status Estimated FCI Yes

Life Cycle

Deficiency Test And Balancing Required

Category Deferred Maintenance System Mechanical

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Fix HVAC Test/Adjust/Balance Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty	UoM	Price	Extension
U	230593101400	Balancing, air, heating and ventilating equipment, roof exhaust fan, (Subcontractor's quote including material & labor)	6	Ea.	267.00	\$1,714
U	230593103600	Balancing, air conditioning equipment, supply, return, exhaust, registers and diffusers, laboratory fume hood, (Subcontractor's quote including material & labor)		Ea.	400.00	\$2,568
U	230593104500	Balancing, taps into ceiling plenums, (Subcontractor's quote including material & labor)	32	Ea.	100.00	\$3,211
U	230593102400	Balancing, air conditioning equipment, central station, built-up variable volume, (Subcontractor's quote including material & labor)	2	Ea.	1,750.00	\$2,809
U	230593104600	Balancing, air conditioning equipment, supply, return, exhaust, registers and diffusers, variable volume boxes, (Subcontractor quote including material & labor)		Ea.	80.00	\$2,568
			S	ub Total		\$12,871
			Construction Ad	justment	35%	4,441
			Constructi	on Cost		\$17,312
			Adjustmer	nt Factor	0%	0
			Soft Cost Ad	justment	46%	7,891
		То	otal Estimated	Amount		\$25,203

Fairway Elementary School

290

M•A•P•P•S ©, Jacobs 2016

Page 278 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

290 Fairway Elementary School
Location: Fairway ES->Bldg 6

Deficiency:

Assess ID 73451 Surveyor/Update Ajai Fraser

Defeciency Code ID M54-03

Status Estimated FCI Yes

Life Cycle 22916

Deficiency Controls Are Inadequate And Should Be Replaced With DDC Controls

Category Capital Renewal System Mechanical

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Replace DDC HVAC Controls Quantity / UoM

Project(s) Note **Estimate:**

Fairway Elementary School 290
Page 257 of 624

M-A-P-P-S ©, Jacobs 2016

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

290 Fairway Elementary School
Location: Fairway ES->Bldg 6

Deficiency:

Assess ID 73456 Surveyor/Update Ajai Fraser

Defeciency Code ID M57-02C

Status Estimated FCI Yes

Life Cycle

Deficiency The Air Handler HVAC Component Requires Replacement

Category Capital Renewal System Mechanical

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Replace 5000 CFM Air Handler Quantity / UoM

Project(s) Note

Estimate:

_5uiii	ate.					
Туре	Number	Description	Qty	UoM	Price	Extension
U	237313202340	Central station air handling unit, packaged indoor, variable air volume, 5000 CFM, cooling coils may be chilled water or DX, heating coils may be hot water, steam or electric	1	Ea.	26,000.00	\$26,000
U	230505100400	Central station air handler, up thru 15 ton, selective demolition	1	Ea.	820.00	\$820
U	015419500100	Crane crew, daily use for small jobs, 12-ton truck-mounted hydraulic crane, portal to portal	1	Day	1,600.00	\$1,600
U	233113131030	Metal ductwork, fabricated rectangular, 500 to 1000 lb., stainless steel, type 304, includes fittings, joints, supports and allow for a flexible connections field sketches, excludes as-built drawings and insulation	250	Lb	13.40	\$3,350
U	260580101590	Motor connections, flexible conduit and fittings, 3 phase, 460 volt, 100 HP motor	1	Ea.	330.00	\$330
			s	ub Total		\$32,100
		Constru	uction Ad	ljustment	35%	11,074
		Co	nstruct	ion Cost		\$43,174
		A	djustme	nt Factor	0%	0
		Sofi	Cost Ac	ljustment	46%	19,679
		Total Es	timated	Amount		\$62,853

Fairway Elementary School

290

M-A-P-P-S ©, Jacobs 2016

Page 268 of 624

Broward County Public Schools

Deficiency Detail

Ajai Fraser

2/4/2016 3:36 PM

290 **Fairway Elementary School** Fairway ES->Bldg 6 Location:

Deficiency:

Assess ID 73458 Surveyor/Update

Defeciency Code ID M57-21c

Status **Estimated** FCI Yes

Life Cycle

Deficiency **Duct Heater Requires Replacement**

Category Capital Renewal System Mechanical

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Learning Environment

Correction Replace Duct Heater Quantity / UoM

Project(s) Note

Estimate:

_5uiii	ate.					
Type	Number	Description	Qty	UoM	Price	Extension
U	238216200360	Duct heater, electric, finned tubular insert, 480 V, 3Ph., 500Deg.F, 26.7 kW, 12" wide x 24" high	1	Ea.	2,825.00	\$2,825
U	230505101850	Air conditioner, duct heater, electric strip, selective demolition, minimum labor/equipment charge	1	Job	161.00	\$161
			5	Sub Total		\$2,986
		Constr	uction A	djustment	35%	1,030
		С	onstruct	ion Cost		\$4,016
		,	Adjustment Factor 0%		0%	0
		Sot	ft Cost A	djustment	46%	1,831
		Total E	stimated	Amount		\$5,847

Fairway Elementary School

M-A-P-P-S ©, Jacobs 2016

Page 225 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

290 Fairway Elementary School
Location: Fairway ES->Bldg 7

Deficiency:

Assess ID 73524 Surveyor/Update Ajai Fraser

Defeciency Code ID M20-01

Status Estimated FCI Yes

Life Cycle

Deficiency The Small Diameter Exhausts/Hoods Require Replacement

Category Deferred Maintenance System Mechanical

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Replace Roof Exhaust/Hoods (<1' Dia) Quantity / UoM

Project(s) Note

Estimate:

	acc.				
Туре	Number	Description	Qty UoM	Price	Extension
U	260580100020	Motor connections, flexible conduit and fittings, 1 phase, 115 volt, up to 1 HP motor	2 Ea.	90.50	\$181
U	230505102120	Fans, up thru 1 H.P. or 2000 CFM, selective demolition	2 Ea.	155.00	\$310
U	233416107120	Fans, roof exhauster, centrifugal, aluminum housing, bird screen, back draft damper, direct drive, 1/4" S.P., 600 CFM, 12" galvanized curb, 11" sq. damper	2 Ea.	1,200.00	\$2,400
			Sub Total		\$2,891
		Constru	iction Adjustment	35%	997
		Co	nstruction Cost		\$3,888
		A	djustment Factor	0%	0
		Soft	Cost Adjustment	46%	1,772
		Total Es	timated Amount		\$5,661
				_	$\overline{}$

Fairway Elementary School

290

M-A-P-P-S ©, Jacobs 2016

Page 281 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

290 Fairway Elementary School
Location: Fairway ES->Bldg 7

Deficiency:

Assess ID 73527 Surveyor/Update Ajai Fraser

Defeciency Code ID M52-01

Status Estimated FCI Yes

Life Cycle

Deficiency Test And Balancing Required

Category Deferred Maintenance System Mechanical

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Fix HVAC Test/Adjust/Balance Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty	UoM	Price	Extension
U	230593101400	Balancing, air, heating and ventilating equipment, roof exhaust fan, (Subcontractor's quote including material & labor)	2	Ea.	267.00	\$537
U	230593103600	Balancing, air conditioning equipment, supply, return, exhaust, registers and diffusers, laboratory fume hood, (Subcontractor's quote including material & labor)		Ea.	400.00	\$804
U	230593104500	Balancing, taps into ceiling plenums, (Subcontractor's quote including material & labor)	10	Ea.	100.00	\$1,005
U	230593102400	Balancing, air conditioning equipment, central station, built-up variable volume, (Subcontractor's quote including material & labor)	1	Ea.	1,750.00	\$879
U	230593104600	Balancing, air conditioning equipment, supply, return, exhaust, registers and diffusers, variable volume boxes, (Subcontractor quote including material & labor)		Ea.	80.00	\$804
			s	ub Total		\$4,028
			Construction Ad	ljustment	35%	1,390
			Constructi	ion Cost		\$5,418
			Adjustme	nt Factor	0%	0
			Soft Cost Ad	ljustment	46%	2,470
		Тс	otal Estimated	Amount	_	\$7,888

Fairway Elementary School

290

M•A•P•P•S ©, Jacobs 2016

Page 279 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

290 **Fairway Elementary School** Location: Fairway ES->Bldg 7

Deficiency:

Assess ID

Life Cycle

Category

73529

Surveyor/Update Ajai Fraser

Defeciency Code ID M54-03 Status

Estimated

FCI Yes

22928

Deficiency Controls Are Inadequate And Should Be Replaced With DDC Controls

> Capital Renewal System Mechanical

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Replace DDC HVAC Controls Quantity / UoM

Project(s) Note Estimate:

Fairway Elementary School

M-A-P-P-S ©, Jacobs 2016

Page 259 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

290 **Fairway Elementary School**

Fairway ES->Bldg 7 Location:

Deficiency:

Assess ID 73536 Surveyor/Update Ajai Fraser

Defeciency Code ID M57-02C

Status **Estimated** FCI Yes

Life Cycle 22938

Deficiency The Air Handler HVAC Component Requires Replacement

Category Capital Renewal Mechanical

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Replace 5000 CFM Air Handler Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty	UoM	Price	Extension
U	237313202340	Central station air handling unit, packaged indoor, variable air volume, 5000 CFM, cooling coils may be chilled water or DX, heating coils may be hot water, steam or electric	1	Ea.	26,000.00	\$26,000
U	230505100400	Central station air handler, up thru 15 ton, selective demolition	1	Ea.	820.00	\$820
U	015419500100	Crane crew, daily use for small jobs, 12-ton truck-mounted hydraulic crane, portal to portal	1	Day	1,600.00	\$1,600
U	233113131030	Metal ductwork, fabricated rectangular, 500 to 1000 lb., stainless steel, type 304, includes fittings, joints, supports and allow for a flexible connections field sketches, excludes as-built drawings and insulation	250	Lb	13.40	\$3,350
U	260580101590	Motor connections, flexible conduit and fittings, 3 phase, 460 volt, 100 HP motor	1	Ea.	330.00	\$330
			s	ub Total		\$32,100
		Constru	uction Ad	ljustment	35%	11,074
		Co	nstruct	ion Cost		\$43,174
		A	djustme	nt Factor	0%	0
		Soft	Cost Ac	ljustment	46%	19,679
		Total Es	timated	Amount	_	\$62,853

Fairway Elementary School

M-A-P-P-S ©, Jacobs 2016

Page 271 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->Bldg 7

Deficiency:

290

Assess ID 73537 Surveyor/Update Ajai Fraser

Defeciency Code ID M57-21c

Status **Estimated** FCI Yes

Life Cycle

Deficiency **Duct Heater Requires Replacement**

Fairway Elementary School

Category Capital Renewal System Mechanical

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Learning Environment

Correction Replace Duct Heater Quantity / UoM

Project(s) Note

Estimate:

Latin	ate.				
Type	Number	Description	Qty UoM	Price	Extension
U	238216200360	Duct heater, electric, finned tubular insert, 480 V, 3Ph., 500Deg.F, 26.7 kW, 12" wide x 24" high	1 Ea.	2,825.00	\$2,825
U	230505101850	Air conditioner, duct heater, electric strip, selective demolition, minimum labor/equipment charge	1 Job	161.00	\$161
			Sub Total		\$2,986
		Const	ruction Adjustment	35%	1,030
		C	onstruction Cost		\$4,016
			Adjustment Factor 0%		0
		So	ft Cost Adjustment	46%	1,831
		Total E	stimated Amount		\$5,847

Fairway Elementary School

M-A-P-P-S ©, Jacobs 2016

Page 228 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

290 Fairway Elementary School
Location: Fairway ES->Sto

Deficiency:

Assess ID 73584 Surveyor/Update Ajai Fraser

Defeciency Code ID M60-03

Status Estimated FCI Yes

Life Cycle 22944

Deficiency Exhaust Fan Ventilation Requires Replacement

Category Capital Renewal System Mechanical

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Replace Exhaust Fan Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
U	230505102120	Fans, up thru 1 H.P. or 2000 CFM, selective demolition	2 Ea.	155.00	\$310
U	233423106180	Fans, propeller exhaust, wall shutter, direct drive, 1/4" S.P., two speed, 3275 CFM, 1/2 H.P.	2 Ea.	1,050.00	\$2,100
			Sub Total	Sub Total	
		Const	ruction Adjustment	35%	831
			Construction Cost		\$3,241
			Adjustment Factor	0%	0
		Sc	oft Cost Adjustment	46%	1,477
		Total E	stimated Amount		\$4,719

Fairway Elementary School

290

M-A-P-P-S ©, Jacobs 2016

Page 263 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->CR

Deficiency:

290

Assess ID 73601 Surveyor/Update Ajai Fraser

Defeciency Code ID M02-03

Status Estimated FCI Yes

Life Cycle

Deficiency The Exterior Condenser Requires Replacement

Fairway Elementary School

Category Capital Renewal System Mechanical

Priority 1-Mission Critical Concerns Functional Adequacy Non Related

Correction Replace 3 ton Exterior Condenser Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
U	236313101630	Condenser, ratings are for air cooled, direct drive, propeller fan, 30Deg.F temperature difference, 3 ton, R-22	1 Ea.	1,725.00	\$1,725
U	230505109000	HVAC, selective demolition, minimum labor/equipment charge	1 Job	680.00	\$680
			Sub Total		\$2,405
		Constru	uction Adjustment	35%	830
		Co	onstruction Cost		\$3,235
		<i>A</i>	Adjustment Factor	0%	0
		Sof	t Cost Adjustment	42%	1,373
		Total Es	stimated Amount		\$4,608

Fairway Elementary School

290

M•A•P•P•S ©, Jacobs 2016

Page 229 of 624

Broward County Public Schools

Fairway Elementary School

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->CR

Deficiency:

290

Assess ID 73605 Surveyor/Update Ajai Fraser

Defeciency Code ID M57-01C

Status **Estimated** FCI Yes

Life Cycle

The Package Unit HVAC Component Requires Replacement Deficiency

Category Capital Renewal System Mechanical

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Replace packaged HVAC Unit Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty	UoM	Price	Extension
М	015433602500	Rent crane truck mounted, hydraulic, 25 ton capacity	0	Day	615.31	\$70
М	D30502011010	A/C packaged, DX, air cooled, electric heat, constant volume, 5 ton	0	Ea.	9,822.62	\$3,929
U	233723104250	Ventilator, stationary mushroom, aluminum, 42" orifice diameter, includes base	0	Ea.	2,950.00	\$1,180
U	230505109000	HVAC, selective demolition, minimum labor/equipment charge	0	Job	680.00	\$311
			s	ub Total		\$5,490
		Constru	action Ac	ljustment	35%	1,894
		Co	nstructi	ion Cost		\$7,384
		A	djustme	nt Factor	0%	0
		Sofi	Cost Ac	ljustment	42%	3,134
		Total Es	timated	Amount		\$10,518

Fairway Elementary School

M-A-P-P-S ©, Jacobs 2016

Page 261 of 624

Broward County Public Schools

Deficiency Detail

Ajai Fraser

2/4/2016 3:36 PM

290 Fairway Elementary School
Location: Fairway ES->CR

Deficiency:

Assess ID 73626

Defeciency Code ID M02-03

Status Estimated FCI Yes

Life Cycle

Deficiency The Exterior Condenser Requires Replacement

Category Capital Renewal System Mechanical

Priority 1-Mission Critical Concerns Functional Adequacy Non Related

Correction Replace 3 ton Exterior Condenser Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
U	236313101630	Condenser, ratings are for air cooled, direct drive, propeller fan, 30Deg.F temperature difference, 3 ton, R-22	1 Ea.	1,725.00	\$1,725
U	230505109000	HVAC, selective demolition, minimum labor/equipment charge	1 Job	680.00	\$680
			Sub Total		\$2,405
		Constr	ruction Adjustment	35%	830
		c	onstruction Cost		\$3,235
			Adjustment Factor	0%	0
		So	ft Cost Adjustment	42%	1,373
		Total E	stimated Amount		\$4,608

Surveyor/Update

Broward County Public Schools

Fairway Elementary School

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->CR

Deficiency:

290

Assess ID 73628 Surveyor/Update Ajai Fraser

Defeciency Code ID M57-01C

Status Estimated FCI Yes

Life Cycle

Deficiency The Package Unit HVAC Component Requires Replacement

Category Capital Renewal System Mechanical

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Replace packaged HVAC Unit Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty	UoM	Price	Extension
М	015433602500	Rent crane truck mounted, hydraulic, 25 ton capacity	0	Day	615.31	\$70
М	D30502011010	A/C packaged, DX, air cooled, electric heat, constant volume, 5 ton	0	Ea.	9,822.62	\$3,929
U	233723104250	Ventilator, stationary mushroom, aluminum, 42" orifice diameter, includes base	0	Ea.	2,950.00	\$1,180
U	230505109000	HVAC, selective demolition, minimum labor/equipment charge	0	Job	680.00	\$311
			s	ub Total		\$5,490
		Constru	uction Ac	ljustment	35%	1,894
		Co	onstructi	ion Cost		\$7,384
		A	Adjustme	nt Factor	0%	0
		Soft	t Cost Ac	ljustment	42%	3,134
		Total Es	stimated	Amount		\$10,518

Fairway Elementary School

290

M-A-P-P-S ©, Jacobs 2016

Page 262 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

290 Fairway Elementary School

Location: Fairway ES->CR

Deficiency:

Assess ID 74061 Surveyor/Update Ajai Fraser

Defeciency Code ID A26-01

Status Estimated FCI Yes

Life Cycle

Deficiency The Exterior Requires Painting

Category Capital Renewal System Exterior

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Paint Building Exterior Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty	UoM	Price	Extension
U	099123528400	Paints & coatings, miscellaneous interior, cornice, ornate design, paint 1 coat, oil base, brushwork	2,253	SF	1.57	\$3,537
U	099113601800	Paints & coatings, siding, exterior, Texture 1-111 or clapboard, oil base, primer coat, brushwork	15,260	SF	0.93	\$14,192
U	099103300080	Surface preparation, exterior, doors, per side, wire brush, metal, flush, excl. frames or trim	15,260	SF	0.79	\$12,055
			s	ub Total		\$29,784
		Con	struction Ac	justment	35%	10,275
	Construction Cost			\$40,059		
			Adjustme	nt Factor	0%	0
		5	oft Cost Ac	justment	48%	19,373
Total Estimated Amount			_	\$59,432		

Fairway Elementary School

290

M-A-P-P-S ©, Jacobs 2016

Page 10 of 624

RFQ Number: 16-182C

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->CR

Deficiency:

290

Assess ID 74062 Surveyor/Update Ajai Fraser

Defeciency Code ID A30-02

Status Estimated FCI Yes

23472

Life Cycle

Deficiency The Stucco Exterior Requires Repair

Fairway Elementary School

Category Deferred Maintenance System Exterior

Priority 3-Short Term Conditions (2-3 Years) Functional Adequacy Non Related

Correction Repair Stucco Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty L	JoM	Price	Extension
U	070505105620	Selective demolition, thermal and moisture protection, siding, stucco siding	15,260 S	SF.	1.34	\$20,448
U	099113601600	Paints & coatings, siding, exterior, stucco, rough, oil base, paint 2 coats, spray	15,260 S	SF.	0.66	\$10,072
U	092423401000	Stucco, exterior, with bonding agent, 3 coats, on walls, excl. mesh	1,688 S	Ϋ́	17.60	\$29,711
			Sut	Total		\$60,231
		Const	ruction Adju	stment	35%	20,780
		C	onstruction	n Cost		\$81,011
			Adjustment	Factor	0%	0
		So	ft Cost Adju	stment	48%	39,177
		Total E	stimated A	mount		\$120,188

Fairway Elementary School

290

M•A•P•P•S ©, Jacobs 2016

Page 8 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES

Deficiency:

290

Assess ID 220832

Defeciency Code ID FireAlarm-01

Status Estimated FCI Yes

Life Cycle

Deficiency Entire Fire Alarm System Needs to be Replaced

Fairway Elementary School

Category Capital Renewal System Fire and Security

Surveyor/Update

Priority 1-Mission Critical Concerns Functional Adequacy Non Related

Correction Replace Entire Fire Alarm System Quantity / UoM

Project(s) Note Model: 7100

Estimate:

Estimat	te:				
Туре	Number	Description	Qty UoM	Price	Extension
М		Allowance for Fire Alarm Replacement	1 LS	175,000.0 0	\$175,000
			Sub Total		\$175,000
			Construction Adjustment	35%	60,375
			Construction Cost		\$235,375
			Adjustment Factor	0%	0
			Soft Cost Adjustment	42%	99,893
			Total Estimated Amount		\$335,268

Fairway Elementary School

290

M-A-P-P-S ©, Jacobs 2016

Page 462 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

290 **Fairway Elementary School** Location: Fairway ES->CR

Deficiency:

Assess ID 223665

Defeciency Code ID BCRoof-02

Status **Estimated** FCI Yes

Life Cycle

Reroofing with new Decking Required (Broward CPS) Deficiency

Category Capital Renewal Roofing

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Non Related

Correction Reroof and Replace Decking Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty UoM	Price	Extension
М		Estimate based of BCPS experience	13,046 SF	7.25	\$94,584
			Sub Total		\$94,584
			Construction Adjustment	35%	32,631
			Construction Cost		\$127,215
			Adjustment Factor	0%	0
			Soft Cost Adjustment	42%	53,990
			Total Estimated Amount		\$181,205

Surveyor/Update

Fairway Elementary School

M-A-P-P-S ©, Jacobs 2016

Page 20 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

290 **Fairway Elementary School** Location: Fairway ES->CR

Deficiency:

Assess ID 223667

Defeciency Code ID BCRoof-02

Status **Estimated** FCI Yes

Life Cycle

Reroofing with new Decking Required (Broward CPS) Deficiency

Category Capital Renewal Roofing

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Non Related

Correction Reroof and Replace Decking Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty UoM	Price	Extension
М		Estimate based of BCPS experience	13,083 SF	7.25	\$94,852
			Sub Total		\$94,852
			Construction Adjustment	35%	32,724
			Construction Cost		\$127,576
			Adjustment Factor	0%	0
			Soft Cost Adjustment	42%	54,143
			Total Estimated Amount		\$181,719

Surveyor/Update

Fairway Elementary School

Page 21 of 624 M-A-P-P-S ©, Jacobs 2016

Broward County Public Schools

Fairway Elementary School

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->CR

Deficiency:

290

Assess ID 223668 Surveyor/Update Abigail Zerbe

Defeciency Code ID BCRoof-02

Status **Estimated** FCI Yes

Life Cycle

Reroofing with new Decking Required (Broward CPS) Deficiency

Category Capital Renewal Roofing

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Non Related

Correction Reroof and Replace Decking Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty UoM	Price	Extension
М		Estimate based of BCPS experience	16,400 SF	7.25	\$118,900
			Sub Total		\$118,900
			Construction Adjustment	35%	41,020
			Construction Cost		\$159,920
			Adjustment Factor	0%	0
			Soft Cost Adjustment	42%	67,870
			Total Estimated Amount		\$227,791

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

290 Fairway Elementary School
Location: Fairway ES->Bldg 4

Deficiency:

Assess ID 223669 Surveyor/Update

Defeciency Code ID BCRoof-02

Status Estimated FCI Yes

Life Cycle

Deficiency Reroofing with new Decking Required (Broward CPS)

Category Capital Renewal System Roofing

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Non Related

Correction Reroof and Replace Decking Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty UoM	Price	Extension
М		Estimate based of BCPS experience	7,799 SF	7.25	\$56,543
			Sub Total		\$56,543
			Construction Adjustment	35%	19,507
			Construction Cost		\$76,050
			Adjustment Factor	0%	0
			Soft Cost Adjustment	42%	32,276
			Total Estimated Amount		\$108,326

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

290 **Fairway Elementary School** Fairway ES->Bldg 5 Location:

Deficiency:

Assess ID 223670

Defeciency Code ID BCRoof-01

Status **Estimated** FCI Yes

Life Cycle

Reroofing Required (Broward CPS) Deficiency

Category Capital Renewal System Roofing

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Non Related

Correction Reroof Building Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty UoM	Price	Extension
М		Estimate based on BCPS experience	18,461 SF	6.25	\$115,381
			Sub Total		\$115,381
			Construction Adjustment	35%	39,807
			Construction Cost		\$155,188
			Adjustment Factor	0%	0
			Soft Cost Adjustment	42%	65,862
			Total Estimated Amount		\$221,049

Surveyor/Update

Fairway Elementary School

M-A-P-P-S ©, Jacobs 2016

Page 19 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

290 Fairway Elementary School
Location: Fairway ES->Bldg 6

Deficiency:

Assess ID **223672**

Defeciency Code ID BCRoof-01

Status Estimated FCI Yes

Life Cycle

Deficiency Reroofing Required (Broward CPS)

Category Capital Renewal System Roofing

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Non Related

Correction Reroof Building Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
М		Estimate based on BCPS experience	16,053 SF	6.25	\$100,331
			Sub Total		\$100,331
			Construction Adjustment	35%	34,614
			Construction Cost		\$134,946
			Adjustment Factor	0%	0
			Soft Cost Adjustment	42%	57,271
			Total Estimated Amount		\$192,216

Surveyor/Update

290

M-A-P-P-S ©, Jacobs 2016

Page 14 of 624

RFQ Number: 16-182C

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->Bldg 7

Deficiency:

290

Assess ID 223673

Fairway Elementary School

Defeciency Code ID BCRoof-01

Status Estimated FCI Yes

Life Cycle

Deficiency Reroofing Required (Broward CPS)

Category Capital Renewal System Roofing

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Non Related

Correction Reroof Building Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty UoM	Price	Extension
М		Estimate based on BCPS experience	5,024 SF	6.25	\$31,400
			Sub Total		\$31,400
			Construction Adjustment	35%	10,833
			Construction Cost		\$42,233
			Adjustment Factor	0%	0
			Soft Cost Adjustment	42%	17,924
			Total Estimated Amount		\$60,157

Surveyor/Update

Fairway Elementary School

290

M-A-P-P-S ©, Jacobs 2016

Page 15 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->Sto

Deficiency:

290

Assess ID 223674 Surveyor/Update

Fairway Elementary School

Defeciency Code ID BCRoof-01

Status Estimated FCI Yes

Life Cycle

Deficiency Reroofing Required (Broward CPS)

Category Capital Renewal System Roofing

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Non Related

Correction Reroof Building Quantity / UoM

Project(s) Note

Estimate:

Type	Number	Description	Qty UoM	Price	Extension
М		Estimate based on BCPS experience	523 SF	6.25	\$3,269
			Sub Total		\$3,269
			Construction Adjustment	35%	1,128
			Construction Cost		\$4,396
			Adjustment Factor	0%	0
			Soft Cost Adjustment	42%	1,866
			Total Estimated Amount		\$6,262

Fairway Elementary School

290

M-A-P-P-S ©, Jacobs 2016

Page 16 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

Location: Fairway ES->CR

Deficiency:

290

Assess ID 223675

Fairway Elementary School

Defeciency Code ID BCRoof-01

Status Estimated FCI Yes

Life Cycle

Deficiency Reroofing Required (Broward CPS)

Category Capital Renewal System Roofing

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Non Related

Correction Reroof Building Quantity / UoM

Project(s) Note

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
М		Estimate based on BCPS experience	13,028 SF	6.25	\$81,425
			Sub Total		\$81,425
			Construction Adjustment	35%	28,092
			Construction Cost		\$109,517
			Adjustment Factor	0%	0
			Soft Cost Adjustment	42%	46,479
			Total Estimated Amount		\$155,995

Surveyor/Update

Fairway Elementary School

290

M•A•P•P•S ©, Jacobs 2016 Page 17 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

290 **Fairway Elementary School** Fairway ES Location:

Deficiency:

Assess ID 314380 Surveyor/Update

Defeciency Code ID A14-02

Estimated FCI Status Yes

Life Cycle

Deficiency Aluminum Covered Walkways Require Replacement

Category Capital Renewal Roofing

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Non Related

Replace Aluminum Walkway Correction Quantity / UoM

Project(s) Note Originally part of roof replacement deficiency. Pulled out separate to reflect covered walk canopy pricing.

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
U	074113100600	Aluminum roof panels, corrugated, on steel frame, painted, .018 thick	" 5,055 SF	3.71	\$18,754
			Sub Total		\$18,754
		Co	onstruction Adjustment	35%	6,470
			Construction Cost		\$25,224
			Adjustment Factor	0%	0
			Soft Cost Adjustment	42%	10,705
		Tot	al Estimated Amount		\$35,929

Fairway Elementary School

M-A-P-P-S ©, Jacobs 2016

Page 24 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

290 **Fairway Elementary School**

Fairway ES Location:

Deficiency:

Assess ID 314381 Surveyor/Update

Defeciency Code ID A14-02

Estimated FCI Status Yes

Life Cycle

Deficiency Aluminum Covered Walkways Require Replacement

Category Capital Renewal Roofing

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Non Related

Replace Aluminum Walkway Correction Quantity / UoM

Project(s) Note Originally part of roof replacement deficiency. Pulled out separate to reflect covered walk canopy pricing.

Estimate:

Type	Number	Description	Qty UoM	Price	Extension
U	074113100600	Aluminum roof panels, corrugated, on steel frame, painted, .018 thick	" 4,767 SF	3.71	\$17,686
			Sub Total		\$17,686
		Co	onstruction Adjustment	35%	6,102
			Construction Cost		\$23,787
			Adjustment Factor	0%	0
			Soft Cost Adjustment	42%	10,095
		Tot	al Estimated Amount		\$33,882

Fairway Elementary School

M-A-P-P-S ©, Jacobs 2016

Page 25 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

290 **Fairway Elementary School** Fairway ES Location:

Deficiency:

Assess ID 314382

Defeciency Code ID A14-02

Estimated FCI Status Yes

Life Cycle

Deficiency Aluminum Covered Walkways Require Replacement

Category Capital Renewal Roofing

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Non Related

Replace Aluminum Walkway Correction Quantity / UoM

Project(s) Note Originally part of roof replacement deficiency. Pulled out separate to reflect covered walk canopy pricing.

Surveyor/Update

Estimate:

Туре	Number	Description	Qty UoM	Price	Extension
U	074113100600	Aluminum roof panels, corrugated, on steel frame, painted, .018 thick	" 1,831 SF	3.71	\$6,793
			Sub Total		\$6,793
		Co	onstruction Adjustment	35%	2,344
			Construction Cost		\$9,137
			Adjustment Factor	0%	0
			Soft Cost Adjustment	42%	3,878
		Tot	al Estimated Amount		\$13,014

Fairway Elementary School

M-A-P-P-S ©, Jacobs 2016

Page 26 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

290 **Fairway Elementary School** Fairway ES Location:

Deficiency:

Assess ID 314641 Surveyor/Update

Defeciency Code ID A14-02

Status **Estimated** FCI Yes

Life Cycle

Deficiency Aluminum Covered Walkways Require Replacement

Category Capital Renewal Roofing

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Non Related

Replace Aluminum Walkway Correction Quantity / UoM

Project(s) Note Originally part of roof replacement deficiency. Pulled out separate to reflect covered walk canopy pricing.

Estimate:

Type	Number	Description	Qty UoM	Price	Extension
U	074113100600	Aluminum roof panels, corrugated, on steel frame, painted, .018 thick	3" 1,560 SF	3.71	\$5,788
			Sub Total		\$5,788
		C	onstruction Adjustment	35%	1,997
			Construction Cost		\$7,784
			Adjustment Factor	0%	0
			Soft Cost Adjustment	42%	3,304
		Tot	tal Estimated Amount		\$11,088

Fairway Elementary School

M-A-P-P-S ©, Jacobs 2016

Page 27 of 624

Broward County Public Schools

Deficiency Detail

2/4/2016 3:36 PM

290 **Fairway Elementary School** Location: Fairway ES->Bldg 4

Deficiency:

Assess ID 316275 Surveyor/Update

Eric Sheppard

Other

Defeciency Code ID EA-Media Status **Estimated**

FCI

Yes

Life Cycle

Deficiency Media Center requires renovation based on condition of room(s)

Category Capital Renewal System

Priority 2-Indirect Impact to Mission (1 Year) Functional Adequacy Other

Correction Renovate / Remodel Media Center Quantity / UoM

Project(s) Note Room design = 380

Estimate:

Extension	Price	Qty UoM	Description	Number	Type
\$99,429	99,428.57	1 LS	Allowance for renovation		М
\$99,429		Sub Total			
34,303	35%	Construction Adjustment			
\$133,731		Construction Cost			
0	0%	Adjustment Factor			
64,673	48%	Soft Cost Adjustment			
\$198,404		Total Estimated Amount			

Fairway Elementary School

M-A-P-P-S ©, Jacobs 2016

Page 622 of 624

Attachment H



The School Board of Broward County, Florida Office of Facilities & Construction 3775 S.W. 16th Street Fort Lauderdale, Florida 33312

(754) 321-1500

Consultant's Authorization To Proceed				
Project No.:		Date:		
Location No.:		CDD CD O N		
Project Title:		SBBC P.O. No	:	
		Line No.:		
Facility Name:		Project Manager		
Project Consultant:		Dir. Capital Plan	ning & Programming	
			s, you are hereby authorized to proceed with the	
following service	es for the project	referenced above.		
Schematic Design	Design D	evelopment	Construction Documents	
Bidding	=	tion Contract Administration		
Other Services:	Attached:	ion Contract 7 turininstration	The warrancy	
other bervices.	7 ttucheu.			
This Authorization	on to Proceed is	subject to the following attachm	ents:	
Attachments:		Services Required		
	Project Sche			
	Previous AT			
			sional Services Required with a Fixed Limit of	
Construction Cos	st (FLCC) for thi	s project as indicated below:		
0.1.1ELGG	<u> </u>	C (C (F)	D : LELCOT AMD	
Original FLCC		Current Cost Estimate	Revised FLCC by ATP	
			_	
The following pr	ofessional servic	es will be provided by the Proje	ct Consultant as a normal part of its Basic Services	
for the Project lis		1	1	
_				
Item	Discipline	Description		

Attachment H



The School Board of Broward County, Florida Office of Facilities & Construction 3775 S.W. 16th Street Fort Lauderdale, Florida 33312

(754) 321-1500

Consultant's Authorization To Proceed (Term Contracts) Cont.				
	Project Schedule			
Project No. & Location No.:	Project Title:			
Facility Name: Project Consultant:				
The required project schedule milestones for this	project are presented below. (Mandatory)			
	Date Required Or Estin	nated Time Period		
ACTIVITY	Start	Finish		
Schematic Design				
Design Development				
Construction Documents Development				
50% Construction Documents				
100% Construction Documents				
Bidding and Award of Contract				
Time for Permitting of Submittals, Prior to the Issuance of the Construction NTP (Pa	art of Contract Administration)			
Construction				
Warranty				

Attachment H



The School Board of Broward County, Florida Office of Facilities & Construction 3775 S.W. 16th Street Fort Lauderdale, Florida 33312

(754) 321-1500

Consultant's Authorization To Proceed (Term Contracts)					
		Professiona	al Fees		
Project No. &		Project Title	: :		
Location No.:					
Facility Name:					
Project Consultant:					
Phase	Original Basic	Fee Authorized by ATP	Fee Previously Paid		
	Fee			Fee Balance	
I (SD) (5%)		%	%	%	
II (DD) (10%)		%	%	%	
III (CD) (35%/60%)		%	%	%	
IV (BID) (65%)		%	%	%	
V (CA) (98%)		%	%	%	
VI (Warr) (100%)		%	%	%	
Other Service		%	%	%	
Item No. 1					
Other Service		%	%	%	
(Item No. 2)					
Other Service		%	%	%	
(Item No. 3)					
Other Service		%	%	%	
(Item No. 4)					
Total:					
Payment for these services shall be made In accordance with the provisions of the Professional Services Agreement					

Payment for these services shall be made in accordance with the provisions of the Professional Services Agreement.

Approved By Consultant				Recommended By SBBC			
Name:				Name: Shelley N. Meloni			
Title:				Title: Director, Pre-Construction			
Signature:		Date:		Signature:		Date	
Certified By SBBC				Approval by SBBC			
Certified By SBB0	C			Approval b	y SBBC		
Name:	<u> </u>			Approval b Name: Leo	•		
<u> </u>	<u> </u>			Name: Leo	•		

This document is part of the Professional Services Agreement between The School Board of Broward County, Florida (Owner) and the Design Professional and is incorporated by reference into the terms and conditions of that agreement.